Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Adams Elementary School 2850 Club House Drive Costa Mesa, CA 92626

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Aug 12, 2019

> Building: NMUSD - Adams Elementary School Contact: Tim Waller Title: Manager, Maintenance & Operations

Company: Cal Building Systems Contact: Beeri Martinez Title: Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD - Adams Elementary School	Contact: Tim V	Waller
Address: 2850 Club House Drive	Phone: 714-23	31-0363
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92626	Mobile:	
Country: United States of America	Email: twaller@	@nmusd.us
Inspection Performed By		
Company: Cal Building Systems	Inspector: Bee	ri Martinez
Address: 2903 Saturn Street	Phone: 714-9	1313100
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: beerima	artinez@calbuildingsystems.com
System Control Unit		
Manufacturer: Silent Knight	Inspection Dat	te: 08/12/2019 IDC Style:
Model Number: IFP-1000	Install Date: 0	8/12/2019 SLC Style:
Software Version:	Version Date:	08/12/2019 NAC Style:
Location: Main Bldg. Nurse Office MDF Room	Current Protec	ction:
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Catalana	Total	Items	Ser	viced	Pa	ssed	Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.70%	1	100.00%	1	100.00%	0	0%
Control	28	19.58%	28	100.00%	28	100.00%	0	0%
Initiating	114	79.72%	114	100.00%	113	99.12%	1	0.88%
Totals	143	100%	143	100.00%	142	99.30%	1	0.70%
Certification								
Company: Cal Building Systems			Bu	ilding: NMU	ISD – Ada	ums Element	tary Schoo	ol
Inspector: Beeri Martinez			Co	ontact: Tim \	Waller			
fleu								
Signed: Aug 12, 2019 10:50:3	4 AM		Sig	gned:				

Discrepancy Report Generated by: BuildingReports.com

Building: NMUSD - Adams Elementary School Control Panel: 1 - Silent Knight						nt
IFP-1000						
1 1		lates each discrepancy listed with gory, and grouped by device type.	6	0.2		
*	•	listed for your convenience. Any i	1 0	*	•	
Product Safety C	Commission's we	bsite and is subject to a recall by t	the manufacturer is in	cluded.		
Device Type		Manufacturer	ModelNumber	Da	te	Qty
		Items listed for Recall b	y Manufacture	e r		
		No recalled items found duri	ng this inspection.			
8 ScanID	C3 Location	9	Problem	Address	Refe	erence
		Initiatin	g			
Waterflow Switch						
61326337	Multi-Purpose	Room Heater Room Fa	ailed to Report	1	NFPA72	14.2.1.2.2
Code References						
NFPA72 14.2.1.2.2 System defects and malfunctions shall be corrected.						

Proposed Solutions Report Generated by: BuildingReports.com

Building: N School	MUSD - Adams Elementary	Control Panel:	1 - Silent Kni	ght IFP-1	1000		
The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.							
ScanID	Location	Solution	Model #	Cost	Fix		
	Initia	ting					
Waterflow Switch							
61326337	Multi-Purpose Room Heater Room	Investigate	VSR	T/M			
			PO #: (none)	T/M			

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Adams Elementary School Control Panel: 1 - Silent Knight IFP-1000

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Main Bldg. Admin Office	Tested	8:31:08 AM	08/12/2019
Battery	Bldg. K Outside Storage Room	Tested	9:27:08 AM	08/12/2019
Battery	Bldg. K Outside Storage Room	Tested	9:27:28 AM	08/12/2019
Battery	Electrical Closet By Classroom 10	Tested	10:15:31 AM	08/12/2019
Battery	Electrical Closet By Classroom 10	Tested	10:15:49 AM	08/12/2019
Battery	IDF Closet Behind Classroom 1	Tested	9:40:33 AM	08/12/2019
Battery	IDF Closet Behind Classroom 1	Tested	9:40:55 AM	08/12/2019
Battery	IDF Closet Behind Classroom 21	Tested	11:01:27 AM	08/12/2019
Battery	IDF Closet Behind Classroom 21	Tested	11:01:39 AM	08/12/2019
Battery	IDF Closet Behind Library	Tested	10:57:04 AM	08/12/2019
Battery	IDF Closet Behind Library	Tested	10:57:16 AM	08/12/2019
Battery	Main Bldg. Nurse Office MDF Room	Tested	8:12:59 AM	08/12/2019
Battery	Main Bldg. Nurse Office MDF Room	Tested	8:14:04 AM	08/12/2019
Battery	Multi-Purpose Room Heater Room	Tested	9:02:01 AM	08/12/2019
Battery	Multi-Purpose Room Heater Room	Tested	9:02:09 AM	08/12/2019
Battery	Portables Classroom 14	Tested	10:32:46 AM	08/12/2019
Battery	Portables Classroom 14	Tested	10:32:55 AM	08/12/2019
Battery	Portables Classroom 4	Tested	9:50:17 AM	08/12/2019
Battery	Portables Classroom 4	Tested	9:50:35 AM	08/12/2019
Control Panel	Main Bldg. Nurse Office MDF Room	Tested	8:10:11 AM	08/12/2019
Power Supply	Bldg. K Outside Storage Room	Tested	9:26:17 AM	08/12/2019
Power Supply	Electrical Closet By Classroom 10	Tested	10:15:09 AM	08/12/2019
Power Supply	IDF Closet Behind Classroom 1	Tested	9:40:01 AM	08/12/2019
Power Supply	IDF Closet Behind Classroom 21	Tested	11:01:09 AM	08/12/2019
Power Supply	IDF Closet Behind Library	Tested	10:56:47 AM	08/12/2019
Power Supply	Multi-Purpose Room Heater Room	Tested	8:59:56 AM	08/12/2019
Power Supply	Portables Classroom 14	Tested	10:32:31 AM	08/12/2019
Power Supply	Portables Classroom 4	Tested	9:49:56 AM	08/12/2019
Initiating				
Heat Detector	Multi-Purpose Room Heater Room	Tested	9:03:56 AM	08/12/2019
Pull Station	Library	Tested	10:39:45 AM	08/12/2019
Pull Station	Library	Tested	10:40:01 AM	08/12/2019
Pull Station	Main Bldg. Admin Office Entrance	Tested	8:39:46 AM	08/12/2019
Pull Station	Main Bldg. Teachers Lounge Exit	Tested	8:33:17 AM	08/12/2019
Pull Station	Multi-Purpose Room Corridor By Restroom	Tested	8:51:08 AM	08/12/2019
Pull Station	Multi-Purpose Room	Tested	8:43:28 AM	08/12/2019
	Multi-Purpose Room	Tested		.,.=,=;1

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector		Tested	9:10:44 AM	08/12/2010
Smoke Detector	Bldg. K Classroom K–1 Boy's Restroom	Tested	9:09:08 AM	08/12/2019
Smoke Detector	Bldg. K Classroom K-1	Tested	9:09:41 AM	08/12/2019
	Bldg. K Classroom K–1		9:18:41 AM	08/12/2019
Smoke Detector	Bldg. K Classroom K-2 Boy's Restroom	Tested	9:18:41 AM	08/12/2019
Smoke Detector	Bldg. K Classroom K-2	Tested	9:18:50 AM	08/12/2019
Smoke Detector	Bldg. K Classroom K-2	Tested	9:18:37 AM 9:24:44 AM	08/12/2019
Smoke Detector	Bldg. K Outside Storage Room	Tested	9:17:10 AM	08/12/2019
Smoke Detector	Bldg. K Workroom	Tested	9:17:10 AM 9:17:47 AM	08/12/2019
Smoke Detector	Bldg. K Workroom Restroom	Tested		08/12/2019
Smoke Detector	Bldg. K Portables Classroom K-3	Tested	9:29:10 AM	08/12/2019
Smoke Detector	Bldg. K Portables Classroom K-3	Tested	9:29:22 AM	08/12/2019
Smoke Detector	Bldg. K Portables Classroom K-4	Tested	9:31:48 AM	08/12/2019
Smoke Detector	Bldg. K Portables Classroom K-4	Tested	9:31:55 AM	08/12/2019
Smoke Detector	Boy's Restroom By Classroom 10	Tested	10:18:29 AM	08/12/2019
Smoke Detector	Boy's Restroom By Classroom 13	Tested	10:26:45 AM	08/12/2019
Smoke Detector	Boy's Restroom By Classroom 7	Tested	10:03:19 AM	08/12/2019
Smoke Detector	Classroom 1	Tested	9:42:26 AM	08/12/2019
Smoke Detector	Classroom 1	Tested	9:42:38 AM	08/12/2019
Smoke Detector	Classroom 10	Tested	10:19:43 AM	08/12/2019
Smoke Detector	Classroom 10	Tested	10:19:54 AM	08/12/2019
Smoke Detector	Classroom 11A	Tested	10:20:52 AM	08/12/2019
Smoke Detector	Classroom 11B	Tested	10:21:44 AM	08/12/2019
Smoke Detector	Classroom 11C	Tested	10:22:39 AM	08/12/2019
Smoke Detector	Classroom 12	Tested	10:25:02 AM	08/12/2019
Smoke Detector	Classroom 12	Tested	10:25:12 AM	08/12/2019
Smoke Detector	Classroom 13	Tested	10:28:24 AM	08/12/2019
Smoke Detector	Classroom 13	Tested	10:28:33 AM	08/12/2019
Smoke Detector	Classroom 18	Tested	10:40:38 AM	08/12/2019
Smoke Detector	Classroom 18	Tested	10:40:49 AM	08/12/2019
Smoke Detector	Classroom 19	Tested	10:42:29 AM	08/12/2019
Smoke Detector	Classroom 19	Tested	10:42:36 AM	08/12/2019
Smoke Detector	Classroom 2	Tested	9:44:40 AM	08/12/2019
Smoke Detector	Classroom 2	Tested	9:44:50 AM	08/12/2019
Smoke Detector	Classroom 20	Tested	10:43:31 AM	08/12/2019
Smoke Detector	Classroom 20	Tested	10:43:38 AM	08/12/2019
Smoke Detector	Classroom 21	Tested	10:52:20 AM	08/12/2019
Smoke Detector	Classroom 21	Tested	10:52:28 AM	08/12/2019
Smoke Detector	Classroom 3	Tested	9:45:59 AM	08/12/2019
Smoke Detector	Classroom 3	Tested	9:46:06 AM	08/12/2019
Smoke Detector	Classroom 6	Tested	10:01:21 AM	08/12/2019
Smoke Detector	Classroom 6	Tested	10:01:27 AM	08/12/2019
Smoke Detector	Classroom 7	Tested	10:04:50 AM	08/12/2019
Smoke Detector	Classroom 7	Tested	10:04:57 AM	08/12/2019
Smoke Detector	Electrical Closet By Classroom 10	Tested	10:13:34 AM	08/12/2019
Smoke Detector	Girl's Restroom By Classroom 10	Tested	10:19:27 AM	08/12/2019
Smoke Detector	Girl's Restroom By Classroom 13	Tested	10:25:55 AM	08/12/2019
Smoke Detector	Girl's Restroom By Classroom 7	Tested	10:03:37 AM	08/12/2019
Smoke Detector	IDF Closet Behind Classroom 1	Tested	9:34:31 AM	08/12/2019
Smoke Detector	IDF Closet Behind Classroom 21	Tested	10:59:37 AM	08/12/2019
				, ,

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Janitors Closet Behind Classroom 10	Tested	10:12:25 AM	08/12/2019
Smoke Detector	Library	Tested	10:37:29 AM	08/12/2019
Smoke Detector	Library	Tested	10:37:50 AM	08/12/2019
Smoke Detector	Library	Tested	10:37:54 AM	08/12/2019
Smoke Detector	Main Bldg. Admin Office Entrance	Tested	8:39:21 AM	08/12/2019
Smoke Detector	Main Bldg. Admin Office Workroom	Tested	8:40:49 AM	08/12/2019
Smoke Detector	Main Bldg. Admin Office	Tested	8:37:40 AM	08/12/2019
Smoke Detector	Main Bldg. Admin Office	Tested	8:40:36 AM	08/12/2019
Smoke Detector	Main Bldg. Nurse Office MDF Room	Tested	8:33:44 AM	08/12/2019
Smoke Detector	Main Bldg. Nurse Office Restroom	Tested	8:33:54 AM	08/12/2019
Smoke Detector	Main Bldg. Nurse Office	Tested	8:34:01 AM	08/12/2019
Smoke Detector	Main Bldg. Principals Office	Tested	8:38:27 AM	08/12/2019
Smoke Detector	Main Bldg. Staff Restroom	Tested	8:42:13 AM	08/12/2019
Smoke Detector	Main Bldg. Teachers Lounge Restroom	Tested	8:36:24 AM	08/12/2019
Smoke Detector	Main Bldg. Teachers Lounge	Tested	8:34:25 AM	08/12/2019
Smoke Detector	Main Bldg. Teachers Lounge	Tested	8:35:41 AM	08/12/2019
Smoke Detector	Multi-Purpose Room Corridor By Restroom	Tested	8:49:50 AM	08/12/2019
Smoke Detector	Multi-Purpose Room Heater Room	Tested	8:59:06 AM	08/12/2019
Smoke Detector	Multi-Purpose Room IDF/Phone Room	Tested	8:51:47 AM	08/12/2019
Smoke Detector	Multi-Purpose Room Stage	Tested	8:46:50 AM	08/12/2019
Smoke Detector	Multi-Purpose Room Stage	Tested	8:47:00 AM	08/12/2019
Smoke Detector	Multi-Purpose Room Teachers Lounge	Tested	8:53:38 AM	08/12/2019
Smoke Detector	Multi-Purpose Room	Tested	8:44:41 AM	08/12/2019
Smoke Detector	Multi-Purpose Room	Tested	8:45:03 AM	08/12/2019
Smoke Detector	Multi-Purpose Room	Tested	8:45:07 AM	08/12/2019
Smoke Detector	Multi-Purpose Room	Tested	8:45:10 AM	08/12/2019
Smoke Detector	Portables Classroom 14	Tested	10:30:48 AM	08/12/2019
Smoke Detector	Portables Classroom 14	Tested	10:30:56 AM	08/12/2019
Smoke Detector	Portables Classroom 15	Tested	10:33:35 AM	08/12/2019
Smoke Detector	Portables Classroom 15	Tested	10:33:43 AM	08/12/2019
Smoke Detector	Portables Classroom 16	Tested	10:34:47 AM	08/12/2019
Smoke Detector	Portables Classroom 16	Tested	10:34:55 AM	08/12/2019
Smoke Detector	Portables Classroom 22	Tested	11:02:06 AM	08/12/2019
Smoke Detector	Portables Classroom 22	Tested	11:02:21 AM	08/12/2019
Smoke Detector	Portables Classroom 23	Tested	11:03:23 AM	08/12/2019
Smoke Detector	Portables Classroom 23	Tested	11:03:31 AM	08/12/2019
Smoke Detector	Portables Classroom 24	Tested	11:03:47 AM	08/12/2019
Smoke Detector	Portables Classroom 24	Tested	11:03:55 AM	08/12/2019
Smoke Detector	Portables Classroom 25	Tested	11:04:55 AM	08/12/2019
Smoke Detector	Portables Classroom 25	Tested	11:05:04 AM	08/12/2019
Smoke Detector	Portables Classroom 26	Tested	11:07:06 AM	08/12/2019
Smoke Detector	Portables Classroom 26	Tested	11:07:22 AM	08/12/2019
Smoke Detector	Portables Classroom 4	Tested	9:47:04 AM	08/12/2019
Smoke Detector	Portables Classroom 4	Tested	9:47:18 AM	08/12/2019
Smoke Detector	Portables Classroom 5	Tested	9:51:44 AM	08/12/2019
Smoke Detector	Portables Classroom 5	Tested	9:51:53 AM	08/12/2019
Smoke Detector	Portables Classroom 8	Tested	10:05:41 AM	08/12/2019
Smoke Detector	Portables Classroom 8	Tested	10:05:47 AM	08/12/2019
Smoke Detector	Portables Classroom 9	Tested	10:05:58 AM	08/12/2019
Smoke Detector	Portables Classroom 9	Tested	10:06:06 AM	08/12/2019

Device Type	Location	Service	Time	Date		
	Passed					
Smoke Detector	Staff Restroom Behind Classroom 13	Tested	10:29:37 AM	08/12/2019		
Smoke Detector	Staff Restroom Behind Classroom 7	Tested	10:09:02 AM	08/12/2019		
Smoke Detector	Staff Restroom By Classroom 13	Tested	10:27:15 AM	08/12/2019		
Smoke Detector	Staff Restroom By Classroom 7	Tested	10:02:48 AM	08/12/2019		
Smoke Detector	Storage Bldg. Custodian Closet	Tested	9:07:43 AM	08/12/2019		
Device Type	Location	Service	Time	Date		
	Failed/Other					
Initiating						
Waterflow Switch	Multi-Purpose Room Heater Room	Tested	11:21:52 AM	08/12/2019		

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Adams Elementary School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity			
Failed/Other					
Waterflow Switch	Tested	1			
Total		1			
	Passed				
Annunciator	Tested	1			
Battery	Tested	18			
Control Panel	Tested	1			
Heat Detector	Tested	1			
Power Supply	Tested	8			
Pull Station	Tested	7			
Smoke Detector	Tested	105			
Total		142			

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - Adams Elementary School

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

		Ambient	Alarm	🦻 Intell	igibility	Sound
C Location	 Comment 	◀ dB	◀ dB	Voice	STI	Test
Passed						
Sound Test Points						
Entire Campus	Passed					0001

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Adams Elementary School Control Panel: 1 - Silent Knight IFP-1000

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category	% of Ir	nventory	Quantity
Control Panel		Control	*	0.70%	1
Battery		Control		12.59%	18
Annunciator		Control		0.70%	1
Pull Station		Initiating		4.90%	7
Smoke Detector		Initiating		73.43%	105
Power Supply		Control		5.59%	8
Heat Detector		Initiating		0.70%	1
Waterflow Switch		Initiating	Γ	0.70%	1
Туре	Qty	Model #	Description		Install Date
New (under 90 days)					
Silent Knight					
Control Panel	1	IFP-1000			08/12/2019
		In Service	- 2 Years to 3 Year	S	
Battery	2	12v 18ah	Sealed Lead Acid		08/07/2017
Battery	16	12v 7ah	Sealed Lead Acid		08/07/2017
Potter Electric					
Waterflow Switch	1	VSR			08/07/2017
Silent Knight					
Annunciator	1	SK-5860			08/07/2017
Heat Detector	1	SD505-AHS	Fixed Temperature		08/07/2017
Power Supply	8	RPS-1000			08/07/2017
Pull Station	7	SD500-PS	Keyed		08/07/2017
Smoke Detector	105	SD505-APS	Photoelectric		08/07/2017

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Anderson Elementary 1900 Port Seabourne Way Newport, CA 92660

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Aug 23, 2019

> Building: NMUSD - Anderson Elementary Contact: Tim Waller Title: M&O Manager

Company: Cal Building Systems Contact: Thomas Galaz Title: Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD - Anderson Elementary	Contact: Tim W	aller
Address: 1900 Port Seabourne Way	Phone: 714–23	1-0363
Address:	Fax:	
City/State/Zip: Newport, CA 92660	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Thor	nas Galaz
Address: 2903 Saturn Street	Phone: 714993	9650
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile: 714215	8050
Country: United States of America	Email: cbs@call	puildingsystems.com
System Control Unit		
Manufacturer: Silent Knight	Inspection Date	:: 08/23/2019 IDC Style :
Model Number: IFP-1000	Install Date: 08	/23/2019 SLC Style:
Software Version:	Version Date: 0	8/23/2019 NAC Style:
Location: Admin BLDG. FACP Room	Current Protect	ion:
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
C .1	Total	ltems	Ser	viced	Pas	ssed	Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Control	6	4.72%	6	100.00%	4	66.67%	2	33.33%
Initiating	121	95.28%	121	100.00%	118	97.52%	3	2.48%
Totals	127	100%	127	100.00%	122	96.06%	5	3.94%
Certification								
Company: Cal Building Systems			Bu	ilding: NML	JSD – And	lerson Elem	nentary	
Inspector: Thomas Galaz			Co	ontact: Tim	Waller			
Signed:			Sig	gned:				

Discrepancy Report Generated by: BuildingReports.com

Building: NMUSD - Anderson Elementary Control Panel: 1 - Silent Knight IFP-1000							
The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.							
Device Type	Manufacturer	ModelNumber	r Da	ate Qty			
	Items listed for I	Recall by Manufactur	rer				
	No recalled items	found during this inspection.					
8 ScanID		Problem	Address	Reference			
	Ι	nitiating					
Smoke De	tector						
47354036	Admin BLDG. Classroom 10	Failed Annunciation	1	NFPA72 10.16.1.1.1			
47354000	Portables. Classroom 29	Failed Annunciation	1	NFPA72 10.16.1.1.1			
47354001	Portables. Classroom 29	Failed Annunciation	1	NFPA72 10.16.1.1.1			
	Code References						
NFPA72 10.16.1.1.1 Visible annunciation of the location of an operated initiating device shall be by an indicator lamp, alphanumeric display, printout, or other approved means.							

Building: N	MUSD - Ai	nderson Elemer	ntary	Control Pan	el: 2		
The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.							
Device Type		Manufacturer		ModelNumber	r Da	ate	Qty
		Items listed for	r Recall by	y Manufactur	rer		
		No recalled item	ns found durin	g this inspection.			
8 ScanID	E Location		ę	Problem	Address	Refe	erence
			Control				
Battery							
47354144	Admin BLDG. F.	ACP Room	Da	te Expired	2	NFPA72 T	able
						14.4.2.2	(5)(b)
47354145	Admin BLDG. F.	ACP Room	Da	te Expired	2	NFPA72 T	able
						14.4.2.2	(5)(b)
Code References							
NFPA72 Table 14.4.2.2 (5)(b)		shall be replaced in acc urer or when the recha ndations					

Proposed Solutions Report Generated by: BuildingReports.com

Building: N	MUSD - Anderson Elementary	Control Panel:	1 - Silent Kni	ght IFP-	1000			
The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.								
ScanID	Location	Solution	Model #	Cost	Fix			
	Initia	ting						
Smoke De	ector							
47354036	Admin BLDG. Classroom 10		SD505-APS	T/M				
47354000	Portables. Classroom 29		SD505-APS	T/M				
47354001	Portables, Classroom 29		SD505-APS	T/M				
17551001			3D303-AF3	I / IVI	-			
	IMUSD - Anderson Elementary			ntrol Par	nel: 2			
Building: N The Proposed S	MUSD - Anderson Elementary olution Report provides a solution for each disc re indicated to approve repairs listed within th		Co Discrepancy Repor	ntrol Par t. Provide	a			
Building: N The Proposed S check mark whe	MUSD - Anderson Elementary olution Report provides a solution for each disc re indicated to approve repairs listed within th		Co Discrepancy Repor	ntrol Par t. Provide	a			
Building: N The Proposed S check mark whe Time and Mater	IMUSD - Anderson Elementary olution Report provides a solution for each disc re indicated to approve repairs listed within th ials basis.	e report. Items listed as Solution	Co Discrepancy Repor T/M are available	ntrol Par t. Provide for repair of	a on a			
Building: N The Proposed S check mark whe Time and Mater	IMUSD - Anderson Elementary olution Report provides a solution for each disc re indicated to approve repairs listed within the tials basis.	e report. Items listed as Solution	Co Discrepancy Repor T/M are available	ntrol Par t. Provide for repair of	a on a			
Building: N The Proposed S check mark whe Time and Mater ScanID	IMUSD - Anderson Elementary olution Report provides a solution for each disc re indicated to approve repairs listed within the tials basis.	e report. Items listed as Solution	Co Discrepancy Repor T/M are available	ntrol Par t. Provide for repair of	a on a			
Building: N The Proposed S check mark whe Time and Mater ScanID Battery	IMUSD - Anderson Elementary olution Report provides a solution for each disc re indicated to approve repairs listed within the ials basis. Location Cont	e report. Items listed as Solution Trol	Co Discrepancy Repor T/M are available Model #	ntrol Par t. Provide for repair o Cost	a on a Fix			

Notes & Recommendations

Generated by: BuildingReports.com

Building: NMUSD - Anderson Elementary Control Panel: 1 - Silent Knight IFP-1000

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

ScanID	Note	Device Type	Location	Comment			
	Initiating						
47354036	1	Smoke Detector	Admin BLDG. Classroom 10	Failed Annunciation			
Descr	iption Is I	ncorrect It Should Be: Classroom	10 West				
47354000	2	Smoke Detector	Portables. Classroom 29	Failed Annunciation			
Panel	Has Inco	rrect Description. It Should Be: Po	ortables Classroom 29				
47354001	3	Smoke Detector	Portables. Classroom 29	Failed Annunciation			
Panel	Has Inco	rrect Description. It Should Be: Po	ortables Classroom 29				

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Anderson Elementary

Control Panel: 1 - Silent Knight IFP-1000

Device Type	Location	Service	Time	Date
	Passed			
Control				
Control Panel	Admin BLDG. FACP Room	Tested	11:03:58 AM	08/23/2019
Initiating				
Heat Detector	2nd Admin BLDG. Women's Restroom	Tested	10:42:32 AM	08/23/2019
Heat Detector	Admin BLDG. East Restroom	Tested	10:00:21 AM	08/23/2019
Heat Detector	Admin BLDG. North Boys Restroom	Tested	9:41:18 AM	08/23/2019
Heat Detector	Admin BLDG. North Girls Restroom	Tested	9:40:59 AM	08/23/2019
Heat Detector	Admin BLDG. North Hallway	Tested	9:02:32 AM	08/23/2019
Heat Detector	Admin BLDG. North Hallway	Tested	9:34:55 AM	08/23/2019
Heat Detector	Admin BLDG. Nurses Restroom	Tested	9:20:42 AM	08/23/2019
Heat Detector	Admin BLDG. Restroom	Tested	9:16:20 AM	08/23/2019
Heat Detector	MPR BLDG. Kitchen Restroom	Tested	10:33:36 AM	08/23/2019
Heat Detector	MPR BLDG. Restroom	Tested	10:07:11 AM	08/23/2019
Heat Detector	MPR BLDG. Restroom	Tested	10:07:46 AM	08/23/2019
Heat Detector	Boys Restroom Inside Classroom 7	Tested	8:42:10 AM	08/23/2019
Heat Detector	Boys Restroom Outside Classroom 2	Tested	8:15:22 AM	08/23/2019
Heat Detector	Girls Restroom Inside Classroom 7	Tested	8:41:08 AM	08/23/2019
Pull Station	Admin BLDG. Lobby	Tested	9:22:55 AM	08/23/2019
Pull Station	MPR BLDG. East Exit	Tested	10:19:51 AM	08/23/2019
Pull Station	MPR BLDG. West Exit	Tested	10:17:55 AM	08/23/2019
Pull Station	Portables. Classroom 21	Tested	7:57:25 AM	08/23/2019
Pull Station	Portables. Classroom 22	Tested	8:01:45 AM	08/23/2019
Pull Station	Portables. Classroom 23	Tested	8:03:47 AM	08/23/2019
Pull Station	Portables. Classroom 24	Tested	8:05:05 AM	08/23/2019
Pull Station	Portables. Classroom 25	Tested	8:06:28 AM	08/23/2019
Smoke Detector	2nd Admin BLDG. Teachers lounge	Tested	10:40:26 AM	08/23/2019
Smoke Detector	Admin BLDG. Classroom 1	Tested	8:24:13 AM	08/23/2019
Smoke Detector	Admin BLDG. Classroom 1	Tested	8:24:45 AM	08/23/2019
Smoke Detector	Admin BLDG. Classroom 10	Tested	9:00:50 AM	08/23/2019
Smoke Detector	Admin BLDG. Classroom 11	Tested	9:01:02 AM	08/23/2019
Smoke Detector	Admin BLDG. Classroom 11	Tested	9:01:15 AM	08/23/2019
Smoke Detector	Admin BLDG. Classroom 12	Tested	9:01:28 AM	08/23/2019
Smoke Detector	Admin BLDG. Classroom 12	Tested	9:01:41 AM	08/23/2019
Smoke Detector	Admin BLDG. Classroom 13	Tested	9:31:06 AM	08/23/2019
Smoke Detector	Admin BLDG. Classroom 13	Tested	9:33:31 AM	08/23/2019
Smoke Detector	Admin BLDG. Classroom 14	Tested	9:33:39 AM	08/23/2019
Smoke Detector	Admin BLDG. Classroom 14	Tested	9:33:52 AM	08/23/2019
Smoke Detector	Admin BLDG. Classroom 15	Tested	9:34:05 AM	08/23/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Admin BLDG. Classroom 15	Tested	9:34:17 AM	08/23/2019
Smoke Detector	Admin BLDG. Classroom 15	Tested	9:34:23 AM	08/23/2019
Smoke Detector	Admin BLDG. Classroom 15	Tested	9:34:30 AM	08/23/2019
Smoke Detector	Admin BLDG. Classroom 16	Tested	9:43:29 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 16	Tested	9:43:45 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 17	Tested	9:46:44 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 17	Tested	9:47:03 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 18	Tested	9:48:30 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 18	Tested	9:48:51 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 19	Tested	10:03:40 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 19	Tested	10:03:53 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 2	Tested	8:26:41 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 2	Tested	8:26:56 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 20	Tested	10:02:01 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 20	Tested	10:03:27 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 26	Tested	8:52:00 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 26	Tested	8:52:13 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 27	Tested	9:29:32 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 3	Tested	8:54:17 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 3	Tested	8:54:39 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 4	Tested	8:34:02 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 4	Tested	8:34:21 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 5	Tested	8:36:26 AM	
Smoke Detector	Admin BLDG. Classroom 6	Tested	8:34:30 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 6	Tested	8:34:48 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 7	Tested	8:34:56 AM	08/23/201
			8:35:09 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 7	Tested	8:35:39 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 8	Tested		08/23/201
Smoke Detector	Admin BLDG. Classroom 8	Tested	8:36:15 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 9	Tested	9:00:06 AM	08/23/201
Smoke Detector	Admin BLDG. Classroom 9	Tested	9:00:27 AM	08/23/201
Smoke Detector	Admin BLDG. Corridor	Tested	8:49:47 AM	08/23/201
Smoke Detector	Admin BLDG. Corridor	Tested	8:50:50 AM	08/23/201
Smoke Detector	Admin BLDG. Corridor	Tested	9:17:39 AM	08/23/201
Smoke Detector	Admin BLDG. Corridor South	Tested	8:56:22 AM	08/23/201
Smoke Detector	Admin BLDG. Custodian Office	Tested	11:29:14 AM	08/23/201
Smoke Detector	Admin BLDG. East Hallway	Tested	9:57:16 AM	08/23/201
Smoke Detector	Admin BLDG. FACP Room	Tested	11:02:32 AM	08/23/201
Smoke Detector	Admin BLDG. Hallway Northwest	Tested	8:40:17 AM	08/23/201
Smoke Detector	Admin BLDG. Hallway Southwest	Tested	8:28:41 AM	08/23/201
Smoke Detector	Admin BLDG. High Smoke East	Tested	11:30:20 AM	08/23/201
Smoke Detector	Admin BLDG. High Smoke East	Tested	11:30:51 AM	08/23/201
Smoke Detector	Admin BLDG. High Smoke East	Tested	11:31:00 AM	08/23/201
Smoke Detector	Admin BLDG. High Smoke East	Tested	11:31:07 AM	08/23/201
Smoke Detector	Admin BLDG. High Smoke West	Tested	11:31:18 AM	08/23/201
Smoke Detector	Admin BLDG. High Smoke West	Tested	11:31:36 AM	08/23/201
Smoke Detector	Admin BLDG. High Smoke West	Tested	11:31:45 AM	08/23/201
Smoke Detector	Admin BLDG. High Smoke West	Tested	11:31:54 AM	08/23/201
Smoke Detector	Admin BLDG. Janitors Closet Outside Classroom	Tested	11:37:08 AM	08/23/201

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Admin BLDG. Library	Tested	9:27:03 AM	08/23/2019
Smoke Detector	Admin BLDG. Library	Tested	9:27:33 AM	08/23/2019
Smoke Detector	Admin BLDG. Library	Tested	9:28:49 AM	08/23/2019
Smoke Detector	Admin BLDG. Lobby	Tested	9:22:20 AM	08/23/2019
Smoke Detector	Admin BLDG. North Entry	Tested	8:47:34 AM	08/23/2019
Smoke Detector	Admin BLDG. North Hallway	Tested	9:03:13 AM	08/23/2019
Smoke Detector	Admin BLDG. North Hallway	Tested	9:40:24 AM	08/23/2019
Smoke Detector	Admin BLDG. Northeast Corridor Exit	Tested	9:45:18 AM	08/23/2019
Smoke Detector	Admin BLDG. Nurses Office	Tested	9:19:42 AM	08/23/2019
Smoke Detector	Admin BLDG. Office	Tested	9:14:18 AM	08/23/2019
Smoke Detector	Admin BLDG. Principals Office	Tested	9:19:02 AM	08/23/2019
Smoke Detector	Admin BLDG. South Corridor	Tested	8:20:27 AM	08/23/2019
Smoke Detector	Admin BLDG. Speech Office	Tested	9:25:58 AM	08/23/2019
Smoke Detector	Admin BLDG. Storage Room	Tested	11:40:19 AM	08/23/2019
Smoke Detector	Admin BLDG. Water Heater Room Outside East	Tested	11:38:02 AM	08/23/2019
Smoke Detector	Admin BLDG. Workroom	Tested	9:15:20 AM	08/23/2019
Smoke Detector	Admin BLDG. Workroom	Tested	9:58:55 AM	08/23/2019
Smoke Detector	Admin BLDG. Workroom	Tested	9:59:26 AM	08/23/2019
Smoke Detector	MPR BLDG. Classroom 28	Tested	10:09:29 AM	08/23/2019
Smoke Detector	MPR BLDG. Classroom 28	Tested	10:10:20 AM	08/23/2019
Smoke Detector	MPR BLDG. Classroom 28 Workroom	Tested	10:11:48 AM	08/23/2019
Smoke Detector	MPR BLDG. Exit Northeast	Tested	10:21:20 AM	08/23/2019
Smoke Detector	MPR BLDG. Kitchen	Tested	10:31:37 AM	08/23/2019
Smoke Detector	MPR BLDG. Kitchen	Tested	10:32:13 AM	08/23/2019
Smoke Detector	MPR BLDG. Kitchen	Tested	10:32:40 AM	08/23/2019
Smoke Detector	MPR BLDG. Kitchen	Tested	10:33:20 AM	08/23/2019
Smoke Detector	MPR BLDG. Northeast	Tested	10:14:37 AM	08/23/2019
Smoke Detector	MPR BLDG. Northwest	Tested	10:13:15 AM	08/23/2019
Smoke Detector	MPR BLDG. Outside Restrooms	Tested	10:05:49 AM	08/23/2019
Smoke Detector	MPR BLDG. Southeast	Tested	10:14:13 AM	08/23/2019
Smoke Detector	MPR BLDG. Southwest	Tested	10:13:51 AM	08/23/2019
Smoke Detector	MPR BLDG. Storage	Tested	10:35:34 AM	08/23/2019
Smoke Detector	MPR BLDG. Storage	Tested	10:36:01 AM	08/23/2019
Waterflow Switch	Admin BLDG. Storage Room	Tested	11:40:46 AM	08/23/2019
Device Type	Location	Service	Time	Date
	Failed/Other			
Initiating				
Smoke Detector	Admin BLDG. Classroom 10	Tested	9:07:00 AM	08/23/2019
Smoke Detector	Portables. Classroom 29	Tested	7:52:43 AM	08/23/2019
Smoke Detector	Portables. Classroom 29	Tested	7:52:52 AM	08/23/2019

Building: NMUSD - Anderson Elementary Control Panel: 2

Device Type	Location	Service	Time	Date
	Passe	ed and a second s		
Control				
Battery	Admin BLDG. FACP Room	Tested	11:05:02 AM	08/23/2019
Battery	Admin BLDG. FACP Room	Tested	11:05:35 AM	08/23/2019
Power Supply	Admin BLDG. FACP Room	Tested	11:04:36 AM	08/23/2019
Device Type	Location	Service	Time	Date
	Failed/C	Other		
Control				
Battery	Admin BLDG. FACP Room	Tested	11:07:02 AM	08/23/2019
Battery	Admin BLDG. FACP Room	Tested	11:07:08 AM	08/23/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Anderson Elementary

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity					
	Failed/Other						
Battery	Tested	2					
Smoke Detector	Tested	3					
Total		5					
	Passed						
Battery	Tested	2					
Control Panel	Tested	1					
Heat Detector	Tested	14					
Power Supply	Tested	1					
Pull Station	Tested	8					
Smoke Detector	Tested	95					
Waterflow Switch	Tested	1					
Total		127					

Time, Temperature & Level Testing Generated by: BuildingReports.com

Building: NMU	JSD - Anderson Elementary	Control Pane IFP-1000	1:1 -	Siler	nt Kni	ight		
The Time, Temperature, & Level Testing section details the measurements taken from various devices that are designed to respond in a certain amount of time, respond at a certain temperature, or respond within the acceptable range of volume or level. Items are grouped by Passed or Failed/Other.								
Туре	Location	Comment	Sec	Deg	Lvl	ScanID		
	Passed							
Waterflow Switch								
	Admin BLDG. Storage Room	Passed	58	n/a	n/a	47354121		

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Anderson Elementary

Control Panel: 1 - Silent Knight IFP-1000

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category	% of In	ventory	Quantity
Smoke Detector		Initiating		77.17%	98
Pull Station		Initiating		6.30%	8
Heat Detector		Initiating		11.02%	14
Control Panel		Control		0.79%	1
Power Supply		Control		0.79%	1
Battery		Control		3.15%	4
Waterflow Switch		Initiating		0.79%	1
Туре	Qty	Model #	Description		Install Date
		New	(under 90 days)		
Potter Electric					
Waterflow Switch	1	VSR			08/23/2019
Silent Knight					
Control Panel	1	IFP-1000			08/23/2019
Heat Detector	14	SD505-AHS			08/23/2019
Pull Station	8	SD500-PS			08/23/2019
Smoke Detector	98	SD505-APS	Photoelectric		08/23/2019

Building: NMUSD - Anderson Elementary Control Panel: 2

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Туре	Qty	Model #	Description	Install Date	
New (under 90 days)					
Battery	2	12v 18ah		08/23/2019	
Battery	2	12v 7ah		08/23/2019	
Silent Knight					
Power Supply	1	RPS-1000		08/23/2019	

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Back Bay Monte Vista 390 Monte Vista Avé. Costa Mesa, CA 92627

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Sep 4, 2019

> Building: NMUSD - Back Bay Monte Vista Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Michael Cannon Title: Service Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD - Back Bay Monte Vista	Contact: Tim Waller	
Address: 390 Monte Vista Avé.	Phone: 714-231-0363	
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92627	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Michael Can	non
Address: 2903 Saturn Street	Phone: 714-715-1223	
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: mcannon@calbu	uildingsystems.com
System Control Unit		
Manufacturer: Simplex	Inspection Date: 09/04	4/2019 IDC Style:
Model Number: 4100U	Install Date: 09/04/20	19 SLC Style:
Software Version:	Version Date: 09/04/2	019 NAC Style:
Location: Building A Electrical Room A20	Current Protection:	
Monitoring		
Company: AceTec	Phone: 1-800-634-3915	Account #: 21-1114
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
	Total Items		Serviced		Passed		Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.64%	1	100.00%	1	100.00%	0	0%
Control	21	13.38%	21	100.00%	21	100.00%	0	0%
Initiating	135	85.99%	135	100.00%	135	100.00%	0	0%
Totals	157	100%	157	100.00%	157	100.00%	0	0%
Certification			Bu	ilding: NMI	ISD - Bac	Ray Monte	a Vista	
Company: Cal Building Systems Building: NMUSD - Back Bay Monte Vista Inspector: Michael Cannon Contact: Tim Waller								
-That -								
Signed: Sep 5, 2019 4:42:08 F	PM		Sig	jned:				

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Back Bay Monte Vista

Control Panel: 1 - Simplex 4100U

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Building A Admin Reception A16	Inspected	4:04:08 PM	09/04/2019
Annunciator	Building A Admin Reception A16	Inspected	4:04:43 PM	09/04/2019
Annunciator	Portable Building E Administration Entrance	Inspected	5:06:51 PM	09/04/2019
Battery	Building A Electrical Room A20	Tested	3:19:20 PM	09/04/2019
Battery	Building A Electrical Room A20	Tested	3:20:35 PM	09/04/2019
Battery	Building B Electrical Room B11	Tested	4:30:41 PM	09/04/2019
Battery	Building B Electrical Room B11	Tested	4:30:57 PM	09/04/2019
Battery	Building C Electrical Room C8	Tested	4:45:48 PM	09/04/2019
Battery	Building C Electrical Room C8	Tested	4:46:05 PM	09/04/2019
Battery	Building D Electrical Room D7	Tested	4:57:43 PM	09/04/2019
Battery	Building D Electrical Room D7	Tested	4:58:20 PM	09/04/2019
Battery	Building G MPR Stage Storage Room	Tested	6:05:29 PM	09/04/2019
Battery	Building G MPR Stage Storage Room	Tested	6:05:56 PM	09/04/2019
Control Panel	Building A Electrical Room A20	Tested	3:17:35 PM	09/04/2019
Power Supply	Building B Electrical Room B11	Inspected	4:30:19 PM	09/04/2019
Power Supply	Building C Electrical Room C8	Inspected	4:42:53 PM	09/04/2019
Power Supply	Building D Electrical Room D7	Inspected	4:56:44 PM	09/04/2019
Power Supply	Building G MPR Stage Storage	Inspected	6:04:38 PM	09/04/2019
Initiating				
Heat Detector	Building A Attendance A14	Tested	5:16:29 PM	09/04/2019
Heat Detector	Building A Computer Room A1	Tested	5:15:07 PM	09/04/2019
Heat Detector	Building A Custodian A10	Tested	5:12:18 PM	09/04/2019
Heat Detector	Building A FAU-1	Tested	5:17:57 PM	09/04/2019
Heat Detector	Building A FAU-2	Tested	5:17:47 PM	09/04/2019
Heat Detector	Building A FAU-3	Tested	5:17:31 PM	09/04/2019
Heat Detector	Building A Office A6	Tested	5:16:52 PM	09/04/2019
Heat Detector	Building A Register A4	Tested	5:16:09 PM	09/04/2019
Heat Detector	Building A Water Heater A12	Tested	5:17:10 PM	09/04/2019
Heat Detector	Building B Classroom B1	Tested	5:19:59 PM	09/04/2019
Heat Detector	Building B Classroom B2	Tested	5:20:13 PM	09/04/2019
Heat Detector	Building B Classroom B3	Tested	5:21:23 PM	09/04/2019
Heat Detector	Building B Classroom B4	Tested	5:21:34 PM	09/04/2019
Heat Detector	Building B Classroom B5	Tested	5:22:12 PM	09/04/2019
Heat Detector	Building B Classroom B5	Tested	5:22:24 PM	09/04/2019
Heat Detector	Building B Classroom B6 Storage	Tested	5:23:29 PM	09/04/2019
Heat Detector	Building B FAU Closet Classroom B1	Tested	5:18:11 PM	09/04/2019
Heat Detector	Building B FAU Closet Classroom B1	Tested	5:20:58 PM	09/04/2019
Heat Detector	Building B FAU Closet Classroom B3	Tested	5:21:08 PM	09/04/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	Building B FAU Closet Classroom B3	Tested	5:21:47 PM	09/04/2019
Heat Detector	Building B FAU Closet Classroom B5	Tested	5:21:52 PM	09/04/2019
Heat Detector	Building B FAU Closet Classroom B5	Tested	5:22:34 PM	09/04/2019
Heat Detector	Building B FAU Closet Classroom B6	Tested	5:22:43 PM	09/04/2019
Heat Detector	Building B KILN Room B8	Tested	5:23:45 PM	09/04/2019
Heat Detector	Building C Classroom C1	Tested	5:25:19 PM	09/04/2019
Heat Detector	Building C Classroom C2	Tested	5:25:57 PM	09/04/2019
Heat Detector	Building C Classroom C3	Tested	5:26:26 PM	09/04/2019
Heat Detector	Building C Classroom C4	Tested	5:27:38 PM	09/04/2019
Heat Detector	Building C FAU Closet Classroom C1	Tested	5:24:28 PM	09/04/2019
Heat Detector	Building C FAU Closet Classroom C2	Tested	5:25:39 PM	09/04/2019
Heat Detector	Building C FAU Closet Classroom C3	Tested	5:26:12 PM	09/04/2019
Heat Detector	Building C FAU Closet Classroom C4	Tested	5:27:21 PM	09/04/2019
Heat Detector	Building D Classroom D1	Tested	5:27:48 PM	09/04/2019
Heat Detector	Building D Classroom D2	Tested	5:28:39 PM	09/04/2019
Heat Detector	Building D Classroom D3	Tested	5:28:49 PM	09/04/2019
Heat Detector	Building D Classroom D4	Tested	5:30:08 PM	09/04/2019
Heat Detector	Building D FAU Closet Classroom D1	Tested	5:28:06 PM	09/04/2019
Heat Detector	Building D FAU Closet Classroom D3	Tested	5:29:52 PM	09/04/2019
Heat Detector	Building G Kitchen	Tested	5:31:40 PM	09/04/2019
Heat Detector	Building G Multipurpose Room	Tested	5:30:20 PM	09/04/2019
Heat Detector	Building G Multipurpose Room	Tested	5:30:42 PM	09/04/2019
Heat Detector	Building G Storage	Tested	5:31:54 PM	09/04/2019
Smoke Detector	Building A Admin Reception A16	Tested	4:05:22 PM	09/04/2019
Smoke Detector	Building A Classroom A1	Tested	4:15:10 PM	09/04/2019
Smoke Detector	Building A Classroom A1	Tested	4:15:42 PM	09/04/2019
Smoke Detector	Building A Classroom A2	Tested	4:16:16 PM	09/04/2019
Smoke Detector	Building A Electrical Room A20	Tested	3:30:47 PM	09/04/2019
Smoke Detector	Building A Nurse A3	Tested	4:14:33 PM	09/04/2019
Smoke Detector	Building A Office Manager A18	Tested	4:05:47 PM	09/04/2019
Smoke Detector	Building A Office Room A16	Tested	4:07:19 PM	09/04/2019
Smoke Detector	Building A Principal's Office A6	Tested	4:12:20 PM	09/04/2019
Smoke Detector	Building A Principal's/VP Workroom A4/A6	Tested	4:12:54 PM	09/04/2019
Smoke Detector	Building A Principal's/VP Workroom A4/A6	Tested	4:13:44 PM	09/04/2019
Smoke Detector	Building A Restroom A11	Tested	4:08:04 PM	09/04/2019
Smoke Detector	Building A Staff Lounge A13	Tested	4:09:52 PM	09/04/2019
Smoke Detector	Building A Staff Lounge Restroom A13	Tested	4:10:25 PM	09/04/2019
Smoke Detector	Building A Staff Lounge Restroom A13	Tested	4:10:48 PM	09/04/2019
Smoke Detector	Building A Staff Workroom A14	Tested	4:08:24 PM	09/04/2019
Smoke Detector	Building A Staff Workroom A14	Tested	4:09:01 PM	09/04/2019
Smoke Detector	Building A Storage Room A17	Tested	4:06:54 PM	09/04/2019
Smoke Detector	Building A Storage Room A19	Tested	4:06:25 PM	09/04/2019
Smoke Detector	Building A Vice Principal's Office A4	Tested	4:13:56 PM	09/04/2019
Smoke Detector	Building B Classroom B1	Tested	4:17:29 PM	09/04/2019
Smoke Detector	Building B Classroom B3	Tested	4:19:53 PM	09/04/2019
Smoke Detector	Building B Classroom B4	Tested	4:20:20 PM	09/04/2019
Smoke Detector	Building B Classroom B5	Tested	4:20:50 PM	09/04/2019
Smoke Detector	Building B Classroom B5	Tested	4:21:36 PM	09/04/2019
Smoke Detector	Building B Classroom B6	Tested	4:22:13 PM	09/04/2019
Smoke Detector	Building B Classroom B6	Tested	4:22:25 PM	09/04/2019

Device Type	Location	Service	Time	Date			
Passed							
Smoke Detector	Building B Classroom B6 Storage	Tested	4:25:30 PM	09/04/2019			
Smoke Detector	Building B Classroom B7	Tested	4:25:55 PM	09/04/2019			
Smoke Detector	Building B Conference/Copy Room B2	Tested	4:18:13 PM	09/04/2019			
Smoke Detector	Building B Custodian Room B10	Tested	4:27:40 PM	09/04/2019			
Smoke Detector	Building B Electrical Room B11	Tested	4:29:11 PM	09/04/2019			
Smoke Detector	Building B Electrical Room B9	Tested	4:28:23 PM	09/04/2019			
Smoke Detector	Building C Boy's Restroom C5	Tested	4:36:46 PM	09/04/2019			
Smoke Detector	Building C Classroom C1	Tested	4:31:43 PM	09/04/2019			
Smoke Detector	Building C Classroom C1	Tested	4:32:50 PM	09/04/2019			
Smoke Detector	Building C Classroom C2	Tested	4:33:00 PM	09/04/2019			
Smoke Detector	Building C Classroom C2	Tested	4:33:19 PM	09/04/2019			
Smoke Detector	Building C Classroom C3	Tested	4:33:33 PM	09/04/2019			
Smoke Detector	Building C Classroom C3	Tested	4:33:46 PM	09/04/2019			
Smoke Detector	Building C Classroom C4	Tested	4:34:36 PM	09/04/2019			
Smoke Detector	Building C Classroom C4	Tested	4:35:26 PM	09/04/2019			
Smoke Detector	Building C Electrical Room C8	Tested	4:42:26 PM	09/04/2019			
Smoke Detector	Building C PE Equipment Room C6	Tested	4:38:43 PM	09/04/2019			
Smoke Detector	Building C Storage Room C7	Tested	4:39:17 PM	09/04/2019			
Smoke Detector	Building D Classroom D1	Tested	4:47:25 PM	09/04/2019			
Smoke Detector	Building D Classroom D1	Tested	4:48:07 PM	09/04/2019			
Smoke Detector	Building D Classroom D2	Tested	4:48:48 PM	09/04/2019			
Smoke Detector	Building D Classroom D2	Tested	4:48:59 PM	09/04/2019			
Smoke Detector	Building D Classroom D3	Tested	4:50:07 PM	09/04/2019			
Smoke Detector	Building D Classroom D3	Tested	4:50:36 PM	09/04/2019			
Smoke Detector	Building D Classroom D4	Tested	4:51:18 PM	09/04/2019			
Smoke Detector	Building D Classroom D4	Tested	4:51:46 PM	09/04/2019			
Smoke Detector	Building D Custodian D6	Tested	4:54:37 PM	09/04/2019			
Smoke Detector	Building D Electrical Room D7	Tested	4:55:43 PM	09/04/2019			
Smoke Detector	Building D Girl's Restroom D5	Tested	4:52:34 PM	09/04/2019			
Smoke Detector	Building D Girl's Restroom D5	Tested	4:54:18 PM	09/04/2019			
Smoke Detector	Building G Kitchen Office	Tested	5:49:29 PM	09/04/2019			
Smoke Detector	Building G MPR Corridor	Tested	5:53:51 PM	09/04/2019			
Smoke Detector	Building G MPR Main Auditorium	Tested	5:56:03 PM	09/04/2019			
Smoke Detector	Building G MPR Main Auditorium	Tested	5:56:23 PM	09/04/2019			
Smoke Detector	Building G MPR Main Auditorium	Tested	5:56:28 PM	09/04/2019			
Smoke Detector	Building G MPR Main Auditorium	Tested	5:56:33 PM	09/04/2019			
Smoke Detector	Building G MPR Main Auditorium	Tested	5:56:40 PM	09/04/2019			
Smoke Detector	Building G MPR Main Auditorium	Tested	5:56:44 PM	09/04/2019			
Smoke Detector	Building G MPR Outside Staff Restroom	Tested	5:57:07 PM	09/04/2019			
Smoke Detector	Building G MPR Stage	Tested	6:02:23 PM	09/04/2019			
Smoke Detector	Building G MPR Stage	Tested	6:02:59 PM	09/04/2019			
Smoke Detector	Building G MPR Stage Storage	Tested	6:03:10 PM	09/04/2019			
Smoke Detector	Building G MPR Storage Room	Tested	5:55:13 PM	09/04/2019			

Building: NMUSD - Back Bay Monte Vista Control Panel: 2 - Silent Knight 5808

Device Type	Location	Service	Time	Date			
Passed							
Control							
Battery	Portable Building E Administration Back Office	Tested	5:12:15 PM	09/04/2019			
Battery	Portable Building E Administration Back Office	Tested	5:12:28 PM	09/04/2019			
Control Panel	Portable Building E Administration Back Office	Tested	5:10:46 PM	09/04/2019			
Initiating							
Pull Station	Building A Admin Reception A16	Tested	6:01:46 PM	09/04/2019			
Pull Station	Building G MPR Corridor	Tested	5:54:24 PM	09/04/2019			
Pull Station	Building G MPR Exit	Tested	5:59:03 PM	09/04/2019			
Pull Station	Building G MPR Exit	Tested	6:00:33 PM	09/04/2019			
Pull Station	Portable Building E Administration Entrance	Tested	5:23:46 PM	09/04/2019			
Smoke Detector	Portable Building E Administration Back Office	Tested	5:14:31 PM	09/04/2019			
Smoke Detector	Portable Building E Administration Back Office	Tested	5:15:39 PM	09/04/2019			
Smoke Detector	Portable Building E Administration Back Office	Tested	5:18:41 PM	09/04/2019			
Smoke Detector	Portable Building E Administration Corridor	Tested	5:20:07 PM	09/04/2019			
Smoke Detector	Portable Building E Administration Entrance	Tested	5:22:25 PM	09/04/2019			
Smoke Detector	Portable Building E Administration Office	Tested	5:20:38 PM	09/04/2019			
Smoke Detector	Portable Building E Administration Office	Tested	5:21:00 PM	09/04/2019			
Smoke Detector	Portable Building E Administration Office	Tested	5:22:18 PM	09/04/2019			
Smoke Detector	Portable Building E Classroom E1	Tested	5:24:53 PM	09/04/2019			
Smoke Detector	Portable Building E Classroom E1	Tested	5:25:51 PM	09/04/2019			
Smoke Detector	Portable Building E Classroom E2	Tested	5:26:19 PM	09/04/2019			
Smoke Detector	Portable Building E Classroom E2	Tested	5:26:46 PM	09/04/2019			
Smoke Detector	Portable Building E Classroom E3	Tested	5:27:14 PM	09/04/2019			
Smoke Detector	Portable Building E Classroom E3	Tested	5:28:07 PM	09/04/2019			
Smoke Detector	Portable Building E Classroom E4	Tested	5:29:35 PM	09/04/2019			
Smoke Detector	Portable Building E Classroom E4	Tested	5:30:16 PM	09/04/2019			
Smoke Detector	Portable Building E Classroom E5	Tested	5:31:05 PM	09/04/2019			
Smoke Detector	Portable Building E Classroom E5	Tested	5:31:17 PM	09/04/2019			

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Back Bay Monte Vista

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity				
Passed						
Annunciator	Inspected	3				
Battery	Tested	12				
Control Panel	Tested	2				
Heat Detector	Tested	42				
Power Supply	Inspected	4				
Pull Station	Tested	5				
Smoke Detector	Tested	88				
Total		156				

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - Back Bay Monte Vista

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

			Ambient	Alarm	Intelligibility		Sound
C Location	🗨 Co	omment	◀ dB	◀ dB	Voice	STI	Test
		Passed					
Sound Test Points							
Entire Campus	Passed						0001

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Back Bay Monte Vista

Control Panel: 1 - Simplex 4100U

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

		_			_				
Device or Type		Category	%	of Inventory	C	Juantity			
Control Panel		Control		1.27%		2			
Battery		Control		7.64%		12			
Smoke Detector		Initiating		56.05%		88			
Annunciator		Control		1.91%		3			
Power Supply		Control		2.55%		4			
Heat Detector		Initiating		26.75%		42			
Pull Station		Initiating		3.18%		5			
Sound Test		Sound Test		0.64%		1			
	Qt								
Туре	y	Model #	Description			Install Date			
	New (under 90 days)								
Silent Knight									
Annunciator	2					09/04/2019			
Simplex						,,			
Annunciator	1					09/04/2019			
Control Panel	1	4100U				09/04/2019			
Power Supply	4	4099				09/04/2019			
Smoke Detector	70	4098-9714	Photoelectric			09/04/2019			
SimplexGrinnell	10	1050 5711	motociccure			03/01/2013			
Heat Detector	42	4098-9403	Fixed Temperat	ture		09/04/2019			
		In Service	- 2 Years to	o 3 Years					
Battery	2	12V18AH	Sealed Lead Aci	id		08/03/2017			
Battery	8	12V7AH	Sealed Lead Aci	id		08/03/2017			
Building: NMUSD Vista	- Ba	ack Bay Monte		Control Panel: 2	2 - Silent				
The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.									
	Qt								
Туре	у	Model #	Description			Install Date			
	New (under 90 days)								
Silent Knight									
Control Panel	1	5808				09/04/2019			

In Service - 2 Years to 3 Years

Battery	2	12V18AH	Sealed Lead Acid	08/03/2017
Silent Knight				
Pull Station	5	SD500-PS	Single Action	08/03/2017
Smoke Detector	18	SD505-APS	Photoelectric	08/03/2017

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - BESST Center 2045 Meyer Place Costa Mesa, CA 92627

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Sep 27, 2019

> Building: NMUSD - BESST Center Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Beeri Martinez Title: Technician

Executive Summary

Generated by: BuildingReports.com

Building Information		
Building: NMUSD – BESST Center	Contact: Tim Waller	
Address: 2045 Meyer Place	Phone: 7142310363	
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92627	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Beeri Marti	nez
Address: 2903 Saturn Street	Phone: 714-9131310	00
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: beerimartinez	@calbuildingsystems.com
System Control Unit		
Manufacturer: Silent Knight	Inspection Date: 09/2	27/2019 IDC Style:
Model Number: IFP-1000	Install Date: 09/27/2	019 SLC Style:
Software Version:	Version Date: 09/27/	2019 NAC Style:
Location: Portables MDF/FACP Room Behind Soy Program Room 108	Current Protection: B	reaker
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
	Total	ltems	Ser	viced	Pas	ssed	Failed	/Other
Category	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.99%	1	100.00%	1	100.00%	0	0%
Control	16	15.84%	16	100.00%	16	100.00%	0	0%
Initiating	84	83.17%	84	100.00%	84	100.00%	0	0%
Totals	101	100%	101	100.00%	101	100.00%	0	0%
Certification								
Company: Cal Building Systems			Bu	ilding: NML	JSD – BES	ST Center		
Inspector: Beeri Martinez			Co	ontact: Tim	Waller			
Signed:			Sig	gned:				

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - BESST Center

Control Panel: 1 - Silent Knight IFP-1000

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Portables Health Services	Tested	4:21:39 PM	09/27/2019
Battery	Portables Classroom 117 Soy	Tested	5:45:15 PM	09/27/2019
Battery	Portables Classroom 117 Soy	Tested	5:45:26 PM	09/27/2019
Battery	Portables Classroom 125	Tested	5:07:27 PM	09/27/2019
Battery	Portables Classroom 125	Tested	5:07:35 PM	09/27/2019
Battery	Portables Classroom 127	Tested	5:00:58 PM	09/27/2019
Battery	Portables Classroom 127	Tested	5:01:14 PM	09/27/2019
Battery	Portables MDF/FACP Room Behind Soy Program Room 108	Tested	3:53:10 PM	09/27/2019
Battery	Portables MDF/FACP Room Behind Soy Program Room 108	Tested	3:53:52 PM	09/27/2019
Battery	Portables Hope Clinic Office 208 Storage	Tested	4:41:34 PM	09/27/2019
Battery	Portables Hope Clinic Office 208 Storage	Tested	4:42:10 PM	09/27/2019
Control Panel	Portables MDF/FACP Room Behind Soy Program Room 108	Tested	3:51:43 PM	09/27/2019
Power Supply	Portables Classroom 117 Soy	Tested	5:44:55 PM	09/27/2019
Power Supply	Portables Classroom 125	Tested	5:07:13 PM	09/27/2019
Power Supply	Portables Classroom 127	Tested	5:00:37 PM	09/27/2019
Power Supply	Portables Hope Clinic Office 208 Storage	Tested	4:41:22 PM	09/27/2019
Initiating				
Smoke Detector	Portables Classroom 110	Tested	5:23:41 PM	09/27/2019
Smoke Detector	Portables Classroom 110B	Tested	5:23:52 PM	09/27/2019
Smoke Detector	Portables Classroom 110C	Tested	5:24:03 PM	09/27/2019
Smoke Detector	Portables Classroom 111	Tested	5:25:37 PM	09/27/2019
Smoke Detector	Portables Classroom 111	Tested	5:25:51 PM	09/27/2019
Smoke Detector	Portables Classroom 112	Tested	5:27:02 PM	09/27/2019
Smoke Detector	Portables Classroom 112	Tested	5:27:09 PM	09/27/2019
Smoke Detector	Portables Classroom 113	Tested	5:33:04 PM	09/27/2019
Smoke Detector	Portables Classroom 113	Tested	5:33:12 PM	09/27/2019
Smoke Detector	Portables Classroom 114	Tested	5:33:16 PM	09/27/2019
Smoke Detector	Portables Classroom 114	Tested	5:33:23 PM	09/27/2019
Smoke Detector	Portables Classroom 115 Soy	Tested	5:33:28 PM	09/27/2019
Smoke Detector	Portables Classroom 115 Soy	Tested	5:33:38 PM	09/27/2019
Smoke Detector	Portables Classroom 116 Soy	Tested	5:33:44 PM	09/27/2019
Smoke Detector	Portables Classroom 116 Soy	Tested	5:33:52 PM	09/27/2019
Smoke Detector	Portables Classroom 117 Soy	Tested	5:33:55 PM	09/27/2019
Smoke Detector	Portables Classroom 117 Soy	Tested	5:34:02 PM	09/27/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Portables Classroom 118	Tested	5:10:32 PM	09/27/2019
Smoke Detector	Portables Classroom 118	Tested	5:10:39 PM	09/27/2019
Smoke Detector	Portables Classroom 119	Tested	5:10:22 PM	09/27/2019
Smoke Detector	Portables Classroom 119	Tested	5:10:29 PM	09/27/2019
Smoke Detector	Portables Classroom 120	Tested	5:09:48 PM	09/27/2019
Smoke Detector	Portables Classroom 120	Tested	5:09:57 PM	09/27/2019
Smoke Detector	Portables Classroom 121	Tested	5:10:01 PM	09/27/2019
Smoke Detector	Portables Classroom 121	Tested	5:10:08 PM	09/27/2019
Smoke Detector	Portables Classroom 122	Tested	5:10:12 PM	09/27/2019
Smoke Detector	Portables Classroom 122	Tested	5:10:18 PM	09/27/2019
Smoke Detector	Portables Classroom 123	Tested	5:02:04 PM	09/27/2019
Smoke Detector	Portables Classroom 123	Tested	5:02:11 PM	09/27/2019
Smoke Detector	Portables Classroom 124	Tested	5:02:48 PM	09/27/2019
Smoke Detector	Portables Classroom 124	Tested	5:02:57 PM	09/27/2019
Smoke Detector	Portables Classroom 125	Tested	5:05:27 PM	09/27/2019
Smoke Detector	Portables Classroom 125	Tested	5:05:34 PM	09/27/2019
Smoke Detector	Portables Classroom 126	Tested	4:54:59 PM	09/27/2019
Smoke Detector	Portables Classroom 126	Tested	4:55:13 PM	09/27/2019
Smoke Detector	Portables Classroom 127	Tested	4:58:29 PM	09/27/2019
Smoke Detector	Portables Classroom 127	Tested	4:58:40 PM	09/27/2019
Smoke Detector	Portables Custodial Closet Next To Classroom 127	Tested	4:49:42 PM	09/27/2019
Smoke Detector	Portables Janitor Closet Behind Soy Program	Tested	5:56:13 PM	09/27/2019
Smoke Detector	Portables MDF/FACP Room Behind Soy Program Room 108	Tested	3:55:43 PM	09/27/2019
Smoke Detector	Portables Men's Restroom Next To Classroom 112	Tested	5:29:34 PM	09/27/2019
Smoke Detector	Portables Men's Restroom Next To Classroom 118	Tested	5:18:51 PM	09/27/2019
Smoke Detector	Portables Soy Program Lounge	Tested	5:51:25 PM	09/27/2019
Smoke Detector	Portables Soy Program Lounge	Tested	5:51:37 PM	09/27/2019
Smoke Detector	Portables Soy Program Lounge	Tested	5:51:40 PM	09/27/2019
Smoke Detector	Portables Soy Program Lounge	Tested	5:51:44 PM	09/27/2019
Smoke Detector	Portables Soy Program Lounge	Tested	5:51:56 PM	09/27/2019
Smoke Detector	Portables Soy Program Lounge Storage	Tested	5:53:40 PM	09/27/2019
Smoke Detector	Portables Soy Program Office	Tested	5:50:09 PM	09/27/2019
Smoke Detector	Portables Soy Program Staff Restroom	Tested	5:54:52 PM	09/27/2019
Smoke Detector	Portables Soy Program	Tested	5:49:03 PM	09/27/2019
Smoke Detector	Portables Soy Program	Tested	5:50:05 PM	09/27/2019
Smoke Detector	Portables Staff Restroom Next To Classroom 112	Tested	5:29:45 PM	09/27/2019
Smoke Detector	Portables Staff Restroom Next To Classroom 118	Tested	5:18:39 PM	09/27/2019
Smoke Detector	Portables Women's Restroom Next To Classroom 112	Tested	5:30:00 PM	09/27/2019
Smoke Detector	Portables Women's Restroom Next To Classroom 118	Tested	5:18:12 PM	09/27/2019
Smoke Detector	Portables Health Services Break Room	Tested	4:10:49 PM	09/27/2019
Smoke Detector	Portables Health Services Office	Tested	4:10:39 PM	09/27/2019
Smoke Detector	Portables Health Services	Tested	4:08:47 PM	09/27/2019

Device Type	Location	Service	Time	Date					
Passed									
Smoke Detector	Portables Health Services	Tested	4:09:55 PM	09/27/2019					
Smoke Detector	Portables Hope Clinic Corridor By Office 202	Tested	4:32:19 PM	09/27/2019					
Smoke Detector	Portables Hope Clinic Corridor By Office 205	Tested	4:35:23 PM	09/27/2019					
Smoke Detector	Portables Hope Clinic Employees Only Office	Tested	4:24:31 PM	09/27/2019					
Smoke Detector	Portables Hope Clinic Office 201	Tested	4:31:24 PM	09/27/2019					
Smoke Detector	Portables Hope Clinic Office 202	Tested	4:32:07 PM	09/27/2019					
Smoke Detector	Portables Hope Clinic Office 203	Tested	4:33:25 PM	09/27/2019					
Smoke Detector	Portables Hope Clinic Office 204	Tested	4:34:43 PM	09/27/2019					
Smoke Detector	Portables Hope Clinic Office 205	Tested	4:35:05 PM	09/27/2019					
Smoke Detector	Portables Hope Clinic Office 206	Tested	4:35:40 PM	09/27/2019					
Smoke Detector	Portables Hope Clinic Office 207	Tested	4:35:50 PM	09/27/2019					
Smoke Detector	Portables Hope Clinic Office 208 Storage	Tested	4:42:15 PM	09/27/2019					
Smoke Detector	Portables Hope Clinic Office 208	Tested	4:34:57 PM	09/27/2019					
Smoke Detector	Portables Hope Clinic Office 209	Tested	4:30:24 PM	09/27/2019					
Smoke Detector	Portables Hope Clinic Office 210	Tested	4:26:37 PM	09/27/2019					
Smoke Detector	Portables Hope Clinic Office A	Tested	4:27:58 PM	09/27/2019					
Smoke Detector	Portables Hope Clinic Office B	Tested	4:27:51 PM	09/27/2019					
Smoke Detector	Portables Hope Clinic Outside Storage	Tested	4:45:19 PM	09/27/2019					
Smoke Detector	Portables Hope Clinic Outside Storage	Tested	4:46:23 PM	09/27/2019					
Smoke Detector	Portables Hope Clinic Restroom	Tested	4:34:07 PM	09/27/2019					
Smoke Detector	Portables Hope Clinic Storage Next To Office B	Tested	4:29:03 PM	09/27/2019					
Smoke Detector	Portables Hope Clinic	Tested	4:22:47 PM	09/27/2019					
Smoke Detector	Portables Hope Clinic	Tested	4:23:11 PM	09/27/2019					
Smoke Detector	Portables Men's Restroom Next To Classroom 127	Tested	4:48:34 PM	09/27/2019					
Smoke Detector	Portables Women's Restroom Next To Classroom 127	Tested	4:50:43 PM	09/27/2019					

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - BESST Center

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Annunciator	Tested	1
Battery	Tested	10
Control Panel	Tested	1
Power Supply	Tested	4
Smoke Detector	Tested	84
Total		100

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - BESST Center

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

		Ambient	Alarm	🦻 Intell	igibility	Sound
🗘 Location	 Comment 	◀ dB	◀ dB	Voice	STI	Test
	Passed	!				
Sound Test Points						
Entire Campus	Passed					0001

Inventory & Warranty Report Generated by: BuildingReports.com

Building: NMUS	D - BE	ESST Center	Control Panel: 1 - S	ilent Knight IFP-1000
complete inventory cour	t by devid	ce type and category	vices and items that are included in you v is provided. Items installed within the grouped together for easy reference.	
Device or Type		Category	% of Inventory	Quantity
Control Panel		Control	0.99%	1
Battery		Control	9.90%	10
Smoke Detector		Initiating	83.17%	84
Annunciator		Control	0.99%	1
Power Supply		Control	3.96%	4
Sound Test		Sound Test	0.99%	1
	Qt			
Туре	y	Model #	Description	Install Date
		New	(under 90 days)	
Silent Knight				
Control Panel	1	IFP-1000		09/27/2019
		In Servic	e - 3 Years to 5 Years	
Battery	2	12v 18ah	Sealed Lead Acid	10/01/2016
Battery	8	12v 7ah	Sealed Lead Acid	10/01/2016
Silent Knight				
Annunciator	1	SD505-PHOTO		10/01/2016
Power Supply	4	RPS-1000		10/01/2016
Smoke Detector	84	SD505-PHOTO	Photoelectric	10/01/2016

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - California Elementary 3232 California Street Costa Mesa, CA 92626

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Aug 13, 2019

> Building: NMUSD - California Elementary Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Michael Cannon Title: Service Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD - California Elementary	Contact: Tim Waller	
Address: 3232 California Street	Phone: 714-231-2420	
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92626	Mobile:	
Country: United States of America	Email: twaller@nmusd.us	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Michael Cannon	
Address: 2903 Saturn Street	Phone: 714-715-1223	
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: mcannon@calbuildingsyste	ems.com
System Control Unit		
Manufacturer: Silent Knight	Inspection Date: 08/13/2019	IDC Style:
Model Number: IFP-1000	Install Date: 08/13/2019	SLC Style:
Software Version:	Version Date: 08/13/2019	NAC Style:
Location: Admin Building FACP/MDF Room inside Nurse's Office	Current Protection:	
Monitoring		
Company: AceTec Pho	one: 1-800-634-3915 Accour	nt #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Catagoria	Total	ltems	Sen	/iced	Pas	ssed	Failed	/Other
Category	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.66%	1	100.00%	1	100.00%	0	0%
Control	25	16.56%	25	100.00%	25	100.00%	0	0%
Initiating	125	82.78%	125	100.00%	124	99.20%	1	0.80%
Totals	151	100%	151	100.00%	150	99.34%	1	0.66%
Certification								
Company: Cal Building Systems			Bu	ilding: NML	JSD – Cali	fornia Elem	entary	
Inspector: Michael Cannon			Co	ntact: Tim	Waller			
The amor								
Signed: Aug 13, 2019 3:33:47	' PM		Sig	jned:				

Discrepancy Report Generated by: BuildingReports.com

Building: NMUSD - California Elementary Control Panel: 1 - Si IFP-1000				el: 1 - Silei	nt Knigl	nt
The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.						
Device Type		Manufacturer	ModelNumber	Da	te	Qty
Items listed for Recall by Manufacturer						
No recalled items found during this inspection.						
8 ScanID	C3 Location		Problem	Address	🛄 Refe	erence
Initiating						
Duct Detector						
61336489	MPR Custodian	Room	Failed to Report	1	NFPA72	4.2.1.2.2
Code References						
NFPA72 14.2.1.2	NFPA72 14.2.1.2.2 System defects and malfunctions shall be corrected.					

Proposed Solutions Report

Generated by: BuildingReports.com

Building: NMUSD - California Control Panel: 1 - Silent Knight IFP-1000 Elementary The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis. ScanID Solution Model # Fix Location Cost Initiating **Duct Detector** 61336489 MPR Custodian Room D4120 T/MSee notes/recommenda tions PO #: (none) T/M

Notes & Recommendations

Generated by: BuildingReports.com

Building: NMUSD - California Elementary		Control Panel: 1 - Silent IFP-1000	Knight		
The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.					
ScanID	Note	Device Type	Location		Comment
ScanID	Note		Location		Comment
ScanID 61336489	Note				Comment Failed to Report

was performed multiple times, failing to report to the panel.

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - California Elementary

Control Panel: 1 - Silent Knight IFP-1000

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Battery Battery Battery Battery Battery Battery Battery Battery Battery	Passed Admin Building Entrance to Staff Lounge Admin Building FACP/MDF Room inside Nurse's Office Admin Building FACP/MDF Room inside Nurse's Office Classroom 8 Classroom 8 Custodian Office next to MPR Custodian Office next to MPR IDF Closet Behind Classroom 15 IDF Closet Behind Classroom 15 IDF Closet Behind Classroom 20 IDF Closet Behind Classroom 20	Tested Tested Tested Tested Tested Tested Tested Tested Tested Tested Tested Tested	8:23:44 AM 7:47:24 AM 7:48:19 AM 10:43:29 AM 10:44:27 AM 9:08:03 AM 9:08:33 AM 9:54:30 AM 9:55:00 AM	08/13/2019 08/13/2019 08/13/2019 08/13/2019 08/13/2019 08/13/2019 08/13/2019 08/13/2019 08/13/2019
Annunciator Battery Battery Battery Battery Battery Battery Battery Battery Battery Battery Battery	Admin Building FACP/MDF Room inside Nurse's Office Admin Building FACP/MDF Room inside Nurse's Office Classroom 8 Classroom 8 Custodian Office next to MPR Custodian Office next to MPR IDF Closet Behind Classroom 15 IDF Closet Behind Classroom 15 IDF Closet Behind Classroom 20	Tested Tested Tested Tested Tested Tested Tested Tested	7:47:24 AM 7:48:19 AM 10:43:29 AM 10:44:27 AM 9:08:03 AM 9:08:33 AM 9:54:30 AM 9:55:00 AM	08/13/2019 08/13/2019 08/13/2019 08/13/2019 08/13/2019 08/13/2019 08/13/2019
Battery Battery Battery Battery Battery Battery Battery Battery Battery	Admin Building FACP/MDF Room inside Nurse's Office Admin Building FACP/MDF Room inside Nurse's Office Classroom 8 Classroom 8 Custodian Office next to MPR Custodian Office next to MPR IDF Closet Behind Classroom 15 IDF Closet Behind Classroom 15 IDF Closet Behind Classroom 20	Tested Tested Tested Tested Tested Tested Tested Tested	7:47:24 AM 7:48:19 AM 10:43:29 AM 10:44:27 AM 9:08:03 AM 9:08:33 AM 9:54:30 AM 9:55:00 AM	08/13/2019 08/13/2019 08/13/2019 08/13/2019 08/13/2019 08/13/2019 08/13/2019
Battery Battery Battery Battery Battery Battery Battery	Office Admin Building FACP/MDF Room inside Nurse's Office Classroom 8 Classroom 8 Custodian Office next to MPR Custodian Office next to MPR IDF Closet Behind Classroom 15 IDF Closet Behind Classroom 15 IDF Closet Behind Classroom 20	Tested Tested Tested Tested Tested Tested Tested	7:48:19 AM 10:43:29 AM 10:44:27 AM 9:08:03 AM 9:08:33 AM 9:54:30 AM 9:55:00 AM	08/13/2019 08/13/2019 08/13/2019 08/13/2019 08/13/2019 08/13/2019
Battery Battery Battery Battery Battery Battery Battery	Office Classroom 8 Classroom 8 Custodian Office next to MPR Custodian Office next to MPR IDF Closet Behind Classroom 15 IDF Closet Behind Classroom 15 IDF Closet Behind Classroom 20	Tested Tested Tested Tested Tested Tested	10:43:29 AM 10:44:27 AM 9:08:03 AM 9:08:33 AM 9:54:30 AM 9:55:00 AM	08/13/2019 08/13/2019 08/13/2019 08/13/2019 08/13/2019
Battery Battery Battery Battery Battery Battery	Classroom 8 Custodian Office next to MPR Custodian Office next to MPR IDF Closet Behind Classroom 15 IDF Closet Behind Classroom 15 IDF Closet Behind Classroom 20	Tested Tested Tested Tested Tested	10:44:27 AM 9:08:03 AM 9:08:33 AM 9:54:30 AM 9:55:00 AM	08/13/2019 08/13/2019 08/13/2019 08/13/2019
Battery Battery Battery Battery Battery	Custodian Office next to MPR Custodian Office next to MPR IDF Closet Behind Classroom 15 IDF Closet Behind Classroom 15 IDF Closet Behind Classroom 20	Tested Tested Tested Tested	9:08:03 AM 9:08:33 AM 9:54:30 AM 9:55:00 AM	08/13/2019 08/13/2019 08/13/2019
Battery Battery Battery Battery	Custodian Office next to MPR IDF Closet Behind Classroom 15 IDF Closet Behind Classroom 15 IDF Closet Behind Classroom 20	Tested Tested Tested	9:08:33 AM 9:54:30 AM 9:55:00 AM	08/13/2019 08/13/2019
Battery Battery Battery	IDF Closet Behind Classroom 15 IDF Closet Behind Classroom 15 IDF Closet Behind Classroom 20	Tested Tested	9:54:30 AM 9:55:00 AM	08/13/2019
Battery Battery	IDF Closet Behind Classroom 15 IDF Closet Behind Classroom 20	Tested	9:55:00 AM	
Battery	IDF Closet Behind Classroom 20			08/12/2010
		Tested	10.02.17	08/13/2019
Detter	IDF Closet Behind Classroom 20		10:03:17 AM	08/13/2019
Battery		Tested	10:03:56 AM	08/13/2019
Battery	IDF Closet Behind Classroom 5	Tested	10:16:34 AM	08/13/2019
Battery	IDF Closet Behind Classroom 5	Tested	10:16:48 AM	08/13/2019
Battery	Office Next To Classroom 7	Tested	10:29:54 AM	08/13/2019
Battery	Office Next To Classroom 7	Tested	10:30:25 AM	08/13/2019
	Storage Room Behind Classrooms 1 And 2	Tested	11:18:57 AM	08/13/2019
	Storage Room Behind Classrooms 1 And 2	Tested	11:19:34 AM	08/13/2019
	Admin Building FACP/MDF Room inside Nurse's Office	Inspected	7:45:12 AM	08/13/2019
Power Supply	Classroom 8	Inspected	10:42:59 AM	08/13/2019
Power Supply	Custodian Office next to MPR	Tested	9:06:38 AM	08/13/2019
Power Supply	IDF Closet Behind Classroom 15	Inspected	9:54:09 AM	08/13/2019
Power Supply	IDF Closet Behind Classroom 20	Inspected	10:02:44 AM	08/13/2019
Power Supply	IDF Closet Behind Classroom 5	Inspected	10:15:45 AM	08/13/2019
Power Supply	Office Next To Classroom 7	Inspected	10:28:45 AM	08/13/2019
Power Supply	Storage Room Behind Classrooms 1 And 2	Inspected	11:20:03 AM	08/13/2019
Initiating				
Heat Detector	Admin Building Outside Unisex Restroom	Tested	9:28:15 AM	08/13/2019
	Admin Building Staff Lounge	Tested	8:20:01 AM	08/13/2019
	Admin Building Staff Lounge Restroom	Tested	8:24:56 AM	08/13/2019
	Classroom 1 & 2 Workroom Unisex Restroom	Tested	9:32:56 AM	08/13/2019
	Classroom 10	Tested	9:56:27 AM	08/13/2019
	Classroom 10	Tested	9:56:40 AM	08/13/2019
	Classroom 10	Tested	12:03:43 PM	08/13/2019
	Classroom 10	Tested	12:03:49 PM	08/13/2019

Cal Building Systems

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	Classroom 11	Tested	9:55:55 AM	08/13/2019
Heat Detector	Classroom 11	Tested	9:56:08 AM	08/13/2019
Heat Detector	Classroom 11	Tested	12:00:13 PM	08/13/2019
Heat Detector	Classroom 11	Tested	12:01:03 PM	08/13/2019
Heat Detector	Classroom 12	Tested	9:59:54 AM	08/13/2019
Heat Detector	Classroom 12	Tested	10:00:52 AM	08/13/2019
Heat Detector	Classroom 28	Tested	9:54:47 AM	08/13/2019
Heat Detector	Classroom 28	Tested	9:55:32 AM	08/13/2019
Heat Detector	Classroom 8	Tested	10:03:22 AM	08/13/2019
Heat Detector	Classroom 8	Tested	10:03:41 AM	08/13/2019
Heat Detector	Classroom 9	Tested	10:02:10 AM	08/13/2019
Heat Detector	Classroom 9	Tested	10:02:20 AM	08/13/2019
Heat Detector	Custodian Closet next to MPR	Tested	9:10:03 AM	08/13/2019
Heat Detector	Electrical Room Behind Classroom 16	Tested	9:57:07 AM	08/13/2019
Heat Detector	Electrical Room Behind Classroom 19	Tested	10:01:41 AM	08/13/2019
Heat Detector	Electrical Room Behind Classroom 3	Tested	10:18:27 AM	08/13/2019
Heat Detector	Electrical Room by Basketball Courts	Tested	9:03:43 AM	08/13/2019
Heat Detector	Kitchen MPR	Tested	9:19:50 AM	08/13/2019
Heat Detector	Outside Unisex Restroom by Classroom 7	Tested	9:39:38 AM	08/13/2019
Heat Detector	Storage Next to Girls Bathroom by Classroom 14	Tested	8:57:43 AM	08/13/2019
Heat Detector	Unisex Restroom next to Classroom 17	Tested	8:49:28 AM	08/13/2019
Pull Station	East MPR Exit	Tested	9:12:31 AM	08/13/2019
Pull Station	North MPR Exit	Tested	9:17:43 AM	08/13/2019
Pull Station	West MPR Exit	Tested	9:17:05 AM	08/13/2019
Pull Station	West Stage Exit MPR	Tested	9:23:06 AM	08/13/2019
Pull Station	Admin Building Entrance	Tested	8:14:51 AM	08/13/2019
Pull Station	Admin Building Entrance	Tested	8:24:39 AM	08/13/2019
Pull Station	Classroom 16 Library	Tested	8:38:59 AM	08/13/2019
Pull Station	Classroom 16 Library	Tested	8:39:53 AM	08/13/2019
Smoke Detector	East Corridor Exit MPR	Tested	9:14:24 AM	08/13/2019
Smoke Detector	North Admin Building Exit	Tested	8:16:52 AM	08/13/2019
Smoke Detector	Admin Building Entrance	Tested	8:16:07 AM	08/13/2019
Smoke Detector	Admin Building FACP/MDF Room inside Nurse's Office	Tested	9:53:32 AM	08/13/2019
Smoke Detector	Admin Building Nurses Office	Tested	8:09:31 AM	08/13/2019
Smoke Detector	Admin Building Nurses Office Restroom	Tested	8:12:43 AM	08/13/2019
Smoke Detector	Admin Building Outside Unisex Restroom	Tested	9:24:14 AM	08/13/2019
Smoke Detector	Admin Building Principals Office	Tested	8:26:39 AM	08/13/2019
Smoke Detector	Admin Building Staff Lounge	Tested	8:17:59 AM	08/13/2019
Smoke Detector	Admin Building Staff Lounge	Tested	8:21:20 AM	08/13/2019
Smoke Detector	Admin Building Staff Lounge Restroom	Tested	8:25:33 AM	08/13/2019
Smoke Detector	Boys Restroom next to Storage	Tested	9:01:37 AM	08/13/2019
Smoke Detector	Boys Restroom next to Unisex Restrooms	Tested	8:51:56 AM	08/13/2019
Smoke Detector	Cafeteria Office MPR	Tested	9:18:51 AM	08/13/2019
Smoke Detector	Classroom 1 Kids Restroom	Tested	9:31:09 AM	08/13/2019
Smoke Detector	Classroom 1	Tested	9:28:50 AM	08/13/2019
Smoke Detector	Classroom 1	Tested	9:29:52 AM	08/13/2019
Smoke Detector	Classroom 1 & 2 Workroom	Tested	9:31:50 AM	08/13/2019
Smoke Detector	Classroom 1 & 2 Workroom Unisex Restroom	Tested	9:32:25 AM	08/13/2019
				50, 10, 2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Classroom 10	Tested	9:46:57 AM	08/13/2019
Smoke Detector	Classroom 10	Tested	9:47:23 AM	08/13/2019
Smoke Detector	Classroom 11	Tested	9:48:15 AM	08/13/2019
Smoke Detector	Classroom 11	Tested	9:48:38 AM	08/13/2019
Smoke Detector	Classroom 12	Tested	9:58:23 AM	08/13/2019
Smoke Detector	Classroom 12	Tested	9:58:42 AM	08/13/2019
Smoke Detector	Classroom 13	Tested	8:41:20 AM	08/13/2019
Smoke Detector	Classroom 13	Tested	8:43:31 AM	08/13/2019
Smoke Detector	Classroom 14	Tested	8:44:34 AM	08/13/2019
Smoke Detector	Classroom 14	Tested	8:45:18 AM	08/13/2019
Smoke Detector	Classroom 15	Tested	8:35:08 AM	08/13/2019
Smoke Detector	Classroom 15	Tested	8:35:52 AM	08/13/2019
Smoke Detector	Classroom 16 Library	Tested	8:36:44 AM	08/13/2019
Smoke Detector	Classroom 16 Library	Tested	8:37:34 AM	08/13/2019
Smoke Detector	Classroom 16 Library	Tested	8:38:14 AM	08/13/2019
Smoke Detector	Classroom 16 Library	Tested	8:38:40 AM	08/13/2019
Smoke Detector	Classroom 17	Tested	8:45:35 AM	08/13/2019
Smoke Detector	Classroom 17	Tested	8:46:33 AM	08/13/2019
Smoke Detector	Classroom 18	Tested	8:54:05 AM	08/13/2019
Smoke Detector	Classroom 18	Tested	8:54:46 AM	08/13/2019
Smoke Detector	Classroom 19	Tested	8:33:10 AM	08/13/2019
Smoke Detector	Classroom 19	Tested	8:33:42 AM	08/13/2019
Smoke Detector	Classroom 2 Kids Restroom	Tested	9:33:41 AM	08/13/2019
Smoke Detector	Classroom 2	Tested	9:34:01 AM	08/13/2019
Smoke Detector	Classroom 2	Tested	9:34:46 AM	08/13/2019
Smoke Detector	Classroom 20	Tested	8:32:09 AM	08/13/2019
Smoke Detector	Classroom 20	Tested	8:32:32 AM	08/13/2019
Smoke Detector	Classroom 21	Tested	8:29:35 AM	08/13/2019
Smoke Detector	Classroom 21	Tested	8:30:46 AM	08/13/2019
Smoke Detector	Classroom 28	Tested	9:49:12 AM	08/13/2019
Smoke Detector	Classroom 28	Tested	9:49:26 AM	08/13/2019
Smoke Detector	Classroom 4	Tested	10:06:16 AM	08/13/2019
Smoke Detector	Classroom 4	Tested	10:06:57 AM	08/13/2019
Smoke Detector	Classroom 5	Tested	10:05:24 AM	08/13/2019
Smoke Detector	Classroom 5	Tested	10:05:54 AM	08/13/2019
Smoke Detector	Classroom 6	Tested	9:36:38 AM	08/13/2019
Smoke Detector	Classroom 6	Tested	9:36:50 AM	08/13/2019
Smoke Detector	Classroom 7	Tested	9:44:49 AM	08/13/2019
Smoke Detector	Classroom 7	Tested	9:46:27 AM	08/13/2019
Smoke Detector	Classroom 8	Tested	10:04:02 AM	08/13/2019
Smoke Detector	Classroom 8	Tested	10:04:20 AM	08/13/2019
Smoke Detector	Classroom 9	Tested	10:01:10 AM	08/13/2019
Smoke Detector	Classroom 9	Tested	10:01:24 AM	08/13/2019
Smoke Detector	Custodian Office next to MPR	Tested	9:09:01 AM	08/13/2019
Smoke Detector	Girls Restroom next to Classroom 14	Tested	8:56:00 AM	08/13/2019
Smoke Detector	Girls Restroom next to Classroom 17	Tested	8:51:21 AM	08/13/2019
Smoke Detector	IDF Closet Behind Classroom 15	Tested	9:52:47 AM	08/13/2019
Smoke Detector	IDF Closet Behind Classroom 20	Tested	10:04:40 AM	08/13/2019
Smoke Detector	IDF Closet Behind Classroom 5	Tested	10:14:46 AM	08/13/2019
Smoke Detector	IDF/Phone Room MPR	Tested	9:21:34 AM	08/13/2019
		resteu		56/15/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	MPR	Tested	9:15:20 AM	08/13/2019
Smoke Detector	MPR	Tested	9:15:42 AM	08/13/2019
Smoke Detector	MPR	Tested	9:15:50 AM	08/13/2019
Smoke Detector	MPR	Tested	9:15:58 AM	08/13/2019
Smoke Detector	Office by Classroom 7	Tested	9:44:02 AM	08/13/2019
Smoke Detector	Office next to Classroom 13	Tested	8:43:54 AM	08/13/2019
Smoke Detector	Office next to Classroom 18	Tested	8:53:02 AM	08/13/2019
Smoke Detector	Outside Boys Restroom by Classroom 7	Tested	9:40:22 AM	08/13/2019
Smoke Detector	Outside Girls Restroom by Classroom 7	Tested	9:37:57 AM	08/13/2019
Smoke Detector	Outside Unisex Restroom by Classroom 7	Tested	9:38:45 AM	08/13/2019
Smoke Detector	Outside Unisex Restroom by Classroom 7	Tested	9:39:14 AM	08/13/2019
Smoke Detector	Stage MPR	Tested	9:20:54 AM	08/13/2019
Smoke Detector	Stage MPR	Tested	9:22:20 AM	08/13/2019
Smoke Detector	Storage by Basketball Courts	Tested	9:04:47 AM	08/13/2019
Smoke Detector	Storage next to Boys Restroom	Tested	9:01:09 AM	08/13/2019
Smoke Detector	Storage Room Behind Classrooms 1 And 2	Tested	11:20:30 AM	08/13/2019
Smoke Detector	Unisex Restroom next to Classroom 17	Tested	8:48:36 AM	08/13/2019
Smoke Detector	Unisex Restroom next to Classroom 17	Tested	8:50:12 AM	08/13/2019
Device Type	Location	Service	Time	Date
	Failed/Other			
Initiating				
Duct Detector	MPR Custodian Room	Tested	1:29:37 PM	08/13/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - California Elementary

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Failed/Other	
Duct Detector	Tested	1
Total		1
	Passed	
Annunciator	Tested	1
Battery	Tested	16
Control Panel	Inspected	1
Heat Detector	Tested	29
Power Supply	Inspected	6
Power Supply	Tested	1
Pull Station	Tested	8
Smoke Detector	Tested	87
Total		150

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - California Elementary

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

		Ambient	Alarm	🦻 Intell	igibility	Sound
C Location	🗨 Commer	nt ◀ dB	◀ dB	Voice	STI	Test
Passed						
Sound Test Points						
Entire Campus	Passed					0001

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: NMUSD - California Elementary	Control Panel: 1 - Silent Knight IFP-1000

The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.

Туре	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
		Passe	ed				
Battery							
Sealed Lead Acid	Custodian Office next to MPR	7	12				
Sealed Lead Acid	Custodian Office next to MPR	7	12				

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - California Elementary

Control Panel: 1 - Silent Knight IFP-1000

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category	% of Inve	ntory	Quantity
Control Panel		Control		0.66%	1
Battery		Control	1	0.60%	16
Smoke Detector		Initiating	5	7.62%	87
Pull Station		Initiating		5.30%	8
Heat Detector		Initiating	1	9.21%	29
Annunciator		Control		0.66%	1
Power Supply		Control		4.64%	7
Duct Detector		Initiating		0.66%	1
Туре	Qty	Model #	Description		Install Date
		New	(under 90 days)		
12V7Ah					
Battery	2	12V7Ah	Sealed Lead Acid		08/13/2019
Silent Knight					
Annunciator	1		LCD Display		08/13/2019
Control Panel	1	IFP-1000			08/13/2019
Heat Detector	21	SD-505-AHS			08/13/2019
Heat Detector	1	SD-505-APS			08/13/2019
Power Supply	1	RPS- 1000			08/13/2019
Pull Station	8	SD-500-PS	Keyed		08/13/2019
Smoke Detector	1	SD-505-AHS			08/13/2019
Smoke Detector	81	SD-505-APS	Photoelectric		08/13/2019
		In Service	- 2 Years to 3 Years		
Battery	2	12V18AH	Sealed Lead Acid		07/13/2017
Battery	12	12V7AH	Sealed Lead Acid		07/13/2017
Silent Knight					
Heat Detector	3	SD505-AHS			07/13/2017
Power Supply	6	RPS-1000			07/13/2017
Smoke Detector	5	SD505-APS	Photoelectric		07/13/2017
System Sensor					
Duct Detector	1	D4120	Photoelectric		07/13/2017
Heat Detector	4	5602	Combination		07/13/2017

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - College Park Elementary School 2380 Notre Dame Road Costa Mesa, CA 92626

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Aug 14, 2019

> Building: NMUSD - College Park Elementary School Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: JD Torres Title: Technician

Executive Summary Generated by: BuildingReports.com

Building Information	
Building: NMUSD - College Park Elementary Scho	ool Contact: Tim Waller
Address: 2380 Notre Dame Road	Phone: 714-231-0363
Address:	Fax:
City/State/Zip: Costa Mesa, CA 92626	Mobile:
Country: United States of America	Email: twaller@nmusd.us
Inspection Performed By	
Company: Cal Building Systems	Inspector: JD Torres
Address: 2903 Saturn Street	Phone: 909–348–3402
Address: Suite F	Fax:
City/State/Zip: Brea, CA 92821	Mobile:
Country: United States of America	Email: jdtorres@calbuildingsystems.com
System Control Unit	
Manufacturer: Silent Knight	Inspection Date: 08/14/2019 IDC Style:
Model Number: 5820XL	Install Date: 08/14/2019 SLC Style:
Software Version:	Version Date: 12/31/1969 NAC Style:
Location: Admin Building Outside Phone Room	Current Protection:
Monitoring	
Company: AceTec	Phone: 1-800-634-3915 Account #: 21-1153
Central Station Signal Verification	
Туре:	Mfg: Model #:
Test Time/Date:	Restore Time

Inspection Summary								
Catanan	Total	ltems	Ser	viced	Pa	ssed	Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.45%	1	100.00%	1	100.00%	0	0%
Control	13	5.80%	13	100.00%	13	100.00%	0	0%
Initiating	210	93.75%	210	100.00%	210	100.00%	0	0%
Totals	224	100%	224	100.00%	224	100.00%	0	0%
Certification								
Company: Cal Building Systems			Bu	ilding: NML	ISD – Col	lege Park El	ementary	School
Inspector: JD Torres			Co	ontact: Tim	Waller			
	Signed:							

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - College Park ElementaryContrSchool5820

Control Panel: 1 - Silent Knight 5820XL

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Admin Building Staff Restroom	Inspected	8:15:15 AM	08/14/2019
Battery	Admin Building Outside Phone Room	Tested	8:02:24 AM	08/14/2019
Battery	Admin Building Outside Phone Room	Tested	8:03:37 AM	08/14/2019
Battery	Admin Building Outside Phone Room	Tested	8:04:45 AM	08/14/2019
Battery	Admin Building Outside Phone Room	Tested	8:04:58 AM	08/14/2019
Battery	Portable 11	Tested	10:44:22 AM	08/14/2019
Battery	Portable 11	Tested	10:45:02 AM	08/14/2019
Battery	Portable 35	Tested	11:01:34 AM	08/14/2019
Battery	Portable 35	Tested	11:02:13 AM	08/14/2019
Control Panel	Admin Building Outside Phone Room	Inspected	8:01:07 AM	08/14/2019
Power Supply	Admin Building Outside Phone Room	Inspected	8:04:14 AM	08/14/2019
Power Supply	Portable 11	Inspected	10:42:43 AM	08/14/2019
Power Supply	Portable 35	Inspected	11:01:15 AM	08/14/2019
Initiating				
Heat Detector	Admin Building Nurse's Restroom	Tested	8:34:42 AM	08/14/2019
Heat Detector	Admin Building Outside Mechanical Room	Tested	8:40:54 AM	08/14/2019
Heat Detector	Admin Building Staff Restroom	Tested	8:11:58 AM	08/14/2019
Heat Detector	Boy's Restroom Next To Classroom 23	Tested	9:16:22 AM	08/14/2019
Heat Detector	Boy's Restroom Next To Classroom 23	Tested	9:16:40 AM	08/14/2019
Heat Detector	Building A Boy's Restroom	Tested	10:11:42 AM	08/14/2019
Heat Detector	Building A Girl's Restroom	Tested	10:14:20 AM	08/14/2019
Heat Detector	Building A Mechanical Room	Tested	10:06:57 AM	08/14/2019
Heat Detector	Building D Boy's Restroom	Tested	9:35:00 AM	08/14/2019
Heat Detector	Building D Boy's Restroom	Tested	9:35:16 AM	08/14/2019
Heat Detector	Building D Girl's Restroom	Tested	9:29:15 AM	08/14/2019
Heat Detector	Building D Girl's Restroom	Tested	9:29:41 AM	08/14/2019
Heat Detector	Building D Mechanical Room	Tested	9:31:30 AM	08/14/2019
Heat Detector	Building E Unisex Restroom	Tested	9:14:42 AM	08/14/2019
Heat Detector	Classrooms 1 And 2 Preschool Staff Restroom	Tested	10:20:23 AM	08/14/2019
Heat Detector	Girl's Restroom Next To Classroom 18	Tested	9:06:36 AM	08/14/2019
Heat Detector	Girl's Restroom Next To Classroom 18	Tested	9:06:47 AM	08/14/2019
Heat Detector	Mechanical Room Inside Custodian Room Near	Tested	9:11:06 AM	08/14/2019
	To Classroom 18			
Heat Detector	MPR Building Kitchen	Tested	9:49:20 AM	08/14/2019
Heat Detector	MPR Building Mechanical Room	Tested	10:02:02 AM	08/14/2019
Heat Detector	MPR Building Storage Room	Tested	9:52:45 AM	08/14/2019
Heat Detector	Nurse Office (Attic)	Tested	10:22:45 AM	08/14/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	Outside Electrical Room Near FACP	Tested	8:53:44 AM	08/14/2019
Heat Detector	Outside Handicap Restroom Near FACP	Tested	9:45:08 AM	08/14/2019
Heat Detector	Outside Handicap Restroom Near FACP	Tested	9:45:42 AM	08/14/2019
Heat Detector	Outside Storage Building Near FACP Electrical	Tested	8:54:24 AM	08/14/2019
	Room			
Heat Detector	Portable 10 (Attic)	Tested	11:44:27 AM	08/14/2019
Heat Detector	Portable 10 (Attic)	Tested	11:45:06 AM	08/14/2019
Heat Detector	Portable 10 (Attic)	Tested	12:02:37 PM	08/14/2019
Heat Detector	Portable 11 (Attic)	Tested	12:03:30 PM	08/14/2019
Heat Detector	Portable 11 (Attic)	Tested	12:03:40 PM	08/14/2019
Heat Detector	Portable 11 (Attic)	Tested	12:03:45 PM	08/14/2019
Heat Detector	Portable 12 (Attic)	Tested	12:03:51 PM	08/14/2019
Heat Detector	Portable 12 (Attic)	Tested	12:04:00 PM	08/14/2019
Heat Detector	Portable 13 (Attic)	Tested	12:04:05 PM	08/14/2019
Heat Detector	Portable 13 (Attic)	Tested	12:04:15 PM	08/14/2019
Heat Detector	Portable 14 (Attic)	Tested	12:04:21 PM	08/14/2019
Heat Detector	Portable 14 (Attic)	Tested	12:04:33 PM	08/14/2019
Heat Detector	Portable 15 (Attic)	Tested	12:04:40 PM	08/14/2019
Heat Detector	Portable 15 (Attic)	Tested	12:04:50 PM	08/14/2019
Heat Detector	Portable 16 (Attic)	Tested	12:04:58 PM	08/14/2019
Heat Detector	Portable 16 (Attic)	Tested	12:05:14 PM	08/14/2019
Heat Detector	Portable 32 (Attic)	Tested	12:06:17 PM	08/14/2019
Heat Detector	Portable 32 (Attic)	Tested	12:06:27 PM	08/14/2019
Heat Detector	Portable 33 (Attic)	Tested	12:06:35 PM	08/14/2019
Heat Detector	Portable 33 (Attic)	Tested	12:06:48 PM	08/14/2019
Heat Detector	Portable 34 (Attic)	Tested	12:06:54 PM	08/14/2019
Heat Detector	Portable 34 (Attic)	Tested	12:07:03 PM	08/14/2019
Heat Detector	Portable 35 (Attic)	Tested	12:07:29 PM	08/14/2019
Heat Detector	Portable 35 (Attic)	Tested	12:07:41 PM	08/14/2019
Heat Detector	Portable 36 (Attic)	Tested	10:56:50 AM	08/14/2019
Heat Detector	Portable 36 (Attic)	Tested	10:57:35 AM	08/14/2019
Heat Detector	Portable 37 (Attic)	Tested	10:57:48 AM	08/14/2019
Heat Detector	Portable 37 (Attic)	Tested	10:58:07 AM	08/14/2019
Heat Detector	Portable 7 (Attic)	Tested	11:43:40 AM	08/14/2019
Heat Detector	Portable 7 (Attic)	Tested	11:44:21 AM	08/14/2019
Heat Detector	Portable 8 (Attic)	Tested	10:39:48 AM	08/14/2019
Heat Detector	Portable 8 (Attic)	Tested	10:40:34 AM	08/14/2019
Heat Detector	Portable 8 (Attic)	Tested	10:40:50 AM	08/14/2019
Heat Detector	Portable 9 (Attic)	Tested	10:41:03 AM	08/14/2019
Heat Detector	Portable 9 (Attic)	Tested	10:41:48 AM	08/14/2019
Heat Detector	Portable 9 (Attic)	Tested	10:41:59 AM	08/14/2019
Heat Detector	Portable Boys Restroom (Attic)	Tested	12:07:47 PM	08/14/2019
Heat Detector	Portable Girls Restroom (Attic)	Tested	12:08:23 PM	08/14/2019
Heat Detector	Portable Staff Restroom (Attic)	Tested	12:08:06 PM	08/14/2019
Heat Detector	Portable YMCA (Attic)	Tested	10:58:18 AM	08/14/2019
Heat Detector	Portable YMCA (Attic)	Tested	10:58:37 AM	08/14/2019
Heat Detector	Principal Office (Attic)	Tested	10:21:59 AM	08/14/2019
Heat Detector	Room 1 (Attic)	Tested	9:58:26 AM	08/14/2019
Heat Detector	Room 1 (Attic)	Tested	10:06:28 AM	08/14/2019
Heat Detector	Room 18 (Attic)	Tested	10:09:35 AM	08/14/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	Room 18 (Attic)	Tested	10:10:16 AM	08/14/2019
Heat Detector	Room 19 (Attic)	Tested	10:10:32 AM	08/14/2019
Heat Detector	Room 19 (Attic)	Tested	10:11:37 AM	08/14/2019
Heat Detector	Room 2 (Attic)	Tested	10:07:16 AM	08/14/201
Heat Detector	Room 2 (Attic)	Tested	10:07:34 AM	08/14/201
Heat Detector	Room 20 (Attic)	Tested	10:13:05 AM	08/14/201
Heat Detector	Room 20 (Attic)	Tested	10:13:32 AM	08/14/201
Heat Detector	Room 21 (Attic)	Tested	10:14:02 AM	08/14/201
Heat Detector	Room 21 (Attic)	Tested	10:14:16 AM	08/14/201
Heat Detector	Room 22 (Attic)	Tested	10:14:31 AM	08/14/201
Heat Detector	Room 22 (Attic)	Tested	10:14:59 AM	08/14/201
Heat Detector	Room 23 (Attic)	Tested	10:15:17 AM	08/14/201
Heat Detector	Room 23 (Attic)	Tested	10:15:38 AM	08/14/201
Heat Detector	Room 24 (Attic)	Tested	10:15:56 AM	08/14/201
Heat Detector	Room 24 (Attic)	Tested	10:16:18 AM	08/14/201
Heat Detector	Room 25 (Attic)	Tested	10:16:32 AM	08/14/201
Heat Detector	Room 25 (Attic)	Tested	10:16:54 AM	08/14/201
Heat Detector	Room 26 (Attic)	Tested	10:17:13 AM	08/14/201
Heat Detector	Room 26 (Attic)	Tested	10:17:32 AM	08/14/201
Heat Detector	Room 27 (Attic)	Tested	10:17:50 AM	08/14/201
Heat Detector	Room 27 (Attic)	Tested	10:18:58 AM	08/14/201
Heat Detector	Room 28 (Attic)	Tested	10:19:14 AM	08/14/201
Heat Detector	Room 28 (Attic)	Tested	10:19:33 AM	08/14/201
Heat Detector	Room 29 (Attic)	Tested	10:19:47 AM	08/14/201
Heat Detector	Room 29 (Attic)	Tested	10:20:10 AM	08/14/201
Heat Detector	Room 30 (Attic)	Tested	10:20:26 AM	08/14/201
Heat Detector	Room 30 (Attic)	Tested	10:20:50 AM	08/14/201
Heat Detector	Room 31 (Attic)	Tested	10:21:02 AM	08/14/201
Heat Detector	Room 31 (Attic)	Tested	10:21:20 AM	08/14/201
Heat Detector	Room 4 (Attic)	Tested	10:07:46 AM	08/14/201
Heat Detector	Room 4 (Attic)	Tested	10:08:08 AM	08/14/201
Heat Detector	Room 5 (Attic)	Tested	10:08:21 AM	08/14/201
Heat Detector	Room 5 (Attic)	Tested	10:08:41 AM	08/14/201
Heat Detector	Room 6 (Attic)	Tested	10:08:57 AM	08/14/201
Heat Detector	Room 6 (Attic)	Tested	10:09:16 AM	08/14/201
Pull Station	Admin Building Front Entrance	Tested	8:19:44 AM	08/14/201
Pull Station	MPR Building Exit	Tested	9:51:25 AM	08/14/201
Pull Station	MPR Building Exit	Tested	9:57:53 AM	08/14/201
Pull Station	MPR Building Front Entrance	Tested	9:50:35 AM	08/14/201
Pull Station	MPR Building Stage Exit	Tested	9:54:59 AM	08/14/201
Smoke Detector	Admin Building Corridor Exit By Staff Room	Tested	8:08:11 AM	08/14/201
Smoke Detector	Admin Building Nurse's Office	Tested	8:33:00 AM	08/14/201
Smoke Detector	Admin Building Nurse's Office Sleeper Room	Tested	8:33:58 AM	08/14/201
Smoke Detector	Admin Building Outside Phone Room	Tested	8:05:17 AM	08/14/201
Smoke Detector	Admin Building Principal's Office	Tested	8:25:36 AM	08/14/201
Smoke Detector	Admin Building Reception	Tested	8:22:07 AM	08/14/201
Smoke Detector	Admin Building Reception By Nurse's Office	Tested	8:38:16 AM	08/14/201
Smoke Detector	Admin Building Staff Lounge	Tested	8:39:10 AM	08/14/201
Smoke Detector	Admin Building Storage Room Next To	Tested	8:26:55 AM	08/14/201
	Reception			

Device Type	Location	Service	Time	Date
	Passed	· · · · · · · · · · · · · · · · · · ·		
Smoke Detector	Boy's Portable Restroom	Tested	10:56:05 AM	08/14/2019
Smoke Detector	Building A Custodian Room	Tested	10:06:39 AM	08/14/2019
Smoke Detector	Building A Storage/Community Facilitator	Tested	10:10:27 AM	08/14/2019
Smoke Detector	Building A Toy Storage Room	Tested	10:04:54 AM	08/14/2019
Smoke Detector	Building B Electrical Room By MPR	Tested	10:03:26 AM	08/14/2019
Smoke Detector	Building D Custodian Room	Tested	9:32:54 AM	08/14/2019
Smoke Detector	Building D Storage Room	Tested	9:34:22 AM	08/14/2019
Smoke Detector	Building E Custodian Room	Tested	9:12:13 AM	08/14/2019
Smoke Detector	Classroom 1 Preschool	Tested	10:17:14 AM	08/14/2019
Smoke Detector	Classroom 1 Preschool	Tested	10:17:37 AM	08/14/2019
Smoke Detector	Classroom 1 Preschool Restroom	Tested	10:17:44 AM	08/14/2019
Smoke Detector	Classroom 1 And 2 Preschool Workroom	Tested	10:19:17 AM	08/14/2019
Smoke Detector	Classroom 18	Tested	9:04:55 AM	08/14/2019
Smoke Detector	Classroom 18	Tested	9:05:06 AM	08/14/2019
Smoke Detector	Classroom 18	Tested	9:05:20 AM	08/14/2019
Smoke Detector	Classroom 19	Tested	9:02:49 AM	08/14/2019
Smoke Detector	Classroom 19	Tested	9:02:57 AM	08/14/2019
Smoke Detector	Classroom 2 Preschool	Tested	10:22:30 AM	08/14/2019
Smoke Detector	Classroom 2 Preschool	Tested	10:22:41 AM	08/14/2019
Smoke Detector	Classroom 2 Preschool Restroom	Tested	10:21:43 AM	08/14/2019
Smoke Detector	Classroom 20	Tested	9:01:48 AM	08/14/2019
Smoke Detector	Classroom 20	Tested	9:02:16 AM	08/14/2019
Smoke Detector	Classroom 21	Tested	9:19:24 AM	08/14/2019
Smoke Detector	Classroom 21	Tested	11:18:25 AM	08/14/2019
Smoke Detector	Classroom 22	Tested	9:18:37 AM	08/14/2019
Smoke Detector	Classroom 22	Tested	9:18:55 AM	08/14/2019
Smoke Detector	Classroom 23	Tested	9:17:45 AM	08/14/2019
Smoke Detector	Classroom 23	Tested	9:18:03 AM	08/14/2019
Smoke Detector	Classroom 24	Tested	9:26:59 AM	08/14/2019
Smoke Detector	Classroom 24	Tested	9:27:25 AM	08/14/2019
Smoke Detector	Classroom 25	Tested	9:25:19 AM	08/14/2019
Smoke Detector	Classroom 25	Tested	9:26:02 AM	08/14/2019
Smoke Detector	Classroom 26	Tested	9:24:35 AM	08/14/2019
Smoke Detector	Classroom 26	Tested	9:24:45 AM	08/14/2019
Smoke Detector	Classroom 27	Tested	9:22:00 AM	08/14/2019
Smoke Detector	Classroom 27	Tested	9:22:13 AM	08/14/2019
Smoke Detector	Classroom 28	Tested	9:37:27 AM	08/14/2019
Smoke Detector	Classroom 28	Tested	9:37:39 AM	08/14/2019
Smoke Detector	Classroom 29	Tested	9:37:44 AM	08/14/2019
Smoke Detector	Classroom 29	Tested	9:37:54 AM	08/14/2019
Smoke Detector	Classroom 30	Tested	9:38:21 AM	08/14/2019
Smoke Detector	Classroom 30	Tested	9:38:36 AM	08/14/2019
Smoke Detector	Classroom 31	Tested	9:38:44 AM	08/14/2019
Smoke Detector	Classroom 31	Tested	9:38:55 AM	08/14/2019
Smoke Detector	Classroom 4	Tested	10:25:35 AM	08/14/2019
Smoke Detector	Classroom 4	Tested	10:25:46 AM	08/14/2019
Smoke Detector	Classroom 5	Tested	10:24:48 AM	08/14/2019
Smoke Detector	Classroom 5	Tested	10:24:57 AM	08/14/2019
Smoke Detector	Classroom 6	Tested	10:24:23 AM	08/14/2019
SHIDKE DELECTOR				

Device Type	Location	Service	Time	Date			
Passed							
Smoke Detector	Girl's Portable Restroom	Tested	10:54:18 AM	08/14/2019			
Smoke Detector	MPR Building Corridor Entrance	Tested	9:50:09 AM	08/14/2019			
Smoke Detector	MPR Building Main Hall	Tested	9:56:15 AM	08/14/2019			
Smoke Detector	MPR Building Main Hall	Tested	9:56:29 AM	08/14/2019			
Smoke Detector	MPR Building Main Hall	Tested	9:56:39 AM	08/14/2019			
Smoke Detector	MPR Building Main Hall	Tested	9:56:48 AM	08/14/2019			
Smoke Detector	MPR Building Stage	Tested	9:58:27 AM	08/14/2019			
Smoke Detector	MPR Building Stage	Tested	9:58:39 AM	08/14/2019			
Smoke Detector	MPR Building Workroom 17	Tested	9:47:22 AM	08/14/2019			
Smoke Detector	Outside Restrooms Near FACP Electrical Room	Tested	8:44:59 AM	08/14/2019			
Smoke Detector	Portable 10	Tested	10:47:28 AM	08/14/2019			
Smoke Detector	Portable 10	Tested	10:47:38 AM	08/14/2019			
Smoke Detector	Portable 11	Tested	10:41:35 AM	08/14/2019			
Smoke Detector	Portable 12	Tested	10:41:02 AM	08/14/2019			
Smoke Detector	Portable 13	Tested	10:40:00 AM	08/14/2019			
Smoke Detector	Portable 14	Tested	10:38:44 AM	08/14/2019			
Smoke Detector	Portable 14	Tested	10:38:55 AM	08/14/2019			
Smoke Detector	Portable 15	Tested	10:37:03 AM	08/14/2019			
Smoke Detector	Portable 15	Tested	10:37:24 AM	08/14/2019			
Smoke Detector	Portable 16	Tested	10:35:51 AM	08/14/2019			
Smoke Detector	Portable 16	Tested	10:36:25 AM	08/14/2019			
Smoke Detector	Portable 32	Tested	11:04:55 AM	08/14/2019			
Smoke Detector	Portable 32	Tested	11:05:22 AM	08/14/2019			
Smoke Detector	Portable 33	Tested	11:03:55 AM	08/14/2019			
Smoke Detector	Portable 33	Tested	11:04:08 AM	08/14/2019			
Smoke Detector	Portable 34	Tested	11:03:15 AM	08/14/2019			
Smoke Detector	Portable 34	Tested	11:03:27 AM	08/14/2019			
Smoke Detector	Portable 35	Tested	10:59:31 AM	08/14/2019			
Smoke Detector	Portable 35	Tested	10:59:46 AM	08/14/2019			
Smoke Detector	Portable 36	Tested	10:51:13 AM	08/14/2019			
Smoke Detector	Portable 36	Tested	10:51:26 AM	08/14/2019			
Smoke Detector	Portable 37	Tested	10:49:46 AM	08/14/2019			
Smoke Detector	Portable 37	Tested	10:50:14 AM	08/14/2019			
Smoke Detector	Portable 38	Tested	10:53:02 AM	08/14/2019			
Smoke Detector	Portable 38	Tested	10:53:13 AM	08/14/2019			
Smoke Detector	Portable 7	Tested	11:05:50 AM	08/14/2019			
Smoke Detector	Portable 7	Tested	11:06:00 AM	08/14/2019			
Smoke Detector	Portable 8	Tested	11:07:26 AM	08/14/2019			
Smoke Detector	Portable 9 Library	Tested	11:07:35 AM	08/14/2019			
Smoke Detector	Unisex Portable Restroom	Tested	10:55:13 AM	08/14/2019			

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - College Park Elementary School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Annunciator	Inspected	1
Battery	Tested	8
Control Panel	Inspected	1
Heat Detector	Tested	106
Power Supply	Inspected	3
Pull Station	Tested	5
Smoke Detector	Tested	99
Total		223

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - College Park Elementary School

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

		Ambient	Alarm	🦻 Intell	igibility	Sound
C Location	 Comment 	◀ dB	◀ dB	Voice	STI	Test
	Passe	d				
Sound Test Points						
Entire Facility	Passed					0001

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - College Park ElementaryControl Panel: 1 - Silent KnightSchool5820XL

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category		% of Inventory	Quantity
Control Panel		Control		0.45%	1
Battery		Control		3.57%	8
Power Supply		Control		1.34%	3
Smoke Detector		Initiating		44.20%	99
Heat Detector		Initiating		47.32%	106
Annunciator		Control		0.45%	1
Pull Station		Initiating		2.23%	5
Туре	Qty	Model #	Description		Install Date
		New	(under 90 days)	
Chemetron					
Heat Detector	29	602	Rate-of-Rise		08/14/2019
Silent Knight					
Annunciator	1				08/14/2019
Control Panel	1	5820XL			08/14/2019
Heat Detector	25	SD505-AHS			08/14/2019
Heat Detector	52	SD505-AHS	Fixed Temperature		08/14/2019
Power Supply	2	5895XL			08/14/2019
Pull Station	5	SD500-PS	Single Action		08/14/2019
Smoke Detector	99	SD505-APS	Photoelectric		08/14/2019
		In Service	e - 2 Years to 3	Years	
Battery	2	12V18AH	Sealed Lead Acid		07/18/2017
Battery	2	12V7AH	Sealed Lead Acid		07/18/2017
Silent Knight					
Power Supply	1	5895XL			07/18/2017
Battery	4	12V7AH	Sealed Lead Acid		07/14/2017

Zone Address Report

Generated by: BuildingReports.com

Building: NMUSD - College Park Elementary School

Control Panel: 1 - Silent Knight 5820XL

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Туре	ScanID
01:003	Heat Detector	Room 27 (Attic)	Fixed Temperature	61325860
01:004	Heat Detector	Room 28 (Attic)	Fixed Temperature	61325861
01:007	Heat Detector	Room 27 (Attic)	Fixed Temperature	61325859
01:008	Heat Detector	Room 28 (Attic)	Fixed Temperature	61325862
01:011	Heat Detector	Room 26 (Attic)	Fixed Temperature	61325857
01:012	Heat Detector	Room 29 (Attic)	Fixed Temperature	61325863
01:015	Heat Detector	Room 26 (Attic)	Fixed Temperature	61325858
01:016	Heat Detector	Room 29 (Attic)	Fixed Temperature	61325864
01:019	Heat Detector	Room 25 (Attic)	Fixed Temperature	61325855
01:020	Heat Detector	Room 30 (Attic)	Fixed Temperature	61325865
01:023	Heat Detector	Room 25 (Attic)	Fixed Temperature	61325856
01:024	Heat Detector	Room 30 (Attic)	Fixed Temperature	61325866
01:027	Heat Detector	Room 24 (Attic)	Fixed Temperature	61325853
01:028	Heat Detector	Room 31 (Attic)	Fixed Temperature	61325867
01:031	Heat Detector	Room 24 (Attic)	Fixed Temperature	61325854
01:032	Heat Detector	Room 31 (Attic)	Fixed Temperature	61325868
01:043	Heat Detector	Room 20 (Attic)	Fixed Temperature	61325845
01:044	Heat Detector	Room 21 (Attic)	Fixed Temperature	61325847
01:047	Heat Detector	Room 20 (Attic)	Fixed Temperature	61325846
01:048	Heat Detector	Room 21 (Attic)	Fixed Temperature	61325848
01:051	Heat Detector	Room 19 (Attic)	Fixed Temperature	61325843
01:052	Heat Detector	Room 22 (Attic)	Fixed Temperature	61325849
01:055	Heat Detector	Room 19 (Attic)	Fixed Temperature	61325844
01:056	Heat Detector	Room 22 (Attic)	Fixed Temperature	61325850
01:059	Heat Detector	Room 18 (Attic)	Fixed Temperature	61325841
01:060	Heat Detector	Room 23 (Attic)	Fixed Temperature	61325851
01:064	Heat Detector	Room 18 (Attic)	Fixed Temperature	61325842
01:065	Heat Detector	Room 23 (Attic)	Fixed Temperature	61325852
01:104	Heat Detector	Portable 36 (Attic)	Fixed Temperature	61325878
01:105	Heat Detector	Portable 36 (Attic)	Fixed Temperature	61325879
01:108	Heat Detector	Portable 37 (Attic)	Fixed Temperature	61325880
01:109	Heat Detector	Portable 37 (Attic)	Fixed Temperature	61325881
01:112	Heat Detector	Portable YMCA (Attic)	Fixed Temperature	61325882
01:113	Heat Detector	Portable YMCA (Attic)	Fixed Temperature	61325883
06:101	Heat Detector	Portable 8 (Attic)	Fixed Temperature	61325872
06:102	Heat Detector	Portable 8 (Attic)	Fixed Temperature	61325873
06:103	Heat Detector	Portable 8 (Attic)	Fixed Temperature	61325874
06:105	Heat Detector	Portable 9 (Attic)	Fixed Temperature	61325875
06:106	Heat Detector	Portable 9 (Attic)	Fixed Temperature	61325876
06:107	Heat Detector	Portable 9 (Attic)	Fixed Temperature	61325877
33:010	Heat Detector	Principal Office (Attic)	Fixed Temperature	61325869

33:015	Heat Detector	Nurse Office (Attic)	Fixed Temperature	61325870
33:022	Heat Detector	Room 2 (Attic)	Fixed Temperature	61325834
33:024	Heat Detector	Room 2 (Attic)	Fixed Temperature	61325835
33:032	Heat Detector	Room 1 (Attic)	Fixed Temperature	61325832
33:033	Heat Detector	Room 1 (Attic)	Fixed Temperature	61325833
33:040	Heat Detector	Room 4 (Attic)	Fixed Temperature	61325836
33:043	Heat Detector	Room 4 (Attic)	Fixed Temperature	61325837
33:044	Heat Detector	Room 5 (Attic)	Fixed Temperature	61325838
33:047	Heat Detector	Room 5 (Attic)	Fixed Temperature	61325839
33:048	Heat Detector	Room 6 (Attic)	Fixed Temperature	61325840
33:051	Heat Detector	Room 6 (Attic)	Fixed Temperature	61325871

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Corona Del Mar Middle & High School 2101 Eastbluff Drive Newport Beach, CA 92660

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Aug 22, 2019

Building: NMUSD - Corona Del Mar Middle & High School Contact: Tim Waller Title: Maintenance & Operations Manager Company: Cal Building Systems Contact: JD Torres Title: Technician

Executive Summary Generated by: BuildingReports.com

Building Information			
Building: NMUSD - Corona Del Mar Middle & High	Contact: Tim Wall	er	
School			
Address: 2101 Eastbluff Drive	Phone: 714–231–	0363	
Address:	Fax:		
City/State/Zip: Newport Beach, CA 92660	Mobile:		
Country: United States of America	Email: Twaller@nr	nusd.us	
Inspection Performed By			
Company: Cal Building Systems	Inspector: JD Torr	es	
Address: 2903 Saturn Street	Phone: 909-348-	3402	
Address: Suite F	Fax:		
City/State/Zip: Brea, CA 92821	Mobile:		
Country: United States of America	Email: jdtorres@c	albuildingsystems	.com
System Control Unit			
Manufacturer: Silent Knight	Inspection Date: (08/20/2019	IDC Style:
Model Number: IFP-200	Install Date: 08/2	0/2019	SLC Style:
Software Version:	Version Date: 08/	20/2019	NAC Style:
Location: Building 100 Admin Data Room	Current Protection	n: Breaker	
Monitoring			
Company: P	hone:	Account a	#:
Central Station Signal Verification			
Туре:	Mfg:	Мо	odel #:
Test Time/Date:	Restore Time		

Inspection Summary								
Catalana	Total	ltems	Serviced		Passed		Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.11%	1	100.00%	0	0%	1	100.00%
Control	50	5.58%	50	100.00%	46	92.00%	4	8.00%
Initiating	833	92.97%	833	100.00%	833	100.00%	0	0%
Supervisory	12	1.34%	12	100.00%	12	100.00%	0	0%
Totals	896	100%	896	100.00%	891	99.44%	5	0.56%
Certification								
Company: Cal Building Systems			Bu Scho	uilding: NMU pol	ISD – Cor	ona Del Ma	r Middle d	& High
Inspector: JD Torres			Co	ontact: Tim V	Waller			
Signed:			Si	gned:				

Discrepancy Report

Generated by: BuildingReports.com

Building: NMUSD - Corona Del Mar Middle & Control Panel: 1 - Silent Knight **IFP-200** High School The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included. ModelNumber Device Type Manufacturer Date Qty Items listed for Recall by Manufacturer No recalled items found during this inspection. **Reference** 8 ScanID C3 Location Ø Address Problem **Control**

Battery								
58093306	2nd Building 400 Telecom Room Next To	Date Expired	1	NFPA72 Table				
	Staff Restroom			14.4.2.2 (5)(b)				
58093307	2nd Building 400 Telecom Room Next To	Date Expired	1	NFPA72 Table				
	Staff Restroom			14.4.2.2 (5)(b)				
58093284	3rd Building 400 Telecom Room Next To	Date Expired	1	NFPA72 Table				
	Staff Restroom			14.4.2.2 (5)(b)				
58093285	3rd Building 400 Telecom Room Next To	Date Expired	1	NFPA72 Table				
	Staff Restroom			14.4.2.2 (5)(b)				
	Code References							
NFPA72 Table	Batteries shall be replaced in accordanc	e with the recommendat	ions of the alar	m equipment				
14.4.2.2 (5)(b)	manufacturer or when the recharged ba	ttery voltage or current	falls below the	manufacturer's				
	recommendations							

Building: N High Schoo		orona Del Mar Mido	ile &	Control I	Panel	: n/a		
The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.								
Device Type		Manufacturer		ModelNum	nber	Da	ıte	Qty
		Items listed for Red	call b	y Manufac	cturei	r		
		No recalled items four	nd durir	ng this inspectio	on.			
Sound Test			Υ Pι	roblem		Device	Ref	erence
Sound Testing								
Sound Test 🖸 Location 🦞 Problem Device 🕮 Reference								
Sound Test Points								
0001	0001 Sound Test							

Proposed Solutions Report

Generated by: BuildingReports.com

Building: NMUSD - Corona Del Mar Middle & High School

Control Panel: 1 - Silent Knight IFP-200

The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.

ScanID	Location	Solution	Model #	Cost	Fix				
	Control								
Battery									
58093306	2nd Building 400 Telecom Room Next To Staff Restroom	Replace	12V7AH	T/M					
58093307	2nd Building 400 Telecom Room Next To Staff Restroom	Replace	12V7AH	T/M					
58093284	3rd Building 400 Telecom Room Next To Staff Restroom	Replace	12V7AH	T/M					
58093285	3rd Building 400 Telecom Room Next To Staff Restroom	Replace	12V7AH	T/M					
•	NMUSD - Corona Del Mar High School		Cont	rol Pane	l: n/a				
	Solution Report provides a solution for each d here indicated to approve repairs listed within terials basis.								
ScanID	Location	Solution	Description	Cost	Fix				
	Sound Testing								
Sound Te	est								
0001				T/M					
			PO #: (none)	T/M					

Notes & Recommendations

Generated by: BuildingReports.com

Building: NMUSD - Corona Del Mar Middle & G High School

Control Panel: n/a

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

ScanID	Note	Device Type	Location	Comment			
0001	1	Sound Test					
Horns	tone in C	Classroom 333 exit is falling. Big g	gym has two hornstrobes that failed to activate. Th	ne trigger			
for bu	for building 600 also failed. Horns and strobes started to work once alarm was activated in building but not						
by out	tside devi	ices.					

Building: NMUSD - Corona Del Mar Middle &
High SchoolControl Panel: 1 - Silent Knight
IFP-200

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

ScanID	Note	Device Type	Location	Comment				
	Initiating							
58092736	2	Pull Station	Building 300 Lecture Hall Northeast Exit	Passed				
Ancho	ors holdir	ng it up are blown out						
61337172	3	Waterflow Switch	Building 400 Fire Riser Room 418	Passed				
Static	71							
Resid	ual 54							
F. Sta	tic 71							
Riser	Diameter	6"						
Main	Drain Dia	meter 2"						
61337163	4	Waterflow Switch	Building 600 Electrical 620 Fire Riser Room 631	Passed				
Static	80							
Resid	ual 62							
F. Sta	tic 80							
Riser	Diameter	4"						
Main	Drain Dia	meter 2"						

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Corona Del Mar Middle &
High SchoolControl Panel: 1 - Silent Knight
IFP-200

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Building 100 Admin Secretary	Tested	2:10:42 PM	08/22/2019
Battery	1st Building 500 Classroom 505 Storage Room	Tested	1:30:21 PM	08/22/2019
Battery	1st Building 500 Classroom 505 Storage Room	Tested	1:30:29 PM	08/22/2019
Battery	Building 100 Admin Data Room	Inspected	8:56:08 AM	08/20/2019
Battery	Building 100 Admin Data Room	Inspected	8:56:17 AM	08/20/2019
Battery	Building 200 Classroom 242 Data Room	Inspected	10:04:55 AM	08/20/2019
Battery	Building 200 Classroom 242 Data Room	Inspected	10:05:05 AM	08/20/2019
Battery	Building 200 Electrical Room 258	Inspected	9:33:42 AM	08/20/2019
Battery	Building 200 Electrical Room 258	Inspected	9:34:08 AM	08/20/2019
Battery	Building 300 North Storage Room	Inspected	2:05:22 PM	08/20/2019
Battery	Building 300 North Storage Room	Inspected	2:06:03 PM	08/20/2019
Battery	Building 300 Electrical Room By 301	Inspected	12:35:32 PM	08/20/2019
Battery	Building 300 Electrical Room By 301	Inspected	12:35:50 PM	08/20/2019
Battery	Building 300 Electrical Room By 318	Inspected	12:45:17 PM	08/20/2019
Battery	Building 300 Electrical Room By 318	Inspected	12:45:54 PM	08/20/2019
Battery	Building 300 Electrical Room By Staff Lounge	Inspected	1:47:10 PM	08/20/2019
Battery	Building 300 Electrical Room By Staff Lounge	Inspected	1:48:11 PM	08/20/2019
Battery	Building 400 Telecom Room Near Classroom 414	Tested	10:19:42 AM	08/22/2019
Battery	Building 400 Telecom Room Near Classroom 414	Tested	10:19:50 AM	08/22/2019
Battery	Building 900 Little Gym Electrical Room	Tested	8:12:01 AM	08/22/2019
Battery	Building 900 Little Gym Electrical Room	Tested	8:12:50 AM	08/22/2019
Battery	Building Pool Data Room	Inspected	8:47:35 AM	08/21/2019
Battery	Building Pool Data Room	Inspected	8:48:13 AM	08/21/2019
Battery	Building Pool Janitor Room	Inspected	8:42:28 AM	08/21/2019
Battery	Building Pool Janitor Room	Inspected	8:42:49 AM	08/21/2019
Control Panel	Building 100 Admin Data Room	Tested	8:47:51 AM	08/20/2019
Power Supply	1st Building 500 Classroom 505 Storage Room	Inspected	1:29:07 PM	08/22/2019
Power Supply	Building 200 Classroom 242 Data Room	Tested	10:03:56 AM	08/20/2019
Power Supply	Building 300 North Storage Room	Tested	2:04:30 PM	08/20/2019
Power Supply	Building 300 Electrical By Staff Lounge	Tested	1:46:14 PM	08/20/2019
Power Supply	Building 300 Electrical Room By 301	Tested	12:34:23 PM	08/20/2019
Power Supply	Building 300 Electrical Room By 318	Tested	12:44:43 PM	08/20/2019
Power Supply	Building 900 Little Gym Electrical Room	Inspected	8:11:00 AM	08/22/2019
Power Supply	Building Pool Data Room	Tested	8:46:53 AM	08/21/2019
Power Supply	Building Pool Janitor Room	Tested	8:40:39 AM	08/21/2019
Voice Evacuation	Building 200 Electrical Room 258	Tested	9:32:08 AM	08/20/2019

Cal Building Systems

Device Type	Location	Service	Time	Date
	Passed			
Initiating				
Beam Detector	Building 300 Lecture Hall	Tested	2:15:05 PM	08/20/2019
Heat Detector	Building 100 Nurse Area Office	Tested	1:36:57 PM	08/22/2019
Heat Detector	Building 100 Storage Exit	Tested	1:37:26 PM	08/22/2019
Heat Detector	Building 200 Athletes Conference	Tested	12:33:03 PM	08/22/2019
Heat Detector	Building 200 Career Center	Tested	12:38:23 PM	08/22/2019
Heat Detector	Building 200 Corridor	Tested	12:30:10 PM	08/22/2019
Heat Detector	Building 200 Corridor Centerwest	Tested	12:34:27 PM	08/22/2019
Heat Detector	Building 200 Corridor East	Tested	12:29:05 PM	08/22/2019
Heat Detector	Building 200 Corridor East	Tested	12:29:36 PM	08/22/2019
Heat Detector	Building 200 Corridor Northeast	Tested	12:31:48 PM	08/22/2019
Heat Detector	Building 200 Corridor Northeast	Tested	12:32:01 PM	08/22/2019
Heat Detector	Building 200 Corridor Southcenter	Tested	1:32:18 PM	08/22/2019
Heat Detector	Building 200 Corridor Southeast	Tested	1:31:51 PM	08/22/2019
Heat Detector	Building 200 Corridor Southeast	Tested	1:32:56 PM	08/22/2019
Heat Detector	Building 200 Corridor Southwest	Tested	1:36:35 PM	08/22/2019
Heat Detector	Building 200 Hallway 214	Tested	12:30:39 PM	08/22/2019
Heat Detector	Building 200 Learning Resource 250	Tested	9:37:47 AM	08/20/2019
Heat Detector	Building 200 Library Northeast	Tested	12:37:17 PM	08/22/2019
Heat Detector	Building 200 Library Northwest	Tested	12:35:13 PM	08/22/2019
Heat Detector	Building 200 Library Office 275	Tested	12:37:34 PM	08/22/2019
Heat Detector	Building 200 Library Southwest	Tested	12:36:45 PM	08/22/2019
Heat Detector	Building 200 Men's Restroom	Tested	1:33:39 PM	08/22/2019
Heat Detector	Building 200 Office 265	Tested	12:29:42 PM	08/22/2019
Heat Detector	Building 200 Room 202	Tested	1:30:30 PM	08/22/2019
Heat Detector	Building 200 Room 204	Tested	1:31:39 PM	08/22/2019
Heat Detector	Building 200 Room 213	Tested	1:33:25 PM	08/22/2019
Heat Detector	Building 200 Room 216	Tested	1:33:08 PM	08/22/2019
Heat Detector	Building 200 Room 221	Tested	1:31:28 PM	08/22/2019
Heat Detector	Building 200 Room 222	Tested	1:30:17 PM	08/22/2019
Heat Detector	Building 200 Room 223	Tested	1:30:03 PM	08/22/2019
Heat Detector	Building 200 Room 206	Tested	1:36:24 PM	08/22/2019
Heat Detector	Building 200 Room 207	Tested	1:35:53 PM	08/22/2019
Heat Detector	Building 200 Room 209	Tested	1:34:55 PM	08/22/2019
Heat Detector	Building 200 Room 210	Tested	12:33:58 PM	08/22/2019
Heat Detector	Building 200 Room 214	Tested	12:34:12 PM	08/22/2019
Heat Detector	Building 200 Room 218	Tested	12:28:39 PM	08/22/2019
Heat Detector	Building 200 Room 220	Tested	12:28:54 PM	08/22/2019
Heat Detector	Building 200 Room 223	Tested	12:28:27 PM	08/22/2019
Heat Detector	Building 200 Room 224	Tested	12:21:59 PM	08/22/2019
Heat Detector	Building 200 Room 225 Electrical	Tested	12:26:41 PM	08/22/2019
Heat Detector	Building 200 Room 227	Tested	12:24:24 PM	08/22/2019
Heat Detector	Building 200 Room 228	Tested	12:25:17 PM	08/22/2019
Heat Detector	Building 200 Room 229	Tested	12:25:34 PM	08/22/2019
Heat Detector	Building 200 Room 230	Tested	12:27:21 PM	08/22/2019
Heat Detector	Building 200 Room 231	Tested	12:27:53 PM	08/22/2019
Heat Detector	Building 200 Room 232	Tested	12:28:04 PM	08/22/2019
Heat Detector	Building 200 Room 234	Tested	12:35:00 PM	08/22/2019
Heat Detector	Building 200 Room 235	Tested	12:28:14 PM	08/22/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	Building 200 Room 238	Tested	12:32:32 PM	08/22/2019
Heat Detector	Building 200 Room 240	Tested	12:32:10 PM	08/22/2019
Heat Detector	Building 200 Room 241	Tested	12:33:35 PM	08/22/2019
Heat Detector	Building 200 Room 242	Tested	12:32:45 PM	08/22/2019
Heat Detector	Building 200 Women's Restroom	Tested	1:34:36 PM	08/22/2019
Heat Detector	Building 300 North Boys Restroom	Tested	2:36:27 PM	08/20/2019
Heat Detector	Building 300 North Girls Restroom	Tested	2:24:48 PM	08/20/2019
Heat Detector	Building 300 Classroom 306	Tested	2:29:01 PM	08/20/2019
Heat Detector	Building 300 Classroom 306	Tested	2:29:13 PM	08/20/2019
Heat Detector	Building 300 Classroom 308	Tested	2:34:40 PM	08/20/2019
Heat Detector	Building 300 Classroom 308	Tested	2:34:49 PM	08/20/2019
Heat Detector	Building 300 Classroom 328	Tested	1:25:55 PM	08/20/2019
Heat Detector	Building 300 Faculty Lounge 383	Tested	1:26:13 PM	08/22/2019
Heat Detector	Building 300 Office 333	Tested	1:25:54 PM	08/22/2019
Heat Detector	Building 300 Room 300	Tested	1:20:16 PM	08/22/2019
Heat Detector	Building 300 Room 301	Tested	1:20:02 PM	08/22/2019
Heat Detector	Building 300 Room 302	Tested	1:17:12 PM	08/22/2019
Heat Detector	Building 300 Room 303	Tested	1:16:29 PM	08/22/2019
Heat Detector	Building 300 Room 304	Tested	1:25:02 PM	08/22/2019
Heat Detector	Building 300 Room 304	Tested	1:25:45 PM	08/22/2019
Heat Detector	Building 300 Room 306	Tested	1:26:41 PM	08/22/2019
Heat Detector	Building 300 Room 306	Tested	1:29:53 PM	08/22/2019
Heat Detector	Building 300 Room 312	Tested	1:20:28 PM	08/22/2019
Heat Detector	Building 300 Room 317	Tested	1:20:39 PM	08/22/2019
Heat Detector	Building 300 Room 318	Tested	1:21:06 PM	08/22/2019
Heat Detector	Building 300 Room 319 IDF	Tested	1:24:04 PM	08/22/2019
Heat Detector	Building 300 Room 320	Tested	1:21:18 PM	08/22/2019
Heat Detector	Building 300 Room 321	Tested	1:23:49 PM	08/22/2019
Heat Detector	Building 300 Room 323	Tested	1:21:41 PM	08/22/2019
Heat Detector	Building 300 Room 324	Tested	1:21:29 PM	08/22/2019
Heat Detector	Building 300 Room 324	Tested	1:27:57 PM	08/22/2019
Heat Detector	Building 300 Room 325	Tested	1:29:34 PM	08/22/2019
Heat Detector	Building 300 Room 326	Tested	1:27:06 PM	08/22/2019
Heat Detector	Building 300 Room 328	Tested	1:27:17 PM	08/22/2019
Heat Detector	Building 300 Room 328	Tested	1:27:49 PM	08/22/2019
Heat Detector	Building 300 Room 330	Tested	1:28:51 PM	08/22/2019
Heat Detector	Building 300 Room 331	Tested	1:28:36 PM	08/22/2019
Heat Detector	Building 400 2nd Floor Elevator Lobby	Tested	1:45:02 PM	08/22/2019
Heat Detector	Building 400 3rd Floor Elevator Lobby	Tested	1:45:22 PM	08/22/2019
Heat Detector	Building 400 Boys Restroom 416	Tested	1:38:02 PM	08/22/2019
Heat Detector	Building 400 Classroom 410	Tested	1:46:34 PM	08/22/2019
Heat Detector	Building 400 Classroom 411	Tested	1:46:21 PM	08/22/2019
Heat Detector	Building 400 Classroom 412	Tested	1:46:09 PM	08/22/2019
Heat Detector	Building 400 Classroom 413	Tested	1:45:47 PM	08/22/2019
Heat Detector	Building 400 Classroom 420	Tested	1:49:12 PM	08/22/2019
Heat Detector	Building 400 Classroom 421	Tested	1:49:02 PM	08/22/2019
Heat Detector	Building 400 Classroom 422 Building 400 Classroom 422	Tested	1:48:51 PM	08/22/2019
Heat Detector	Building 400 Classroom 423	Tested	1:48:35 PM	08/22/2019
Heat Detector	Building 400 Classroom 420 Building 400 Classroom 430	Tested	1:50:33 PM	08/22/2019
	-	Tested	1:50:07 PM	
Heat Detector	Building 400 Classroom 431	resteu	1.50.07 110	08/22/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	Building 400 Classroom 432	Tested	1:49:56 PM	08/22/2019
Heat Detector	Building 400 Classroom 433	Tested	1:49:45 PM	08/22/2019
Heat Detector	Building 400 Conference Room 402	Tested	1:52:05 PM	08/22/2019
Heat Detector	Building 400 Copy Room 405	Tested	1:54:19 PM	08/22/2019
Heat Detector	Building 400 Elevator Lobby	Tested	1:44:18 PM	08/22/2019
Heat Detector	Building 400 Girls Restroom 415	Tested	1:38:30 PM	08/22/2019
Heat Detector	Building 400 Lobby 400	Tested	1:52:39 PM	08/22/2019
Heat Detector	Building 400 Lobby A101	Tested	1:47:29 PM	08/22/2019
Heat Detector	Building 400 Men's Restroom 408	Tested	1:55:14 PM	08/22/2019
Heat Detector	Building 400 Prep Storage 429	Tested	1:39:52 PM	08/22/2019
Heat Detector	Building 400 Prep Storage 429	Tested	1:40:19 PM	08/22/2019
Heat Detector	Building 400 Principal Office 403	Tested	1:53:02 PM	08/22/2019
Heat Detector	Building 400 Room 414A	Tested	1:43:08 PM	08/22/2019
Heat Detector	Building 400 Room 414B	Tested	1:43:33 PM	08/22/2019
Heat Detector	Building 400 Science Lab 425	Tested	1:41:43 PM	08/22/2019
Heat Detector	Building 400 Science Lab 425	Tested	1:41:58 PM	08/22/2019
Heat Detector	Building 400 Science Lab 426	Tested	1:41:21 PM	08/22/2019
Heat Detector	Building 400 Science Lab 426	Tested	1:41:33 PM	08/22/2019
Heat Detector	Building 400 Science Lab 427	Tested	1:40:47 PM	08/22/2019
Heat Detector	Building 400 Science Lab 427	Tested	1:41:13 PM	08/22/2019
Heat Detector	Building 400 Science Lab 428	Tested	1:39:03 PM	08/22/2019
Heat Detector	Building 400 Science Lab 428	Tested	1:39:26 PM	08/22/2019
Heat Detector	Building 400 Science Tech Lab 414	Tested	1:42:05 PM	08/22/2019
Heat Detector	Building 400 Science Tech Lab 414	Tested	1:42:34 PM	08/22/2019
Heat Detector	Building 400 Staff Restroom 424	Tested	1:51:32 PM	08/22/2019
Heat Detector	Building 400 Staff Restroom 434	Tested	1:51:04 PM	08/22/2019
Heat Detector	Building 400 Staff Workroom 407	Tested	1:47:02 PM	08/22/2019
Heat Detector	Building 400 Supply Storage 404	Tested	1:54:44 PM	08/22/2019
Heat Detector	Building 400 Women's Restroom 409	Tested	1:55:33 PM	08/22/2019
Heat Detector	Building 500 Room 502	Tested	12:40:27 PM	08/22/2019
Heat Detector	Building 500 Room 502	Tested	12:40:40 PM	08/22/2019
Heat Detector	Building 500 Room 502	Tested	12:41:09 PM	08/22/2019
Heat Detector	Building 500 Room 503	Tested	12:41:17 PM	08/22/2019
Heat Detector	Building 500 Room 503	Tested	12:41:29 PM	08/22/2019
Heat Detector	Building 500 Room 503	Tested	12:41:56 PM	08/22/2019
Heat Detector	Building 500 Room 504	Tested	12:42:04 PM	08/22/2019
Heat Detector	Building 500 Room 504	Tested	12:42:17 PM	08/22/2019
Heat Detector	Building 500 Room 505	Tested	12:42:24 PM	08/22/2019
Heat Detector	Building 500 Room 505	Tested	12:43:26 PM	08/22/2019
Heat Detector	Building 500 Room 505 Office	Tested	12:44:12 PM	08/22/2019
Heat Detector	Building 500 Room 510	Tested	12:39:30 PM	08/22/2019
Heat Detector	Building 500 Room 510	Tested	12:40:05 PM	08/22/2019
Heat Detector	Building 600 Theater Lower Mechanical Room	Tested	1:22:52 PM	08/21/2019
Heat Detector	Building 600 Theater Lower Mechanical Room	Tested	1:23:19 PM	08/21/2019
Heat Detector	Building 600 Theater Lower Mechanical Room	Tested	1:23:32 PM	08/21/2019
Heat Detector	Building 600 Theater Lower Mechanical Room	Tested	1:25:04 PM	08/21/2019
Heat Detector	Building 600 Black Box 607	Tested	1:57:53 PM	08/22/2019
Heat Detector	Building 600 Black Box 607	Tested	1:58:15 PM	08/22/2019
Heat Detector	Building 600 Scene Shop 610	Tested	1:58:27 PM	08/22/2019
Heat Detector	Building 600 Scene Shop 610	Tested	1:58:40 PM	08/22/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	Building 600 Scene Shop 611	Tested	1:57:30 PM	08/22/2019
Heat Detector	Building 600 Stage Room 612	Tested	1:56:18 PM	08/22/2019
Heat Detector	Building 600 Stage Room 612	Tested	1:56:42 PM	08/22/2019
Heat Detector	Building 600 Stage Room 612	Tested	1:56:48 PM	08/22/2019
Heat Detector	Building 600 Stage Room 612	Tested	1:56:54 PM	08/22/2019
Heat Detector	Building 600 Stage Room 612	Tested	1:57:00 PM	08/22/2019
Heat Detector	Building 600 Stage Room 612	Tested	1:57:18 PM	08/22/2019
Heat Detector	Building 700 Boys Locker Room Office	Tested	9:45:20 AM	08/21/2019
Heat Detector	Building 700 Boys Locker Room Office	Tested	9:47:04 AM	08/21/2019
Heat Detector	Building 700 Boys Locker Room Storage Outside	Tested	9:50:41 AM	08/21/2019
Heat Detector	Building 700 Boys Locker Room	Tested	9:39:00 AM	08/21/2019
Heat Detector	Building 700 Boys Locker Room	Tested	9:39:25 AM	08/21/2019
Heat Detector	Building 700 Boys Locker Room	Tested	9:39:43 AM	08/21/2019
Heat Detector	Building 700 Boys Locker Room	Tested	9:39:50 AM	08/21/2019
Heat Detector	Building 700 Boys Locker Room	Tested	9:40:36 AM	08/21/2019
Heat Detector	Building 700 Drying Area 708	Tested	12:48:13 PM	08/22/2019
Heat Detector	Building 700 Staff Shower 716	Tested	12:45:54 PM	08/22/2019
Heat Detector	Building 700 Weight Storage	Tested	12:45:22 PM	08/22/2019
Heat Detector	Building 800 Boys Locker Room	Tested	9:08:30 AM	08/22/2019
Heat Detector	Building 800 Boys Locker Room	Tested	9:09:33 AM	
	-		9:09:33 AM	08/21/2019
Heat Detector	Building 800 Boys Locker Room	Tested	9:09:53 AM	08/21/2019
Heat Detector	Building 800 Boys Locker Room	Tested	9:10:00 AM	08/21/2019
Heat Detector	Building 800 Boys Locker Room	Tested	9:10:10 AM	08/21/2019
Heat Detector	Building 800 Boys Locker Room	Tested	10:12:57 AM	08/21/2019
Heat Detector	Building 800 Girls Locker Room Varsity Room	Tested	10:03:56 AM	08/21/2019
Heat Detector	Building 800 Girls Locker Room	Tested	10:04:46 AM	08/21/2019
Heat Detector	Building 800 Girls Locker Room	Tested	10:05:32 AM	08/21/2019
Heat Detector	Building 800 Girls Locker Room	Tested	10:06:03 AM	08/21/2019
Heat Detector	Building 800 Girls Locker Room	Tested		08/21/2019
Heat Detector	Building 800 Girls Locker Room	Tested	10:07:05 AM	08/21/2019
Heat Detector	Building 900 Gym Centereast 903	Tested	1:00:36 PM	08/22/2019
Heat Detector	Building 900 Gym Centereast 903	Tested	1:00:56 PM	08/22/2019
Heat Detector	Building 900 Gym Centereast 903	Tested	1:01:06 PM	08/22/2019
Heat Detector	Building 900 Gym Centereast 903	Tested	1:01:14 PM	08/22/2019
Heat Detector	Building 900 Gym Centereast 903	Tested	1:01:20 PM	08/22/2019
Heat Detector	Building 900 Gym Centereast 903	Tested	1:01:26 PM	08/22/2019
Heat Detector	Building 900 Gym Centerwest 903	Tested	12:58:25 PM	08/22/2019
Heat Detector	Building 900 Gym Centerwest 903	Tested	12:59:45 PM	08/22/2019
Heat Detector	Building 900 Gym Centerwest 903	Tested	1:00:30 PM	08/22/2019
Heat Detector	Building 900 Gym Centerwest 903	Tested	1:02:25 PM	08/22/2019
Heat Detector	Building 900 Gym Centerwest 903	Tested	1:02:40 PM	08/22/2019
Heat Detector	Building 900 Gym Centerwest 903	Tested	1:02:49 PM	08/22/2019
Heat Detector	Building 900 Gym Northeast 902	Tested	1:07:40 PM	08/22/2019
Heat Detector	Building 900 Gym Northeast 902	Tested	1:08:21 PM	08/22/2019
Heat Detector	Building 900 Gym Northeast 902	Tested	1:08:46 PM	08/22/2019
Heat Detector	Building 900 Gym Northeast 902	Tested	1:10:28 PM	08/22/2019
Heat Detector	Building 900 Gym Northeast 902	Tested	1:10:59 PM	08/22/2019
Heat Detector	Building 900 Gym Northeast 902	Tested	1:11:10 PM	08/22/2019
Heat Detector	Building 900 Gym Northeast 903	Tested	1:03:37 PM	08/22/2019
Heat Detector	Building 900 Gym Northeast 903	Tested	1:04:25 PM	08/22/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	Building 900 Gym Northeast 903	Tested	1:04:32 PM	08/22/2019
Heat Detector	Building 900 Gym Northeast 903	Tested	1:04:41 PM	08/22/2019
Heat Detector	Building 900 Gym Northeast 903	Tested	1:04:51 PM	08/22/2019
Heat Detector	Building 900 Gym Northwest 902	Tested	1:08:59 PM	08/22/2019
Heat Detector	Building 900 Gym Northwest 902	Tested	1:09:40 PM	08/22/2019
Heat Detector	Building 900 Gym Northwest 902	Tested	1:09:50 PM	08/22/2019
Heat Detector	Building 900 Gym Northwest 902	Tested	1:09:59 PM	08/22/2019
Heat Detector	Building 900 Gym Northwest 902	Tested	1:10:08 PM	08/22/2019
Heat Detector	Building 900 Gym Northwest 902	Tested	1:10:18 PM	08/22/2019
Heat Detector	Building 900 Gym Northwest 902 Building 900 Gym Northwest 903	Tested	1:03:13 PM	08/22/2019
Heat Detector	Building 900 Gym Northwest 903	Tested	1:03:29 PM	08/22/2019
Heat Detector	Building 900 Gym Northwest 903	Tested	1:04:59 PM	08/22/2019
Heat Detector	Building 900 Gym Northwest 903	Tested	1:06:09 PM	08/22/2019
Heat Detector	Building 900 Gym Northwest 903	Tested	1:06:23 PM	08/22/2019
Heat Detector	-	Tested	1:11:18 PM	
Heat Detector	Building 900 Gym Southeast 902 Building 900 Gym Southeast 902	Tested	1:11:43 PM	08/22/2019
Heat Detector		Tested	1:11:50 PM	08/22/2019
	Building 900 Gym Southeast 902	Tested	1:14:48 PM	08/22/2019
Heat Detector	Building 900 Gym Southeast 902 Building 900 Gym Southeast 902	Tested	1:15:22 PM	08/22/2019
Heat Detector Heat Detector	C	Tested	1:15:35 PM	08/22/2019
	Building 900 Gym Southeast 902		12:54:57 PM	08/22/2019
Heat Detector	Building 900 Gym Southeast 903	Tested	12:56:21 PM	08/22/2019
Heat Detector	Building 900 Gym Southeast 903	Tested	12:56:27 PM	08/22/2019
Heat Detector	Building 900 Gym Southeast 903	Tested	12:56:32 PM	08/22/2019
Heat Detector	Building 900 Gym Southeast 903	Tested	12:56:40 PM	08/22/2019
Heat Detector	Building 900 Gym Southeast 903	Tested	1:12:00 PM	08/22/2019
Heat Detector	Building 900 Gym Southwest 902	Tested	1:12:16 PM	08/22/2019
Heat Detector	Building 900 Gym Southwest 902	Tested	1:14:00 PM	08/22/2019
Heat Detector	Building 900 Gym Southwest 902	Tested Tested	1:14:27 PM	08/22/2019
Heat Detector	Building 900 Gym Southwest 902	Tested	1:14:37 PM	08/22/2019
Heat Detector	Building 900 Gym Southwest 902		1:14:37 PM	08/22/2019
Heat Detector	Building 900 Gym Southwest 902	Tested	12:57:34 PM	08/22/2019
Heat Detector	Building 900 Gym Southwest 903	Tested Tested	12:58:11 PM	08/22/2019
Heat Detector	Building 900 Gym Southwest 903		12:54:18 PM	08/22/2019
Heat Detector	Building 900 Gym Southwest 903	Tested	12:54:18 PM	08/22/2019
Heat Detector	Building 900 Gym Southwest 903	Tested	12:54:37 PM	08/22/2019
Heat Detector	Building 900 Gym Southwest 903	Tested		08/22/2019
Heat Detector	Building 900 Wrestling Room	Tested	12:53:54 PM	08/22/2019
Heat Detector	Building Pool Men's Restroom	Tested	8:44:16 AM 8:44:55 AM	08/21/2019
Heat Detector	Building Pool Men's Restroom	Tested		08/21/2019
Heat Detector	Building Pool Men's Restroom	Tested	8:45:13 AM	08/21/2019
Heat Detector	Building Pool Men's Restroom	Tested	8:45:35 AM	08/21/2019
Heat Detector	Building Pool Women's Restroom	Tested	8:35:02 AM	08/21/2019
Heat Detector	Building Pool Women's Restroom	Tested	8:35:51 AM 8:36:34 AM	08/21/2019
Heat Detector	Building Pool Women's Restroom	Tested	8:36:34 AM 8:37:07 AM	08/21/2019
Heat Detector	Building Pool Women's Restroom	Tested		08/21/2019
Pull Station	Building 100 Admin North Exit	Tested	2:38:49 PM	08/22/2019
Pull Station	Building 100 Admin Nurse	Tested	2:22:44 PM	08/22/2019
Pull Station	Building 100 Admin Reception	Tested	2:40:50 PM	08/22/2019
Pull Station	Building 100 Admin West Exit	Tested	2:39:46 PM	08/22/2019
Pull Station	Building 300 Classroom 333 Exit	Tested	12:28:38 PM	08/21/2019

Device Type	Location	Service	Time	Date
	Passed			
Pull Station	Building 300 Kitchen	Tested	1:43:53 PM	08/20/2019
Pull Station	Building 300 Kitchen Exit	Tested	1:40:56 PM	08/20/2019
Pull Station	Building 300 Lecture Hall Backstage	Tested	2:16:09 PM	08/20/2019
Pull Station	Building 300 Lecture Hall Backstage	Tested	2:18:24 PM	08/20/2019
Pull Station	Building 300 Lecture Hall Northeast Exit	Tested	2:11:15 PM	08/20/2019
Pull Station	Building 300 Lecture Hall Northeast Exit	Tested	2:12:58 PM	08/20/2019
Pull Station	Building 600 Theater Northeast Exit	Tested	1:56:36 PM	08/21/2019
Pull Station	Building 600 Theater Northwest Exit	Tested	1:58:33 PM	08/21/2019
Pull Station	Building 600 Theater Southeast Exit	Tested	1:15:18 PM	08/21/2019
Pull Station	Building 600 Theater Southwest Exit	Tested	2:00:07 PM	08/21/2019
Pull Station	Building 900 Big Gym NE Exit	Tested	8:18:31 AM	08/22/2019
Pull Station	Building 900 Big Gym NW Exit	Tested	8:19:47 AM	08/22/2019
Pull Station	Building 900 Big Gym SE Exit	Tested	8:17:12 AM	08/22/2019
Pull Station	Building 900 Big Gym SW Exit	Tested	8:22:15 AM	08/22/2019
Pull Station	Building 900 Little Gym North Exit	Tested	8:02:26 AM	08/22/2019
Pull Station	Building 900 Little Gym SE Exit	Tested	8:00:36 AM	08/22/2019
Pull Station	Building 900 Little Gym West Exit	Tested	8:03:36 AM	08/22/2019
Pull Station	Building 900 East Lobby	Tested	8:14:10 AM	08/21/2019
Pull Station	Building 900 East Lobby	Tested	8:15:26 AM	08/21/2019
Pull Station	Building Pool Snack Bar	Tested	8:54:05 AM	08/21/2019
Pull Station	Building Pool West Wall	Tested	8:53:25 AM	08/21/2019
Smoke Detector	1st Building 400 Classroom 410	Tested	1:06:21 PM	08/22/2019
Smoke Detector	1st Building 400 Classroom 410	Tested	1:06:57 PM	08/22/2019
Smoke Detector	1st Building 400 Classroom 411	Tested	1:05:04 PM	08/22/2019
Smoke Detector	1st Building 400 Classroom 411	Tested	1:05:11 PM	08/22/2019
Smoke Detector	1st Building 400 Classroom 412	Tested	1:02:11 PM	08/22/2019
Smoke Detector	1st Building 400 Classroom 412	Tested	1:03:42 PM	08/22/2019
Smoke Detector	1st Building 400 Classroom 413	Tested	12:59:55 PM	08/22/2019
Smoke Detector	1st Building 400 Classroom 413	Tested	1:00:13 PM	08/22/2019
Smoke Detector	1st Building 400 Conference Room 402	Tested	1:15:17 PM	08/22/2019
Smoke Detector	1st Building 400 Copy Room 405	Tested	1:18:09 PM	08/22/2019
Smoke Detector	1st Building 400 Electrical Room 406	Tested	1:19:15 PM	08/22/2019
Smoke Detector	1st Building 400 Office Lobby 400	Tested	1:14:18 PM	08/22/2019
Smoke Detector	1st Building 400 Office Lobby 400	Tested	1:15:10 PM	08/22/2019
Smoke Detector	1st Building 400 Office Lobby 400	Tested	1:18:01 PM	08/22/2019
Smoke Detector	1st Building 400 Office Lobby Foyer 400	Tested	1:13:33 PM	08/22/2019
Smoke Detector	1st Building 400 Office Room 403	Tested	1:16:07 PM	08/22/2019
Smoke Detector	1st Building 400 Office Room 404	Tested	1:16:57 PM	08/22/2019
Smoke Detector	1st Building 400 Staff Workroom 407	Tested	1:08:02 PM	08/22/2019
Smoke Detector	1st Building 400 Staff Workroom 407	Tested	1:08:22 PM	08/22/2019
Smoke Detector	1st Building 400 Staff Workroom Restroom	Tested	1:09:26 PM	08/22/2019
Smoke Detector	1st Building 400 Staff Workroom Restroom	Tested	1:10:54 PM	08/22/2019
Smoke Detector	1st Building 500 Boy's Restroom	Tested	1:52:06 PM	08/22/2019
Smoke Detector	1st Building 500 Classroom 501	Tested	1:44:36 PM	08/22/2019
Smoke Detector	1st Building 500 Classroom 501	Tested	1:45:05 PM	08/22/2019
Smoke Detector	1st Building 500 Classroom 502 Office	Tested	1:42:57 PM	08/22/2019
Smoke Detector	1st Building 500 Classroom 502	Tested	1:43:16 PM	08/22/2019
Smoke Detector	1st Building 500 Classroom 502	Tested	1:43:26 PM	08/22/2019
Smoke Detector	1st Building 500 Classroom 503 Office	Tested	1:40:29 PM	08/22/2019
Smoke Detector	1st Building 500 Classroom 503	Tested	1:39:55 PM	08/22/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	1st Building 500 Classroom 503	Tested	1:40:05 PM	08/22/2019
Smoke Detector	1st Building 500 Classroom 503	Tested	1:40:11 PM	08/22/2019
Smoke Detector	1st Building 500 Classroom 503	Tested	1:40:18 PM	08/22/2019
Smoke Detector	1st Building 500 Classroom 504 Office	Tested	1:34:29 PM	08/22/2019
Smoke Detector	1st Building 500 Classroom 504 Outside Storage Room	Tested	1:36:03 PM	08/22/2019
Smoke Detector	1st Building 500 Classroom 504	Tested	1:33:01 PM	08/22/2019
Smoke Detector	1st Building 500 Classroom 504	Tested	1:33:14 PM	08/22/2019
Smoke Detector	1st Building 500 Classroom 504	Tested	1:33:21 PM	08/22/2019
Smoke Detector	1st Building 500 Classroom 505 Damp Room	Tested	1:26:50 PM	08/22/2019
Smoke Detector	1st Building 500 Classroom 505 Office	Tested	1:26:06 PM	08/22/2019
Smoke Detector	1st Building 500 Classroom 505 Storage Room	Tested	1:26:24 PM	08/22/2019
Smoke Detector	1st Building 500 Classroom 505	Tested	1:23:56 PM	08/22/2019
Smoke Detector	1st Building 500 Classroom 505	Tested	1:25:05 PM	08/22/2019
Smoke Detector	1st Building 500 Girl's Restroom	Tested	1:47:13 PM	08/22/2019
Smoke Detector	1st Building 500 SE Mechanical Room Near Car Roundabout	Tested	1:54:41 PM	08/22/2019
Smoke Detector	1st Building 500 Unisex Restroom	Tested	1:50:06 PM	08/22/2019
Smoke Detector	1st Building 500 Unisex Restroom	Tested	1:51:52 PM	08/22/2019
Smoke Detector	1st Building 900 Ticket Booth	Tested	2:15:07 PM	08/22/2019
Smoke Detector	2nd Building 400 Classroom 420	Tested	12:44:46 PM	08/22/2019
Smoke Detector	2nd Building 400 Classroom 420	Tested	12:44:58 PM	08/22/2019
Smoke Detector	2nd Building 400 Classroom 421	Tested	12:45:30 PM	08/22/2019
Smoke Detector	2nd Building 400 Classroom 421	Tested	12:46:19 PM	08/22/2019
Smoke Detector	2nd Building 400 Classroom 422	Tested	12:46:48 PM	08/22/2019
Smoke Detector	2nd Building 400 Classroom 422	Tested	12:47:40 PM	08/22/2019
Smoke Detector	2nd Building 400 Classroom 423	Tested	12:48:02 PM	08/22/2019
Smoke Detector	2nd Building 400 Classroom 423	Tested	12:48:36 PM	08/22/2019
Smoke Detector	2nd Building 400 Classroom 425	Tested	12:22:39 PM	08/22/2019
Smoke Detector	2nd Building 400 Classroom 425	Tested	12:23:36 PM	08/22/2019
Smoke Detector	2nd Building 400 Classroom 426	Tested	12:21:33 PM	08/22/2019
Smoke Detector	2nd Building 400 Classroom 426	Tested	12:22:13 PM	08/22/2019
Smoke Detector	2nd Building 400 Classroom 427	Tested	12:20:07 PM	08/22/2019
Smoke Detector	2nd Building 400 Classroom 427	Tested	12:20:21 PM	08/22/2019
Smoke Detector	2nd Building 400 Classroom 428	Tested	12:17:40 PM	08/22/2019
Smoke Detector	2nd Building 400 Classroom 428	Tested	12:17:59 PM	08/22/2019
Smoke Detector	2nd Building 400 Prep Room Storage Behind Classrooms 425–428	Tested	12:24:24 PM	08/22/2019
Smoke Detector	2nd Building 400 Prep Room Storage Behind Classrooms 425–428	Tested	12:27:21 PM	08/22/2019
Smoke Detector	2nd Building 400 Prep Room Storage Behind Classrooms 425–428	Tested	12:27:30 PM	08/22/2019
Smoke Detector	2nd Building 400 Staff Restroom	Tested	12:49:01 PM	08/22/2019
Smoke Detector	2nd Building 400 Telecom Room	Tested	12:52:18 PM	08/22/2019
Smoke Detector	3rd Building 400 Classroom 430	Tested	12:42:48 PM	08/22/2019
Smoke Detector	3rd Building 400 Classroom 430	Tested	12:43:02 PM	08/22/2019
Smoke Detector	3rd Building 400 Classroom 431	Tested	12:41:27 PM	08/22/2019
Smoke Detector	3rd Building 400 Classroom 431	Tested	12:41:38 PM	08/22/2019
Smoke Detector	3rd Building 400 Classroom 432	Tested	12:38:54 PM	08/22/2019
Smoke Detector	3rd Building 400 Classroom 432	Tested	12:39:07 PM	08/22/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	3rd Building 400 Classroom 433	Tested	12:37:44 PM	08/22/2019
Smoke Detector	3rd Building 400 Classroom 433	Tested	12:38:46 PM	08/22/2019
Smoke Detector	3rd Building 400 Staff Restroom	Tested	12:36:19 PM	08/22/2019
Smoke Detector	3rd Building 400 Telecom Room	Tested	12:32:48 PM	08/22/2019
Smoke Detector	Building 100 Admin Attendance Office 101	Tested	2:47:59 PM	08/22/2019
Smoke Detector	Building 100 Admin Counselor 126	Tested	2:11:19 PM	08/22/2019
Smoke Detector	Building 100 Admin Electrical Closet	Tested	2:33:05 PM	08/22/2019
Smoke Detector	Building 100 Admin Exit	Tested	2:09:49 PM	08/22/2019
Smoke Detector	Building 100 Admin Hallway	Tested	2:29:06 PM	08/22/2019
Smoke Detector	Building 100 Admin Hallway	Tested	2:36:47 PM	08/22/2019
Smoke Detector	Building 100 Admin Hallway South	Tested	2:40:23 PM	08/22/2019
Smoke Detector	Building 100 Admin Kitchen	Tested	2:38:05 PM	08/22/2019
Smoke Detector	Building 100 Admin Mail Room 103	Tested	2:44:19 PM	08/22/2019
Smoke Detector	Building 100 Admin Office 104	Tested	2:42:32 PM	08/22/2019
Smoke Detector	Building 100 Admin Office 105	Tested	2:41:53 PM	08/22/2019
Smoke Detector	Building 100 Admin Office 106	Tested	2:39:06 PM	08/22/2019
Smoke Detector	Building 100 Admin Office 107	Tested	2:34:59 PM	08/22/2019
Smoke Detector	Building 100 Admin Office 108	Tested	2:17:39 PM	08/22/2019
Smoke Detector	Building 100 Admin Office 109	Tested	2:17:02 PM	08/22/2019
Smoke Detector	Building 100 Admin Office 110	Tested	2:15:58 PM	08/22/2019
Smoke Detector	Building 100 Admin Office 112	Tested	2:13:54 PM	08/22/2019
Smoke Detector	Building 100 Admin Office 118	Tested	2:15:33 PM	08/22/2019
Smoke Detector	Building 100 Admin Office 122	Tested	2:13:32 PM	08/22/2019
Smoke Detector	Building 100 Admin Reception	Tested	2:45:21 PM	08/22/2019
Smoke Detector	Building 100 Admin Secretary	Tested	2:07:30 PM	08/22/2019
Smoke Detector	Building 100 Admin Secretary	Tested	2:11:13 PM	08/22/2019
Smoke Detector	Building 100 Admin Secretary Closet	Tested	2:08:48 PM	08/22/2019
Smoke Detector	Building 100 Admin Secretary Storage	Tested	2:08:21 PM	08/22/2019
Smoke Detector	Building 100 Admin Staff Restroom	Tested	2:31:05 PM	08/22/2019
Smoke Detector	Building 100 Admin Staff Restroom	Tested	2:31:21 PM	08/22/2019
Smoke Detector	Building 100 Admin Storage 102	Tested	2:48:51 PM	08/22/2019
Smoke Detector	Building 100 Admin Storage 112	Tested	2:19:50 PM	08/22/2019
Smoke Detector	Building 100 Admin Storage 124	Tested	2:12:51 PM	08/22/2019
Smoke Detector	Building 100 Admin Data Room	Tested	8:57:29 AM	08/20/2019
Smoke Detector	Building 100 Admin Nurse Boy's Restroom	Tested	2:32:57 PM	08/22/2019
Smoke Detector	Building 100 Admin Nurse Girl's Restroom	Tested	2:31:01 PM	08/22/2019
Smoke Detector	Building 100 Admin Nurse Reception	Tested	2:26:08 PM	08/22/2019
Smoke Detector	Building 100 Admin Nurse Restroom	Tested	2:24:56 PM	08/22/2019
Smoke Detector	Building 100 Admin Nurse	Tested	2:22:22 PM	08/22/2019
Smoke Detector	Building 200 Corridor By Classroom 201B	Tested	9:01:44 AM	08/20/2019
Smoke Detector	Building 200 Corridor By Classroom 205	Tested	10:26:24 AM	08/20/2019
Smoke Detector	Building 200 Corridor By Classroom 210	Tested	10:17:14 AM	08/20/2019
Smoke Detector	Building 200 Corridor By Classroom 213	Tested	10:16:01 AM	08/20/2019
Smoke Detector	Building 200 Corridor By Classroom 214	Tested	10:14:13 AM	08/20/2019
Smoke Detector	Building 200 Corridor By Classroom 216	Tested	10:25:13 AM	08/20/2019
Smoke Detector	Building 200 Corridor By Classroom 219	Tested	10:39:59 AM	08/20/2019
Smoke Detector	Building 200 Corridor By Classroom 221	Tested	10:43:14 AM	08/20/2019
Smoke Detector	Building 200 Corridor By Classroom 222	Tested	9:03:29 AM	08/20/2019
Smoke Detector	Building 200 Corridor By Classroom 222	Tested	9:12:25 AM	08/20/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building 200 Corridor By Classroom 227	Tested	9:14:01 AM	08/20/2019
Smoke Detector	Building 200 Corridor By Classroom 227	Tested	10:45:33 AM	08/20/2019
Smoke Detector	Building 200 Corridor By Classroom 228	Tested	9:14:28 AM	08/20/2019
Smoke Detector	Building 200 Corridor By Classroom 230	Tested	9:18:05 AM	08/20/2019
Smoke Detector	Building 200 Corridor By Classroom 232	Tested	9:25:07 AM	08/20/2019
Smoke Detector	Building 200 Corridor By Classroom 234	Tested	9:28:37 AM	08/20/2019
Smoke Detector	Building 200 Corridor By Classroom 237	Tested	10:13:26 AM	08/20/2019
Smoke Detector	Building 200 Corridor By Classroom 238	Tested	10:06:44 AM	08/20/2019
Smoke Detector	Building 200 Corridor By Classroom 240	Tested	10:09:43 AM	08/20/2019
Smoke Detector	Building 200 Corridor By Classroom 265	Tested	10:39:22 AM	08/20/2019
Smoke Detector	Building 200 Corridor By Classroom 268	Tested	10:29:14 AM	08/20/2019
Smoke Detector	Building 200 Corridor By Learning Resource 250	Tested	9:35:35 AM	08/20/2019
Smoke Detector	Building 200 Corridor By Learning Resource 250	Tested	9:52:40 AM	08/20/2019
Smoke Detector	Building 200 Corridor By West Restroom	Tested	10:20:18 AM	08/20/2019
Smoke Detector	Building 200 Learning Resource 250 Exit	Tested	9:42:29 AM	08/20/2019
Smoke Detector	Building 200 Learning Resource 250 Multimedia 254	Tested	9:41:02 AM	08/20/2019
Smoke Detector	Building 200 Learning Resource 250 Multimedia 254	Tested	9:41:58 AM	08/20/2019
Smoke Detector	Building 200 Learning Resource 250 Office 255	Tested	9:40:25 AM	08/20/2019
Smoke Detector	Building 200 Learning Resource 250 Office 256	Tested	9:39:21 AM	08/20/2019
Smoke Detector	Building 200 Learning Resource 250 Reception	Tested	9:39:53 AM	08/20/2019
Smoke Detector	Building 200 Learning Resource 250 Storage 257	Tested	9:38:41 AM	08/20/2019
Smoke Detector	Building 200 Learning Resource 250 Study Room 252	Tested	9:49:13 AM	08/20/2019
Smoke Detector	Building 200 Learning Resource 250 Study Room 252	Tested	9:49:38 AM	08/20/2019
Smoke Detector	Building 200 Learning Resource 250 Study Room 253	Tested	9:48:29 AM	08/20/2019
Smoke Detector	Building 200 Learning Resource 250	Tested	9:43:18 AM	08/20/2019
Smoke Detector	Building 200 Learning Resource 250	Tested	9:44:31 AM	08/20/2019
Smoke Detector	Building 200 Learning Resource 250	Tested	9:45:30 AM	08/20/2019
Smoke Detector	Building 200 Learning Resource 250	Tested	9:45:42 AM	08/20/2019
Smoke Detector	Building 200 Learning Resource 250	Tested	9:46:18 AM	08/20/2019
Smoke Detector	Building 200 Learning Resource 250	Tested	9:50:38 AM	08/20/2019
Smoke Detector	Building 200 Athletics Office	Tested	8:21:41 AM	08/21/2019
Smoke Detector	Building 200 Athletics Office	Tested	8:25:50 AM	08/21/2019
Smoke Detector	Building 200 Athletics Office Reception	Tested	8:27:23 AM	08/21/2019
Smoke Detector	Building 200 Athletics Office Storage	Tested	8:23:13 AM	08/21/2019
Smoke Detector	Building 200 Athletics Office Storage	Tested	8:26:53 AM	08/21/2019
Smoke Detector	Building 200 Athletics Office Storage Restroom	Tested	8:23:46 AM	08/21/2019
Smoke Detector	Building 200 Book Storage 217	Tested	10:34:33 AM	08/20/2019
Smoke Detector	Building 200 Classroom 202	Tested	10:51:48 AM	08/20/2019
Smoke Detector	Building 200 Classroom 203	Tested	10:52:20 AM	08/20/2019
Smoke Detector	Building 200 Classroom 204	Tested	10:53:11 AM	08/20/2019
Smoke Detector	Building 200 Classroom 205	Tested	10:27:00 AM	08/20/2019
Smoke Detector	Building 200 Classroom 206	Tested	10:54:29 AM	08/20/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building 200 Classroom 207	Tested	10:55:29 AM	08/20/2019
Smoke Detector	Building 200 Classroom 208	Tested	10:57:22 AM	08/20/2019
Smoke Detector	Building 200 Classroom 209	Tested	10:58:22 AM	08/20/2019
Smoke Detector	Building 200 Classroom 210	Tested	10:17:33 AM	08/20/2019
Smoke Detector	Building 200 Classroom 211	Tested	10:22:22 AM	08/20/2019
Smoke Detector	Building 200 Classroom 212	Tested	10:16:16 AM	08/20/2019
Smoke Detector	Building 200 Classroom 213	Tested	10:22:49 AM	08/20/2019
Smoke Detector	Building 200 Classroom 214	Tested	10:14:39 AM	08/20/2019
Smoke Detector	Building 200 Classroom 215	Tested	10:23:59 AM	08/20/2019
Smoke Detector	Building 200 Classroom 216	Tested	10:25:36 AM	08/20/2019
Smoke Detector	Building 200 Classroom 218	Tested	10:41:37 AM	08/20/2019
Smoke Detector	Building 200 Classroom 219	Tested	10:40:49 AM	08/20/2019
Smoke Detector	Building 200 Classroom 220	Tested	10:42:42 AM	08/20/2019
Smoke Detector	Building 200 Classroom 221	Tested	10:43:41 AM	08/20/2019
Smoke Detector	Building 200 Classroom 222	Tested	9:06:08 AM	08/20/2019
Smoke Detector	Building 200 Classroom 223	Tested	9:07:46 AM	08/20/2019
Smoke Detector	Building 200 Classroom 224	Tested	9:09:29 AM	08/20/2019
Smoke Detector	Building 200 Classroom 224	Tested	9:09:42 AM	08/20/2019
Smoke Detector	Building 200 Classroom 225	Tested	10:47:38 AM	08/20/2019
Smoke Detector	Building 200 Classroom 226	Tested	9:11:44 AM	08/20/2019
Smoke Detector	Building 200 Classroom 227	Tested	9:13:42 AM	08/20/2019
Smoke Detector	Building 200 Classroom 228	Tested	9:14:43 AM	08/20/2019
Smoke Detector	Building 200 Classroom 229	Tested	9:16:11 AM	08/20/2019
Smoke Detector	Building 200 Classroom 230	Tested	9:18:44 AM	08/20/2019
Smoke Detector	Building 200 Classroom 231	Tested	9:19:40 AM	08/20/2019
Smoke Detector	Building 200 Classroom 231	Tested	9:21:57 AM	08/20/2019
Smoke Detector	Building 200 Classroom 232	Tested	9:22:09 AM	08/20/2019
Smoke Detector	Building 200 Classroom 232	Tested	9:23:41 AM	08/20/2019
Smoke Detector	Building 200 Classroom 232	Tested	9:24:04 AM	08/20/2019
Smoke Detector	Building 200 Classroom 234	Tested	9:26:29 AM	08/20/2019
Smoke Detector	Building 200 Classroom 234	Tested	9:26:56 AM	08/20/2019
Smoke Detector	Building 200 Classroom 234	Tested	9:27:41 AM	08/20/2019
Smoke Detector	Building 200 Classroom 235	Tested	9:25:32 AM	08/20/2019
Smoke Detector	Building 200 Classroom 236	Tested	9:53:39 AM	08/20/2019
Smoke Detector	Building 200 Classroom 236	Tested	9:54:04 AM	08/20/2019
Smoke Detector	Building 200 Classroom 236	Tested	9:55:00 AM	08/20/2019
Smoke Detector	Building 200 Classroom 236	Tested	9:55:16 AM	08/20/2019
Smoke Detector	Building 200 Classroom 237	Tested	10:11:49 AM	08/20/2019
Smoke Detector	Building 200 Classroom 238	Tested	10:07:02 AM	08/20/2019
Smoke Detector	Building 200 Classroom 239	Tested	10:10:01 AM	08/20/2019
Smoke Detector	Building 200 Classroom 240	Tested	10:08:02 AM	08/20/2019
Smoke Detector	Building 200 Classroom 240	Tested	10:09:19 AM	08/20/2019
Smoke Detector	Building 200 Classroom 240 Building 200 Classroom 242	Tested	9:58:00 AM	08/20/2019
Smoke Detector	Building 200 Classroom 242	Tested	9:59:18 AM	08/20/2019
Smoke Detector	-	Tested	10:02:35 AM	
	Building 200 Classroom 242 By Restroom		10:00:32 AM	08/20/2019
Smoke Detector Smoke Detector	Building 200 Classroom 242 Conference Room	Tested Tested	10:01:01 AM	08/20/2019
Smoke Detector	Building 200 Classroom 242 Restroom	Tested	9:55:28 AM	08/20/2019
	Building 200 Classroom 243	Tested	9:55:38 AM	08/20/2019
Smoke Detector	Building 200 Classroom 243	Tested	10:38:42 AM	08/20/2019
Smoke Detector	Building 200 Classroom 265	Tested	10.30.42 AM	08/20/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building 200 Classroom 266	Tested	10:37:17 AM	08/20/2019
Smoke Detector	Building 200 Classroom 267	Tested	10:36:39 AM	08/20/2019
Smoke Detector	Building 200 Classroom 268	Tested	10:35:41 AM	08/20/2019
Smoke Detector	Building 200 Electrical Room 258	Tested	9:29:12 AM	08/20/2019
Smoke Detector	Building 200 Learning Resource 250	Tested	9:37:02 AM	08/20/2019
Smoke Detector	Building 200 Room 262	Tested	10:30:44 AM	08/20/2019
Smoke Detector	Building 200 Room 262	Tested	10:31:47 AM	08/20/2019
Smoke Detector	Building 200 Room 262	Tested	10:32:15 AM	08/20/2019
Smoke Detector	Building 200 Storage Room	Tested	10:28:19 AM	08/20/2019
Smoke Detector	Building 200 West Restroom	Tested	10:19:32 AM	08/20/2019
Smoke Detector	Building 200 West Restroom	Tested	10:20:07 AM	08/20/2019
Smoke Detector	Building 300 Corridor By Classroom 307	Tested	2:33:41 PM	08/20/2019
Smoke Detector	Building 300 Corridor By Classroom 308	Tested	2:34:12 PM	08/20/2019
Smoke Detector	Building 300 Corridor By Classroom 309	Tested	2:38:21 PM	08/20/2019
Smoke Detector	Building 300 Corridor By Classroom 311	Tested	2:38:58 PM	08/20/2019
Smoke Detector	Building 300 Corridor By Classroom 315	Tested	12:29:48 PM	08/20/2019
Smoke Detector	Building 300 Corridor By Classroom 316	Tested	12:31:14 PM	08/20/2019
Smoke Detector	Building 300 Corridor By Classroom 317	Tested	12:41:20 PM	08/20/2019
Smoke Detector	Building 300 Corridor By Classroom 320	Tested	12:56:42 PM	08/20/2019
Smoke Detector	Building 300 Corridor By Classroom 321	Tested	12:59:27 PM	08/20/2019
Smoke Detector	Building 300 Corridor By Classroom 323	Tested	1:16:27 PM	08/20/2019
Smoke Detector	Building 300 Corridor By Classroom 324	Tested	1:15:50 PM	08/20/2019
Smoke Detector	Building 300 Corridor By Classroom 329	Tested	1:31:51 PM	08/20/2019
Smoke Detector	Building 300 Corridor By Classroom 330	Tested	1:14:58 PM	08/20/2019
Smoke Detector	Building 300 Corridor By Classroom 330	Tested	1:15:30 PM	08/20/2019
Smoke Detector	Building 300 Corridor By Classroom 332	Tested	1:50:16 PM	08/20/2019
Smoke Detector	Building 300 Corridor By Classroom 332	Tested	2:25:53 PM	08/20/2019
Smoke Detector	Building 300 Corridor By Conference Room	Tested	1:33:30 PM	08/20/2019
Smoke Detector	Building 300 Corridor By Girls Restroom	Tested	2:26:12 PM	08/20/2019
Smoke Detector	Building 300 Corridor By Maintenance Room	Tested	2:00:16 PM	08/20/2019
Smoke Detector	Building 300 Corridor By North Boys Restroom	Tested	2:36:40 PM	08/20/2019
Smoke Detector	Building 300 Corridor By Staff Dinning	Tested	1:49:01 PM	08/20/2019
Smoke Detector	Building 300 Corridor By Staff Lounge	Tested	1:32:34 PM	08/20/2019
Smoke Detector	Building 300 Corridor By Staff Lounge	Tested	1:33:09 PM	08/20/2019
Smoke Detector	Building 300 Classroom 301	Tested	12:31:34 PM	08/20/2019
Smoke Detector	Building 300 Classroom 301	Tested	12:31:52 PM	08/20/2019
Smoke Detector	Building 300 Classroom 307	Tested	2:32:07 PM	08/20/2019
Smoke Detector	Building 300 Classroom 307	Tested	2:32:32 PM	08/20/2019
Smoke Detector	Building 300 Classroom 309	Tested	7:59:58 AM	08/21/2019
Smoke Detector	Building 300 Classroom 309	Tested	8:01:37 AM	08/21/2019
Smoke Detector	Building 300 Classroom 309	Tested	8:01:51 AM	08/21/2019
Smoke Detector	Building 300 Classroom 309	Tested	8:03:30 AM	08/21/2019
Smoke Detector	Building 300 Classroom 309	Tested	8:03:50 AM	08/21/2019
Smoke Detector	Building 300 Classroom 309	Tested	8:03:55 AM	08/21/2019
Smoke Detector	Building 300 Classroom 309 Electrical Room	Tested	8:02:20 AM	08/21/2019
Smoke Detector	Building 300 Classroom 310	Tested	2:42:10 PM	08/20/2019
Smoke Detector	Building 300 Classroom 311	Tested	2:39:16 PM	08/20/2019
Smoke Detector	Building 300 Classroom 312	Tested	2:43:15 PM	08/20/2019
Smoke Detector	Building 300 Classroom 313	Tested	2:40:49 PM	08/20/2019
Smoke Detector	Building 300 Classroom 314	Tested	2:43:59 PM	08/20/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building 300 Classroom 315	Tested	12:30:16 PM	08/20/2019
Smoke Detector	Building 300 Classroom 316	Tested	12:37:25 PM	08/20/2019
Smoke Detector	Building 300 Classroom 316	Tested	12:37:39 PM	08/20/2019
Smoke Detector	Building 300 Classroom 317	Tested	12:41:49 PM	08/20/2019
Smoke Detector	Building 300 Classroom 317	Tested	12:42:30 PM	08/20/2019
Smoke Detector	Building 300 Classroom 318	Tested	12:49:12 PM	08/20/2019
Smoke Detector	Building 300 Classroom 318	Tested	12:50:01 PM	08/20/2019
Smoke Detector	Building 300 Classroom 319	Tested	12:52:33 PM	08/20/2019
Smoke Detector	Building 300 Classroom 319	Tested	12:53:18 PM	08/20/2019
Smoke Detector	Building 300 Classroom 319	Tested	12:53:29 PM	08/20/2019
Smoke Detector	Building 300 Classroom 319	Tested	12:54:12 PM	08/20/2019
Smoke Detector	Building 300 Classroom 319	Tested	12:58:42 PM	08/20/2019
Smoke Detector	Building 300 Classroom 320	Tested	12:57:16 PM	08/20/2019
Smoke Detector	Building 300 Classroom 321	Tested	12:59:41 PM	08/20/2019
Smoke Detector	Building 300 Classroom 321	Tested	1:00:14 PM	08/20/2019
Smoke Detector	Building 300 Classroom 322	Tested	1:01:12 PM	08/20/2019
Smoke Detector	Building 300 Classroom 323	Tested	1:03:17 PM	08/20/2019
Smoke Detector	Building 300 Classroom 323	Tested	1:04:40 PM	08/20/2019
Smoke Detector	Building 300 Classroom 323 Workroom	Tested	1:05:27 PM	08/20/2019
Smoke Detector	Building 300 Classroom 323 Workroom	Tested	1:08:32 PM	08/20/2019
Smoke Detector	Building 300 Classroom 323 Workroom	Tested	1:08:37 PM	08/20/2019
Smoke Detector	Building 300 Classroom 324	Tested	1:16:54 PM	08/20/2019
Smoke Detector	Building 300 Classroom 324	Tested	1:17:07 PM	08/20/2019
Smoke Detector	Building 300 Classroom 326	Tested	1:21:07 PM	08/20/2019
Smoke Detector	Building 300 Classroom 326	Tested	1:22:20 PM	08/20/2019
Smoke Detector	Building 300 Classroom 327	Tested	1:29:30 PM	08/20/2019
Smoke Detector	Building 300 Classroom 328	Tested	1:25:09 PM	08/20/2019
Smoke Detector	Building 300 Classroom 329	Tested	1:12:25 PM	08/20/2019
Smoke Detector	Building 300 Classroom 329 Workroom	Tested	1:14:16 PM	08/20/2019
Smoke Detector	Building 300 Classroom 330	Tested	1:07:43 PM	08/20/2019
Smoke Detector	Building 300 Classroom 330	Tested	1:08:03 PM	08/20/2019
Smoke Detector	Building 300 Classroom 331	Tested	1:09:49 PM	08/20/2019
Smoke Detector	Building 300 Classroom 331	Tested	1:10:25 PM	08/20/2019
Smoke Detector	Building 300 Classroom 331	Tested	1:10:48 PM	08/20/2019
Smoke Detector	Building 300 Classroom 332	Tested	12:21:10 PM	08/21/2019
Smoke Detector	Building 300 Classroom 332	Tested	12:21:58 PM	08/21/2019
Smoke Detector	Building 300 Classroom 332	Tested	12:22:27 PM	08/21/2019
Smoke Detector	Building 300 Classroom 332	Tested	12:22:48 PM	08/21/2019
Smoke Detector	Building 300 Classroom 333 Exit	Tested	12:26:59 PM	08/21/2019
Smoke Detector	Building 300 Classroom Workroom	Tested	1:22:39 PM	08/20/2019
Smoke Detector	Building 300 Classroom Workroom	Tested	1:23:23 PM	08/20/2019
Smoke Detector	Building 300 Classroom Workroom	Tested	1:24:17 PM	08/20/2019
Smoke Detector	Building 300 Conference Room	Tested	1:34:10 PM	08/20/2019
Smoke Detector	Building 300 Conference Room	Tested	1:34:52 PM	08/20/2019
Smoke Detector	Building 300 Copy Room	Tested	12:40:47 PM	08/20/2019
Smoke Detector	Building 300 Electrical Room By 301	Tested	12:36:24 PM	08/20/2019
Smoke Detector	Building 300 Electrical Room By 318	Tested	12:46:51 PM	08/20/2019
Smoke Detector	Building 300 Electrical Room West Outside	Tested	12:25:25 PM	08/21/2019
Smoke Detector	Building 300 Kitchen	Tested	1:41:38 PM	08/20/2019
Smoke Detector	Building 300 Kitchen	Tested	1:42:09 PM	08/20/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building 300 Kitchen	Tested	1:43:20 PM	08/20/2019
Smoke Detector	Building 300 Kitchen	Tested	1:43:30 PM	08/20/2019
Smoke Detector	Building 300 Kitchen	Tested	1:43:42 PM	08/20/2019
Smoke Detector	Building 300 Kitchen Restroom	Tested	1:42:28 PM	08/20/2019
Smoke Detector	Building 300 Lecture Hall Backstage	Tested	2:17:10 PM	08/20/2019
Smoke Detector	Building 300 Lecture Hall Backstage	Tested	2:17:29 PM	08/20/2019
Smoke Detector	Building 300 Lecture Hall Backstage Ramp	Tested	2:19:23 PM	08/20/2019
Smoke Detector	Building 300 Lecture Hall Backstage Ramp	Tested	2:20:02 PM	08/20/2019
Smoke Detector	Building 300 Lecture Hall North	Tested	2:13:54 PM	08/20/2019
Smoke Detector	Building 300 Lecture Hall West Exit	Tested	2:09:43 PM	08/20/2019
Smoke Detector	Building 300 Maintenance Room	Tested	2:01:10 PM	08/20/2019
Smoke Detector	Building 300 Office	Tested	1:19:30 PM	08/20/2019
Smoke Detector	Building 300 Prep Room	Tested	12:55:24 PM	08/20/2019
Smoke Detector	Building 300 Room 333	Tested	1:54:53 PM	08/20/2019
Smoke Detector	Building 300 Room 333	Tested	1:55:18 PM	08/20/2019
Smoke Detector	Building 300 Room 333	Tested	1:55:25 PM	08/20/2019
Smoke Detector	Building 300 Room 333	Tested	1:56:20 PM	08/20/2019
Smoke Detector	Building 300 Room 333	Tested	1:56:37 PM	08/20/2019
Smoke Detector	Building 300 Room 333	Tested	1:57:21 PM	08/20/2019
Smoke Detector	Building 300 Room 333B	Tested	1:54:15 PM	08/20/2019
Smoke Detector	Building 300 Staff Dinning	Tested	1:38:05 PM	08/20/2019
Smoke Detector	Building 300 Staff Dinning	Tested	1:40:11 PM	08/20/2019
Smoke Detector	Building 300 Storage Room	Tested	1:27:41 PM	08/20/2019
Smoke Detector	Building 300 Storage Room	Tested	2:02:14 PM	08/20/2019
Smoke Detector	Building 300 Teachers Lounge	Tested	1:35:15 PM	08/20/2019
Smoke Detector	Building 300 Teachers Lounge	Tested	1:36:09 PM	08/20/2019
Smoke Detector	Building 300 Teachers Lounge	Tested	1:36:31 PM	08/20/2019
Smoke Detector	Building 300 Teachers Lounge Restroom	Tested	1:35:38 PM	08/20/2019
Smoke Detector	Building 300 Teachers Lounge Restroom	Tested	1:35:55 PM	08/20/2019
Smoke Detector	Building 300 Teachers Lounge Restroom	Tested	1:37:20 PM	08/20/2019
Smoke Detector	Building 300 Teachers Lounge Restroom	Tested	1:37:37 PM	08/20/2019
Smoke Detector	Building 300 West Restroom	Tested	12:51:05 PM	08/20/2019
Smoke Detector	Building 400 Boy's Restroom In Courtyard	Tested	10:23:08 AM	08/22/2019
Smoke Detector	Building 400 Boy's Restroom In Courtyard	Tested	10:23:46 AM	08/22/2019
Smoke Detector	Building 400 Classroom 414 Materials	Tested	10:31:04 AM	08/22/2019
	Processing Room			
Smoke Detector	Building 400 Classroom 414 Materials	Tested	10:31:53 AM	08/22/2019
	Processing Room			
Smoke Detector	Building 400 Classroom 414 Support Storage Room	Tested	10:32:02 AM	08/22/2019
Smoke Detector	Building 400 Classroom 414	Tested	10:32:29 AM	08/22/2019
Smoke Detector	Building 400 Classroom 414	Tested	10:32:41 AM	08/22/2019
Smoke Detector	Building 400 Classroom 414	Tested	10:32:46 AM	08/22/2019
Smoke Detector	Building 400 Classroom 414	Tested	10:32:51 AM	08/22/2019
Smoke Detector	Building 400 Electrical Room Near Classroom 414	Tested	10:22:03 AM	08/22/2019
Smoke Detector	Building 400 Fire Riser Room 418 Elevator Control Closet	Tested	9:59:03 AM	08/22/2019
Smoke Detector	Building 400 Fire Riser Room 418	Tested	10:01:15 AM	08/22/2019
Smoke Detector	Building 400 Girl's Restroom In Courtyard	Tested	10:26:14 AM	08/22/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building 400 Girl's Restroom In Courtyard	Tested	10:26:45 AM	08/22/2019
Smoke Detector	Building 400 Janitor's Closet Near Courtyard	Tested	10:28:06 AM	08/22/2019
Smoke Detector	Building 400 Telecom Room Near Classroom	Tested	10:18:00 AM	08/22/2019
	414			, ,
Smoke Detector	Building 600 Black Box Control Room	Tested	2:07:26 PM	08/21/2019
Smoke Detector	Building 600 Black Box Elevator Landing	Tested	2:06:13 PM	08/21/2019
Smoke Detector	Building 600 Black Box Green Room	Tested	2:08:53 PM	08/21/2019
Smoke Detector	Building 600 Black Box Green Room Restroom	Tested	2:09:42 PM	08/21/2019
Smoke Detector	Building 600 Black Box Green Room Restroom	Tested	2:11:49 PM	08/21/2019
Smoke Detector	Building 600 Black Box Green Room Vestibule	Tested	2:16:32 PM	08/21/2019
Smoke Detector	Building 600 Black Box Office	Tested	2:12:45 PM	08/21/2019
Smoke Detector	Building 600 Black Box Ticket Booth	Tested	2:13:20 PM	08/21/2019
Smoke Detector	Building 600 Choral Room 622	Tested	9:07:12 AM	08/22/2019
Smoke Detector	Building 600 Choral Room 622	Tested	9:07:49 AM	08/22/2019
Smoke Detector	Building 600 Choral Room 622	Tested	9:08:10 AM	08/22/2019
Smoke Detector	Building 600 Choral Room 622	Tested	9:08:16 AM	08/22/2019
Smoke Detector	Building 600 Corridor Next To 612	Tested	9:11:32 AM	08/22/2019
Smoke Detector	Building 600 Corridor Next To 622	Tested	9:11:57 AM	08/22/2019
Smoke Detector	Building 600 Corridor Next To 622	Tested	9:12:30 AM	08/22/2019
Smoke Detector	Building 600 Corridor Next To 622	Tested	9:12:57 AM	08/22/2019
Smoke Detector	Building 600 Corridor Next To 627	Tested	9:11:07 AM	08/22/2019
Smoke Detector	Building 600 Costume Storage 619	Tested	9:14:47 AM	08/22/2019
Smoke Detector	Building 600 Custodian Room By Theater Exit	Tested	9:20:46 AM	08/22/2019
	613			
Smoke Detector	Building 600 Dimmer Room 616	Tested	9:22:19 AM	08/22/2019
Smoke Detector	Building 600 Dressing Room #1	Tested	2:19:19 PM	08/21/2019
Smoke Detector	Building 600 Dressing Room #2	Tested	2:17:54 PM	08/21/2019
Smoke Detector	Building 600 Electrical 620 Data 621	Tested	9:25:36 AM	08/22/2019
Smoke Detector	Building 600 Electrical 620	Tested	9:35:07 AM	08/22/2019
Smoke Detector	Building 600 Instrument Office 625	Tested	9:05:34 AM	08/22/2019
Smoke Detector	Building 600 Instrument Storage 628	Tested	8:57:54 AM	08/22/2019
Smoke Detector	Building 600 Instrumental Room 627	Tested	8:59:56 AM	08/22/2019
Smoke Detector	Building 600 Instrumental Room 627	Tested	9:02:18 AM	08/22/2019
Smoke Detector	Building 600 Instrumental Room 627	Tested	9:02:28 AM	08/22/2019
Smoke Detector	Building 600 Instrumental Room 627	Tested	9:03:03 AM	08/22/2019
Smoke Detector	Building 600 Instrumental Room 627	Tested	9:03:16 AM	08/22/2019
Smoke Detector	Building 600 Instrumental Room 627	Tested	9:03:26 AM	08/22/2019
Smoke Detector	Building 600 Men's Restroom	Tested	9:14:16 AM	08/22/2019
Smoke Detector	Building 600 Music Library 626	Tested	9:06:14 AM	08/22/2019
Smoke Detector	Building 600 Practice Room 623	Tested	9:08:34 AM	08/22/2019
Smoke Detector	Building 600 Recording Studio 624	Tested	9:05:02 AM	08/22/2019
Smoke Detector	Building 600 Scene Shop	Tested	2:29:40 PM	08/21/2019
Smoke Detector	Building 600 Scene Shop	Tested	2:30:38 PM	08/21/2019
Smoke Detector	Building 600 Scene Shop	Tested	2:31:10 PM	08/21/2019
Smoke Detector	Building 600 Stage Corridor	Tested	2:23:29 PM	08/21/2019
Smoke Detector	Building 600 Theater Catwalk	Tested	1:41:26 PM	08/21/2019
Smoke Detector	Building 600 Theater Catwalk	Tested	1:42:16 PM	08/21/2019
Smoke Detector	Building 600 Theater Catwalk	Tested	1:42:58 PM	08/21/2019
Smoke Detector	Building 600 Theater Catwalk	Tested	1:43:15 PM	08/21/2019
Smoke Detector	Building 600 Theater Catwalk	Tested	1:54:24 PM	08/21/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building 600 Theater Catwalk	Tested	1:54:29 PM	08/21/2019
Smoke Detector	Building 600 Theater Catwalk	Tested	1:54:33 PM	08/21/2019
Smoke Detector	Building 600 Theater Catwalk	Tested	1:54:39 PM	08/21/2019
Smoke Detector	Building 600 Theater Catwalk	Tested	1:54:44 PM	08/21/2019
Smoke Detector	Building 600 Theater Catwalk	Tested	1:54:54 PM	08/21/2019
Smoke Detector	Building 600 Theater Catwalk	Tested	1:55:01 PM	08/21/2019
Smoke Detector	Building 600 Theater Catwalk	Tested	1:55:08 PM	08/21/2019
Smoke Detector	Building 600 Theater Catwalk	Tested	1:55:23 PM	08/21/2019
Smoke Detector	Building 600 Theater Catwalk	Tested	1:55:29 PM	08/21/2019
Smoke Detector	Building 600 Theater Catwalk	Tested	1:55:35 PM	08/21/2019
Smoke Detector	Building 600 Theater Catwalk	Tested	1:55:40 PM	08/21/2019
Smoke Detector	Building 600 Theater Concessions Room	Tested	1:32:31 PM	08/21/2019
Smoke Detector	Building 600 Theater East Stage	Tested	1:34:49 PM	08/21/2019
Smoke Detector	Building 600 Theater Entrance Vestibule	Tested	1:17:37 PM	08/21/2019
Smoke Detector	Building 600 Theater Entrance Vestibule	Tested	1:27:22 PM	08/21/2019
Smoke Detector	Building 600 Theater Lights Storage	Tested	1:19:33 PM	08/21/2019
Smoke Detector	Building 600 Theater Lower Mechanical Room	Tested	1:21:31 PM	08/21/2019
Smoke Detector	Building 600 Theater Men's Restroom	Tested	1:10:25 PM	08/21/2019
Smoke Detector	Building 600 Theater Restroom Vestibule	Tested	1:11:56 PM	08/21/2019
Smoke Detector	Building 600 Theater South Corridor	Tested	1:09:07 PM	08/21/2019
Smoke Detector	Building 600 Theater South Corridor	Tested	1:09:41 PM	08/21/2019
Smoke Detector	Building 600 Theater South Corridor	Tested	1:09:47 PM	08/21/2019
Smoke Detector	Building 600 Theater Women's Restroom	Tested	1:10:57 PM	08/21/2019
Smoke Detector	Building 600 Theater Arts 617	Tested	9:16:22 AM	08/22/2019
Smoke Detector	Building 600 Theater Arts 617	Tested	9:16:48 AM	08/22/2019
Smoke Detector	Building 600 Theater Arts Office 618	Tested	9:17:05 AM	08/22/2019
Smoke Detector	Building 600 Theater Exit 613	Tested	9:19:08 AM	08/22/2019
Smoke Detector	Building 600 Uniform Storage 629	Tested	8:58:35 AM	08/22/2019
Smoke Detector	Building 600 Women's Restroom	Tested	9:13:52 AM	08/22/2019
Smoke Detector	Building 600 Theater Lobby	Tested	1:08:26 PM	08/21/2019
Smoke Detector	Building 600 Theater Lobby	Tested	1:08:54 PM	08/21/2019
Smoke Detector	Building 600 Theater Lobby	Tested	1:08:58 PM	08/21/2019
Smoke Detector	Building 600 Theater Lobby	Tested	1:09:03 PM	08/21/2019
Smoke Detector	Building 700 Boys Locker Room	Tested	9:37:04 AM	08/21/2019
Smoke Detector	Building 700 Boys Locker Room	Tested	9:38:07 AM	08/21/2019
Smoke Detector	Building 700 Boys Locker Room	Tested	9:38:41 AM	08/21/2019
Smoke Detector	Building 700 Boys Locker Room	Tested	9:41:08 AM	08/21/2019
Smoke Detector	Building 700 Boys Locker Room Equipment	Tested	9:53:25 AM	08/21/2019
	Room			
Smoke Detector	Building 700 Boys Locker Room Equipment Room	Tested	9:55:33 AM	08/21/2019
Smoke Detector	Building 700 Boys Locker Room Equipment Room	Tested	9:57:07 AM	08/21/2019
Smoke Detector	Building 700 Boys Locker Room Ice Room	Tested	9:43:39 AM	08/21/2019
Smoke Detector	Building 700 Boys Locker Room Office	Tested	9:46:33 AM	08/21/2019
Smoke Detector	Building 700 Boys Locker Room Storage	Tested	9:48:32 AM	08/21/2019
Smoke Detector	Building 700 Boys Locker Room Therapy Room	Tested	9:44:28 AM	08/21/2019
				, ,==
Smoke Detector		Tested	9:35:09 AM	08/21/2019
Smoke Detector Smoke Detector	Building 700 Mechanical Room Building 800 Boys Locker Room Laundry	Tested Tested	9:35:09 AM 9:16:14 AM	08/21/2019 08/21/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building 800 Boys Locker Room Office	Tested	9:08:12 AM	08/21/2019
Smoke Detector	Restroom	lested		00,21,2013
Smoke Detector	Building 800 Boys Locker Room Office Storage	Tested	9:00:48 AM	08/21/2019
Smoke Detector	Building 800 Boys Locker Room Office Storage	Tested	9:06:40 AM	08/21/2019
Smoke Detector	Building 800 Boys Locker Room Office Storage	Tested	9:07:37 AM	08/21/2019
	Room			00,21,2010
Smoke Detector	Building 800 Boys Locker Room	Tested	9:13:59 AM	08/21/2019
Smoke Detector	Building 800 Girls Locker Room Issue Room	Tested	10:08:57 AM	08/21/2019
Smoke Detector	Building 800 Girls Locker Room Issue Room	Tested	10:09:27 AM	08/21/2019
Smoke Detector	Building 800 Girls Locker Room Office	Tested	10:14:05 AM	08/21/2019
Smoke Detector	Building 800 Girls Locker Room Office	Tested	10:15:19 AM	08/21/2019
Smoke Detector	Building 800 Girls Locker Room Office	Tested	10:17:45 AM	08/21/2019
Smoke Detector	Building 800 Girls Locker Room Office	Tested	10:19:28 AM	08/21/2019
	Restroom			
Smoke Detector	Building 800 Girls Locker Room Office Storage	Tested	10:18:20 AM	08/21/2019
Smoke Detector	Building 800 Girls Locker Room Storage Room	Tested	10:24:07 AM	08/21/2019
Smoke Detector	Building 800 Girls Locker Room Varsity Room	Tested	10:11:55 AM	08/21/2019
Smoke Detector	Building 800 Girls Locker Room Varsity Room	Tested	10:12:47 AM	08/21/2019
Smoke Detector	Building 800 Girls Locker Room	Tested	10:01:53 AM	08/21/2019
Smoke Detector	Building 800 Girls Locker Room	Tested	10:02:40 AM	08/21/2019
Smoke Detector	Building 800 Chair Storage Room	Tested	9:26:49 AM	08/21/2019
Smoke Detector	Building 800 Chair Storage Room	Tested	9:27:38 AM	08/21/2019
Smoke Detector	Building 800 Custodian Storage	Tested	9:28:46 AM	08/21/2019
Smoke Detector	Building 800 Custodian Storage	Tested	9:29:52 AM	08/21/2019
Smoke Detector	Building 800 Custodian Storage	Tested	9:30:52 AM	08/21/2019
Smoke Detector	Building 800 Equipment Storage	Tested	9:18:06 AM	08/21/2019
Smoke Detector	Building 800 Equipment Storage	Tested	9:20:10 AM	08/21/2019
Smoke Detector	Building 800 Mechanical Room	Tested	10:00:15 AM	08/21/2019
Smoke Detector	Building 800 Oxygen Storage	Tested	9:22:43 AM	08/21/2019
Smoke Detector	Building 800 Tank Pump Room	Tested	9:24:59 AM	08/21/2019
Smoke Detector	Building 900 Big Gym	Tested	2:57:03 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	2:57:21 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	2:57:26 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	2:57:31 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	2:57:39 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	2:57:46 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	2:57:53 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	2:57:59 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	2:58:12 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	2:59:18 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	2:59:25 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	2:59:29 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	2:59:34 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	2:59:39 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	2:59:44 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	3:00:48 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	3:01:25 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	3:01:31 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	3:01:57 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	3:02:13 PM	08/22/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building 900 Big Gym	Tested	3:02:18 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	3:02:24 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	3:02:29 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	3:02:34 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	3:02:43 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	3:02:53 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	3:03:01 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	3:03:08 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	3:03:13 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	3:03:21 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	3:03:57 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	3:04:16 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	3:04:27 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	3:04:36 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	3:04:43 PM	08/22/2019
Smoke Detector	Building 900 Big Gym	Tested	3:04:48 PM	08/22/2019
Smoke Detector	Building 900 Little Gym Electrical Room	Tested	8:13:49 AM	08/22/2019
Smoke Detector	Building 900 Little Gym Electrical Room	Tested	8:14:47 AM	08/22/2019
Smoke Detector	Building 900 Little Gym Electrical Room/Public	Tested	8:15:31 AM	08/22/2019
	Address			
Smoke Detector	Building 900 Little Gym	Tested	8:31:53 AM	08/22/2019
Smoke Detector	Building 900 Little Gym	Tested	8:32:26 AM	08/22/2019
Smoke Detector	Building 900 Little Gym	Tested	8:33:17 AM	08/22/2019
Smoke Detector	Building 900 Little Gym	Tested	8:33:24 AM	08/22/2019
Smoke Detector	Building 900 Little Gym	Tested	8:33:31 AM	08/22/2019
Smoke Detector	Building 900 Little Gym	Tested	8:33:38 AM	08/22/2019
Smoke Detector	Building 900 Little Gym	Tested	8:33:48 AM	08/22/2019
Smoke Detector	Building 900 Little Gym	Tested	8:33:57 AM	08/22/2019
Smoke Detector	Building 900 Little Gym	Tested	8:34:03 AM	08/22/2019
Smoke Detector	Building 900 Little Gym	Tested	8:34:11 AM	08/22/2019
Smoke Detector	Building 900 Little Gym	Tested	8:34:18 AM	08/22/2019
Smoke Detector	Building 900 Little Gym	Tested	8:34:25 AM	08/22/2019
Smoke Detector	Building 900 Little Gym	Tested	8:34:35 AM	08/22/2019
Smoke Detector	Building 900 Little Gym	Tested	8:34:42 AM	08/22/2019
Smoke Detector	Building 900 Little Gym	Tested	8:34:48 AM	08/22/2019
Smoke Detector	Building 900 Little Gym	Tested	8:34:59 AM	08/22/2019
Smoke Detector	Building 900 Little Gym	Tested	8:35:07 AM	08/22/2019
Smoke Detector	Building 900 Little Gym	Tested	8:35:15 AM	08/22/2019
Smoke Detector	Building 900 Little Gym	Tested	8:35:29 AM	08/22/2019
Smoke Detector	Building 900 Little Gym	Tested	8:35:35 AM	08/22/2019
Smoke Detector	Building 900 Little Gym	Tested	8:35:55 AM	08/22/2019
Smoke Detector	Building 900 Little Gym	Tested	8:36:03 AM	08/22/2019
Smoke Detector	Building 900 Little Gym	Tested	8:36:17 AM	08/22/2019
Smoke Detector	Building 900 Little Gym	Tested	8:36:25 AM	08/22/2019
Smoke Detector	Building 900 East Lobby	Tested	8:12:06 AM	08/21/2019
Smoke Detector	Building 900 East Lobby	Tested	8:13:46 AM	08/21/2019
Smoke Detector	Building 900 East Lobby Boys Restroom	Tested	8:18:25 AM	08/21/2019
Smoke Detector	Building 900 East Lobby Girls Restroom	Tested	8:19:50 AM	08/21/2019
Smoke Detector	Building 900 East Lobby Storage Room	Tested	8:17:56 AM	08/21/2019
Smoke Detector	Building 900 Wrestling Room	Tested	12:32:58 PM	08/21/2019

Device Type	Location	Service	Time	Date	
	Passed				
Smoke Detector	Building 900 Wrestling Room	Tested	12:33:42 PM	08/21/2019	
Smoke Detector	Building 900 Wrestling Room	Tested	12:34:32 PM	08/21/2019	
Smoke Detector	Building 900 Wrestling Room	Tested	12:35:28 PM	08/21/2019	
Smoke Detector	Building 900 Wrestling Room	Tested	12:35:42 PM	08/21/2019	
Smoke Detector	Building 900 Wrestling Room	Tested	12:35:59 PM	08/21/2019	
Smoke Detector	Building 900 Wrestling Room	Tested	12:36:15 PM	08/21/2019	
Smoke Detector	Building 900 Wrestling Room	Tested	1:08:04 PM	08/21/2019	
Smoke Detector	Building Pool Data Room	Tested	8:48:31 AM	08/21/2019	
Smoke Detector	Building Pool Janitor Room	Tested	8:38:32 AM	08/21/2019	
Waterflow Switch	Building 400 Fire Riser Room 418	Tested	10:11:32 AM	08/22/2019	
Waterflow Switch	Building 600 Electrical 620 Fire Riser Room 631	Tested	9:41:36 AM	08/22/2019	
Supervisory					
Tamper Switch	Building 400 Fire Riser Room 418	Tested	10:04:28 AM	08/22/2019	
Tamper Switch	Building 400 NW Parking Lot "PIV"	Tested	9:51:40 AM	08/22/2019	
Tamper Switch	Building 600 Electrical 620 Fire Riser Room 631	Tested	9:42:25 AM	08/22/2019	
Tamper Switch	Building 600 Electrical 620 Fire Riser Room 631	Tested	9:43:51 AM	08/22/2019	
Tamper Switch	Building 600 Fire Pump Room	Tested	2:24:27 PM	08/21/2019	
Tamper Switch	Building 600 Fire Pump Room	Tested	2:26:20 PM	08/21/2019	
Tamper Switch	Building 600 Fire Pump Room	Tested	2:26:32 PM	08/21/2019	
Tamper Switch	Building 600 Fire Pump Room	Tested	2:26:41 PM	08/21/2019	
Tamper Switch	Building 600 Fire Pump Room	Tested	2:26:48 PM	08/21/2019	
Tamper Switch	Building 600 Fire Pump Room	Tested	2:27:32 PM	08/21/2019	
Tamper Switch	Building 600 Fire Pump Room	Tested	2:27:52 PM	08/21/2019	
Tamper Switch	Building 600 Outside Near Electrical 620 "PIV"	Tested	9:49:10 AM	08/22/2019	
Device Type	Location	Service	Time	Date	
	Failed/Other				
Control					
Battery	2nd Building 400 Telecom Room Next To Staff Restroom	Tested	12:54:13 PM	08/22/2019	
Battery	2nd Building 400 Telecom Room Next To Staff Restroom	Tested	12:54:29 PM	08/22/2019	
Battery	3rd Building 400 Telecom Room Next To Staff Restroom	Tested	12:34:24 PM	08/22/2019	
Battery	3rd Building 400 Telecom Room Next To Staff Restroom	Tested	12:34:45 PM	08/22/2019	

Building: NMUSD - Corona Del Mar Middle &Control Panel: 2 - Silent KnightHigh SchoolIFP-2000

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Building 600 Electrical 620	Inspected	9:45:47 AM	08/22/2019
Battery	Building 600 Electrical 620 Data 621	Tested	9:29:52 AM	08/22/2019
Battery	Building 600 Electrical 620 Data 621	Tested	9:30:26 AM	08/22/2019
Control Panel	Building 600 Electrical 620 Data 621	Inspected	9:28:12 AM	08/22/2019

Building: NMUSD - Corona Del Mar Middle &Control Panel: 3 - Silent KnightHigh SchoolIFP-2000

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Battery	Building 400 Telecom Room Near Classroom 414	Tested	10:16:56 AM	08/22/2019
Battery	Building 400 Telecom Room Near Classroom 414	Tested	10:17:04 AM	08/22/2019
Control Panel	Building 400 Telecom Room Near Classroom 414	Inspected	10:13:12 AM	08/22/2019
Power Supply	3rd Building 400 Telecom Room	Inspected	12:31:00 PM	08/22/2019
Power Supply	3rd Building 400 Telecom Room	Inspected	12:53:02 PM	08/22/2019
Power Supply	Building 400 Telecom Room Near Classroom 414	Inspected	10:18:52 AM	08/22/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Corona Del Mar Middle & High School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Failed/Other	
Battery	Tested	4
Total		4
	Passed	
Annunciator	Inspected	1
Annunciator	Tested	1
Battery	Inspected	18
Battery	Tested	10
Beam Detector	Tested	1
Control Panel	Inspected	2
Control Panel	Tested	1
Heat Detector	Tested	243
Power Supply	Inspected	5
Power Supply	Tested	7
Pull Station	Tested	26
Smoke Detector	Tested	561
Tamper Switch	Tested	12
Voice Evacuation	Tested	1
Waterflow Switch	Tested	2
Total		895

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - Corona Del Mar Middle & High School

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

		Ambient	Alarm	🦻 Intell	igibility	Sound
C Location	Comment	◀ dB	◀ dB	Voice	STI	Test
	Failed/Otl	her				
Sound Test Points						
						0001

Time, Temperature & Level Testing

Generated by: BuildingReports.com

Building: NMUSD - Corona Del Mar Middle &Control Panel: 1 - Silent KnightHigh SchoolIFP-200

The Time, Temperature, & Level Testing section details the measurements taken from various devices that are designed to respond in a certain amount of time, respond at a certain temperature, or respond within the acceptable range of volume or level. Items are grouped by Passed or Failed/Other.

Туре	Location	Comment	Sec	Deg	Lvl	ScanID
	Passed	1				
Waterflow Swit	tch					
	Building 400 Fire Riser Room 418	Passed	51	n/a	n/a	61337172
	Building 600 Electrical 620 Fire Riser Room 631	Passed	32	n/a	n/a	61337163

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Corona Del Mar Middle &Control Panel: 1 - Silent KnightHigh SchoolIFP-200

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category	% of Inventory	Quantity
Control Panel		Control	0.33%	3
Battery		Control	3.57%	32
Smoke Detector		Initiating	62.61%	561
Voice Evacuation		Control	0.11%	1
Heat Detector		Initiating	27.12%	243
Power Supply		Control	1.34%	12
Pull Station		Initiating	2.90%	26
Beam Detector		Initiating	0.11%	1
Tamper Switch		Supervisory	1.34%	12
Waterflow Switch		Initiating	0.22%	2
Annunciator		Control	0.22%	2
Туре	Qty	Model #	Description	Install Date
		New	(under 90 days)	
Silent Knight				
Control Panel	1	IFP-200		08/20/2019
	-		e - 1 Year to 2 Years	
Battery	6	12V7AH	Sealed Lead Acid	07/25/2018
Battery	2	12v7ah	Sealed Lead Acid	02/19/2018
		In Service	- 2 Years to 3 Years	
Battery	2	12v7ah	Sealed Lead Acid	07/27/2017
Beam Detector	1			07/25/2017
Tamper Switch	7			07/25/2017
Fivalco, Inc.				
Tamper Switch	1	HG14B00321		07/25/2017
Global Safety Produc				
Tamper Switch	1	BO-300		07/25/2017
Potter Electric				
Tamper Switch	1	PIBV2		07/25/2017
Waterflow Switch	1	VSR		07/25/2017
Silent Knight				
Annunciator	1		LCD Display	07/25/2017
Battery	2	12v26ah	Sealed Lead Acid	07/25/2017
Heat Detector	4	IDP-Heat-HT	Fixed Temperature	07/25/2017
Heat Detector	35	SD505-AHS		07/25/2017
Heat Detector	204	SD505-AHS	Fixed Temperature	07/25/2017
Power Supply	6	5495		07/25/2017

Cal Building Systems

09/18/2019

1				Í.		
Power Supply	3	RSP-1000		07/25/2017		
Pull Station	4	IDP-PULL-DA	Dual Action	07/25/2017		
Pull Station	15	SD500-PS	Single Action	07/25/2017		
Pull Station	4	SD505	Single Action	07/25/2017		
Pull Station	3	SD505-		07/25/2017		
Smoke Detector	561	SD505-APS	Photoelectric	07/25/2017		
Voice Evacuation	1	SKE Series		07/25/2017		
System Sensor						
Tamper Switch	1	PIBV2		07/25/2017		
Waterflow Switch	1	WFD60V		07/25/2017		
Victaulic						
Tamper Switch	1	705		07/25/2017		
		In Service	- 3 Years to 5 Years			
Battery	2	12v7ah	Sealed Lead Acid	04/01/2016		
Battery	4	12v7ah	Sealed Lead Acid	08/01/2015		
Silent Knight						
Battery	2	12v7ah	Sealed Lead Acid	08/01/2015		
Battery	2	12v7ah	Sealed Lead Acid	04/01/2015		
	In Service - 5 Years to 10 Years					
Battery	2	12v7ah	Sealed Lead Acid	07/18/2014		
Battery	4	12V7AH	Sealed Lead Acid	12/25/2013		

Building: NMUSD - Corona Del Mar Middle &Control Panel: 2 - Silent KnightHigh SchoolIFP-2000

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Туре	Qty	Model #	Description	Install Date			
In Service - 2 Years to 3 Years							
Battery	2	12V18AH	Sealed Lead Acid	08/25/2017			
Silent Knight							
Annunciator	1	RA-2000		07/25/2017			
Control Panel	1	IFP-2000		07/25/2017			

Building: NMUSD - Corona Del Mar Middle &Control Panel: 3 - Silent KnightHigh SchoolIFP-2000

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Туре	Qty	Model #	Description	Install Date
		In Service	e - 2 Years to 3 Years	
Battery	2	12V18AH	Sealed Lead Acid	08/25/2017
Silent Knight				
Control Panel	1	IFP-2000		07/25/2017
Power Supply	2	5495		07/25/2017
Power Supply	1	5496		07/25/2017

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Costa Mesa High School 2650 Fairview Rd Costa Mesa, CA 92626

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Aug 28, 2019

> Building: NMUSD - Costa Mesa High School Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Phillip Burton Title: Inspector

Executive Summary Generated by: BuildingReports.com

Building Information					
Building: NMUSD – Costa Mesa High School	Contact: Tim Waller				
Address: 2650 Fairview Rd	Phone: 714-231-03	63			
Address:	Fax:				
City/State/Zip: Costa Mesa, CA 92626	Mobile:				
Country: United States of America	Email:				
Inspection Performed By					
Company: Cal Building Systems	Inspector: Phillip Bu	rton			
Address: 2903 Saturn Street	Phone: 714-345-12	52			
Address: Suite F	Fax:				
City/State/Zip: Brea, CA 92821	Mobile:	Mobile:			
Country: United States of America	Email: phillipburton	@calbuildingsystems.com			
System Control Unit					
Manufacturer: Silent Knight	Inspection Date: 08	/26/2019 IDC Style :			
Model Number: IFP-2000	Install Date: 08/26/	2019 SLC Style:			
Software Version:	Version Date: 08/26	5/2019 NAC Style:			
Location: Main Bldg. Library FACP Room	Current Protection:	Breaker			
Monitoring					
Company:	Phone:	Account #:			
Central Station Signal Verification					
Type: Digital Communicator	Mfg: Silent Knight	Model #:			
Test Time/Date: 8/28/19 7:27:09 AM	Restore Time				

Inspection Summary								
Catalana	Total	ltems	Ser	viced	Pas	ssed	Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.12%	1	100.00%	0	0%	1	100.00%
Control	47	5.79%	47	100.00%	45	95.74%	2	4.26%
Initiating	757	93.23%	757	100.00%	757	100.00%	0	0%
Supervisory	7	0.86%	7	100.00%	7	100.00%	0	0%
Totals	812	100%	812	100.00%	809	99.63%	3	0.37%
Certification								
Company: Cal Building Systems			Bi	ilding: NMU	ISD – Cos	ta Mesa Hig	jh School	
Inspector: Phillip Burton			Co	ontact: Tim V	Waller			
Signed:			Sig	gned:				

Discrepancy Report

Generated by: BuildingReports.com

Control Panel: 1 - Silent Knight Building: NMUSD - Costa Mesa High School **IFP-2000** The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included. Device Type Manufacturer ModelNumber Date Qty Items listed for Recall by Manufacturer No recalled items found during this inspection. Reference 8 ScanID C3 Location ø Problem Address Control Battery 61326693 1st Bldg. EE Signal Room 117 Date Expired 1 NFPA72 Table 14.4.2.2 (5)(b) 61326694 1st Bldg. EE Signal Room 117 Date Expired 1 NFPA72 Table 14.4.2.2 (5)(b) Code References Batteries shall be replaced in accordance with the recommendations of the alarm equipment NFPA72 Table 14.4.2.2 (5)(b) manufacturer or when the recharged battery voltage or current falls below the manufacturer's recommendations

Building: NMUSD - Costa Mesa High School Control Panel: n/a								
Discrepancies a appropriate, cod	re listed by Cate le references are	dates each discrepancy listed gory, and grouped by device listed for your convenience. bsite and is subject to a reca	type Any	e. The descriptic item that was in	on of the spected	e problem is that is listed	provided a	and where
Device Type		Manufacturer		ModelNum	ber	Da	te	Qty
	Items listed for Recall by Manufacturer							
		No recalled items found	d du	ring this inspectio	n.			
Sound Test	C Location		Ŷ	Problem	C	evice	Ref	erence
	Sound Testing							
Sound Test	C3 Location		Ŷ	Problem	۵	evice	🛄 Ref	erence
Sound Test	Sound Test Points							
0001	Entire Campus				So	und Test		

Proposed Solutions Report

Generated by: BuildingReports.com

Building: NMUSD - Costa Mesa High School

Control Panel: 1 - Silent Knight IFP-2000

The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.

ScanID	Location	Solution	Model #	Cost	Fix			
	Cont	rol						
Battery								
61326693	1st Bldg. EE Signal Room 117	Replace	12v 7ah	T/M				
61326694	1st Bldg. EE Signal Room 117	Replace	12v 7ah	T/M				
Building: N School	MUSD - Costa Mesa High		Cont	rol Panel	: n/a			
check mark when	The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.							
ScanID	Location	Solution	Description	Cost	Fix			
Sound Testing								
Sound Test	:							
0001	Entire Campus			T/M				
			PO #: (none)	T/M				

Notes & Recommendations

Generated by: BuildingReports.com

Building: NMUSD - Costa Mesa High School

Control Panel: n/a

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

ScanID	Note	Device Type	Location	Comment		
0001	1	Sound Test	Entire Campus			
Strobe	Strobe portion of a hornstrobe by counselers offices did not work.					

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Costa Mesa High School

Control Panel: 1 - Silent Knight IFP-2000

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Main Bldg. Admin Office	Tested	11:00:53 AM	08/28/2019
Battery	1st Bldg. C Classroom C101	Tested	1:52:11 PM	08/27/2019
Battery	1st Bldg. C Classroom C101	Tested	1:52:25 PM	08/27/2019
Battery	1st Bldg. EE Signal Room 106	Tested	9:27:03 AM	08/26/2019
Battery	1st Bldg. EE Signal Room 106	Tested	9:27:31 AM	08/26/2019
Battery	1st Bldg. P Classroom P152 Storage Room	Tested	10:04:41 AM	08/27/2019
Battery	1st Bldg. P Classroom P152 Storage Room	Tested	10:04:59 AM	08/27/2019
Battery	1st Bldg. T Electrical Room 114	Tested	1:13:29 PM	08/26/2019
Battery	1st Bldg. T Electrical Room 114	Tested	1:13:59 PM	08/26/2019
Battery	1st Mustang Field Electrical/Data Room	Tested	10:12:46 AM	08/27/2019
Battery	1st Mustang Field Electrical/Data Room	Tested	10:13:14 AM	08/27/2019
Battery	1st Mustang Field Electrical/Data Room	Tested	10:13:50 AM	08/27/2019
Battery	1st Mustang Field Electrical/Data Room	Tested	10:13:53 AM	08/27/2019
Battery	AQ Center Custodial Storage	Tested	8:24:25 AM	08/28/2019
Battery	AQ Center Custodial Storage	Tested	8:24:57 AM	08/28/2019
Battery	Bldg. R Trainer R102	Tested	9:52:32 AM	08/28/2019
Battery	Bldg. R Trainer R102	Tested	9:52:50 AM	08/28/2019
Battery	Main Bldg. Library FACP Room	Tested	7:37:23 AM	08/26/2019
Battery	Main Bldg. Library FACP Room	Tested	7:38:05 AM	08/26/2019
Battery	Main Bldg. Library FACP Room	Tested	7:38:48 AM	08/26/2019
Battery	Main Bldg. Library FACP Room	Tested	7:38:50 AM	08/26/2019
Battery	Portables Staff Restroom	Tested	8:09:53 AM	08/28/2019
Battery	Portables Staff Restroom	Tested	8:10:07 AM	08/28/2019
Battery	Storage Bldg. Weight Room	Tested	8:52:10 AM	08/28/2019
Battery	Storage Bldg. Weight Room	Tested	8:52:27 AM	08/28/2019
Control Panel	Main Bldg. Library FACP Room	Tested	7:36:36 AM	08/26/2019
Power Supply	1st AQ Center Custodial Storage	Tested	8:23:36 AM	08/28/2019
Power Supply	1st Bldg. EE Signal Room 106	Tested	9:26:34 AM	08/26/2019
Power Supply	1st Bldg. EE Signal Room 117	Tested	8:44:34 AM	08/26/2019
Power Supply	1st Bldg. P Classroom P152 Storage Room	Tested	10:04:11 AM	08/27/2019
Power Supply	1st Bldg. R Trainer R102	Tested	9:51:54 AM	08/28/2019
Power Supply	1st Bldg. T Electrical Room 114	Tested	1:13:09 PM	08/26/2019
Power Supply	1st Storage Bldg. Weight Room	Tested	8:51:34 AM	08/28/2019
Power Supply	Main Bldg. Library FACP Room	Tested	7:38:31 AM	08/26/2019
Initiating				
Heat Detector	1st Attendance Office C109	Tested	1:56:51 PM	08/28/2019
Heat Detector	1st Camp. Sec C108	Tested	1:58:48 PM	08/28/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	1st Elev. Rm 1st Floor C	Tested	2:10:02 PM	08/28/2019
Heat Detector	1st Mech. C107	Tested	1:56:26 PM	08/28/2019
Heat Detector	2nd Elev. Rm 2nd Floor C	Tested	2:11:04 PM	08/28/2019
Heat Detector	100 Pub X102	Tested	2:25:40 PM	08/28/2019
Heat Detector	100 Pub X102	Tested	2:26:03 PM	08/28/2019
Heat Detector	2nd FLR C.S. Exit Storage	Tested	2:01:03 PM	08/28/2019
Heat Detector	2nd FLR C.S. Exit Storage	Tested	2:01:34 PM	08/28/2019
Heat Detector	ADV BUS HWAY W121	Tested	1:32:11 PM	08/28/2019
Heat Detector	ADV. BUS W121	Tested	1:27:55 PM	08/28/2019
Heat Detector	ADV. BUS W121	Tested	1:29:14 PM	08/28/2019
Heat Detector	AQCNTR A Custodian Office	Tested	1:02:22 PM	08/28/2019
Heat Detector	AQCNTR A MEN RR	Tested	1:01:27 PM	08/28/2019
Heat Detector	AQCNTR A MENS Locker Cust. RM	Tested	1:04:41 PM	08/28/2019
Heat Detector	AQCNTR A MENS Locker RM	Tested	1:06:18 PM	08/28/2019
Heat Detector	AQCNTR A MENS Locker RR	Tested	1:07:07 PM	08/28/2019
Heat Detector	AQCNTR A WOMEN RR	Tested	1:02:02 PM	08/28/2019
Heat Detector	AQCNTR A WOMENS RR LOCKERS	Tested	1:03:14 PM	08/28/2019
Heat Detector	AQCNTR A WOMENS RR LOCKERS Mech. RM	Tested	1:04:02 PM	08/28/2019
Heat Detector	AQCNTR B 103 Chemical RM	Tested	1:09:54 PM	08/28/2019
Heat Detector	AQCNTR B 104 Chemical RM	Tested	1:11:08 PM	08/28/2019
Heat Detector	AQCNTR B 105 Chemical RM	Tested	1:11:30 PM	08/28/2019
Heat Detector	AQCNTR B Equipment	Tested	1:08:12 PM	08/28/2019
Heat Detector	AQCNTR B Equipment	Tested	1:08:52 PM	08/28/2019
Heat Detector	Art V164	Tested	10:59:22 AM	08/28/2019
Heat Detector	Art V164	Tested	10:59:43 AM	08/28/2019
Heat Detector	ASB RM BB111	Tested	12:54:12 PM	08/28/2019
Heat Detector	Assist Admin CC121	Tested	12:50:27 PM	08/28/2019
Heat Detector	Assist Admin CC132	Tested	12:46:03 PM	08/28/2019
Heat Detector	Assist. Princple CC133	Tested	12:45:25 PM	08/28/2019
Heat Detector	Bio K133	Tested	1:24:03 PM	08/28/2019
Heat Detector	Bio K133	Tested	1:24:32 PM	08/28/2019
Heat Detector	Bio K134	Tested	1:20:02 PM	08/28/2019
Heat Detector	Bio K134	Tested	1:20:46 PM	08/28/2019
Heat Detector	Bk KPG RM 123	Tested	1:24:44 PM	08/28/2019
Heat Detector	Bk KPG RM 123	Tested	1:25:30 PM	08/28/2019
Heat Detector	BLDG R MEZZ. Area	Tested	1:44:53 PM	08/28/2019
Heat Detector	BLDG R MEZZ. Area	Tested	1:45:27 PM	08/28/2019
Heat Detector	Boiler Room	Tested	1:36:50 PM	08/28/2019
Heat Detector	Breakroom CC134	Tested	12:42:26 PM	08/28/2019
Heat Detector	CKMP. V165	Tested	10:57:17 AM	08/28/2019
Heat Detector	Comp. V165	Tested	10:56:09 AM	08/28/2019
Heat Detector	Conference CC108	Tested	12:43:43 PM	08/28/2019
Heat Detector	Conference Rm BB115	Tested	12:53:00 PM	08/28/2019
Heat Detector	Control RM BB107	Tested	12:55:34 PM	08/28/2019
Heat Detector	CORR BB202	Tested	2:19:41 PM	08/28/2019
Heat Detector	CORR BB202	Tested	2:20:03 PM	08/28/2019
Heat Detector	CORR BB202	Tested	2:20:10 PM	08/28/2019
Heat Detector	Counseling CC 117	Tested	12:49:35 PM	08/28/2019
Heat Detector	Counseling CC 126	Tested	12:50:06 PM	08/28/2019
Heat Detector	Counseling CC 126	Tested	12:50:19 PM	08/28/2019

Passed	-		
=	1		
Custodian U111	Tested	10:06:11 AM	08/28/2019
DEPT. OFFICE W104	Tested	1:27:11 PM	08/28/2019
Dish Wash Rm	Tested	1:39:02 PM	08/28/2019
Dish Wash Rm	Tested	1:39:22 PM	08/28/2019
Elevator Lobby	Tested	12:51:34 PM	08/28/2019
Film Chain BB107	Tested	12:57:04 PM	08/28/2019
Film Chain BB107	Tested	12:57:35 PM	08/28/2019
Flex Lab V107	Tested	11:02:24 AM	08/28/2019
Flex Lab V107	Tested	11:02:56 AM	08/28/2019
Hall Attic BLDG T104	Tested	10:21:05 AM	08/28/2019
Hall Attic BLDG T104	Tested	10:22:47 AM	08/28/2019
Hallway Attic	Tested	1:42:50 PM	08/28/2019
Hallway BB114	Tested	12:53:31 PM	08/28/2019
Hallway X106	Tested	2:26:43 PM	08/28/2019
Heater RM 101	Tested	1:35:00 PM	08/28/2019
INT RM K135	Tested	1:16:30 PM	08/28/2019
INT RM K135		1:17:40 PM	08/28/2019
Kitchen	Tested	1:43:12 PM	08/28/2019
Kitchen	Tested	1:43:34 PM	08/28/2019
Lecture V105	Tested	11:00:17 AM	08/28/2019
Lecture V108	Tested	11:03:47 AM	08/28/2019
		12:51:56 PM	08/28/2019
		10:31:08 AM	08/28/2019
		12:58:17 PM	08/28/2019
M1 Band Attic BLDG T111	Tested	10:30:04 AM	08/28/2019
M1 Band Attic BLDG T111		10:30:58 AM	08/28/2019
		10:32:39 AM	08/28/2019
		10:34:02 AM	08/28/2019
		12:41:24 PM	08/28/2019
		2:00:41 PM	08/28/2019
		2:03:06 PM	08/28/2019
		1:17:46 PM	08/28/2019
Mech. RM R U104	Tested	9:55:51 AM	08/28/2019
Mech. RM R. U101	Tested	9:53:25 AM	08/28/2019
	Tested	10:04:12 AM	08/28/2019
		1:32:41 PM	08/28/2019
		12:48:09 PM	08/28/2019
		10:31:37 AM	08/28/2019
		2:09:43 PM	08/28/2019
		2:17:38 PM	08/28/2019
			08/28/2019
		1:15:09 PM	08/28/2019
		1:14:37 PM	08/28/2019
		2:31:31 PM	08/28/2019
		10:47:10 AM	08/28/2019
		10:55:31 AM	08/28/2019
		1:47:36 PM	08/28/2019
			08/28/2019
			08/28/2019
			08/28/2019
	Dish Wash Rm Elevator Lobby Film Chain BB107 Film Chain BB107 Flex Lab V107 Flex Lab V107 Hall Attic BLDG T104 Hall Attic BLDG T104 Hallway Attic Hallway Attic Hallway X106 Heater RM 101 INT RM K135 INT RM K135 Kitchen Lecture V105 Lecture V108 Lib. Admin BB118 Library BLDG T112 M.S. OFF	Dish Wash RmTestedElevator LobbyTestedFilm Chain BB107TestedFilm Chain BB107TestedFlex Lab V107TestedFlex Lab V107TestedHall Attic BLDG T104TestedHall Attic BLDG T104TestedHallway AtticTestedHallway BB114TestedHallway SB114TestedHallway SB114TestedHallway SB114TestedHallway BB115TestedINT RM K135TestedINT RM K135TestedKitchenTestedLecture V105TestedLecture V105TestedLibrary BLDG T112TestedM1 Band Attic BLDG T111TestedM2 Choir Attic BLDG T114TestedM2 Choir Attic BLDG T114TestedMech. C202TestedMech. C205TestedMech. RM R U104TestedMech. RM R U104TestedMech. RM R U107TestedMech. RM R U107TestedMech. RM R U107TestedMechanical Attic BLDG T113TestedMechanical C124TestedMechanical C136TestedMechanical C137TestedMechanical C136TestedMechanical P101TestedMechanical RM A109TestedMechanical RM A109Tested	Dish Wash Rm Tested 1:39:22 PM Elevator Lobby Tested 1:251:34 PM Film Chain BB107 Tested 1:257:35 PM Film Chain BB107 Tested 1:257:35 PM Filex Lab V107 Tested 1:22:56 AM Hall Attic BLDG T104 Tested 1:22:56 AM Hall Attic BLDG T104 Tested 1:22:37 AM Hallway Xtic Tested 1:22:37 AM Hallway Xtic Tested 1:22:36 AM Hallway Xtic Tested 1:25:31 PM Hallway Xtic Tested 1:25:37 PM Hallway Xtic Tested 1:25:30 PM Hallway Xtio6 Tested 1:3:30 PM INT RM K135 Tested 1:16:30 PM INT RM K135 Tested 1:3:100 PM Kitchen Tested 1:3:100 PM Lib. Admin BB118 Tested 1:3:107 AM Lecture V105 Tested 1:3:0:17 AM Lib. Admin BB118 Tested 1:3:0:3:4 PM Libadmin BB118 Tested 1:0:3:0:4 AM<

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	Mechanical RM D105	Tested	10:36:58 AM	08/28/2019
Heat Detector	MECHANICAL RM K106	Tested	1:22:59 PM	08/28/2019
Heat Detector	Mechanical Rm X104	Tested	2:22:04 PM	08/28/2019
Heat Detector	Mechanical Rm105	Tested	1:52:08 PM	08/28/2019
Heat Detector	Mechanical Room	Tested	1:46:04 PM	08/28/2019
Heat Detector	Mechanical Room	Tested	1:53:27 PM	08/28/2019
Heat Detector	Mechanical U201	Tested	10:08:55 AM	08/28/2019
Heat Detector	Mechanical U204	Tested	10:25:54 AM	08/28/2019
Heat Detector	Mechanical U207	Tested	10:14:08 AM	08/28/2019
Heat Detector	Mechanical U209	Tested	10:16:02 AM	08/28/2019
Heat Detector	Mechanical V104	Tested	10:59:50 AM	08/28/2019
Heat Detector	Mechanical V109	Tested	11:03:21 AM	08/28/2019
Heat Detector	Mechanical V110	Tested	11:01:42 AM	08/28/2019
Heat Detector	Mechanical V110	Tested	11:02:15 AM	08/28/2019
Heat Detector	Men RR CC104	Tested	12:40:31 PM	08/28/2019
Heat Detector	Men's RR U112	Tested	10:06:45 AM	08/28/2019
Heat Detector	Men's Staff RR	Tested	1:38:03 PM	08/28/2019
Heat Detector	Module_33Point_88	Tested	12:57:42 PM	08/28/2019
Heat Detector	Office Area CC COMM.	Tested	12:44:18 PM	
Heat Detector	Office Attic BLDG T105	Tested	10:23:58 AM	08/28/2019
	Office X103	Tested	2:22:43 PM	08/28/2019
Heat Detector		Tested	1:40:49 PM	08/28/2019
Heat Detector	Outside Serving		1:39:33 PM	08/28/2019
Heat Detector	Passage	Tested	12:52:25 PM	08/28/2019
Heat Detector	Periodicals BB120	Tested	12:52:54 PM	08/28/2019
Heat Detector	Periodicals BB120	Tested	2:26:11 PM	08/28/2019
Heat Detector	Photo Lab X101	Tested	2:26:38 PM	08/28/2019
Heat Detector	Photo Lab X101	Tested		08/28/2019
Heat Detector	Platform	Tested	1:35:57 PM	08/28/2019
Heat Detector	Portable Restroom Boys Restroom	Tested	8:10:41 AM	08/28/2019
Heat Detector	Portable Restroom Girls Restroom	Tested	8:11:59 AM	08/28/2019
Heat Detector	Portable Restroom Staff Restroom	Tested	8:10:51 AM	08/28/2019
Heat Detector	Practice Attic BLDG T105	Tested	10:25:00 AM	08/28/2019
Heat Detector	Practice Attic BLDG T106	Tested	10:25:33 AM	08/28/2019
Heat Detector	Practice BLDG T107	Tested	10:28:36 AM	08/28/2019
Heat Detector	Practice BLDG T107	Tested	10:29:00 AM	08/28/2019
Heat Detector	Practice BLDG T109	Tested	10:29:07 AM	08/28/2019
Heat Detector	Rear Storage Area Attic	Tested	1:42:25 PM	08/28/2019
Heat Detector	Reception Area CC 115	Tested	12:48:43 PM	08/28/2019
Heat Detector	RM 103	Tested	1:34:05 PM	08/28/2019
Heat Detector	Rm 106	Tested	1:52:33 PM	08/28/2019
Heat Detector	Rm 116	Tested	1:47:11 PM	08/28/2019
Heat Detector	Rm 116	Tested	1:47:28 PM	08/28/2019
Heat Detector	Rm 117	Tested	1:46:38 PM	08/28/2019
Heat Detector	Rm 117	Tested	1:47:03 PM	08/28/2019
Heat Detector	Rm 118	Tested	1:45:36 PM	08/28/2019
Heat Detector	Rm 118	Tested	1:45:57 PM	08/28/2019
Heat Detector	RM 120	Tested	1:33:27 PM	08/28/2019
Heat Detector	RM 120	Tested	1:33:58 PM	08/28/2019
Heat Detector	RM 205	Tested	2:11:50 PM	08/28/2019
Heat Detector	RM 205	Tested	2:12:38 PM	08/28/2019

Device Type	Location	Service	Time	Date
		Passed		
Heat Detector	Rm 206	Tested	2:15:11 PM	08/28/2019
Heat Detector	Rm 206	Tested	2:15:37 PM	08/28/2019
Heat Detector	RM A107	Tested	2:30:24 PM	08/28/2019
Heat Detector	RM A107	Tested	2:30:40 PM	08/28/2019
Heat Detector	RM A108	Tested	2:29:24 PM	08/28/2019
Heat Detector	RM A108	Tested	2:29:36 PM	08/28/2019
Heat Detector	RM A109	Tested	2:28:56 PM	08/28/2019
Heat Detector	RM A109	Tested	2:29:16 PM	08/28/2019
Heat Detector	RM A110	Tested	2:27:24 PM	08/28/2019
Heat Detector	Rm C101	Tested	1:54:30 PM	08/28/2019
Heat Detector	Rm C201	Tested	1:59:31 PM	08/28/2019
Heat Detector	Rm C201	Tested	2:00:36 PM	08/28/2019
Heat Detector	RM C202	Tested	2:01:56 PM	08/28/2019
Heat Detector	RM C202	Tested	2:02:23 PM	08/28/2019
Heat Detector	RM C203	Tested	2:02:35 PM	08/28/2019
Heat Detector	RM C203	Tested	2:02:49 PM	08/28/2019
Heat Detector	Rm C204	Tested	2:07:35 PM	08/28/2019
Heat Detector	Rm C204	Tested	2:11:20 PM	08/28/2019
Heat Detector	RM C207	Tested	2:15:44 PM	08/28/2019
Heat Detector	RM C207	Tested	2:16:05 PM	08/28/2019
Heat Detector	Rm C207	Tested	2:18:08 PM	08/28/2019
Heat Detector	Rm C207	Tested	2:18:42 PM	08/28/2019
Heat Detector	Rm C209	Tested	2:18:50 PM	08/28/2019
Heat Detector	Rm C209	Tested	2:19:06 PM	08/28/2019
Heat Detector	Rm C210	Tested	2:20:53 PM	08/28/2019
Heat Detector	Rm C210	Tested	2:21:12 PM	08/28/2019
Heat Detector	Rm C211	Tested	2:21:18 PM	08/28/2019
Heat Detector	Rm C211	Tested	2:21:31 PM	08/28/2019
Heat Detector	Rm C212	Tested	2:21:38 PM	08/28/2019
Heat Detector	Rm C212	Tested	2:21:53 PM	08/28/2019
Heat Detector	RM CC146	Tested	1:13:52 PM	08/28/2019
Heat Detector	RM CC146	Tested	1:14:11 PM	08/28/2019
Heat Detector	RM CC147	Tested	1:12:50 PM	08/28/2019
Heat Detector	RM CC147	Tested	1:13:22 PM	08/28/2019
Heat Detector	RM CC148	Tested	1:12:11 PM	08/28/2019
Heat Detector	RM CC148	Tested	1:12:36 PM	08/28/2019
Heat Detector	RM D161	Tested	10:42:20 AM	08/28/2019
Heat Detector	RM M111	Tested	2:32:48 PM	08/28/2019
Heat Detector	RM M111	Tested	2:33:25 PM	08/28/2019
Heat Detector	RM M112	Tested	2:32:30 PM	08/28/2019
Heat Detector	RM M112	Tested	2:32:42 PM	08/28/2019
Heat Detector	RM M113	Tested	2:32:00 PM	08/28/2019
Heat Detector	RM M113	Tested	2:32:25 PM	08/28/2019
Heat Detector	Rm M114	Tested	2:31:08 PM	08/28/2019
Heat Detector	Rm M114	Tested	2:31:26 PM	08/28/2019
Heat Detector	Rm P110	Tested	10:47:40 AM	08/28/2019
Heat Detector	Rm P110	Tested	10:48:13 AM	08/28/2019
Heat Detector	Rm P150	Tested	10:54:17 AM	08/28/2019
Heat Detector	Rm P150	Tested	10:54:33 AM	08/28/2019
	· · · · · · · · · · · · · · · · · · ·			

Device Type	Location	Service	Time	Date
		Passed		
Heat Detector	Rm P150	Tested	10:55:05 AM	08/28/2019
Heat Detector	Rm P151	Tested	10:51:47 AM	08/28/2019
Heat Detector	Rm P151	Tested	10:52:59 AM	08/28/2019
Heat Detector	Rm P151	Tested	10:53:31 AM	08/28/2019
Heat Detector	Rm P151	Tested	10:54:06 AM	08/28/2019
Heat Detector	Rm P152	Tested	10:51:19 AM	08/28/2019
Heat Detector	Rm P152	Tested	10:51:38 AM	08/28/2019
Heat Detector	RM P153	Tested	10:46:08 AM	08/28/2019
Heat Detector	RM P153	Tested	10:46:28 AM	08/28/2019
Heat Detector	RM P153	Tested	10:46:34 AM	08/28/2019
Heat Detector	RM P153	Tested	10:46:58 AM	08/28/2019
Heat Detector	RM U 172	Tested	9:57:41 AM	08/28/2019
Heat Detector	RM U170	Tested	10:04:46 AM	08/28/2019
Heat Detector	RM U170	Tested	10:05:07 AM	08/28/2019
Heat Detector	RM U171	Tested	10:03:33 AM	08/28/2019
Heat Detector	RM U171	Tested	10:03:59 AM	08/28/2019
Heat Detector	RM U172	Tested	10:02:18 AM	08/28/2019
Heat Detector	RM U173	Tested	9:55:20 AM	08/28/2019
Heat Detector	RM U173	Tested	9:55:38 AM	08/28/2019
Heat Detector	RM U174	Tested	9:54:43 AM	08/28/2019
Heat Detector	RM U174	Tested	9:55:13 AM	08/28/2019
Heat Detector	RM U270	Tested	10:16:29 AM	08/28/2019
Heat Detector	RM U270	Tested	10:16:55 AM	08/28/2019
Heat Detector	RM U271	Tested	10:14:33 AM	08/28/2019
Heat Detector	RM U271	Tested	10:15:12 AM	08/28/2019
Heat Detector	RM U272	Tested	10:13:24 AM	08/28/2019
Heat Detector	RM U272	Tested	10:13:44 AM	08/28/2019
Heat Detector	RM U273	Tested	10:12:13 AM	08/28/2019
Heat Detector	RM U273	Tested	10:13:13 AM	08/28/2019
Heat Detector	RM U274	Tested	10:09:56 AM	08/28/2019
Heat Detector	RM U274	Tested	10:10:26 AM	08/28/2019
Heat Detector	RM U275	Tested	10:09:28 AM	08/28/2019
Heat Detector	RM U275	Tested	10:09:49 AM	08/28/2019
Heat Detector	RM W122	Tested	1:26:18 PM	08/28/2019
Heat Detector	RM W122	Tested	1:26:47 PM	08/28/2019
Heat Detector	Room 102	Tested	1:50:56 PM	08/28/2019
Heat Detector	Room 102	Tested	1:51:13 PM	08/28/2019
Heat Detector	Room 102	Tested	1:51:21 PM	08/28/2019
Heat Detector	Room 103	Tested	1:51:37 PM	08/28/2019
Heat Detector	Room 115	Tested	1:47:56 PM	08/28/2019
Heat Detector	Room 115	Tested	1:48:15 PM	08/28/2019
Heat Detector	RR STAFF	Tested	1:41:40 PM	08/28/2019
Heat Detector	Sci. Rm D102	Tested	10:44:06 AM	08/28/2019
Heat Detector	Sci. Rm D102	Tested	10:44:30 AM	08/28/2019
Heat Detector	Sci. Rm D160	Tested	10:45:06 AM	08/28/2019
Heat Detector	Sci. Rm D160	Tested	10:45:24 AM	08/28/2019
Heat Detector	Sci. Rm D161	Tested	10:36:26 AM	08/28/2019
Heat Detector	Serving Rm	Tested	1:39:57 PM	08/28/2019
Heat Detector	Serving Rm	Tested	1:40:20 PM	08/28/2019
Heat Detector	Serving Rm	Tested	1:40:25 PM	08/28/2019
ווכמו שפופנוטו		resteu	1.10.23111	00/20/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	Serving Rm	Tested	1:40:30 PM	08/28/2019
Heat Detector	Staff Dining	Tested	1:44:17 PM	08/28/2019
Heat Detector	Staff Dining	Tested	1:44:40 PM	08/28/2019
Heat Detector	Storage	Tested	2:30:45 PM	08/28/2019
Heat Detector	Storage Attic	Tested	1:42:01 PM	08/28/2019
Heat Detector	Storage Attic BLDG T	Tested	10:17:04 AM	08/28/2019
Heat Detector	Storage Attic BLDG T108	Tested	10:26:13 AM	08/28/2019
Heat Detector	Storage BLDG T 102	Tested	10:19:07 AM	08/28/2019
Heat Detector	Storage IDF D104	Tested	10:42:52 AM	08/28/2019
Heat Detector	Storage V106	Tested	11:00:47 AM	08/28/2019
Heat Detector	Storage W105	Tested	1:31:44 PM	08/28/2019
Heat Detector	Student Activities	Tested	1:35:33 PM	08/28/2019
Heat Detector	Teacher Lounge	Tested	1:52:54 PM	08/28/2019
Heat Detector	Teacher Lounge	Tested	1:53:16 PM	08/28/2019
Heat Detector	Teacher Lounge	Tested	1:53:21 PM	08/28/2019
Heat Detector	Training 102	Tested	1:34:28 PM	08/28/2019
Heat Detector	Transformer RM U109	Tested	10:05:34 AM	08/28/2019
Heat Detector	Vestibule CC105	Tested	12:43:08 PM	08/28/2019
Heat Detector	WKRM BB108	Tested	12:55:05 PM	08/28/2019
Heat Detector	WKRM K103	Tested	1:18:30 PM	08/28/2019
Heat Detector	WKRM K105	Tested	1:22:09 PM	08/28/2019
Heat Detector	Women RR CC135	Tested	12:39:24 PM	08/28/2019
Heat Detector	WOMENS Staff RR	Tested	1:36:17 PM	08/28/2019
Heat Detector	Women's RR U110	Tested	10:07:10 AM	08/28/2019
Heat Detector	Work RM U210	Tested	10:15:27 AM	08/28/2019
Pull Station	1st AQ Center Office 301	Tested	9:26:51 AM	08/28/2019
Pull Station	1st AQ Center Pool Equipment/Fire Sprinkler	Tested	8:43:44 AM	08/28/2019
	Riser			
Pull Station	1st AQ Center Small Gym Outside East	Tested	8:46:36 AM	08/28/2019
Pull Station	1st AQ Center Small Gym Outside West	Tested	8:59:52 AM	08/28/2019
Pull Station	1st Boys Locker Room Outside East	Tested	9:09:08 AM	08/28/2019
Pull Station	1st Boys Locker Room Outside Southeast	Tested	9:10:28 AM	08/28/2019
Pull Station	1st Boys Locker Room Outside West	Tested	9:15:30 AM	08/28/2019
Pull Station	1st Corridor By Classroom K134	Tested	12:43:26 PM	08/27/2019
Pull Station	1st Corridor By Library	Tested	1:57:42 PM	08/27/2019
Pull Station	1st Girls Locker Room Outside East	Tested	9:05:25 AM	08/28/2019
Pull Station	1st Main Gym Outside South	Tested	9:16:55 AM	08/28/2019
Pull Station	1st Main Gym Outside South	Tested	9:18:22 AM	08/28/2019
Pull Station	Bldg. BB Corridor By 113	Tested	10:27:22 AM	08/28/2019
Pull Station	Bldg. DD Auditorium Lobby DD100	Tested	1:19:21 PM	08/28/2019
Pull Station	Bldg. DD Corridor Exit	Tested	12:39:49 PM	08/28/2019
Pull Station	Bldg. DD Corridor Exit	Tested	12:54:52 PM	08/28/2019
Pull Station	Bldg. DD Entrance Lobby 100	Tested	1:19:06 PM	08/28/2019
Pull Station	Bldg. DD Entrance Lobby 100	Tested	1:21:47 PM	08/28/2019
Pull Station	Bldg. DD Exit East	Tested	12:49:37 PM	08/28/2019
Pull Station	Bldg. DD Stairwell 125	Tested	1:11:08 PM	08/28/2019
Pull Station	Bldg. R Student Dinning 123	Tested	9:45:16 AM	08/28/2019
Pull Station	Bldg. R Student Dinning 123	Tested	9:46:52 AM	08/28/2019
Pull Station	Main Bldg. Admin Office	Tested	10:56:23 AM	08/28/2019
Smoke Detector	1st Bldg. C Classroom C101	Tested	1:49:39 PM	08/27/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	1st Bldg. C Classroom C101	Tested	1:49:46 PM	08/27/2019
Smoke Detector	1st Bldg. C Classroom C102	Tested	1:47:53 PM	08/27/2019
Smoke Detector	1st Bldg. C Classroom C102	Tested	1:48:08 PM	08/27/2019
Smoke Detector	1st Bldg. C Classroom C103	Tested	1:45:19 PM	08/27/2019
Smoke Detector	1st Bldg. C Classroom C103	Tested	1:45:33 PM	08/27/2019
Smoke Detector	1 st Bldg. C Classroom C108 Security Office	Tested	1:44:52 PM	08/27/2019
Smoke Detector	1st Bldg. C Duplications Room	Tested	1:47:02 PM	08/27/2019
Smoke Detector	1 st Bldg. C Office By Duplications Room	Tested	1:53:53 PM	08/27/2019
Smoke Detector	1st Bldg. CC Classroom CC146	Tested	12:29:58 PM	08/27/2019
Smoke Detector	1st Bldg. CC Classroom CC146	Tested	12:30:13 PM	08/27/2019
Smoke Detector	1st Bldg. CC Classroom CC147	Tested	12:31:39 PM	08/27/2019
Smoke Detector	1st Bldg. CC Classroom CC147	Tested	12:31:47 PM	08/27/2019
Smoke Detector	1st Bldg. CC Classroom CC148	Tested	12:33:31 PM	08/27/2019
Smoke Detector	1st Bldg. CC Classroom CC148	Tested	12:33:40 PM	08/27/2019
Smoke Detector	1st Bldg. D Classroom D102 Flex Lab	Tested	9:49:58 AM	08/27/2019
Smoke Detector	1st Bldg. D Classroom D102 Flex Lab	Tested	9:50:14 AM	08/27/2019
Smoke Detector	1st Bldg. D Classroom D102 Flex Lab Storage	Tested	9:51:09 AM	08/27/2019
Smoke Detector	1st Bldg. D Classroom D160	Tested	9:51:56 AM	08/27/2019
Smoke Detector	1st Bldg. D Classroom D160	Tested	9:52:09 AM	08/27/2019
Smoke Detector	1st Bldg. D Classroom D161	Tested	9:46:26 AM	08/27/2019
Smoke Detector	1st Bldg. D Classroom D161	Tested	9:46:43 AM	08/27/2019
Smoke Detector	1st Bldg. D Classroom D161	Tested	9:48:53 AM	08/27/2019
Smoke Detector	1st Bldg. DD Concessions 105	Tested	1:22:54 PM	08/28/2019
Smoke Detector	1st Bldg. DD Control Room 101	Tested	1:25:58 PM	08/28/2019
Smoke Detector	1st Bldg. DD Corridor 113	Tested	12:44:27 PM	08/28/2019
Smoke Detector	1st Bldg. DD Corridor 113	Tested	12:44:54 PM	08/28/2019
Smoke Detector	1st Bldg. DD Corridor 113	Tested	12:45:06 PM	08/28/2019
Smoke Detector	1st Bldg. DD Corridor 113	Tested	12:45:10 PM	08/28/2019
Smoke Detector	1st Bldg. DD Corridor 113	Tested	12:45:17 PM	08/28/2019
Smoke Detector	1st Bldg. DD Corridor 113	Tested	12:45:21 PM	08/28/2019
Smoke Detector	1st Bldg. DD Corridor 113	Tested	12:45:25 PM	08/28/2019
Smoke Detector	1st Bldg. DD Corridor 113	Tested	12:45:29 PM	08/28/2019
Smoke Detector	1st Bldg. DD Corridor 113	Tested	12:45:35 PM	08/28/2019
Smoke Detector	1st Bldg. DD Corridor 113	Tested	12:45:41 PM	08/28/2019
Smoke Detector	1st Bldg. DD Corridor 113	Tested	12:45:45 PM	08/28/2019
Smoke Detector	1st Bldg. DD Corridor 113	Tested	12:45:51 PM	08/28/2019
Smoke Detector	1st Bldg. DD Corridor By Restrooms	Tested	1:30:14 PM	08/28/2019
Smoke Detector	1st Bldg. DD Electrical Room 137	Tested	1:45:52 PM	08/28/2019
Smoke Detector	1st Bldg. DD Electrical Room 137	Tested	1:46:08 PM	08/28/2019
Smoke Detector	1st Bldg. DD Entrance Lobby	Tested	1:18:10 PM	08/28/2019
Smoke Detector	1st Bldg. DD Entrance Lobby	Tested	1:18:26 PM	08/28/2019
Smoke Detector	1st Bldg. DD Entrance Lobby	Tested	1:18:32 PM	08/28/2019
Smoke Detector	1st Bldg. DD Entrance Lobby	Tested	1:18:38 PM	08/28/2019
Smoke Detector	1st Bldg. DD Entrance Lobby	Tested	1:18:45 PM	08/28/2019
Smoke Detector	1st Bldg. DD Entrance Lobby	Tested	1:18:49 PM	08/28/2019
Smoke Detector	1st Bldg. DD Entrance Lobby	Tested	1:18:53 PM	08/28/2019
Smoke Detector	1st Bldg. DD Fire Riser Room 136	Tested	1:40:28 PM	08/28/2019
Smoke Detector	1st Bldg. DD Fire Riser Room 136		1:41:22 PM	
Smoke Detector	1st Bldg. DD Fire Riser Room 136	Tested Tested	12:51:42 PM	08/28/2019
			12:52:15 PM	08/28/2019
Smoke Detector	1st Bldg. DD Girls Dressing Room	Tested	12.32.13 11	08/28/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	1st Bldg. DD Girls Dressing Room Restroom	Tested	12:52:38 PM	08/28/2019
Smoke Detector	1st Bldg. DD Janitor Room 110	Tested	1:28:59 PM	08/28/2019
Smoke Detector	1 st Bldg. DD Piano Storage	Tested	12:54:18 PM	08/28/2019
Smoke Detector	1 st Bldg. DD Women's Restroom	Tested	1:30:50 PM	08/28/2019
Smoke Detector	1 st Bldg. DD Women's Restroom	Tested	1:31:20 PM	08/28/2019
Smoke Detector	1st Bldg. EE Admin Assistant Office 105	Tested	9:04:41 AM	08/26/2019
Smoke Detector	1st Bldg. EE Admin Assistant Principals Office	Tested	9:10:10 AM	08/26/2019
Smoke Detector	1st Bldg. EE Admin Corridor By Restroom	Tested	9:05:34 AM	08/26/2019
Smoke Detector	1st Bldg. EE Admin Counselors Office 104	Tested	9:02:59 AM	08/26/2019
Smoke Detector	1 st Bldg. EE Admin Office Lobby	Tested	8:57:39 AM	08/26/2019
Smoke Detector	1st Bldg. EE Admin Office Lobby	Tested	8:59:18 AM	08/26/2019
Smoke Detector	1st Bldg. EE Admin Principles Office 109	Tested	9:01:00 AM	08/26/2019
Smoke Detector	1 st Bldg. EE Admin Restroom	Tested	9:08:26 AM	08/26/2019
Smoke Detector	1 st Bldg. EE Admin Restroom	Tested	9:09:31 AM	08/26/2019
Smoke Detector	1st Bldg. EE Admin Workroom 107	Tested	9:06:56 AM	08/26/2019
Smoke Detector	1st Bldg. EE Boy's Restroom By Classroom 191	Tested	9:39:40 AM	08/26/2019
Smoke Detector	1st Bldg. EE Classroom 191	Tested	9:43:30 AM	08/26/2019
Smoke Detector	1st Bldg. EE Classroom 191	Tested	9:43:42 AM	08/26/2019
Smoke Detector	1st Bldg. EE Electrical Room 113	Tested	8:55:47 AM	08/26/2019
Smoke Detector	1st Bldg. EE Electrical Room 121	Tested	9:30:52 AM	08/26/2019
Smoke Detector	1st Bldg. EE Elevator Machine Room 120	Tested	9:32:25 AM	08/26/2019
Smoke Detector	1st Bldg. EE Exploring Tech Lab Classroom 190 High Ceiling	Tested	9:48:20 AM	08/26/2019
Smoke Detector	1st Bldg. EE Exploring Tech Lab Classroom 190 High Ceiling	Tested	9:48:32 AM	08/26/2019
Smoke Detector	1st Bldg. EE Exploring Tech Lab Classroom 190 Low Ceiling	Tested	9:45:19 AM	08/26/2019
Smoke Detector	1st Bldg. EE Exploring Tech Lab Classroom 190 Low Ceiling	Tested	9:46:50 AM	08/26/2019
Smoke Detector	1st Bldg. EE Fire Riser Closet 125	Tested	9:59:17 AM	08/26/2019
Smoke Detector	1st Bldg. EE Girl's Restroom By Classroom 191	Tested	9:38:11 AM	08/26/2019
Smoke Detector	1st Bldg. EE Janitors Closet 124	Tested	9:41:55 AM	08/26/2019
Smoke Detector	1st Bldg. EE Material Prep 128A	Tested	9:52:46 AM	08/26/2019
Smoke Detector	1st Bldg. EE Material Prep Storage 128B	Tested	9:53:06 AM	08/26/2019
Smoke Detector	1st Bldg. EE Prep Room Classroom 192 & 193	Tested	8:52:16 AM	08/26/2019
Smoke Detector	1st Bldg. EE Prep Room Classroom 194 & 195	Tested	8:39:44 AM	08/26/2019
Smoke Detector	1st Bldg. EE Science Lab Classroom 192	Tested	8:53:31 AM	08/26/2019
Smoke Detector	1st Bldg. EE Science Lab Classroom 192	Tested	8:53:46 AM	08/26/2019
Smoke Detector	1st Bldg. EE Science Lab Classroom 193	Tested	8:50:04 AM	08/26/2019
Smoke Detector	1st Bldg. EE Science Lab Classroom 193	Tested	8:50:12 AM	08/26/2019
Smoke Detector	1st Bldg. EE Science Lab Classroom 194	Tested	8:41:09 AM	08/26/2019
Smoke Detector	1st Bldg. EE Science Lab Classroom 194	Tested	8:41:16 AM	08/26/2019
Smoke Detector	1st Bldg. EE Science Lab Classroom 195	Tested	8:35:05 AM	08/26/2019
Smoke Detector	1st Bldg. EE Science Lab Classroom 195	Tested	8:36:32 AM	08/26/2019
Smoke Detector	1st Bldg. EE Signal Room 106	Tested	9:26:10 AM	08/26/2019
Smoke Detector	1st Bldg. EE Signal Room 117	Tested	8:46:37 AM	08/26/2019
Smoke Detector	1 st Bldg. EE Staff Restroom By Elevator	Tested	9:36:51 AM	08/26/2019
Smoke Detector	1st Bldg. K Classroom K103 Science Workroom	Tested	12:37:38 PM	08/27/2019
Smoke Detector	1st Bldg. K Classroom K105 Science Workroom	Tested	12:39:24 PM	08/27/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	1st Bldg. K Classroom K133 Science	Tested	12:40:08 PM	08/27/2019
Smoke Detector	1st Bldg. K Classroom K133 Science	Tested	12:40:27 PM	08/27/2019
Smoke Detector	1st Bldg. K Classroom K134 Science	Tested	12:38:01 PM	08/27/2019
Smoke Detector	1st Bldg. K Classroom K134 Science	Tested	12:38:10 PM	08/27/2019
Smoke Detector	1st Bldg. K Classroom K135 Science	Tested	12:35:57 PM	08/27/2019
Smoke Detector	1st Bldg. K Classroom K135 Science	Tested	12:36:18 PM	08/27/2019
Smoke Detector	1st Bldg. P Classroom P150 Mechanical Room	Tested	9:56:50 AM	08/27/2019
Smoke Detector	1st Bldg. P Classroom P150 Storage Room	Tested	9:57:49 AM	08/27/2019
Smoke Detector	1st Bldg. P Classroom P150	Tested	9:53:32 AM	08/27/2019
Smoke Detector	1st Bldg. P Classroom P150	Tested	9:53:44 AM	08/27/2019
Smoke Detector	1st Bldg. P Classroom P150	Tested	9:53:51 AM	08/27/2019
Smoke Detector	1st Bldg. P Classroom P150	Tested	9:54:03 AM	08/27/2019
Smoke Detector	1st Bldg. P Classroom P151	Tested	9:58:37 AM	08/27/2019
Smoke Detector	1st Bldg. P Classroom P151	Tested	9:59:05 AM	08/27/2019
Smoke Detector	1st Bldg. P Classroom P151	Tested	9:59:44 AM	08/27/2019
Smoke Detector	1st Bldg. P Classroom P152 Mechanical Room	Tested	10:05:26 AM	08/27/2019
Smoke Detector	1st Bldg. P Classroom P152 Storage Room	Tested	10:02:26 AM	08/27/2019
Smoke Detector	1st Bldg. P Classroom P152	Tested	10:01:35 AM	08/27/2019
Smoke Detector	1st Bldg. P Classroom P152	Tested	10:01:47 AM	08/27/2019
Smoke Detector	1st Bldg. P Classroom P152A	Tested	10:02:02 AM	08/27/2019
Smoke Detector	1st Bldg. P Classroom P152B	Tested	10:02:45 AM	08/27/2019
Smoke Detector	1st Bldg. P Classroom P154	Tested	10:06:37 AM	08/27/2019
Smoke Detector	1st Bldg. P Classroom P154	Tested	10:06:47 AM	08/27/2019
Smoke Detector	1st Bldg. Q Classroom Q130 Science	Tested	1:59:31 PM	08/27/2019
Smoke Detector	1st Bldg. Q Classroom Q130 Science	Tested	1:59:54 PM	08/27/2019
Smoke Detector	1st Bldg. Q Classroom Q131 Science	Tested	2:01:29 PM	08/27/2019
Smoke Detector	1st Bldg. Q Classroom Q131 Science	Tested	2:01:58 PM	08/27/2019
Smoke Detector	1st Bldg. Q Classroom Q132 Science	Tested	2:04:02 PM	08/27/2019
Smoke Detector	1st Bldg. Q Classroom Q132 Science	Tested	7:49:52 AM	08/28/2019
Smoke Detector	1st Bldg. Q Science Workroom Q102	Tested	2:02:45 PM	08/27/2019
Smoke Detector	1st Bldg. Q Science Workroom Q105	Tested	2:00:50 PM	08/27/2019
Smoke Detector	1st Bldg. T Choral Classroom 100	Tested	1:19:33 PM	08/26/2019
Smoke Detector	1st Bldg. T Choral Classroom 100	Tested	1:19:50 PM	08/26/2019
Smoke Detector	1st Bldg. T Choral Corridor 112	Tested	1:16:37 PM	08/26/2019
Smoke Detector	1st Bldg. T Choral Music Library 108	Tested	1:23:36 PM	08/26/2019
Smoke Detector	1st Bldg. T Choral Practice 109	Tested	1:22:22 PM	08/26/2019
Smoke Detector	1st Bldg. T Choral Practice 110	Tested	1:21:13 PM	08/26/2019
Smoke Detector	1 st Bldg. T Custodian Office	Tested	1:15:04 PM	08/26/2019
Smoke Detector	1st Bldg. T Electrical Room 114	Tested	1:11:02 PM	08/26/2019
Smoke Detector	1st Bldg. T Electrical Room 114	Tested	1:12:34 PM	08/26/2019
Smoke Detector	1 st Bldg. T Instrumental Practice 104	Tested	1:35:01 PM	08/26/2019
Smoke Detector	1st Bldg. T Instrumental Practice 104	Tested	1:35:15 PM	08/26/2019
Smoke Detector	1st Bldg. T Instrumental Room 102	Tested	1:29:57 PM	08/26/2019
Smoke Detector	1st Bldg. T Instrumental Room 102	Tested	1:30:29 PM	08/26/2019
Smoke Detector	1st Bldg. T Instrumental Room 102	Tested	1:30:32 PM	08/26/2019
Smoke Detector	1st Bldg. T Instrumental Room 102	Tested	1:30:36 PM	08/26/2019
Smoke Detector	1st Bldg. T Instrumental Storage 104	Tested	1:37:36 PM	08/26/2019
Smoke Detector	1st Bldg. T Instrumental Storage 104	Tested	1:38:27 PM	08/26/2019
Smoke Detector	1st Bldg. T Instrumental Storage 107 Corridor	Tested	1:39:23 PM	08/26/2019
				, .,

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	1st Bldg. T Uniform Storage 116	Tested	1:41:04 PM	08/26/2019
Smoke Detector	1st Bldg. T Workroom 101	Tested	1:25:08 PM	08/26/2019
Smoke Detector	1st Bldg. U Classroom U170	Tested	12:31:54 PM	08/26/2019
Smoke Detector	1st Bldg. U Classroom U170	Tested	12:32:20 PM	08/26/2019
Smoke Detector	1st Bldg. U Classroom U171	Tested	12:31:36 PM	08/26/2019
Smoke Detector	1st Bldg. U Classroom U171	Tested	12:31:51 PM	08/26/2019
Smoke Detector	1st Bldg. U Classroom U172	Tested	12:31:26 PM	08/26/2019
Smoke Detector	1st Bldg. U Classroom U172	Tested	12:31:33 PM	08/26/2019
Smoke Detector	1st Bldg. U Classroom U173	Tested	12:30:07 PM	08/26/2019
Smoke Detector	1st Bldg. U Classroom U173	Tested	12:30:15 PM	08/26/2019
Smoke Detector	1st Bldg. U Classroom U174	Tested	12:25:27 PM	08/26/2019
Smoke Detector	1st Bldg. U Classroom U174	Tested	12:25:43 PM	08/26/2019
Smoke Detector	1st Bldg. U Electrical Room	Tested	12:40:26 PM	08/26/2019
Smoke Detector	1 st Bldg. U Electrical Room	Tested	12:40:39 PM	08/26/2019
Smoke Detector	1st Bldg. U Elevator Machine Room	Tested	12:42:16 PM	08/26/2019
Smoke Detector	1 st Bldg. U Men's Restroom	Tested	12:32:23 PM	08/26/2019
Smoke Detector	1 st Bldg. U Women's Restroom	Tested	12:38:57 PM	08/26/2019
Smoke Detector	1st Bldg. V Classroom 162 Mechanical	Tested	1:57:53 PM	08/26/2019
Smoke Detector	1st Bldg. V Classroom V162 Computer Lab	Tested	1:55:40 PM	08/26/2019
Smoke Detector	1st Bldg. V Classroom V162 Computer Lab	Tested	1:56:15 PM	08/26/2019
Smoke Detector	1st Bldg. V Classroom V162 Mechanical	Tested	1:54:40 PM	08/26/2019
Smoke Detector	1st Bldg. V Classroom V162	Tested	1:48:06 PM	08/26/2019
Smoke Detector	1st Bldg. V Classroom V162	Tested	1:52:30 PM	08/26/2019
Smoke Detector	1st Bldg. V Classroom V162B Photo Studio	Tested	1:53:03 PM	08/26/2019
Smoke Detector	1st Bldg. V Classroom V163	Tested	2:08:33 PM	08/26/2019
Smoke Detector	1st Bldg. V Classroom V164 Mechanical Room	Tested	2:11:27 PM	08/26/2019
Smoke Detector	1st Bldg. V Classroom V164	Tested	2:08:40 PM	08/26/2019
Smoke Detector	1st Bldg. V Classroom V164	Tested	2:10:12 PM	08/26/2019
Smoke Detector	1st Bldg. V Classroom V165	Tested	2:12:22 PM	08/26/2019
Smoke Detector	1st Bldg. V Classroom V165	Tested	2:12:36 PM	08/26/2019
Smoke Detector	1st Corridor By Classroom K133	Tested	12:46:05 PM	08/27/2019
Smoke Detector	1st Corridor By Classroom K133	Tested	12:46:19 PM	08/27/2019
Smoke Detector	1st Corridor By Workroom K105	Tested	12:45:30 PM	08/27/2019
Smoke Detector	1st Main Bldg. Library BB116 A.V Storage	Tested	12:57:09 PM	08/27/2019
Smoke Detector	1st Main Bldg. Library BB119 Librarian	Tested	12:55:31 PM	08/27/2019
Smoke Detector	1st Main Bldg. Library BB120 Periodical	Tested	12:54:13 PM	08/27/2019
Smoke Detector	1st Main Bldg. Library BB120 Periodical	Tested	12:54:50 PM	08/27/2019
Smoke Detector	1st Main Bldg. Library Computer Lab	Tested	12:56:13 PM	08/27/2019
Smoke Detector	1st Main Bldg. Library Computer Lab	Tested	12:56:45 PM	08/27/2019
Smoke Detector	1st Main Bldg. Library FACP Room	Tested	12:53:08 PM	08/27/2019
Smoke Detector	1st Main Bldg. Library Reception	Tested	12:53:39 PM	08/27/2019
Smoke Detector	1st Main Bldg. Library Reception	Tested	12:58:14 PM	08/27/2019
Smoke Detector	1st Mustang Field Concessions 106	Tested	10:21:06 AM	08/27/2019
Smoke Detector	1st Mustang Field Concessions 106	Tested	10:21:29 AM	08/27/2019
Smoke Detector	1st Mustang Field Custodian 102	Tested	10:26:13 AM	08/27/2019
Smoke Detector	1st Mustang Field Electrical/Data Room 105	Tested	10:14:05 AM	08/27/2019
Smoke Detector	1st Mustang Field Men's Restroom 104	Tested	10:22:37 AM	08/27/2019
Smoke Detector	1st Mustang Field Men's Restroom 109	Tested	10:28:15 AM	08/27/2019
Smoke Detector	1st Mustang Field Storage 101	Tested	10:27:16 AM	08/27/2019
Smoke Detector	1st Mustang Field Storage 202	Tested	10:30:07 AM	08/27/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	1st Mustang Field Storage 202	Tested	10:30:22 AM	08/27/2019
Smoke Detector	1st Mustang Field Storage 202	Tested	10:30:32 AM	08/27/2019
Smoke Detector	1st Mustang Field Tickets 107	Tested	10:16:30 AM	08/27/2019
Smoke Detector	1st Mustang Field Women's Restroom 103	Tested	10:25:21 AM	08/27/2019
Smoke Detector	1st Mustang Field Women's Restroom 108	Tested	10:19:40 AM	08/27/2019
Smoke Detector	2nd Bldg. C Classroom C201 Journalism	Tested	1:09:32 PM	08/27/2019
Smoke Detector	2nd Bldg. C Classroom C201 Journalism	Tested	1:10:24 PM	08/27/2019
Smoke Detector	2nd Bldg. C Classroom C202	Tested	1:11:58 PM	08/27/2019
Smoke Detector	2nd Bldg. C Classroom C202	Tested	1:12:14 PM	08/27/2019
Smoke Detector	2nd Bldg. C Classroom C203	Tested	1:13:41 PM	08/27/2019
Smoke Detector	2nd Bldg. C Classroom C203	Tested	1:13:49 PM	08/27/2019
Smoke Detector	2nd Bldg. C Classroom C204	Tested	1:14:38 PM	08/27/2019
Smoke Detector	2nd Bldg. C Classroom C204	Tested	1:14:45 PM	08/27/2019
Smoke Detector	2nd Bldg. C Classroom C205	Tested	1:15:34 PM	08/27/2019
Smoke Detector	2nd Bldg. C Classroom C205	Tested	1:15:43 PM	08/27/2019
Smoke Detector	2nd Bldg. C Classroom C206	Tested	1:16:42 PM	08/27/2019
Smoke Detector	2nd Bldg. C Classroom C206	Tested	1:16:50 PM	08/27/2019
Smoke Detector	2nd Bldg. C Classroom C207	Tested	1:18:28 PM	08/27/2019
Smoke Detector	2nd Bldg. C Classroom C208	Tested	1:20:26 PM	08/27/2019
Smoke Detector	2nd Bldg. C Classroom C208	Tested	1:20:33 PM	08/27/2019
Smoke Detector	2nd Bldg. C Classroom C209	Tested	1:21:23 PM	08/27/2019
Smoke Detector	2nd Bldg. C Classroom C209	Tested	1:21:32 PM	08/27/2019
Smoke Detector	2nd Bldg. C Classroom C210	Tested	1:24:21 PM	08/27/2019
Smoke Detector	2nd Bldg. C Classroom C210	Tested	1:24:31 PM	08/27/2019
Smoke Detector	2nd Bldg. C Classroom C211	Tested	1:30:47 PM	08/27/2019
Smoke Detector	2nd Bldg. C Classroom C211	Tested	1:30:53 PM	08/27/2019
Smoke Detector	2nd Bldg. C Classroom C212	Tested	1:27:25 PM	08/27/2019
Smoke Detector	2nd Bldg. C Classroom C212	Tested	1:27:31 PM	08/27/2019
Smoke Detector	2nd Bldg. C Corridor By Classroom 207	Tested	1:18:44 PM	08/27/2019
Smoke Detector	2nd Bldg. C Corridor By Classroom 207	Tested	1:23:10 PM	08/27/2019
Smoke Detector	2nd Bldg. C Corridor By Classroom 207	Tested	1:23:37 PM	08/27/2019
Smoke Detector	2nd Bldg. C Corridor By Classroom 211	Tested	1:30:04 PM	08/27/2019
Smoke Detector	2nd Bldg. C Corridor By Classroom 212	Tested	1:29:38 PM	08/27/2019
Smoke Detector	2nd Bldg. C Corridor By Elevator	Tested	1:24:04 PM	08/27/2019
Smoke Detector	2nd Bldg. C Elevator Machine Inside Classroom C210	Tested	1:25:25 PM	08/27/2019
Smoke Detector	2nd Bldg. DD Stairwell #3 Lighting DD107	Tested	1:17:47 PM	08/28/2019
Smoke Detector	2nd Bldg. EE Classroom 280	Tested	12:13:51 PM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 280	Tested	12:13:58 PM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 281	Tested	12:11:25 PM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 281	Tested	12:11:33 PM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 282	Tested	12:11:15 PM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 282	Tested	12:11:22 PM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 283	Tested	12:11:04 PM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 283	Tested	12:11:11 PM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 284	Tested	12:00:43 PM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 284	Tested	12:00:50 PM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 285	Tested	12:00:24 PM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 285	Tested	12:00:39 PM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 286	Tested	11:57:08 AM	08/26/201

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	2nd Bldg. EE Classroom 286	Tested	11:57:17 AM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 287	Tested	11:52:42 AM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 287	Tested	11:52:52 AM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 288	Tested	11:52:27 AM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 288	Tested	11:52:38 AM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 289	Tested	11:49:47 AM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 289	Tested	11:49:54 AM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 290	Tested	11:47:48 AM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 290	Tested	11:47:54 AM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 291	Tested	11:44:40 AM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 291	Tested	11:44:48 AM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 292	Tested	11:43:08 AM	08/26/2019
Smoke Detector	2nd Bldg. EE Classroom 292	Tested	11:43:20 AM	08/26/2019
Smoke Detector	2nd Bldg. EE Janitor Closet 206	Tested	11:51:22 AM	08/26/2019
Smoke Detector	2nd Bldg. EE Staff Restroom By Elevator	Tested	12:07:33 PM	08/26/2019
Smoke Detector	2nd Bldg. U Classroom U270	Tested	12:45:20 PM	08/26/2019
Smoke Detector	2nd Bldg. U Classroom U270	Tested	12:45:30 PM	08/26/2019
Smoke Detector	2nd Bldg. U Classroom U271	Tested	12:49:12 PM	08/26/2019
Smoke Detector	2nd Bldg. U Classroom U271	Tested	12:49:23 PM	08/26/2019
Smoke Detector	2nd Bldg. U Classroom U272	Tested	12:51:12 PM	08/26/2019
Smoke Detector	2nd Bldg. U Classroom U272	Tested	12:51:19 PM	08/26/2019
Smoke Detector	2nd Bldg. U Classroom U273	Tested	12:51:23 PM	08/26/2019
Smoke Detector	2nd Bldg. U Classroom U273	Tested	12:51:33 PM	08/26/2019
Smoke Detector	2nd Bldg. U Classroom U274	Tested	12:51:42 PM	08/26/2019
Smoke Detector	2nd Bldg. U Classroom U274	Tested	12:51:52 PM	08/26/2019
Smoke Detector	2nd Bldg. U Classroom U275	Tested	12:54:53 PM	08/26/2019
Smoke Detector	2nd Bldg. U Classroom U275	Tested	12:55:08 PM	08/26/2019
Smoke Detector	2nd Bldg. U Custodian Closet	Tested	12:47:36 PM	08/26/2019
Smoke Detector	2nd Bldg. U Workroom U210	Tested	12:48:53 PM	08/26/2019
Smoke Detector	AQ Center Concession Room 308	Tested	8:19:37 AM	08/28/2019
Smoke Detector	AQ Center Health Classroom 300	Tested	9:23:39 AM	08/28/2019
Smoke Detector	AQ Center Health Classroom 300	Tested	9:24:08 AM	08/28/2019
Smoke Detector	AQ Center Health Classroom 311 Storage	Tested	9:24:33 AM	08/28/2019
Smoke Detector	AQ Center Office 301	Tested	9:25:56 AM	08/28/2019
Smoke Detector	Bldg. A Classroom A107	Tested	10:24:33 AM	08/28/2019
Smoke Detector	Bldg. A Classroom A107	Tested	10:24:40 AM	08/28/2019
Smoke Detector	Bldg. A Classroom A108	Tested	10:23:20 AM	08/28/2019
Smoke Detector	Bldg. A Classroom A108	Tested	10:23:30 AM	08/28/2019
Smoke Detector	Bldg. A Classroom A109	Tested	10:22:48 AM	08/28/2019
Smoke Detector	Bldg. A Classroom A109	Tested	10:22:56 AM	08/28/2019
Smoke Detector	Bldg. A Classroom A110	Tested	10:21:40 AM	08/28/2019
Smoke Detector	Bldg. A Custodian Room	Tested	10:25:26 AM	08/28/2019
Smoke Detector	Bldg. A Men's Restroom	Tested	10:23:24 AM	08/28/2019
Smoke Detector	Bldg. A Women's Restroom	Tested	10:21:29 AM	08/28/2019
Smoke Detector	Bldg. A Women's Restroom	Tested	10:22:40 AM	08/28/2019
Smoke Detector	Bldg. BB ASB BB111	Tested	10:28:13 AM	08/28/2019
Smoke Detector	Bldg. BB ASB Office 110	Tested	10:28:44 AM	08/28/2019
Smoke Detector	Bldg. BB ASB Office 110 Storage	Tested	10:30:15 AM	08/28/2019
1				
Smoke Detector	Bldg. BB Conference BB115	Tested	10:29:39 AM	08/28/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Bldg. BB Film Chain 104	Tested	10:32:34 AM	08/28/2019
Smoke Detector	Bldg. BB Office BB113 Storage	Tested	10:27:51 AM	08/28/2019
Smoke Detector	Bldg. BB Office BB113	Tested	10:27:00 AM	08/28/2019
Smoke Detector	Bldg. BB Sound Studio	Tested	10:33:08 AM	08/28/2019
Smoke Detector	Bldg. BB T.V. Studio BB105	Tested	10:32:26 AM	08/28/2019
Smoke Detector	Bldg. BB T.V. Studio BB105	Tested	10:32:55 AM	08/28/2019
Smoke Detector	Bldg. BB TV Studio 105	Tested	10:31:48 AM	08/28/2019
Smoke Detector	Bldg. BB TV Studio 105	Tested	10:32:15 AM	08/28/2019
Smoke Detector	Bldg. BB Workroom BB108	Tested	10:31:24 AM	08/28/2019
Smoke Detector	Bldg. BB Workroom BB108	Tested	10:31:40 AM	08/28/2019
Smoke Detector	Bldg. DD Auditorium DD104	Tested	1:13:30 PM	08/28/2019
Smoke Detector	Bldg. DD Box Office DD101	Tested	1:25:36 PM	08/28/2019
Smoke Detector	Bldg. DD Boy's Dressing Room DD-126	Tested	12:49:12 PM	08/28/2019
Smoke Detector	Bldg. DD Boy's Dressing Room DD-126	Tested	12:50:31 PM	08/28/2019
Smoke Detector	Bldg. DD Boy's Dressing Room DD-126	Tested	12:50:58 PM	08/28/2019
	Restroom			
Smoke Detector	Bldg. DD Cat Walk	Tested	1:00:22 PM	08/28/2019
Smoke Detector	Bldg. DD Cat Walk	Tested	1:00:36 PM	08/28/2019
Smoke Detector	Bldg. DD Cat Walk	Tested	1:02:31 PM	08/28/2019
Smoke Detector	Bldg. DD Cat Walk	Tested	1:03:39 PM	08/28/2019
Smoke Detector	Bldg. DD Classroom DD118	Tested	1:31:14 PM	08/28/2019
Smoke Detector	Bldg. DD Classroom DD118	Tested	1:31:38 PM	08/28/2019
Smoke Detector	Bldg. DD Costume Storage DD100	Tested	12:44:09 PM	08/28/2019
Smoke Detector	Bldg. DD Costume Storage DD100	Tested	12:44:50 PM	08/28/2019
Smoke Detector	Bldg. DD Dimmer DD123	Tested	1:22:26 PM	08/28/2019
Smoke Detector	Bldg. DD Green Room DD134	Tested	12:53:22 PM	08/28/2019
Smoke Detector	Bldg. DD Men's Restroom	Tested	1:29:01 PM	08/28/2019
Smoke Detector	Bldg. DD Men's Restroom	Tested	1:29:31 PM	08/28/2019
Smoke Detector	Bldg. DD Office DD114	Tested	12:36:43 PM	08/28/2019
Smoke Detector	Bldg. DD Prop Storage DD115	Tested	12:41:35 PM	08/28/2019
Smoke Detector	Bldg. DD Prop Storage DD115	Tested	12:42:09 PM	08/28/2019
Smoke Detector	Bldg. DD Staff Restroom	Tested	12:46:40 PM	08/28/2019
Smoke Detector	Bldg. DD Stairwell #1 Orchestra Pit DD124	Tested	1:23:40 PM	08/28/2019
Smoke Detector	Bldg. DD Stairwell #1 DD122	Tested	1:23:19 PM	08/28/2019
Smoke Detector	Bldg. DD Stairwell #2 Orchestra Pit DD124	Tested	1:11:55 PM	08/28/2019
Smoke Detector	Bldg. DD Stairwell #2 DD125	Tested	1:09:36 PM	08/28/2019
Smoke Detector	Bldg. DD Stairwell #2 DD125	Tested	1:10:42 PM	08/28/2019
Smoke Detector	Bldg. DD Stairwell #3 Audio DD106	Tested	1:16:25 PM	08/28/2019
Smoke Detector	Bldg. DD Stairwell #3 DD108	Tested	1:15:19 PM	08/28/2019
Smoke Detector	Bldg. DD Stairwell #3 Lightning DD107	Tested	1:16:09 PM	08/28/2019
Smoke Detector	Bldg. DD Storage DD109	Tested	1:14:18 PM	08/28/2019
Smoke Detector	Bldg. DD Uni-Sex Restroom	Tested	12:51:45 PM	08/28/2019
Smoke Detector	Bldg. DD Uni-Sex Restroom	Tested	12:52:05 PM	08/28/2019
Smoke Detector	Bldg. DD Vestibule DD103D	Tested	12:42:31 PM	08/28/2019
Smoke Detector	Bldg. DD Vestibule DD104A	Tested	1:20:48 PM	08/28/2019
Smoke Detector	Bldg. DD Vestibule DD130A	Tested	1:28:31 PM	08/28/2019
Smoke Detector	Bldg. H Cafeteria	Tested	9:21:38 AM	08/28/2019
Smoke Detector	Bldg. H Cafeteria Storage	Tested	9:20:04 AM	08/28/2019
Smoke Detector		Tested	9:19:49 AM	08/28/2019
JINOKE DELECTOR	Bldg. H Kitchen	resteu	5115115740	00/20/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Bldg. M Book Room M101	Tested	10:16:45 AM	08/28/2019
Smoke Detector	Bldg. M Classroom 114	Tested	10:15:14 AM	08/28/2019
Smoke Detector	Bldg. M Classroom 114	Tested	10:18:07 AM	08/28/2019
Smoke Detector	Bldg. M Classroom M111	Tested	10:19:19 AM	08/28/2019
Smoke Detector	Bldg. M Classroom M111	Tested	10:19:28 AM	08/28/2019
Smoke Detector	Bldg. M Classroom M112	Tested	10:18:28 AM	08/28/2019
Smoke Detector	Bldg. M Classroom M112	Tested	10:18:36 AM	08/28/2019
Smoke Detector	Bldg. M Classroom M113	Tested	10:17:18 AM	08/28/2019
Smoke Detector	Bldg. M Classroom M113	Tested	10:17:39 AM	08/28/2019
Smoke Detector	Bldg. N Classroom 107	Tested	10:13:48 AM	08/28/2019
Smoke Detector	Bldg. N Classroom 107	Tested	10:14:03 AM	08/28/2019
Smoke Detector	Bldg. N Classroom 107	Tested	10:14:08 AM	08/28/2019
Smoke Detector	Bldg. N Classroom 107 Storage	Tested	10:15:00 AM	08/28/2019
Smoke Detector	Bldg. N Classroom 117	Tested	10:10:11 AM	08/28/2019
Smoke Detector	Bldg. N Classroom 117	Tested	10:10:48 AM	08/28/2019
Smoke Detector	Bldg. N Classroom N115	Tested	10:11:25 AM	08/28/2019
Smoke Detector	Bldg. N Classroom N115	Tested	10:11:33 AM	08/28/2019
Smoke Detector	Bldg. N Classroom N116	Tested	10:10:39 AM	08/28/2019
Smoke Detector	Bldg. N Classroom N116	Tested	10:10:51 AM	08/28/2019
Smoke Detector	Bldg. N Classroom N118	Tested	10:10:04 AM	08/28/2019
Smoke Detector	Bldg. N Classroom N118	Tested	10:10:14 AM	08/28/2019
Smoke Detector	Bldg. P Trophy Display	Tested	11:06:00 AM	08/28/2019
Smoke Detector	Bldg. R Cheer R126	Tested	9:49:53 AM	08/28/2019
Smoke Detector	Bldg. R Cheer R126	Tested	9:50:18 AM	08/28/2019
Smoke Detector	Bldg. R Custodian Closet	Tested	9:42:03 AM	08/28/2019
Smoke Detector	Bldg. R Custodian Staff Restroom	Tested	9:40:46 AM	08/28/2019
Smoke Detector	Bldg. R Kitchen Corridor	Tested	9:33:34 AM	08/28/2019
Smoke Detector	Bldg. R Kitchen Restroom	Tested	9:35:09 AM	08/28/2019
Smoke Detector	Bldg. R Kitchen Serving Line Restroom	Tested	9:43:18 AM	08/28/2019
Smoke Detector	Bldg. R Kitchen Serving Line Restroom Corridor	Tested	9:40:33 AM	08/28/2019
Smoke Detector	Bldg. R Kitchen Serving Line	Tested	9:38:40 AM	08/28/2019
Smoke Detector	Bldg. R Kitchen Serving Line	Tested	9:40:11 AM	08/28/2019
Smoke Detector	Bldg. R Kitchen Storage	Tested	9:34:37 AM	08/28/2019
Smoke Detector	Bldg. R Kitchen Window	Tested	9:36:33 AM	08/28/2019
Smoke Detector	Bldg. R Receiving R115 Storage	Tested	9:34:34 AM	08/28/2019
Smoke Detector	Bldg. R Receiving R115	Tested	9:32:23 AM	08/28/2019
Smoke Detector	Bldg. R Receiving R115	Tested	9:33:25 AM	08/28/2019
Smoke Detector	Bldg. R Student Dinning R123	Tested	9:44:12 AM	08/28/2019
Smoke Detector	Bldg. R Student Dinning R123	Tested	9:44:50 AM	08/28/2019
Smoke Detector	Bldg. R Student Dinning R123	Tested	9:45:17 AM	08/28/2019
Smoke Detector	Bldg. R Student Dinning R123	Tested	9:45:43 AM	08/28/2019
Smoke Detector	Bldg. R Student Dinning R123	Tested	9:46:19 AM	08/28/2019
Smoke Detector	Bldg. R Student Dinning R123	Tested	9:46:23 AM	08/28/2019
Smoke Detector	Bldg. R Student Dinning R123	Tested	9:46:27 AM	08/28/2019
Smoke Detector	Bldg. R Student Dinning R123	Tested	9:46:31 AM	08/28/2019
Smoke Detector	Bldg. R Student Dinning R123	Tested	9:46:35 AM	08/28/2019
Smoke Detector	Bldg. R Training Room 102	Tested	9:51:21 AM	08/28/2019
Smoke Detector	Bldg. R Training Room 102	Tested	9:51:56 AM	08/28/2019
Smoke Detector	Bldg. W Classroom 120	Tested	9:57:53 AM	08/28/2019
Smoke Detector	Bldg. W Classroom 120	Tested	10:01:12 AM	08/28/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Bldg. W Classroom 120	Tested	10:01:46 AM	08/28/2019
Smoke Detector	Bldg. W Classroom 120	Tested	10:02:32 AM	08/28/2019
Smoke Detector	Bldg. W Classroom 120	Tested	10:03:22 AM	08/28/2019
Smoke Detector	Bldg. W Classroom 120	Tested	10:03:38 AM	08/28/2019
Smoke Detector	Bldg. W Classroom 120 Storage	Tested	10:05:08 AM	08/28/2019
Smoke Detector	Bldg. W Classroom W120	Tested	9:55:44 AM	08/28/2019
Smoke Detector	Bldg. W Classroom W120	Tested	9:55:59 AM	08/28/2019
Smoke Detector	Bldg. W Classroom W121	Tested	9:59:39 AM	08/28/2019
Smoke Detector	Bldg. W Classroom W121	Tested	9:59:54 AM	08/28/2019
Smoke Detector	Bldg. W Men's Restroom	Tested	9:55:56 AM	08/28/2019
Smoke Detector	Bldg. W Men's Restroom Storage	Tested	9:56:49 AM	08/28/2019
Smoke Detector	Bldg. W Room 120 Department Office	Tested	9:59:32 AM	08/28/2019
Smoke Detector	Bldg. W Room 120 Department Office	Tested	10:00:12 AM	08/28/2019
Smoke Detector	Main Bldg. Admin Office Athletic Director	Tested	10:57:17 AM	08/28/2019
Smoke Detector	Main Bldg. Admin Office Athletics Office CC133	Tested	10:59:11 AM	08/28/2019
Smoke Detector	Main Bldg. Admin Office Corridor	Tested	11:01:54 AM	08/28/2019
Smoke Detector	Main Bldg. Admin Office Corridor Exit	Tested	11:01:26 AM	08/28/2019
Smoke Detector	Main Bldg. Admin Office Men's Staff Restroom	Tested	11:03:26 AM	08/28/2019
Smoke Detector	Main Bldg. Admin Office Women's Staff	Tested	11:04:08 AM	08/28/2019
	Restroom			
Smoke Detector	Main Bldg. Admin Office Workroom CC107	Tested	11:02:19 AM	08/28/2019
Smoke Detector	Main Bldg. Admin Office Workroom CC107	Tested	11:02:57 AM	08/28/2019
Smoke Detector	Main Bldg. Admin Office	Tested	10:55:56 AM	08/28/2019
Smoke Detector	Main Bldg. Admin Office	Tested	10:58:44 AM	08/28/2019
Smoke Detector	Main Bldg. Admin Office By Athletic Director	Tested	10:58:01 AM	08/28/2019
Smoke Detector	Main Bldg. Career Center CC126	Tested	10:49:15 AM	08/28/2019
Smoke Detector	Main Bldg. Career Center CC126	Tested	10:49:41 AM	08/28/2019
Smoke Detector	Main Bldg. Corridor By Counseling Office	Tested	10:52:13 AM	08/28/2019
Smoke Detector	Main Bldg. Corridor By Custodian	Tested	10:41:46 AM	08/28/2019
Smoke Detector	Main Bldg. Corridor By Library	Tested	10:44:09 AM	08/28/2019
Smoke Detector	Main Bldg. Corridor By Library	Tested	10:45:02 AM	08/28/2019
Smoke Detector	Main Bldg. Corridor By Main Office	Tested	10:39:32 AM	08/28/2019
Smoke Detector	Main Bldg. Corridor By Resource Officers Office	Tested	10:40:06 AM	08/28/2019
Smoke Detector	Main Bldg. Counseling Office	Tested	10:51:16 AM	08/28/2019
Smoke Detector	Main Bldg. Custodian Closet	Tested	10:42:45 AM	08/28/2019
Smoke Detector	Main Bldg. Records CC130	Tested	10:53:39 AM	08/28/2019
Smoke Detector	Main Bldg. Records CC130	Tested	10:53:49 AM	08/28/2019
Smoke Detector	Main Bldg. Resources Officers Office	Tested	10:40:42 AM	08/28/2019
Smoke Detector	Main Building Administration Assistant 112	Tested	10:56:14 AM	08/28/2019
Smoke Detector	Main Building Assistant Principal Office 122	Tested	10:57:41 AM	08/28/2019
Smoke Detector	Main Building Corridor By Principal Office	Tested	11:01:27 AM	08/28/2019
Smoke Detector	Main Building Counselor Corridor	Tested	10:55:01 AM	08/28/2019
Smoke Detector	Main Building Counselor Office 125	Tested	10:49:25 AM	08/28/2019
Smoke Detector	Main Building Counselor Office	Tested	10:51:55 AM	08/28/2019
Smoke Detector	Main Building Counselor Office	Tested	10:53:11 AM	08/28/2019
Smoke Detector	Main Building Counselor Secretary	Tested	10:53:46 AM	08/28/2019
Smoke Detector	Main Building Elevator Lobby	Tested	10:43:13 AM	08/28/2019
Smoke Detector	Main Building Nurse Office 120	Tested	10:43:42 AM	08/28/2019
Smoke Detector	Main Building Nurse Office 120 Restroom	Tested	10:44:35 AM	08/28/2019
Smoke Detector	Main Building Nurse Office 121	Tested	10:44:17 AM	08/28/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Main Building Principal Office 109	Tested	10:57:10 AM	08/28/2019
Smoke Detector	Main Building Staff Restroom	Tested	10:42:01 AM	08/28/2019
Smoke Detector	Main Building Staff Restroom	Tested	10:42:46 AM	08/28/2019
Smoke Detector	Main Building Storage Room	Tested	10:58:36 AM	08/28/2019
Smoke Detector	Main Building TV Studio Corridor	Tested	10:40:33 AM	08/28/2019
Smoke Detector	Portables Boy's Restroom	Tested	8:13:14 AM	08/28/2019
Smoke Detector	Portables Girl's Restroom	Tested	8:16:17 AM	08/28/2019
Smoke Detector	Storage Bldg. Weight Room	Tested	8:56:00 AM	08/28/2019
Waterflow Switch	1st AQ Center Custodial Storage	Tested	8:25:44 AM	08/28/2019
Waterflow Switch	1 st AQ Center Pool Equipment/Fire Sprinkler Riser	Tested	8:38:46 AM	08/28/2019
Waterflow Switch	1st Bldg. EE Fire Riser Closet 125	Tested	9:59:59 AM	08/26/2019
Waterflow Switch	1st Main Bldg. Custodian Closet	Tested	10:43:13 AM	08/28/2019
Waterflow Switch	Bldg. DD Fire Riser Room DD136	Tested	1:36:57 PM	08/28/2019
Waterflow Switch	Main Building Mechanical Room By Storage Room	Tested	11:00:05 AM	08/28/2019
Supervisory				
Tamper Switch	1 st South Outside Of Bldg. EE	Tested	10:03:52 AM	08/26/2019
Tamper Switch	AQ Center By Custodian Storage	Tested	8:27:34 AM	08/28/2019
Tamper Switch	AQ Center By Pool Equipment Room	Tested	8:38:13 AM	08/28/2019
Tamper Switch	Bldg. DD Fire Riser Room DD136	Tested	1:41:08 PM	08/28/2019
Tamper Switch	Bldg. EE South By Street (OS&Y)	Tested	1:35:49 PM	08/28/2019
Tamper Switch	Bldg. EE South By Street (OS&Y)	Tested	1:38:09 PM	08/28/2019
Tamper Switch	Bldg. EE South Outside Electrical Room 137 (PIV)	Tested	1:42:44 PM	08/28/2019
Device Type	Location	Service	Time	Date
	Failed/Other			
Control				
Battery	1st Bldg. EE Signal Room 117	Tested	8:46:10 AM	08/26/2019
Battery	1st Bldg. EE Signal Room 117	Tested	8:46:29 AM	08/26/2019

Building: NMUSD - Costa Mesa High School Control Panel: 2 - Silent Knight IFP-2000ECS

Device Type	Location	Service	Time	Date
	Passed			
Control				
Control Panel	Mustang Field Electrical/Data Room	Tested	10:09:42 AM	08/27/2019
Power Supply	1st Bldg. C Classroom C101	Tested	1:51:45 PM	08/27/2019
Power Supply	Mustang Field Electrical/Data Room	Tested	10:13:29 AM	08/27/2019

Building: NMUSD - Costa Mesa High School Control Panel: 3 - Silent Knight IFP-2000

Device Type	Location	Service	Time	Date
	Passed	l		
Control				
Battery	Bldg. DD Signal Room DD117	Tested	7:19:11 AM	08/28/2019
Battery	Bldg. DD Signal Room DD117	Tested	7:25:53 AM	08/28/2019
Battery	Bldg. DD Signal Room DD117	Tested	7:26:08 AM	08/28/2019
Battery	Bldg. DD Signal Room DD117	Tested	7:51:18 AM	08/28/2019
Communicator	Bldg. DD Signal Room DD117	Tested	7:27:09 AM	08/28/2019
Control Panel	Bldg. DD Signal Room DD117	Tested	7:14:36 AM	08/28/2019
Power Supply	Bldg. DD Signal Room DD117	Tested	7:23:32 AM	08/28/2019

Building: NMUSD - Costa Mesa High School Control Panel: 4 - Silent Knight IFP-50

Device Type	Location	Service	Time	Date
	Passed			
Control				
Control Panel	Portables Staff Restroom	Tested	8:08:51 AM	08/28/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Costa Mesa High School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Failed/Other	
Battery	Tested	2
Total		2
	Passed	
Annunciator	Tested	1
Battery	Tested	28
Communicator	Tested	1
Control Panel	Tested	4
Heat Detector	Tested	277
Power Supply	Tested	11
Pull Station	Tested	23
Smoke Detector	Tested	451
Tamper Switch	Tested	7
Waterflow Switch	Tested	6
Total		811

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - Costa Mesa High School

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

			Ambient	Alarm	🦻 Intell	igibility	Sound
C Location		Comment	◀ dB	◀ dB	Voice	STI	Test
Failed/Other							
Sound Test Points							
Entire Campus							0001

Time, Temperature & Level Testing

Generated by: BuildingReports.com

Building: NMUSD - Costa Mesa High School Control Panel: 1 - Silent Knight IFP-2000

The Time, Temperature, & Level Testing section details the measurements taken from various devices that are designed to respond in a certain amount of time, respond at a certain temperature, or respond within the acceptable range of volume or level. Items are grouped by Passed or Failed/Other.

Туре	Location	Comment	Sec	Deg	Lvl	ScanID
	Passed	đ				
Waterflow	/ Switch					
	1st AQ Center Custodial Storage	Passed	49	n/a	n/a	61327266
	1st AQ Center Pool Equipment/Fire Sprinkler Riser	Passed	64	n/a	n/a	61327267
	1 st Main Bldg. Custodian Closet	Passed	40	n/a	n/a	61327335
	Main Building Mechanical Room By Storage Room	Passed	38	n/a	n/a	61327398

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Costa Mesa High School

Control Panel: 1 - Silent Knight IFP-2000

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type		Category	% of Inventory	Quantity
Control Panel		Control	0.49%	4
Battery		Control	3.69%	30
Power Supply		Control	1.35%	11
Smoke Detector		Initiating	55.54%	451
Waterflow Switch		Initiating	0.74%	6
Tamper Switch		Supervisory	0.86%	7
Pull Station		Initiating	2.83%	23
Communicator		Control	0.12%	1
Heat Detector		Initiating Control	34.11% 0.12%	277
Annunciator Sound Test		Sound Test	0.12%	1
	Qt			
Туре	y	Model #	Description	Install Date
		New	(under 90 days)	
Silent Knight				
Heat Detector	27	SD505-AHS		08/28/2019
Theat Detector	4	56505 7415		00/20/2015
Control Panel	1	IFP-2000		08/26/2019
Power Supply	1	RPS-2000		08/26/2019
			e - 2 Years to 3 Years	
Battery	6	12v 18ah	Sealed Lead Acid	09/28/2017
Battery	18	12v 7ah	Sealed Lead Acid	09/28/2017
·	10	1207411	Sealed Lead Acid	09/28/2017
Potter				
Tamper Switch	1	PCVS-2		09/28/2017
Waterflow Switch	5	VSR		09/28/2017
Potter Electric				
Tamper Switch	5	PCVS-2		09/28/2017
Waterflow Switch	1	VSR		09/28/2017
Silent Knight				
Annunciator	1	RA-2000	LCD Display	09/28/2017
Heat Detector	3	SD505-AHS	Fixed Temperature	09/28/2017
Power Supply	2	5496	• -	09/28/2017
Power Supply	5	RPS-1000		09/28/2017
Pull Station	2	PA-DA	Keyed	09/28/2017
Pull Station	1	SD500-PS	- /	09/28/2017
	•			
Pull Station	17	SD500-PSDA	Keyed	09/28/2017

Smalle Datastar	4.7		Disete e la strie	00/20/2017	
Smoke Detector	43 3	SD505-APS	Photoelectric	09/28/2017	
Smoke Detector	5	SD505-PHOTO	Photoelectric	09/28/2017	
Smoke Detector	13	SK-PHOTO	Photoelectric	09/28/2017	
Victaulic					
Tamper Switch	1	705 Series		09/28/2017	
		In Service	- 5 Years to 10 Years		
Battery	2	12v 7ah	Sealed Lead Acid	05/09/2014	
Building: NMUSE) - C			2 - Silent Knight	
School		0		IFP-2000ECS	
complete inventory count	by <i>Âev</i>	vice type and category	rices and items that are included in your Inspe is provided. Items installed within the last 90 grouped together for easy reference.		
	Qt				
Туре	у	Model #	Description	Install Date	
		New	(under 90 days)		
Silent Knight					
Control Panel	1	IFP-2000ECS		08/26/2019	
Power Supply	2	ECS-125W		08/26/2019	
Building: NMUSE School) - C	osta Mesa High	Control Panel: 3 - Silent	Knight IFP-2000	
complete inventory count	by dev	vice type and category	ices and items that are included in your Inspe is provided. Items installed within the last 90 grouped together for easy reference.		
	Qt				
Туре	у	Model #	Description	Install Date	
		New	(under 90 days)		
Silent Knight					
Communicator	1		Digital Communicator	08/26/2019	
Control Panel	1	IFP-2000		08/26/2019	
Power Supply	1	5496		08/26/2019	
			e - 1 Year to 2 Years		
Battery	2	12v 55ah	Sealed Lead Acid	10/04/2017	
Battery Building: NMUSE	$\frac{2}{2}$	12v 7ah Osta Mesa High	Sealed Lead Acid	10/04/2017	
Building: NMUSD - Costa Mesa High School Control Panel: 4 - Silent Knight IFP-50					
The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.					
	Qt				
Туре	у	Model #	Description	Install Date	
		Now	(under 90 days)		

Silent Knight			
Control Panel	1	IFP-50	08/26/2019

i.

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Davis Magnet Elementary School 1050 Arlington Drive Costa Mesa, Ca 92626

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Aug 20, 2019

> Building: NMUSD - Davis Magnet Elementary School Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Thomas Galaz Title: Technician

Executive Summary Generated by: BuildingReports.com

Building Information	
Building: NMUSD – Davis Magnet Elementary School	Contact: Tim Waller
Address: 1050 Arlington Drive	Phone: 714-231-0363
Address:	Fax:
City/State/Zip: Costa Mesa, Ca 92626	Mobile:
Country: United States of America	Email:
Inspection Performed By	
Company: Cal Building Systems	Inspector: Thomas Galaz
Address: 2903 Saturn Street	Phone: 7149939650
Address: Suite F	Fax:
City/State/Zip: Brea, CA 92821	Mobile: 7142158050
Country: United States of America	Email: cbs@calbuildingsystems.com
Monitoring	
Company: Ph	hone: Account #:
Central Station Signal Verification	
Туре:	Mfg: Model #:
Test Time/Date:	Restore Time

Inspection Summary								
Calanda	Tota	Items	Ser	viced	Pas	ssed	Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Initiating	129	100.00%	129	100.00%	124	96.12%	5	3.88%
Totals	129	100%	129	100.00%	124	96.12%	5	3.88%
Certification								
Company: Cal Building Systems	s Building: NMUSD – Davis Magnet Elementary School							
Inspector: Thomas Galaz			Co	ontact: Tim \	Waller			
Signed:			Sie	gned:				

Discrepancy Report Generated by: BuildingReports.com

Building: N School	MUSD - Davis Magnet Elementa	Control Pane	el: 1		
Discrepancies a appropriate, cod	y Report consolidates each discrepancy listed w re listed by Category, and grouped by device ty le references are listed for your convenience. A Commission's website and is subject to a recall	ype. The description of Any item that was inspect	the problem is ted that is liste	s provided c	and where
Device Type	Manufacturer	ModelNumber	Da	ate	Qty
	Items listed for Reca	ll by Manufactur	rer		
	No recalled items found	during this inspection.			
8 ScanID	Location	Problem	Address	Refe	erence
	Initia	ting			
Heat Detec	tor				
47353267	Main Office Above ceiling next to health office	Failed Annunciation	1-1 35	NFPA72	0.16.1.1.1
47353268	Main Office Above ceiling next to restrooms	Failed Annunciation	1-1 36	NFPA72	0.16.1.1.1
47353271	Main Office Receptionist Area	Failed Annunciation	1-M1 34	NFPA72	0.16.1.1.1
47353269	Main Office Restroom	Failed Annunciation	1-1 40	NFPA72	0.16.1.1.1
47353270	Main Office Restroom	Failed Annunciation	1-1 41	NFPA72	0.16.1.1.1
	Code Ref	ferences			
NFPA72 10.16.1.	1.1 Visible annunciation of the location of an alphanumeric display, printout, or other a	-	e shall be by a	n indicator l	amp,

Proposed Solutions Report

Generated by: BuildingReports.com

Building: NMUSD - Davis Magnet Elementary School

The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.

ScanID	Location	Solution	Model #	Cost	Fix
	Initia	ting			
Heat Dete	ector				
47353267	Main Office Above ceiling next to health office	See notes/recommenda tions	4098-9733	T/M	
47353268	Main Office Above ceiling next to restrooms	See notes/recommenda tions	4098-9733	T/M	
47353271	Main Office Receptionist Area	See notes/recommenda tions	4098-9733	T/M	
47353269	Main Office Restroom	See notes/recommenda tions	4098-9733	T/M	
47353270	Main Office Restroom	See notes/recommenda tions	4098-9733	T/M	
			PO #: (none)	T/M	

Control Panel: 1

Notes & Recommendations

Generated by: BuildingReports.com

Building: NMUSD - Davis Magnet Elementary School Control Panel: 1

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

ScanID	Note	Device Type	Location	Comment		
			Initiating			
47353294	1	Smoke Detector	Building F Classroom 12	Passed		
Dupli	Duplicate address					
47353295	2	Smoke Detector	Building F Classroom 13	Passed		
Dupli	cate addr	ess				
47353299	3	Smoke Detector	Building F Classroom 15	Passed		
Parts	of the de	tector are missing and needs to b	be replaced			
47353267	4	Heat Detector	Main Office Above ceiling next to health office	Failed Annunciation		
Descr	ription is i	incorrect change to building repo	rts description.			
47353268	5	Heat Detector	Main Office Above ceiling next to restrooms	Failed Annunciation		
Descr	ription is i	incorrect change to building repo	rts description.			
47353271	6	Heat Detector	Main Office Receptionist Area	Failed Annunciation		
Descr	ription is i	incorrect change to building repo	rts description.			
47353269	7	Heat Detector	Main Office Restroom	Failed Annunciation		
Descr	ription is i	incorrect change to building repo	rts description.			
47353270	8	Heat Detector	Main Office Restroom	Failed Annunciation		
Descr	ription is i	incorrect change to building repo	rts description.			

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Davis Magnet Elementary School Control Panel: 1

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Initiating				
Heat Detector	Building A Boys Restroom	Tested	2:28:02 PM	08/19/2019
Heat Detector	Building A Classroom 26	Tested	1:47:58 PM	08/19/2019
Heat Detector	Building A Classroom 27	Tested	1:55:25 PM	08/19/2019
Heat Detector	Building A Classroom 28	Tested	2:05:09 PM	08/19/2019
Heat Detector	Building A Classroom 29	Tested	2:13:26 PM	08/19/2019
Heat Detector	Building A Classroom 30 Above Ceiling	Tested	10:55:12 AM	08/20/2019
Heat Detector	Building A Classroom 31 Above Ceiling	Tested	10:56:06 AM	08/20/2019
Heat Detector	Building A Girls Restroom	Tested	1:58:25 PM	08/19/2019
Heat Detector	Building B Boys Restroom	Tested	10:51:12 AM	08/20/2019
Heat Detector	Building B Classroom 3 Above Ceiling	Tested	11:05:20 AM	08/19/2019
Heat Detector	Building B Classroom 3 Above Ceiling	Tested	11:11:09 AM	08/19/2019
Heat Detector	Building B Girls Restroom	Tested	11:40:53 AM	08/19/2019
Heat Detector	Building B Mechanical Room North	Tested	10:50:31 AM	08/20/2019
Heat Detector	Building C Boys Restroom	Tested	10:52:49 AM	08/20/2019
Heat Detector	Building C Classroom 1 Above Ceiling	Tested	10:53:44 AM	08/20/2019
Heat Detector	Building C Classroom 1 Above Ceiling	Tested	10:54:47 AM	08/20/2019
Heat Detector	Building C Girls Restroom	Tested	10:51:52 AM	08/20/2019
Heat Detector	Building D Admin E Corridor Above Ceiling	Tested	10:37:06 AM	08/20/2019
Heat Detector	Building D Admin W Corridor Above Ceiling	Tested	10:35:46 AM	08/20/2019
Heat Detector	Building D Boys Restroom	Tested	10:39:05 AM	08/20/2019
Heat Detector	Building D Boys Restroom Above Ceiling	Tested	10:42:49 AM	08/20/2019
Heat Detector	Building D Conference Room Attic	Tested	10:32:01 AM	08/20/2019
Heat Detector	Building D Girls Restroom	Tested	10:37:46 AM	08/20/2019
Heat Detector	Building D Library Above Ceiling	Tested	10:32:50 AM	08/20/2019
Heat Detector	Building D Library Above Ceiling	Tested	10:33:51 AM	08/20/2019
Heat Detector	Building D Library Above Ceiling	Tested	10:34:12 AM	08/20/2019
Heat Detector	Building D Library Above Ceiling	Tested	10:34:32 AM	08/20/2019
Heat Detector	Building D Library Computer Room	Tested	10:34:50 AM	08/20/2019
Heat Detector	Building D Library Computer Room	Tested	10:35:28 AM	08/20/2019
Heat Detector	Building D men's Restroom	Tested	10:42:20 AM	08/20/2019
Heat Detector	Building D Nurses Restroom	Tested	10:38:45 AM	08/20/2019
Heat Detector	Building D Women's Restroom	Tested	10:41:39 AM	08/20/2019
Heat Detector	Building E Mechanical Room East	Tested	10:50:01 AM	08/20/2019
Heat Detector	Building E Mechanical Room West	Tested	10:49:14 AM	08/20/2019
Heat Detector	Building F Mechanical Room	Tested	9:21:43 AM	08/20/2019
Heat Detector	Building G Mechanical Room East	Tested	10:46:39 AM	08/20/2019
Heat Detector	Building G Mechanical Room West	Tested	10:47:44 AM	08/20/2019
Heat Detector	Building H Classroom 36 Storage Above Ceiling	Tested	9:17:35 AM	08/20/2019

Cal Building Systems

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	Building H Classroom 37 Entry Above Ceiling	Tested	9:20:03 AM	08/20/2019
Heat Detector	Building H Classroom 37 Storage Above Ceiling	Tested	9:18:45 AM	08/20/2019
Heat Detector	Building H Custodian Can Wash	Tested	9:15:20 AM	08/20/2019
Heat Detector	Building H Kitchen Toilet	Tested	9:13:53 AM	08/20/2019
Heat Detector	Building H Mechanical Room H110	Tested	9:16:05 AM	08/20/2019
Heat Detector	Building H Mechanical Room H120	Tested	9:16:58 AM	08/20/2019
Heat Detector	Building H MPR Attic	Tested	9:03:43 AM	08/20/2019
Heat Detector	Building H MPR Attic	Tested	9:05:27 AM	08/20/2019
Heat Detector	Building H MPR Attic	Tested	9:06:31 AM	08/20/2019
Heat Detector	Building H MPR Attic	Tested	9:06:50 AM	08/20/2019
Heat Detector	Building H MPR Attic	Tested	9:07:11 AM	08/20/2019
Heat Detector	Building H MPR Attic	Tested	9:07:36 AM	08/20/2019
Heat Detector	Building J Mechanical Room	Tested	9:21:01 AM	08/20/2019
Heat Detector	kitchen Area H106	Tested	9:11:20 AM	08/20/2019
Heat Detector	kitchen Area H106	Tested	9:12:12 AM	08/20/2019
Heat Detector	kitchen hall H106	Tested	9:09:55 AM	08/20/2019
Heat Detector	kitchen hall H106	Tested	9:10:53 AM	08/20/2019
Heat Detector	kitchen Hall H106	Tested	9:12:50 AM	08/20/2019
Heat Detector	Portable Boys Restroom	Tested	10:57:49 AM	08/20/2019
Heat Detector	Portable Classroom 32	Tested	10:45:56 AM	08/20/2019
Heat Detector	Portable Classroom 32	Tested	10:46:19 AM	08/20/2019
Heat Detector	Portable Classroom 33	Tested	10:43:48 AM	08/20/2019
Heat Detector	Portable Classroom 33	Tested	10:44:36 AM	08/20/2019
Heat Detector	Portable Classroom 34	Tested	10:31:20 AM	08/20/2019
Heat Detector	Portable Classroom 34	Tested	10:31:40 AM	08/20/2019
Heat Detector	Portable Classroom 35	Tested	10:27:05 AM	08/20/2019
Heat Detector	Portable Classroom 35	Tested	10:31:03 AM	08/20/2019
Heat Detector	Portable Gurls Restroom	Tested	10:58:32 AM	08/20/2019
Heat Detector	Portable men's Restroom	Tested	11:00:02 AM	08/20/2019
Heat Detector	Portable Women's Restroom	Tested	10:59:41 AM	08/20/2019
Smoke Detector	Building A Classroom 26	Tested	1:46:18 PM	08/19/2019
Smoke Detector	Building A Classroom 27	Tested	1:51:41 PM	08/19/2019
Smoke Detector	Building A Classroom 27	Tested	1:52:46 PM	08/19/2019
Smoke Detector	Building A Classroom 28	Tested	2:01:35 PM	08/19/2019
Smoke Detector	Building A Classroom 28	Tested	2:02:59 PM	08/19/2019
Smoke Detector	Building A Classroom 28 Storage	Tested	2:08:29 PM	08/19/2019
Smoke Detector	Building A Classroom 29	Tested	2:13:00 PM	08/19/2019
Smoke Detector	Building A Classroom 29	Tested	2:13:13 PM	08/19/2019
Smoke Detector	Building A Classroom 29 Storage	Tested	2:12:41 PM	08/19/2019
Smoke Detector	Building A Janitor Closet	Tested	2:23:12 PM	08/19/2019
Smoke Detector	Building B Classroom 3	Tested	10:56:58 AM	08/19/2019
Smoke Detector	Building B Classroom 3	Tested	11:03:44 AM	08/19/2019
Smoke Detector	Building B Classroom 3 Office	Tested	11:15:58 AM	08/19/2019
Smoke Detector	Building B Mechanical room south inside	Tested	11:36:47 AM	08/19/2019
	classroom 3			
Smoke Detector	Building E Classroom 17	Tested	12:54:34 PM	08/19/2019
Smoke Detector	Building E Classroom 17	Tested	12:56:10 PM	08/19/2019
Smoke Detector	Building E Classroom 18	Tested	12:58:17 PM	08/19/2019
Smoke Detector	Building E Classroom 18	Tested	12:58:51 PM	08/19/2019
Smoke Detector	Building E Classroom 19	Tested	1:00:43 PM	08/19/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building E Classroom 19	Tested	1:02:40 PM	08/19/2019
Smoke Detector	Building E Classroom 20	Tested	1:04:04 PM	08/19/2019
Smoke Detector	Building E Classroom 20	Tested	1:04:43 PM	08/19/2019
Smoke Detector	Building E Classroom 21	Tested	1:06:37 PM	08/19/2019
Smoke Detector	Building E Classroom 21	Tested	1:07:34 PM	08/19/2019
Smoke Detector	Building E Classroom 22	Tested	1:09:43 PM	08/19/2019
Smoke Detector	Building E Classroom 22	Tested	1:10:44 PM	08/19/2019
Smoke Detector	Building F Classroom 11	Tested	12:04:49 PM	08/19/2019
Smoke Detector	Building F Classroom 11	Tested	12:06:04 PM	08/19/2019
Smoke Detector	Building F Classroom 12	Tested	12:08:00 PM	08/19/2019
Smoke Detector	Building F Classroom 12	Tested	12:09:17 PM	08/19/2019
Smoke Detector	Building F Classroom 13	Tested	12:13:51 PM	08/19/2019
Smoke Detector	Building F Classroom 13	Tested	12:28:21 PM	08/19/2019
Smoke Detector	Building F Classroom 14	Tested	12:29:39 PM	08/19/2019
Smoke Detector	Building F Classroom 14	Tested	12:30:33 PM	08/19/2019
Smoke Detector	Building F Classroom 15	Tested	12:32:59 PM	
Smoke Detector	-		12:37:26 PM	08/19/2019
	Building F Classroom 15	Tested	12:50:52 PM	08/19/2019
Smoke Detector	Building F Classroom 16	Tested	12:51:51 PM	08/19/2019
Smoke Detector	Building F Classroom 16	Tested		08/19/2019
Smoke Detector	Building G Classroom 10	Tested	12:01:59 PM	08/19/2019
Smoke Detector	Building G Classroom 10	Tested	12:02:48 PM	08/19/2019
Smoke Detector	Building G Classroom 5	Tested	11:43:53 AM	08/19/2019
Smoke Detector	Building G Classroom 5	Tested	11:46:00 AM	08/19/2019
Smoke Detector	Building G Classroom 6	Tested	11:49:08 AM	08/19/2019
Smoke Detector	Building G Classroom 6	Tested	11:50:24 AM	08/19/2019
Smoke Detector	Building G Classroom 7	Tested	11:52:21 AM	08/19/2019
Smoke Detector	Building G Classroom 7	Tested	11:53:16 AM	08/19/2019
Smoke Detector	Building G Classroom 8	Tested	11:54:51 AM	08/19/2019
Smoke Detector	Building G Classroom 8	Tested	11:55:28 AM	08/19/2019
Smoke Detector	Building G Classroom 9	Tested	11:57:28 AM	08/19/2019
Smoke Detector	Building G Classroom 9	Tested	11:57:45 AM	08/19/2019
Smoke Detector	Building j Classroom 23	Tested	1:34:15 PM	08/19/2019
Smoke Detector	Building j Classroom 23	Tested	1:35:09 PM	08/19/2019
Smoke Detector	Building j Classroom 24	Tested	1:37:34 PM	08/19/2019
Smoke Detector	Building j Classroom 24	Tested	1:38:07 PM	08/19/2019
Smoke Detector	Building j Classroom 25	Tested	1:39:44 PM	08/19/2019
Smoke Detector	Building j Classroom 25	Tested	1:41:03 PM	08/19/2019
Device Type	Location	Service	Time	Date
	Failed/Other			
Initiating				
Heat Detector	Main Office Above ceiling next to health office	Tested	10:26:25 AM	08/19/2019
Heat Detector	Main Office Above ceiling next to restrooms	Tested	10:33:18 AM	08/19/2019
Heat Detector	Main Office Receptionist Area	Tested	10:45:47 AM	08/19/2019
Heat Detector	Main Office Restroom	Tested	10:36:28 AM	08/19/2019
Heat Detector	Main Office Restroom	Tested	10:40:23 AM	08/19/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Davis Magnet Elementary School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity			
Failed/Other					
Heat Detector	Tested	5			
Total		5			
	Passed				
Heat Detector	Tested	68			
Smoke Detector	Tested	56			
Total		129			

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Davis Magnet Elementary School Control Panel: 1

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category		% of Inventory	Quantity
Heat Detector		Initiating		56.59%	73
Smoke Detector		Initiating	1	43.41%	56
Туре	Qty	Model #	Description		Install Date
New (under 90 days)					
SimplexGrinnell					
Heat Detector	73	4098-9733	Fixed Temperatu	re	08/19/2019
Smoke Detector	56	4098-9714			08/19/2019

Zone Address Report

Generated by: BuildingReports.com

Building: NMUSD - Davis Magnet Elementary School Control Panel: 1

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Туре	ScanID
Zone/Cii	rcuit: 1			
03	Heat Detector	Building H MPR Attic	Fixed Temperature	47353400
05	Heat Detector	Building H MPR Attic	Fixed Temperature	47353401
07	Heat Detector	Building H MPR Attic	Fixed Temperature	47353402
10	Heat Detector	Building H MPR Attic	Fixed Temperature	47353403
100	Smoke Detector	Building F Classroom 11		47353291
102	Heat Detector	Portable Classroom 35	Fixed Temperature	47353421
103	Heat Detector	Portable Classroom 35	Fixed Temperature	47353422
106	Heat Detector	Portable Classroom 34	Fixed Temperature	47353423
108	Heat Detector	Portable Classroom 34	Fixed Temperature	47353424
111	Heat Detector	Building D Conference Room Attic	Fixed Temperature	47353425
114	Heat Detector	Building D Library Above Ceiling	Fixed Temperature	47353426
116	Heat Detector	Building D Library Above Ceiling	Fixed Temperature	47353427
118	Heat Detector	Building D Library Above Ceiling	Fixed Temperature	47353429
12	Heat Detector	Building H MPR Attic	Fixed Temperature	47353404
120	Heat Detector	Building D Library Above Ceiling	Fixed Temperature	47353430
124	Heat Detector	Building D Library Computer Room	Fixed Temperature	47353431
126	Heat Detector	Building D Library Computer Room	Fixed Temperature	47353432
128	Heat Detector	Building D Admin W Corridor Above	Fixed Temperature	47353433
131	Heat Detector	Ceiling Building D Admin E Corridor Above Ceiling	Fixed Temperature	47353434
135	Heat Detector	Building D Girls Restroom	Fixed Temperature	47353435
136	Heat Detector	Building D Nurses Restroom	Fixed Temperature	47353436
14	Heat Detector	Building H MPR Attic	Fixed Temperature	47353405
146	Heat Detector	Building D Boys Restroom	Fixed Temperature	47353437
147	Heat Detector	Building D Women's Restroom	Fixed Temperature	47353438
148	Heat Detector	Building D men's Restroom	Fixed Temperature	47353439
152	Heat Detector	Building D Boys Restroom Above Ceiling	Fixed Temperature	47353440
153	Heat Detector	Portable Classroom 33	Fixed Temperature	47353441
154	Heat Detector	Portable Classroom 33	Fixed Temperature	47353442
157	Heat Detector	Portable Classroom 32	Fixed Temperature	47353443
159	Heat Detector	Portable Classroom 32	Fixed Temperature	47353444
160	Smoke Detector	Building G Classroom 5		47353279
161	Smoke Detector	Building G Classroom 5		47353280
162	Smoke Detector	Building G Classroom 6		47353281
163	Smoke Detector	Building G Classroom 6		47353282
164	Heat Detector	Building G Mechanical Room East	Fixed Temperature	47353445
165	Smoke Detector	Building G Classroom 7		47353283
166	Smoke Detector	Building G Classroom 7		47353284

167	Smoke Detector	Building G Classroom 8		47353285
168	Smoke Detector	Building G Classroom 8		47353286
169	Smoke Detector	Building G Classroom 9		47353287
170	Smoke Detector	Building G Classroom 9		47353288
171	Heat Detector	Building G Mechanical Room West	Fixed Temperature	47353446
172	Smoke Detector	Building G Classroom 10		47353289
173	Smoke Detector	Building G Classroom 10		47353290
175	Smoke Detector	Building E Classroom 17		47353306
176	Smoke Detector	Building E Classroom 17		47353307
177	Heat Detector	Building E Mechanical Room West	Fixed Temperature	47353447
178	Smoke Detector	Building E Classroom 18	•	47353308
179	Smoke Detector	Building E Classroom 18		47353309
18	Heat Detector	kitchen hall H106	Fixed Temperature	47353406
180	Smoke Detector	Building E Classroom 19	•	47353310
181	Smoke Detector	Building E Classroom 19		47353311
182	Smoke Detector	Building E Classroom 20		47353312
183	Smoke Detector	Building E Classroom 20		47353313
184	Heat Detector	Building E Mechanical Room East	Fixed Temperature	47353448
185	Smoke Detector	Building E Classroom 21		47353314
186	Smoke Detector	Building E Classroom 21		47353315
187	Smoke Detector	Building E Classroom 22		47353316
188	Smoke Detector	Building E Classroom 22		47353317
190	Heat Detector	Building B Mechanical Room North	Fixed Temperature	47353449
191	Heat Detector	Building B Boys Restroom	Fixed Temperature	47353450
192	Heat Detector	Building B Girls Restroom	Fixed Temperature	47353278
193	Smoke Detector	Building B Mechanical room south inside	· · · · · · · · · · · · · · · · · · ·	47353277
		classroom 3		
196	Smoke Detector	Building B Classroom 3 Office		47353276
197	Smoke Detector	Building B Classroom 3		47353273
198	Heat Detector	Building B Classroom 3 Above Ceiling	Fixed Temperature	47353274
199	Smoke Detector	Building B Classroom 3		47353272
20	Heat Detector	kitchen hall H106	Fixed Temperature	47353407
200	Heat Detector	Building B Classroom 3 Above Ceiling	Fixed Temperature	47353275
205	Heat Detector	Building C Girls Restroom	Fixed Temperature	47353451
206	Heat Detector	Building C Boys Restroom	Fixed Temperature	47353452
21	Heat Detector	kitchen Area H106	Fixed Temperature	47353408
213	Heat Detector	Building C Classroom 1 Above Ceiling	Fixed Temperature	47353453
215	Heat Detector	Building C Classroom 1 Above Ceiling	Fixed Temperature	47353454
22	Heat Detector	kitchen Area H106	Fixed Temperature	47353409
221	Heat Detector	Building A Classroom 26	Fixed Temperature	47353324
222	Smoke Detector	Building A Classroom 26		47353300
223	Smoke Detector	Building A Classroom 27		47353326
224	Heat Detector	Building A Classroom 27	Fixed Temperature	47353302
225	Smoke Detector	Building A Classroom 27		47353325
226	Heat Detector	Building A Girls Restroom	Fixed Temperature	47353327
227	Smoke Detector	Building A Classroom 28		47353328
228	Heat Detector	Building A Classroom 28	Fixed Temperature	47353330
229	Smoke Detector	Building A Classroom 28		47353329
23	Heat Detector	kitchen Hall H106	Fixed Temperature	47353410
230	Smoke Detector	Building A Classroom 28 Storage		47353331
231	Smoke Detector	Building A Classroom 29 Storage		47353335
232	Smoke Detector	Building A Classroom 29		47353332
233	Heat Detector	Building A Classroom 29	Fixed Temperature	47353334

34	Heat Detector	Main Office Receptionist Area	Fixed Temperature	47353271
	Circuit: M1			
99	Smoke Detector	Building F Classroom 11		47353292
97	Smoke Detector	Building F Classroom 12		47353293
96	Smoke Detector	Building F Classroom 13		47353295
96	Smoke Detector	Building F Classroom 12		47353294
94	Smoke Detector	Building F Classroom 13		47353296
93	Smoke Detector	Building F Classroom 14		47353297
92	Smoke Detector	Building F Classroom 14		47353298
91	Smoke Detector	Building F Classroom 15		47353301
90	Smoke Detector	Building F Classroom 15	•····	47353299
88	Heat Detector	Building F Mechanical Room	Fixed Temperature	47353419
87	Smoke Detector	Building F Classroom 16		47353304
86	Smoke Detector	Building F Classroom 16		47353305
84	Smoke Detector	Building j Classroom 23		47353318
83	Smoke Detector	Building j Classroom 23		47353319
82	Smoke Detector	Building j Classroom 24		47353320
81	Smoke Detector	Building j Classroom 24	incu remperature	473533418
78	Heat Detector	Building J Mechanical Room	Fixed Temperature	47353522
78	Smoke Detector	Building j Classroom 25 Building j Classroom 25		47353323
77	Smoke Detector	Building j Classroom 25		47353323
71	Heat Detector	Building H Classroom 37 Entry Above Ceiling	Fixed Temperature	47353417
71	Host Detector	Ceiling Building H Classroom 37 Entry Above	Fixed Tomporature	17252117
60	Heat Detector	Building H Classroom 37 Storage Above	Fixed Temperature	47353416
65	Heat Detector	Ceiling	Fixed Tomporature	47252416
58	Heat Detector	Building H Classroom 36 Storage Above	Fixed Temperature	47353415
46 58	Heat Detector	Building H Mechanical Room H120	Fixed Temperature	47353414
41 46	Heat Detector	Main Office Restroom	Fixed Temperature	47353270
40	Heat Detector	Main Office Restroom	Fixed Temperature	47353269
40	Heat Date 1	restrooms	First True 1	47252260
36	Heat Detector	Main Office Above ceiling next to	Fixed Temperature	47353268
26		office		
35	Heat Detector	Main Office Above ceiling next to health	Fixed Temperature	47353267
28	Heat Detector	Building H Mechanical Room H110	Fixed Temperature	47353413
26	Heat Detector	Building H Custodian Can Wash	Fixed Temperature	47353412
25	Heat Detector	Building H Kitchen Toilet	Fixed Temperature	47353411
248	Heat Detector	Portable Women's Restroom	Fixed Temperature	47353460
246	Heat Detector	Portable men's Restroom	Fixed Temperature	47353459
244	Heat Detector	Portable Gurls Restroom	Fixed Temperature	47353458
242	Heat Detector	Portable Boys Restroom	Fixed Temperature	47353457
241	Heat Detector	Building A Classroom 31 Above Ceiling	Fixed Temperature	47353456
238	Heat Detector	Building A Classroom 30 Above Ceiling	Fixed Temperature	47353455
236	Heat Detector	Building A Boys Restroom	Fixed Temperature	47353337
235	Smoke Detector	Building A Janitor Closet		47353336
234	Smoke Detector	Building A Classroom 29		47353333

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Davis Magnet Elementary School 1050 Arlington Drive Costa Mesa, Ca 92626

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Aug 19, 2019

> Building: NMUSD - Davis Magnet Elementary School Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Thomas Galaz Title: Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD - Davis Magnet Elementary School	Contact: Tim Waller	
Address: 1050 Arlington Drive	Phone: 714-231-0363	
Address:	Fax:	
City/State/Zip: Costa Mesa, Ca 92626	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Thomas Galaz	
Address: 2903 Saturn Street	Phone: 7149939650	
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile: 7142158050	
Country: United States of America	Email: cbs@calbuildingsystems.com	
System Control Unit		
Manufacturer: simplex	Inspection Date: 08/19/2019 IDC Style	:
Model Number: 4100u	Install Date: 08/19/2019 SLC Style	:
Software Version:	Version Date: 08/19/2019 NAC Style	2:
Location: Main office server room	Current Protection:	
Monitoring		
Company: Pł	hone: Account #:	
Central Station Signal Verification		
Туре:	Mfg: Model #:	
Test Time/Date:	Restore Time	

Inspection Summary								
Cohanan	Tota	ltems	Serviced		Passed		Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Control	6	30.00%	6	100.00%	6	100.00%	0	0%
Initiating	14	70.00%	14	100.00%	10	71.43%	4	28.57%
Totals	20	100%	20	100.00%	16	80.00%	4	20.00%
Certification								
Company: Cal Building Systems			Bu	ilding: NML	JSD – Dav	is Magnet I	Elementary	/ School
Inspector: Thomas Galaz			Co	ontact: Tim	Waller			
Signed:			Sig	gned:				

Discrepancy Report Generated by: BuildingReports.com

Building: NMUSD - Davis Magnet Elementary Control Panel: 1 - simplex 4100u									
School									
The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.									
Device Type	Manufacturer	ModelNumber	Da	ite Qty					
	Items listed for Recal	ll by Manufactur	rer						
	No recalled items found d	luring this inspection.							
🖔 ScanID	C Location	Problem	Address	Reference					
	Initiat	ting							
Smoke De	tector								
47353258	front of main office Main office	Failed Annunciation	1	NFPA72 10.16.1.1.1					
47353259	front of main office Main office	Failed Annunciation	1	NFPA72 10.16.1.1.1					
47353261	principal office Main office	Failed Annunciation	1	NFPA72 10.16.1.1.1					
47353262	principal office Main office	Failed Annunciation	1	NFPA72 10.16.1.1.1					
Code References									
NFPA72 10.16.1.1.1 Visible annunciation of the location of an operated initiating device shall be by an indicator lamp, alphanumeric display, printout, or other approved means.									

Proposed Solutions Report

Generated by: BuildingReports.com

Building: NMUSD - Davis Magnet Elementary School

Control Panel: 1 - simplex 4100u

The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.

ScanID	Location	Solution	Model #	Cost	Fix				
	Initiating								
Smoke D	Smoke Detector								
47353258	front of main office Main office	See notes/recommenda tions	4098-9714	T/M					
47353259	front of main office Main office	See notes/recommenda tions	4098-9714	T/M					
47353261	principal office Main office	See notes/recommenda tions	4098-9714	T/M					
47353262	principal office Main office	See notes/recommenda tions	4098-9714	T/M					
			PO #: (none)	T/M					

Notes & Recommendations

Generated by: BuildingReports.com

Building: NMUSD - Davis Magnet Elementary School Control Panel: 1 - simplex 4100u

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

ScanID	Note	Device Type	Location	Comment				
	Initiating							
47353258	1	Smoke Detector	front of main office Main office	Failed Annunciation				
Descr	iption is i	incorrect. Change to build	ding report description.					
47353259	2	Smoke Detector	front of main office Main office	Failed Annunciation				
Regist	tered inco	prrect location change in	building reports					
47353261	3	Smoke Detector	principal office Main office	Failed Annunciation				
Incorr	ect locati	on registering at panel n	eed to change on building reports					
47353262	4	Smoke Detector	principal office Main office	Failed Annunciation				
Incorr	ect locati	on registering on panel						

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Davis Magnet Elementary School

Control Panel: 1 - simplex 4100u

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Battery	Main office server room	Tested	8:41:35 AM	08/19/2019
Battery	Main office server room	Tested	8:42:56 AM	08/19/2019
Battery	Main office server room	Tested	8:44:55 AM	08/19/2019
Battery	Main office server room	Tested	8:46:24 AM	08/19/2019
Control Panel	Main office server room	Tested	8:39:29 AM	08/19/2019
Power Supply	Main office server room	Tested	8:43:54 AM	08/19/2019
Initiating				
Smoke Detector	2nd health office by rear entrance	Tested/Cleaned	9:19:30 AM	08/19/2019
Smoke Detector	classroom #1 back of room	Tested/Cleaned	9:59:20 AM	08/19/2019
Smoke Detector	classroom #1	Tested/Cleaned	9:57:30 AM	08/19/2019
Smoke Detector	classroom #2 back of room	Tested/Cleaned	10:10:29 AM	08/19/2019
Smoke Detector	classroom #2	Tested/Cleaned	10:08:35 AM	08/19/2019
Smoke Detector	main office hallway by rear entrance	Tested/Cleaned	9:25:16 AM	08/19/2019
Smoke Detector	principal office Main office	Tested/Cleaned	9:42:30 AM	08/19/2019
Smoke Detector	Side hallway behind restrooms Main office	Tested/Cleaned	9:27:29 AM	08/19/2019
Smoke Detector	Side hallway behind restrooms Main office	Tested/Cleaned	9:31:44 AM	08/19/2019
Smoke Detector	Main office server room	Tested/Cleaned	9:14:43 AM	08/19/2019
Device Type	Location	Service	Time	Date
	Failed/Other			
Initiating				
Smoke Detector	front of main office Main office	Tested/Cleaned	9:39:07 AM	08/19/2019
Smoke Detector	front of main office Main office	Tested/Cleaned	9:41:29 AM	08/19/2019
Smoke Detector	principal office Main office	Tested/Cleaned	9:46:43 AM	08/19/2019
Smoke Detector	principal office Main office	Tested/Cleaned	9:49:53 AM	08/19/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Davis Magnet Elementary School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity				
Failed/Other						
Smoke Detector	Tested/Cleaned	4				
Total		4				
	Passed					
Battery	Tested	4				
Control Panel	Tested	1				
Power Supply	Tested	1				
Smoke Detector	Tested/Cleaned	10				
Total		20				

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Davis Magnet Elementary School Control Panel: 1 - simplex 4100u

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category	% of Invento	ry Quantity
Control Panel		Control	5.0	0% 1
Battery		Control	20.0	0% 4
Power Supply		Control	5.0	0% 1
Smoke Detector		Initiating	70.0	0% 14
Туре	Qty	Model #	Description	Install Date
		New	(under 90 days)	
Battery	2	12v 26a	-	08/19/2019
Battery	2	12v 7a		08/19/2019
simplex				
Control Panel	1	4100u		08/19/2019
Power Supply	1	4009		08/19/2019
Smoke Detector	14	4098-9714		08/19/2019

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Davis Magnet Elementary School 1050 Arlington Drive Costa Mesa, Ca 92626

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Aug 20, 2019

> Building: NMUSD - Davis Magnet Elementary School Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Michael Cannon Title: Service Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD – Davis Magnet Elementary Schoo	ol Contact: Tim Wal	ler
Address: 1050 Arlington Drive	Phone: 714–231-	-0363
Address:	Fax:	
City/State/Zip: Costa Mesa, Ca 92626	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Michae	el Cannon
Address: 2903 Saturn Street	Phone: 714–715-	-1223
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: mcannon@	Dcalbuildingsystems.com
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
C	Tota	Items	Ser	Serviced		ssed	Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Control	4	4.88%	4	100.00%	4	100.00%	0	0%
Initiating	78	95.12%	78	100.00%	78	100.00%	0	0%
Totals	82	100%	82	100.00%	82	100.00%	0	0%
Certification								
Company: Cal Building Systems			Βι	uilding: NMU	SD – Dav	is Magnet E	lementary	/ School
Inspector: Michael Cannon			Co	ontact: Tim \	Waller			
The Came								
Signed: Aug 22, 2019 7:25:32	AM		Si	gned:				

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Davis Magnet Elementary School Control Panel: 1

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Admin Entrance Area	Inspected	11:02:35 AM	08/20/2019
Battery	Portable 35 YMCA	Tested	9:28:06 AM	08/20/2019
Battery	Portable 35 YMCA	Tested	9:28:41 AM	08/20/2019
Power Supply	Portable 35 YMCA	Inspected	9:27:43 AM	08/20/2019
Initiating				
Pull Station	MPR Building Main Hall Exit	Tested	8:44:24 AM	08/20/2019
Pull Station	MPR Building Main Hall Exit	Tested	8:45:35 AM	08/20/2019
Pull Station	MPR Building Main Hall Exit	Tested	8:45:40 AM	08/20/2019
Pull Station	MPR Building Main Hall Exit	Tested	8:45:50 AM	08/20/2019
Pull Station	Portable 38	Tested	10:22:42 AM	08/20/2019
Pull Station	Portable 39	Tested	10:23:48 AM	08/20/2019
Pull Station	Portable 40	Tested	10:24:05 AM	08/20/2019
Pull Station	Portable 41	Tested	10:25:20 AM	08/20/2019
Smoke Detector	Admin Conference Room	Tested	11:07:40 AM	08/20/2019
Smoke Detector	Admin Corridor By Restrooms	Tested	11:15:58 AM	08/20/2019
Smoke Detector	Admin Nurse's Clinic	Tested	11:10:07 AM	08/20/2019
Smoke Detector	Admin Nurse's Clinic	Tested	11:10:30 AM	08/20/2019
Smoke Detector	Admin Staff Lounge	Tested	11:16:33 AM	08/20/2019
Smoke Detector	Admin Storage Room	Tested	11:18:22 AM	08/20/2019
Smoke Detector	Admin Storage/Mail Room	Tested	11:20:27 AM	08/20/2019
Smoke Detector	Admin Workroom	Tested	11:12:53 AM	08/20/2019
Smoke Detector	Admin Workroom	Tested	11:14:44 AM	08/20/2019
Smoke Detector	Admin Corridor Exit	Tested	11:01:43 AM	08/20/2019
Smoke Detector	Admin Corridor Exit	Tested	11:06:02 AM	08/20/2019
Smoke Detector	Admin Corridor	Tested	11:03:15 AM	08/20/2019
Smoke Detector	Admin Corridor	Tested	11:05:40 AM	08/20/2019
Smoke Detector	Admin Corridor Next To Conference Room	Tested	11:08:06 AM	08/20/2019
Smoke Detector	Admin Office	Tested	11:08:57 AM	08/20/2019
Smoke Detector	Admin Planning Workroom Next To Staff	Tested	11:17:20 AM	08/20/2019
	Lounge			
Smoke Detector	Boy's Portable Restroom	Tested	10:34:43 AM	08/20/2019
Smoke Detector	Building H Classroom 37	Tested	9:08:45 AM	08/20/2019
Smoke Detector	Building H Classroom 37	Tested	9:08:59 AM	08/20/2019
Smoke Detector	Building H Classroom 37	Tested	9:09:05 AM	08/20/2019
Smoke Detector	Building H Classroom 37	Tested	9:09:11 AM	08/20/2019
Smoke Detector	Building H Classroom 37	Tested	9:12:28 AM	08/20/2019
Smoke Detector	Building H Classroom 37	Tested	9:12:34 AM	08/20/2019

Device Type	Location	Service	Time	Date
	Passed			-
Smoke Detector	Building H Classroom 37 Storage Room	Tested	9:09:45 AM	08/20/2019
Smoke Detector	Building H Classroom 37 Workroom	Tested	9:09:19 AM	08/20/2019
Smoke Detector	Building H Corridor Between Speech And	Tested	8:50:31 AM	08/20/2019
	Kitchen			, -,
Smoke Detector	Building H Custodian Storage Outside Of Kitchen	Tested	9:01:12 AM	08/20/2019
Smoke Detector	Building H Kitchen Dry Storage	Tested	8:51:28 AM	08/20/2019
Smoke Detector	Building H Kitchen Freezer Storage	Tested	8:56:03 AM	08/20/2019
Smoke Detector	Building H Music Room	Tested	9:04:37 AM	08/20/2019
Smoke Detector	Building H Music Room	Tested	9:04:55 AM	08/20/2019
Smoke Detector	Building H Music Room Corridor Entrance	Tested	9:06:04 AM	08/20/2019
Smoke Detector	Building H Music Room Workroom	Tested	9:04:07 AM	08/20/2019
Smoke Detector	Building H Music Room Workroom	Tested	9:07:17 AM	08/20/2019
Smoke Detector	Building H Speech Classroom	Tested	8:49:36 AM	08/20/2019
Smoke Detector	Classroom 1 Electrical/Storage Room	Tested	11:37:10 AM	08/20/2019
Smoke Detector	Classroom 2 Electrical/Storage Room	Tested	11:40:46 AM	08/20/2019
Smoke Detector	Classroom 30	Tested	9:50:56 AM	08/20/2019
Smoke Detector	Classroom 30	Tested	9:51:05 AM	08/20/2019
Smoke Detector	Classroom 31	Tested	9:46:41 AM	08/20/2019
Smoke Detector	Classroom 4	Tested	11:29:56 AM	08/20/2019
Smoke Detector	Classroom 4	Tested	11:30:48 AM	08/20/2019
Smoke Detector	Custodian Room Next To Classroom 2	Tested	11:42:41 AM	08/20/2019
Smoke Detector	Girl's Portable Restroom	Tested	10:35:09 AM	08/20/2019
Smoke Detector	Library Book Storage	Tested	10:48:34 AM	08/20/2019
Smoke Detector	Library Classroom	Tested	10:57:19 AM	08/20/2019
Smoke Detector	Library Conference Room	Tested	10:47:47 AM	08/20/2019
Smoke Detector	Library Reading Conference Room	Tested	10:55:25 AM	08/20/2019
Smoke Detector	Library Reading Room	Tested	10:50:28 AM	08/20/2019
Smoke Detector	Library Reception	Tested	10:49:41 AM	08/20/2019
Smoke Detector	Library	Tested	10:51:53 AM	08/20/2019
Smoke Detector	Library	Tested	10:52:04 AM	08/20/2019
Smoke Detector	Library	Tested	10:52:09 AM	08/20/2019
Smoke Detector	Library	Tested	10:52:21 AM	08/20/2019
Smoke Detector	Men's Portable Restroom	Tested	10:36:07 AM	08/20/2019
Smoke Detector	MPR Building Main Hall	Tested	8:33:05 AM	08/20/2019
Smoke Detector	MPR Building Main Hall	Tested	8:33:18 AM	08/20/2019
Smoke Detector	MPR Building Main Hall	Tested	8:33:24 AM	08/20/2019
Smoke Detector	MPR Building Main Hall	Tested	8:33:32 AM	08/20/2019
Smoke Detector	MPR Building Stage	Tested	8:31:26 AM	08/20/2019
			8:32:58 AM	
Smoke Detector Smoke Detector	MPR Building Stage Portable 32	Tested Tested	9:41:06 AM	08/20/2019
Smoke Detector	Portable 32 Portable 32	Tested	9:41:24 AM	08/20/2019 08/20/2019
Smoke Detector	Portable 32 Portable 33 YMCA	Tested	9:35:06 AM	
			9:35:21 AM	08/20/2019
Smoke Detector	Portable 33 YMCA	Tested	9:30:59 AM	08/20/2019
Smoke Detector	Portable 34	Tested		08/20/2019
Smoke Detector	Portable 34	Tested	9:31:10 AM	08/20/2019
Smoke Detector	Portable 35 YMCA	Tested	9:24:16 AM	08/20/2019
Smoke Detector	Portable 35 YMCA	Tested	9:24:45 AM	08/20/2019
Smoke Detector	Women's Portable Restroom	Tested	10:36:22 AM	08/20/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Davis Magnet Elementary School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Annunciator	Inspected	1
Battery	Tested	2
Power Supply	Inspected	1
Pull Station	Tested	8
Smoke Detector	Tested	70
Total		82

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Davis Magnet Elementary School Control Panel: 1

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category		% of Inventory	Quantity
Smoke Detector		Initiating		85.37%	70
Pull Station		Initiating		9.76%	8
Power Supply		Control		1.22%	1
Battery		Control		2.44%	2
Annunciator		Control		1.22%	1
Туре	Qty	Model #	Description		Install Date
	New (under 90 days)				
Simplex					
Annunciator	1	4098-9714			08/20/2019
Power Supply	1	4009			08/20/2019
Pull Station	8	4099-9001	Dual Action		08/20/2019
Smoke Detector	70	4098-9714	Photoelectric		08/20/2019
		In Service	e - 2 Years to	3 Years	
Battery	2	12V7AH	Sealed Lead Acid	b	07/31/2017

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Early College High School 2990 Mesa Verde Costa Mesa, CA 92626

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Sep 3, 2019

> Building: NMUSD - Early College High School Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Chris Ferreira Title: Service

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD – Early College High School	Contact: Tim V	Valler
Address: 2990 Mesa Verde	Phone: 714-23	31-0363
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92626	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Chr	is Ferreira
Address: 2903 Saturn Street	Phone: 714–99	93-9650
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: chrisfer	reira@calbuildingsystems.com
System Control Unit		
Manufacturer: Silent Knight	Inspection Dat	ie: 09/03/2019 IDC Style:
Model Number: ECS-RCU2000	Install Date: 0	9/03/2019 SLC Style:
Software Version:	Version Date:	09/03/2019 NAC Style:
Location: Main Office Outside Electrical Eoom	Current Protec	tion:
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Catalana	Total	ltems	Ser	viced	Pas	ssed	Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Control	7	10.61%	7	100.00%	7	100.00%	0	0%
Initiating	59	89.39%	59	100.00%	59	100.00%	0	0%
Totals	66	100%	66	100.00%	66	100.00%	0	0%
Certification								
Company: Cal Building Systems			Bu	ilding: NML	JSD – Earl	y College H	ligh Schoo	I
Inspector: Chris Ferreira			Co	ontact: Tim	Waller			
Signed:			Sic	gned:				

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Early College High School

Control Panel: 1 - Silent Knight ECS-RCU2000

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Main Office Behind Recpetion	Tested	3:17:26 PM	09/03/2019
Battery	Main Office Outside Electrical Eoom	Tested	3:45:37 PM	09/03/2019
Battery	Main Office Outside Electrical Eoom	Tested	3:46:23 PM	09/03/2019
Battery	Main Office Outside Electrical Eoom	Tested	3:48:00 PM	09/03/2019
Battery	Main Office Outside Electrical Eoom	Tested	3:48:12 PM	09/03/2019
Control Panel	Main Office Outside Electrical Eoom	Tested	3:44:50 PM	09/03/2019
Power Supply	Main Office Outside Electrical Eoom	Tested	3:51:44 PM	09/03/2019
Initiating				
Pull Station	Main Office Behind Recpetion	Tested	5:47:13 PM	09/03/2019
Smoke Detector	Boys Locker Room	Tested	4:41:06 PM	09/03/2019
Smoke Detector	Classroom 10	Tested	4:07:59 PM	09/03/2019
Smoke Detector	Classroom 10	Tested	4:09:48 PM	09/03/2019
Smoke Detector	Classroom 10	Tested	4:09:55 PM	09/03/2019
Smoke Detector	Classroom 10	Tested	4:10:05 PM	09/03/2019
Smoke Detector	Classroom 11	Tested	4:13:10 PM	09/03/2019
Smoke Detector	Classroom 11	Tested	4:13:20 PM	09/03/2019
Smoke Detector	Classroom 11	Tested	4:13:27 PM	09/03/2019
Smoke Detector	Classroom 11	Tested	4:13:37 PM	09/03/2019
Smoke Detector	Classroom 12	Tested	4:22:46 PM	09/03/2019
Smoke Detector	Classroom 12	Tested	4:22:59 PM	09/03/2019
Smoke Detector	Classroom 12	Tested	4:23:09 PM	09/03/2019
Smoke Detector	Classroom 12	Tested	4:23:17 PM	09/03/2019
Smoke Detector	Electrical Room by Classroom 12	Tested	4:26:52 PM	09/03/2019
Smoke Detector	Electrical Room by Classroom 13	Tested	4:27:58 PM	09/03/2019
Smoke Detector	Electrical Room by Classroom 17	Tested	4:50:27 PM	09/03/2019
Smoke Detector	Electrical Room by Classroom 8	Tested	4:52:57 PM	09/03/2019
Smoke Detector	Janitor Room by Girls Locker Room	Tested	4:43:34 PM	09/03/2019
Smoke Detector	Main Office Behind Recpetion	Tested	5:47:10 PM	09/03/2019
Smoke Detector	Main Office Corridor by Office 4	Tested	5:46:16 PM	09/03/2019
Smoke Detector	Main Office Corridor by Storage	Tested	5:45:47 PM	09/03/2019
Smoke Detector	Main Office North Exit	Tested	5:45:55 PM	09/03/2019
Smoke Detector	Main Office Nurse	Tested	5:46:49 PM	09/03/2019
Smoke Detector	Main Office Nurse Electrical Room	Tested	5:46:19 PM	09/03/2019
Smoke Detector	Main Office Nurse Restroom	Tested	5:46:46 PM	09/03/2019
Smoke Detector	Main Office Office 2	Tested	5:46:52 PM	09/03/2019
Smoke Detector	Main Office Office 2	Tested	5:47:06 PM	09/03/2019
Smoke Detector	Main Office Office 3	Tested	5:46:56 PM	09/03/2019

Device Type	Location	Service	Time	Date		
Passed						
Smoke Detector	Main Office Office 4	Tested	5:46:12 PM	09/03/2019		
Smoke Detector	Main Office Outside Custodian Room	Tested	5:45:18 PM	09/03/2019		
Smoke Detector	Main Office Outside Electrical Room	Tested	5:45:22 PM	09/03/2019		
Smoke Detector	Main Office Outside Office 2	Tested	5:47:02 PM	09/03/2019		
Smoke Detector	Main Office Outside Storage Room	Tested	5:45:15 PM	09/03/2019		
Smoke Detector	Main Office Storage	Tested	5:45:27 PM	09/03/2019		
Smoke Detector	Main Office Unisex Restroom	Tested	5:45:25 PM	09/03/2019		
Smoke Detector	Men's Restroom by Classroom 8	Tested	5:00:04 PM	09/03/2019		
Smoke Detector	Storage by Classroom 8	Tested	4:57:45 PM	09/03/2019		
Smoke Detector	Storage Room by Girls Locker Room	Tested	4:42:03 PM	09/03/2019		
Smoke Detector	Classroom 13	Tested	4:29:51 PM	09/03/2019		
Smoke Detector	Classroom 13	Tested	4:30:12 PM	09/03/2019		
Smoke Detector	Classroom 13	Tested	4:30:23 PM	09/03/2019		
Smoke Detector	Classroom 13	Tested	4:30:29 PM	09/03/2019		
Smoke Detector	Classroom 14	Tested	4:33:02 PM	09/03/2019		
Smoke Detector	Classroom 14	Tested	4:33:17 PM	09/03/2019		
Smoke Detector	Classroom 14	Tested	4:33:25 PM	09/03/2019		
Smoke Detector	Classroom 14	Tested	4:33:32 PM	09/03/2019		
Smoke Detector	Classroom 15	Tested	4:36:02 PM	09/03/2019		
Smoke Detector	Classroom 15	Tested	4:36:18 PM	09/03/2019		
Smoke Detector	Classroom 15	Tested	4:36:25 PM	09/03/2019		
Smoke Detector	Classroom 15	Tested	4:36:40 PM	09/03/2019		
Smoke Detector	Classroom 17	Tested	4:45:35 PM	09/03/2019		
Smoke Detector	Classroom 17	Tested	4:45:47 PM	09/03/2019		
Smoke Detector	Classroom 17	Tested	4:45:57 PM	09/03/2019		
Smoke Detector	Classroom 17	Tested	4:46:07 PM	09/03/2019		
Smoke Detector	Classroom 8	Tested	4:54:37 PM	09/03/2019		
Smoke Detector	Classroom 8	Tested	4:54:49 PM	09/03/2019		
Smoke Detector	Classroom 8	Tested	4:54:59 PM	09/03/2019		
Smoke Detector	Classroom 8	Tested	4:55:07 PM	09/03/2019		

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Early College High School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Annunciator	Tested	1
Battery	Tested	4
Control Panel	Tested	1
Power Supply	Tested	1
Pull Station	Tested	1
Smoke Detector	Tested	58
Total		66

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: NMUSD - Early College High School

Control Panel: 1 - Silent Knight ECS-RCU2000

The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.

Туре	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
		Passe	d				
Battery							
Sealed Lead Acid	Main Office Outside Electrical Eoom	18	12				
Sealed Lead Acid	Main Office Outside Electrical Eoom	18	12				
Sealed Lead Acid	Main Office Outside Electrical Eoom	18	12				
Sealed Lead Acid	Main Office Outside Electrical Eoom	18	12				

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Early College High School

Control Panel: 1 - Silent Knight ECS-RCU2000

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category		% of Inventory	Quantity
Annunciator	ľ	Control		1.52%	1
Control Panel		Control		1.52%	1
		Control		6.06%	1
Battery					4
Power Supply		Control		1.52%	I
Smoke Detector		Initiating		87.88%	58
Pull Station		Initiating	L	1.52%	1
Туре	Qty	Model #	Description		Install Date
		New	(under 90 da	ys)	
Silent Knight					
Annunciator	1	ECS-RCU2000			09/03/2019
Control Panel	1	ECS-RCU2000			09/03/2019
Pull Station	1	IDP-PULL-SA	Keyed		09/03/2019
Smoke Detector	58	IDP-PHOTO	Photoelectric		09/03/2019
		In Service	- 2 Years to	3 Years	
12V18Ah					
Battery	4	12V18Ah	Sealed Lead Acic	1	08/17/2017
Silent Knight					
Power Supply	1	ECS-50W			08/17/2017

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Early College High School 2990 Mesa Verde Costa Mesa, CA 92626

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Sep 3, 2019

> Building: NMUSD - Early College High School Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Michael Cannon Title: Service Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD – Early College High School	Contact: Tim V	Valler
Address: 2990 Mesa Verde	Phone: 714–2	31-0363
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92626	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Mic	hael Cannon
Address: 2903 Saturn Street	Phone: 714–7	15-1223
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: mcanno	on@calbuildingsystems.com
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

	Tota	Items	Ser	viced	Pa	ssed	Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	1.61%	1	100.00%	1	100.00%	0	0%
Control	3	4.84%	3	100.00%	3	100.00%	0	0%
Initiating	55	88.71%	55	100.00%	55	100.00%	0	0%
Supervisory	3	4.84%	3	100.00%	3	100.00%	0	0%
Totals	62	100%	62	100.00%	62	100.00%	0	0%
Certification								
Company: Cal Building Systems			Βι	ilding: NML	ISD – Ear	y College Hi	igh Schoo	I
Inspector: Michael Cannon			Co	ontact: Tim	Waller			
- And Down								
Signed: Sep 3, 2019 7:39:22 F	м		Si	aned:				

Notes & Recommendations

Generated by: BuildingReports.com

Building: NMUSD - Early College High School

Control Panel: 1

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

ScanID	Note	Device Type	Location	Comment
			Initiating	
58090778	1	Waterflow Switch	Cage Outside Of Science Lab 2	Passed
Static	94			
Resid	ual 76			
F. Sta	tic 94			

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Early College High School

Control Panel: 1

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Battery	Electrical Room Next To Classroom 5	Tested	3:45:51 PM	09/03/2019
Battery	Electrical Room Next To Classroom 5	Tested	3:46:12 PM	09/03/2019
Power Supply	Electrical Room Next To Classroom 5	Inspected	3:44:44 PM	09/03/2019
Initiating				
Smoke Detector	Boy's Restroom Near Classroom 4	Tested	4:30:32 PM	09/03/2019
Smoke Detector	Classroom 1	Tested	4:45:38 PM	09/03/2019
Smoke Detector	Classroom 1	Tested	4:45:50 PM	09/03/2019
Smoke Detector	Classroom 1	Tested	4:45:55 PM	09/03/2019
Smoke Detector	Classroom 1	Tested	4:46:01 PM	09/03/2019
Smoke Detector	Classroom 2	Tested	4:41:09 PM	09/03/2019
Smoke Detector	Classroom 2	Tested	4:41:21 PM	09/03/2019
Smoke Detector	Classroom 2	Tested	4:41:26 PM	09/03/2019
Smoke Detector	Classroom 2	Tested	4:41:31 PM	09/03/2019
Smoke Detector	Classroom 3	Tested	4:37:41 PM	09/03/2019
Smoke Detector	Classroom 3	Tested	4:37:49 PM	09/03/2019
Smoke Detector	Classroom 3	Tested	4:37:54 PM	09/03/2019
Smoke Detector	Classroom 3	Tested	4:37:58 PM	09/03/2019
Smoke Detector	Classroom 4	Tested	4:34:03 PM	09/03/2019
Smoke Detector	Classroom 4	Tested	4:34:13 PM	09/03/2019
Smoke Detector	Classroom 4	Tested	4:34:18 PM	09/03/2019
Smoke Detector	Classroom 4	Tested	4:34:24 PM	09/03/2019
Smoke Detector	Classroom 5	Tested	4:24:56 PM	09/03/2019
Smoke Detector	Classroom 5	Tested	4:25:10 PM	09/03/2019
Smoke Detector	Classroom 5	Tested	4:25:28 PM	09/03/2019
Smoke Detector	Classroom 5	Tested	4:25:35 PM	09/03/2019
Smoke Detector	Electrical Room Next To Classroom 1	Tested	5:21:19 PM	09/03/2019
Smoke Detector	Electrical Room Next To Classroom 5	Tested	3:43:16 PM	09/03/2019
Smoke Detector	Electrical Room Next To Science Lab 1	Tested	3:46:48 PM	09/03/2019
Smoke Detector	Girl's Restroom Near Classroom 4	Tested	4:30:16 PM	09/03/2019
Smoke Detector	MPR Building Chair Storage	Tested	3:29:56 PM	09/03/2019
Smoke Detector	MPR Building Corridor By Restrooms	Tested	3:28:47 PM	09/03/2019
Smoke Detector	MPR Building Custodian Closet	Tested	3:36:02 PM	09/03/2019
Smoke Detector	MPR Building Custodian Office	Tested	3:35:42 PM	09/03/2019
Smoke Detector	MPR Building Kitchen	Tested	3:34:37 PM	09/03/2019
Smoke Detector	MPR Building Kitchen Office Storage	Tested	3:34:11 PM	09/03/2019
Smoke Detector	MPR Building Main Auditorium	Tested	3:25:24 PM	09/03/2019
Smoke Detector	MPR Building Main Auditorium	Tested	3:26:10 PM	09/03/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	MPR Building Main Auditorium	Tested	3:26:19 PM	09/03/2019
Smoke Detector	MPR Building Main Auditorium	Tested	3:26:32 PM	09/03/2019
Smoke Detector	MPR Building Stage	Tested	3:26:57 PM	09/03/2019
Smoke Detector	MPR Building Stage	Tested	3:27:11 PM	09/03/2019
Smoke Detector	MPR Building Unisex Restroom	Tested	3:32:00 PM	09/03/2019
Smoke Detector	MPR Building Unisex Restroom	Tested	3:33:48 PM	09/03/2019
Smoke Detector	Science Lab 1	Tested	4:17:41 PM	09/03/2019
Smoke Detector	Science Lab 1	Tested	5:32:08 PM	09/03/2019
Smoke Detector	Science Lab 1	Tested	5:32:16 PM	09/03/2019
Smoke Detector	Science Lab 1	Tested	5:32:21 PM	09/03/2019
Smoke Detector	Science Lab 1	Tested	5:32:26 PM	09/03/2019
Smoke Detector	Science Lab 2	Tested	4:24:38 PM	09/03/2019
Smoke Detector	Science Lab 2	Tested	5:35:00 PM	09/03/2019
Smoke Detector	Science Lab 2	Tested	5:35:13 PM	09/03/2019
Smoke Detector	Science Lab 2	Tested	5:35:17 PM	09/03/2019
Smoke Detector	Science Lab 2	Tested	5:35:22 PM	09/03/2019
Smoke Detector	Science Lab Workroom	Tested	4:19:27 PM	09/03/2019
Smoke Detector	Stand Alone Building Storage Room Outside Of MPR	Tested	3:39:42 PM	09/03/2019
Smoke Detector	Stand Alone Building Storage Room Outside Of MPR	Tested	3:40:38 PM	09/03/2019
Smoke Detector	Storage Room Near Classroom 4	Tested	4:29:41 PM	09/03/2019
Smoke Detector	Storage Room Next To Science Lab 1	Tested	3:49:29 PM	09/03/2019
Waterflow Switch	Cage Outside Of Science Lab 2	Tested	5:17:09 PM	09/03/2019
Supervisory				
Tamper Switch	Cage Outside Of Science Lab 2	Tested	3:53:21 PM	09/03/2019
Tamper Switch	Parking Lot Entrance "OS&Y"	Tested	3:57:57 PM	09/03/2019
Tamper Switch	Parking Lot Entrance "OS&Y"	Tested	3:59:03 PM	09/03/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Early College High School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Battery	Tested	2
Power Supply	Inspected	1
Smoke Detector	Tested	54
Tamper Switch	Tested	3
Waterflow Switch	Tested	1
Total		61

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - Early College High School

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

		Ambient	Alarm	🦻 Intell	igibility	Sound
C Location	🗨 Commen	t ∢ dB	◀ dB	Voice	STI	Test
	Pas	sed				
Sound Test Points						
Entire Campus	Passed					0001

Time, Temperature & Level Testing

Generated by: BuildingReports.com

Building: NMUSD - Early College High School

Control Panel: 1

The Time, Temperature, & Level Testing section details the measurements taken from various devices that are designed to respond in a certain amount of time, respond at a certain temperature, or respond within the acceptable range of volume or level. Items are grouped by Passed or Failed/Other.

Туре	Location	Comment	Sec	Deg	Lvl	ScanID
	Passed	d				
Waterflow Swit	ch					
	Cage Outside Of Science Lab 2	Passed	71	n/a	n/a	58090778

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Early College High School

Control Panel: 1

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category		% of Inventory	Quantity
Smoke Detector	·	Initiating		87.10%	54
Power Supply		Control		1.61%	1
Battery		Control		3.23%	2
Tamper Switch		Supervisory		4.84%	3
Waterflow Switch		Initiating	1	1.61%	1
Туре	Qty	Model #	Description		Install Date
		New	(under 90 days	s)	
Potter					
Tamper Switch	2	OSYSU-2			09/03/2019
Silent Knight					
Power Supply	1	RPS-1000			09/03/2019
Smoke Detector	54	IDP-PHOTO	Photoelectric		09/03/2019
System Sensor					
Waterflow Switch	1	WFD40VN			09/03/2019
Victaulic					
Tamper Switch	1	705			09/03/2019
		In Service	- 2 Years to 3	Years	
Battery	2	12V18AH	Sealed Lead Acid		08/17/2017

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Early College High School 2990 Mesa Verde Costa Mesa, CA 92626

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Sep 3, 2019

> Building: NMUSD - Early College High School Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Phillip Burton Title: Inspector

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD – Early College High School	Contact: Tim W	aller
Address: 2990 Mesa Verde	Phone: 714–23	1-0363
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92626	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Philli	p Burton
Address: 2903 Saturn Street	Phone: 714–34	5-1252
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: phillipbu	rton@calbuildingsystems.com
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Catagory	Tota	l Items	Ser	viced	Pa	ssed	Failed,	Other
Category	Qty	%	Qty	%	Qty	%	Qty	%
Initiating	46	100.00%	46	100.00%	46	100.00%	0	0%
Totals	46	100%	46	100.00%	46	100.00%	0	0%
Certification								
Company: Cal Building Systems			Bu	ilding: NMU	SD – Ear	ly College Hi	igh Schoo	l
Inspector: Phillip Burton			Co	ontact: Tim \	Waller			
Signed:				gned:				

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Early College High School

Control Panel: 1

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed	l		
Initiating				
Heat Detector	BLDG A Hallway Center	Tested	5:14:48 PM	09/03/2019
Heat Detector	BLDG A N/W Hallway	Tested	5:16:32 PM	09/03/2019
Heat Detector	BLDG B CORR	Tested	4:58:01 PM	09/03/2019
Heat Detector	BLDG B STORAGE	Tested	5:02:58 PM	09/03/2019
Heat Detector	Computer Rm North Center	Tested	5:20:54 PM	09/03/2019
Heat Detector	Computer Rm South Center	Tested	5:21:26 PM	09/03/2019
Heat Detector	Girls Locker Rm North Center	Tested	5:19:32 PM	09/03/2019
Heat Detector	Girls Locker Rm South Center	Tested	5:18:47 PM	09/03/2019
Heat Detector	MPR Center	Tested	5:05:00 PM	09/03/2019
Heat Detector	MPR East	Tested	5:05:20 PM	09/03/2019
Heat Detector	MPR WEST	Tested	5:04:34 PM	09/03/2019
Heat Detector	Nurse Room South	Tested	5:11:01 PM	09/03/2019
Heat Detector	Office 1 Center	Tested	5:13:05 PM	09/03/2019
Heat Detector	Office 2 Center	Tested	5:12:08 PM	09/03/2019
Heat Detector	Office 3 Center	Tested	5:11:37 PM	09/03/2019
Heat Detector	Office 4 Center	Tested	5:15:30 PM	09/03/2019
Heat Detector	Platform Area West	Tested	5:01:54 PM	09/03/2019
Heat Detector	Prep Rm North Center	Tested	5:22:07 PM	09/03/2019
Heat Detector	Prep Rm South Center	Tested	5:23:28 PM	09/03/2019
Heat Detector	Reception Area	Tested	5:13:32 PM	09/03/2019
Heat Detector	RM 1 North	Tested	5:07:38 PM	09/03/2019
Heat Detector	RM 1 South	Tested	5:07:09 PM	09/03/2019
Heat Detector	Rm 10 North Center	Tested	5:34:56 PM	09/03/2019
Heat Detector	Rm 10 South Center	Tested	5:35:18 PM	09/03/2019
Heat Detector	Rm 11 North Center	Tested	5:34:40 PM	09/03/2019
Heat Detector	Rm 11 South Center	Tested	5:34:26 PM	09/03/2019
Heat Detector	Rm 12 North Center	Tested	5:33:47 PM	09/03/2019
Heat Detector	Rm 12 South Center	Tested	5:34:06 PM	09/03/2019
Heat Detector	Rm 13 North Center	Tested	5:29:35 PM	09/03/2019
Heat Detector	Rm 13 South Center	Tested	5:26:25 PM	09/03/2019
Heat Detector	Rm 14 North Center	Tested	5:30:17 PM	09/03/2019
Heat Detector	Rm 14 South Center	Tested	5:27:02 PM	09/03/2019
Heat Detector	Rm 15 North Center	Tested	5:32:52 PM	09/03/2019
Heat Detector	Rm 15 South Center	Tested	5:31:49 PM	09/03/2019
Heat Detector	RM 2 North	Tested	5:09:51 PM	09/03/2019
Heat Detector	RM 2 South	Tested	5:09:20 PM	09/03/2019
Heat Detector	RM 3 North	Tested	5:10:38 PM	09/03/2019
Heat Detector	RM 3 South	Tested	5:10:06 PM	09/03/2019

Cal Building Systems

Device Type	Location	Service	Time	Date
		Passed		
Heat Detector	RM 4 North	Tested	5:06:47 PM	09/03/2019
Heat Detector	RM 4 South	Tested	5:06:22 PM	09/03/2019
Heat Detector	RM 5 North	Tested	5:06:07 PM	09/03/2019
Heat Detector	RM 5 South	Tested	5:05:42 PM	09/03/2019
Heat Detector	RM 7 North Center	Tested	5:18:26 PM	09/03/2019
Heat Detector	RM 7 South Center	Tested	5:17:45 PM	09/03/2019
Heat Detector	Serving Kitchen	Tested	5:01:05 PM	09/03/2019
Heat Detector	Waiting Area	Tested	5:12:28 PM	09/03/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Early College High School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Heat Detector	Tested	46
Total		46

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Early College High School

Control Panel: 1

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category		% of Inventory		Quantity	
Heat Detector		Initiating		100.00%		46	
Туре	Qty	Model #	Description			Install Date	
New (under 90 days)							
Silent Knight							
Heat Detector	46	IDP-HEAT	Rate-of-Rise			09/03/2019	

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Eastbluff Elementary School 2627 Vista Del Oro Newport Beach, CA 92660

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Aug 28, 2019

> Building: NMUSD - Eastbluff Elementary School Contact: Tim Waller Title: District Manager

Company: Cal Building Systems Contact: Michael Cannon Title: Service Technician

Executive Summary Generated by: BuildingReports.com

Building Information					
Building: NMUSD – Eastbluff Elementary School	Contact: Tim Wa	ller			
Address: 2627 Vista Del Oro	Phone: 714–231	-0363			
Address:	Fax:				
City/State/Zip: Newport Beach, CA 92660	Mobile:				
Country: United States of America	Email:				
Inspection Performed By					
Company: Cal Building Systems	Inspector: Micha	el Cannon			
Address: 2903 Saturn Street	Phone: 714–715	-1223			
Address: Suite F	Fax:				
City/State/Zip: Brea, CA 92821	Mobile:	Mobile:			
Country: United States of America	Email: mcannon	@calbuildingsyste	ems.com		
System Control Unit					
Manufacturer: Simplex	Inspection Date:	08/28/2019	IDC Style:		
Model Number: 4020	Install Date: 08/	28/2019	SLC Style:		
Software Version:	Version Date: 08	8/28/2019	NAC Style:		
Location: Admin Building A3 Utility Room	Current Protection	on:			
Monitoring					
Company:	Phone:	Accoun	t #:		
Central Station Signal Verification					
Туре:	Mfg:	-	Model #:		
Test Time/Date:	Restore Time				

Inspection Summary								
Catagoria	Tota	l Items	Sei	viced	Ра	ssed	Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	1.06%	1	100.00%	0	0%	1	100.00%
Control	22	23.40%	22	100.00%	22	100.00%	0	0%
Initiating	71	75.53%	71	100.00%	71	100.00%	0	0%
Totals	94	100%	94	100.00%	93	98.94%	1	1.06%
Certification								
Company: Cal Building Systems			В	uilding: NMU	SD – Eas	tbluff Eleme	entary Sch	nool
Inspector: Michael Cannon			C	ontact: Tim \	Naller			
the amore								
Signed: Aug 28, 2019 3:07:20	PM		Si	gned:				

Discrepancy Report Generated by: BuildingReports.com

Building: N	MUSD - Ea	stbluff Elementary		Control Do	nol n/		
School	School Control Panel: n/a						
The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.							
Device Type		Manufacturer		ModelNumb	er	Date	Qty
		Items listed for Rec	call by I	Manufactı	ırer		
		No recalled items foun	nd during t	his inspection.			
Sound Test	E Location		9 Prob	lem	Devi	ce 🛛 🖾 Ref	erence
Sound Testing							
Sound Test	C3 Location		9 Prob	lem	Devi	ce 🛛 🖾 Ref	erence
Sound Test Points							
0001	Entire Campus				Sound ⁻	Fest	

Proposed Solutions Report Generated by: BuildingReports.com

Building: NMUSD - Eastbluff Elementary School Control I								
The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.								
ScanID	Location	Solution	Description	Cost	Fix			
	Sound Testing							
Sound Test								
0001	Entire Campus			T/M				
			PO #: (none)	T/M				

Notes & Recommendations

Generated by: BuildingReports.com

Building: NMUSD - Eastbluff Elementary School

Control Panel: n/a

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

ScanID	Note	Device Type	Location	Comment		
0001	1	Sound Test	Entire Campus			
On bւ	On building E, the horns (3 total) outside of classrooms E1, E2 and E3 failed to activate during our					
audio	audio/visual inspection. Hank, from NMUSD is aware of this and arrived on site to troubleshoot the issue.					

Building: NMUSD - Eastbluff Elementary School

Control Panel: 1 - Simplex 4020

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

ScanID	Note	Device Type	Location	Comment			
Control							
61337426	2	Control Panel	Admin Building A3 Utility Room	Passed			
Upon	Upon arrival there were two troubles on the panel: Card 2, Power Supply/Charger—negative ground fault;						
and a	and an open circuit trouble—Building E Horns. NMUSD technician, Hank was on site to troubleshoot the						
issues. (Also, see Sound Test on the building report).							

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Eastbluff Elementary School

Control Panel: 1 - Simplex 4020

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Admin Building Reception	Inspected	8:27:55 AM	08/28/2019
Battery	Admin Building A3 Utility Room	Tested	8:00:15 AM	08/28/2019
Battery	Admin Building A3 Utility Room	Tested	8:00:49 AM	08/28/2019
Battery	Admin Building A3 Utility Room	Tested	8:02:22 AM	08/28/2019
Battery	Admin Building A3 Utility Room	Tested	8:02:39 AM	08/28/2019
Battery	B-10 Utility Room	Tested	8:48:04 AM	08/28/2019
Battery	B-10 Utility Room	Tested	8:48:33 AM	08/28/2019
Battery	C-7 Utility Room	Tested	9:53:01 AM	08/28/2019
Battery	C-7 Utility Room	Tested	9:53:20 AM	08/28/2019
Battery	D-3 Utility Room	Tested	9:41:16 AM	08/28/2019
Battery	D-3 Utility Room	Tested	9:41:36 AM	08/28/2019
Battery	E-5 Utility Room	Tested	9:24:34 AM	08/28/2019
Battery	E-5 Utility Room	Tested	9:25:58 AM	08/28/2019
Battery	F-6 Utility Room	Tested	9:01:13 AM	08/28/2019
Battery	F-6 Utility Room	Tested	9:01:35 AM	08/28/2019
Control Panel	Admin Building A3 Utility Room	Tested	7:59:00 AM	08/28/2019
Power Supply	Admin Building A3 Utility Room	Inspected	8:01:28 AM	08/28/2019
Power Supply	B-10 Utility Room	Inspected	8:47:33 AM	08/28/2019
Power Supply	C-7 Utility Room	Inspected	9:50:19 AM	08/28/2019
Power Supply	D-3 Utility Room	Inspected	9:40:53 AM	08/28/2019
Power Supply	E-5 Utility Room	Inspected	9:24:16 AM	08/28/2019
Power Supply	F-6 Utility Room	Inspected	9:00:50 AM	08/28/2019
Initiating				
Heat Detector	Portable Science Classroom	Tested	12:04:38 PM	08/28/2019
Heat Detector	Portable Science Classroom	Tested	12:05:34 PM	08/28/2019
Pull Station	A–1 Kindergarten	Tested	8:34:29 AM	08/28/2019
Pull Station	A-1 Kindergarten	Tested	8:34:59 AM	08/28/2019
Pull Station	A-2 Kindergarten	Tested	8:35:58 AM	08/28/2019
Pull Station	A-2 Kindergarten	Tested	8:36:41 AM	08/28/2019
Pull Station	Admin Building Principal's Office	Tested	8:32:24 AM	08/28/2019
Pull Station	Admin Building Reception Exit	Tested	8:27:06 AM	08/28/2019
Pull Station	Admin Building Staff Lounge	Tested	9:18:50 AM	08/28/2019
Pull Station	B–1 Theater Back Stage	Tested	8:41:09 AM	08/28/2019
Pull Station	B-1 Theater MPR Exit	Tested	8:42:48 AM	08/28/2019
Pull Station	B-1 Theater	Tested	8:38:47 AM	08/28/2019
Pull Station	B–6 Kitchen	Tested	8:44:31 AM	08/28/2019
Pull Station	Building D Library	Tested	10:51:02 AM	08/28/2019

Device Type	Location	Service	Time	Date
	Passed	!		
Pull Station	Building D Library	Tested	10:51:09 AM	08/28/2019
Pull Station	Building D Library	Tested	10:51:33 AM	08/28/2019
Pull Station	Building D Library	Tested	10:52:45 AM	08/28/2019
Pull Station	Building D Library	Tested	10:53:09 AM	08/28/2019
Pull Station	Building D Library	Tested	10:53:52 AM	08/28/2019
Pull Station	Building F Workroom	Tested	8:54:37 AM	08/28/2019
Pull Station	Building F Workroom	Tested	8:56:39 AM	08/28/2019
Pull Station	C-1 Classroom	Tested	10:58:23 AM	08/28/2019
Pull Station	C-1 Classroom	Tested	11:00:26 AM	08/28/2019
Pull Station	C-2 Classroom	Tested	11:35:08 AM	08/28/2019
Pull Station	C-2 Classroom	Tested	11:35:17 AM	08/28/2019
Pull Station	C-3 Classroom	Tested	11:28:54 AM	08/28/2019
Pull Station	C-3 Classroom	Tested	11:28:58 AM	08/28/2019
Pull Station	C-4 Classroom	Tested	11:27:51 AM	08/28/2019
Pull Station	C-4 Classroom	Tested	11:27:55 AM	08/28/2019
Pull Station	C-5 Classroom	Tested	11:27:33 AM	08/28/2019
Pull Station	C-5 Classroom	Tested	11:27:41 AM	08/28/2019
Pull Station	C-6 Classroom	Tested	11:27:24 AM	08/28/2019
Pull Station	C-6 Classroom	Tested	11:27:28 AM	08/28/2019
Pull Station	D-1 Classroom	Tested	10:56:27 AM	08/28/2019
Pull Station	D-1 Classroom	Tested	10:56:48 AM	08/28/2019
Pull Station	D-1 Classroom	Tested	10:57:06 AM	08/28/2019
Pull Station	D-2 Classroom	Tested	10:54:40 AM	08/28/2019
Pull Station	D-2 Classroom	Tested	10:55:52 AM	08/28/2019
Pull Station	D-2 Classroom	Tested	10:56:15 AM	08/28/2019
Pull Station	E-1 Classroom	Tested	10:45:19 AM	08/28/2019
Pull Station	E-1 Classroom	Tested	10:45:57 AM	08/28/2019
Pull Station	E-1 Classroom	Tested	10:46:08 AM	08/28/2019
Pull Station	E-2 Classroom	Tested	10:47:05 AM	08/28/2019
Pull Station	E-2 Classroom	Tested	10:47:15 AM	08/28/2019
Pull Station	E-2 Classroom	Tested	10:47:23 AM	08/28/2019
Pull Station	E-3 Classroom	Tested	10:47:46 AM	08/28/2019
Pull Station	E-3 Classroom	Tested	10:48:07 AM	08/28/2019
Pull Station	E-3 Classroom	Tested	10:48:23 AM	08/28/2019
Pull Station	E-4 Classroom	Tested	10:48:53 AM	08/28/2019
Pull Station	E-4 Classroom	Tested	10:48:57 AM	08/28/2019
Pull Station	E-4 Classroom	Tested	10:49:04 AM	08/28/2019
Pull Station	F–1 Classroom	Tested	8:50:44 AM	08/28/2019
Pull Station	F–1 Classroom	Tested	8:51:09 AM	08/28/2019
Pull Station	F-2 Classroom	Tested	8:51:46 AM	08/28/2019
Pull Station	F-2 Classroom	Tested	8:55:51 AM	08/28/2019
Pull Station	F-3 Classroom	Tested	8:54:52 AM	08/28/2019
Pull Station	F-3 Classroom	Tested	8:55:34 AM	08/28/2019
Pull Station	F-4 Classroom	Tested	9:04:18 AM	08/28/2019
Pull Station	F-4 Classroom	Tested	9:04:42 AM	08/28/2019
Pull Station	F-5 Classroom	Tested	10:44:29 AM	08/28/2019
Pull Station	F-5 Classroom	Tested	10:45:00 AM	08/28/2019
Pull Station	Portable Science Classroom	Tested	12:01:03 PM	08/28/2019
Smoke Detector	Admin Building A3 Utility Room	Tested	8:03:58 AM	08/28/2019
Smoke Detector	Admin Building Reception	Tested	8:28:15 AM	08/28/2019

Device Type	Location	Service	Time	Date
	Passe	d		
Smoke Detector	B–10 Utility Room	Tested	8:46:31 AM	08/28/2019
Smoke Detector	C-7 Utility Room	Tested	11:44:12 AM	08/28/2019
Smoke Detector	D-3 Utility Room	Tested	11:40:35 AM	08/28/2019
Smoke Detector	E–5 Utility Room	Tested	11:37:49 AM	08/28/2019
Smoke Detector	F–6 Utility Room	Tested	8:57:31 AM	08/28/2019
Smoke Detector	Portable Science Classroom	Tested	11:50:43 AM	08/28/2019
Smoke Detector	Portable Science Classroom	Tested	11:51:35 AM	08/28/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Eastbluff Elementary School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Annunciator	Inspected	1
Battery	Tested	14
Control Panel	Tested	1
Heat Detector	Tested	2
Power Supply	Inspected	6
Pull Station	Tested	60
Smoke Detector	Tested	9
Total		93

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - Eastbluff Elementary School

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

			Ambient	Alarm	🦻 Intell	igibility	Sound
C Location		Comment	◀ dB	◀ dB	Voice	STI	Test
Failed/Other							
Sound Test Points							
Entire Campus							0001

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Eastbluff Elementary School

Control Panel: 1 - Simplex 4020

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category		% of Inventory	Quantity
Control Panel		Control		1.06%	1
Battery		Control		14.89%	14
Power Supply		Control		6.38%	6
Smoke Detector		Initiating		9.57%	9
Pull Station		Initiating		63.83%	60
Annunciator		Control		1.06%	1
Heat Detector		Initiating		2.13%	2
Туре	Qty	Model #	Description		Install Date
		New	(under 90 da	ys)	
Simplex				-	
Annunciator	1				08/28/2019
Control Panel	1	4020			08/28/2019
Heat Detector	2	4098-9733			08/28/2019
Pull Station	60	2099-9761	Dual Action		08/28/2019
Smoke Detector	9	4098-9714	Photoelectric		08/28/2019
		In Service	e - 2 Years to	3 Years	
Battery	2	12V18AH	Sealed Lead Acid	l	08/26/2017
Battery	12	12V7AH	Sealed Lead Acid	l	08/26/2017
Simplex					
Power Supply	6	4009			08/26/2017

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Education Center 2985 Bear Street Costa Mesa, CA 92626

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Sep 13, 2019

> Building: NMUSD - Education Center Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Michael Cannon Title: Service Technician

Executive Summary

Generated by: BuildingReports.com

Building Information				
Building: NMUSD - Education Center	Contact: Tim Waller			
Address: 2985 Bear Street	Phone: 714-231-0363			
Address:	Fax:			
City/State/Zip: Costa Mesa, CA 92626	Mobile:			
Country: United States of America	Email:			
Inspection Performed By				
Company: Cal Building Systems	Inspector: Michael Cannon			
Address: 2903 Saturn Street	Phone: 714-715-1223			
Address: Suite F	Fax:			
City/State/Zip: Brea, CA 92821	Mobile:			
Country: United States of America	Email: mcannon@calbuildings	ystems.com		
System Control Unit				
Manufacturer: Simplex	Inspection Date: 09/13/2019	IDC Style:		
Model Number: 4020	Install Date: 09/13/2019	SLC Style:		
Software Version:	Version Date: 09/13/2019	NAC Style:		
Location: Roderick H. Macmillian Board Room/FACP Room	Current Protection:			
Monitoring				
Company: Pho	one: Acc	ount #:		
Central Station Signal Verification				
Туре:	Mfg:	Model #:		
Test Time/Date:	Restore Time			

Inspection Summary								
C. L.	Total Items		Serviced		Passed		Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	4.55%	1	100.00%	1	100.00%	0	0%
Control	7	31.82%	7	100.00%	7	100.00%	0	0%
Initiating	13	59.09%	13	100.00%	13	100.00%	0	0%
Supervisory	1	4.55%	1	100.00%	1	100.00%	0	0%
Totals	22	100%	22	100.00%	22	100.00%	0	0%
Certification								
Company: Cal Building Systems			Bu	ilding: NML	JSD – Edu	cation Cent	er	
Inspector: Michael Cannon			Co	ntact: Tim	Waller			
Signed: Signed:								

Notes & Recommendations

Generated by: BuildingReports.com

Building: NMUSD - Education Center

Control Panel: 1 - Simplex 4020

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

ScanID	Note	Device Type	Location	Comment
			Initiating	
58091468	1	Waterflow Switch	Custodian Room Near The North Exit ITV In Southwest Corner Office	Passed
Static Resid	98 ual 84			
F. Sta	tic 98			
Riser	Diameter	4"		
Main	Drain Dia	meter 1.25"		

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Education Center

Control Panel: 1 - Simplex 4020

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Front Lobby By Roderick H. Macmillian Board Room	Inspected	3:43:29 PM	09/13/2019
Battery	Roderick H. Macmillian Board Room/FACP Room	Tested	3:30:15 PM	09/13/2019
Battery	Roderick H. Macmillian Board Room/FACP Room	Tested	3:30:28 PM	09/13/2019
Battery	Roderick H. Macmillian Board Room/FACP Room	Tested	3:32:11 PM	09/13/2019
Battery	Roderick H. Macmillian Board Room/FACP Room	Tested	3:32:42 PM	09/13/2019
Control Panel	Roderick H. Macmillian Board Room/FACP Room	Tested	3:16:26 PM	09/13/2019
Power Supply	Roderick H. Macmillian Board Room/FACP Room	Inspected	3:31:46 PM	09/13/2019
Initiating				
Heat Detector	Custodian Room Near The North Exit	Tested	4:12:11 PM	09/13/2019
Heat Detector	North Break Room Near Conference Room A	Tested	4:31:14 PM	09/13/2019
Pull Station	Cubicle Area South Exit	Tested	3:46:12 PM	09/13/2019
Pull Station	Front Lobby By Roderick H. Macmillian Board Room	Tested	3:41:46 PM	09/13/2019
Pull Station	North Exit	Tested	4:09:05 PM	09/13/2019
Pull Station	North Exit	Tested	4:11:10 PM	09/13/2019
Pull Station	Office East Exit	Tested	3:47:21 PM	09/13/2019
Pull Station	South Exit	Tested	4:04:15 PM	09/13/2019
Pull Station	South Exit Corridor Next To Staff Lounge	Tested	4:01:34 PM	09/13/2019
Pull Station	West Exit	Tested	4:05:54 PM	09/13/2019
Pull Station	West Exit	Tested	4:08:18 PM	09/13/2019
Smoke Detector	Staff Lounge Electrical Room	Tested	3:56:42 PM	09/13/2019
Waterflow Switch	Custodian Room Near The North Exit ITV In Southwest Corner Office	Tested	4:16:58 PM	09/13/2019
Supervisory				
Tamper Switch	North Of Building Off Baker Street	Tested	4:19:37 PM	09/13/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Education Center

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Annunciator	Inspected	1
Battery	Tested	4
Control Panel	Tested	1
Heat Detector	Tested	2
Power Supply	Inspected	1
Pull Station	Tested	9
Smoke Detector	Tested	1
Tamper Switch	Tested	1
Waterflow Switch	Tested	1
Total		21

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - Education Center

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

		Ambient	Alarm	🦻 Intell	igibility	Sound	
C Location	 Comment 	◀ dB	◀ dB	Voice	STI	Test	
Passed							
Sound Test Points							
Entire Site	Passed					0001	

Time, Temperature & Level Testing Generated by: BuildingReports.com

Building: NMUSD - Education CenterControl Panel: 1 - Simplex4020								
The Time, Temperature, & Level Testing section details the measurements taken from various devices that are designed to respond in a certain amount of time, respond at a certain temperature, or respond within the acceptable range of volume or level. Items are grouped by Passed or Failed/Other.								
Туре	Location	Comment	Sec	Deg	Lvl	ScanID		
	Passed							
Waterflow Switch								
	Custodian Room Near The North Exit ITV In Southwest Corner Office	Passed	79	n/a	n/a	58091468		

Inventory & Warranty Report Generated by: BuildingReports.com

- Edu	ucation Center	r	Control Pa	nel: 1 - Simplex 4020			
The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.Device or TypeCategory% of InventoryQuantity							
	Category	% of	Inventory	Quantity			
	Control		4.55%	1			
	Control		18.18%	4			
	Control		4.55%	1			
	Initiating	4	40.91%	9			
	Control		4.55%	1			
	Initiating		4.55%	1			
	Initiating		9.09%	2			
	Initiating		4.55%	1			
	Supervisory		4.55%	1			
	Sound Test	1	4.55%	1			
Qt							
y	Model #	Description		Install Date			
	New	(under 90 days	5)				
1	PCVS-2			09/13/2019			
1	VSR-F			09/13/2019			
1				09/13/2019			
1	4020			09/13/2019			
2				09/13/2019			
		Keved		09/13/2019			
1		Reyea		09/13/2019			
		e - 2 Years to 3	Years				
2			20015	08/05/2017			
2	12V78AH	Sealed Lead Acid		08/05/2017			
_							
,	P Report by devic for two Qt y 1 1 1 1 2 9 1 1 2	P Report lists each of the de by device type and category for two years or more are Control Control Control Initiating Control Initiating Initiating Initiating Initiating Supervisory Sound Test Qt y Model # New 1 PCVS-2 1 VSR-F 1 PCVS-2 1 VSR-F 1 PCVS-2 1 VSR-F 2 4098-9733 9 2099-9795 1 2098-9201 In Servic	by device type and category is provided. Items in for two years or more are grouped together for Category % of Control Control Control Initiating Initiating Initiating Initiating Supervisory Sound Test Qt y Model # Description New (under 90 days 1 PCVS-2 1 VSR-F 1 PCVS-2 1 VSR-F 1 PCVS-2 1 VSR-F 1 2098-9733 9 2099-9795 Keyed 1 2098-9201 In Service - 2 Years to 3 2 12V18AH Sealed Lead Acid	Report lists each of the devices and items that are included in you by device type and category is provided. Items installed within the left two years or more are grouped together for easy reference. Category % of Inventory Control 4.55% Control 18.18% Control 4.55% Control 4.55% Control 4.55% Initiating 40.91% Control 4.55% Initiating 4.55% Initiating 4.55% Initiating 4.55% Supervisory 4.55% Sound Test 4.55% V Model # Description 1 PCVS-2 VSR-F 1 4020 2 2 12098-9733 9 2 12V18AH Sealed Lead Acid			

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Ensign Intermediate School 2000 Cliff Drive Newport Beach, CA 92663

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Oct 2, 2019

> Building: NMUSD - Ensign Intermediate School Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Beeri Martinez Title: Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD – Ensign Intermediate School	Contact: Tim Waller	
Address: 2000 Cliff Drive	Phone: 714-231-0363	
Address:	Fax:	
City/State/Zip: Newport Beach, CA 92663	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Beeri Martinez	
Address: 2903 Saturn Street	Phone: 714-91313100	
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: beerimartinez@calbuild	ingsystems.com
System Control Unit		
Manufacturer: Silent Knight	Inspection Date: 09/30/2019	IDC Style:
Model Number: 5820XL	Install Date: 09/30/2019	SLC Style:
Software Version:	Version Date: 09/30/2019	NAC Style:
Location: 1 st Admin Bldg. FACP/Mechanical Closet Outside Of Nurse Office	Current Protection: Breaker	
Monitoring		
Company: Pho	one: Acco	ount #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Cotogony	Total Items		Serviced		Passed		Failed/Other	
Category	Qty	%		%	Qty	%	Qty	%
Sound Test	1	0.92%	1	100.00%	1	100.00%	0	0%
Control	7	6.42%	7	100.00%	7	100.00%	0	0%
Initiating	101	92.66%	101	100.00%	101	100.00%	0	0%
Totals	109	100%	109	100.00%	109	100.00%	0	0%
Certification Company: Cal Building Systems			Bu	ilding: NMU	ISD – Ens	ign Interme	diate Scho	ol
Inspector: Beeri Martinez								
				gned:				

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Ensign Intermediate School

Control Panel: 1 - Silent Knight 5820XL

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	1st Admin Bldg. Front Office	Tested	3:44:52 PM	09/30/2019
Battery	1st Admin Bldg. FACP/Mechanical Closet Outside Of Nurse Office	Tested	3:28:41 PM	09/30/2019
Battery	1st Admin Bldg. FACP/Mechanical Closet Outside Of Nurse Office	Tested	3:28:45 PM	09/30/2019
Battery	Classroom 21 Storage	Tested	5:05:26 PM	09/30/2019
Battery	Classroom 21 Storage	Tested	5:05:46 PM	09/30/2019
Control Panel	1st Admin Bldg. FACP/Mechanical Closet Outside Of Nurse Office	Tested	3:25:51 PM	09/30/2019
Power Supply	Classroom 21 Storage	Tested	5:04:38 PM	09/30/2019
Initiating				
Pull Station	Northeast Gymnasium Exit	Tested	5:48:47 PM	09/30/2019
Pull Station	Southwest Gymnasium Exit	Tested	5:49:43 PM	09/30/2019
Pull Station	Gymnasium	Tested	5:46:43 PM	09/30/2019
Pull Station	Gymnasium	Tested	5:47:25 PM	09/30/2019
Pull Station	Gymnasium	Tested	5:47:29 PM	09/30/2019
Smoke Detector	1st Admin Bldg. ASB Office	Tested	3:34:41 PM	09/30/2019
Smoke Detector	1st Admin Bldg. Corridor Exit By Elevator	Inspected	6:05:36 PM	09/30/2019
Smoke Detector	1st Admin Bldg. Corridor Exit By Nurse Office	Tested	3:32:08 PM	09/30/2019
Smoke Detector	1st Admin Bldg. Elevator Machine Room	Inspected	6:05:21 PM	09/30/2019
Smoke Detector	1st Admin Bldg. FACP/Mechanical Closet Outside Of Nurse Office	Tested	3:29:50 PM	09/30/2019
Smoke Detector	1st Admin Bldg. Front Office	Tested	3:41:24 PM	09/30/2019
Smoke Detector	1st Admin Bldg. Front Office	Tested	3:43:46 PM	09/30/2019
Smoke Detector	1st Admin Bldg. Health Office	Tested	3:33:50 PM	09/30/2019
Smoke Detector	1st Admin Bldg. Nurse's Office	Tested	3:32:37 PM	09/30/2019
Smoke Detector	1st Admin Bldg. Office Manager	Tested	3:38:41 PM	09/30/2019
Smoke Detector	1st Admin Bldg. Principals Office	Tested	3:37:28 PM	09/30/2019
Smoke Detector	2nd Admin Bldg. Assistant Principal's Office	Tested	3:50:26 PM	09/30/2019
Smoke Detector	2nd Admin Bldg. Assistant Principal's Office	Tested	4:07:58 PM	09/30/2019
Smoke Detector	2nd Admin Bldg. Assistant Principal's Office Storage	Tested	3:52:02 PM	09/30/2019
Smoke Detector	2nd Admin Bldg. Community Coordinator	Tested	4:09:08 PM	09/30/2019
Smoke Detector	2nd Admin Bldg. Corridor By Community Coordinator	Tested	4:09:57 PM	09/30/2019
Smoke Detector	2nd Admin Bldg. Corridor By Registrar Office	Tested	3:58:05 PM	09/30/2019
Smoke Detector	2nd Admin Bldg. Corridor By Restroom	Tested	3:49:21 PM	09/30/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	2nd Admin Bldg. Corridor Exit By Elevator	Inspected	6:05:45 PM	09/30/2019
Smoke Detector	2nd Admin Bldg. Counselors Office	Tested	3:53:15 PM	09/30/2019
Smoke Detector	2nd Admin Bldg. Counselors Office	Tested	4:08:41 PM	09/30/2019
Smoke Detector	2nd Admin Bldg. Psychologist Office	Tested	3:47:12 PM	09/30/2019
Smoke Detector	2nd Admin Bldg. Registrar Office	Tested	3:56:24 PM	09/30/2019
Smoke Detector	2nd Admin Bldg. Restroom	Tested	3:48:44 PM	09/30/2019
Smoke Detector	2nd Admin Bldg. Teacher's Lounge Conference Room	Tested	4:06:01 PM	09/30/2019
Smoke Detector	2nd Admin Bldg. Teacher's Lounge Copy Room	Tested	4:04:26 PM	09/30/2019
Smoke Detector	2nd Admin Bldg. Teacher's Lounge Speech Office Storage	Tested	4:02:31 PM	09/30/2019
Smoke Detector	2nd Admin Bldg. Teacher's Lounge Speech Office	Tested	4:01:42 PM	09/30/2019
Smoke Detector	2nd Admin Bldg. Teacher's Lounge Workroom	Tested	4:05:49 PM	09/30/2019
Smoke Detector	2nd Admin Bldg. Teacher's Lounge	Tested	3:59:52 PM	09/30/2019
Smoke Detector	2nd Admin Bldg. Teacher's Lounge	Tested	4:00:53 PM	09/30/2019
Smoke Detector	2nd Gymnasium Classroom 48	Tested	5:51:20 PM	09/30/2019
Smoke Detector	2nd Gymnasium Classroom 48	Tested	5:51:47 PM	09/30/2019
Smoke Detector	Southwest Gymnasium Corridor Exit	Tested	5:54:12 PM	09/30/2019
Smoke Detector	Southwest Gymnasium Storage Next To Girl's Locker Room	Tested	5:55:07 PM	09/30/2019
Smoke Detector	Book Storage By Classroom 21	Tested	4:53:35 PM	09/30/2019
Smoke Detector	Classroom 1	Tested	4:13:20 PM	09/30/2019
Smoke Detector	Classroom 1	Tested	4:13:42 PM	09/30/2019
Smoke Detector	Classroom 10	Tested	4:31:10 PM	09/30/2019
Smoke Detector	Classroom 10	Tested	4:31:14 PM	09/30/2019
Smoke Detector	Classroom 11	Tested	4:31:22 PM	09/30/2019
Smoke Detector	Classroom 11	Tested	4:35:03 PM	09/30/2019
Smoke Detector	Classroom 2	Tested	4:14:59 PM	09/30/2019
Smoke Detector	Classroom 2	Tested	4:15:15 PM	09/30/2019
Smoke Detector	Classroom 21 Storage	Tested	4:55:11 PM	09/30/2019
Smoke Detector	Classroom 21 Storage	Tested	4:55:19 PM	09/30/2019
Smoke Detector	Classroom 21	Tested	4:55:00 PM	09/30/2019
Smoke Detector	Classroom 21	Tested	4:55:08 PM	09/30/2019
Smoke Detector	Classroom 22	Tested	5:07:11 PM	09/30/2019
Smoke Detector	Classroom 22	Tested	5:07:28 PM	09/30/2019
Smoke Detector	Classroom 23	Tested	5:07:33 PM	09/30/2019
Smoke Detector	Classroom 23	Tested	5:07:43 PM	09/30/2019
Smoke Detector	Classroom 24	Tested	5:07:47 PM	09/30/2019
Smoke Detector	Classroom 24	Tested	5:07:55 PM	09/30/2019
Smoke Detector	Classroom 25	Tested	5:17:07 PM	09/30/2019
Smoke Detector	Classroom 25	Tested	5:17:17 PM	09/30/2019
Smoke Detector	Classroom 26	Tested	5:17:22 PM	09/30/2019
Smoke Detector	Classroom 26	Tested	5:17:32 PM	09/30/2019
Smoke Detector	Classroom 27	Tested	5:17:36 PM	09/30/2019
Smoke Detector	Classroom 27	Tested	5:17:43 PM	09/30/2019
Smoke Detector	Classroom 28	Tested	5:17:46 PM	09/30/2019
Smoke Detector	Classroom 28	Tested	5:17:59 PM	09/30/2019
		Tested	5:26:29 PM	09/30/2019
Smoke Detector	Classroom 29	resteu	5.20.25114	03/30/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Classroom 29 & 30 Storage	Tested	5:26:42 PM	09/30/2019
Smoke Detector	Classroom 29 & 30 Storage Cleaning	Tested	5:28:14 PM	09/30/2019
Smoke Detector	Classroom 3	Tested	4:16:46 PM	09/30/2019
Smoke Detector	Classroom 3	Tested	4:16:57 PM	09/30/2019
Smoke Detector	Classroom 30	Tested	5:29:07 PM	09/30/2019
Smoke Detector	Classroom 30	Tested	5:29:17 PM	09/30/2019
Smoke Detector	Classroom 31	Tested	5:29:58 PM	09/30/2019
Smoke Detector	Classroom 31	Tested	5:30:05 PM	09/30/2019
Smoke Detector	Classroom 32	Tested	5:33:14 PM	09/30/2019
Smoke Detector	Classroom 32	Tested	5:33:20 PM	09/30/2019
Smoke Detector	Classroom 4	Tested	4:17:00 PM	09/30/2019
Smoke Detector	Classroom 4	Tested	4:17:07 PM	09/30/2019
Smoke Detector	Classroom 4A Storage	Tested	4:17:10 PM	09/30/2019
Smoke Detector	Classroom 5	Tested	4:17:39 PM	09/30/2019
Smoke Detector	Classroom 5	Tested	4:23:41 PM	09/30/2019
Smoke Detector	Classroom 6	Tested	4:24:50 PM	09/30/2019
Smoke Detector	Classroom 6	Tested	4:24:57 PM	09/30/2019
Smoke Detector	Classroom 7	Tested	4:25:00 PM	09/30/2019
Smoke Detector	Classroom 7	Tested	4:25:09 PM	09/30/2019
Smoke Detector	Classroom 8	Tested	4:25:12 PM	09/30/2019
Smoke Detector	Classroom 8	Tested	4:25:20 PM	09/30/2019
Smoke Detector	Classroom 9 Storage	Tested	4:32:11 PM	09/30/2019
Smoke Detector	Classroom 9	Tested	4:30:51 PM	09/30/2019
Smoke Detector	Classroom 9	Tested	4:31:00 PM	09/30/2019
Smoke Detector	Gymnasium Girl's Locker Room Coach's Office	Tested	5:57:39 PM	09/30/2019
Smoke Detector	Gymnasium Girl's Locker Room Coach's Office	Tested	5:58:46 PM	09/30/2019
	Storage			
Smoke Detector	Gymnasium Girl's Locker Room Restroom	Tested	6:01:08 PM	09/30/2019
Smoke Detector	Gymnasium Girl's Locker Room Storage	Tested	5:56:34 PM	09/30/2019
Smoke Detector	Gymnasium Girl's Locker Room	Tested	5:59:23 PM	09/30/2019
Smoke Detector	Gymnasium Girl's Locker Room	Tested	5:59:40 PM	09/30/2019
Smoke Detector	Portables Boy's Restroom Across Classroom 53	Tested	5:37:19 PM	09/30/2019
Smoke Detector	Portables Girl's Restroom Across Classroom 53	Tested	5:38:49 PM	09/30/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Ensign Intermediate School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Device Type Service						
Passed							
Annunciator	Tested	1					
Battery	Tested	4					
Control Panel	Tested	1					
Power Supply	Tested	1					
Pull Station	Tested	5					
Smoke Detector	Inspected	3					
Smoke Detector	Tested	93					
Total		108					

Auxiliary Functions Testing Generated by: BuildingReports.com

School	USD - Ensign Intermediate	Control Panel: 5820XL	Control Panel: 1 - Silent Knight 5820XL					
The Auxiliary Functions Testing section lists each of the ancillary items, systems, and emergency equipment that are controlled by the system control unit. Items are grouped by Passed or Failed/Other. The items are listed by device type, and a check box is provided to indicate if the test conducted was simulated.								
Туре	Location	Comment	ScanID	Simulated				
Туре	Location	I	ScanID	Simulated				
Type Smoke Detect	Passe	I	ScanID	Simulated				

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - Ensign Intermediate School

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

		Ambient	Alarm	🦻 Intell	igibility	Sound	
C Location	 Comment 	◀ dB	◀ dB	Voice	STI	Test	
Passed							
Sound Test Points							
Entire Campus	Passed					0001	

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Ensign Intermediate School

Control Panel: 1 - Silent Knight 5820XL

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type		Category		% of Inventory	Quantity		
Control Panel		Control		0.92%	1		
Battery		Control		3.67%	4		
Smoke Detector		Initiating		88.07%	96		
Annunciator		Control		0.92%	1		
Power Supply		Control		0.92%	1		
Pull Station		Initiating		4.59%	5		
Sound Test		Sound Test		0.92%	1		
	Qt						
Туре	У	Model #	Desci	ription	Install Date		
New (under 90 days)							
Silent Knight							
Control Panel	1	5820XL			09/30/2019		
		In Service	e - 2 Y	ears to 3 Years			
Battery	2	12v 18ah	Sealed	Lead Acid	08/18/2017		
Battery	2	12v 7ah	Sealed	Lead Acid	08/18/2017		
Silent Knight							
Annunciator	1	5820	LCD D	isplay	08/18/2017		
Power Supply	1	5496			08/18/2017		
Pull Station	5	SD500-PS	Keyed		08/18/2017		
Smoke Detector	90	SD505-APS	Photoe	electric	08/18/2017		
Smoke Detector	6	SD505-PHOTO	Photoe	electric	08/18/2017		

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Estancia High School 2323 Placentia Ave Costa Mesa, CA 92627

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Sep 25, 2019

> Building: NMUSD - Estancia High School Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Chris Ferreira Title: Service

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD – Estancia High School	Contact: Tim V	Valler
Address: 2323 Placentia Ave	Phone: 949515	56970
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92627	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Chri	is Ferreira
Address: 2903 Saturn Street	Phone: 714–99	93-9650
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: chrisfer	reira@calbuildingsystems.com
System Control Unit		
Manufacturer: SimplexGrinnell	Inspection Dat	e: 09/23/2019 IDC Style:
Model Number: 4100U	Install Date: 09	9/23/2019 SLC Style:
Software Version:	Version Date: (09/23/2019 NAC Style:
Location: Admin Telcom Room A112	Current Protec	tion: Breaker
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Catalogue	Total	ltems	Ser	viced	Pas	sed	Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty 2 7 9	%
Control	7	2.10%	7	100.00%	5	71.43%	2	28.57%
Initiating	327	97.90%	327	100.00%	320	97.86%	7	2.14%
Totals	334	100%	334	100.00%	325	97.31%	9	2.69%
Certification								
Company: Cal Building Systems			Bu	ilding: NML	JSD – Esta	ncia High S	School	
Inspector: Chris Ferreira			Co	ontact: Tim	Waller			
Signed:			Sig	gned:				

Discrepancy Report Generated by: BuildingReports.com

Battery 1 Statlend 1 S	Building: N	MUSD - Estancia High	School	Control Pan	el: 1 - Simj	plexGri	nnell	
Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included. Device Type Manufacturer ModelNumber Date Qty Items listed for Recall by the manufacturer is included. Device Type Manufacturer ModelNumber Date Qty Bexitee Type No recalled items found during this inspection. Items listed for Recall by Manufacturer No recalled items found during this inspection. Items listed for Recall by Manufacturer Battery SeanID Location No recalled items found during this inspection. Items listed for Recall by Manufacturer Battery Sa094504 Building H Office 1 Sa094505 Building F Filter Rm. F513 1 Sa094576 Building F Filter Rm. F513 1 Sa094576 Building F Paundry F520 1 Sa094590 Building F Pausage F524 1 Sa094590 Building F Boys Locker F529 1 <td co<="" td=""><td>Dunung. IV</td><td>Listaneia mgi</td><th></th><td>4100U</td><td></td><td></td><td></td></td>	<td>Dunung. IV</td> <td>Listaneia mgi</td> <th></th> <td>4100U</td> <td></td> <td></td> <td></td>	Dunung. IV	Listaneia mgi		4100U			
Items listed for Recall by Manufacturer No recalled items found during this inspection. ScanID Location Problem Address Reference Control Control Battery Image: Control Control S8094504 Building H Office 1 Second Battery Image: Control Image: Control Image: Control S8094504 Building H Office 1 S8094505 Building H Office 1 S8094505 Building F Filter Rm. F513 1 S8094576 Building F Filter Rm. F513 1 S8094588 Building F Issue F510 1 S8094590 Building F Issue F510 1 S8094591 Building F Passage F524 1 S8094592 North Building F Boys Locker F529 1 S8094589 North Building F Girls Shower/Locker	Discrepancies a appropriate, cod	re listed by Category, and group le references are listed for your o	ed by device type. convenience. Any i	The description of tem that was inspec	f the problem is ted that is listed	provided a	and where	
No recalled items found during this inspection. ScanID Location Problem Address Reference Eattery Control Image: Control Contecont Contro Control Control Control Control Control Control Con	Device Type	Manufactur	er	ModelNumber	r Da	te	Qty	
ScanIDLocationProblemAddressReferenceControlBattery58094504Building H Office158094505Building H Office1InitiatingBeam Detector58094676Building F Filter Rm. F513158094588Building F Issue F510158094590Building F Issue F510158094591Building F Passage F524158094592North Building F Boys Locker F529158094588North Building F Girls Shower/Locker1		Items listed	l for Recall b	y Manufactur	rer			
Control Battery 1 58094504 Building H Office 1 58094505 Building H Office 1 Initiating Beam Detector 58094676 Building F Filter Rm. F513 1 58094676 Building F Issue F510 1 58094590 Building F Issue F510 1 58094590 Building F Laundry F520 1 1 58094591 Building F Passage F524 1 58094592 North Building F Boys Locker F529 1 1 58094589 North Building F Girls Shower/Locker 1		No recalle	d items found durii	ng this inspection.				
Battery58094504Building H Office158094505Building H Office1InitiatingS8094506Building F Filter Rm. F5131S8094676Building F Filter Rm. F513158094588Building F Issue F510158094590Building F Laundry F520158094591Building F Passage F524158094592North Building F Boys Locker F529158094589North Building F Girls Shower/Locker1	8 ScanID	C Location	ę	Problem	Address	🛄 Ref	erence	
58094504Building H Office158094505Building H Office1InitiatingS8094506Building F Filter Rm. F5131S8094676Building F Filter Rm. F513158094588Building F Issue F510158094590Building F Laundry F520158094591Building F Passage F524158094592North Building F Boys Locker F529158094589North Building F Girls Shower/Locker1			Control	1				
50004504building if office158094505Building H Office1InitiatingS8094676Building F Filter Rm. F513158094676Building F Filter Rm. F513158094588Building F Issue F510158094590Building F Laundry F520158094591Building F Passage F524158094592North Building F Boys Locker F529158094589North Building F Girls Shower/Locker1	Battery							
InitiatingBeam Detector58094676Building F Filter Rm. F513158094588Building F Issue F510158094590Building F Laundry F520158094591Building F Passage F524158094592North Building F Boys Locker F529158094589North Building F Girls Shower/Locker1	58094504	Building H Office			1			
Beam Detector 1 58094676 Building F Filter Rm. F513 1 58094588 Building F Issue F510 1 58094590 Building F Laundry F520 1 58094591 Building F Passage F524 1 58094592 North Building F Boys Locker F529 1 58094589 North Building F Girls Shower/Locker 1	58094505	Building H Office			1			
58094676 Building F Filter Rm. F513 1 58094576 Building F Issue F510 1 58094580 Building F Issue F510 1 58094590 Building F Laundry F520 1 58094591 Building F Passage F524 1 58094592 North Building F Boys Locker F529 1 58094589 North Building F Girls Shower/Locker 1			Initiating	g				
58094588 Building F Issue F510 1 58094590 Building F Laundry F520 1 58094591 Building F Passage F524 1 58094592 North Building F Boys Locker F529 1 58094589 North Building F Cirls Shower/Locker 1	Beam Dete	ctor						
58094590Building F Laundry F520158094591Building F Passage F524158094592North Building F Boys Locker F529158094589North Building F Girls Shower/Locker1	58094676	Building F Filter Rm. F513			1			
58094591Building F Passage F524158094592North Building F Boys Locker F529158094589North Building F Girls Shower/Locker1	58094588	Building F Issue F510			1			
58094592North Building F Boys Locker F529158094589North Building F Girls Shower/Locker1	58094590	Building F Laundry F520			1			
58094589North Building F Girls Shower/Locker1	58094591	Building F Passage F524			1			
-	58094592	North Building F Boys Locker F5	29		1			
58094593South Building F Boys Locker F5291	58094589	North Building F Girls Shower/L	ocker		1			
	58094593	South Building F Boys Locker F5	29		1			

Proposed Solutions Report

Generated by: BuildingReports.com

Building: NMUSD - Estancia High School Control Panel: 1 - SimplexGrinnell 4100U

The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.

ScanID	Location	Solution	Model #	Cost	Fix					
	Control									
Battery										
58094504	Building H Office		12V 7AH	T/M						
58094505	Building H Office		12V 7AH	T/M						
	Init	tiating								
Beam Det	Beam Detector									
58094676	Building F Filter Rm. F513			T/M						
58094588	Building F Issue F510			T/M						
58094590	Building F Laundry F520			T/M						
58094591	Building F Passage F524			T/M						
58094592	North Building F Boys Locker F529			T/M						
58094589	North Building F Girls Shower/Locker			T/M						
58094593	South Building F Boys Locker F529			T/M						
			PO #: (none)	T/M						

Notes & Recommendations

Generated by: BuildingReports.com

Building: NMUSD - Estancia High School

Control Panel: 1 - SimplexGrinnell 4100U

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

ScanID	Note	Device Type	Location	Comment			
	Initiating						
58094676	1	Beam Detector	Building F Filter Rm. F513				
Disab	led on pa	nel prior to arrival					
58094588	2	Beam Detector	Building F Issue F510				
Disab	led on pa	nel prior to arrival					
58094590	3	Beam Detector	Building F Laundry F520				
Disab	Disabled on panel prior to arrival						
58094591	4	Beam Detector	Building F Passage F524				
Disab	led on pa	nel prior to arrival					
58094592	5	Beam Detector	North Building F Boys Locker F529				
Disab	led on pa	nel prior to arrival					
58094589	6	Beam Detector	North Building F Girls Shower/Locker				
Disab	led on pa	nel prior to arrival					
58094593	7	Beam Detector	South Building F Boys Locker F529				
Disab	Disabled on panel prior to arrival						

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Estancia High School

Control Panel: 1 - SimplexGrinnell 4100U

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Building A Near Admin Front Entrance	Tested	4:10:53 PM	09/24/2019
Battery	Admin Telcom Room A112	Inspected	3:59:51 PM	09/23/2019
Battery	Admin Telcom Room A112	Inspected	4:01:23 PM	09/23/2019
Control Panel	Admin Telcom Room A112	Tested	3:50:41 PM	09/23/2019
Power Supply	Building H Office	Tested	5:45:37 PM	09/24/2019
Initiating				
Beam Detector	East Building K Lecture K901	Tested	3:35:39 PM	09/25/2019
Beam Detector	North Building G Gym	Tested	3:48:14 PM	09/25/2019
Beam Detector	North Building G Gym	Tested	3:48:48 PM	09/25/2019
Beam Detector	North Building G Gym	Tested	3:48:56 PM	09/25/2019
Beam Detector	North Building G Gym Center	Tested	3:49:08 PM	09/25/2019
Beam Detector	North Building G Gym Center	Tested	3:49:22 PM	09/25/2019
Beam Detector	North Building G Gym South	Tested	3:49:37 PM	09/25/2019
Beam Detector	North Building G Gym South	Tested	3:49:58 PM	09/25/2019
Beam Detector	North Building L Gym North	Tested	3:51:07 PM	09/25/2019
Beam Detector	North Building L Gym South	Tested	3:50:48 PM	09/25/2019
Beam Detector	South Building F Girls Shower/Locker	Tested	3:41:35 PM	09/25/2019
Beam Detector	South Building G Gym	Tested	3:36:40 PM	09/25/2019
Beam Detector	South Building G Gym Center	Tested	3:37:56 PM	09/25/2019
Beam Detector	South Building G Gym Center	Tested	3:38:39 PM	09/25/2019
Beam Detector	South Building G Gym North	Tested	3:38:21 PM	09/25/2019
Beam Detector	South Building G Gym South	Tested	3:39:10 PM	09/25/2019
Beam Detector	South Building L Gym North	Tested	3:50:31 PM	09/25/2019
Beam Detector	South Building L Gym South	Tested	3:50:10 PM	09/25/2019
Beam Detector	West Building K Lecture K901	Tested	3:35:26 PM	09/25/2019
Beam Detector	Admin Attendance A117	Tested	5:52:29 PM	09/24/2019
Beam Detector	Admin Lobby A100	Tested	5:57:58 PM	09/24/2019
Beam Detector	Between Bldg. B&C	Tested	3:32:32 PM	09/25/2019
Beam Detector	Between Building J&H	Tested	3:51:23 PM	09/25/2019
Beam Detector	Between Building J&K	Tested	3:44:42 PM	09/25/2019
Beam Detector	Between Building K&Cafe	Tested	3:51:48 PM	09/25/2019
Beam Detector	Building B Court B211	Tested	5:58:21 PM	09/24/2019
Beam Detector	Building B Court B239	Tested	5:59:20 PM	09/24/2019
Beam Detector	Building B Court B241	Tested	5:59:51 PM	09/24/2019
Beam Detector	Building B Court B273	Tested	6:02:00 PM	09/24/2019
Beam Detector	Building C Choral C376	Tested	6:15:45 PM	09/24/2019
Beam Detector	Building C Computer Lab C346	Tested	6:06:58 PM	09/24/2019

Device Type	Location	Service	Time	Date
	Passed			
Beam Detector	Building C Corridor 331	Tested	6:08:13 PM	09/24/2019
Beam Detector	Building C Corridor C333	Tested	6:07:27 PM	09/24/2019
Beam Detector	Building C Corridor C334	Tested	6:06:07 PM	09/24/2019
Beam Detector	Building C Court C300	Tested	6:17:51 PM	09/24/2019
Beam Detector	Building C Court C307	Tested	6:19:31 PM	09/24/2019
Beam Detector	Building C Court C320	Tested	6:17:33 PM	09/24/2019
Beam Detector	Building C Court C321	Tested	6:18:03 PM	09/24/2019
Beam Detector	Building C Drafting C345	Tested	6:06:31 PM	09/24/2019
Beam Detector	Building C Electronics C342	Tested	6:07:47 PM	09/24/2019
Beam Detector	Building C Instrumental C363	Tested	6:09:18 PM	09/24/2019
Beam Detector	Building C Maintenance C350	Tested	6:08:58 PM	09/24/2019
Beam Detector	Building C Metal Shop C344	Tested	6:19:06 PM	09/24/2019
Beam Detector	Building C Weight Room C 343	Tested	6:18:18 PM	09/24/2019
Beam Detector	Building C Wood Shop C347	Tested	6:08:33 PM	09/24/2019
Beam Detector	Building D Cafeteria D419	Tested	3:39:26 PM	09/25/2019
Beam Detector	Building D Cafeteria D419	Tested	3:43:12 PM	09/25/2019
Beam Detector	Building D Faculty Dining D410	Tested	3:41:04 PM	09/25/2019
Beam Detector	Building D Student Serving D401	Tested	3:40:29 PM	09/25/2019
Beam Detector	Building G Classroom G602	Tested	3:37:20 PM	09/25/2019
Beam Detector	Building H Court H743	Tested	6:19:51 PM	09/24/2019
Beam Detector	Building J Corridor B276	Tested	6:02:58 PM	09/24/2019
Beam Detector	Building J East Corridor By Building H	Tested	6:04:06 PM	09/24/2019
Beam Detector	Building J Reading Stacks	Tested	6:02:13 PM	09/24/2019
Beam Detector	Building J Reading Stacks	Tested	6:05:49 PM	09/24/2019
Beam Detector	Building J Study Area	Tested	6:03:51 PM	09/24/2019
Beam Detector	Building J Study Area North	Tested	6:02:36 PM	09/24/2019
Beam Detector	Building K Between B&K	Tested	3:29:41 PM	09/25/2019
Beam Detector	Building K Lecture K901	Tested	3:32:50 PM	09/25/2019
Beam Detector	Building K Platform K902	Tested	3:35:56 PM	09/25/2019
Beam Detector	Between Building C And K	Tested	6:16:33 PM	09/24/2019
Beam Detector	Between Building C&D	Tested	3:40:01 PM	09/25/2019
Pull Station	Building A Admin Near Attendance	Tested	3:53:30 PM	09/24/2019
Pull Station	Building A Near Admin Front Entrance	Tested	4:09:27 PM	09/24/2019
Pull Station	Building B Corridor	Tested	4:37:42 PM	09/23/2019
Pull Station	Building B Corridor By B250	Tested	5:39:58 PM	09/23/2019
Pull Station	Building B Corridor Entrance	Tested	4:01:41 PM	09/23/2019
Pull Station	Building C Outside Corridor	Tested	6:04:50 PM	09/23/2019
Pull Station	Building C Weight Room	Tested	6:55:03 PM	09/23/2019
Pull Station	Building C Wood Shop	Tested	6:57:42 PM	09/23/2019
Pull Station	Building C Wood Shop	Tested	7:02:00 PM	09/23/2019
Pull Station	Building D Southwest Exit	Tested	5:02:13 PM	09/24/2019
Pull Station	Building G Gym	Tested	5:31:04 PM	09/24/2019
Pull Station	Building G Gym North Exit	Tested	5:32:02 PM	09/24/2019
Pull Station	Building G Gym North Exit	Tested	5:32:34 PM	09/24/2019
Pull Station	Building G Gym Southwest Exit	Tested	5:31:22 PM	09/24/2019
Pull Station	Building G North Exit	Tested	5:25:02 PM	09/24/2019
Pull Station	Building H Corridor	Tested	4:17:11 PM	09/24/2019
Pull Station	Building H Exit	Tested	5:53:23 PM	09/24/2019
Pull Station	Building J Library	Tested	4:23:21 PM	09/24/2019
Pull Station	Building K Theater East Exit	Tested	4:34:41 PM	09/24/2019

Device Type	Location	Service	Time	Date
	Passed			
Pull Station	Building K Theater East Exit	Tested	4:35:17 PM	09/24/2019
Pull Station	Building K Theater West Exit	Tested	4:35:39 PM	09/24/2019
Pull Station	Building K Theater West Exit	Tested	4:36:59 PM	09/24/2019
Pull Station	Cafeteria North Exit	Tested	5:14:43 PM	09/24/2019
Smoke Detector	Admin Telecomm Room	Tested	3:53:38 PM	09/23/2019
Smoke Detector	Admin Telecomm Room	Tested	3:55:33 PM	09/23/2019
Smoke Detector	Building A Admin Assistant Office	Tested	4:12:23 PM	09/24/2019
Smoke Detector	Building A Admin Assistant Principals Office	Tested	4:04:48 PM	09/24/2019
Smoke Detector	Building A Admin Avid Office	Tested	3:57:29 PM	09/24/2019
Smoke Detector	Building A Admin Community Facilitators Office	Tested	3:59:30 PM	09/24/2019
Smoke Detector	Building A Admin Counselors Office	Tested	3:58:20 PM	09/24/2019
Smoke Detector	Building A Admin Counselors Office	Tested	4:00:54 PM	09/24/2019
Smoke Detector	Building A Admin Counselors Office	Tested	4:01:33 PM	09/24/2019
Smoke Detector	Building A Admin Near Counseling	Tested	3:52:01 PM	09/24/2019
Smoke Detector	Building A Admin Near Counseling	Tested	3:54:34 PM	09/24/2019
Smoke Detector	Building A Admin Near Nurses Office	Tested	3:51:39 PM	09/24/2019
Smoke Detector	Building A Admin Registrar	Tested	3:55:08 PM	09/24/2019
Smoke Detector	Building A Admin School Resource Officer	Tested	4:03:26 PM	09/24/2019
Smoke Detector	Building A Admin Social Workers Office	Tested	4:01:43 PM	09/24/2019
Smoke Detector	Building A Admin Storage	Tested	3:56:21 PM	09/24/2019
Smoke Detector	Building A Admin Workroom	Tested	4:04:04 PM	09/24/2019
Smoke Detector	Building A Assistant Principals Office	Tested	4:15:02 PM	09/24/2019
Smoke Detector	Building A Corridor Near Assistant Principals Office	Tested	4:05:23 PM	09/24/2019
Smoke Detector	Building A Corridor Near Principals Office	Tested	4:08:07 PM	09/24/2019
Smoke Detector	Building A Nurses Office	Tested	4:07:17 PM	09/24/2019
Smoke Detector	Building A Nurses Office	Tested	4:07:33 PM	09/24/2019
Smoke Detector	Building A Nurses Office Restroom	Tested	4:06:45 PM	09/24/2019
Smoke Detector	Building A Office Managers Office	Tested	4:11:51 PM	09/24/2019
Smoke Detector	Building A Principals Office	Tested	4:11:14 PM	09/24/2019
Smoke Detector	Building B Classroom 250	Tested	5:34:43 PM	09/23/2019
Smoke Detector	Building B Classroom 250	Tested	5:36:33 PM	09/23/2019
Smoke Detector	Building B Classroom 251	Tested	5:32:21 PM	09/23/2019
Smoke Detector	Building B Classroom 251	Tested	5:32:39 PM	09/23/2019
Smoke Detector	Building B Classroom 252	Tested	5:30:30 PM	09/23/2019
Smoke Detector	Building B Classroom 252	Tested	5:30:49 PM	09/23/2019
Smoke Detector	Building B Classroom 253	Tested	5:28:05 PM	09/23/2019
Smoke Detector	Building B Classroom 253	Tested	5:29:34 PM	09/23/2019
Smoke Detector	Building B Classroom 263	Tested	5:55:16 PM	09/23/2019
Smoke Detector	Building B Classroom 264	Tested	5:56:10 PM	09/23/2019
Smoke Detector	Building B Classroom 264	Tested	5:57:48 PM	09/23/2019
Smoke Detector	Building B Classroom 265	Tested	5:58:13 PM	09/23/2019
Smoke Detector	Building B Classroom 265	Tested	5:59:28 PM	09/23/2019
Smoke Detector	Building B Classroom 266	Tested	5:42:52 PM	09/23/2019
Smoke Detector	Building B Classroom 266	Tested	5:43:37 PM	09/23/2019
Smoke Detector	Building B Classroom 267	Tested	5:45:28 PM	09/23/2019
Smoke Detector	Building B Classroom 267	Tested	5:45:51 PM	09/23/2019
Smoke Detector	Building B Classroom 267	Tested	5:46:23 PM	09/23/2019
Smoke Detector	Building B Classroom 267	Tested	5:46:40 PM	09/23/2019
Smoke Detector	Building B Classroom 268	Tested	5:47:55 PM	09/23/2019

Device Type	Location	Service	Time	Date
	Passe	d		
Smoke Detector	Building B Classroom 268	Tested	5:48:18 PM	09/23/2019
Smoke Detector	Building B Classroom 269	Tested	5:49:53 PM	09/23/2019
Smoke Detector	Building B Classroom 269	Tested	5:50:24 PM	09/23/2019
Smoke Detector	Building B Classroom 270	Tested	5:51:24 PM	09/23/2019
Smoke Detector	Building B Classroom 270	Tested	5:51:40 PM	09/23/2019
Smoke Detector	Building B Classroom B203	Tested	4:28:38 PM	09/23/2019
Smoke Detector	Building B Classroom B204	Tested	4:29:25 PM	09/23/2019
Smoke Detector	Building B Classroom B207	Tested	4:35:40 PM	09/23/2019
Smoke Detector	Building B Classroom B207	Tested	4:36:21 PM	09/23/2019
Smoke Detector	Building B Classroom B207	Tested	4:37:21 PM	09/23/2019
Smoke Detector	Building B Classroom B208	Tested	4:35:09 PM	09/23/2019
Smoke Detector	Building B Classroom B209	Tested	4:33:14 PM	09/23/2019
Smoke Detector	Building B Classroom B209	Tested	4:33:40 PM	09/23/2019
Smoke Detector	Building B Classroom B210	Tested	4:31:33 PM	09/23/2019
Smoke Detector	Building B Classroom B210	Tested	4:32:03 PM	09/23/2019
Smoke Detector	Building B Classroom B223	Tested	4:54:10 PM	09/23/2019
Smoke Detector	Building B Classroom B223	Tested	4:54:45 PM	09/23/2019
Smoke Detector	Building B Classroom B224	Tested	4:52:25 PM	09/23/2019
Smoke Detector	Building B Classroom B224	Tested	4:52:41 PM	09/23/2019
Smoke Detector	Building B Classroom B225	Tested	4:50:53 PM	09/23/2019
Smoke Detector	Building B Classroom B225	Tested	4:51:03 PM	09/23/2019
Smoke Detector	Building B Classroom B225	Tested	4:44:28 PM	
Smoke Detector	Building B Classroom B226	Tested	4:45:21 PM	09/23/2019 09/23/2019
Smoke Detector	Building B Classroom B227	Tested	4:46:46 PM	09/23/2019
Smoke Detector	Building B Classroom B227	Tested	4:47:12 PM	09/23/2019
Smoke Detector	Building B Classroom B228	Tested	4:48:14 PM	09/23/2019
Smoke Detector	Building B Classroom B228	Tested	4:49:32 PM	09/23/2019
Smoke Detector	Building B Classroom B229	Tested	5:02:23 PM	09/23/2019
Smoke Detector	Building B Classroom B229	Tested	5:03:34 PM	09/23/2019
Smoke Detector	-	Tested	4:58:55 PM	
Smoke Detector	Building B Classroom B231	Tested	4:59:13 PM	09/23/2019
Smoke Detector	Building B Classroom B231	Tested	4:59:40 PM	09/23/2019
Smoke Detector	Building B Classroom B231	Tested	4:59:54 PM	09/23/2019 09/23/2019
	Building B Classroom B231		4:57:33 PM	
Smoke Detector	Building B Classroom B232	Tested	5:20:26 PM	09/23/2019
Smoke Detector	Building B Classroom B243	Tested	5:20:20 PM	09/23/2019
Smoke Detector	Building B Classroom B243	Tested	5:19:26 PM	09/23/2019
Smoke Detector	Building B Classroom B244	Tested		09/23/2019
Smoke Detector	Building B Classroom B245	Tested	5:16:45 PM 5:18:16 PM	09/23/2019
Smoke Detector	Building B Classroom B245	Tested		09/23/2019
Smoke Detector	Building B Classroom B246	Tested	5:15:56 PM	09/23/2019
Smoke Detector	Building B Classroom B247	Tested	5:05:44 PM	09/23/2019
Smoke Detector	Building B Classroom B247	Tested	5:06:14 PM	09/23/2019
Smoke Detector	Building B Classroom B248	Tested	5:10:16 PM	09/23/2019
Smoke Detector	Building B Classroom B248	Tested	5:10:32 PM	09/23/2019
Smoke Detector	Building B Classroom B249	Tested	5:13:14 PM	09/23/2019
Smoke Detector	Building B Classroom B249	Tested	5:13:54 PM	09/23/2019
Smoke Detector	Building B Classroom B205	Tested	6:15:26 PM	09/24/2019
Smoke Detector	Building B Classroom B205	Tested	6:15:49 PM	09/24/2019
Smoke Detector	Building B Classroom B205	Tested	6:15:55 PM	09/24/2019
Smoke Detector	Building B Classroom B205	Tested	6:16:01 PM	09/24/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building B Classroom B205	Tested	6:16:07 PM	09/24/2019
Smoke Detector	Building B Corridor	Tested	5:22:09 PM	09/23/2019
Smoke Detector	Building B Corridor By B207	Tested	4:41:53 PM	09/23/2019
Smoke Detector	Building B Corridor By B207	Tested	4:43:00 PM	09/23/2019
Smoke Detector	Building B Corridor By B226	Tested	4:43:20 PM	09/23/2019
Smoke Detector	Building B Corridor By B227	Tested	4:46:06 PM	09/23/2019
Smoke Detector	Building B Corridor By B228	Tested	4:49:59 PM	09/23/2019
Smoke Detector	Building B Corridor By B229	Tested	5:04:37 PM	09/23/2019
Smoke Detector	Building B Corridor By B247	Tested	5:04:18 PM	09/23/2019
Smoke Detector	Building B Corridor By B248	Tested	5:09:15 PM	09/23/2019
Smoke Detector	Building B Corridor By B250	Tested	5:33:53 PM	09/23/2019
Smoke Detector	Building B Corridor By B250	Tested	5:37:29 PM	09/23/2019
Smoke Detector	Building B Corridor By B250	Tested	5:41:55 PM	09/23/2019
Smoke Detector	Building B Corridor By B254	Tested	6:02:19 PM	09/23/2019
Smoke Detector	Building B Corridor By B254	Tested	6:03:08 PM	09/23/2019
Smoke Detector	Building B Corridor By B263	Tested	5:59:53 PM	09/23/2019
Smoke Detector	Building B Corridor By B263	Tested	6:00:44 PM	09/23/2019
Smoke Detector	Building B Entrance	Tested	4:25:20 PM	09/23/2019
Smoke Detector	Building B Entry Way	Tested	4:06:06 PM	09/23/2019
Smoke Detector	Building B Office B201	Tested	4:26:07 PM	09/23/2019
Smoke Detector	Building B Office B202	Tested	4:27:27 PM	09/23/2019
Smoke Detector	Building B Office By B232	Tested	4:56:30 PM	09/23/2019
Smoke Detector	Building B Office By B244	Tested	5:26:45 PM	09/23/2019
Smoke Detector	Building B Storage Room	Tested	5:22:46 PM	09/23/2019
Smoke Detector	Building B Storage Room	Tested	5:24:41 PM	09/23/2019
Smoke Detector	Building B Storage Room By B232	Tested	4:55:47 PM	09/23/2019
Smoke Detector	Building B Teachers Lounge	Tested	5:53:21 PM	09/23/2019
Smoke Detector	Building B Teachers Lounge	Tested	5:54:04 PM	09/23/2019
Smoke Detector	Building C Band Storage	Tested	6:46:19 PM	09/23/2019
Smoke Detector	Building C Cheer Room	Tested	4:59:30 PM	09/24/2019
Smoke Detector	Building C Cheer Room Office	Tested	5:00:28 PM	09/24/2019
Smoke Detector	Building C Choral/Library	Tested	4:46:33 PM	09/24/2019
Smoke Detector	Building C Classroom C303	Tested	6:14:44 PM	09/23/2019
Smoke Detector	Building C Classroom 325	Tested	6:37:42 PM	09/23/2019
Smoke Detector	Building C Classroom 325	Tested	6:38:40 PM	09/23/2019
Smoke Detector	Building C Classroom 325 Storage	Tested	6:41:49 PM	09/23/2019
Smoke Detector	Building C Classroom C305	Tested	6:24:48 PM	09/23/2019
Smoke Detector	Building C Classroom C305	Tested	6:25:40 PM	09/23/2019
Smoke Detector	Building C Classroom C305	Tested	6:25:45 PM	09/23/2019
Smoke Detector	Building C Classroom C342	Tested	6:51:57 PM	09/23/2019
Smoke Detector	Building C Classroom C346	Tested	7:06:55 PM	09/23/2019
Smoke Detector	Building C Classroom C363 Brass & Woodwinds	Tested	4:53:39 PM	09/24/2019
	Room			
Smoke Detector	Building C Classroom C363 Office	Tested	4:51:09 PM	09/24/2019
Smoke Detector	Building C Classroom C363 Office	Tested	4:51:49 PM	09/24/2019
Smoke Detector	Building C Classroom C363 Office	Tested	4:51:57 PM	09/24/2019
Smoke Detector	Building C Classroom C363 Storage	Tested	4:52:52 PM	09/24/2019
Smoke Detector	Building C Classroom C363 Teachers Office	Tested	4:54:46 PM	09/24/2019
Smoke Detector	Building C Classroom C376	Tested	4:47:12 PM	09/24/2019
Smoke Detector	Building C Classroom C376 Office	Tested	4:49:16 PM	09/24/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building C Classroom C376 Storage	Tested	4:50:15 PM	09/24/2019
Smoke Detector	Building C Corridor Entry	Tested	4:45:54 PM	09/24/2019
Smoke Detector	Building C Corridor Entry	Tested	4:46:12 PM	09/24/2019
Smoke Detector	Building C Entrance	Tested	4:43:02 PM	09/24/2019
Smoke Detector	Building C IT Office	Tested	6:47:43 PM	09/23/2019
Smoke Detector	Building C Janitor Room	Tested	6:42:43 PM	09/23/2019
Smoke Detector	Building C Janitor Room	Tested	6:44:24 PM	09/23/2019
Smoke Detector	Building C Office By 325	Tested	6:36:16 PM	09/23/2019
Smoke Detector	Building C Pottery	Tested	6:21:28 PM	09/23/2019
Smoke Detector	Building C Pottery	Tested	6:22:19 PM	09/23/2019
Smoke Detector	Building C Pottery	Tested	6:30:09 PM	09/23/2019
Smoke Detector	Building C Pottery	Tested	6:31:12 PM	09/23/2019
Smoke Detector	Building C Restroom	Tested	6:18:24 PM	09/23/2019
Smoke Detector	Building C Restroom	Tested	6:52:51 PM	09/23/2019
Smoke Detector	Building C Storage Room	Tested	6:16:38 PM	09/23/2019
Smoke Detector	Building C Storage Room	Tested	6:17:40 PM	09/23/2019
Smoke Detector	Building C Women's Restroom	Tested	6:33:08 PM	09/23/2019
Smoke Detector	Building D Athletic Office	Tested	5:12:03 PM	09/24/2019
Smoke Detector	Building D Athletic Office	Tested	5:12:45 PM	09/24/2019
Smoke Detector	Building D Athletic Office Entrance	Tested	5:10:16 PM	09/24/2019
Smoke Detector	Building D Athletic Office Restroom	Tested	5:11:23 PM	09/24/2019
Smoke Detector	Building D Athletic Office Restroom	Tested	5:13:19 PM	09/24/2019
Smoke Detector	Building D Athletic Office Restroom Corridor	Tested	5:10:51 PM	09/24/2019
Smoke Detector	Building D Faculty Serving Room	Tested	5:07:57 PM	09/24/2019
Smoke Detector	Building D Kitchen	Tested/Cleaned	5:03:48 PM	09/24/2019
Smoke Detector	Building D Kitchen Locker room	Tested	5:06:46 PM	09/24/2019
Smoke Detector	Building D Kitchen Locker Room Restroom	Tested	5:07:19 PM	09/24/2019
Smoke Detector	Building D Kitchen Storage	Tested	5:05:25 PM	09/24/2019
Smoke Detector	Building D Water Heater Room	Tested	5:09:09 PM	09/24/2019
Smoke Detector	Building G Corridor	Tested	5:24:29 PM	09/24/2019
Smoke Detector	Building G Corridor	Tested	5:24:45 PM	09/24/2019
Smoke Detector	Building G Electrical Room	Tested	5:27:02 PM	09/24/2019
Smoke Detector	Building G Electrical Room	Tested	5:27:54 PM	09/24/2019
Smoke Detector	Building G Wrestling Room	Tested	5:25:46 PM	09/24/2019
Smoke Detector	Building G Wrestling Room	Tested	5:26:00 PM	09/24/2019
Smoke Detector	Building G Wrestling Room	Tested	5:26:06 PM	09/24/2019
Smoke Detector	Building G Yoga Studio	Tested	5:23:02 PM	09/24/2019
Smoke Detector	Building H ASB Office	Tested	5:39:37 PM	09/24/2019
Smoke Detector	Building H ASB Storage	Tested/Cleaned	5:36:21 PM	09/24/2019
Smoke Detector	Building H Back ASB Office	Tested	5:38:53 PM	09/24/2019
Smoke Detector	Building H Classroom H701	Tested	6:04:46 PM	09/24/2019
Smoke Detector	Building H Classroom H701	Tested	6:05:05 PM	09/24/2019
Smoke Detector	Building H Classroom H701 Prep Room	Tested	6:05:47 PM	09/24/2019
Smoke Detector	Building H Classroom H703	Tested	6:06:17 PM	09/24/2019
Smoke Detector	Building H Classroom H703	Tested	6:06:27 PM	09/24/2019
Smoke Detector	Building H Classroom H705	Tested	6:07:17 PM	09/24/2019
Smoke Detector	Building H Classroom H705	Tested	6:07:37 PM	09/24/2019
Smoke Detector	Building H Classroom H705 Prep Room	Tested	6:08:03 PM	09/24/2019
	Building H Classroom H723	Tested	5:56:38 PM	09/24/2019
Smoke Detector				

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building H Classroom H724	Tested	5:56:20 PM	09/24/2019
Smoke Detector	Building H Classroom H724	Tested	5:56:31 PM	09/24/2019
Smoke Detector	Building H Classroom H725	Tested	5:54:44 PM	09/24/2019
Smoke Detector	Building H Classroom H725	Tested	5:55:04 PM	09/24/2019
Smoke Detector	Building H Classroom H726	Tested	5:53:49 PM	09/24/2019
Smoke Detector	Building H Classroom H726	Tested	5:54:00 PM	09/24/2019
Smoke Detector	Building H Classroom H728	Tested	5:51:47 PM	09/24/2019
Smoke Detector	Building H Classroom H728	Tested	5:51:55 PM	09/24/2019
Smoke Detector	Building H Classroom H729	Tested	5:50:45 PM	09/24/2019
Smoke Detector	Building H Classroom H729	Tested	5:51:01 PM	09/24/2019
Smoke Detector	Building H Classroom H730	Tested	5:49:49 PM	09/24/2019
Smoke Detector	Building H Classroom H730	Tested	5:50:00 PM	09/24/2019
Smoke Detector	Building H Classroom H731	Tested	5:48:16 PM	09/24/2019
Smoke Detector	Building H Classroom H731	Tested	5:48:41 PM	09/24/2019
Smoke Detector	Building H Conference Room	Tested	5:47:18 PM	09/24/2019
Smoke Detector	Building H Corridor Exit Near H726	Tested	5:59:15 PM	09/24/2019
Smoke Detector	Building H Custodian Near Men's Restroom	Tested	6:02:08 PM	09/24/2019
Smoke Detector	Building H Electrical	Tested	6:02:44 PM	09/24/2019
Smoke Detector	Building H Entrance	Tested	5:41:47 PM	09/24/2019
Smoke Detector	Building H Entrance Corridor	Tested	6:09:09 PM	09/24/2019
Smoke Detector	Building H Men's Restroom	Tested	6:01:23 PM	09/24/2019
Smoke Detector	Building H Office	Tested	5:42:29 PM	09/24/2019
Smoke Detector	Building H Restroom Near ASB	Tested	5:40:40 PM	09/24/2019
Smoke Detector	Building H Women's Restroom	Tested	6:03:30 PM	09/24/2019
Smoke Detector	Building J Library Behind Reception	Tested	4:21:33 PM	09/24/2019
Smoke Detector	Building J Library Lounge Area	Tested	4:30:26 PM	09/24/2019
Smoke Detector	Building J Library Lounge Area	Tested	4:30:56 PM	09/24/2019
Smoke Detector	Building J Library Office	Tested	4:28:11 PM	09/24/2019
Smoke Detector	Building J Library Over Reception	Tested	4:21:27 PM	09/24/2019
Smoke Detector	Building J Software Area	Tested	4:26:23 PM	09/24/2019
Smoke Detector	Building J Textbook Storage Room 125	Tested	4:18:45 PM	09/24/2019
Smoke Detector	Building K Theater Stage	Tested	4:37:38 PM	09/24/2019
Smoke Detector	Building K Theater Stage	Tested	4:38:07 PM	09/24/2019
Smoke Detector	Cafeteria North Exit	Tested	5:16:49 PM	09/24/2019
Smoke Detector	Cafeteria North Exit Men's Restroom	Tested	5:17:28 PM	09/24/2019
Smoke Detector	Cafeteria North Exit Men's Restroom	Tested	5:18:00 PM	09/24/2019
Smoke Detector	Cafeteria North Exit Men's Restroom Storage	Tested	5:22:03 PM	09/24/2019
Smoke Detector	Cafeteria North Exit Women's Restroom	Tested	5:18:19 PM	09/24/2019
Smoke Detector	Cafeteria North Exit Women's Restroom	Tested	5:18:36 PM	09/24/2019
Waterflow Switch	Building B Corridor By B250	Tested	5:38:37 PM	09/23/2019
Waterflow Switch	Cafeteria North Exit Riser	Tested	5:20:19 PM	09/24/2019
Device Type	Location	Service	Time	Date
	Failed/Other			Dutt
Control	T uneu/Other			
Control		Tested	E-44-30 DM	00/24/2010
Battery	Building H Office	Tested	5:44:26 PM	09/24/2019
Battery	Building H Office	Tested	5:44:59 PM	09/24/2019
Initiating				
Beam Detector	North Building F Boys Locker F529	Tested	6:05:55 PM	09/25/2019

Device Type	Location	Service	Time	Date
	Failed/Othe	r		
Beam Detector	North Building F Girls Shower/Locker	Tested	6:00:24 PM	09/25/2019
Beam Detector	South Building F Boys Locker F529	Tested	6:04:56 PM	09/25/2019
Beam Detector	Building F Filter Rm. F513	Tested	6:04:18 PM	09/25/2019
Beam Detector	Building F Issue F510	Tested	6:01:15 PM	09/25/2019
Beam Detector	Building F Laundry F520	Tested	6:06:33 PM	09/25/2019
Beam Detector	Building F Passage F524	Tested	6:06:16 PM	09/25/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Estancia High School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity				
Failed/Other						
Battery	Tested	2				
Beam Detector	Tested	7				
Total		9				
	Passed					
Annunciator	Tested	1				
Battery	Inspected	2				
Beam Detector	Tested	62				
Control Panel	Tested	1				
Power Supply	Tested	1				
Pull Station	Tested	23				
Smoke Detector	Tested	231				
Smoke Detector	Tested/Cleaned	2				
Waterflow Switch	Tested	2				
Total		334				

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Estancia High School Control Panel: 1 - SimplexGrinnell 4100U

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type		Category	% of Inventory	Quantity
Control Panel		Control	0.30%	1
Smoke Detector		Initiating	69.76%	233
Battery		Control	1.20%	4
Pull Station		Initiating	6.89%	23
Waterflow Switch		Initiating	0.60%	2
Annunciator		Control	0.30%	1
Power Supply		Control	0.30%	1
Beam Detector		Initiating	20.66%	69
	Qt			
Туре	y	Model #	Description	Install Date
		New	(under 90 days)	
Smoke Detector	51	4099-9001	· · · · ·	09/23/2019
Potter				
Waterflow Switch	1	VSR		09/23/2019
Simplex				
Annunciator	1			09/23/2019
Pull Station	17	4099-9001		09/23/2019
Smoke Detector	68	4099-9001		09/23/2019
SimplexGrinnell				
Control Panel	1	4100U		09/23/2019
		In Service	e - 3 Years to 5 Years	
Battery	2	12v75ah	Sealed Lead Acid	08/01/2015
Beam Detector	69			08/01/2015
SimplexGrinnell				
Pull Station	6	4099-9001		08/01/2015
Smoke Detector	11	4099-9001		08/01/2015
	4			
Waterflow Switch	1	4099-9001		08/01/2015
Battery	2	12V 7AH		03/23/2015
Power Supply	1	12V 7AH		03/23/2015

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Estancia High School 2323 Placentia Ave Costa Mesa, CA 92627

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Sep 24, 2019

> Building: NMUSD - Estancia High School Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: JD Torres Title: Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD – Estancia High School	Contact: Tim W	aller
Address: 2323 Placentia Ave	Phone: 949515	6970
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92627	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: JD To	orres
Address: 2903 Saturn Street	Phone: 909–34	8-3402
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: jdtorres@	<pre>@calbuildingsystems.com</pre>
System Control Unit		
Manufacturer: SimplexGrinnell	Inspection Date	:: 09/23/2019 IDC Style :
Model Number: 4100U	Install Date: 09	/23/2019 SLC Style:
Software Version:	Version Date: 0	9/23/2019 NAC Style:
Location: Admin Telcom Room A112	Current Protect	ion: Breaker
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
	Total Items		Serviced		Passed		Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Control	7	2.37%	7	100.00%	5	71.43%	2	28.57%
Initiating	288	97.63%	288	100.00%	288	100.00%	0	0%
Totals	295	100%	295	100.00%	293	99.32%	2	0.68%
Certification								
Company: Cal Building Systems			Bu	uilding: NMU	SD – Esta	ancia High S	School	
Inspector: JD Torres			Co	ontact: Tim \	Waller			
Signed:			Si	gned:				

Discrepancy Report Generated by: BuildingReports.com

Building: NMUSD - Estancia High School			Control Pane	l: 1 - Simp	lexGri	nnell	
Dunung. IV	MOSD - LS	4100U					
The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.							
Device Type		Manufacturer	ModelNumber	Dat	:e	Qty	
Items listed for Recall by Manufacturer							
		No recalled items found du	ring this inspection.				
8 ScanID	C Location		Problem	Address	🛄 Refe	erence	
Control							
Battery							
58094504 Building H Office				1			
58094505	Building H Offic	e		1			

Proposed Solutions Report

Generated by: BuildingReports.com

Building: NMUSD - Estancia High School Control Panel: 1 - SimplexGrinnell 4100U

The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.

ScanID	Location	Solution	Model #	Cost	Fix
		Control			
Battery					
58094504	Building H Office		12V 7AH	T/M	
58094505	Building H Office		12V 7AH	T/M	
			PO #: (none)	T/M	

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Estancia High School

Control Panel: 1 - SimplexGrinnell 4100U

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Building A Near Admin Front Entrance	Tested	4:10:53 PM	09/24/2019
Battery	Admin Telcom Room A112	Inspected	3:59:51 PM	09/23/2019
Battery	Admin Telcom Room A112	Inspected	4:01:23 PM	09/23/2019
Control Panel	Admin Telcom Room A112	Tested	3:50:41 PM	09/23/2019
Power Supply	Building H Office	Tested	5:45:37 PM	09/24/2019
Initiating				
Beam Detector	Admin Attendance A117	Tested	5:52:29 PM	09/24/2019
Beam Detector	Admin Lobby A100	Tested	5:57:58 PM	09/24/2019
Beam Detector	Building B Court B211	Tested	5:58:21 PM	09/24/2019
Beam Detector	Building B Court B239	Tested	5:59:20 PM	09/24/2019
Beam Detector	Building B Court B241	Tested	5:59:51 PM	09/24/2019
Beam Detector	Building B Court B273	Tested	6:02:00 PM	09/24/2019
Beam Detector	Building C Choral C376	Tested	6:15:45 PM	09/24/2019
Beam Detector	Building C Computer Lab C346	Tested	6:06:58 PM	09/24/2019
Beam Detector	Building C Corridor 331	Tested	6:08:13 PM	09/24/2019
Beam Detector	Building C Corridor C333	Tested	6:07:27 PM	09/24/2019
Beam Detector	Building C Corridor C334	Tested	6:06:07 PM	09/24/2019
Beam Detector	Building C Court C300	Tested	6:17:51 PM	09/24/2019
Beam Detector	Building C Court C307	Tested	6:19:31 PM	09/24/2019
Beam Detector	Building C Court C320	Tested	6:17:33 PM	09/24/2019
Beam Detector	Building C Court C321	Tested	6:18:03 PM	09/24/2019
Beam Detector	Building C Drafting C345	Tested	6:06:31 PM	09/24/2019
Beam Detector	Building C Electronics C342	Tested	6:07:47 PM	09/24/2019
Beam Detector	Building C Instrumental C363	Tested	6:09:18 PM	09/24/2019
Beam Detector	Building C Maintenance C350	Tested	6:08:58 PM	09/24/2019
Beam Detector	Building C Metal Shop C344	Tested	6:19:06 PM	09/24/2019
Beam Detector	Building C Weight Room C 343	Tested	6:18:18 PM	09/24/2019
Beam Detector	Building C Wood Shop C347	Tested	6:08:33 PM	09/24/2019
Beam Detector	Building H Court H743	Tested	6:19:51 PM	09/24/2019
Beam Detector	Building J Corridor B276	Tested	6:02:58 PM	09/24/2019
Beam Detector	Building J East Corridor By Building H	Tested	6:04:06 PM	09/24/2019
Beam Detector	Building J Reading Stacks	Tested	6:02:13 PM	09/24/2019
Beam Detector	Building J Reading Stacks	Tested	6:05:49 PM	09/24/2019
Beam Detector	Building J Study Area	Tested	6:03:51 PM	09/24/2019
Beam Detector	Building J Study Area North	Tested	6:02:36 PM	09/24/2019
Beam Detector	Between Building C And K	Tested	6:16:33 PM	09/24/2019
Pull Station	Building A Admin Near Attendance	Tested	3:53:30 PM	09/24/2019

Device Type	Location	Service	Time	Date
	Passed			
Pull Station	Building A Near Admin Front Entrance	Tested	4:09:27 PM	09/24/2019
Pull Station	Building B Corridor	Tested	4:37:42 PM	09/23/2019
Pull Station	Building B Corridor By B250	Tested	5:39:58 PM	09/23/2019
Pull Station	Building B Corridor Entrance	Tested	4:01:41 PM	09/23/2019
Pull Station	Building C Outside Corridor	Tested	6:04:50 PM	09/23/2019
Pull Station	Building C Weight Room	Tested	6:55:03 PM	09/23/2019
Pull Station	Building C Wood Shop	Tested	6:57:42 PM	09/23/2019
Pull Station	Building C Wood Shop	Tested	7:02:00 PM	09/23/2019
Pull Station	Building D Southwest Exit	Tested	5:02:13 PM	09/24/2019
Pull Station	Building G Gym	Tested	5:31:04 PM	09/24/2019
Pull Station	Building G Gym North Exit	Tested	5:32:02 PM	09/24/2019
Pull Station	Building G Gym North Exit	Tested	5:32:34 PM	09/24/2019
Pull Station	Building G Gym Southwest Exit	Tested	5:31:22 PM	09/24/2019
Pull Station	Building G North Exit	Tested	5:25:02 PM	09/24/2019
Pull Station	Building H Corridor	Tested	4:17:11 PM	09/24/2019
Pull Station	Building H Exit	Tested	5:53:23 PM	09/24/2019
Pull Station	Building J Library	Tested	4:23:21 PM	09/24/2019
Pull Station	Building K Theater East Exit	Tested	4:34:41 PM	09/24/2019
Pull Station	Building K Theater East Exit	Tested	4:35:17 PM	09/24/2019
Pull Station	Building K Theater West Exit	Tested	4:35:39 PM	09/24/2019
Pull Station	Building K Theater West Exit	Tested	4:36:59 PM	09/24/2019
Pull Station	Cafeteria North Exit	Tested	5:14:43 PM	09/24/2019
Smoke Detector	Admin Telecomm Room	Tested	3:53:38 PM	09/23/2019
Smoke Detector	Admin Telecomm Room	Tested	3:55:33 PM	09/23/2019
Smoke Detector	Building A Admin Assistant Office	Tested	4:12:23 PM	09/24/2019
Smoke Detector	Building A Admin Assistant Principals Office	Tested	4:04:48 PM	09/24/2019
Smoke Detector	Building A Admin Avid Office	Tested	3:57:29 PM	09/24/2019
Smoke Detector	Building A Admin Community Facilitators Office	Tested	3:59:30 PM	09/24/2019
Smoke Detector	Building A Admin Counselors Office	Tested	3:58:20 PM	09/24/2019
Smoke Detector	Building A Admin Counselors Office	Tested	4:00:54 PM	09/24/2019
Smoke Detector	Building A Admin Counselors Office	Tested	4:01:33 PM	09/24/2019
Smoke Detector	Building A Admin Near Counseling	Tested	3:52:01 PM	09/24/2019
Smoke Detector	Building A Admin Near Counseling	Tested	3:54:34 PM	09/24/2019
Smoke Detector	Building A Admin Near Nurses Office	Tested	3:51:39 PM	09/24/2019
Smoke Detector	Building A Admin Registrar	Tested	3:55:08 PM	09/24/2019
Smoke Detector	Building A Admin School Resource Officer	Tested	4:03:26 PM	09/24/2019
Smoke Detector	Building A Admin Social Workers Office	Tested	4:01:43 PM	09/24/2019
Smoke Detector	Building A Admin Storage	Tested	3:56:21 PM	09/24/2019
Smoke Detector	Building A Admin Workroom	Tested	4:04:04 PM	09/24/2019
Smoke Detector	Building A Assistant Principals Office	Tested	4:15:02 PM	09/24/2019
Smoke Detector	Building A Corridor Near Assistant Principals Office	Tested	4:05:23 PM	09/24/2019
Smoke Detector	Building A Corridor Near Principals Office	Tested	4:08:07 PM	09/24/2019
Smoke Detector	Building A Nurses Office	Tested	4:07:17 PM	09/24/2019
Smoke Detector	Building A Nurses Office	Tested	4:07:33 PM	09/24/2019
Smoke Detector	Building A Nurses Office Restroom	Tested	4:06:45 PM	09/24/2019
Smoke Detector	Building A Office Managers Office	Tested	4:11:51 PM	09/24/2019
Smoke Detector	Building A Principals Office	Tested	4:11:14 PM	09/24/2019
Smoke Detector	Building B Classroom 250	Tested	5:34:43 PM	09/23/2019

Device Type	Location	Service	Time	Date
	Passe	d		
Smoke Detector	Building B Classroom 251	Tested	5:32:21 PM	09/23/2019
Smoke Detector	Building B Classroom 251	Tested	5:32:39 PM	09/23/2019
Smoke Detector	Building B Classroom 252	Tested	5:30:30 PM	09/23/2019
Smoke Detector	Building B Classroom 252	Tested	5:30:49 PM	09/23/2019
Smoke Detector	Building B Classroom 253	Tested	5:28:05 PM	09/23/2019
Smoke Detector	Building B Classroom 253	Tested	5:29:34 PM	09/23/2019
Smoke Detector	Building B Classroom 263	Tested	5:55:16 PM	09/23/2019
Smoke Detector	Building B Classroom 264	Tested	5:56:10 PM	09/23/2019
Smoke Detector	Building B Classroom 264	Tested	5:57:48 PM	09/23/2019
Smoke Detector	Building B Classroom 265	Tested	5:58:13 PM	09/23/2019
Smoke Detector	Building B Classroom 265	Tested	5:59:28 PM	09/23/2019
Smoke Detector	Building B Classroom 266	Tested	5:42:52 PM	09/23/2019
Smoke Detector	Building B Classroom 266	Tested	5:43:37 PM	09/23/2019
Smoke Detector	Building B Classroom 267	Tested	5:45:28 PM	09/23/2019
Smoke Detector	Building B Classroom 267	Tested	5:45:51 PM	09/23/2019
Smoke Detector	Building B Classroom 267	Tested	5:46:23 PM	09/23/2019
Smoke Detector	Building B Classroom 267	Tested	5:46:40 PM	09/23/2019
Smoke Detector	Building B Classroom 268	Tested	5:47:55 PM	09/23/2019
Smoke Detector	Building B Classroom 268	Tested	5:48:18 PM	09/23/2019
Smoke Detector	Building B Classroom 269	Tested	5:49:53 PM	09/23/2019
Smoke Detector	Building B Classroom 269	Tested	5:50:24 PM	09/23/2019
Smoke Detector	Building B Classroom 270	Tested	5:51:24 PM	09/23/2019
Smoke Detector	Building B Classroom 270	Tested	5:51:40 PM	09/23/2019
Smoke Detector	Building B Classroom B203	Tested	4:28:38 PM	09/23/2019
Smoke Detector	Building B Classroom B204	Tested	4:29:25 PM	09/23/2019
Smoke Detector	Building B Classroom B207	Tested	4:35:40 PM	09/23/2019
Smoke Detector	Building B Classroom B207	Tested	4:36:21 PM	09/23/2019
Smoke Detector	Building B Classroom B207	Tested	4:37:21 PM	09/23/2019
Smoke Detector	Building B Classroom B208	Tested	4:35:09 PM	09/23/2019
Smoke Detector	Building B Classroom B209	Tested	4:33:14 PM	09/23/2019
Smoke Detector	Building B Classroom B209	Tested	4:33:40 PM	09/23/2019
Smoke Detector	Building B Classroom B210	Tested	4:31:33 PM	09/23/2019
Smoke Detector	Building B Classroom B210	Tested	4:32:03 PM	09/23/2019
Smoke Detector	Building B Classroom B223	Tested	4:54:10 PM	09/23/2019
Smoke Detector	Building B Classroom B223	Tested	4:54:45 PM	09/23/2019
Smoke Detector	Building B Classroom B224	Tested	4:52:25 PM	09/23/2019
Smoke Detector	Building B Classroom B224	Tested	4:52:41 PM	09/23/2019
Smoke Detector	Building B Classroom B225	Tested	4:50:53 PM	09/23/2019
Smoke Detector	Building B Classroom B225	Tested	4:51:03 PM	09/23/2019
Smoke Detector	Building B Classroom B226	Tested	4:44:28 PM	09/23/2019
Smoke Detector	Building B Classroom B226	Tested	4:45:21 PM	09/23/2019
Smoke Detector	Building B Classroom B227	Tested	4:46:46 PM	09/23/2019
Smoke Detector	Building B Classroom B227	Tested	4:47:12 PM	09/23/2019
Smoke Detector	Building B Classroom B228	Tested	4:48:14 PM	09/23/2019
Smoke Detector	Building B Classroom B228	Tested	4:49:32 PM	09/23/2019
Smoke Detector	Building B Classroom B229	Tested	5:02:23 PM	09/23/2019
Smoke Detector	Building B Classroom B229	Tested	5:03:34 PM	09/23/2019
Smoke Detector	Building B Classroom B231	Tested	4:58:55 PM	09/23/2019
Smoke Detector	Building B Classroom B231	Tested	4:59:13 PM	09/23/2019
Smoke Detector	Building B Classroom B231	Tested	4:59:40 PM	09/23/2019
		resteu		05/25/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building B Classroom B231	Tested	4:59:54 PM	09/23/2019
Smoke Detector	Building B Classroom B232	Tested	4:57:33 PM	09/23/2019
Smoke Detector	Building B Classroom B243	Tested	5:20:26 PM	09/23/2019
Smoke Detector	Building B Classroom B243	Tested	5:20:44 PM	09/23/2019
Smoke Detector	Building B Classroom B244	Tested	5:19:26 PM	09/23/2019
Smoke Detector	Building B Classroom B245	Tested	5:16:45 PM	09/23/2019
Smoke Detector	Building B Classroom B245	Tested	5:18:16 PM	09/23/2019
Smoke Detector	Building B Classroom B246	Tested	5:15:56 PM	09/23/2019
Smoke Detector	Building B Classroom B247	Tested	5:05:44 PM	09/23/2019
Smoke Detector	Building B Classroom B247	Tested	5:06:14 PM	09/23/2019
Smoke Detector	Building B Classroom B248	Tested	5:10:16 PM	09/23/2019
Smoke Detector	Building B Classroom B248	Tested	5:10:32 PM	09/23/2019
Smoke Detector	Building B Classroom B249	Tested	5:13:14 PM	09/23/2019
Smoke Detector	Building B Classroom B249	Tested	5:13:54 PM	09/23/2019
Smoke Detector	Building B Classroom B205	Tested	6:15:26 PM	09/24/2019
Smoke Detector	Building B Classroom B205	Tested	6:15:49 PM	09/24/2019
Smoke Detector	Building B Classroom B205	Tested	6:15:55 PM	09/24/2019
Smoke Detector	Building B Classroom B205	Tested	6:16:01 PM	09/24/2019
Smoke Detector	Building B Classroom B205	Tested	6:16:07 PM	09/24/2019
Smoke Detector	Building B Corridor	Tested	5:22:09 PM	09/23/2019
Smoke Detector	Building B Corridor By B207	Tested	4:41:53 PM	09/23/2019
Smoke Detector	Building B Corridor By B207	Tested	4:43:00 PM	09/23/2019
Smoke Detector	Building B Corridor By B226	Tested	4:43:20 PM	09/23/2019
Smoke Detector	Building B Corridor By B227	Tested	4:46:06 PM	09/23/2019
Smoke Detector	Building B Corridor By B228	Tested	4:49:59 PM	09/23/2019
Smoke Detector	Building B Corridor By B229	Tested	5:04:37 PM	09/23/2019
Smoke Detector	Building B Corridor By B247	Tested	5:04:18 PM	09/23/2019
Smoke Detector	Building B Corridor By B248	Tested	5:09:15 PM	09/23/2019
Smoke Detector	Building B Corridor By B250	Tested	5:33:53 PM	09/23/2019
Smoke Detector	Building B Corridor By B250	Tested	5:37:29 PM	09/23/2019
Smoke Detector	Building B Corridor By B250	Tested	5:41:55 PM	09/23/2019
Smoke Detector	Building B Corridor By B254	Tested	6:02:19 PM	09/23/2019
Smoke Detector	Building B Corridor By B254	Tested	6:03:08 PM	09/23/2019
Smoke Detector	Building B Corridor By B263	Tested	5:59:53 PM	09/23/2019
Smoke Detector	Building B Corridor By B263	Tested	6:00:44 PM	09/23/2019
Smoke Detector	Building B Entrance	Tested	4:25:20 PM	09/23/2019
Smoke Detector	Building B Entry Way	Tested	4:06:06 PM	09/23/2019
Smoke Detector	Building B Office B201	Tested	4:26:07 PM	09/23/2019
Smoke Detector	Building B Office B202	Tested	4:27:27 PM	09/23/2019
Smoke Detector	Building B Office By B232	Tested	4:56:30 PM	09/23/2019
Smoke Detector	Building B Office By B244	Tested	5:26:45 PM	09/23/2019
Smoke Detector	Building B Storage Room	Tested	5:22:46 PM	09/23/2019
Smoke Detector	Building B Storage Room	Tested	5:24:41 PM	09/23/2019
Smoke Detector	Building B Storage Room By B232	Tested	4:55:47 PM	09/23/2019
Smoke Detector	Building B Teachers Lounge	Tested	5:53:21 PM	09/23/2019
Smoke Detector	Building B Teachers Lounge	Tested	5:54:04 PM	09/23/2019
Smoke Detector	Building C Band Storage	Tested	6:46:19 PM	09/23/2019
Smoke Detector	Building C Cheer Room	Tested	4:59:30 PM	09/24/2019
Smoke Detector	Building C Cheer Room Office	Tested	5:00:28 PM	09/24/2019
				~~, _ , _ 0 , J

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building C Classroom C303	Tested	6:14:44 PM	09/23/2019
Smoke Detector	Building C Classroom 325	Tested	6:37:42 PM	09/23/2019
Smoke Detector	Building C Classroom 325	Tested	6:38:40 PM	09/23/2019
Smoke Detector	Building C Classroom 325 Storage	Tested	6:41:49 PM	09/23/2019
Smoke Detector	Building C Classroom C305	Tested	6:24:48 PM	09/23/2019
Smoke Detector	Building C Classroom C305	Tested	6:25:40 PM	09/23/2019
Smoke Detector	Building C Classroom C305	Tested	6:25:45 PM	09/23/2019
Smoke Detector	Building C Classroom C342	Tested	6:51:57 PM	09/23/2019
Smoke Detector	Building C Classroom C346	Tested	7:06:55 PM	09/23/2019
Smoke Detector	Building C Classroom C363 Brass & Woodwinds	Tested	4:53:39 PM	09/24/2019
	Room			
Smoke Detector	Building C Classroom C363 Office	Tested	4:51:09 PM	09/24/2019
Smoke Detector	Building C Classroom C363 Office	Tested	4:51:49 PM	09/24/2019
Smoke Detector	Building C Classroom C363 Office	Tested	4:51:57 PM	09/24/2019
Smoke Detector	Building C Classroom C363 Storage	Tested	4:52:52 PM	09/24/2019
Smoke Detector	Building C Classroom C363 Teachers Office	Tested	4:54:46 PM	09/24/2019
Smoke Detector	Building C Classroom C376	Tested	4:47:12 PM	09/24/2019
Smoke Detector	Building C Classroom C376 Office	Tested	4:49:16 PM	09/24/2019
Smoke Detector	Building C Classroom C376 Storage	Tested	4:50:15 PM	09/24/2019
Smoke Detector	Building C Corridor Entry	Tested	4:45:54 PM	09/24/2019
Smoke Detector	Building C Corridor Entry	Tested	4:46:12 PM	09/24/2019
Smoke Detector	Building C Entrance	Tested	4:43:02 PM	09/24/2019
Smoke Detector	Building C IT Office	Tested	6:47:43 PM	09/23/2019
Smoke Detector	Building C Janitor Room	Tested	6:42:43 PM	09/23/2019
Smoke Detector	Building C Janitor Room	Tested	6:44:24 PM	09/23/2019
Smoke Detector	Building C Office By 325	Tested	6:36:16 PM	09/23/2019
Smoke Detector	Building C Pottery	Tested	6:21:28 PM	09/23/2019
Smoke Detector	Building C Pottery	Tested	6:22:19 PM	09/23/2019
Smoke Detector	Building C Pottery	Tested	6:30:09 PM	09/23/2019
Smoke Detector	Building C Pottery	Tested	6:31:12 PM	09/23/2019
Smoke Detector	Building C Restroom	Tested	6:18:24 PM	09/23/2019
Smoke Detector	Building C Restroom	Tested	6:52:51 PM	09/23/2019
Smoke Detector	Building C Storage Room	Tested	6:16:38 PM	09/23/2019
Smoke Detector	Building C Storage Room	Tested	6:17:40 PM	09/23/2019
Smoke Detector	Building C Women's Restroom	Tested	6:33:08 PM	09/23/2019
Smoke Detector	Building D Athletic Office	Tested	5:12:03 PM	09/24/2019
Smoke Detector	Building D Athletic Office	Tested	5:12:45 PM	09/24/2019
Smoke Detector	Building D Athletic Office Entrance	Tested	5:10:16 PM	09/24/2019
Smoke Detector	Building D Athletic Office Restroom	Tested	5:11:23 PM	09/24/2019
Smoke Detector	Building D Athletic Office Restroom	Tested	5:13:19 PM	09/24/2019
Smoke Detector	Building D Athletic Office Restroom Corridor	Tested	5:10:51 PM	09/24/2019
Smoke Detector	Building D Faculty Serving Room	Tested	5:07:57 PM	09/24/2019
Smoke Detector	Building D Kitchen	Tested/Cleaned	5:03:48 PM	09/24/2019
Smoke Detector	Building D Kitchen Locker room	Tested	5:06:46 PM	09/24/2019
Smoke Detector	Building D Kitchen Locker Room Restroom	Tested	5:07:19 PM	09/24/2019
Smoke Detector	Building D Kitchen Storage	Tested	5:05:25 PM	09/24/2019
Smoke Detector	Building D Water Heater Room	Tested	5:09:09 PM	09/24/2019
Smoke Detector	Building G Corridor	Tested	5:24:29 PM	09/24/2019
Smoke Detector	Building G Corridor	Tested	5:24:45 PM	09/24/2019
Smoke Detector	Building G Electrical Room	Tested	5:27:02 PM	09/24/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building G Electrical Room	Tested	5:27:54 PM	09/24/2019
Smoke Detector	Building G Wrestling Room	Tested	5:25:46 PM	09/24/2019
Smoke Detector	Building G Wrestling Room	Tested	5:26:00 PM	09/24/2019
Smoke Detector	Building G Wrestling Room	Tested	5:26:06 PM	09/24/2019
Smoke Detector	Building G Yoga Studio	Tested	5:23:02 PM	09/24/2019
Smoke Detector	Building H ASB Office	Tested	5:39:37 PM	09/24/2019
Smoke Detector	Building H ASB Storage	Tested/Cleaned	5:36:21 PM	09/24/2019
Smoke Detector	Building H Back ASB Office	Tested	5:38:53 PM	09/24/2019
Smoke Detector	Building H Classroom H701	Tested	6:04:46 PM	09/24/2019
Smoke Detector	Building H Classroom H701	Tested	6:05:05 PM	09/24/2019
Smoke Detector	Building H Classroom H701 Prep Room	Tested	6:05:47 PM	09/24/2019
Smoke Detector	Building H Classroom H703	Tested	6:06:17 PM	09/24/2019
Smoke Detector	Building H Classroom H703	Tested	6:06:27 PM	09/24/2019
Smoke Detector	Building H Classroom H705	Tested	6:07:17 PM	09/24/2019
Smoke Detector	Building H Classroom H705	Tested	6:07:37 PM	09/24/2019
Smoke Detector	Building H Classroom H705 Prep Room	Tested	6:08:03 PM	09/24/2019
Smoke Detector	Building H Classroom H723	Tested	5:56:38 PM	09/24/2019
Smoke Detector	Building H Classroom H723	Tested	5:56:49 PM	09/24/2019
Smoke Detector	Building H Classroom H724	Tested	5:56:20 PM	09/24/2019
Smoke Detector	Building H Classroom H724	Tested	5:56:31 PM	09/24/2019
Smoke Detector	Building H Classroom H725	Tested	5:54:44 PM	09/24/2019
Smoke Detector	Building H Classroom H725	Tested	5:55:04 PM	09/24/2019
Smoke Detector	Building H Classroom H726	Tested	5:53:49 PM	09/24/2019
Smoke Detector	Building H Classroom H726	Tested	5:54:00 PM	09/24/2019
Smoke Detector	Building H Classroom H728	Tested	5:51:47 PM	09/24/2019
Smoke Detector	Building H Classroom H728	Tested	5:51:55 PM	09/24/2019
Smoke Detector	Building H Classroom H729	Tested	5:50:45 PM	09/24/2019
Smoke Detector	Building H Classroom H729	Tested	5:51:01 PM	09/24/2019
Smoke Detector	Building H Classroom H730	Tested	5:49:49 PM	09/24/2019
Smoke Detector	Building H Classroom H730	Tested	5:50:00 PM	09/24/2019
Smoke Detector	Building H Classroom H731	Tested	5:48:16 PM	09/24/2019
Smoke Detector	Building H Classroom H731	Tested	5:48:41 PM	09/24/2019
Smoke Detector	Building H Conference Room	Tested	5:47:18 PM	09/24/2019
Smoke Detector	Building H Corridor Exit Near H726	Tested	5:59:15 PM	09/24/2019
Smoke Detector	Building H Custodian Near Men's Restroom	Tested	6:02:08 PM	09/24/2019
Smoke Detector	Building H Electrical	Tested	6:02:44 PM	09/24/2019
Smoke Detector	Building H Entrance	Tested	5:41:47 PM	09/24/2019
Smoke Detector	Building H Entrance Corridor	Tested	6:09:09 PM	09/24/2019
Smoke Detector	Building H Men's Restroom	Tested	6:01:23 PM	09/24/2019
Smoke Detector	Building H Office	Tested	5:42:29 PM	09/24/2019
Smoke Detector	Building H Restroom Near ASB	Tested	5:40:40 PM	09/24/2019
Smoke Detector	Building H Women's Restroom	Tested	6:03:30 PM	09/24/2019
Smoke Detector	Building J Library Behind Reception	Tested	4:21:33 PM	09/24/2019
Smoke Detector	Building J Library Lounge Area	Tested	4:30:26 PM	09/24/2019
Smoke Detector	Building J Library Lounge Area	Tested	4:30:56 PM	09/24/2019
Smoke Detector	Building J Library Office	Tested	4:28:11 PM	09/24/2019
Smoke Detector	Building J Library Over Reception	Tested	4:21:27 PM	09/24/2019
Smoke Detector	Building J Software Area	Tested	4:26:23 PM	09/24/2019
Smoke Detector	Building J Textbook Storage Room 125	Tested	4:18:45 PM	09/24/2019
Smoke Detector	Building K Theater Stage	Tested	4:37:38 PM	09/24/2019

Device Type	Location	Service	Time	Date				
Passed								
Smoke Detector	Building K Theater Stage	Tested	4:38:07 PM	09/24/2019				
Smoke Detector	Cafeteria North Exit	Tested	5:16:49 PM	09/24/2019				
Smoke Detector	Cafeteria North Exit Men's Restroom	Tested	5:17:28 PM	09/24/2019				
Smoke Detector	Cafeteria North Exit Men's Restroom	Tested	5:18:00 PM	09/24/2019				
Smoke Detector	Cafeteria North Exit Men's Restroom Storage	Tested	5:22:03 PM	09/24/2019				
Smoke Detector	Cafeteria North Exit Women's Restroom	Tested	5:18:19 PM	09/24/2019				
Smoke Detector	Cafeteria North Exit Women's Restroom	Tested	5:18:36 PM	09/24/2019				
Waterflow Switch	Building B Corridor By B250	Tested	5:38:37 PM	09/23/2019				
Waterflow Switch	Cafeteria North Exit Riser	Tested	5:20:19 PM	09/24/2019				
Device Type	Location	Service	Time	Date				
	Failed/Other							
Control								
Battery	Building H Office	Tested	5:44:26 PM	09/24/2019				
Battery	Building H Office	Tested	5:44:59 PM	09/24/2019				

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Estancia High School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity				
Failed/Other						
Battery	Tested	2				
Total		2				
	Passed					
Annunciator	Tested	1				
Battery	Inspected	2				
Beam Detector	Tested	30				
Control Panel	Tested	1				
Power Supply	Tested	1				
Pull Station	Tested	23				
Smoke Detector	Tested	231				
Smoke Detector	Tested/Cleaned	2				
Waterflow Switch	Tested	2				
Total		295				

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Estancia High School Control Panel: 1 - SimplexGrinnell 4100U

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type		Category	% of Inventory	Quantity
Control Panel		Control	0.34%	1
Smoke Detector		Initiating	78.98%	233
Battery		Control	1.36%	4
Pull Station		Initiating	7.80%	23
Waterflow Switch		Initiating	0.68%	2
Annunciator		Control	0.34%	1
Power Supply		Control	0.34%	1
Beam Detector		Initiating	10.17%	30
	Qt			
Туре	y	Model #	Description	Install Date
		New	(under 90 days)	
Smoke Detector	51	4099-9001		09/23/2019
Potter				
Waterflow Switch	1	VSR		09/23/2019
Simplex				
Annunciator	1			09/23/2019
Pull Station	17	4099-9001		09/23/2019
Smoke Detector	68	4099-9001		09/23/2019
SimplexGrinnell				
Control Panel	1	4100U		09/23/2019
		In Service	e - 3 Years to 5 Years	
Battery	2	12v75ah	Sealed Lead Acid	08/01/2015
Beam Detector	30			08/01/2015
SimplexGrinnell				
Pull Station	6	4099-9001		08/01/2015
Smoke Detector	11	4099-9001		08/01/2015
	4			
Waterflow Switch	1	4099-9001		08/01/2015
Battery	2	12V 7AH		03/23/2015
Power Supply	1	12V 7AH		03/23/2015

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Estancia High School 2323 Placentia Ave Costa Mesa, CA 92627

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Sep 25, 2019

> Building: NMUSD - Estancia High School Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: JD Torres Title: Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD – Estancia High School	Contact: Tim W	aller
Address: 2323 Placentia Ave	Phone: 949515	6970
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92627	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: JD To	orres
Address: 2903 Saturn Street	Phone : 909–34	8-3402
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: jdtorres@	<pre>@calbuildingsystems.com</pre>
System Control Unit		
Manufacturer: SimplexGrinnell	Inspection Date	:: 09/23/2019 IDC Style :
Model Number: 4100U	Install Date: 09	/23/2019 SLC Style:
Software Version:	Version Date: 0	9/23/2019 NAC Style:
Location: Admin Telcom Room A112	Current Protect	ion: Breaker
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
6 .	Total	ltems	Ser	viced	Pa	ssed	Failed	/Other
Category	Qty	%	Qty	%	Qty	%	Qty	%
Control	10	2.92%	10	100.00%	8	80.00%	2	20.00%
Initiating	332	97.08%	332	100.00%	332	100.00%	0	0%
Totals	342	100%	342	100.00%	340	99.42%	2	0.58%
Certification								
Company: Cal Building Systems			Bu	uilding: NML	JSD – Esta	ancia High S	School	
Inspector: JD Torres			Co	ontact: Tim V	Waller			
Signed:			Si	gned:				

Discrepancy Report Generated by: BuildingReports.com

Building: NMUSD - Estancia High School			Control Pane	l: 1 - Simp	lexGri	nnell		
Dunung. IV	MOSD - LS	talicia mgil School	4100U					
The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.								
Device Type		Manufacturer	ModelNumber	Dat	:e	Qty		
Items listed for Recall by Manufacturer								
		No recalled items found du	ring this inspection.					
8 ScanID	C Location		Problem	Address	🛄 Refe	erence		
Control								
Battery								
58094504	Building H Offic	e		1				
58094505	Building H Offic	e		1				

Proposed Solutions Report

Generated by: BuildingReports.com

Building: NMUSD - Estancia High School Control Panel: 1 - SimplexGrinnell 4100U

The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.

ScanID	Location	Solution	Model #	Cost	Fix		
Control							
Battery							
58094504	Building H Office		12V 7AH	T/M			
58094505	Building H Office		12V 7AH	T/M			
			PO #: (none)	T/M			

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Estancia High School

Control Panel: 1 - SimplexGrinnell 4100U

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Building A Near Admin Front Entrance	Tested	4:10:53 PM	09/24/2019
Battery	Admin Telcom Room A112	Inspected	3:59:51 PM	09/23/2019
Battery	Admin Telcom Room A112	Inspected	4:01:23 PM	09/23/2019
Battery	Building G Electrical Room	Inspected	4:22:17 PM	09/25/2019
Battery	Building G Electrical Room	Inspected	4:23:59 PM	09/25/2019
Control Panel	Admin Telcom Room A112	Tested	3:50:41 PM	09/23/2019
Expander Panel	Building G Electrical Room	Tested	4:21:39 PM	09/25/2019
Power Supply	Building H Office	Tested	5:45:37 PM	09/24/2019
Initiating				
Beam Detector	Admin Attendance A117	Tested	5:52:29 PM	09/24/2019
Beam Detector	Admin Lobby A100	Tested	5:57:58 PM	09/24/2019
Beam Detector	Building B Court B211	Tested	5:58:21 PM	09/24/2019
Beam Detector	Building B Court B239	Tested	5:59:20 PM	09/24/2019
Beam Detector	Building B Court B241	Tested	5:59:51 PM	09/24/2019
Beam Detector	Building B Court B273	Tested	6:02:00 PM	09/24/2019
Beam Detector	Building C Choral C376	Tested	6:15:45 PM	09/24/2019
Beam Detector	Building C Computer Lab C346	Tested	6:06:58 PM	09/24/2019
Beam Detector	Building C Corridor 331	Tested	6:08:13 PM	09/24/2019
Beam Detector	Building C Corridor C333	Tested	6:07:27 PM	09/24/2019
Beam Detector	Building C Corridor C334	Tested	6:06:07 PM	09/24/2019
Beam Detector	Building C Court C300	Tested	6:17:51 PM	09/24/2019
Beam Detector	Building C Court C307	Tested	6:19:31 PM	09/24/2019
Beam Detector	Building C Court C320	Tested	6:17:33 PM	09/24/2019
Beam Detector	Building C Court C321	Tested	6:18:03 PM	09/24/2019
Beam Detector	Building C Drafting C345	Tested	6:06:31 PM	09/24/2019
Beam Detector	Building C Electronics C342	Tested	6:07:47 PM	09/24/2019
Beam Detector	Building C Instrumental C363	Tested	6:09:18 PM	09/24/2019
Beam Detector	Building C Maintenance C350	Tested	6:08:58 PM	09/24/2019
Beam Detector	Building C Metal Shop C344	Tested	6:19:06 PM	09/24/2019
Beam Detector	Building C Weight Room C 343	Tested	6:18:18 PM	09/24/2019
Beam Detector	Building C Wood Shop C347	Tested	6:08:33 PM	09/24/2019
Beam Detector	Building H Court H743	Tested	6:19:51 PM	09/24/2019
Beam Detector	Building J Corridor B276	Tested	6:02:58 PM	09/24/2019
Beam Detector	Building J East Corridor By Building H	Tested	6:04:06 PM	09/24/2019
Beam Detector	Building J Reading Stacks	Tested	6:02:13 PM	09/24/2019
Beam Detector	Building J Reading Stacks	Tested	6:05:49 PM	09/24/2019
Beam Detector	Building J Study Area	Tested	6:03:51 PM	09/24/2019

Device Type	Location	Service	Time	Date
	Passed			
Beam Detector	Building J Study Area North	Tested	6:02:36 PM	09/24/2019
Beam Detector	Between Building C And K	Tested	6:16:33 PM	09/24/2019
Heat Detector	Building C Court C320	Tested	5:47:02 PM	09/25/2019
Heat Detector	Building C Finishing C348	Tested	5:46:31 PM	09/25/2019
Heat Detector	Building C Foods C324	Tested	5:46:37 PM	09/25/2019
Heat Detector	Building C Foods C324	Tested	5:46:56 PM	09/25/2019
Heat Detector	Building C Homemaker C323	Tested	5:48:21 PM	09/25/2019
Heat Detector	Building C Homemaker C323 East	Tested	5:47:25 PM	09/25/2019
Heat Detector	Building C Metal Shop C344 Southeast	Tested	5:48:44 PM	09/25/2019
Heat Detector	Building C Metal Shop C344 Southeast	Tested	5:49:20 PM	09/25/2019
Heat Detector	Building D Alcove D400 North NR Pass D418	Tested	5:51:37 PM	09/25/2019
Heat Detector	Building D Alcove D404	Tested	5:51:04 PM	09/25/2019
Heat Detector	Building D Dishwash D407	Tested	5:53:41 PM	09/25/2019
Heat Detector	Building D Kitchen D400 Center	Tested	5:50:30 PM	09/25/2019
Heat Detector	Building D Kitchen D400 South	Tested	5:50:15 PM	09/25/2019
Heat Detector	Building D Kitchen D400 Southeast Exit	Tested	5:49:28 PM	09/25/2019
Heat Detector	Building F Dressing F504	Tested	5:55:03 PM	09/25/2019
Heat Detector	Building L Water Heater L103	Tested	5:56:20 PM	09/25/2019
Pull Station	Building A Admin Near Attendance	Tested	3:53:30 PM	09/24/2019
Pull Station	Building A Near Admin Front Entrance	Tested	4:09:27 PM	09/24/2019
Pull Station	Building B Corridor	Tested	4:37:42 PM	09/23/2019
Pull Station	Building B Corridor By B250	Tested	5:39:58 PM	09/23/2019
Pull Station	Building B Corridor Entrance	Tested	4:01:41 PM	09/23/2019
Pull Station	Building C Outside Corridor	Tested	6:04:50 PM	09/23/2019
Pull Station	Building C Weight Room	Tested	6:55:03 PM	09/23/2019
Pull Station	Building C Wood Shop	Tested	6:57:42 PM	09/23/2019
Pull Station	Building C Wood Shop	Tested	7:02:00 PM	09/23/2019
Pull Station	Building D Southwest Exit	Tested	5:02:13 PM	09/24/2019
Pull Station	Building G Gym	Tested	5:31:04 PM	09/24/2019
Pull Station	Building G Gym North Exit	Tested	5:32:02 PM	09/24/2019
Pull Station	Building G Gym North Exit	Tested	5:32:34 PM	09/24/2019
Pull Station	Building G Gym Southwest Exit	Tested	5:31:22 PM	09/24/2019
Pull Station	Building G North Exit	Tested	5:25:02 PM	09/24/2019
Pull Station	Building H Corridor	Tested	4:17:11 PM	09/24/2019
Pull Station	Building H Exit	Tested	5:53:23 PM	09/24/2019
Pull Station	Building J Library	Tested	4:23:21 PM	09/24/2019
Pull Station	Building K Theater East Exit	Tested	4:34:41 PM	09/24/2019
Pull Station	Building K Theater East Exit	Tested	4:35:17 PM	09/24/2019
Pull Station	Building K Theater West Exit	Tested	4:35:39 PM	09/24/2019
Pull Station	Building K Theater West Exit	Tested	4:36:59 PM	09/24/2019
Pull Station	Building L Gym North Exit	Tested	4:04:43 PM	09/25/2019
Pull Station	Building L Gym North Exit	Tested	4:09:09 PM	09/25/2019
Pull Station	Building L Gym South Exit	Tested	4:05:46 PM	09/25/2019
Pull Station	Building L Gym South Exit	Tested	4:06:42 PM	09/25/2019
Pull Station	Cafeteria North Exit	Tested	5:14:43 PM	09/24/2019
Smoke Detector	Admin Telecomm Room	Tested	3:53:38 PM	09/23/2019
Smoke Detector	Admin Telecomm Room	Tested	3:55:33 PM	09/23/2019
Smoke Detector	Building A Admin Assistant Office	Tested	4:12:23 PM	09/24/2019
Smoke Detector	Building A Admin Assistant Principals Office	Tested	4:04:48 PM	
SHICKE DELECTOR	bunding A Admin Assistant Thirdpais Office	resteu		09/24/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building A Admin Community Facilitators Office	e Tested	3:59:30 PM	09/24/2019
Smoke Detector	Building A Admin Counselors Office	Tested	3:58:20 PM	09/24/2019
Smoke Detector	Building A Admin Counselors Office	Tested	4:00:54 PM	09/24/2019
Smoke Detector	Building A Admin Counselors Office	Tested	4:01:33 PM	09/24/2019
Smoke Detector	Building A Admin Near Counseling	Tested	3:52:01 PM	09/24/2019
Smoke Detector	Building A Admin Near Counseling	Tested	3:54:34 PM	09/24/2019
Smoke Detector	Building A Admin Near Nurses Office	Tested	3:51:39 PM	09/24/2019
Smoke Detector	Building A Admin Registrar	Tested	3:55:08 PM	09/24/2019
Smoke Detector	Building A Admin School Resource Officer	Tested	4:03:26 PM	09/24/2019
Smoke Detector	Building A Admin Social Workers Office	Tested	4:01:43 PM	09/24/2019
Smoke Detector	Building A Admin Storage	Tested	3:56:21 PM	09/24/2019
Smoke Detector	Building A Admin Workroom	Tested	4:04:04 PM	09/24/2019
Smoke Detector	Building A Assistant Principals Office	Tested	4:15:02 PM	09/24/2019
Smoke Detector	Building A Corridor Near Assistant Principals	Tested	4:05:23 PM	09/24/2019
Smoke Detector	Office	lested		0372172013
Smoke Detector	Building A Corridor Near Principals Office	Tested	4:08:07 PM	09/24/2019
Smoke Detector	Building A Nurses Office	Tested	4:07:17 PM	09/24/2019
Smoke Detector	Building A Nurses Office	Tested	4:07:33 PM	09/24/2019
Smoke Detector	Building A Nurses Office Restroom	Tested	4:06:45 PM	09/24/2019
Smoke Detector	Building A Office Managers Office	Tested	4:11:51 PM	09/24/2019
Smoke Detector	Building A Principals Office	Tested	4:11:14 PM	09/24/2019
Smoke Detector	Building B Classroom 250	Tested	5:34:43 PM	09/23/2019
Smoke Detector	Building B Classroom 250	Tested	5:36:33 PM	09/23/2019
Smoke Detector	Building B Classroom 251	Tested	5:32:21 PM	09/23/2019
Smoke Detector	Building B Classroom 251	Tested	5:32:39 PM	09/23/2019
Smoke Detector	Building B Classroom 252	Tested	5:30:30 PM	09/23/2019
Smoke Detector	Building B Classroom 252	Tested	5:30:49 PM	09/23/2019
Smoke Detector	Building B Classroom 253	Tested	5:28:05 PM	09/23/2019
Smoke Detector	Building B Classroom 253	Tested	5:29:34 PM	09/23/2019
Smoke Detector	Building B Classroom 263	Tested	5:55:16 PM	09/23/2019
Smoke Detector	Building B Classroom 264	Tested	5:56:10 PM	09/23/2019
Smoke Detector	Building B Classroom 264	Tested	5:57:48 PM	09/23/2019
Smoke Detector	Building B Classroom 265	Tested	5:58:13 PM	09/23/2019
Smoke Detector	Building B Classroom 265	Tested	5:59:28 PM	09/23/2019
Smoke Detector	Building B Classroom 266	Tested	5:42:52 PM	09/23/2019
Smoke Detector	Building B Classroom 266	Tested	5:43:37 PM	09/23/2019
Smoke Detector	Building B Classroom 267	Tested	5:45:28 PM	09/23/2019
Smoke Detector	Building B Classroom 267	Tested	5:45:51 PM	09/23/2019
Smoke Detector	Building B Classroom 267	Tested	5:46:23 PM	09/23/2019
Smoke Detector	Building B Classroom 267	Tested	5:46:40 PM	09/23/2019
Smoke Detector	Building B Classroom 268	Tested	5:47:55 PM	09/23/2019
Smoke Detector	Building B Classroom 268	Tested	5:48:18 PM	09/23/2019
Smoke Detector	Building B Classroom 269	Tested	5:49:53 PM	09/23/2019
Smoke Detector	Building B Classroom 269	Tested	5:50:24 PM	09/23/2019
Smoke Detector	Building B Classroom 270	Tested	5:51:24 PM	09/23/2019
Smoke Detector	Building B Classroom 270	Tested	5:51:40 PM	09/23/2019
Smoke Detector	Building B Classroom B203	Tested	4:28:38 PM	09/23/2019
Smoke Detector	Building B Classroom B204	Tested	4:29:25 PM	09/23/2019
Smoke Detector	Building B Classroom B207	Tested	4:35:40 PM	09/23/2019

Device Type	Location	Service	Time	Date
	Passe	d		
Smoke Detector	Building B Classroom B207	Tested	4:37:21 PM	09/23/2019
Smoke Detector	Building B Classroom B208	Tested	4:35:09 PM	09/23/2019
Smoke Detector	Building B Classroom B209	Tested	4:33:14 PM	09/23/2019
Smoke Detector	Building B Classroom B209	Tested	4:33:40 PM	09/23/2019
Smoke Detector	Building B Classroom B210	Tested	4:31:33 PM	09/23/2019
Smoke Detector	Building B Classroom B210	Tested	4:32:03 PM	09/23/2019
Smoke Detector	Building B Classroom B223	Tested	4:54:10 PM	09/23/2019
Smoke Detector	Building B Classroom B223	Tested	4:54:45 PM	09/23/2019
Smoke Detector	Building B Classroom B224	Tested	4:52:25 PM	09/23/2019
Smoke Detector	Building B Classroom B224	Tested	4:52:41 PM	09/23/2019
Smoke Detector	Building B Classroom B225	Tested	4:50:53 PM	09/23/2019
Smoke Detector	Building B Classroom B225	Tested	4:51:03 PM	09/23/2019
Smoke Detector	Building B Classroom B226	Tested	4:44:28 PM	09/23/2019
Smoke Detector	Building B Classroom B226	Tested	4:45:21 PM	09/23/2019
Smoke Detector	Building B Classroom B227	Tested	4:46:46 PM	09/23/2019
Smoke Detector	Building B Classroom B227	Tested	4:47:12 PM	09/23/2019
Smoke Detector	Building B Classroom B228	Tested	4:48:14 PM	09/23/2019
Smoke Detector	Building B Classroom B228	Tested	4:49:32 PM	09/23/2019
Smoke Detector	Building B Classroom B229	Tested	5:02:23 PM	09/23/2019
Smoke Detector	Building B Classroom B229	Tested	5:03:34 PM	09/23/2019
Smoke Detector	Building B Classroom B231	Tested	4:58:55 PM	09/23/2019
Smoke Detector	Building B Classroom B231	Tested	4:59:13 PM	09/23/2019
Smoke Detector	Building B Classroom B231	Tested	4:59:40 PM	09/23/2019
Smoke Detector	Building B Classroom B231	Tested	4:59:54 PM	09/23/2019
Smoke Detector	Building B Classroom B232	Tested	4:57:33 PM	09/23/2019
Smoke Detector	Building B Classroom B243	Tested	5:20:26 PM	09/23/2019
Smoke Detector	Building B Classroom B243	Tested	5:20:44 PM	09/23/2019
Smoke Detector	Building B Classroom B244	Tested	5:19:26 PM	09/23/2019
Smoke Detector	Building B Classroom B245	Tested	5:16:45 PM	09/23/2019
Smoke Detector	Building B Classroom B245	Tested	5:18:16 PM	09/23/2019
Smoke Detector	Building B Classroom B246	Tested	5:15:56 PM	09/23/2019
Smoke Detector	Building B Classroom B247	Tested	5:05:44 PM	09/23/2019
Smoke Detector	Building B Classroom B247	Tested	5:06:14 PM	09/23/2019
Smoke Detector	Building B Classroom B248	Tested	5:10:16 PM	09/23/2019
Smoke Detector	Building B Classroom B248	Tested	5:10:32 PM	09/23/2019
Smoke Detector	Building B Classroom B249	Tested	5:13:14 PM	09/23/2019
Smoke Detector	Building B Classroom B249	Tested	5:13:54 PM	09/23/2019
Smoke Detector	Building B Classroom B205	Tested	6:15:26 PM	09/24/2019
Smoke Detector	Building B Classroom B205	Tested	6:15:49 PM	09/24/2019
Smoke Detector	Building B Classroom B205	Tested	6:15:55 PM	09/24/2019
Smoke Detector	Building B Classroom B205	Tested	6:16:01 PM	09/24/2019
Smoke Detector	Building B Classroom B205	Tested	6:16:07 PM	09/24/2019
Smoke Detector	Building B Corridor	Tested	5:22:09 PM	09/23/2019
Smoke Detector	Building B Corridor By B207	Tested	4:41:53 PM	09/23/2019
Smoke Detector	Building B Corridor By B207	Tested	4:43:00 PM	09/23/2019
Smoke Detector	Building B Corridor By B226	Tested	4:43:20 PM	09/23/2019
Smoke Detector	Building B Corridor By B227	Tested	4:46:06 PM	09/23/2019
Smoke Detector	Building B Corridor By B228	Tested	4:49:59 PM	09/23/2019
Smoke Detector	Building B Corridor By B229	Tested	5:04:37 PM	09/23/2019
Smoke Detector	Building B Corridor By B247	Tested	5:04:18 PM	09/23/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building B Corridor By B248	Tested	5:09:15 PM	09/23/2019
Smoke Detector	Building B Corridor By B250	Tested	5:33:53 PM	09/23/2019
Smoke Detector	Building B Corridor By B250 Building B Corridor By B250	Tested	5:37:29 PM	09/23/2019
Smoke Detector	Building B Corridor By B250 Building B Corridor By B250	Tested	5:41:55 PM	09/23/2019
Smoke Detector	Building B Corridor By B250 Building B Corridor By B254	Tested	6:02:19 PM	09/23/2019
Smoke Detector	Building B Corridor By B254 Building B Corridor By B254	Tested	6:03:08 PM	09/23/2019
Smoke Detector	Building B Corridor By B254 Building B Corridor By B263	Tested	5:59:53 PM	09/23/2019
Smoke Detector	Building B Corridor By B203 Building B Corridor By B263	Tested	6:00:44 PM	09/23/2019
Smoke Detector	Building B Entrance	Tested	4:25:20 PM	09/23/2019
Smoke Detector	Building B Entry Way	Tested	4:06:06 PM	09/23/2019
Smoke Detector		Tested	4:26:07 PM	
Smoke Detector	Building B Office B201	Tested	4:27:27 PM	09/23/2019
	Building B Office B202	Tested	4:56:30 PM	09/23/2019
Smoke Detector	Building B Office By B232		5:26:45 PM	09/23/2019
Smoke Detector	Building B Office By B244	Tested	5:22:46 PM	09/23/2019
Smoke Detector	Building B Storage Room	Tested	5:22:40 PM	09/23/2019
Smoke Detector	Building B Storage Room	Tested	4:55:47 PM	09/23/2019
Smoke Detector	Building B Storage Room By B232	Tested	5:53:21 PM	09/23/2019
Smoke Detector	Building B Teachers Lounge	Tested		09/23/2019
Smoke Detector	Building B Teachers Lounge	Tested	5:54:04 PM	09/23/2019
Smoke Detector	Building C Band Storage	Tested	6:46:19 PM	09/23/2019
Smoke Detector	Building C Cheer Room	Tested	4:59:30 PM	09/24/2019
Smoke Detector	Building C Cheer Room Office	Tested	5:00:28 PM	09/24/2019
Smoke Detector	Building C Choral/Library	Tested	4:46:33 PM	09/24/2019
Smoke Detector	Building C Classroom C303	Tested	6:14:44 PM	09/23/2019
Smoke Detector	Building C Classroom 325	Tested	6:37:42 PM	09/23/2019
Smoke Detector	Building C Classroom 325	Tested	6:38:40 PM	09/23/2019
Smoke Detector	Building C Classroom 325 Storage	Tested	6:41:49 PM	09/23/2019
Smoke Detector	Building C Classroom C305	Tested	6:24:48 PM	09/23/2019
Smoke Detector	Building C Classroom C305	Tested	6:25:40 PM	09/23/2019
Smoke Detector	Building C Classroom C305	Tested	6:25:45 PM	09/23/2019
Smoke Detector	Building C Classroom C342	Tested	6:51:57 PM	09/23/2019
Smoke Detector	Building C Classroom C346	Tested	7:06:55 PM	09/23/2019
Smoke Detector	Building C Classroom C363 Brass & Woodwinds	Tested	4:53:39 PM	09/24/2019
	Room			
Smoke Detector	Building C Classroom C363 Office	Tested	4:51:09 PM	09/24/2019
Smoke Detector	Building C Classroom C363 Office	Tested	4:51:49 PM	09/24/2019
Smoke Detector	Building C Classroom C363 Office	Tested	4:51:57 PM	09/24/2019
Smoke Detector	Building C Classroom C363 Storage	Tested	4:52:52 PM	09/24/2019
Smoke Detector	Building C Classroom C363 Teachers Office	Tested	4:54:46 PM	09/24/2019
Smoke Detector	Building C Classroom C376	Tested	4:47:12 PM	09/24/2019
Smoke Detector	Building C Classroom C376 Office	Tested	4:49:16 PM	09/24/2019
Smoke Detector	Building C Classroom C376 Storage	Tested	4:50:15 PM	09/24/2019
Smoke Detector	Building C Corridor Entry	Tested	4:45:54 PM	09/24/2019
Smoke Detector	Building C Corridor Entry	Tested	4:46:12 PM	09/24/2019
Smoke Detector	Building C Entrance	Tested	4:43:02 PM	09/24/2019
Smoke Detector	Building C IT Office	Tested	6:47:43 PM	09/23/2019
Smoke Detector	Building C Janitor Room	Tested	6:42:43 PM	09/23/2019
Smoke Detector	Building C Janitor Room	Tested	6:44:24 PM	09/23/2019
Smoke Detector	Building C Office By 325	Tested	6:36:16 PM	09/23/2019
Smoke Detector	Building C Pottery	Tested	6:21:28 PM	09/23/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building C Pottery	Tested	6:22:19 PM	09/23/2019
Smoke Detector	Building C Pottery	Tested	6:30:09 PM	09/23/2019
Smoke Detector	Building C Pottery	Tested	6:31:12 PM	09/23/2019
Smoke Detector	Building C Restroom	Tested	6:18:24 PM	09/23/2019
Smoke Detector	Building C Restroom	Tested	6:52:51 PM	09/23/2019
Smoke Detector	Building C Storage Room	Tested	6:16:38 PM	09/23/2019
Smoke Detector	Building C Storage Room	Tested	6:17:40 PM	09/23/2019
Smoke Detector	Building C Women's Restroom	Tested	6:33:08 PM	09/23/2019
Smoke Detector	Building D Athletic Office	Tested	5:12:03 PM	09/24/2019
Smoke Detector	Building D Athletic Office	Tested	5:12:45 PM	09/24/2019
Smoke Detector	Building D Athletic Office Entrance	Tested	5:10:16 PM	09/24/2019
Smoke Detector	Building D Athletic Office Restroom	Tested	5:11:23 PM	09/24/2019
Smoke Detector	Building D Athletic Office Restroom	Tested	5:13:19 PM	09/24/2019
Smoke Detector	Building D Athletic Office Restroom Corridor	Tested	5:10:51 PM	09/24/2019
Smoke Detector	Building D Faculty Serving Room	Tested	5:07:57 PM	09/24/2019
Smoke Detector	Building D Kitchen	Tested/Cleaned	5:03:48 PM	09/24/2019
Smoke Detector	Building D Kitchen Locker room	Tested	5:06:46 PM	09/24/2019
Smoke Detector	Building D Kitchen Locker Room Restroom	Tested	5:07:19 PM	09/24/2019
Smoke Detector	Building D Kitchen Storage	Tested	5:05:25 PM	09/24/2019
Smoke Detector	Building D Water Heater Room	Tested	5:09:09 PM	09/24/2019
Smoke Detector	Building G Corridor	Tested	5:24:29 PM	09/24/2019
Smoke Detector	Building G Corridor	Tested	5:24:45 PM	09/24/2019
Smoke Detector	Building G Electrical Room	Tested	5:27:02 PM	09/24/2019
Smoke Detector	Building G Electrical Room	Tested	4:20:47 PM	09/25/2019
Smoke Detector	Building G Wrestling Room	Tested	5:25:46 PM	09/24/2019
Smoke Detector	Building G Wrestling Room	Tested	5:26:00 PM	09/24/2019
Smoke Detector	Building G Wrestling Room	Tested	5:26:06 PM	09/24/2019
Smoke Detector	Building G Yoga Studio	Tested	5:23:02 PM	09/24/2019
Smoke Detector	Building H ASB Office	Tested	5:39:37 PM	09/24/2019
Smoke Detector	Building H ASB Storage	Tested/Cleaned	5:36:21 PM	09/24/2019
Smoke Detector	Building H Back ASB Office	Tested	5:38:53 PM	09/24/2019
Smoke Detector	Building H Classroom H701	Tested	6:04:46 PM	09/24/2019
Smoke Detector	Building H Classroom H701	Tested	6:05:05 PM	09/24/2019
Smoke Detector	Building H Classroom H701 Prep Room	Tested	6:05:47 PM	09/24/2019
Smoke Detector	Building H Classroom H702	Tested	3:57:56 PM	09/25/2019
Smoke Detector	Building H Classroom H702	Tested	3:58:08 PM	09/25/2019
Smoke Detector	Building H Classroom H703	Tested	6:06:17 PM	09/24/2019
Smoke Detector	Building H Classroom H703	Tested	6:06:27 PM	09/24/2019
Smoke Detector	Building H Classroom H704	Tested	3:56:11 PM	09/25/2019
Smoke Detector	Building H Classroom H704	Tested	3:56:22 PM	09/25/2019
Smoke Detector	Building H Classroom H704 Prep Room	Tested	3:57:35 PM	09/25/2019
Smoke Detector	Building H Classroom H705	Tested	6:07:17 PM	09/24/2019
Smoke Detector	Building H Classroom H705	Tested	6:07:37 PM	09/24/2019
Smoke Detector	Building H Classroom H705 Prep Room	Tested	6:08:03 PM	09/24/2019
Smoke Detector	Building H Classroom H706	Tested	3:54:31 PM	09/25/2019
Smoke Detector	Building H Classroom H706	Tested	3:54:48 PM	09/25/2019
Smoke Detector	Building H Classroom H707	Tested	3:49:07 PM	09/25/2019
Smoke Detector	Building H Classroom H707	Tested	3:49:32 PM	09/25/2019
Smoke Detector	Building H Classroom H708	Tested	3:53:00 PM	09/25/2019
Smoke Detector	Building H Classroom H708	Tested	3:53:26 PM	09/25/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building H Classroom H708 Prep Room	Tested	3:53:58 PM	09/25/2019
Smoke Detector	Building H Classroom H723	Tested	5:56:38 PM	09/24/2019
Smoke Detector	Building H Classroom H723	Tested	5:56:49 PM	09/24/2019
Smoke Detector	Building H Classroom H724	Tested	5:56:20 PM	09/24/2019
Smoke Detector	Building H Classroom H724	Tested	5:56:31 PM	09/24/2019
Smoke Detector	Building H Classroom H725	Tested	5:54:44 PM	09/24/2019
Smoke Detector	Building H Classroom H725	Tested	5:55:04 PM	09/24/2019
Smoke Detector	Building H Classroom H726	Tested	5:53:49 PM	09/24/2019
Smoke Detector	Building H Classroom H726	Tested	5:54:00 PM	09/24/2019
Smoke Detector	Building H Classroom H728	Tested	5:51:47 PM	09/24/2019
Smoke Detector	Building H Classroom H728	Tested	5:51:55 PM	09/24/2019
Smoke Detector	Building H Classroom H729	Tested	5:50:45 PM	09/24/2019
Smoke Detector	Building H Classroom H729	Tested	5:51:01 PM	09/24/2019
Smoke Detector	Building H Classroom H730	Tested	5:49:49 PM	09/24/2019
Smoke Detector	Building H Classroom H730	Tested	5:50:00 PM	09/24/2019
Smoke Detector	Building H Classroom H731	Tested	5:48:16 PM	09/24/2019
Smoke Detector	Building H Classroom H731	Tested	5:48:41 PM	09/24/2019
Smoke Detector	Building H Conference Room	Tested	5:47:18 PM	09/24/2019
Smoke Detector	Building H Corridor By Classroom H704	Tested	3:36:17 PM	09/25/2019
Smoke Detector	Building H Corridor By Classroom H706	Tested	3:37:38 PM	09/25/2019
Smoke Detector	Building H Corridor By Classroom H708	Tested	3:52:02 PM	09/25/2019
Smoke Detector	Building H Corridor Exit Near H726	Tested	5:59:15 PM	09/24/2019
Smoke Detector	Building H Custodian Near Men's Restroom	Tested	6:02:08 PM	09/24/2019
Smoke Detector	Building H Electrical	Tested	6:02:44 PM	09/24/2019
Smoke Detector	Building H Entrance	Tested	5:41:47 PM	09/24/2019
Smoke Detector	Building H Entrance Corridor	Tested	3:34:45 PM	09/25/2019
Smoke Detector	Building H Men's Restroom	Tested	6:01:23 PM	09/24/2019
Smoke Detector	Building H Office	Tested	5:42:29 PM	09/24/2019
Smoke Detector	Building H Restroom Near ASB	Tested	5:40:40 PM	09/24/2019
Smoke Detector	Building H Women's Restroom	Tested	6:03:30 PM	09/24/2019
Smoke Detector	Building J Library Behind Reception	Tested	4:21:33 PM	09/24/2019
Smoke Detector	Building J Library Lounge Area	Tested	4:30:26 PM	09/24/2019
Smoke Detector	Building J Library Lounge Area	Tested	4:30:56 PM	09/24/2019
Smoke Detector	Building J Library Office	Tested	4:28:11 PM	09/24/2019
Smoke Detector	Building J Library Over Reception	Tested	4:21:27 PM	09/24/2019
Smoke Detector	Building J Software Area	Tested	4:26:23 PM	09/24/2019
Smoke Detector	Building J Textbook Storage Room 125	Tested	4:18:45 PM	09/24/2019
Smoke Detector	Building K Theater Stage	Tested	4:37:38 PM	09/24/2019
Smoke Detector	Building K Theater Stage	Tested	4:38:07 PM	09/24/2019
Smoke Detector	Building L Corridor By Restrooms	Tested	4:34:00 PM	09/25/2019
Smoke Detector	Building L Custodian Storage	Tested	4:08:30 PM	09/25/2019
Smoke Detector	Building L Locker Room L102	Tested	4:30:06 PM	09/25/2019
Smoke Detector	Building L Locker Room L102	Tested	4:30:47 PM	09/25/2019
Smoke Detector	Building L Men's Restroom	Tested	4:09:35 PM	09/25/2019
Smoke Detector	Building L Men's Restroom	Tested	4:09:54 PM	09/25/2019
Smoke Detector	Building L Training Room	Tested	4:35:18 PM	09/25/2019
Smoke Detector	Cafeteria North Exit	Tested	4:26:33 PM	09/25/2019
Smoke Detector	Cafeteria North Exit Men's Restroom	Tested	5:17:28 PM	09/24/2019
Smoke Detector	Cafeteria North Exit Men's Restroom	Tested	5:18:00 PM	09/24/2019
Smoke Detector	Cafeteria North Exit Men's Restroom Storage	Tested	5:22:03 PM	09/24/2019

Device Type	Location	Service	Time	Date			
Passed							
Smoke Detector	Cafeteria North Exit Riser	Tested	4:24:52 PM	09/25/2019			
Smoke Detector	Cafeteria North Exit Women's Restroom	Tested	5:18:19 PM	09/24/2019			
Smoke Detector	Cafeteria North Exit Women's Restroom	Tested	5:18:36 PM	09/24/2019			
Waterflow Switch	Building B Corridor By B250	Tested	5:38:37 PM	09/23/2019			
Waterflow Switch	Building C Chiller Room C310 South	Tested	5:39:45 PM	09/25/2019			
Waterflow Switch	Cafeteria North Exit Riser	Tested	4:24:04 PM	09/25/2019			
Device Type	Location	Service	Time	Date			
	Failed/Other	•					
Control							
Battery	Building H Office	Tested	5:44:26 PM	09/24/2019			
Battery	Building H Office	Tested	5:44:59 PM	09/24/2019			

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Estancia High School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Failed/Other	
Battery	Tested	2
Total		2
	Passed	
Annunciator	Tested	1
Battery	Inspected	4
Beam Detector	Tested	30
Control Panel	Tested	1
Expander Panel	Tested	1
Heat Detector	Tested	16
Power Supply	Tested	1
Pull Station	Tested	27
Smoke Detector	Tested	254
Smoke Detector	Tested/Cleaned	2
Waterflow Switch	Tested	3
Total		342

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Estancia High School Control Panel: 1 - SimplexGrinnell 4100U

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type		Category	% of Inventory	Quantity
Control Panel		Control	0.29%	1
Smoke Detector		Initiating	74.85%	256
Battery		Control	1.75%	6
Pull Station		Initiating	7.89%	27
Waterflow Switch		Initiating	0.88%	3
Annunciator		Control	0.29%	1
Power Supply		Control	0.29%	1
Beam Detector		Initiating	8.77%	30
Expander Panel		Control	0.29%	1
Heat Detector		Initiating	4.68%	16
	Qt			
Туре	y	Model #	Description	Install Date
		New	(under 90 days)	
Smoke Detector	51	4099-9001		09/23/2019
	51	1000 2001		05/25/2015
Potter				
Waterflow Switch	1	VSR		09/23/2019
Simplex				
Annunciator	1			09/23/2019
Expander Panel	1			09/23/2019
Heat Detector	16	4099-9403	Fixed Temperature	09/23/2019
Pull Station	21	4099-9001		09/23/2019
Smoke Detector	90	4099-9001		09/23/2019
SimplexGrinnell				
Control Panel	1	4100U		09/23/2019
Smoke Detector	1	4099-9001		09/23/2019
Shloke Detector			2 V 1 2 V	
		In Service	e - 2 Years to 3 Years	
Simplex				
Battery	2		Sealed Lead Acid	07/01/2017
		In Service	e - 3 Years to 5 Years	
Battery	2	12v75ah	Sealed Lead Acid	08/01/2015
Beam Detector	30			08/01/2015
Potter Electric				
Waterflow Switch	2	VSR		08/01/2015
SimplexGrinnell				, - ,
-	e	4000 0001		00/01/2015
Pull Station	6	4099-9001		08/01/2015
Smoke Detector	11	4099-9001		08/01/2015

10/03/2019

	4		
_	-		
Battery	2	12V 7AH	03/23/2015
Power Supply	1	12V 7AH	03/23/2015

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Harbor View Elementary 900 Goldenrod Ave Corona Del Mar, CA 92625

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Aug 29, 2019

> Building: NMUSD - Harbor View Elementary Contact: Tim Waller Title: Contact

Company: Cal Building Systems Contact: Chris Ferreira Title: Service

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD - Harbor View Elementary	Contact: Tim W	aller
Address: 900 Goldenrod Ave	Phone: 714–23	1-0363
Address:	Fax:	
City/State/Zip: Corona Del Mar, CA 92625	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Chris	5 Ferreira
Address: 2903 Saturn Street	Phone: 714–99	3-9650
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: chrisferr	eira@calbuildingsystems.com
System Control Unit		
Manufacturer: Simplex	Inspection Date	:: 08/29/2019 IDC Style :
Model Number: 4100	Install Date: 08	/29/2019 SLC Style:
Software Version:	Version Date: 0	8/29/2019 NAC Style:
Location: Admin By Principal Office	Current Protect	ion:
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
6	Total Items		Serviced		Passed		Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Control	10	9.90%	10	100.00%	10	100.00%	0	0%
Initiating	91	90.10%	91	100.00%	91	100.00%	0	0%
Totals	101	100%	101	100.00%	101	100.00%	0	0%
Certification								
Company: Cal Building Systems			Bu	ilding: NML	JSD – Har	bor View El	ementary	
Inspector: Chris Ferreira			Co	ontact: Tim	Waller			
Signed:			Sig	gned:				

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Harbor View Elementary Control Panel: 1 - Simplex 4100

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Admin By Entrance	Tested	7:34:58 AM	08/29/2019
Battery	Admin FACP	Tested	7:33:24 AM	08/29/2019
Battery	Admin FACP	Tested	7:34:02 AM	08/29/2019
Battery	Building C Janitor Closet	Tested	8:52:18 AM	08/29/2019
Battery	Building C Janitor Closet	Tested	8:53:01 AM	08/29/2019
Battery	Building D Electrical Room	Tested	8:11:49 AM	08/29/2019
Battery	Building D Electrical Room	Tested	8:12:26 AM	08/29/2019
Control Panel	Admin By Principal Office	Tested	7:32:42 AM	08/29/2019
Power Supply	Building C Janitor Closet	Tested	8:51:46 AM	08/29/2019
Power Supply	Building D Electrical Room	Tested	8:11:10 AM	08/29/2019
Initiating				
Heat Detector	Admin By Principal Office	Tested	7:38:04 AM	08/29/2019
Heat Detector	Admin H3 – Nurse Restroom	Tested	7:44:02 AM	08/29/2019
Heat Detector	Admin Teachers Lounge	Tested	7:46:30 AM	08/29/2019
Heat Detector	Admin Entrance	Tested	7:27:37 AM	08/29/2019
Heat Detector	Building A Boys Restroom	Tested	8:09:40 AM	08/29/2019
Heat Detector	Building A Girls Restroom	Tested	8:07:59 AM	08/29/2019
Heat Detector	Building A Janitor Closet	Tested	8:09:08 AM	08/29/2019
Heat Detector	Building C Boys Restroom	Tested	8:55:08 AM	08/29/2019
Heat Detector	Building C Girls Restroom	Tested	8:55:29 AM	08/29/2019
Heat Detector	Building C Janitor Closet	Tested	8:50:47 AM	08/29/2019
Heat Detector	Building D Electrical Room	Tested	8:10:34 AM	08/29/2019
Heat Detector	Building D Supply Room	Tested	8:03:09 AM	08/29/2019
Heat Detector	Building J Classroom 25 Restroom	Tested	9:11:30 AM	08/29/2019
Heat Detector	Building J Classroom 25 Restroom	Tested	9:12:09 AM	08/29/2019
Heat Detector	Portables Classroom 27	Tested	8:32:58 AM	08/29/2019
Heat Detector	Portables Classroom 27	Tested	8:33:11 AM	08/29/2019
Heat Detector	Portables Classroom 28	Tested	8:27:33 AM	08/29/2019
Heat Detector	Portables Classroom 28	Tested	8:27:52 AM	08/29/2019
Heat Detector	Portables Classroom 29	Tested	8:30:34 AM	08/29/2019
Heat Detector	Portables Classroom 29	Tested	8:30:47 AM	08/29/2019
Heat Detector	Portables Classroom 30	Tested	8:35:44 AM	08/29/2019
Heat Detector	Portables Classroom 30	Tested	8:35:57 AM	08/29/2019
Pull Station	Admin Entrance	Tested	7:21:56 AM	08/29/2019
Smoke Detector	Admin Above FACP	Tested	7:30:55 AM	08/29/2019
Smoke Detector	Admin Copy Room	Tested	7:29:39 AM	08/29/2019
Smoke Detector	Admin H3 – Nurse	Tested	7:43:08 AM	08/29/2019
Smoke Detector	Admin H7 - Principal Office	Tested	7:32:09 AM	08/29/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Admin Office across from Principal Office	Tested	7:36:44 AM	08/29/2019
Smoke Detector	Admin Supply Room	Tested	7:45:32 AM	08/29/2019
Smoke Detector	Admin Teachers Lounge	Tested	7:46:08 AM	08/29/2019
Smoke Detector	Admin Entrance	Tested	7:23:58 AM	08/29/2019
Smoke Detector	Building A Classroom 1	Tested	8:21:39 AM	08/29/2019
Smoke Detector	Building A Classroom 1	Tested	8:21:51 AM	08/29/2019
Smoke Detector	Building A Classroom 1	Tested	8:21:58 AM	08/29/2019
Smoke Detector	Building A Classroom 2	Tested	8:19:53 AM	08/29/2019
Smoke Detector	Building A Classroom 2	Tested	8:20:04 AM	08/29/2019
Smoke Detector	Building A Classroom 2	Tested	8:20:12 AM	08/29/2019
Smoke Detector	5	Tested	8:17:56 AM	
Smoke Detector	Building A Classroom 3	Tested	8:18:09 AM	08/29/2019
Smoke Detector	Building A Classroom 3 Building A Classroom 3	Tested	8:18:17 AM	08/29/2019
Smoke Detector	Building A Classroom 4	Tested	8:15:04 AM	08/29/2019
	-	Tested	8:15:22 AM	08/29/2019
Smoke Detector	Building A Classroom 4	Tested	8:15:32 AM	08/29/2019
Smoke Detector	Building A Classroom 4		8:40:17 AM	08/29/2019
Smoke Detector	Building C Classroom 17	Tested	8:40:17 AM	08/29/2019
Smoke Detector	Building C Classroom 17	Tested	8:40:56 AM	08/29/2019
Smoke Detector	Building C Classroom 17	Tested	8:40:30 AM	08/29/2019
Smoke Detector	Building C Classroom 18	Tested	8:42:40 AM	08/29/2019
Smoke Detector	Building C Classroom 18	Tested	8:42:50 AM	08/29/2019
Smoke Detector	Building C Classroom 18	Tested	8:42:37 AM 8:44:34 AM	08/29/2019
Smoke Detector	Building C Classroom 19	Tested	8:44:34 AM 8:44:40 AM	08/29/2019
Smoke Detector	Building C Classroom 19	Tested	8:44:40 AM 8:44:47 AM	08/29/2019
Smoke Detector	Building C Classroom 19	Tested	8:44:47 AM 8:48:02 AM	08/29/2019
Smoke Detector	Building C Classroom 20	Tested	8:48:02 AM	08/29/2019
Smoke Detector	Building C Classroom 20	Tested	8:48:14 AM	08/29/2019
Smoke Detector	Building C Classroom 20	Tested Tested	7:58:36 AM	08/29/2019
Smoke Detector	Building D Classroom 5	Tested	7:58:30 AM	08/29/2019
Smoke Detector	Building D Classroom 5	Tested	7:59:02 AM	08/29/2019
Smoke Detector Smoke Detector	Building D Classroom 5	Tested	7:56:23 AM	08/29/2019
	Building D Classroom 6	Tested	7:56:51 AM	08/29/2019
Smoke Detector	Building D Classroom 6		7:56:59 AM	08/29/2019
Smoke Detector Smoke Detector	Building D Classroom 6	Tested Tested	7:53:33 AM	08/29/2019
	Building D Classroom 7		7:53:35 AM	08/29/2019
Smoke Detector	Building D Classroom 7	Tested	7:53:51 AM	08/29/2019
Smoke Detector Smoke Detector	Building D Classroom 7 Building D Classroom 8	Tested Tested	7:50:47 AM	08/29/2019 08/29/2019
Smoke Detector	Building D Classroom 8	Tested	7:51:05 AM	
Smoke Detector	Building D Classroom 8	Tested	7:51:13 AM	08/29/2019 08/29/2019
	Building G Outside Equipment Room		9:21:27 AM	
Smoke Detector Smoke Detector		Tested	9:20:05 AM	08/29/2019
	Building G Outside Heater Room	Tested	9:13:14 AM	08/29/2019
Smoke Detector	Building J Classroom 25 Adult Restroom	Tested	9:14:01 AM	08/29/2019
Smoke Detector	Building J Classroom 25 Work Room	Tested	9:07:57 AM	08/29/2019
Smoke Detector	Building J Classroom 25 Building L Classroom 25	Tested	9:08:10 AM	08/29/2019
Smoke Detector	Building J Classroom 25 Building L Classroom 25	Tested	9:08:16 AM	08/29/2019
Smoke Detector	Building J Classroom 25 Building L Classroom 25	Tested	9:08:22 AM	08/29/2019
Smoke Detector	Building J Classroom 25 Building J Classroom 25	Tested	9:10:52 AM	08/29/2019
Smoke Detector	Building J Classroom 25	Tested		08/29/2019
Smoke Detector	Building J Classroom 26 Adult Restroom	Tested	9:18:18 AM	08/29/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building J Classroom 26 Work Room	Tested	9:14:47 AM	08/29/2019
Smoke Detector	Building J Classroom 26	Tested	9:15:25 AM	08/29/2019
Smoke Detector	Building J Classroom 26	Tested	9:15:57 AM	08/29/2019
Smoke Detector	Building J Classroom 26	Tested	9:16:04 AM	08/29/2019
Smoke Detector	Building J Classroom 26	Tested	9:16:12 AM	08/29/2019
Smoke Detector	Building J Classroom 26	Tested	9:16:17 AM	08/29/2019
Smoke Detector	Portables Classroom 27	Tested	8:33:21 AM	08/29/2019
Smoke Detector	Portables Classroom 27	Tested	8:33:32 AM	08/29/2019
Smoke Detector	Portables Classroom 28	Tested	8:25:44 AM	08/29/2019
Smoke Detector	Portables Classroom 28	Tested	8:26:10 AM	08/29/2019
Smoke Detector	Portables Classroom 29	Tested	8:29:58 AM	08/29/2019
Smoke Detector	Portables Classroom 29	Tested	8:30:20 AM	08/29/2019
Smoke Detector	Portables Classroom 30	Tested	8:35:21 AM	08/29/2019
Smoke Detector	Portables Classroom 30	Tested	8:35:32 AM	08/29/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Harbor View Elementary

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Annunciator	Tested	1
Battery	Tested	6
Control Panel	Tested	1
Heat Detector	Tested	22
Power Supply	Tested	2
Pull Station	Tested	1
Smoke Detector	Tested	68
Total		101

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: NMUSD - Harbor View Elementary Control Panel: 1 - Simplex 4100

The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.

Туре	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
		Passe	d				
Battery							
Sealed Lead Acid	Admin FACP	18	12				ĺ
Sealed Lead Acid	Admin FACP	18	12				
Sealed Lead Acid	Building C Janitor Closet	7	12				
Sealed Lead Acid	Building C Janitor Closet	7	12				
Sealed Lead Acid	Building D Electrical Room	7	12				
Sealed Lead Acid	Building D Electrical Room	7	12				

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Harbor View Elementary Control Panel: 1 - Simplex 4100

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category		% of Inventory	Quantity
Pull Station		Initiating		0.99%	1
Smoke Detector		Initiating		67.33%	68
Heat Detector		Initiating		21.78%	22
Control Panel		Control		0.99%	1
Battery		Control		5.94%	6
Annunciator		Control		0.99%	1
Power Supply		Control	-1	1.98%	2
Туре	Qty	Model #	Description		Install Date
		New	(under 90 day	s)	
12V18Ah					
Battery	2	12V18Ah	Sealed Lead Acid		08/29/2019
Simplex					
Annunciator	1	4100	LCD Display		08/29/2019
Control Panel	1	4100			08/29/2019
Heat Detector	22	4098-9733	Fixed Temperature	e	08/29/2019
Power Supply	2				08/29/2019
Pull Station	1	4099-9001	Keyed		08/29/2019
Smoke Detector	68	4098-9714	Photoelectric		08/29/2019
		In Service	e - 2 Years to 3	Years	
12V7Ah					
Battery	4	12V7Ah	Sealed Lead Acid		07/27/2017

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Harbor View Elementary 900 Goldenrod Ave Corona Del Mar, CA 92625

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Aug 29, 2019

> Building: NMUSD - Harbor View Elementary Contact: Tim Waller Title: Contact

Company: Cal Building Systems Contact: Beeri Martinez Title: Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD - Harbor View Elementary	Contact: Tim V	Waller
Address: 900 Goldenrod Ave	Phone: 714–2	31-0363
Address:	Fax:	
City/State/Zip: Corona Del Mar, CA 92625	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Bee	ri Martinez
Address: 2903 Saturn Street	Phone: 714–9	1313100
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: beerima	artinez@calbuildingsystems.com
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Catagoni	Tota	ltems	Serviced		Pa	ssed	Failed,	Other
Category	Qty	%	Qty	%	Qty	%	Qty	%
Initiating	68	100.00%	68	100.00%	68	100.00%	0	0%
Totals	68	100%	68	100.00%	68	100.00%	0	0%
Certification								
Company: Cal Building Systems	Building: NMUSD – Harbor View Elementary							
Inspector: Beeri Martinez			Co	ntact: Tim \	Waller			
Signadi			c:	un a du				
Signed:			Sig	gned:				

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Harbor View Elementary Control Panel: 1

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passe	d		
Initiating				
Heat Detector	Bldg. B Boy's Restroom	Tested	8:39:28 AM	08/29/2019
Heat Detector	Bldg. B Girl's Restroom	Tested	8:37:42 AM	08/29/2019
Heat Detector	Bldg. B Janitor B2	Tested	8:36:47 AM	08/29/2019
Heat Detector	Bldg. E Conference Office	Tested	8:19:51 AM	08/29/2019
Heat Detector	Bldg. E Office	Tested	8:18:37 AM	08/29/2019
Heat Detector	Bldg. F Boy's Restroom	Tested	8:51:42 AM	08/29/2019
Heat Detector	Bldg. F Girl's Restroom	Tested	8:53:22 AM	08/29/2019
Heat Detector	Bldg. F Janitor F2	Tested	8:52:04 AM	08/29/2019
Heat Detector	MPR Bldg. Kitchen	Tested	8:00:23 AM	08/29/2019
Heat Detector	MPR Bldg. Kitchen	Tested	8:00:31 AM	08/29/2019
Heat Detector	MPR Bldg. Kitchen Restroom	Tested	8:10:20 AM	08/29/2019
Pull Station	MPR Bldg. Back Stage Exit	Tested	7:53:27 AM	08/29/2019
Pull Station	MPR Bldg. Entrance	Tested	7:43:40 AM	08/29/2019
Pull Station	MPR Bldg.	Tested	7:54:16 AM	08/29/2019
Pull Station	MPR Bldg.	Tested	7:54:23 AM	08/29/2019
Pull Station	MPR Bldg.	Tested	7:54:26 AM	08/29/2019
Smoke Detector	Bldg. B Classroom 10	Tested	8:43:47 AM	08/29/2019
Smoke Detector	Bldg. B Classroom 10	Tested	8:43:54 AM	08/29/2019
Smoke Detector	Bldg. B Classroom 10	Tested	8:43:57 AM	08/29/2019
Smoke Detector	Bldg. B Classroom 11	Tested	8:41:48 AM	08/29/2019
Smoke Detector	Bldg. B Classroom 11	Tested	8:41:58 AM	08/29/2019
Smoke Detector	Bldg. B Classroom 11	Tested	8:42:01 AM	08/29/2019
Smoke Detector	Bldg. B Classroom 12	Tested	8:40:23 AM	08/29/2019
Smoke Detector	Bldg. B Classroom 12	Tested	8:40:35 AM	08/29/2019
Smoke Detector	Bldg. B Classroom 12	Tested	8:40:38 AM	08/29/2019
Smoke Detector	Bldg. B Classroom 9	Tested	8:45:00 AM	08/29/2019
Smoke Detector	Bldg. B Classroom 9	Tested	8:45:08 AM	08/29/2019
Smoke Detector	Bldg. B Classroom 9	Tested	8:45:11 AM	08/29/2019
Smoke Detector	Bldg. E Classroom 13	Tested	8:22:16 AM	08/29/2019
Smoke Detector	Bldg. E Classroom 13	Tested	8:22:20 AM	08/29/2019
Smoke Detector	Bldg. E Classroom 13	Tested	8:22:23 AM	08/29/2019
Smoke Detector	Bldg. E Classroom 14	Tested	8:24:45 AM	08/29/2019
Smoke Detector	Bldg. E Classroom 14	Tested	8:24:52 AM	08/29/2019
Smoke Detector	Bldg. E Classroom 14	Tested	8:24:55 AM	08/29/2019
Smoke Detector	Bldg. E Classroom 15	Tested	8:27:23 AM	08/29/2019
Smoke Detector	Bldg. E Classroom 15	Tested	8:27:37 AM	08/29/2019
Smoke Detector	Bldg. E Classroom 15	Tested	8:27:40 AM	08/29/2019
Smoke Detector	Bldg. E Classroom 16	Tested	8:28:43 AM	08/29/2019
Smoke Detector	Bldg. E Classroom 16	Tested	8:28:51 AM	08/29/2019

Cal Building Systems

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Bldg. E Classroom 16	Tested	8:28:54 AM	08/29/2019
Smoke Detector	Bldg. F Classroom 21	Tested	8:55:56 AM	08/29/2019
Smoke Detector	Bldg. F Classroom 21	Tested	8:56:05 AM	08/29/2019
Smoke Detector	Bldg. F Classroom 21	Tested	8:56:10 AM	08/29/2019
Smoke Detector	Bldg. F Classroom 22	Tested	8:55:32 AM	08/29/2019
Smoke Detector	Bldg. F Classroom 22	Tested	8:55:42 AM	08/29/2019
Smoke Detector	Bldg. F Classroom 22	Tested	8:55:47 AM	08/29/2019
Smoke Detector	Bldg. F Classroom 23	Tested	8:55:17 AM	08/29/2019
Smoke Detector	Bldg. F Classroom 23	Tested	8:55:24 AM	08/29/2019
Smoke Detector	Bldg. F Classroom 23	Tested	8:55:29 AM	08/29/2019
Smoke Detector	Bldg. F Classroom 24	Tested	8:55:02 AM	08/29/2019
Smoke Detector	Bldg. F Classroom 24	Tested	8:55:11 AM	08/29/2019
Smoke Detector	Bldg. F Classroom 24	Tested	8:55:14 AM	08/29/2019
Smoke Detector	MPR Bldg. Back Stage Storage	Tested	8:22:59 AM	08/29/2019
Smoke Detector	MPR Bldg. Back Stage	Tested	8:22:52 AM	08/29/2019
Smoke Detector	MPR Bldg. Back Stage	Tested	8:22:55 AM	08/29/2019
Smoke Detector	MPR Bldg. Custodian Closet	Tested	8:23:03 AM	08/29/2019
Smoke Detector	MPR Bldg. Kitchen Corridor To Restroom	Tested	8:23:13 AM	08/29/2019
Smoke Detector	MPR Bldg. Kitchen Dry Storage	Tested	8:23:10 AM	08/29/2019
Smoke Detector	MPR Bldg. Kitchen Office	Tested	8:23:17 AM	08/29/2019
Smoke Detector	MPR Bldg. Kitchen Office	Tested	8:23:20 AM	08/29/2019
Smoke Detector	MPR Bldg. Kitchen Outside Custodian Room	Tested	8:23:23 AM	08/29/2019
Smoke Detector	MPR Bldg. Kitchen Table Storage	Tested	8:23:07 AM	08/29/2019
Smoke Detector	MPR Bldg.	Tested	8:22:33 AM	08/29/2019
Smoke Detector	MPR Bldg.	Tested	8:22:36 AM	08/29/2019
Smoke Detector	MPR Bldg.	Tested	8:22:40 AM	08/29/2019
Smoke Detector	MPR Bldg.	Tested	8:22:42 AM	08/29/2019
Smoke Detector	MPR Bldg.	Tested	8:22:45 AM	08/29/2019
Smoke Detector	MPR Bldg.	Tested	8:22:48 AM	08/29/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Harbor View Elementary

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Heat Detector	Tested	11
Pull Station	Tested	5
Smoke Detector	Tested	52
Total		68

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Harbor View Elementary Control Panel: 1

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category		% of Inventory	Quantity
Pull Station		Initiating		7.35%	5
Heat Detector		Initiating		16.18%	11
Smoke Detector		Initiating		76.47%	52
Туре	Qty	Model #	Description		Install Date
		New	(under 90 day	vs)	
Simplex					
Heat Detector	11	4098-9733	Fixed Temperatur	e	08/29/2019
Pull Station	5	4099-9001	Keyed		08/29/2019
Smoke Detector	52	4098-9714	Photoelectric		08/29/2019

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Harper Elementary 425 E 18th Street Costa Mesa, CA 92627

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Oct 2, 2019

> Building: NMUSD - Harper Elementary Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Beeri Martinez Title: Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD - Harper Elementary	Contact: Tim \	Waller
Address: 425 E 18th Street	Phone: (714)2	31-0363
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92627	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Bee	ri Martinez
Address: 2903 Saturn Street	Phone: 714–9	1313100
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: beerima	artinez@calbuildingsystems.com
System Control Unit		
Manufacturer: Simplex	Inspection Dat	te: 10/02/2019 IDC Style:
Model Number: 4020	Install Date: 1	0/02/2019 SLC Style:
Software Version:	Version Date:	10/02/2019 NAC Style:
Location: Bldg. D FACP Cloest	Current Protect	ction: Breaker
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
	Total	ltems	Ser	viced	Pa	ssed	Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	2.08%	1	100.00%	1	100.00%	0	0%
Control	7	14.58%	7	100.00%	7	100.00%	0	0%
Initiating	40	83.33%	40	100.00%	40	100.00%	0	0%
Totals	48	100%	48	100.00%	48	100.00%	0	0%
Certification								
Company: Cal Building Systems			Bu	ilding: NML	JSD – Har	per Elemen	tary	
Inspector: Beeri Martinez			Co	ontact: Tim	Waller			
Signed:				gned:				

Notes & Recommendations

Generated by: BuildingReports.com

Building: NMUSD - Harper Elementary

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

General Note						
Upon finalizing fire alarm inspection. I called center station (AceTec) to place the system back online and check signals. I gave them the account number (21–1141) and the operator said that it was a security system. No fire trucks arrived while testing. The operator said no signals came in for a general fire alarm and that they didn't have any other accounts besides the security system for the school. She tried calling her contact person for information and got a voicemail for Albert.						
Building:	NMUS	SD - Harper Elementary	y Control Panel: 1 - Simpl	ex 4020		
ScanID	Note	Device Type	Location	Comment		
Initiating						
58736034	2	Pull Station	Bldg. A Classroom 21	Passed		
Pull st	Pull station lever is halfway broken.					

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Harper Elementary

Control Panel: 1 - Simplex 4020

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed	l		
Control				
Annunciator	Bldg. E Admin Office	Tested	3:34:17 PM	10/02/2019
Battery	Bldg. D FACP Cloest	Tested	3:30:11 PM	10/02/2019
Battery	Bldg. D FACP Cloest	Tested	3:30:22 PM	10/02/201
Battery	Bldg. F MPR	Tested	4:47:44 PM	10/02/201
Battery	Bldg. F MPR	Tested	4:48:20 PM	10/02/201
Control Panel	Bldg. D FACP Cloest	Tested	3:17:47 PM	10/02/201
Power Supply	Bldg. F MPR	Tested	4:47:33 PM	10/02/201
Initiating				
Pull Station	Bldg. A Classroom 16	Tested	4:24:06 PM	10/02/201
Pull Station	Bldg. A Classroom 17	Tested	4:27:12 PM	10/02/201
Pull Station	Bldg. A Classroom 18	Tested	4:28:03 PM	10/02/201
Pull Station	Bldg. A Classroom 19	Tested	4:28:47 PM	10/02/201
Pull Station	Bldg. A Classroom 20	Tested	4:30:23 PM	10/02/201
Pull Station	Bldg. A Classroom 21	Tested	4:32:32 PM	10/02/201
Pull Station	Bldg. B Classroom 12	Tested	4:09:37 PM	10/02/201
Pull Station	Bldg. B Classroom 13	Tested	4:13:13 PM	10/02/201
Pull Station	Bldg. B Classroom 14	Tested	4:15:55 PM	10/02/201
Pull Station	Bldg. B Classroom 16	Tested	4:16:46 PM	10/02/201
Pull Station	Bldg. B Medical Therapy	Tested	4:10:47 PM	10/02/201
Pull Station	Bldg. C Classroom 10	Tested	4:02:38 PM	10/02/201
Pull Station	Bldg. C Classroom 11	Tested	4:02:46 PM	10/02/201
Pull Station	Bldg. C Classroom 7A	Tested	3:58:12 PM	10/02/201
Pull Station	Bldg. C Classroom 7B	Tested	3:59:29 PM	10/02/201
Pull Station	Bldg. C Classroom 8	Tested	4:00:58 PM	10/02/201
Pull Station	Bldg. C Classroom 9	Tested	4:02:32 PM	10/02/201
Pull Station	Bldg. D Classroom 2	Tested	3:44:43 PM	10/02/201
Pull Station	Bldg. D Classroom 3	Tested	3:46:09 PM	10/02/201
Pull Station	Bldg. D Classroom 4	Tested	3:47:42 PM	10/02/201
Pull Station	Bldg. D Classroom 5	Tested	3:48:49 PM	10/02/201
Pull Station	Bldg. D Classroom 6	Tested	3:48:56 PM	10/02/201
Pull Station	Bldg. E Admin Office Entrance	Tested	3:34:56 PM	10/02/201
Pull Station	Bldg. E Admin Office Exit	Tested	3:39:47 PM	10/02/201
Pull Station	Bldg. E Classroom 1 Entrance	Tested	3:41:44 PM	10/02/201
Pull Station	Bldg. E Classroom 1 Exit	Tested	3:42:31 PM	10/02/201
Pull Station	Bldg. E Pre-School Corridor	Tested	3:38:47 PM	10/02/201
Pull Station	Bldg. E Pre-School Staff Office	Tested	3:36:50 PM	10/02/201
Pull Station	Bldg. F MPR Office	Tested	4:50:22 PM	10/02/201
Pull Station	Bldg. F MPR Office	Tested	4:50:46 PM	10/02/201

Device Type	Location	Service	Time	Date
	Pass	ed		
Pull Station	Bldg. F MPR	Tested	4:42:55 PM	10/02/2019
Pull Station	Bldg. F MPR	Tested	4:43:14 PM	10/02/2019
Pull Station	Bldg. F MPR	Tested	4:43:17 PM	10/02/2019
Pull Station	Bldg. F MPR	Tested	4:43:21 PM	10/02/2019
Pull Station	Portables Classroom G2	Tested	4:36:20 PM	10/02/2019
Pull Station	Portables Classroom G3	Tested	4:37:25 PM	10/02/2019
Smoke Detector	Bldg. A Classroom 16	Tested	4:26:00 PM	10/02/2019
Smoke Detector	Bldg. C Janitor Closet	Tested	3:57:10 PM	10/02/2019
Smoke Detector	Bldg. D FACP Cloest	Tested	3:31:02 PM	10/02/2019
Smoke Detector	Bldg. F MPR	Tested	4:48:48 PM	10/02/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Harper Elementary

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Annunciator	Tested	1
Battery	Tested	4
Control Panel	Tested	1
Power Supply	Tested	1
Pull Station	Tested	36
Smoke Detector	Tested	4
Total		47

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - Harper Elementary

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

		Ambient	Alarm	🦻 Intell	igibility	Sound
C Location	🗨 Commen	t ∢ dB	◀ dB	Voice	STI	Test
Passed						
Sound Test Points						
Entire Campus	Passed					0001

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Harper Elementary

Control Panel: 1 - Simplex 4020

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type		Category	% of Inventory	Quantity		
Control Panel		Control	2.08%	1		
Battery		Control	8.33%	4		
Smoke Detector		Initiating	8.33%	4		
Annunciator		Control	2.08%	1		
Pull Station		Initiating	75.00%	36		
Power Supply		Control	2.08%	1		
Sound Test		Sound Test	2.08%	1		
	Qt					
Туре	y	Model #	Description	Install Date		
New (under 90 days)						
Simplex						
Annunciator	1			10/02/2019		
Control Panel	1	4020		10/02/2019		
Power Supply	1	4009 IDNet		10/02/2019		
Pull Station	36	2099-9001	Keyed	10/02/2019		
Smoke Detector	4	4098-9714	Photoelectric	10/02/2019		
In Service - 1 Year to 2 Years						
Battery	2	12v 7ah	Sealed Lead Acid	11/01/2017		
		In Servic	e - 2 Years to 3 Years			
Battery	2	12v 18ah	Sealed Lead Acid	07/01/2017		

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Jim Scott Stadium 2323 Placentia Avenue Costa Mesa, CA 92627

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Sep 26, 2019

> Building: NMUSD - Jim Scott Stadium Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Michael Cannon Title: Service Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD – Jim Scott Stadium	Contact: Tim Waller	
Address: 2323 Placentia Avenue	Phone: 714-231-0363	
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92627	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Michael Cannon	
Address: 2903 Saturn Street	Phone: 714-715-1223	
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: mcannon@calbuilding	gsystems.com
System Control Unit		
Manufacturer: Simplex	Inspection Date: 09/26/201	9 IDC Style:
Model Number: 4100U	Install Date: 09/26/2019	SLC Style:
Software Version:	Version Date: 09/26/2019	NAC Style:
Location: Jim Scott Stadium FACP Rm./Electrical Rm.	Current Protection:	
Monitoring		
Company: Pho	ne: Ac	ccount #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Catalana	Tota	ltems	Ser	viced	Pa	ssed	Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	1.52%	1	100.00%	1	100.00%	0	0%
Control	6	9.09%	6	100.00%	6	100.00%	0	0%
Initiating	59	89.39%	59	100.00%	59	100.00%	0	0%
Totals	66	100%	66	100.00%	66	100.00%	0	0%
Certification								
Company: Cal Building Systems			Bi	ilding: NMU	JSD – Jim	Scott Stadiu	um	
Inspector: Michael Cannon			Co	ontact: Tim V	Waller			
- Allow								
Signed: Sep 26, 2019 8:12:15	PM		Sig	gned:				

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Jim Scott Stadium

Control Panel: 1 - Simplex 4100U

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date					
Passed									
Control									
Battery	Storage Building Janitor's Room	Tested	3:45:16 PM	09/26/2019					
Battery	Storage Building Janitor's Room	Tested	3:46:09 PM	09/26/2019					
Control Panel	Jim Scott Stadium FACP Rm./Electrical Rm.	Tested	4:22:21 PM	09/26/2019					
Power Supply	Storage Building Janitor's Room	Inspected	3:44:54 PM	09/26/2019					
Initiating									
Heat Detector	East Jim Scott Stadium Home Team Rm.	Tested	3:49:46 PM	09/26/2019					
Heat Detector	East Jim Scott Stadium Visitor Team Rm.	Tested	3:52:04 PM	09/26/2019					
Heat Detector	West Jim Scott Stadium Home Team Rm.	Tested	3:51:51 PM	09/26/2019					
Heat Detector	West Jim Scott Stadium Visitor Team Rm.	Tested	3:52:29 PM	09/26/2019					
Heat Detector	West Jim Scott Stadium Visitor Team Workroom	Tested	3:52:39 PM	09/26/2019					
Heat Detector	Jim Scott Stadium Concession Rm. 101	Tested	3:57:12 PM	09/26/2019					
Heat Detector	Jim Scott Stadium Concession Rm. 102	Tested	4:01:11 PM	09/26/2019					
Heat Detector	Jim Scott Stadium Concession Rm. 103	Tested	4:00:58 PM	09/26/2019					
Heat Detector	Jim Scott Stadium Concession Rm. 104	Tested	4:00:43 PM	09/26/2019					
Heat Detector	Jim Scott Stadium Concession Rm. 105	Tested	4:00:24 PM	09/26/2019					
Heat Detector	Jim Scott Stadium Concession Rm. 106	Tested	3:58:03 PM	09/26/2019					
Heat Detector	Jim Scott Stadium Concession Rm. 107	Tested	3:57:53 PM	09/26/2019					
Heat Detector	Jim Scott Stadium Concession Rm. 108	Tested	3:57:40 PM	09/26/2019					
Heat Detector	Jim Scott Stadium Home Team Boys RR	Tested	3:55:30 PM	09/26/2019					
Heat Detector	Jim Scott Stadium Home Team Boys RR	Tested	3:55:53 PM	09/26/2019					
Heat Detector	Jim Scott Stadium Home Team Concession	Tested	3:56:00 PM	09/26/2019					
Heat Detector	Jim Scott Stadium Home Team Girls RR	Tested	3:55:01 PM	09/26/2019					
Heat Detector	Jim Scott Stadium Home Team Girls RR	Tested	3:55:17 PM	09/26/2019					
Heat Detector	Jim Scott Stadium Home Team Rm.	Tested	3:54:38 PM	09/26/2019					
Heat Detector	Jim Scott Stadium Home Team RR	Tested	3:56:37 PM	09/26/2019					
Heat Detector	Jim Scott Stadium Home Team Workroom	Tested	3:56:19 PM	09/26/2019					
Heat Detector	Jim Scott Stadium Visitor Team Boys RR	Tested	3:54:02 PM	09/26/2019					
Heat Detector	Jim Scott Stadium Visitor Team Boys RR	Tested	3:54:14 PM	09/26/2019					
Heat Detector	Jim Scott Stadium Visitor Team Concession	Tested	3:53:01 PM	09/26/2019					
Heat Detector	Jim Scott Stadium Visitor Team Girls RR	Tested	3:53:36 PM	09/26/2019					
Heat Detector	Jim Scott Stadium Visitor Team Girls RR	Tested	3:53:56 PM	09/26/2019					
Heat Detector	Jim Scott Stadium Visitor Team Rm.	Tested	3:54:23 PM	09/26/2019					
Heat Detector	Jim Scott Stadium Visitor Team RR	Tested	3:56:56 PM	09/26/2019					
Pull Station	Press Box	Tested	4:01:35 PM	09/26/2019					
Smoke Detector	Press Box	Tested	4:00:04 PM	09/26/2019					
Smoke Detector	Press Box	Tested	4:00:22 PM	09/26/2019					
Smoke Detector	Press Box	Tested	4:00:42 PM	09/26/2019					
Smoke Detector	Press Box	Tested	4:00:54 PM	09/26/2019					

Device Type	Location	Service	Time	Date							
	Passed										
Smoke Detector	Stadium Building Main Electrical Room	Tested	4:20:32 PM	09/26/2019							
Smoke Detector	Stadium Home Boy's Restroom	Tested	4:10:04 PM	09/26/2019							
Smoke Detector	Stadium Home Classroom 108	Tested	4:14:10 PM	09/26/2019							
Smoke Detector	Stadium Home Classroom 108	Tested	4:14:31 PM	09/26/2019							
Smoke Detector	Stadium Home Classroom 108 Restroom	Tested	4:13:55 PM	09/26/2019							
Smoke Detector	Stadium Home Classroom 109	Tested	4:11:37 PM	09/26/2019							
Smoke Detector	Stadium Home Classroom 109	Tested	4:11:54 PM	09/26/2019							
Smoke Detector	Stadium Home Classroom 109 Restroom	Tested	4:12:04 PM	09/26/2019							
Smoke Detector	Stadium Home Concession	Tested	4:08:32 PM	09/26/2019							
Smoke Detector	Stadium Home Men's Restroom	Tested	4:16:34 PM	09/26/2019							
Smoke Detector	Stadium Home Restroom	Tested	4:10:47 PM	09/26/2019							
Smoke Detector	Stadium Home Ticket Booth	Tested	4:09:13 PM	09/26/2019							
Smoke Detector	Stadium Home Women's Restroom	Tested	4:15:56 PM	09/26/2019							
Smoke Detector	Stadium Home Workroom	Tested	4:07:54 PM	09/26/2019							
Smoke Detector	Stadium Visitors Concession	Tested	4:18:42 PM	09/26/2019							
Smoke Detector	Stadium Visitors Ticket Booth	Tested	4:19:18 PM	09/26/2019							
Smoke Detector	Stadium Visitors Workroom	Tested	4:18:22 PM	09/26/2019							
Smoke Detector	Storage Building Boy's Restroom	Tested	3:46:39 PM	09/26/2019							
Smoke Detector	Storage Building Girl's Restroom	Tested	3:47:58 PM	09/26/2019							
Smoke Detector	Storage Building Janitor's Room	Tested	3:42:40 PM	09/26/2019							
Smoke Detector	Storage Building Room A	Tested	3:59:36 PM	09/26/2019							
Smoke Detector	Storage Building Room B	Tested	3:58:04 PM	09/26/2019							
Smoke Detector	Storage Building Room C	Tested	3:57:00 PM	09/26/2019							
Smoke Detector	Storage Building Room D	Tested	3:50:19 PM	09/26/2019							
Smoke Detector	Storage Building Room E	Tested	3:50:05 PM	09/26/2019							

Building: NMUSD - Jim Scott Stadium

Control Panel: 2

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date						
	Location	Jervice	Time	Dute						
Passed										
Control										
Battery	Jim Scott Stadium FACP Rm./Electrical Rm.	Tested	4:23:11 PM	09/26/2019						
Battery	Jim Scott Stadium FACP Rm./Electrical Rm.	Tested	4:24:47 PM	09/26/2019						
Initiating										
Smoke Detector	Jim Scott Stadium FACP Rm./Electrical Rm.	Tested	4:28:41 PM	09/26/2019						

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Jim Scott Stadium

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Battery	Tested	4
Control Panel	Tested	1
Heat Detector	Tested	28
Power Supply	Inspected	1
Pull Station	Tested	1
Smoke Detector	Tested	30
Total		65

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - Jim Scott Stadium

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

			Ambient	Alarm	🦻 Intell	igibility	Sound	
C Location	🗨 Cor	mment	◀ dB	◀ dB	Voice	STI	Test	
Passed								
Sound Test Points								
Entire Campus	Passed						0001	

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: NMUSD - Jim Scott Stadium

Control Panel: 2

The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.

Туре	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah		
Passed									
Battery									
Sealed Lead Acid	Jim Scott Stadium FACP Rm./Electrical Rm.	26	12						
Sealed Lead Acid	Jim Scott Stadium FACP Rm./Electrical Rm.	26	12						

Inventory & Warranty Report Generated by: BuildingReports.com

Building: NMUS	D - Jim	Scott Stadiu	m Control Panel:	1 - Simplex 4100U
complete inventory cour	it by devic	e type and categor	evices and items that are included in your In y is provided. Items installed within the last e grouped together for easy reference.	
Device or Type		Category	% of Inventory	Quantity
Smoke Detector		Initiating	45.45%	30
Power Supply		Control	1.52%	1
Battery		Control	6.06%	4
Heat Detector		Initiating	42.42%	28
Pull Station		Initiating	1.52%	1
Control Panel		Control	1.52%	1
Sound Test		Sound Test	1.52%	1
	Qt			
Туре	У	Model #	Description	Install Date
		New	v (under 90 days)	
Silent Knight				
Power Supply	1	5495		09/26/2019
Simplex				
Control Panel	1	4100U		09/26/2019
Heat Detector	28	4098-9734	Rate-of-Rise	09/26/2019
Pull Station	1	4099-9001	Single Action	09/26/2019
Smoke Detector	29	4098-9714	Photoelectric	09/26/2019
		In Servic	ce - 3 Years to 5 Years	
Battery	2	12V7AH	Sealed Lead Acid	10/26/2015
Building: NMUS	D - Jim	Scott Stadiu	m	Control Panel:
The Inventory & Warran complete inventory cour	nty Report 1t by devic	lists each of the d e type and categor	evices and items that are included in your In ry is provided. Items installed within the last e grouped together for easy reference.	
	Qt			
Туре	У	Model #	Description	Install Date
		In Servic	ce - 2 Years to 3 Years	
12V26Ah				
Battery	2	12V26Ah	Sealed Lead Acid	07/17/2017
Simplex				

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Kaiser Elementary 2130 Santa Ana Costa Mesa, CA 92627

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Aug 22, 2019

> Building: NMUSD - Kaiser Elementary Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Beeri Martinez Title: Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD – Kaiser Elementary	Contact: Tim	Waller
Address: 2130 Santa Ana	Phone: 714-2	231-0363
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92627	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Bee	eri Martinez
Address: 2903 Saturn Street	Phone: 714–9	91313100
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: beerim	artinez@calbuildingsystems.com
System Control Unit		
Manufacturer: Simplex	Inspection Da	ite: 08/22/2019 IDC Style:
Model Number: 4100U	Install Date: (08/22/2019 SLC Style:
Software Version:	Version Date:	08/22/2019 NAC Style:
Location: Bldg. D Admin Office	Current Prote	ction:
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Catalogue	Total	Items	Sen	viced	Pas	ssed	Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.62%	1	100.00%	0	0%	1	100.00%
Control	21	12.96%	21	100.00%	21	100.00%	0	0%
Initiating	140	86.42%	140	100.00%	140	100.00%	0	0%
Totals	162	100%	162	100.00%	161	99.38%	1	0.62%
Certification								
Company: Cal Building Systems			Bu	ilding: NML	JSD – Kais	er Element	ary	
Inspector: Beeri Martinez			Co	ntact: Tim	Waller			
Signed:			Sig	gned:				

Discrepancy Report Generated by: BuildingReports.com

Building: NMUSD - Kaiser ElementaryControl Panel: n/a										
The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.										
Device Type		Manufacturer	ModelNun	nber	Date	Qty				
Items listed for Recall by Manufacturer										
		No recalled items four	d during this inspection	on.						
Sound Test	C3 Location		የ Problem	Device	🚨 Ref	erence				
		Sound	Testing							
Sound Test	C Location		Problem	Device	🕮 Ref	erence				
Sound Test Points										
0001	Entire Campus		Failed Operation	Sound Test						

Proposed Solutions Report Generated by: BuildingReports.com

Building: NMUSD - Kaiser Elementary Contr					: n/a	
The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.						
ScanID	Location	Solution Description Cost			Fix	
Sound Testing						
Sound Test						
0001	Entire Campus	Replace	Red, Square, Wall – Surface	T/M		
PO #: (none)						

Notes & Recommendations

Generated by: BuildingReports.com

Building: NMUSD - Kaiser Elementary

Control Panel: n/a

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

ScanID	Note	Device Type	Location	Comment		
0001	1	Sound Test	Entire Campus	Failed Operation		
Outsid	Outside horns on building F,C,G,E,B & H did not work during AV test.					

Building: NMUSD - Kaiser Elementary

Control Panel: 1 - Simplex 4100U

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

ScanID	Note	Device Type	Location	Comment
Initiating				
61326839	2	Pull Station	Bldg. D MPR Exit	Passed
Device is functional but cover plate is broken. Cover plate falls when opening Manuel pull.				

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Kaiser Elementary

Control Panel: 1 - Simplex 4100U

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Battery	Bldg. C Classroom 8	Tested	10:29:17 AM	08/22/2019
Battery	Bldg. C Classroom 8	Tested	10:29:32 AM	08/22/2019
Battery	Bldg. D Admin Office	Tested	7:23:08 AM	08/22/2019
Battery	Bldg. D Admin Office	Tested	7:24:27 AM	08/22/2019
Battery	Bldg. E Classroom 15	Tested	10:16:42 AM	08/22/2019
Battery	Bldg. E Classroom 15	Tested	10:16:53 AM	08/22/2019
Battery	Bldg. F Classroom 14	Tested	10:11:45 AM	08/22/2019
Battery	Bldg. F Classroom 14	Tested	10:11:55 AM	08/22/2019
Battery	Bldg. G Classroom 1	Tested	10:47:10 AM	08/22/2019
Battery	Bldg. G Classroom 1	Tested	10:47:20 AM	08/22/2019
Battery	Bldg. H Classroom 17	Tested	8:37:01 AM	08/22/2019
Battery	Bldg. H Classroom 17	Tested	8:37:29 AM	08/22/2019
Battery	Portables Classroom R35	Tested	9:47:05 AM	08/22/2019
Battery	Portables Classroom R35	Tested	9:47:28 AM	08/22/2019
Control Panel	Bldg. D Admin Office	Tested	7:21:48 AM	08/22/2019
Power Supply	Bldg. C Classroom 8	Tested	10:29:01 AM	08/22/2019
Power Supply	Bldg. E Classroom 15	Tested	10:16:27 AM	08/22/2019
Power Supply	Bldg. F Classroom 14	Tested	10:11:25 AM	08/22/2019
Power Supply	Bldg. G Classroom 1	Tested	10:46:53 AM	08/22/2019
Power Supply	Bldg. H Classroom 17	Tested	8:36:27 AM	08/22/2019
Power Supply	Portables Classroom R35	Tested	9:46:23 AM	08/22/2019
Initiating				
Heat Detector	Bldg. A Boy's Restroom	Tested	9:28:57 AM	08/22/2019
Heat Detector	Bldg. A Girl's Restroom	Tested	9:23:30 AM	08/22/2019
Heat Detector	Bldg. B Mechanical Room	Tested	9:42:34 AM	08/22/2019
Heat Detector	Bldg. C Boy's Restroom	Tested	10:22:24 AM	08/22/2019
Heat Detector	Bldg. C Girl's Restroom	Tested	10:24:19 AM	08/22/2019
Heat Detector	Bldg. D Kitchen	Tested	8:07:01 AM	08/22/2019
Heat Detector	Bldg. D Kitchen	Tested	8:07:21 AM	08/22/2019
Heat Detector	Bldg. D Kitchen	Tested	8:11:18 AM	08/22/2019
Heat Detector	Bldg. D Kitchen Office	Tested	8:13:20 AM	08/22/2019
Heat Detector	Bldg. D Kitchen Staff Restroom	Tested	8:07:28 AM	08/22/2019
Heat Detector	Bldg. D Kitchen Storage	Tested	8:15:12 AM	08/22/2019
Heat Detector	Bldg. D Mechanical Room	Tested	8:17:14 AM	08/22/2019
Heat Detector	Bldg. D Mechanical Room	Tested	8:27:31 AM	08/22/2019
Heat Detector	Bldg. E Mechanical Room	Tested	10:18:10 AM	08/22/2019
Heat Detector	Bldg. E Men's Staff Restroom	Tested	10:19:21 AM	08/22/2019
Heat Detector	Bldg. E Women's Staff Restroom	Tested	10:21:59 AM	08/22/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	Bldg. F Mechanical Room	Tested	10:08:51 AM	08/22/2019
Heat Detector	Bldg. F Mechanical Room	Tested	10:13:34 AM	08/22/2019
Heat Detector	Bldg. G Mechanical Room	Tested	10:43:37 AM	08/22/2019
Heat Detector	Bldg. G Mechanical Room	Tested	10:44:31 AM	08/22/2019
Heat Detector	Bldg. H Mechanical Room	Tested	8:33:17 AM	08/22/2019
Heat Detector	Bldg. H Mechanical Room	Tested	8:48:49 AM	08/22/2019
Heat Detector	Bldg. I Mechanical Room	Tested	8:59:15 AM	08/22/2019
Heat Detector	Bldg. J Boy's Restroom	Tested	9:08:09 AM	08/22/2019
Heat Detector	Bldg. J Girl's Restroom	Tested	9:07:12 AM	08/22/2019
Heat Detector	Bldg. L Boy's Restroom	Tested	9:04:05 AM	08/22/2019
Heat Detector	Bldg. L Girl's Restroom	Tested	9:03:41 AM	08/22/2019
Heat Detector	Bldg. L Kids Restroom	Tested	9:04:48 AM	08/22/2019
Heat Detector	Bldg. L Staff Restroom	Tested	9:06:04 AM	08/22/2019
Pull Station	Bldg. D Admin Office	Tested	7:27:32 AM	08/22/2019
Pull Station	Bldg. D Kitchen Exit	Tested	8:10:04 AM	08/22/2019
Pull Station	Bldg. D Kitchen Exit	Tested	8:10:09 AM	08/22/2019
Pull Station	Bldg. D MPR Exit	Tested	7:49:23 AM	08/22/2019
Pull Station	Bldg. D MPR Exit	Tested	7:50:08 AM	08/22/2019
Pull Station	Bldg. D MPR Exit	Tested	7:50:51 AM	08/22/2019
Pull Station	Bldg. D MPR Exit	Tested	7:55:23 AM	08/22/2019
Pull Station	Bldg. D MPR Stage Exit	Tested	7:47:31 AM	08/22/2019
Pull Station	Portables Classroom R35	Tested	9:49:40 AM	08/22/2019
Smoke Detector	Bldg. A Classroom 26	Tested	9:09:04 AM	08/22/2019
Smoke Detector	Bldg. A Classroom 27 Storage	Tested	9:25:14 AM	08/22/2019
Smoke Detector	Bldg. A Classroom 27 Storage	Tested	9:25:44 AM	08/22/2019
Smoke Detector	Bldg. A Classroom 27	Tested	9:24:13 AM	08/22/2019
Smoke Detector	Bldg. A Classroom 27	Tested	9:25:03 AM	08/22/2019
Smoke Detector	Bldg. A Classroom 28	Tested	9:27:28 AM	08/22/2019
Smoke Detector	Bldg. A Classroom 28	Tested	9:27:59 AM	08/22/2019
Smoke Detector	Bldg. A Classroom 29	Tested	9:30:24 AM	08/22/2019
Smoke Detector	Bldg. A Custodian Closet	Tested	9:28:31 AM	08/22/2019
Smoke Detector	Bldg. B Library	Tested	9:39:33 AM	08/22/2019
Smoke Detector	Bldg. B Library	Tested	9:39:49 AM	08/22/2019
Smoke Detector	Bldg. B Library	Tested	9:41:12 AM	08/22/2019
Smoke Detector	Bldg. C Classroom 7	Tested	10:30:43 AM	08/22/2019
Smoke Detector	Bldg. C Classroom 8 Mechanical Room	Tested	10:26:58 AM	08/22/2019
Smoke Detector	Bldg. C Classroom 8	Tested	10:26:14 AM	08/22/2019
Smoke Detector	Bldg. C Custodian Closet	Tested	10:25:30 AM	08/22/2019
Smoke Detector	Bldg. D Admin Assistant Office	Tested	7:39:03 AM	08/22/2019
Smoke Detector	Bldg. D Admin Assistant Principal	Tested	7:44:31 AM	08/22/2019
Smoke Detector	Bldg. D Admin Corridor By Data Closet	Tested	7:44:59 AM	08/22/2019
Smoke Detector	Bldg. D Admin Data Closet	Tested	7:42:38 AM	08/22/2019
Smoke Detector	Bldg. D Admin Nurse Office Restroom	Tested	7:41:03 AM	08/22/2019
Smoke Detector	Bldg. D Admin Nurse Office	Tested	7:40:35 AM	08/22/2019
Smoke Detector	Bldg. D Admin Office	Tested	7:26:36 AM	08/22/2019
Smoke Detector	Bldg. D Admin Principles Office	Tested	7:38:33 AM	08/22/2019
Smoke Detector	Bldg. D Admin Staff Restroom	Tested	7:41:34 AM	08/22/2019
Smoke Detector	Bldg. D Admin Storage	Tested	7:43:03 AM	08/22/2019
Smoke Detector	Bldg. D Admin Workroom	Tested	7:39:49 AM	08/22/2019
Smoke Detector	Bldg. D Classroom 30	Tested	8:18:42 AM	08/22/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Bldg. D Classroom 30	Tested	8:18:54 AM	08/22/2019
Smoke Detector	Bldg. D Conference Room 30A–C Office	Tested	8:29:17 AM	08/22/2019
Smoke Detector	Bldg. D Conference Room 30A–C Office	Tested	8:29:52 AM	08/22/2019
Smoke Detector	Bldg. D Conference Room 30A–C Office	Tested	8:30:39 AM	08/22/2019
Smoke Detector	Bldg. D Conference Room 30A–C	Tested	8:28:27 AM	08/22/2019
Smoke Detector	Bldg. D Conference Room 30A–C	Tested	8:31:04 AM	08/22/2019
Smoke Detector	Bldg. D Custodian Office	Tested	8:15:58 AM	08/22/2019
Smoke Detector	Bldg. D Kitchen	Tested	8:11:28 AM	08/22/2019
Smoke Detector	Bldg. D Kitchen	Tested	8:11:53 AM	08/22/2019
Smoke Detector	Bldg. D MPR	Tested	7:57:23 AM	08/22/2019
Smoke Detector	Bldg. D MPR	Tested	7:57:54 AM	08/22/2019
Smoke Detector	Bldg. D MPR	Tested	7:57:58 AM	08/22/2019
Smoke Detector	Bldg. D MPR	Tested	7:58:02 AM	08/22/2019
Smoke Detector	Bldg. D Teachers Lounge	Tested	7:59:57 AM	08/22/2019
Smoke Detector	Bldg. D Teachers Lounge Exit	Tested	7:59:32 AM	08/22/2019
Smoke Detector	Bldg. E Classroom 15 Telephone Cabinet	Tested	10:17:17 AM	08/22/2019
Smoke Detector	Bldg. E Classroom 15	Tested	10:15:11 AM	08/22/2019
Smoke Detector	Bldg. E Classroom 16	Tested	10:14:40 AM	08/22/2019
Smoke Detector	Bldg. F Classroom 10	Tested	10:04:42 AM	08/22/2019
Smoke Detector	Bldg. F Classroom 10	Tested	10:04:51 AM	08/22/2019
Smoke Detector	Bldg. F Classroom 11	Tested	10:05:53 AM	08/22/2019
Smoke Detector	Bldg. F Classroom 12	Tested	10:06:32 AM	08/22/2019
Smoke Detector	Bldg. F Classroom 13	Tested	10:07:37 AM	08/22/2019
Smoke Detector	Bldg. F Classroom 13	Tested	10:07:50 AM	08/22/2019
Smoke Detector	Bldg. F Classroom 14	Tested	10:10:05 AM	08/22/2019
Smoke Detector	Bldg. F Classroom 9	Tested	10:03:12 AM	08/22/2019
Smoke Detector	Bldg. G Classroom 1	Tested	10:44:51 AM	08/22/2019
Smoke Detector	Bldg. G Classroom 2	Tested	10:41:52 AM	08/22/2019
Smoke Detector	Bldg. G Classroom 2	Tested	10:42:05 AM	08/22/2019
Smoke Detector	Bldg. G Classroom 2	Tested	10:42:48 AM	08/22/2019
Smoke Detector	Bldg. G Classroom 3	Tested	10:40:45 AM	08/22/2019
Smoke Detector	Bldg. G Classroom 4	Tested	10:40:35 AM	08/22/2019
Smoke Detector	Bldg. G Classroom 5	Tested	10:38:42 AM	08/22/2019
Smoke Detector	Bldg. G Classroom 5	Tested	10:38:55 AM	08/22/2019
Smoke Detector	Bldg. G Classroom 5	Tested	10:39:04 AM	08/22/2019
Smoke Detector	Bldg. G Classroom 6	Tested	10:36:55 AM	08/22/2019
Smoke Detector	Bldg. H Classroom 17	Tested	8:34:14 AM	08/22/2019
Smoke Detector	Bldg. H Classroom 18	Tested	8:39:42 AM	08/22/2019
Smoke Detector	Bldg. H Classroom 18	Tested	8:40:12 AM	08/22/2019
Smoke Detector	Bldg. H Classroom 18	Tested	8:40:30 AM	08/22/2019
Smoke Detector	Bldg. H Classroom 19	Tested	8:41:39 AM	08/22/2019
Smoke Detector	Bldg. H Classroom 20	Tested	8:42:27 AM	08/22/2019
Smoke Detector	Bldg. H Classroom 21	Tested	8:43:09 AM	08/22/2019
Smoke Detector	Bldg. H Classroom 21	Tested	8:43:43 AM	08/22/2019
Smoke Detector	Bldg. H Classroom 21	Tested	8:44:01 AM	08/22/2019
Smoke Detector	Bldg. H Classroom 22	Tested	8:46:01 AM	08/22/2019
Smoke Detector	Bldg. I Classroom 23	Tested	8:55:46 AM	08/22/2019
Smoke Detector	Bldg. I Classroom 24	Tested	8:57:11 AM	08/22/2019
Smoke Detector	Bldg. I Classroom 24	Tested	8:57:36 AM	08/22/2019
Smoke Detector	Bldg. I Classroom 25	Tested	9:00:18 AM	08/22/2019

Device Type	Location	Service	Time	Date		
Passed						
Smoke Detector	Portables Classroom P10	Tested	8:51:47 AM	08/22/2019		
Smoke Detector	Portables Classroom P10	Tested	8:51:56 AM	08/22/2019		
Smoke Detector	Portables Classroom P11	Tested	8:50:08 AM	08/22/2019		
Smoke Detector	Portables Classroom P11	Tested	8:50:57 AM	08/22/2019		
Smoke Detector	Portables Classroom P12	Tested	9:59:03 AM	08/22/2019		
Smoke Detector	Portables Classroom P12	Tested	9:59:31 AM	08/22/2019		
Smoke Detector	Portables Classroom P9	Tested	8:52:37 AM	08/22/2019		
Smoke Detector	Portables Classroom P9	Tested	8:52:43 AM	08/22/2019		
Smoke Detector	Portables Classroom R31	Tested	9:50:57 AM	08/22/2019		
Smoke Detector	Portables Classroom R31	Tested	9:51:03 AM	08/22/2019		
Smoke Detector	Portables Classroom R32	Tested	9:52:30 AM	08/22/2019		
Smoke Detector	Portables Classroom R32	Tested	9:52:38 AM	08/22/2019		
Smoke Detector	Portables Classroom R33	Tested	9:56:01 AM	08/22/2019		
Smoke Detector	Portables Classroom R33	Tested	9:56:09 AM	08/22/2019		
Smoke Detector	Portables Classroom R34	Tested	9:57:16 AM	08/22/2019		
Smoke Detector	Portables Classroom R34	Tested	9:57:24 AM	08/22/2019		
Smoke Detector	Portables Classroom R35	Tested	9:44:23 AM	08/22/2019		
Smoke Detector	Portables Classroom R35	Tested	9:44:33 AM	08/22/2019		
Smoke Detector	Portables Classroom R36	Tested	9:53:10 AM	08/22/2019		
Smoke Detector	Portables Classroom R36	Tested	9:53:20 AM	08/22/2019		
Smoke Detector	Portables Classroom R37	Tested	9:55:34 AM	08/22/2019		
Smoke Detector	Portables Classroom R37	Tested	9:55:41 AM	08/22/2019		
Smoke Detector	Portables Classroom R38	Tested	9:57:39 AM	08/22/2019		
Smoke Detector	Portables Classroom R38	Tested	9:57:46 AM	08/22/2019		

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Kaiser Elementary

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Battery	Tested	14
Control Panel	Tested	1
Heat Detector	Tested	29
Power Supply	Tested	6
Pull Station	Tested	9
Smoke Detector	Tested	102
Total		161

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - Kaiser Elementary

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

		Ambient	Alarm	🦻 Intell	igibility	Sound
🗘 Location	 Comment 	◀ dB	◀ dB	Voice	STI	Test
Failed/Other						
Sound Test Points						
Entire Campus	Failed Operation					0001

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Kaiser Elementary

Control Panel: 1 - Simplex 4100U

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category	% of Inventor	/ Quantity
Control Panel		Control	0.629	6 1
Battery		Control	8.649	6 14
Smoke Detector		Initiating	62.969	6 102
Pull Station		Initiating	5.569	6 9
Heat Detector		Initiating	17.909	6 29
Power Supply		Control	3.709	6 6
Туре	Qty	Model #	Description	Install Date
		New	(under 90 days)	
Simplex			•	
Control Panel	1	4100U		08/22/2019
Heat Detector	29	4098-9403	Fixed Temperature	08/22/2019
Power Supply	6	4009		08/22/2019
Pull Station	9	4099-9001	Keyed	08/22/2019
Smoke Detector	102	4098-9714	Photoelectric	08/22/2019
		In Service	- 2 Years to 3 Years	
Battery	2	12v 18ah	Sealed Lead Acid	08/15/2017
Battery	2	12v 26ah	Sealed Lead Acid	08/15/2017
Battery	10	12v 7ah	Sealed Lead Acid	08/15/2017

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Killybrooke Elementary 3155 Killybrooke Ln Costa Mesa, CA 92626

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Aug 15, 2019

> Building: NMUSD - Killybrooke Elementary Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Michael Cannon Title: Service Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD – Killybrooke Elementary	Contact: Tim Waller	
Address: 3155 Killybrooke Ln	Phone: 714-231-0363	
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92626	Mobile:	
Country: United States of America	Email: twaller@nmusd.	us
Inspection Performed By		
Company: Cal Building Systems	Inspector: Michael Can	non
Address: 2903 Saturn Street	Phone: 714-715-1223	
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: mcannon@calbu	ildingsystems.com
System Control Unit		
Manufacturer: Silent Knight	Inspection Date: 08/15	5/2019 IDC Style:
Model Number: 5820XL	Install Date: 08/15/20	19 SLC Style:
Software Version:	Version Date: 08/15/2	019 NAC Style:
Location: Admin Electrical Room	Current Protection: Bre	aker
Monitoring		
Company: AceTec	Phone: 1-800-634-3195	Account #: 21-1160
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Catalan	Total	Items	Serv	/iced	Passed		Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.60%	1	100.00%	1	100.00%	0	0%
Control	22	13.25%	22	100.00%	22	100.00%	0	0%
Initiating	143	86.14%	143	100.00%	143	100.00%	0	0%
Totals	166	100%	166	100.00%	166	100.00%	0	0%
Certification Company: Cal Building Systems								
Inspector: Michael Cannon			Co	ntact: Tim	Waller			
The Camon	Contact. Tim Waller							
Signed: Aug 15, 2019 1:45:39	PM		Sig	ned:				

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Killybrooke Elementary

Control Panel: 1 - Silent Knight 5820XL

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Admin Reception	Tested	8:02:32 AM	08/15/2019
Battery	Admin Electrical Room	Inspected	7:46:35 AM	08/15/2019
Battery	Admin Electrical Room	Inspected	7:47:09 AM	08/15/2019
Battery	Electrical/IDF Room Behind Classroom 25	Tested	8:28:02 AM	08/15/2019
Battery	Electrical/IDF Room Behind Classroom 25	Tested	8:28:58 AM	08/15/2019
Battery	IDF Room Behind Classroom 22	Tested	8:20:30 AM	08/15/2019
Battery	IDF Room Behind Classroom 22	Tested	8:21:05 AM	08/15/2019
Battery	IDF Room Behind Classroom 5	Tested	9:35:16 AM	08/15/2019
Battery	IDF Room Behind Classroom 5	Tested	9:35:26 AM	08/15/2019
Battery	MPR Building Outside Custodian Room	Tested	10:01:59 AM	08/15/2019
Battery	MPR Building Outside Custodian Room	Tested	10:02:23 AM	08/15/2019
Battery	Storage Room Near Classroom 14	Tested	8:34:07 AM	08/15/2019
Battery	Storage Room Near Classroom 14	Tested	8:34:35 AM	08/15/2019
Battery	Storage/IDF Room Between Classrooms 1 And 2	Tested	9:47:12 AM	08/15/2019
Battery	Storage/IDF Room Between Classrooms 1 And 2	Tested	9:47:53 AM	08/15/2019
Control Panel	Admin Electrical Room	Tested	7:45:31 AM	08/15/2019
Power Supply	Electrical/IDF Room Behind Classroom 25	Inspected	8:27:02 AM	08/15/2019
Power Supply	IDF Room Behind Classroom 22	Inspected	8:17:33 AM	08/15/2019
Power Supply	IDF Room Behind Classroom 5	Inspected	9:34:58 AM	08/15/2019
Power Supply	MPR Building Outside Custodian Room	Inspected	10:01:20 AM	08/15/2019
Power Supply	Storage Room Near Classroom 14	Inspected	8:35:16 AM	08/15/2019
Power Supply	Storage/IDF Room Between Classrooms 1 And 2	Inspected	9:46:34 AM	08/15/2019
Initiating				
Heat Detector	Building 6 Staff Restroom Attic	Tested	9:49:10 AM	08/15/2019
Heat Detector	Building 8 Staff Restroom Attic	Tested	9:59:27 AM	08/15/2019
Heat Detector	Building 9 Mechanical Room	Tested	10:01:37 AM	08/15/2019
Heat Detector	Building 9 Workroom Attic	Tested	10:00:34 AM	08/15/2019
Heat Detector	Building 9 Workroom Restroom Attic	Tested	10:01:10 AM	08/15/2019
Heat Detector	Admin Nurse Office Restroom Attic	Tested	9:08:59 AM	08/15/2019
Heat Detector	Admin Staff Lounge Restroom Attic	Tested	9:09:20 AM	08/15/2019
Heat Detector	Room 1 Restroom Attic	Tested	10:00:12 AM	08/15/2019
Heat Detector	Room 11 Attic	Tested	9:46:05 AM	08/15/2019
Heat Detector	Room 11 Attic	Tested	9:46:14 AM	08/15/2019
Heat Detector	Room 12 Attic	Tested	9:46:20 AM	08/15/2019
Heat Detector	Room 12 Attic	Tested	9:46:29 AM	08/15/2019
Heat Detector	Room 13 Attic	Tested	9:46:33 AM	08/15/2019
Heat Detector	Room 13 Attic	Tested	9:46:43 AM	08/15/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	Room 18 Attic	Tested	9:47:15 AM	08/15/2019
Heat Detector	Room 18 Attic	Tested	9:47:27 AM	08/15/2019
Heat Detector	Room 19 Attic	Tested	9:47:32 AM	08/15/2019
Heat Detector	Room 19 Attic	Tested	9:47:42 AM	08/15/2019
Heat Detector	Room 2 Restroom Attic	Tested	9:59:44 AM	08/15/2019
Heat Detector	Room 26 Attic	Tested	9:47:47 AM	08/15/2019
Heat Detector	Room 26 Attic	Tested	9:48:01 AM	08/15/2019
Heat Detector	Room 27 Attic	Tested	9:48:07 AM	08/15/2019
Heat Detector	Room 27 Attic	Tested	9:48:17 AM	08/15/2019
Heat Detector	Room 8 Attic	Tested	9:45:34 AM	08/15/2019
Heat Detector	Room 8 Attic	Tested	9:45:58 AM	08/15/2019
Heat Detector	Science Room Attic	Tested	9:46:47 AM	08/15/2019
Heat Detector	Science Room Attic	Tested	9:47:04 AM	08/15/2019
Heat Detector	Kitchen	Tested	9:16:45 AM	08/15/2019
Heat Detector	MPR IDF Room Attic	Tested	9:43:51 AM	08/15/2019
Heat Detector	MPR Men's Restroom Attic	Tested	9:44:24 AM	08/15/2019
Heat Detector	MPR Northeast Attic	Tested	9:17:16 AM	08/15/2019
Heat Detector	MPR Northwest Attic	Tested	9:20:11 AM	08/15/2019
Heat Detector	MPR Southeast Attic	Tested	9:18:40 AM	08/15/2019
Heat Detector	MPR Southwest Attic	Tested	9:43:25 AM	08/15/2019
Heat Detector	Room 6 Attic	Tested	9:45:24 AM	08/15/2019
Heat Detector	Room 6 Attic	Tested	9:45:30 AM	08/15/2019
Pull Station	Admin Main Entrance	Tested	7:44:50 AM	08/15/2019
Pull Station	Admin Teachers Lounge	Tested	7:57:46 AM	08/15/2019
Pull Station	MPR Building Corridor Exit	Tested	10:11:04 AM	08/15/2019
Pull Station	MPR Building Main Exit	Tested	10:10:39 AM	08/15/2019
Pull Station	MPR Building Stage Exit	Tested	10:11:32 AM	08/15/2019
Smoke Detector	Admin Nurse Office	Tested	7:56:25 AM	08/15/2019
Smoke Detector	Admin Nurse Office Restroom	Tested	7:53:44 AM	08/15/2019
Smoke Detector	Admin Outside Principal Office	Tested	7:55:14 AM	08/15/2019
Smoke Detector	Admin Principal Office	Tested	8:00:48 AM	08/15/2019
Smoke Detector	Admin Reception	Tested	7:55:40 AM	08/15/2019
Smoke Detector	Admin Staff Restroom	Tested	10:31:40 AM	08/15/2019
Smoke Detector	Admin Teachers Lounge	Tested	7:56:55 AM	08/15/2019
Smoke Detector	Admin Teachers Lounge	Tested	7:57:23 AM	08/15/2019
Smoke Detector	Admin Teachers Lounge Restroom	Tested	7:58:05 AM	08/15/2019
Smoke Detector	Admin Workroom	Tested	7:56:06 AM	08/15/2019
Smoke Detector	Admin Electrical Room	Tested	7:40:22 AM	08/15/2019
Smoke Detector	Boy's Restroom Near Classroom 10	Tested	9:39:41 AM	08/15/2019
Smoke Detector	Boy's Restroom Near Classroom 14	Tested	8:32:10 AM	08/15/2019
Smoke Detector	Boy's Restroom Near Classroom 17	Tested	8:44:27 AM	08/15/2019
Smoke Detector	Classroom 1 Restroom	Tested	9:50:42 AM	08/15/2019
Smoke Detector	Classroom 1	Tested	9:49:08 AM	08/15/2019
Smoke Detector	Classroom 1	Tested	9:49:19 AM	08/15/2019
Smoke Detector	Classroom 10	Tested	9:37:17 AM	08/15/2019
Smoke Detector	Classroom 10	Tested	9:37:49 AM	08/15/2019
Smoke Detector	Classroom 10	Tested	9:43:42 AM	08/15/2019
Smoke Detector	Classroom 10	Tested	9:44:56 AM	08/15/2019
Smoke Detector	Classroom 14	Tested	8:05:36 AM	08/15/2019
Smoke Detector	Classroom 14	Tested	8:07:16 AM	08/15/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Classroom 15	Tested	8:11:23 AM	08/15/2019
Smoke Detector	Classroom 15	Tested	8:11:42 AM	08/15/2019
Smoke Detector	Classroom 16	Tested	8:40:43 AM	08/15/2019
Smoke Detector	Classroom 16	Tested	8:42:27 AM	08/15/2019
Smoke Detector	Classroom 17	Tested	8:56:51 AM	08/15/2019
Smoke Detector	Classroom 17	Tested	8:57:14 AM	08/15/2019
Smoke Detector	Classroom 2 Restroom	Tested	9:54:57 AM	08/15/2019
Smoke Detector	Classroom 2	Tested	9:55:17 AM	08/15/2019
Smoke Detector	Classroom 2	Tested	9:55:26 AM	08/15/2019
Smoke Detector	Classroom 20	Tested	8:07:45 AM	08/15/2019
Smoke Detector	Classroom 20	Tested	8:08:42 AM	08/15/2019
Smoke Detector	Classroom 21	Tested	8:08:55 AM	08/15/2019
Smoke Detector	Classroom 21	Tested	8:09:06 AM	08/15/2019
Smoke Detector	Classroom 22	Tested	8:09:36 AM	08/15/2019
Smoke Detector	Classroom 22	Tested	8:09:53 AM	08/15/2019
Smoke Detector	Classroom 23	Tested	8:57:59 AM	08/15/2019
Smoke Detector	Classroom 23	Tested	8:58:35 AM	08/15/2019
Smoke Detector	Classroom 24	Tested	8:59:07 AM	08/15/2019
Smoke Detector	Classroom 24	Tested	8:59:57 AM	08/15/2019
Smoke Detector	Classroom 25	Tested	9:00:32 AM	08/15/2019
Smoke Detector	Classroom 25	Tested	9:01:22 AM	08/15/2019
Smoke Detector	Classroom 3	Tested	9:31:29 AM	08/15/2019
Smoke Detector	Classroom 3	Tested	9:31:50 AM	08/15/2019
Smoke Detector	Classroom 4	Tested	9:29:13 AM	08/15/2019
Smoke Detector	Classroom 4	Tested	9:29:32 AM	08/15/2019
Smoke Detector	Classroom 5	Tested	9:28:46 AM	08/15/2019
Smoke Detector	Classroom 5	Tested	9:29:06 AM	08/15/2019
Smoke Detector	Classrooms 1 And 2 Workroom	Tested	9:53:44 AM	08/15/2019
Smoke Detector	Electrical Room Behind Classroom 21	Tested	8:23:03 AM	08/15/2019
Smoke Detector	Electrical Room Behind Classroom 24	Tested	8:26:11 AM	08/15/2019
Smoke Detector	Electrical Room Behind Classroom 5	Tested	9:33:34 AM	08/15/2019
Smoke Detector	Electrical Room Behind Classroom 5	Tested	9:34:36 AM	08/15/2019
Smoke Detector	Electrical/IDF Room Behind Classroom 25	Tested	8:26:30 AM	08/15/2019
Smoke Detector	Girl's Restroom Near Classroom 10	Tested	9:39:26 AM	08/15/2019
Smoke Detector	Girl's Restroom Near Classroom 14	Tested	8:31:38 AM	08/15/2019
Smoke Detector	Girl's Restroom Near Classroom 17	Tested	8:45:20 AM	08/15/2019
Smoke Detector	IDF Room Behind Classroom 22	Tested	8:22:12 AM	08/15/2019
Smoke Detector	MPR Building Chair Storage	Tested	10:25:49 AM	08/15/2019
Smoke Detector	MPR Building Chair Storage	Tested	1:21:43 PM	08/15/2019
Smoke Detector	MPR Building Corridor Exit	Tested	10:20:14 AM	08/15/2019
Smoke Detector	MPR Building Main Hall	Tested	10:13:37 AM	08/15/2019
Smoke Detector	MPR Building Main Hall	Tested	10:13:58 AM	08/15/2019
Smoke Detector	MPR Building Main Hall	Tested	10:14:07 AM	08/15/2019
Smoke Detector	MPR Building Main Hall	Tested	10:14:13 AM	08/15/2019
Smoke Detector	MPR Building Men's Restroom	Tested	10:21:29 AM	08/15/2019
Smoke Detector	MPR Building Outside Custodian Room	Tested	10:00:21 AM	08/15/2019
Smoke Detector	MPR Building Staff Lounge/Workroom	Tested	10:07:27 AM	08/15/2019
Smoke Detector	MPR Building Stage	Tested	10:12:46 AM	08/15/2019
Smoke Detector	MPR Building Stage	Tested	10:13:04 AM	08/15/2019
Smoke Detector	MPR Building Women's Restroom	Tested	10:21:11 AM	08/15/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Portable Science Lab	Tested	9:21:11 AM	08/15/2019
Smoke Detector	Portable Science Lab	Tested	9:21:30 AM	08/15/2019
Smoke Detector	Portable 11	Tested	9:15:39 AM	08/15/2019
Smoke Detector	Portable 11	Tested	9:16:44 AM	08/15/2019
Smoke Detector	Portable 12	Tested	9:17:42 AM	08/15/2019
Smoke Detector	Portable 12	Tested	9:17:58 AM	08/15/2019
Smoke Detector	Portable 13	Tested	9:19:13 AM	08/15/2019
Smoke Detector	Portable 13	Tested	9:19:25 AM	08/15/2019
Smoke Detector	Portable 18	Tested	9:13:17 AM	08/15/2019
Smoke Detector	Portable 18	Tested	9:13:29 AM	08/15/2019
Smoke Detector	Portable 19	Tested	9:11:16 AM	08/15/2019
Smoke Detector	Portable 19	Tested	9:11:28 AM	08/15/2019
Smoke Detector	Portable 26	Tested	9:03:03 AM	08/15/2019
Smoke Detector	Portable 26	Tested	9:03:48 AM	08/15/2019
Smoke Detector	Portable 27	Tested	9:09:58 AM	08/15/2019
Smoke Detector	Portable 27	Tested	9:11:03 AM	08/15/2019
Smoke Detector	Portable 6	Tested	9:25:50 AM	08/15/2019
Smoke Detector	Portable 6	Tested	9:26:01 AM	08/15/2019
Smoke Detector	Portable 7	Tested	9:25:00 AM	08/15/2019
Smoke Detector	Portable 7	Tested	9:25:28 AM	08/15/2019
Smoke Detector	Portable 8	Tested	9:22:27 AM	08/15/2019
Smoke Detector	Portable 8	Tested	9:24:07 AM	08/15/2019
Smoke Detector	Storage IDF Room Between Classrooms 1 And 2	Tested	9:45:20 AM	08/15/2019
Smoke Detector	Storage Room Behind Classroom 14	Tested	8:36:04 AM	08/15/2019
Smoke Detector	Storage Room Near Classroom 14	Tested	8:33:35 AM	08/15/2019
Smoke Detector	Unisex Restroom Behind Classroom 17	Tested	8:46:26 AM	08/15/2019
Smoke Detector	Unisex Restroom Near Classroom 10	Tested	9:39:58 AM	08/15/2019
Smoke Detector	Unisex Restroom Near Classroom 17	Tested	8:45:55 AM	08/15/2019
Smoke Detector	Unisex Restroom Unisex Classroom 10	Tested	9:42:47 AM	08/15/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Killybrooke Elementary

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Annunciator	Tested	1
Battery	Inspected	2
Battery	Tested	12
Control Panel	Tested	1
Heat Detector	Tested	36
Power Supply	Inspected	6
Pull Station	Tested	5
Smoke Detector	Tested	102
Total		165

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - Killybrooke Elementary

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

		Ambient	Alarm	🦻 Intell	igibility	Sound
C Location	 Comment 	◀ dB	◀ dB	Voice	STI	Test
	Passea	!				
Sound Test Points						
Entire Campus	Passed					0001

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Killybrooke Elementary

Control Panel: 1 - Silent Knight 5820XL

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category	% of Inventory	Quantity
Smoke Detector		Initiating	61.45%	102
Pull Station		Initiating	3.01%	5
Control Panel		Control	0.60%	1
Battery		Control	8.43%	14
Annunciator		Control	0.60%	1
Power Supply		Control	3.61%	6
Heat Detector		Initiating	21.69%	36
Туре	Qty	Model #	Description	Install Date
		New	(under 90 days)	
Chemetron				
Heat Detector	20	602	Rate-of-Rise	08/15/2019
Silent Knight				
Annunciator	1		LCD Display	08/15/2019
Battery	2	12V7AH	Sealed Lead Acid	08/15/2019
Control Panel	1	5820XL		08/15/2019
Heat Detector	16	SD505-AHS	Fixed Temperature	08/15/2019
Power Supply	4	5895XL		08/15/2019
Pull Station	2	SD500-PS		08/15/2019
Pull Station	2	SD500-PS	Single Action	08/15/2019
Pull Station	1	SD505-APS		08/15/2019
Smoke Detector	98	SD505-APS	Photoelectric	08/15/2019
		In Service	e - 2 Years to 3 Years	
Battery	2	12v18ah	Sealed Lead Acid	08/15/2017
Battery	8	12V7AH	Sealed Lead Acid	08/15/2017
Silent Knight				
Battery	2	12V7AH	Sealed Lead Acid	08/15/2017
Power Supply	2	5895XL		08/15/2017
Smoke Detector	4	SD505-APS	Photoelectric	08/15/2017

Zone Address Report

Generated by: BuildingReports.com

Building: NMUSD - Killybrooke Elementary

Control Panel: 1 - Silent Knight 5820XL

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Туре	ScanID
33:012	Heat Detector	Admin Nurse Office Restroom Attic	Fixed Temperature	61336716
33:013	Heat Detector	Admin Staff Lounge Restroom Attic	Fixed Temperature	61336717
33:031	Heat Detector	Building 6 Staff Restroom Attic	Fixed Temperature	61336745
33:038	Heat Detector	Room 2 Restroom Attic	Fixed Temperature	61336747
33:040	Heat Detector	Room 1 Restroom Attic	Fixed Temperature	61336748
33:042	Heat Detector	Building 9 Workroom Attic	Fixed Temperature	61336749
33:044	Heat Detector	Building 9 Workroom Restroom Attic	Fixed Temperature	61336750
33:045	Heat Detector	Building 9 Mechanical Room	Fixed Temperature	61336751
33:052	Heat Detector	Building 8 Staff Restroom Attic	Fixed Temperature	61336746
33:069	Heat Detector	Kitchen	Fixed Temperature	61336718
33:075	Heat Detector	MPR Northeast Attic	Fixed Temperature	61336719
33:076	Heat Detector	MPR Southeast Attic	Fixed Temperature	61336720
33:077	Heat Detector	MPR Northwest Attic	Fixed Temperature	61336721
33:078	Heat Detector	MPR Southwest Attic	Fixed Temperature	61336722
33:081	Heat Detector	MPR IDF Room Attic	Fixed Temperature	61336723
33:081	Heat Detector	MPR Men's Restroom Attic	Fixed Temperature	61336724

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Lincoln Elementary 3101 Pacific View Dr Newport Beach, CA 92625

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Aug 29, 2019

> Building: NMUSD - Lincoln Elementary Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Michael Cannon Title: Service Technician

Executive Summary Generated by: BuildingReports.com

Building Information	
Building: NMUSD - Lincoln Elementary	Contact: Tim Waller
Address: 3101 Pacific View Dr	Phone: 714–231–0363
Address:	Fax:
City/State/Zip: Newport Beach, CA 92625	Mobile:
Country: United States of America	Email:
Inspection Performed By	
Company: Cal Building Systems	Inspector: Michael Cannon
Address: 2903 Saturn Street	Phone: 714–715–1223
Address: Suite F	Fax:
City/State/Zip: Brea, CA 92821	Mobile:
Country: United States of America	Email: mcannon@calbuildingsystems.com
System Control Unit	
Manufacturer: FCI	Inspection Date: 08/29/2019 IDC Style:
Model Number: 7200	Install Date: 08/29/2019 SLC Style:
Software Version:	Version Date: 08/29/2019 NAC Style:
Location: Admin Building Workroom Behind Reception	Current Protection:
Monitoring	
Company: AceTec	Phone: 800-634-3915 Account #: 21-1139
Central Station Signal Verification	
Туре:	Mfg: Silent Knight Model #: 5104B
Test Time/Date: 8/29/19 8:01:12 AM	Restore Time

Inspection Summary								
C. L.	Total	ltems	Ser	viced	Passed		Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.42%	1	100.00%	1	100.00%	0	0%
Control	19	7.98%	19	100.00%	19	100.00%	0	0%
Initiating	218	91.60%	218	100.00%	218	100.00%	0	0%
Totals	238	100%	238	100.00%	238	100.00%	0	0%
Certification								
Company: Cal Building Systems			Bu	ilding: NML	JSD – Lind	oln Elemen	itary	
Inspector: Michael Cannon			Co	ontact: Tim	Waller			
Mar Canno								
Signed: Aug 29, 2019 3:01:22	PM		Sig	gned:				

Notes & Recommendations

Generated by: BuildingReports.com

Building: NMUSD - Lincoln Elementary

Control Panel: 1 - FCI 7200

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

ScanID	Note	Device Type	Location	Comment
			Initiating	
58090562	1	Waterflow Switch	Sprinkler Riser Room Outside Classroom 11	Passed
			ITV Outside Of Classroom 4	
Static	80			
Resid	ual 58			
F. Sta	tic 74			
Riser	Diameter	4"		
Main	Drain Dia	meter 2"		

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Lincoln Elementary

Control Panel: 1 - FCI 7200

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Admin Building Reception	Inspected	8:05:26 AM	08/29/2019
Annunciator	Admin Building Reception (For The Dialer)	Inspected	8:06:24 AM	08/29/2019
Battery	Admin Building Workroom Behind Reception	Tested	7:58:00 AM	08/29/2019
Battery	Admin Building Workroom Behind Reception	Tested	7:58:55 AM	08/29/2019
Battery	Admin Building Workroom Behind Reception	Tested	8:02:29 AM	08/29/2019
Battery	Classroom 25 Electrical Room	Tested	10:30:50 AM	08/29/2019
Battery	Classroom 25 Electrical Room	Tested	10:30:58 AM	08/29/2019
Battery	Electrical Room Near Classroom 5	Tested	9:11:01 AM	08/29/2019
Battery	Electrical Room Near Classroom 5	Tested	9:11:33 AM	08/29/2019
Battery	Electrical Room Near Classroom Computer Lab	Tested	9:52:16 AM	08/29/2019
Battery	Electrical Room Near Classroom Computer Lab	Tested	9:52:34 AM	08/29/2019
Battery	Electrical Room Outside MPR Building	Tested	11:06:20 AM	08/29/2019
Battery	Electrical Room Outside MPR Building	Tested	11:06:49 AM	08/29/201
Communicator	Admin Building Workroom Behind Reception	Tested	8:01:12 AM	08/29/201
Control Panel	Admin Building Workroom Behind Reception	Tested	7:55:32 AM	08/29/201
Power Supply	Classroom 25 Electrical Room	Inspected	10:30:02 AM	08/29/201
Power Supply	Electrical Room Near Classroom 5	Inspected	9:10:18 AM	08/29/201
Power Supply	Electrical Room Near Classroom Computer Lab	Inspected	9:51:54 AM	08/29/201
Power Supply	Electrical Room Outside MPR Building	Inspected	11:05:36 AM	08/29/201
Initiating				
Heat Detector	Admin Building Nurse's Restroom	Tested	10:46:03 AM	08/29/2019
Heat Detector	Admin Building Staff Restroom	Tested	8:13:36 AM	08/29/201
Heat Detector	Admin Building Staff Restroom	Tested	8:18:58 AM	08/29/2019
Heat Detector	Boy's Restroom Near Classroom 26	Tested	11:10:52 AM	08/29/2019
Heat Detector	Boy's Restroom Outside Of Staff Lounge	Tested	9:41:49 AM	08/29/2019
Heat Detector	Girl's Restroom Near Classroom 26	Tested	11:09:16 AM	08/29/2019
Heat Detector	Girl's Restroom Outside Of Staff Lounge	Tested	9:40:46 AM	08/29/201
Heat Detector	MPR Building Men's Restroom	Tested	12:34:53 PM	08/29/201
Heat Detector	MPR Building Women's Restroom	Tested	12:32:48 PM	08/29/2019
Heat Detector	MPR Building Women's Restroom Near Staff	Tested	11:02:09 AM	08/29/2019
Heat Dotoctor	Locker Room Staff Men's Restroom Outside Of Computer Lab	Tested	9:34:42 AM	00/20/201
Heat Detector	Staff Men's Restroom Outside Of Computer Lab		9:34:42 AM 9:48:37 AM	08/29/2019
Heat Detector	Staff Women's Restroom Outside Of Computer Lab	Tested	א זכ.ס י .נ	08/29/2019
Heat Detector	Staff Workroom Unisex Room	Tested	9:15:37 AM	08/29/2019
Heat Detector	Unisex Restroom Near Classroom 2	Tested	9:01:41 AM	08/29/2019
Heat Detector	Unisex Restroom Near Classroom 2	Tested	9:02:36 AM	08/29/2019
Heat Detector	Unisex Restroom Staff Workroom/File Room	Tested	9:14:50 AM	08/29/2019

Device Type	Location	Service	Time	Date
	Passed			
Pull Station	Admin Building Reception	Tested	8:08:02 AM	08/29/2019
Pull Station	Child Development Center Portable 1	Tested	10:12:50 AM	08/29/2019
Pull Station	Child Development Center Portable 2	Tested	10:11:32 AM	08/29/2019
Pull Station	Classroom 30	Tested	9:56:03 AM	08/29/2019
Pull Station	Classroom 31	Tested	9:57:13 AM	08/29/2019
Pull Station	Classroom 32	Tested	10:05:42 AM	08/29/2019
Pull Station	Classroom 33	Tested	10:05:05 AM	08/29/2019
Pull Station	Computer Lab Exit	Tested	9:46:22 AM	08/29/2019
Pull Station	Computer Lab Exit	Tested	9:47:08 AM	08/29/2019
Pull Station	Corridor Exit Near Classroom 1	Tested	8:49:41 AM	08/29/2019
Pull Station	Corridor Near Classroom 5 And Staff Workroom	Tested	9:12:01 AM	08/29/2019
Pull Station	Gymnasium	Tested	10:16:00 AM	08/29/2019
Pull Station	Gymnasium	Tested	10:16:42 AM	08/29/2019
Pull Station	Gymnasium	Tested	10:17:13 AM	08/29/2019
Pull Station	Gymnasium	Tested	10:18:04 AM	08/29/2019
Pull Station	Kitchen Food Prep	Tested	10:56:26 AM	08/29/2019
Pull Station	Library Exit	Tested	8:29:09 AM	08/29/2019
Pull Station	MPR Building Corridor By ISP Classroom	Tested	12:30:39 PM	08/29/2019
Pull Station	MPR Building Corridor Next To Staff Conference Room	Tested	11:03:19 AM	08/29/2019
Pull Station	MPR Building ISP Classroom Exit	Tested	12:40:49 PM	08/29/2019
Pull Station	MPR Building Stage Exit	Tested	12:19:13 PM	08/29/2019
Pull Station	MPR Building	Tested	12:16:41 PM	08/29/2019
Pull Station	MPR Building	Tested	12:17:14 PM	08/29/2019
Pull Station	MPR Building	Tested	12:18:00 PM	08/29/2019
Smoke Detector	Admin Building Administrative Assistant	Tested	8:11:18 AM	08/29/2019
Smoke Detector	Admin Building Corridor Outside Of Staff	Tested	8:18:27 AM	08/29/2019
	Restroom			, -,
Smoke Detector	Admin Building Corridor Outside Principal's Office	Tested	8:12:27 AM	08/29/2019
Smoke Detector	Admin Building Main Workroom	Tested	8:14:46 AM	08/29/2019
Smoke Detector	Admin Building Main Workroom	Tested	8:15:28 AM	08/29/2019
Smoke Detector	Admin Building Main Workroom Electrical Room	Tested	8:16:57 AM	08/29/2019
Smoke Detector	Admin Building Main Workroom Office Storage	Tested	8:15:51 AM	08/29/2019
Smoke Detector	Admin Building Main Workroom Storage Room	Tested	8:17:42 AM	08/29/2019
Smoke Detector	Admin Building Nurse's Cot Room	Tested	10:45:10 AM	08/29/2019
Smoke Detector	Admin Building Nurse's Office	Tested	10:51:17 AM	08/29/2019
Smoke Detector	Admin Building Nurse's Reception	Tested	10:50:27 AM	08/29/2019
Smoke Detector	Admin Building Principal's Office	Tested	8:11:50 AM	08/29/2019
Smoke Detector	Admin Building Reception	Tested	8:10:19 AM	08/29/2019
Smoke Detector	Admin Building Reception Front Office	Tested	8:11:01 AM	08/29/2019
Smoke Detector	Admin Building Reception Telecom Room	Tested	8:09:52 AM	08/29/2019
Smoke Detector	Admin Building Staff Lounge	Tested	8:18:01 AM	08/29/2019
Smoke Detector	Admin Building Staff Lounge Telecom Room	Tested	8:20:39 AM	08/29/2019
Smoke Detector	Admin Building Workroom Behind Reception	Tested	8:05:07 AM	08/29/2019
Smoke Detector	Classroom 1 Storage	Tested	8:58:55 AM	08/29/2019
Smoke Detector	Classroom 1 Storage	Tested	8:59:37 AM	08/29/2019
Smoke Detector	Classroom 1	Tested	8:51:22 AM	08/29/2019
Smoke Detector	Classroom 1	Tested	8:58:20 AM	08/29/2019
Smoke Detector	Classroom 1	Tested	8:58:29 AM	08/29/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Classroom 1	Tested	8:58:34 AM	08/29/2019
Smoke Detector	Classroom 11	Tested	8:40:47 AM	08/29/2019
Smoke Detector	Classroom 11	Tested	8:41:08 AM	08/29/2019
Smoke Detector	Classroom 12	Tested	8:44:38 AM	08/29/2019
Smoke Detector	Classroom 12	Tested	8:45:28 AM	08/29/2019
Smoke Detector	Classroom 13	Tested	8:45:56 AM	08/29/2019
Smoke Detector	Classroom 13	Tested	8:46:22 AM	08/29/2019
Smoke Detector	Classroom 14	Tested	8:46:32 AM	08/29/2019
Smoke Detector	Classroom 14	Tested	8:46:42 AM	08/29/2019
Smoke Detector	Classroom 15	Tested	9:30:58 AM	08/29/2019
Smoke Detector	Classroom 15	Tested	9:31:13 AM	08/29/2019
Smoke Detector	Classroom 16	Tested	9:31:32 AM	08/29/2019
Smoke Detector	Classroom 16	Tested	9:32:02 AM	08/29/2019
Smoke Detector	Classroom 17	Tested	9:32:25 AM	08/29/2019
Smoke Detector	Classroom 17	Tested	9:32:37 AM	08/29/2019
Smoke Detector	Classroom 18	Tested	9:32:43 AM	08/29/2019
Smoke Detector	Classroom 18	Tested	9:33:56 AM	08/29/2019
Smoke Detector	Classroom 19	Tested	9:49:53 AM	08/29/2019
Smoke Detector	Classroom 2	Tested	9:00:26 AM	08/29/2019
Smoke Detector	Classroom 2	Tested	9:01:21 AM	08/29/2019
Smoke Detector	Classroom 20	Tested	9:45:59 AM	08/29/2019
Smoke Detector	Classroom 21	Tested	9:44:26 AM	08/29/2019
Smoke Detector	Classroom 21	Tested	9:44:38 AM	08/29/2019
Smoke Detector	Classroom 22 Office C	Tested	10:23:41 AM	08/29/2019
Smoke Detector	Classroom 22 Storage Room	Tested	10:21:40 AM	08/29/2019
Smoke Detector	Classroom 22 Storage Room	Tested	10:22:49 AM	08/29/2019
Smoke Detector	Classroom 22	Tested	10:19:41 AM	08/29/2019
Smoke Detector	Classroom 22	Tested	10:20:51 AM	08/29/2019
Smoke Detector	Classroom 22	Tested	10:20:56 AM	08/29/2019
Smoke Detector	Classroom 22	Tested	10:21:03 AM	08/29/2019
Smoke Detector	Classroom 23 Office B	Tested	10:24:06 AM	08/29/2019
Smoke Detector	Classroom 23 Preparation Room	Tested	10:25:24 AM	08/29/2019
Smoke Detector	Classroom 23	Tested	10:24:29 AM	08/29/2019
Smoke Detector	Classroom 23	Tested	10:24:43 AM	08/29/2019
Smoke Detector	Classroom 23	Tested	10:24:47 AM	08/29/2019
Smoke Detector	Classroom 23	Tested	10:24:51 AM	08/29/2019
Smoke Detector	Classroom 24 Office A	Tested	10:26:34 AM	08/29/2019
Smoke Detector	Classroom 24	Tested	10:26:12 AM	08/29/2019
Smoke Detector	Classroom 24	Tested	10:26:23 AM	08/29/2019
Smoke Detector	Classroom 25 Electrical Room	Tested	10:29:25 AM	08/29/2019
Smoke Detector	Classroom 25 Storage Room	Tested	10:28:54 AM	08/29/2019
Smoke Detector	Classroom 25	Tested	10:27:40 AM	08/29/2019
Smoke Detector	Classroom 25	Tested	10:28:02 AM	08/29/2019
Smoke Detector	Classroom 25	Tested	10:28:24 AM	08/29/2019
Smoke Detector	Classroom 26 Preparation Room	Tested	10:36:55 AM	08/29/2019
Smoke Detector	Classroom 26 Storage Room	Tested	10:34:14 AM	08/29/2019
Smoke Detector	Classroom 26	Tested	10:35:17 AM	08/29/2019
Smoke Detector	Classroom 26	Tested	10:35:32 AM	08/29/2019
Smoke Detector	Classroom 26	Tested	10:35:38 AM	08/29/2019
			10:35:42 AM	
Smoke Detector	Classroom 26	Tested	10.33.42 AM	08/29/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Classroom 26	Tested	10:36:45 AM	08/29/201
Smoke Detector	Classroom 27 Storage Room	Tested	10:39:04 AM	08/29/2019
Smoke Detector	Classroom 27	Tested	10:38:34 AM	08/29/2019
Smoke Detector	Classroom 27	Tested	10:38:50 AM	08/29/2019
Smoke Detector	Classroom 28 Work Area	Tested	10:41:13 AM	08/29/201
Smoke Detector	Classroom 28	Tested	10:40:14 AM	08/29/201
Smoke Detector	Classroom 28	Tested	10:40:34 AM	08/29/201
Smoke Detector	Classroom 28	Tested	10:40:40 AM	08/29/201
Smoke Detector	Classroom 28	Tested	10:40:55 AM	08/29/201
Smoke Detector	Classroom 3	Tested	9:02:51 AM	08/29/201
Smoke Detector	Classroom 3	Tested	9:03:03 AM	08/29/201
Smoke Detector	Classroom 3	Tested	9:03:14 AM	08/29/201
Smoke Detector	Classroom 3	Tested	9:03:36 AM	08/29/201
Smoke Detector	Classroom 4	Tested	9:05:02 AM	08/29/201
Smoke Detector	Classroom 4	Tested	9:05:09 AM	08/29/201
Smoke Detector	Classroom 4	Tested	9:05:39 AM	08/29/201
Smoke Detector	Classroom 4	Tested	9:05:45 AM	08/29/201
Smoke Detector	Classroom 5	Tested	9:16:58 AM	08/29/201
Smoke Detector	Classroom 5	Tested	9:17:12 AM	08/29/201
Smoke Detector	Classroom 6	Tested	9:18:04 AM	08/29/201
Smoke Detector	Classroom 6	Tested	9:18:23 AM	08/29/201
Smoke Detector	Classroom 7	Tested	8:43:39 AM	08/29/201
Smoke Detector	Classroom 7	Tested	8:44:21 AM	08/29/201
Smoke Detector	Classroom 8	Tested	8:43:07 AM	08/29/201
Smoke Detector	Classroom 8	Tested	8:43:15 AM	08/29/201
Smoke Detector	Classroom 9	Tested	8:42:06 AM	08/29/201
Smoke Detector	Classroom 9	Tested	8:42:43 AM	08/29/201
Smoke Detector	Computer Lab Audio Workroom	Tested	9:39:21 AM	08/29/201
Smoke Detector	Computer Lab Video Workroom	Tested	9:37:59 AM	08/29/201
Smoke Detector	Computer Lab Workroom Storage	Tested	9:38:32 AM	08/29/201
Smoke Detector	Computer Lab	Tested	9:35:22 AM	08/29/201
Smoke Detector	Computer Lab	Tested	9:35:52 AM	08/29/201
Smoke Detector	Computer Lab	Tested	9:36:32 AM	08/29/201
Smoke Detector	Computer Lab	Tested	9:36:59 AM	08/29/201
Smoke Detector	Corridor Near Classroom 1	Tested	8:48:42 AM	08/29/201
Smoke Detector	Corridor Near Classroom 12	Tested	8:47:45 AM	08/29/201
Smoke Detector	Corridor Near Classroom 7	Tested	8:48:14 AM	08/29/201
Smoke Detector	Corridor Outside Classroom 11	Tested	8:34:46 AM	08/29/201
Smoke Detector	Corridor Outside Classroom 12	Tested	8:33:37 AM	08/29/201
Smoke Detector	Corridor Outside Classroom 12	Tested	8:34:20 AM	08/29/201
Smoke Detector	Corridor Outside Classroom 8	Tested	8:35:51 AM	08/29/201
Smoke Detector	Corridor Outside Classroom 8	Tested	8:36:02 AM	08/29/201
Smoke Detector	Corridor Outside Classroom 1	Tested	8:50:56 AM	08/29/201
Smoke Detector	Corridor Ramp Near Classroom 3	Tested	9:08:52 AM	08/29/201
Smoke Detector	Counseling Office	Tested	8:50:24 AM	08/29/201
Smoke Detector	Electrical Room Near Classroom 5	Tested	9:09:47 AM	08/29/201
Smoke Detector	Electrical Room Near Computer Lab	Tested	9:51:16 AM	08/29/201
Smoke Detector	Electrical Room Outside MPR Building	Tested	11:04:53 AM	08/29/201
Smoke Detector	Electrical Room/Water And Gas Room Outside MPR Building	Tested	11:08:16 AM	08/29/201

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Equipment Storage Room Outside Of Classroom	Tested	9:07:10 AM	08/29/2019
	4			
Smoke Detector	Indoor Janitor's Closer Next To Classroom 4	Tested	9:04:23 AM	08/29/2019
Smoke Detector	Kitchen Food Lines	Tested	10:55:01 AM	08/29/2019
Smoke Detector	Kitchen Food Prep	Tested	10:55:59 AM	08/29/2019
Smoke Detector	Library Corridor Outside Classroom 13	Tested	8:31:57 AM	08/29/2019
Smoke Detector	Library Office	Tested	8:27:40 AM	08/29/2019
Smoke Detector	Library Parent Lounge	Tested	8:28:17 AM	08/29/2019
Smoke Detector	Library Reading Room	Tested	8:22:51 AM	08/29/2019
Smoke Detector	Library	Tested	8:24:08 AM	08/29/2019
Smoke Detector	Library	Tested	8:24:49 AM	08/29/2019
Smoke Detector	Library	Tested	8:24:59 AM	08/29/2019
Smoke Detector	Library	Tested	8:25:50 AM	08/29/2019
Smoke Detector	Library	Tested	8:26:08 AM	08/29/2019
Smoke Detector	Library	Tested	8:26:37 AM	08/29/2019
Smoke Detector	Library (Literacy) Storage Room	Tested	8:30:48 AM	08/29/2019
Smoke Detector	Library Foyer Outside Of Reading Room	Tested	8:23:18 AM	08/29/2019
Smoke Detector	Maintenance Supervisor's Office Storage	Tested	9:42:38 AM	08/29/2019
	Corridor			
Smoke Detector	Maintenance Supervisor's Office	Tested	9:43:39 AM	08/29/2019
Smoke Detector	MPR Building Conference Room/Staff Dining	Tested	10:59:15 AM	08/29/2019
Smoke Detector	MPR Building Conference Room/Staff Dining	Tested	10:59:40 AM	08/29/2019
Smoke Detector	MPR Building Corridor By ISP Classroom m	Tested	12:29:38 PM	08/29/2019
Smoke Detector	MPR Building Corridor By Women's Restroom	Tested	12:31:26 PM	08/29/2019
Smoke Detector	MPR Building Dry Food Storage Across From	Tested	11:00:56 AM	08/29/2019
	Staff Dining			
Smoke Detector	MPR Building ISP Classroom	Tested	12:37:50 PM	08/29/2019
Smoke Detector	MPR Building ISP Classroom	Tested	12:38:13 PM	08/29/2019
Smoke Detector	MPR Building ISP Classroom	Tested	12:40:15 PM	08/29/2019
Smoke Detector	MPR Building ISP Office	Tested	12:42:10 PM	08/29/2019
Smoke Detector	MPR Building ISP Office	Tested	12:45:01 PM	08/29/2019
Smoke Detector	MPR Building ISP Office	Tested	12:45:21 PM	08/29/2019
Smoke Detector	MPR Building ISP Office Corridor	Tested	12:46:26 PM	08/29/2019
Smoke Detector	MPR Building ISP Office Storage	Tested	12:42:26 PM	08/29/2019
Smoke Detector	MPR Building ISP Office Storage	Tested	12:45:28 PM	08/29/2019
Smoke Detector	MPR Building ISP/Speech Classroom	Tested	12:45:50 PM	08/29/2019
Smoke Detector	MPR Building Main Hall	Tested	12:22:32 PM	08/29/2019
Smoke Detector	MPR Building Main Hall	Tested	12:22:51 PM	08/29/2019
Smoke Detector	MPR Building Main Hall	Tested	12:23:01 PM	08/29/2019
Smoke Detector	MPR Building Main Hall	Tested	12:23:06 PM	08/29/2019
Smoke Detector	MPR Building Main Hall	Tested	12:23:15 PM	08/29/2019
Smoke Detector	MPR Building Main Hall	Tested	12:23:23 PM	08/29/2019
Smoke Detector	MPR Building OT Clinic	Tested	12:50:05 PM	08/29/2019
Smoke Detector	MPR Building OT Clinic	Tested	12:50:20 PM	08/29/2019
Smoke Detector	MPR Building OT Clinic	Tested	12:54:11 PM	08/29/2019
Smoke Detector	MPR Building OT Clinic	Tested	12:54:19 PM	08/29/2019
Smoke Detector	MPR Building OT Clinic	Tested	12:54:24 PM	08/29/2019
Smoke Detector	MPR Building OT Clinic Storage Room	Tested	12:52:54 PM	08/29/2019
Smoke Detector	MPR Building Staff Locker Room	Tested	11:01:39 AM	08/29/2019
Smoke Detector	MPR Building Stage	Tested	12:19:36 PM	08/29/2019

Device Type	Location	Service	Time	Date					
	Passed								
Smoke Detector	MPR Building Stage	Tested	12:19:57 PM	08/29/2019					
Smoke Detector	MPR Building Stage Storage Room	Tested	12:20:10 PM	08/29/2019					
Smoke Detector	MPR Corridor Next To Kitchen	Tested	10:57:52 AM	08/29/2019					
Smoke Detector	MPR Custodian Room Next To Kitchen	Tested	10:57:15 AM	08/29/2019					
Smoke Detector	Staff Workroom File Room	Tested	9:14:12 AM	08/29/2019					
Smoke Detector	Staff Workroom Near Psychology Room	Tested	9:12:38 AM	08/29/2019					
Smoke Detector	Staff Workroom Near Psychology Room	Tested	9:13:10 AM	08/29/2019					
Smoke Detector	Staff Workroom Psychology Room	Tested	9:13:30 AM	08/29/2019					
Waterflow Switch	Sprinkler Riser Room Outside Classroom 11 ITV	Tested	1:26:35 PM	08/29/2019					
	Outside Of Classroom 4								

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Lincoln Elementary

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Annunciator	Inspected	2
Battery	Tested	11
Communicator	Tested	1
Control Panel	Tested	1
Heat Detector	Tested	16
Power Supply	Inspected	4
Pull Station	Tested	24
Smoke Detector	Tested	177
Waterflow Switch	Tested	1
Total		237

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - Lincoln Elementary

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

			Ambient	Alarm	🦻 Intell	igibility	Sound
C Location	🗨 Cor	mment	◀ dB	◀ dB	Voice	STI	Test
Passed							
Sound Test Points							
Entire Campus	Passed						0001

Time, Temperature & Level Testing Generated by: BuildingReports.com

Building: NMUSD - Lincoln ElementaryControl Panel: 1 - FCI72								
The Time, Temperature, & Level Testing section details the measurements taken from various devices that are designed to respond in a certain amount of time, respond at a certain temperature, or respond within the acceptable range of volume or level. Items are grouped by Passed or Failed/Other.								
Туре	Location	Comment	Sec	Deg	Lvl	ScanID		
	Passed							
Waterflow Switch								
	Sprinkler Riser Room Outside Classroom 11 ITV Outside Of Classroom 4	Passed	44	n/a	n/a	58090562		

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Lincoln Elementary

Control Panel: 1 - FCI 7200

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category	% of Inventory	Quantity			
Control Panel		Control	0.42%				
Battery		Control	4.62%	11			
Communicator		Control	0.42%	1			
Smoke Detector		Initiating	74.37%	177			
Annunciator		Control	0.84%	2			
Pull Station		Initiating	10.08%	24			
Heat Detector		Initiating	6.72%	16			
Power Supply		Control	1.68%	4			
Waterflow Switch		Initiating	0.42%	1			
Туре	Qty	Model #	Description	Install Date			
				inistan Dute			
		New	(under 90 days)				
FCI							
Control Panel	1	7200		08/29/2019			
In Service - 90 Days - 1 Year							
Battery	2	12V7AH	Sealed Lead Acid	02/19/2019			
		In Service	e - 2 Years to 3 Years				
Battery	9	12V7AH	Sealed Lead Acid	07/19/2017			
FCI							
Annunciator	1			07/19/2017			
Heat Detector	16	ATD-RL2F	Rate-of-Rise	07/19/2017			
Power Supply	4	SNAC-6		07/19/2017			
Pull Station	24	MS-7A	Dual Action	07/19/2017			
Smoke Detector	1	ASD-PL2		07/19/2017			
Smoke Detector	176	ASD-PL2	Photoelectric	07/19/2017			
Silent Knight							
Annunciator	1			07/19/2017			
Communicator	1	5104B		07/19/2017			
System Sensor							
Waterflow Switch	1	WFD40		07/19/2017			

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Mariners Elementary 2100 Mariners Dr Newport Beach, CA 92660

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Sep 6, 2019

> Building: NMUSD - Mariners Elementary Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Beeri Martinez Title: Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD – Mariners Elementary	Contact: Tim	Waller
Address: 2100 Mariners Dr	Phone: 71423	10363
Address:	Fax:	
City/State/Zip: Newport Beach, CA 92660	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Bee	eri Martinez
Address: 2903 Saturn Street	Phone: 714-9	1313100
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: beerim	artinez@calbuildingsystems.com
System Control Unit		
Manufacturer: Simplex	Inspection Da	te: 09/06/2019 IDC Style:
Model Number: 4100U	Install Date: 0	9/06/2019 SLC Style:
Software Version:	Version Date:	09/06/2019 NAC Style:
Location: Bldg. F Admin Office FACP/Custodial Storage	Current Prote	ction: Breaker
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Control	3	5.36%	3	100.00%	3	100.00%	0	0%
Initiating	53	94.64%	53	100.00%	53	100.00%	0	0%
Totals	56	100%	56	100.00%	56	100.00%	0	0%
Certification								
Company: Cal Building Systems	Building: NMUSD – Mariners Elementary							
Inspector: Beeri Martinez	Contact: Tim Waller							
Signed:			Sie	gned:				

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Mariners Elementary

Control Panel: 1 - Simplex 4100U

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Battery	Bldg. F Admin Office FACP/Custodial Storage	Tested	3:28:25 PM	09/06/2019
Battery	Bldg. F Admin Office FACP/Custodial Storage	Tested	3:30:22 PM	09/06/2019
Control Panel	Bldg. F Admin Office FACP/Custodial Storage	Tested	3:25:14 PM	09/06/2019
Initiating				
Heat Detector	Bldg. A Boy's Restroom	Tested	6:32:42 PM	09/06/2019
Heat Detector	Bldg. A FAU Rooms 7&8	Tested	6:33:15 PM	09/06/2019
Heat Detector	Bldg. A FAU Rooms 9&10	Tested	6:33:32 PM	09/06/2019
Heat Detector	Bldg. A Gilr's Restroom	Tested	6:32:51 PM	09/06/2019
Heat Detector	Bldg. B Boy's Restroom	Tested	6:28:13 PM	09/06/2019
Heat Detector	Bldg. B Custodial Closet	Tested	6:28:31 PM	09/06/2019
Heat Detector	Bldg. B FAU Rooms 1&2	Tested	6:27:52 PM	09/06/2019
Heat Detector	Bldg. B Girl's Restroom	Tested	6:28:45 PM	09/06/2019
Heat Detector	Bldg. C Boy's Restroom	Tested	6:36:27 PM	09/06/2019
Heat Detector	Bldg. C FAU Rooms 19&20	Tested	6:36:55 PM	09/06/2019
Heat Detector	Bldg. C FAU Rooms 21&22	Tested	6:37:07 PM	09/06/2019
Heat Detector	Bldg. C Girl's Restroom	Tested	6:36:42 PM	09/06/2019
Heat Detector	Bldg. D FAU Rooms 11&12	Tested	6:35:30 PM	09/06/2019
Heat Detector	Bldg. E FAU Rooms 5&6	Tested	6:33:46 PM	09/06/2019
Heat Detector	Bldg. F Nurse Restroom	Tested	6:27:01 PM	09/06/2019
Heat Detector	Bldg. F Staff Restroom	Tested	6:27:06 PM	09/06/2019
Heat Detector	Bldg. F Staff Restroom	Tested	6:27:47 PM	09/06/2019
Heat Detector	Bldg. F Storage	Tested	6:27:37 PM	09/06/2019
Heat Detector	Bldg. G Children's Restroom K–A	Tested	6:31:07 PM	09/06/2019
Heat Detector	Bldg. G Children's Restroom K–B	Tested	6:30:52 PM	09/06/2019
Heat Detector	Bldg. G Custodial Closet	Tested	6:31:27 PM	09/06/2019
Heat Detector	Bldg. G FAU MPR	Tested	6:31:58 PM	09/06/2019
Heat Detector	Bldg. G Kitchen	Tested	6:31:45 PM	09/06/2019
Heat Detector	Bldg. G Kitchen	Tested	6:32:28 PM	09/06/2019
Heat Detector	Bldg. G Kitchen Restroom	Tested	6:32:15 PM	09/06/2019
Heat Detector	Bldg. G Men's Restroom	Tested	6:29:33 PM	09/06/2019
Heat Detector	Bldg. G MPR Storage	Tested	6:29:13 PM	09/06/2019
Heat Detector	Bldg. G Staff Restroom K–A	Tested	6:30:34 PM	09/06/2019
Heat Detector	Bldg. G Staff Restroom K-B	Tested	6:30:17 PM	09/06/2019
Heat Detector	Bldg. G Women's Restroom	Tested	6:29:59 PM	09/06/2019
Heat Detector	Bldg. H Boy's Restroom	Tested	6:35:10 PM	09/06/2019
Heat Detector	Bldg. H Custodial Closet	Tested	6:34:52 PM	09/06/2019
Heat Detector	Bldg. H FAU Rooms 13&14	Tested	6:34:03 PM	09/06/2019
Heat Detector	Bldg. H FAU Rooms 15&16	Tested	6:34:24 PM	09/06/2019

Device Type	Location	Service	Time	Date			
Passed							
Heat Detector	Bldg. H Girl's Restroom	Tested	6:34:36 PM	09/06/2019			
Heat Detector	Bldg. J FAU Rooms 17&18	Tested	6:37:23 PM	09/06/2019			
Heat Detector	Bldg. K FAU Rooms 23&24	Tested	6:37:41 PM	09/06/2019			
Heat Detector	Bldg. K FAU Rooms 25&26	Tested	6:38:07 PM	09/06/2019			
Heat Detector	Portables Library	Tested	6:40:00 PM	09/06/2019			
Heat Detector	Portables Library	Tested	6:40:09 PM	09/06/2019			
Heat Detector	Portables Room 30	Tested	6:39:42 PM	09/06/2019			
Heat Detector	Portables Room 30	Tested	6:39:51 PM	09/06/2019			
Heat Detector	Portables Room 30	Tested	6:39:55 PM	09/06/2019			
Heat Detector	Portables Room 33	Tested	6:38:22 PM	09/06/2019			
Heat Detector	Portables Room 33	Tested	6:38:41 PM	09/06/2019			
Heat Detector	Portables Room 34	Tested	6:38:47 PM	09/06/2019			
Heat Detector	Portables Room 34	Tested	6:38:56 PM	09/06/2019			
Heat Detector	Portables Room 35	Tested	6:39:30 PM	09/06/2019			
Heat Detector	Portables Room 36	Tested	6:39:11 PM	09/06/2019			
Heat Detector	Portables Room 36	Tested	6:39:21 PM	09/06/2019			
Heat Detector	Portables Room 37	Tested	6:39:00 PM	09/06/2019			
Heat Detector	Portables Room 37	Tested	6:39:07 PM	09/06/2019			
Heat Detector	Custodial Closet	Tested	6:36:01 PM	09/06/2019			

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Mariners Elementary

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Battery	Tested	2
Control Panel	Tested	1
Heat Detector	Tested	53
Total		56

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Mariners Elementary Control Panel: 1 - Simplex 4100U The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference. % of Inventory Quantity **Device or Type** Category **Control Panel** Control 1.79% 1 2 Battery Control 3.57% Heat Detector Initiating 94.64% 53 Qt Type Model # Description **Install Date** y New (under 90 days) Simplex **Control Panel** 1 4100U 09/06/2019 Heat Detector 53 4098-9403 Fixed Temperature 09/06/2019 In Service - 2 Years to 3 Years Sealed Lead Acid Battery 2 12v 24ah 08/10/2017

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Mariners Elementary 2100 Mariners Dr Newport Beach, CA 92660

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Sep 6, 2019

> Building: NMUSD - Mariners Elementary Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: JD Torres Title: Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD - Mariners Elementary	Contact: Tim V	Valler
Address: 2100 Mariners Dr	Phone: 71423	10363
Address:	Fax:	
City/State/Zip: Newport Beach, CA 92660	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: JD T	orres
Address: 2903 Saturn Street	Phone: 909–34	48-3402
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: jdtorres	@calbuildingsystems.com
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Control	15	11.90%	15	100.00%	15	100.00%	0	0%
Initiating	111	88.10%	111	100.00%	111	100.00%	0	0%
Totals	126	100%	126	100.00%	126	100.00%	0	0%
Certification								
Company: Cal Building Systems	Building: NMUSD – Mariners Elementary							
Inspector: JD Torres	Contact: Tim Waller							
Signed:			Sig	gned:				

Notes & Recommendations

Generated by: BuildingReports.com

Building: NMUSD - Mariners Elementary

Control Panel: 1

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

ScanID	Note	Device Type	Location	Comment		
Initiating						
58094058	1	Smoke Detector	Bldg. G Multipurpose Stage	Passed		
Cover	Cover has fallen off					

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Mariners Elementary

Control Panel: 1

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passe	d		
Control				
Battery	Bldg. C Storage Room	Inspected	4:12:30 PM	09/06/2019
Battery	Bldg. C Storage Room	Inspected	4:13:07 PM	09/06/2019
Battery	Bldg. G Storage Room	Inspected	5:26:16 PM	09/06/2019
Battery	Bldg. G Storage Room	Inspected	5:26:30 PM	09/06/2019
Battery	Bldg. H Storage Room	Inspected	4:25:15 PM	09/06/2019
Battery	Bldg. H Storage Room	Inspected	4:25:33 PM	09/06/2019
Battery	Portable Classroom 34	Inspected	3:47:46 PM	09/06/2019
Battery	Portable Classroom 34	Inspected	3:48:20 PM	09/06/2019
Battery	Portable Classroom 37	Inspected	3:56:18 PM	09/06/2019
Battery	Portable Classroom 37	Inspected	3:56:40 PM	09/06/2019
Power Supply	Bldg. C Storage Room	Tested	4:11:49 PM	09/06/2019
Power Supply	Bldg. G Storage Room	Tested	5:26:02 PM	09/06/2019
Power Supply	Bldg. H Storage Room	Tested	4:24:52 PM	09/06/2019
Power Supply	Portable Classroom 34	Tested	3:47:31 PM	09/06/2019
Power Supply	Portable Classroom 37	Tested	3:56:03 PM	09/06/2019
Initiating				
Pull Station	Bldg. F Admin Reception	Tested	5:06:54 PM	09/06/2019
Pull Station	Bldg. G Multipurpose Room	Tested	5:22:19 PM	09/06/2019
Pull Station	Bldg. G Multipurpose Room	Tested	5:22:46 PM	09/06/2019
Pull Station	Bldg. G Multipurpose Room	Tested	5:22:54 PM	09/06/2019
Pull Station	Bldg. G Multipurpose Room	Tested	5:23:47 PM	09/06/2019
Smoke Detector	Bldg. A Classroom 10	Tested	4:50:38 PM	09/06/2019
Smoke Detector	Bldg. A Classroom 10	Tested	4:50:52 PM	09/06/2019
Smoke Detector	Bldg. A Classroom 7	Tested	4:44:43 PM	09/06/2019
Smoke Detector	Bldg. A Classroom 7	Tested	4:45:16 PM	09/06/2019
Smoke Detector	Bldg. A Classroom 8	Tested	4:45:51 PM	09/06/2019
Smoke Detector	Bldg. A Classroom 8	Tested	4:46:01 PM	09/06/2019
Smoke Detector	Bldg. A Classroom 9	Tested	4:48:52 PM	09/06/2019
Smoke Detector	Bldg. A Classroom 9	Tested	4:49:25 PM	09/06/2019
Smoke Detector	Bldg. A Storage Room	Tested	4:40:30 PM	09/06/2019
Smoke Detector	Bldg. B Classroom 1	Tested	5:00:25 PM	09/06/2019
Smoke Detector	Bldg. B Classroom 1	Tested	5:01:02 PM	09/06/2019
Smoke Detector	Bldg. B Classroom 2	Tested	4:58:03 PM	09/06/2019
Smoke Detector	Bldg. B Classroom 2	Tested	4:58:16 PM	09/06/2019
Smoke Detector	Bldg. B Classroom 3	Tested	4:56:41 PM	09/06/2019
Smoke Detector	Bldg. B Classroom 3	Tested	4:56:52 PM	09/06/2019
Smoke Detector	Bldg. B Classroom 4	Tested	4:54:13 PM	09/06/2019
Smoke Detector	Bldg. B Classroom 4	Tested	4:55:21 PM	09/06/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Bldg. B Storage Room	Tested	4:52:45 PM	09/06/2019
Smoke Detector	Bldg. C Classroom 19	Tested	4:17:43 PM	09/06/2019
Smoke Detector	Bldg. C Classroom 19	Tested	4:18:04 PM	09/06/2019
Smoke Detector	Bldg. C Classroom 20	Tested	4:18:14 PM	09/06/2019
Smoke Detector	Bldg. C Classroom 20	Tested	4:18:25 PM	09/06/2019
Smoke Detector	Bldg. C Classroom 21	Tested	4:19:10 PM	09/06/2019
Smoke Detector	Bldg. C Classroom 21	Tested	4:19:21 PM	09/06/2019
Smoke Detector	Bldg. C Classroom 22	Tested	4:21:51 PM	09/06/2019
Smoke Detector	Bldg. C Classroom 22	Tested	4:22:12 PM	09/06/2019
Smoke Detector	Bldg. D Classroom 11	Tested	4:34:02 PM	09/06/2019
Smoke Detector	Bldg. D Classroom 11	Tested	4:35:50 PM	09/06/2019
Smoke Detector	Bldg. D Classroom 12	Tested	4:36:03 PM	09/06/2019
Smoke Detector	Bldg. D Classroom 12	Tested	4:36:17 PM	09/06/2019
Smoke Detector	Bldg. E Classroom 5	Tested	4:41:06 PM	09/06/2019
Smoke Detector	Bldg. E Classroom 5	Tested	4:42:06 PM	09/06/2019
Smoke Detector	Bldg. E Classroom 5	Tested	4:43:29 PM	09/06/2019
Smoke Detector	Bldg. E Classroom 5	Tested	4:44:24 PM	09/06/2019
Smoke Detector	Bldg. F Admin Closet	Tested	5:08:01 PM	09/06/2019
Smoke Detector	Bldg. F Admin Copy Room	Tested	5:03:10 PM	09/06/2019
Smoke Detector	Bldg. F Admin Corridor	Tested	5:03:35 PM	09/06/2019
Smoke Detector	Bldg. F Admin Corridor	Tested	5:05:49 PM	09/06/2019
Smoke Detector	Bldg. F Admin Counseling Office	Tested	5:03:54 PM	09/06/2019
Smoke Detector	Bldg. F Admin Custodian Electrical Room	Tested	3:33:52 PM	09/06/2019
Smoke Detector	Bldg. F Admin Custodian Room	Tested	3:38:03 PM	09/06/2019
Smoke Detector	Bldg. F Admin Nurse Office	Tested	5:04:24 PM	09/06/2019
Smoke Detector	Bldg. F Admin Office	Tested	5:05:18 PM	09/06/2019
Smoke Detector	Bldg. F Admin Office	Tested	5:08:59 PM	09/06/2019
Smoke Detector	Bldg. F Admin Principals Office	Tested	5:08:25 PM	09/06/2019
Smoke Detector	Bldg. F Admin Reception	Tested	5:06:14 PM	09/06/2019
Smoke Detector	Bldg. F Admin Staff Lounge	Tested	5:02:23 PM	09/06/2019
Smoke Detector	Bldg. G Kindergarten A	Tested	5:29:53 PM	09/06/2019
Smoke Detector	Bldg. G Kindergarten A	Tested	5:30:26 PM	09/06/2019
Smoke Detector	Bldg. G Kindergarten A Storage	Tested	5:35:26 PM	09/06/2019
Smoke Detector	Bldg. G Kindergarten B	Tested	5:33:33 PM	09/06/2019
Smoke Detector	Bldg. G Kindergarten B	Tested	5:34:17 PM	09/06/2019
Smoke Detector	Bldg. G Kindergarten B Storage	Tested	5:34:47 PM	09/06/2019
Smoke Detector	Bldg. G Kindergarten Electrical	Tested	5:32:10 PM	09/06/2019
Smoke Detector	Bldg. G Kindergarten Storage	Tested	5:32:41 PM	09/06/2019
Smoke Detector	Bldg. G Kitchen	Tested	5:16:38 PM	09/06/2019
Smoke Detector	Bldg. G Kitchen	Tested	5:17:00 PM	09/06/2019
Smoke Detector	Bldg. G Kitchen Dry Storage	Tested	5:17:15 PM	09/06/2019
Smoke Detector	Bldg. G Kitchen Restroom	Tested	5:18:03 PM	09/06/2019
Smoke Detector	Bldg. G Kitchen Storage	Tested	5:15:59 PM	09/06/2019
Smoke Detector	Bldg. G Kitchen Water Heater Room	Tested	5:18:26 PM	09/06/2019
Smoke Detector	Bldg. G Multipurpose	Tested	5:20:45 PM	09/06/2019
Smoke Detector	Bldg. G Multipurpose	Tested	5:20:53 PM	09/06/2019
Smoke Detector	Bldg. G Multipurpose	Tested	5:21:00 PM	09/06/2019
Smoke Detector	Bldg. G Multipurpose	Tested	5:21:09 PM	09/06/2019
Smoke Detector	Bldg. G Multipurpose	Tested	5:21:13 PM	09/06/2019
Smoke Detector	Bldg. G Multipurpose	Tested	5:21:19 PM	09/06/2019
SHOKE DELECTOR	Bidy. a Multipulpose	residu	5.21.15114	09/00/2019

Device Type	Location	Service	Time	Date
	Passe	d		
Smoke Detector	Bldg. G Multipurpose Stage	Tested	5:20:01 PM	09/06/2019
Smoke Detector	Bldg. G Multipurpose Stage	Tested	5:20:33 PM	09/06/2019
Smoke Detector	Bldg. H Classroom 13	Tested	4:31:26 PM	09/06/2019
Smoke Detector	Bldg. H Classroom 13	Tested	4:33:23 PM	09/06/2019
Smoke Detector	Bldg. H Classroom 14	Tested	4:30:43 PM	09/06/2019
Smoke Detector	Bldg. H Classroom 14	Tested	4:31:12 PM	09/06/2019
Smoke Detector	Bldg. H Classroom 15	Tested	4:29:31 PM	09/06/2019
Smoke Detector	Bldg. H Classroom 15	Tested	4:29:54 PM	09/06/2019
Smoke Detector	Bldg. H Classroom 16	Tested	4:27:03 PM	09/06/2019
Smoke Detector	Bldg. H Classroom 16	Tested	4:27:55 PM	09/06/2019
Smoke Detector	Bldg. H Storage Room	Tested	4:23:54 PM	09/06/2019
Smoke Detector	Bldg. J Classroom 17	Tested	4:13:55 PM	09/06/2019
Smoke Detector	Bldg. J Classroom 17	Tested	4:14:43 PM	09/06/2019
Smoke Detector	Bldg. J Classroom 18	Tested	4:16:08 PM	09/06/2019
Smoke Detector	Bldg. J Classroom 18	Tested	4:16:34 PM	09/06/2019
Smoke Detector	Bldg. K Classroom 23	Tested	4:07:34 PM	09/06/2019
Smoke Detector	Bldg. K Classroom 23	Tested	4:07:47 PM	09/06/2019
Smoke Detector	Bldg. K Classroom 24	Tested	4:05:52 PM	09/06/2019
Smoke Detector	Bldg. K Classroom 24	Tested	4:06:50 PM	09/06/2019
Smoke Detector	Bldg. K Classroom 25	Tested	4:04:26 PM	09/06/2019
Smoke Detector	Bldg. K Classroom 25	Tested	4:04:47 PM	09/06/2019
Smoke Detector	Bldg. K Classroom 26	Tested	4:00:59 PM	09/06/2019
Smoke Detector	Bldg. K Classroom 26	Tested	4:02:36 PM	09/06/2019
Smoke Detector	Bldg. K Room C	Tested	4:08:51 PM	09/06/2019
Smoke Detector	Bldg. K Room D	Tested	4:09:36 PM	09/06/2019
Smoke Detector	Portable Classroom 30	Tested	3:50:40 PM	09/06/2019
Smoke Detector	Portable Classroom 30	Tested	3:50:59 PM	09/06/2019
Smoke Detector	Portable Classroom 30	Tested	3:51:11 PM	09/06/2019
Smoke Detector	Portable Classroom 30	Tested	3:51:20 PM	09/06/2019
Smoke Detector	Portable Classroom 33	Tested	3:44:22 PM	09/06/2019
Smoke Detector	Portable Classroom 33	Tested	3:45:14 PM	09/06/2019
Smoke Detector	Portable Classroom 34	Tested	3:45:56 PM	09/06/2019
Smoke Detector	Portable Classroom 34	Tested	3:46:21 PM	09/06/2019
Smoke Detector	Portable Classroom 35	Tested	3:49:25 PM	09/06/2019
Smoke Detector	Portable Classroom 35	Tested	3:49:35 PM	09/06/2019
Smoke Detector	Portable Classroom 36	Tested	3:52:45 PM	09/06/2019
Smoke Detector	Portable Classroom 36	Tested	3:53:04 PM	09/06/2019
Smoke Detector	Portable Classroom 37	Tested	3:54:41 PM	09/06/2019
Smoke Detector	Portable Classroom 37	Tested	3:55:17 PM	09/06/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Mariners Elementary

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Battery	Inspected	10
Power Supply	Tested	5
Pull Station	Tested	5
Smoke Detector	Tested	106
Total		126

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Mariners Elementary

Control Panel: 1

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type		Category	% of Inventory	Quantity		
Smoke Detector		Initiating	84.13%	106		
Power Supply		Control	3.97%	5		
Battery		Control	7.94%	10		
Pull Station		Initiating	3.97%	5		
	Qt					
Туре	y	Model #	Description	Install Date		
		New (under 90 days)			
SimplexGrinnell						
Power Supply	5	4099		09/06/2019		
Pull Station	5	4098-9001		09/06/2019		
Smoke Detector	10	4098-9714	Photoelectric	09/06/2019		
	6					
In Service - 2 Years to 3 Years						
SimplexGrinnell						
Battery	10	4099	Sealed Lead Acid	08/01/2017		

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Newport Coast Elementary 6655 Ridge Park Rd Newport Coast, CA 92657

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Oct 23, 2019

> Building: NMUSD - Newport Coast Elementary Contact: Tim Waller Title: M&O Manager

Company: Cal Building Systems Contact: Beeri Martinez Title: Technician

Executive Summary

Generated by: BuildingReports.com

Building Information		
Building: NMUSD - Newport Coast Elementary	Contact: Tim W	aller
Address: 6655 Ridge Park Rd	Phone: 714–23	1-0363
Address:	Fax:	
City/State/Zip: Newport Coast, CA 92657	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Beer	Martinez
Address: 2903 Saturn Street	Phone: 714–91	313100
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: beerimar	tinez@calbuildingsystems.com
System Control Unit		
Manufacturer: Simplex	Inspection Date	: 10/23/2019 IDC Style :
Model Number: 4020	Install Date: 10	/23/2019 SLC Style:
Software Version:	Version Date: 1	0/23/2019 NAC Style:
Location: Bldg. B Admin Office FACP Room	Current Protect	i on : Breaker
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
	Total Items		Serviced		Passed		Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.82%	1	100.00%	0	0%	1	100.00%
Control	25	20.49%	25	100.00%	25	100.00%	0	0%
Initiating	96	78.69%	96	100.00%	96	100.00%	0	0%
Totals	122	100%	122	100.00%	121	99.18%	1	0.82%
Certification Company: Cal Building Systems			Bu	ıilding: NML	JSD – Nev	vport Coast	Elementa	ıry
Inspector: Beeri Martinez			Co	ontact: Tim	Waller			
Blott								
Signed: Oct 23, 2019 8:49:34	PM		Si	gned:				

Discrepancy Report

Generated by: BuildingReports.com

Building: NMUSD - Newport Coast

Control Panel: n/a

Elementary

The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.

Device Type		Manufacturer	ModelNur	mber	Date	Qty		
	Items listed for Recall by Manufacturer							
No recalled items found during this inspection.								
Sound Test	C3 Location		စု Problem	Devi	ce 🚨 Re	ference		
		Sound	Testing					
Sound Test	C3 Location		የ Problem	Devi	ce 🛛 🛱 Re	ference		
Sound Test Points								

Proposed Solutions Report Generated by: BuildingReports.com

Building: N Elementary	NMUSD - Newport	Coast	Cont	rol Pane	l: n/a	
check mark wh	The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.					
ScanID	Location	Solution	Description	Cost	Fix	
		Sound Testing				
Sound Test	:					
0001	Entire Campus	Investigate		T/M		
			PO #: (none)	T/M		

Notes & Recommendations

Generated by: BuildingReports.com

Building: NMUSD - Newport Coast Elementary

Control Panel: n/a

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

ScanID	Note	Device Type	Location	Comment			
0001	1	Sound Test	Entire Campus	Failed Test			
Upon	Upon AV test we pulled a pull station and AV's started to go off, within a few seconds all AV's silenced and						
two tr	oubles ca	me up on panel. First trouble said	d (Card 2, power supply/charger 24 volt B output.)	Second			
troub	trouble (Building A AHU–2 roof duct detector)						
After	After resetting panel went back to normal.						

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Newport Coast Elementary

Control Panel: 1 - Simplex 4020

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Bldg. B Admin Office Entrance	Tested	3:33:45 PM	10/23/2019
Battery	Bldg. B Admin Office FACP Room	Tested	3:15:03 PM	10/23/201
Battery	Bldg. B Admin Office FACP Room	Tested	3:15:12 PM	10/23/201
Battery	Bldg. B Admin Office FACP Room	Tested	3:19:55 PM	10/23/201
Battery	Bldg. B Admin Office FACP Room	Tested	3:20:22 PM	10/23/201
Battery	Bldg. C Electrical Room	Tested	4:11:24 PM	10/23/201
Battery	Bldg. C Electrical Room	Tested	4:11:40 PM	10/23/201
Battery	Bldg. C Librarian Office Electrical Room	Tested	3:50:45 PM	10/23/201
Battery	Bldg. C Librarian Office Electrical Room	Tested	3:51:08 PM	10/23/201
Battery	Bldg. D Electrical Room	Tested	5:25:56 PM	10/23/201
Battery	Bldg. D Electrical Room	Tested	5:26:05 PM	10/23/201
Battery	Bldg. E Electrical Room	Tested	5:04:48 PM	10/23/201
Battery	Bldg. E Electrical Room	Tested	5:04:55 PM	10/23/201
Battery	Bldg. F Electrical Room	Tested	4:35:43 PM	10/23/201
Battery	Bldg. F Electrical Room	Tested	4:36:10 PM	10/23/201
Battery	Bldg. H Electrical Room	Tested	5:40:08 PM	10/23/201
Battery	Bldg. H Electrical Room	Tested	5:40:20 PM	10/23/201
Control Panel	Bldg. B Admin Office FACP Room	Tested	3:08:54 PM	10/23/201
Power Supply	Bldg. B Admin Office FACP Room	Tested	3:19:26 PM	10/23/201
Power Supply	Bldg. C Electrical Room	Tested	4:10:35 PM	10/23/201
Power Supply	Bldg. C Librarian Office Electrical Room	Tested	3:50:13 PM	10/23/201
Power Supply	Bldg. D Electrical Room	Tested	5:25:40 PM	10/23/201
Power Supply	Bldg. E Electrical Room	Tested	5:04:26 PM	10/23/201
Power Supply	Bldg. F Electrical Room	Tested	4:33:30 PM	10/23/201
Power Supply	Bldg. H Electrical Room	Tested	5:39:56 PM	10/23/201
Initiating				
Duct Detector	Bldg. A MPR Back Stage	Tested	6:02:42 PM	10/23/201
Duct Detector	Bldg. C Kindergarten Classroom 1	Tested	4:21:09 PM	10/23/201
Duct Detector	Bldg. C Kindergarten Classroom 2 Storage Room	Tested	4:27:46 PM	10/23/201
Duct Detector	Bldg. C Kindergarten Classroom 2 Storage Room	Tested	4:28:02 PM	10/23/201
Duct Detector	Bldg. C Kindergarten Workroom	Tested	4:20:23 PM	10/23/201
Pull Station	North Bldg. A Kitchen Exit	Tested	5:56:23 PM	10/23/201
Pull Station	North Bldg. B Workroom Exit	Tested	3:38:02 PM	10/23/201
Pull Station	Northeast Bldg. A Kitchen Entrance	Tested	5:57:38 PM	10/23/201
Pull Station	Northeast Bldg. B Admin Office Entrance	Tested	3:32:45 PM	10/23/201

Device Type	Location	Service	Time	Date
	Passed			
Pull Station	Northeast Bldg. C Library Entrance	Tested	3:42:18 PM	10/23/2019
Pull Station	Northwest Bldg. A Kitchen Exit	Tested	5:58:15 PM	10/23/2019
Pull Station	Northwest Bldg. B Admin Office Exit	Tested	3:34:44 PM	10/23/2019
Pull Station	South Bldg. B Admin Office Exit By Principal's	Tested	3:29:04 PM	10/23/2019
	Office			-, -,
Pull Station	South Bldg. C Library Exit	Tested	3:45:22 PM	10/23/2019
Pull Station	Southeast Bldg. B Admin Office Entrance	Tested	3:33:02 PM	10/23/2019
Pull Station	Southwest Bldg. B Admin Office Exit	Tested	3:34:30 PM	10/23/2019
Pull Station	West Bldg. B Teacher's Lounge	Tested	3:40:06 PM	10/23/2019
Pull Station	West Bldg. C Library Exit	Tested	3:43:29 PM	10/23/2019
Pull Station	Bldg. A Electrical Room	Tested	5:54:09 PM	10/23/2019
Pull Station	Bldg. A Janitors Closet	Tested	5:55:12 PM	10/23/2019
Pull Station	Bldg. A MPR Exit	Tested	5:59:30 PM	10/23/2019
Pull Station	Bldg. A MPR Exit	Tested	5:59:55 PM	10/23/2019
Pull Station	Bldg. A MPR Exit	Tested	6:00:43 PM	10/23/2019
Pull Station	Bldg. A MPR Exit	Tested	6:04:13 PM	10/23/2019
Pull Station	Bldg. A MPR Exit	Tested	6:05:10 PM	10/23/2019
Pull Station	Bldg. A MPR Exit	Tested	6:05:18 PM	10/23/2019
Pull Station	Bldg. A MPR Exit	Tested	6:06:17 PM	10/23/2019
Pull Station	Bldg. A MPR Exit	Tested	6:06:39 PM	10/23/2019
Pull Station	Bldg. B Nurse Office	Tested	3:36:47 PM	10/23/2019
Pull Station	Bldg. C Classroom 3	Tested	4:03:51 PM	10/23/2019
Pull Station	Bldg. C Classroom 4	Tested	3:59:40 PM	10/23/2019
Pull Station	Bldg. C Classroom 5	Tested	3:54:09 PM	10/23/2019
Pull Station	Bldg. C Classroom 6	Tested	3:56:47 PM	10/23/2019
Pull Station	Bldg. C Classroom 7	Tested	3:57:45 PM	10/23/2019
Pull Station	Bldg. C Electrical Room	Tested	4:09:20 PM	10/23/2019
Pull Station	Bldg. C Janitors Closet	Tested	4:08:10 PM	10/23/2019
Pull Station		Tested	4:20:53 PM	
Pull Station	Bldg. C Kindergarten Classroom 1		4:29:53 PM	10/23/2019
Pull Station	Bldg. C Kindergarten Classroom 2	Tested Tested	4:12:29 PM	10/23/2019
Pull Station	Bldg. C Kindergarten Entrance Bldg. D Classroom 19	Tested	5:22:51 PM	10/23/2019
Pull Station	Bldg. D Classroom 20	Tested	5:22:25 PM	10/23/2019 10/23/2019
	5		5:33:34 PM	
Pull Station Pull Station	Bldg. D Classroom 21 Bldg. D Classroom 22	Tested Tested	5:33:11 PM	10/23/2019 10/23/2019
Pull Station	Bldg. D Classroom 23 Entrance	Tested	5:27:21 PM	10/23/2019
Pull Station	-		5:26:45 PM	
	Bldg. D Classroom 23 Exit	Tested	5:28:23 PM	10/23/2019
Pull Station	Bldg. D Classroom 24 Entrance	Tested	5:28:07 PM	10/23/2019
Pull Station	Bldg. D Classroom 24 Exit	Tested		10/23/2019
Pull Station	Bldg. D Classroom 25 Entrance	Tested	5:29:37 PM	10/23/2019
Pull Station	Bldg. D Classroom 25 Exit	Tested	5:28:53 PM	10/23/2019
Pull Station	Bldg. D Electrical Room	Tested	5:24:15 PM	10/23/2019
Pull Station	Bldg. D Janitors Closet	Tested	5:32:26 PM	10/23/2019
Pull Station	Bldg. E Classroom 12	Tested	5:20:21 PM	10/23/2019
Pull Station	Bldg. E Classroom 13	Tested	5:19:54 PM	10/23/2019
Pull Station	Bldg. E Classroom 14	Tested	5:18:37 PM	10/23/2019
Pull Station	Bldg. E Classroom 15	Tested	5:18:02 PM	10/23/2019
Pull Station	Bldg. E Classroom 16 Entrance	Tested	5:12:07 PM	10/23/2019
Pull Station	Bldg. E Classroom 16 Exit	Tested	5:11:41 PM	10/23/2019
Pull Station	Bldg. E Classroom 17 Entrance	Tested	5:13:03 PM	10/23/2019
Pull Station	Bldg. E Classroom 17 Exit	Tested	5:12:48 PM	10/23/2019

Cal Building Systems

Device Type	Location	Service	Time	Date
	Passed			
Pull Station	Bldg. E Classroom 18 Entrance	Tested	5:14:27 PM	10/23/2019
Pull Station	Bldg. E Classroom 18 Exit	Tested	5:13:55 PM	10/23/2019
Pull Station	Bldg. E Electrical Room	Tested	5:01:32 PM	10/23/2019
Pull Station	Bldg. E Janitors Closet	Tested	5:17:10 PM	10/23/2019
Pull Station	Bldg. F Classroom 10 Entrance	Tested	4:42:07 PM	10/23/2019
Pull Station	Bldg. F Classroom 10 Exit	Tested	4:41:43 PM	10/23/2019
Pull Station	Bldg. F Classroom 11 Entrance	Tested	4:43:46 PM	10/23/2019
Pull Station	Bldg. F Classroom 11 Exit	Tested	4:43:22 PM	10/23/2019
Pull Station	Bldg. F Classroom 8	Tested	4:39:11 PM	10/23/2019
Pull Station	Bldg. F Classroom 9 Entrance	Tested	4:40:28 PM	10/23/2019
Pull Station	Bldg. F Classroom 9 Exit	Tested	4:39:47 PM	10/23/2019
Pull Station	Bldg. F Electrical Room	Tested	4:32:04 PM	10/23/2019
Pull Station	Bldg. H Classroom 26	Tested	5:36:35 PM	10/23/2019
Pull Station	Bldg. H Classroom 27	Tested	5:35:12 PM	10/23/2019
Pull Station	Bldg. H Classroom 28	Tested	5:43:32 PM	10/23/2019
Pull Station	Bldg. H Classroom 29	Tested	5:43:10 PM	10/23/2019
Pull Station	Bldg. H Electrical Room	Tested	5:37:58 PM	10/23/2019
Pull Station	Bldg. H Janitors Closet	Tested	5:41:59 PM	10/23/2019
Pull Station	Portables Classroom 30	Tested	5:45:48 PM	10/23/2019
Pull Station	Portables Classroom 31	Tested	5:46:24 PM	10/23/2019
Pull Station	Portables Classroom 32	Tested	5:47:59 PM	10/23/2019
Smoke Detector	Bldg. A MPR Exit	Tested	6:04:38 PM	10/23/2019
Smoke Detector	Bldg. B Admin Office FACP Room	Tested	3:15:55 PM	10/23/2019
Smoke Detector	Bldg. C Classroom 3	Tested	4:04:31 PM	10/23/2019
Smoke Detector	Bldg. C Classroom 3	Tested	4:04:38 PM	10/23/2019
Smoke Detector	Bldg. C Classroom 4	Tested	4:00:05 PM	10/23/2019
Smoke Detector	Bldg. C Classroom 4	Tested	4:00:20 PM	10/23/2019
Smoke Detector	Bldg. C Electrical Room	Tested	4:09:29 PM	10/23/2019
Smoke Detector	Bldg. C Librarian Office Electrical Room	Tested	3:47:32 PM	10/23/2019
Smoke Detector	Bldg. D Electrical Room	Tested	5:24:26 PM	10/23/2019
Smoke Detector	Bldg. E Electrical Room	Tested	5:03:12 PM	10/23/2019
Smoke Detector	Bldg. F Electrical Room	Tested	4:32:56 PM	10/23/2019
Smoke Detector	Bldg. H Electrical Room	Tested	5:38:54 PM	10/23/2019
Smoke Detector	Portables Classroom 33	Tested	5:52:19 PM	10/23/2019
Smoke Detector	Portables Classroom 33	Tested	5:52:28 PM	10/23/2019
Smoke Detector	Portables Classroom 34	Tested	5:49:53 PM	10/23/2019
Smoke Detector	Portables Classroom 34	Tested	5:50:09 PM	10/23/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Newport Coast Elementary

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Annunciator	Tested	1
Battery	Tested	16
Control Panel	Tested	1
Duct Detector	Tested	5
Power Supply	Tested	7
Pull Station	Tested	75
Smoke Detector	Tested	16
Total		121

Auxiliary Functions Testing

Generated by: BuildingReports.com

Building: NMUSD - Newport Coast Elementary

Control Panel: 1 - Simplex 4020

The Auxiliary Functions Testing section lists each of the ancillary items, systems, and emergency equipment that are controlled by the system control unit. Items are grouped by Passed or Failed/Other. The items are listed by device type, and a check box is provided to indicate if the test conducted was simulated.

Туре	Location	Comment	ScanID	Simulated
	Passed			
Duct Detector				
AHU Shutdown	Bldg. A MPR Back Stage	Passed	58736219	
AHU Shutdown	Bldg. C Kindergarten Classroom 1	Passed	58736146	
AHU Shutdown	Bldg. C Kindergarten Classroom 2 Storage	Passed	58736147	
	Room			
AHU Shutdown	Bldg. C Kindergarten Classroom 2 Storage	Passed	58736148	
	Room			
AHU Shutdown	Bldg. C Kindergarten Workroom	Passed	58736144	

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - Newport Coast Elementary

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

		Ambient	Alarm	🦻 Intell	igibility	Sound
🗘 Location	 Comment 	◀ dB	◀ dB	Voice	STI	Test
Failed/Other						
Sound Test Points						
Entire Campus	Failed Test					0001

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Newport Coast Elementary

Control Panel: 1 - Simplex 4020

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type		Category	% of Inventory	Quantity	
Control Panel		Control	0.82%	1	
Battery		Control	13.11%	16	
Smoke Detector		Initiating	13.11%	16	
Power Supply		Control	5.74%	7	
Pull Station		Initiating	61.48%	75	
Annunciator		Control	0.82%	1	
Duct Detector		Initiating	4.10%	5	
Sound Test		Sound Test	0.82%	1	
	Qt				
Туре	у	Model #	Description	Install Date	
New (under 90 days)					
Simplex					
Annunciator	1	4606-9101	LCD Display	10/23/2019	
Control Panel	1	4020		10/23/2019	
Duct Detector	5	2098-9806	Photoelectric	10/23/2019	
Power Supply	7	4009		10/23/2019	
Pull Station	75	2099-9795	Keyed	10/23/2019	
Smoke Detector	16	4098-9714	Photoelectric	10/23/2019	
In Service - 2 Years to 3 Years					
Battery	2	12v 18ah	Sealed Lead Acid	07/10/2017	
Battery	2	12v 7ah	Sealed Lead Acid	07/10/2017	
		In Servic	e - 3 Years to 5 Years		
Battery	12	12v 7ah	Sealed Lead Acid	08/10/2015	

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Newport Elementary 1327 W Balboa blvd Newport Beach, CA 92661

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Sep 9, 2019

> Building: NMUSD - Newport Elementary Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: JD Torres Title: Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD - Newport Elementary	Contact: Tim Waller	
Address: 1327 W Balboa blvd	Phone: 7142310363	
Address:	Fax:	
City/State/Zip: Newport Beach, CA 92661	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: JD Torres	
Address: 2903 Saturn Street	Phone: 909-348-3402	
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: jdtorres@calbuild	dingsystems.com
System Control Unit		
Manufacturer: Silent Knight	Inspection Date: 09/09	/2019 IDC Style :
Model Number: IFP-1000	Install Date: 09/09/201	9 SLC Style:
Software Version:	Version Date: 09/09/20	NAC Style:
Location: FACP/Electrical Room By Classroom 4	Current Protection: Brea	aker
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg: Ademco	Model #: VISTA-50P
Test Time/Date: 9/9/19 3:33:51 PM	Restore Time	

Inspection Summary								
Catalana	Total	ltems	Ser	viced	Pa	ssed	Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.47%	1	100.00%	1	100.00%	0	0%
Control	16	7.51%	16	100.00%	14	87.50%	2	12.50%
Initiating	196	92.02%	196	100.00%	196	100.00%	0	0%
Totals	213	100%	213	100.00%	211	99.06%	2	0.94%
Certification								
Company: Cal Building Systems			Bu	ilding: NML	JSD – Nev	/port Eleme	ntary	
Inspector: JD Torres			Co	ontact: Tim	Waller			
Signed:			Sig	gned:				

Discrepancy Report Generated by: BuildingReports.com

Building: N	ilding: NMUSD - Newport Elementary Control Panel: 1 - Silent Knight IFP-1000						
The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.							
Device Type	Manufacturer	ModelNumbe	r Da	ite Qty			
Items listed for Recall by Manufacturer							
No recalled items found during this inspection.							
8 ScanID	C Location	ণ Problem	Address	Reference			
	Con	etrol					
Battery							
58095203	FACP/Electrical Room By Classroom 4	Date Expired	1	NFPA72 Table			
				14.4.2.2 (5)(b)			
58095205	FACP/Electrical Room By Classroom 4	Date Expired	1	NFPA72 Table 14.4.2.2 (5)(b)			
	Code References						
NFPA72 Table 14.4.2.2 (5)(b)	Batteries shall be replaced in accordance manufacturer or when the recharged ba recommendations						

Proposed Solutions Report

Generated by: BuildingReports.com

Building: NMUSD - Newport Elementary Control Panel: 1 - Silent Knight IFP-1000

The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.

ScanID	Location	Solution	Model #	Cost	Fix
	Со	ntrol			
Battery					
58095203	FACP/Electrical Room By Classroom 4	Replace	12v 7ah	T/M	
58095205	FACP/Electrical Room By Classroom 4	Replace	12v 7ah	T/M	
			PO #: (none)	T/M	

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Newport Elementary

Control Panel: 1 - Silent Knight IFP-1000

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Main Office	Tested	4:21:01 PM	09/09/2019
Battery	Classroom 23 Storage	Tested	5:40:40 PM	09/09/2019
Battery	Classroom 23 Storage	Tested	5:40:56 PM	09/09/2019
Battery	Electrical Room By Double Doors	Tested	4:12:16 PM	09/09/2019
Battery	Electrical Room By Double Doors	Tested	4:12:28 PM	09/09/2019
Battery	FACP/Electrical Room By Classroom 4	Tested	3:31:41 PM	09/09/2019
Battery	FACP/Electrical Room By Classroom 4	Tested	3:32:52 PM	09/09/2019
Battery	MPR Back Stage	Tested	4:56:56 PM	09/09/2019
Battery	MPR Back Stage	Tested	4:57:21 PM	09/09/2019
Communicator	FACP/Electrical Room By Classroom 4	Tested	3:33:51 PM	09/09/2019
Control Panel	FACP/Electrical Room By Classroom 4	Tested	3:30:20 PM	09/09/2019
Power Supply	Classroom 23 Storage	Tested	5:40:20 PM	09/09/2019
Power Supply	Electrical Room By Double Doors	Tested	4:11:29 PM	09/09/2019
Power Supply	MPR Back Stage	Tested	4:56:19 PM	09/09/2019
Initiating				
Heat Detector	Above Library Attic	Tested	6:08:35 PM	09/09/2019
Heat Detector	Attic West	Tested	5:52:41 PM	09/09/2019
Heat Detector	Bldg A Boys Restroom	Tested	5:55:25 PM	09/09/2019
Heat Detector	Bldg A Boys Restroom Attic	Tested	5:56:16 PM	09/09/2019
Heat Detector	Bldg A Girls Restroom	Tested	5:54:44 PM	09/09/2019
Heat Detector	Bldg A Girls Restroom	Tested	5:58:57 PM	09/09/2019
Heat Detector	Bldg A Girls Restroom Attic	Tested	5:54:10 PM	09/09/2019
Heat Detector	Bldg A Janitor Closet	Tested	5:56:48 PM	09/09/2019
Heat Detector	Boys Restroom Bldg B	Tested	6:07:23 PM	09/09/2019
Heat Detector	Boys Restroom Bldg B	Tested	6:08:25 PM	09/09/2019
Heat Detector	Boys Restroom Bldg D	Tested	6:09:15 PM	09/09/2019
Heat Detector	Conference Room Attic	Tested	5:43:51 PM	09/09/2019
Heat Detector	Corr Attic BL.A	Tested	5:48:44 PM	09/09/2019
Heat Detector	Corridor Attic BL.A	Tested	5:45:54 PM	09/09/2019
Heat Detector	Corridor Attic BL.A	Tested	5:57:48 PM	09/09/2019
Heat Detector	Corridor Attic BL.A	Tested	5:58:14 PM	09/09/2019
Heat Detector	Corridor Attic BL.A	Tested	5:58:20 PM	09/09/2019
Heat Detector	Corridor Attic BL.A	Tested	5:58:27 PM	09/09/2019
Heat Detector	Corridor Attic BL.A	Tested	5:58:34 PM	09/09/2019
Heat Detector	Corridor Attic Bldg C	Tested	6:00:58 PM	09/09/2019
Heat Detector	Corridor Attic Bldg C	Tested	6:01:25 PM	09/09/2019
Heat Detector	Corridor Attic Bldg C	Tested	6:01:31 PM	09/09/2019

Device Type	Location	Service	Time	Date
	Pass	ed		
Heat Detector	Corridor Northwest	Tested	5:58:39 PM	09/09/2019
Heat Detector	Corridor Southwest Attic	Tested	6:05:31 PM	09/09/2019
Heat Detector	Corridor West Attic	Tested	6:02:43 PM	09/09/2019
Heat Detector	Electrical BL.B	Tested	6:05:07 PM	09/09/2019
Heat Detector	Faculty Restroom Bldg B	Tested	6:06:51 PM	09/09/2019
Heat Detector	Girls Restroom Bldg D	Tested	6:09:38 PM	09/09/2019
Heat Detector	Janitor Closet Bldg D	Tested	6:09:59 PM	09/09/2019
Heat Detector	Janitor Closet Bldg E	Tested	6:10:58 PM	09/09/2019
Heat Detector	Kitchen	Tested	5:34:36 PM	09/09/2019
Heat Detector	Kitchen	Tested	5:38:51 PM	09/09/2019
Heat Detector	Kitchen	Tested	5:39:15 PM	09/09/2019
Heat Detector	Kitchen	Tested	5:39:28 PM	09/09/2019
Heat Detector	Kitchen Attic	Tested	5:39:00 PM	09/09/2019
Heat Detector	Kitchen Corridor	Tested	5:38:14 PM	09/09/2019
Heat Detector	Kitchen Food Line	Tested	6:00:37 PM	09/09/2019
Heat Detector	Library Attic	Tested	6:14:14 PM	09/09/2019
Heat Detector	Library West	Tested	6:14:37 PM	09/09/2019
Heat Detector	MPR	Tested	5:39:35 PM	09/09/2019
Heat Detector	MPR	Tested	5:39:53 PM	09/09/2019
Heat Detector	MPR	Tested	5:39:57 PM	09/09/2019
Heat Detector	MPR	Tested	5:40:01 PM	09/09/2019
Heat Detector	MPR	Tested	5:40:09 PM	09/09/2019
Heat Detector	MPR	Tested	5:40:15 PM	09/09/2019
Heat Detector	MPR	Tested	5:40:20 PM	09/09/2019
Heat Detector	MPR	Tested	5:40:24 PM	09/09/2019
Heat Detector	MPR	Tested	5:40:28 PM	09/09/2019
Heat Detector	MPR	Tested	5:40:35 PM	09/09/2019
Heat Detector	MPR Stage	Tested	5:41:02 PM	09/09/2019
Heat Detector	MPR Stage	Tested	5:41:14 PM	09/09/2019
Heat Detector	Nurse Attic	Tested	5:43:35 PM	09/09/2019
Heat Detector	Nurse Restroom	Tested	5:42:35 PM	09/09/2019
Heat Detector	Office Restroom	Tested	5:42:20 PM	09/09/2019
Heat Detector	Room 1 Attic	Tested	5:44:49 PM	09/09/2019
Heat Detector	Room 1 Closet	Tested	5:50:18 PM	09/09/2019
Heat Detector	Room 1 Closet	Tested	5:50:41 PM	09/09/2019
Heat Detector	Room 1 Closet	Tested	5:51:54 PM	09/09/2019
Heat Detector	Room 10 Closet	Tested	5:53:20 PM	09/09/2019
Heat Detector	Room 11 Attic	Tested	5:53:52 PM	09/09/2019
Heat Detector	Room 12 Attic	Tested	5:54:58 PM	09/09/2019
Heat Detector	Room 15 Restroom	Tested	5:59:56 PM	09/09/2019
Heat Detector	Room 16	Tested	5:59:25 PM	09/09/2019
Heat Detector	Room 16	Tested	5:59:36 PM	09/09/2019
Heat Detector	Room 16	Tested	5:59:51 PM	09/09/2019
Heat Detector	Room 17 Closet	Tested	6:11:56 PM	09/09/2019
Heat Detector	Room 17 Restroom	Tested	6:12:24 PM	09/09/2019
Heat Detector	Room 18 Restroom	Tested	6:10:28 PM	09/09/2019
Heat Detector	Room 2 Attic	Tested	5:46:32 PM	09/09/2019
Heat Detector	Room 2 Closet	Tested	5:52:18 PM	09/09/2019
Heat Detector	Room 2 Closet	Tested	5:52:33 PM	09/09/2019
Heat Detector	Room 3 Attic	Tested	6:01:55 PM	09/09/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	Room 5 Attic	Tested	6:06:19 PM	09/09/2019
Heat Detector	Room 6 Attic	Tested	6:04:03 PM	09/09/2019
Heat Detector	Room 8 Attic	Tested	5:42:10 PM	09/09/2019
Heat Detector	Room 9 Attic	Tested	5:41:21 PM	09/09/2019
Heat Detector	Storage S Bldg E	Tested	6:11:27 PM	09/09/2019
Heat Detector	Workroom Bldg E	Tested	6:13:29 PM	09/09/2019
Pull Station	Classroom 18	Tested	5:19:08 PM	09/09/2019
Pull Station	Classroom 19B	Tested	5:24:37 PM	09/09/2019
Smoke Detector	Northwest Corridor Hallway By Handicap	Tested	4:14:49 PM	09/09/2019
	Elevator			
Smoke Detector	South Corridor Hallway By Boy's Restroom	Tested	4:42:40 PM	09/09/2019
Smoke Detector	South Corridor Hallway By Classroom 13	Tested	4:45:07 PM	09/09/2019
Smoke Detector	South Corridor Hallway By Custodial Closet	Tested	4:43:16 PM	09/09/2019
Smoke Detector	South Corridor Hallway By Girl's Restroom	Tested	4:32:41 PM	09/09/2019
Smoke Detector	South Custodial Closet	Tested	4:43:40 PM	09/09/2019
Smoke Detector	Southeast Corridor Hallway By Handicap	Tested	4:13:46 PM	09/09/2019
Smoke Detector	Elevator Admin Office Conference Room	Tested	4:27:51 PM	09/09/2019
Smoke Detector	Admin Office Principals Office	Tested	4:26:24 PM	09/09/2019
Smoke Detector	Admin Office Storage	Tested	4:27:06 PM	09/09/2019
Smoke Detector	Admin Office	Tested	4:26:10 PM	09/09/2019
Smoke Detector	Classroom 1	Tested	4:19:22 PM	09/09/2019
Smoke Detector	Classroom 1	Tested	4:19:28 PM	09/09/2019
Smoke Detector	Classroom 10	Tested	4:28:53 PM	09/09/2019
Smoke Detector	Classroom 10	Tested	4:29:01 PM	09/09/2019
Smoke Detector	Classroom 11	Tested	4:30:54 PM	09/09/2019
Smoke Detector	Classroom 11	Tested	4:31:00 PM	09/09/2019
Smoke Detector	Classroom 12 Storage	Tested	4:38:24 PM	09/09/2019
Smoke Detector	Classroom 12	Tested	4:38:14 PM	09/09/2019
Smoke Detector	Classroom 12	Tested	4:38:21 PM	09/09/2019
Smoke Detector	Classroom 13	Tested	4:46:23 PM	09/09/2019
Smoke Detector	Classroom 13	Tested	4:46:30 PM	09/09/2019
Smoke Detector	Classroom 14	Tested	5:03:53 PM	09/09/2019
Smoke Detector	Classroom 14	Tested	5:04:07 PM	09/09/2019
Smoke Detector	Classroom 15 Storage	Tested	5:08:32 PM	09/09/2019
Smoke Detector	Classroom 15	Tested	5:07:58 PM	09/09/2019
Smoke Detector	Classroom 17	Tested	5:16:13 PM	09/09/2019
Smoke Detector	Classroom 17	Tested	5:16:54 PM	09/09/2019
Smoke Detector	Classroom 17	Tested	5:16:57 PM	09/09/2019
Smoke Detector	Classroom 18	Tested	5:17:56 PM	09/09/2019
Smoke Detector	Classroom 18	Tested	5:18:05 PM	09/09/2019
Smoke Detector	Classroom 18	Tested	5:18:09 PM	09/09/2019
Smoke Detector	Classroom 19A	Tested	5:21:04 PM	09/09/2019
Smoke Detector	Classroom 19A	Tested	5:21:11 PM	09/09/2019
Smoke Detector	Classroom 198	Tested	5:23:09 PM	09/09/2019
Smoke Detector	Classroom 19B	Tested	5:23:17 PM	09/09/2019
Smoke Detector	Classroom 2	Tested	4:17:40 PM	09/09/2019
Smoke Detector	Classroom 2	Tested	4:17:46 PM	09/09/2019
Smoke Detector	Classroom 20	Tested	5:25:47 PM	09/09/2019
Smoke Detector	Classroom 20	Tested	5:25:55 PM	09/09/2019
SHOKE DELECTOR		resteu	5.25.551.0	03/03/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Classroom 21	Tested	5:27:47 PM	09/09/2019
Smoke Detector	Classroom 21	Tested	5:27:54 PM	09/09/2019
Smoke Detector	Classroom 22 Storage	Tested	5:33:12 PM	09/09/2019
Smoke Detector	Classroom 22	Tested	5:31:41 PM	09/09/2019
Smoke Detector	Classroom 22	Tested	5:31:49 PM	09/09/2019
Smoke Detector	Classroom 23 Storage	Tested	5:37:54 PM	09/09/2019
Smoke Detector	Classroom 23	Tested	5:37:11 PM	09/09/2019
Smoke Detector	Classroom 23	Tested	5:37:19 PM	09/09/2019
Smoke Detector	Classroom 24	Tested	5:43:06 PM	09/09/2019
Smoke Detector	Classroom 26	Tested	5:35:50 PM	09/09/2019
Smoke Detector	Classroom 27	Tested	5:30:27 PM	09/09/2019
Smoke Detector	Classroom 3	Tested	4:15:55 PM	09/09/2019
Smoke Detector	Classroom 3	Tested	4:16:01 PM	09/09/2019
Smoke Detector	Classroom 4 Storage	Tested	4:15:38 PM	09/09/2019
Smoke Detector	Classroom 4	Tested	4:15:26 PM	09/09/2019
Smoke Detector	Classroom 4	Tested	4:15:33 PM	09/09/2019
Smoke Detector	Classroom 5 Storage	Tested	4:15:19 PM	09/09/2019
Smoke Detector	Classroom 5	Tested	4:15:07 PM	09/09/2019
Smoke Detector	Classroom 5	Tested	4:15:13 PM	09/09/2019
Smoke Detector	Classroom 6 Storage	Tested	4:16:20 PM	09/09/2019
Smoke Detector	Classroom 6 Storage	Tested	4:16:26 PM	09/09/2019
Smoke Detector	Classroom 6	Tested	4:16:07 PM	09/09/2019
Smoke Detector	Classroom 6	Tested	4:16:14 PM	09/09/2019
Smoke Detector	Classroom 7	Tested	4:31:31 PM	09/09/2019
Smoke Detector	Classroom 7	Tested	4:31:37 PM	09/09/2019
Smoke Detector	Classroom 8	Tested	4:36:38 PM	09/09/2019
Smoke Detector	Classroom 8	Tested	4:36:46 PM	09/09/2019
Smoke Detector	Classroom 9 Storage	Tested	4:40:20 PM	09/09/2019
Smoke Detector	Classroom 9	Tested	4:40:08 PM	09/09/2019
Smoke Detector	Classroom 9	Tested	4:40:16 PM	09/09/2019
Smoke Detector	Corridor Hallway By Classroom 13	Tested	4:45:56 PM	09/09/2019
Smoke Detector	Corridor Hallway By Classroom 14	Tested	5:06:06 PM	09/09/2019
Smoke Detector	Corridor Hallway By Classroom 15	Tested	5:06:31 PM	09/09/2019
Smoke Detector	Corridor Hallway By Classroom 16	Tested	5:07:04 PM	09/09/2019
Smoke Detector	Corridor Hallway By Classroom 21	Tested	5:29:47 PM	09/09/2019
Smoke Detector	Corridor Hallway By Classroom 22	Tested	5:30:52 PM	09/09/2019
Smoke Detector	Corridor Hallway By Classroom 23	Tested	5:36:22 PM	09/09/2019
Smoke Detector	Corridor Hallway By Classroom 23	Tested	5:42:28 PM	09/09/2019
Smoke Detector	Corridor Hallway By FACP/Electrical Room	Tested	4:13:39 PM	09/09/2019
Smoke Detector	Corridor Hallway By FACP/Electrical Room	Tested	4:15:01 PM	09/09/2019
Smoke Detector	Corridor Hallway By MPR	Tested	4:47:33 PM	09/09/2019
Smoke Detector	Corridor Hallway Classroom 1	Tested	4:19:57 PM	09/09/2019
Smoke Detector	Corridor Hallway Classroom 10	Tested	4:28:24 PM	09/09/2019
Smoke Detector	Corridor Hallway Classroom 11	Tested	4:29:49 PM	09/09/2019
Smoke Detector	Corridor Hallway Classroom 2	Tested	4:16:57 PM	09/09/2019
Smoke Detector	Corridor Hallway Classroom 3	Tested	4:15:50 PM	09/09/2019
Smoke Detector	Corridor Hallway Classroom 7	Tested	4:31:21 PM	09/09/2019
Smoke Detector	Corridor Hallway Classroom 8	Tested	4:36:21 PM	09/09/2019
Smoke Detector	Corridor Hallway Classroom 9	Tested	4:39:06 PM	09/09/2019
Smoke Detector	Corridor Hallway Custodial/Library	Tested	4:13:58 PM	09/09/2019
SHOKE DELECTOR	Corrigor Hanway Custoular/ Library	resteu		09/09/2019

Device Type	Location	Service	Time	Date				
Passed								
Smoke Detector	Corridor Hallway Double Doors	Tested	4:16:32 PM	09/09/2019				
Smoke Detector	Corridor Hallway Double Doors	Tested	4:16:41 PM	09/09/2019				
Smoke Detector	Corridor Hallway Staff Restroom/Handicap	Tested	4:14:55 PM	09/09/2019				
	Elevator							
Smoke Detector	Corridor Hallway Student Services	Tested	4:41:18 PM	09/09/2019				
Smoke Detector	Custodial Closet By Library	Tested	4:13:52 PM	09/09/2019				
Smoke Detector	Electrical Room By Double Doors	Tested	4:16:38 PM	09/09/2019				
Smoke Detector	FACP/Electrical Room By Classroom 4	Tested	4:12:41 PM	09/09/2019				
Smoke Detector	Kitchen Dry Storage	Tested	5:00:22 PM	09/09/2019				
Smoke Detector	Kitchen	Tested	5:00:56 PM	09/09/2019				
Smoke Detector	Library Break Room	Tested	4:14:19 PM	09/09/2019				
Smoke Detector	Library Storage	Tested	4:14:42 PM	09/09/2019				
Smoke Detector	Library	Tested	4:14:07 PM	09/09/2019				
Smoke Detector	Library	Tested	4:14:13 PM	09/09/2019				
Smoke Detector	Library	Tested	4:14:25 PM	09/09/2019				
Smoke Detector	Library	Tested	4:14:31 PM	09/09/2019				
Smoke Detector	Library	Tested	4:14:36 PM	09/09/2019				
Smoke Detector	Main Office Corridor By Workroom Restroom	Tested	4:23:59 PM	09/09/2019				
Smoke Detector	Main Office Nurse Restroom	Tested	4:22:10 PM	09/09/2019				
Smoke Detector	Main Office Office Manager	Tested	4:24:59 PM	09/09/2019				
Smoke Detector	Main Office Workroom	Tested	4:23:23 PM	09/09/2019				
Smoke Detector	Main Office	Tested	4:20:32 PM	09/09/2019				
Smoke Detector	Main Office	Tested	4:20:50 PM	09/09/2019				
Smoke Detector	MPR Back Stage	Tested	4:57:51 PM	09/09/2019				
Smoke Detector	MPR Street Entrance	Tested	5:02:28 PM	09/09/2019				
Smoke Detector	Student Services	Tested	4:42:06 PM	09/09/2019				
Smoke Detector	Workroom For Classroom 5&6	Tested	4:15:43 PM	09/09/2019				
Device Type	Location	Service	Time	Date				
	Failed/Other							
Control								
Battery	FACP/Electrical Room By Classroom 4	Tested	3:35:24 PM	09/09/2019				
Battery	FACP/Electrical Room By Classroom 4	Tested	3:35:56 PM	09/09/2019				

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Newport Elementary

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity				
Failed/Other						
Battery	Tested	2				
Total		2				
Passed						
Annunciator	Tested	1				
Battery	Tested	8				
Communicator	Tested	1				
Control Panel	Tested	1				
Heat Detector	Tested	78				
Power Supply	Tested	3				
Pull Station	Tested	2				
Smoke Detector	Tested	116				
Total		212				

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - Newport Elementary

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

			Ambient	Alarm	🦻 Intell	igibility	Sound
C Location	🗨 Co	omment	◀ dB	◀ dB	Voice	STI	Test
Passed							
Sound Test Points							
Entire Campus	Passed						0001

Inventory & Warranty Report Generated by: BuildingReports.com

complete inventory count	by devi	ce type and categor	evices and items that are included in your y is provided. Items installed within the la grouped together for easy reference.	
Device or Type		Category	% of Inventory	Quantity
Control Panel		Control	0.47%	1
Battery		Control	4.69%	10
Communicator		Control	0.47%	1
Power Supply		Control	1.41%	3
Smoke Detector		Initiating	54.46%	116
Annunciator		Control	0.47%	1
Pull Station		Initiating	0.94%	2
Heat Detector		Initiating	36.62%	78
Sound Test		Sound Test	0.47%	1
	Qt			
Туре	v	Model #	Description	Install Date
<u> </u>				inistan Dutt
		New	v (under 90 days)	
Silent Knight				
Annunciator	1	5860R		09/09/2019
Control Panel	1	IFP-1000		09/09/2019
Heat Detector	78	SD505-AHS	Fixed Temperature	09/09/2019
Power Supply	2	5496	·	09/09/2019
Power Supply	1	RPS-1000		09/09/2019
Pull Station	2	SD500-PS		09/09/2019
Smoke Detector	11	SD505-APS	Photoelectric	09/09/2019
Smoke Detector	5	50505 745	hotoclectie	0570572015
Smoke Detector	1	SD505-PHOTO	Photoelectric	09/09/2019
				0370372013
_	_		e - 2 Years to 3 Years	
Battery	2	12v 18ah	Sealed Lead Acid	08/15/2017
Battery	6	12v 7ah	Sealed Lead Acid	08/15/2017
Ademco				
Communicator	1	VISTA-50P		08/15/2017
		In Service	e - 5 Years to 10 Years	
Battery	1	12v 7ah	Sealed Lead Acid	07/01/2014
Battery	1	12v 7ah	Sealed Lead Acid	06/01/2014

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Newport Harbor High School 600 Irvine Avenue Newport Beach, CA 92663

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Sep 25, 2019

Building: NMUSD - Newport Harbor High School Contact: Tim Waller Title: Maintenance & Operations Manager Company: Cal Building Systems Contact: Michael Cannon Title: Service Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD – Newport Harbor High School	Contact: Tim Waller	
Address: 600 Irvine Avenue	Phone: 714-231-0363	
Address:	Fax:	
City/State/Zip: Newport Beach, CA 92663	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Michael Cannon	
Address: 2903 Saturn Street	Phone: 714-715-1223	
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: mcannon@calbuilding:	systems.com
System Control Unit		
Manufacturer: Silent Knight	Inspection Date: 09/17/2019	DC Style:
Model Number: IFP-1000	Install Date: 09/17/2019	SLC Style:
Software Version:	Version Date: 12/31/1969	NAC Style:
Location: Robins-Loats Building FACP Room Inside Dining Room 138	Current Protection:	
Monitoring		
Company: Pho	one: Acc	count #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Cotomore	Total Items		Serviced		Passed		Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.11%	1	100.00%	0	0%	1	100.00%
Control	44	4.79%	44	100.00%	44	100.00%	0	0%
Initiating	864	94.12%	864	100.00%	864	100.00%	0	0%
Supervisory	9	0.98%	9	100.00%	8	88.89%	1	11.11%
Totals	918	100%	918	100.00%	916	99.78%	2	0.22%
Certification								
Company: Cal Building Systems			Bı	uilding: NMU	SD – Nev	vport Harbo	r High So	hool
Inspector: Michael Cannon			C	ontact: Tim \	Waller			

al and 44

Signed: Sep 25, 2019 7:03:47 PM

Signed:

Discrepancy Report Generated by: BuildingReports.com

Building: NMUSD - Newport Harbor HighControl Panel: 1 - Silent Knight								
School IFP-1000								
The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.								
Device Type	Manufacturer	ModelNumber	Da	te	Qty			
Items listed for Recall by Manufacturer								
	No recalled items found o	during this inspection.						
8 ScanID	☐ Location							
	Supervi	isory						
Tamper Sw	itch							
58092130	Gymnasium West Outside Off Irvine Blvd. OS&Y	Failed to Report	1	NFPA72 1	7.16.1.1			
Code References								
NFPA72 17.16.1.	NFPA72 17.16.1.1 Two separate and distinct signals shall be initiated: one indicating movement of the valve from its normal position (off-normal), and the other indicating restoration of the valve to its normal position							

Building: NMUSD - Newport Harbor High								
School								
	· •	dates each discrepancy liste			0	0.5		
		gory, and grouped by devic						
		listed for your convenience bsite and is subject to a rec					d on the Co	onsumer
Device Type		Manufacturer		ModelNu	nber	Da	ate	Qty
		Items listed for Red	call	by Manufa	cturei	~		
		No recalled items four	nd dui	ring this inspecti	on.			
Sound Test	C3 Location		Ŷ	Problem		Device	🛄 Ref	erence
		Sound	l Tes	sting				
Sound Test	C3 Location		Ŷ	Problem	0	Device	🛄 Ref	erence
Sound Test Points								
0001	Entire Campus				So	und Test		

Proposed Solutions Report Generated by: BuildingReports.com

U	Building: NMUSD - Newport Harbor High School Control Panel: 1 - Silent Knight IFP-100							
check mark when	The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.							
ScanID	Location	Solution	Model #	Cost	Fix			
Supervisory								
Tamper Sw	itch							
58092130	Gymnasium West Outside Off Irvine Blvd. OS&Y	Adjust	OSY2	T/M				
Building: N High Schoo	MUSD - Newport Harbor l		Cont	trol Panel	l: n/a			
check mark when	The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.							
ScanID	Location	Solution	Description	Cost	Fix			
Sound Testing								
Sound Test								
0001	Entire Campus			T/M				
			PO #: (none)	T/M				

Notes & Recommendations

Generated by: BuildingReports.com

Building: NMUSD - Newport Harbor High School

Control Panel: n/a

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

ScanID	Note	Device Type	Location	Comment		
0001	1	Sound Test	Entire Campus			
A hori	A horn failed to operate during our audio/visual inspection. The location is on the outside wall of the Home					
Arts B	uilding.					

Building: NMUSD - Newport Harbor High School

Control Panel: 1 - Silent Knight IFP-1000

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

ScanID	Note	Device Type	Location	Comment
			Initiating	
58092106	2	Waterflow Switch	Gymnasium West Outside Off Irvine Blvd.	Passed
	ual 87			
58091728	3	Waterflow Switch	Robins–Loats Building Mechanical/Riser Room By Elevator	Passed
	ual 82			
58091729	4	Waterflow Switch	Robins-Loats Building Mechanical/Riser Room By Elevator	Passed
	ual 98			
58091730	5	Waterflow Switch	Robins–Loats Building Mechanical/Riser Room By Elevator	Passed
	ual 82			
58091731	6	Waterflow Switch	Robins-Loats Building Mechanical/Riser Room By Elevator	Passed
	ual 79			
58091732	7	Waterflow Switch	Robins–Loats Building Mechanical/Riser Room By Elevator	Passed
	ual 90			
			Supervisory	
58091755	8	Tamper Switch	Outside Gymnasium Off Irvine Blvd. OS&Y	Passed

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Newport Harbor High School

Control Panel: 1 - Silent Knight IFP-1000

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Robins-Loats Building Admin Reception	Inspected	6:22:21 PM	09/17/2019
Annunciator	Robins-Loats Building Admin Reception	Inspected	6:22:44 PM	09/17/2019
Battery	1st Dodge Hall Classroom 141-Janitor Rm.	Tested	6:29:24 PM	09/17/2019
Battery	1st Dodge Hall Classroom 141-Janitor Rm.	Tested	6:30:01 PM	09/17/2019
Battery	1st Dodge Hall Classroom 141-Janitor Rm.	Tested	6:30:12 PM	09/17/2019
Battery	1st Dodge Hall Classroom 141-Janitor Rm.	Tested	6:30:19 PM	09/17/2019
Battery	1 st Sims Hall Student Leadership Center By Entrance	Tested	5:21:12 PM	09/17/2019
Battery	1 st Sims Hall Student Leadership Center By Entrance	Tested	5:21:36 PM	09/17/2019
Battery	2nd Sims Hall Storage by Classroom 295	Tested	4:58:58 PM	09/18/2019
Battery	2nd Sims Hall Storage by Classroom 295	Tested	4:59:25 PM	09/18/2019
Battery	2nd Robins-Loats Building Prep Room 211A Storage	Tested	5:26:39 PM	09/18/2019
Battery	2nd Robins-Loats Building Prep Room 211A Storage	Tested	5:27:11 PM	09/18/2019
Battery	Small Gym Girl's Locker Room Coach's Office Storage Room	Tested	6:43:33 PM	09/24/2019
Battery	Small Gym Girl's Locker Room Coach's Office Storage Room	Tested	6:43:41 PM	09/24/2019
Battery	Small Gym Girl's Locker Room Coach's Office Storage Room	Tested	6:43:47 PM	09/24/2019
Battery	Small Gym Girl's Locker Room Coach's Office Storage Room	Tested	6:43:54 PM	09/24/2019
Battery	Classroom 170 Storage Room	Tested	7:57:07 PM	09/24/2019
Battery	Classroom 170 Storage Room	Tested	7:57:34 PM	09/24/2019
Battery	Main Gym East Storage Next To Athletics Office	Tested	5:14:40 PM	09/24/2019
Battery	Main Gym East Storage Next To Athletics Office	Tested	5:14:47 PM	09/24/2019
Battery	Main Gym East Storage Next To Athletics Office	Tested	5:14:54 PM	09/24/2019
Battery	Main Gym East Storage Next To Athletics Office	Tested	5:14:58 PM	09/24/2019
Battery	Robins-Loats Building Data Room By Vocal 106	Tested	7:45:26 PM	09/19/2019
Battery	Robins-Loats Building Data Room By Vocal 106	Tested	7:45:59 PM	09/19/2019
Battery	Robins-Loats Building Electrical Room By Office	Tested	6:17:32 PM	09/17/2019
Battery	Robins–Loats Building Electrical Room By Office 121	Tested	6:18:07 PM	09/17/2019
Battery	Robins–Loats Building FACP Room Inside Dining Room 138	Tested	4:34:20 PM	09/17/2019

Device Type	Location	Service	Time	Date
	Passed			
Battery	Robins-Loats Building FACP Room Inside Dining	Tested	4:34:59 PM	09/17/2019
	Room 138			
Battery	Tech Building FACP/Communications Room	Tested	4:43:44 PM	09/17/2019
Battery	Tech Building FACP/Communications Room	Tested	4:44:48 PM	09/17/2019
Control Panel	Robins-Loats Building FACP Room Inside Dining	Tested	4:26:41 PM	09/17/2019
	Room 138			
Power Supply	1st Dodge Hall Classroom 141-Janitor Rm.	Tested	6:28:36 PM	09/17/2019
Power Supply	1st Dodge Hall Classroom 141-Janitor Rm.	Tested	6:30:27 PM	09/17/2019
Power Supply	1st Sims Hall Student Leadership Center By	Tested	5:20:07 PM	09/17/2019
	Entrance			
Power Supply	2nd Sims Hall Storage by Classroom 295	Tested	4:58:02 PM	09/18/2019
Power Supply	2nd Robins-Loats Building Prep Room 211A	Inspected	5:26:13 PM	09/18/2019
	Storage			
Power Supply	Small Gym Girl's Locker Room Coach's Office	Inspected	6:42:11 PM	09/24/2019
	Storage Room			
Power Supply	Small Gym Girl's Locker Room Coach's Office	Inspected	6:42:57 PM	09/24/2019
	Storage Room			
Power Supply	Classroom 170 Storage Room	Inspected	7:56:30 PM	09/24/2019
Power Supply	Main Gym East Storage Next To Athletics Office	Inspected	5:12:21 PM	09/24/2019
Power Supply	Main Gym East Storage Next To Athletics Office	Inspected	5:12:49 PM	09/24/2019
Power Supply	Robins-Loats Building Data Room By Vocal 106	Inspected	7:44:55 PM	09/19/2019
Power Supply	Robins-Loats Building Electrical Room By Office	Inspected	6:17:11 PM	09/17/2019
	121			
Initiating				
Heat Detector	Basement Girls Gym	Tested	6:25:36 PM	09/18/2019
Heat Detector	Basement Girls Gym	Tested	6:27:33 PM	09/18/2019
Heat Detector	Basement Girls Gym	Tested	6:27:49 PM	09/18/2019
Heat Detector	Basement Girls Gym	Tested	6:27:56 PM	09/18/2019
Heat Detector	Basement Girls Gym	Tested	6:28:01 PM	09/18/2019
Heat Detector	Basement Girls Gym	Tested	6:07:37 PM	09/25/2019
Heat Detector	1st Band Closet RR	Tested	6:29:56 PM	09/18/2019
Heat Detector	1st Band Equipment Storage	Tested	6:42:32 PM	09/18/2019
Heat Detector	1st Band RR	Tested	6:41:38 PM	09/18/2019
Heat Detector	1st Band Social Hall	Tested	6:39:52 PM	09/18/2019
Heat Detector	1st Band Social Hall	Tested	6:41:01 PM	09/18/2019
Heat Detector	1st Band Social Hall Corridor	Tested	6:30:33 PM	09/18/2019
Heat Detector	1st Band Storage Rm.	Tested	6:41:09 PM	09/18/2019
Heat Detector	1st Band	Tested	6:31:04 PM	09/18/2019
Heat Detector	1st Band	Tested	6:42:17 PM	09/18/2019
Heat Detector	1st Girl Gym Equipment Office	Tested	6:54:11 PM	09/18/2019
Heat Detector	1st Girl Gym Girls Locker	Tested	6:42:50 PM	09/18/2019
Heat Detector	1st Girl Gym Girls Locker	Tested	6:43:33 PM	09/18/2019
Heat Detector	1st Girl Gym Girls Locker	Tested	6:43:39 PM	09/18/2019
Heat Detector	1st Girl Gym Girls Locker	Tested	6:43:47 PM	09/18/2019
Heat Detector	1st Girl Gym Girls Locker	Tested	6:44:00 PM	09/18/2019
Heat Detector	1st Girl Gym Girls Locker	Tested	6:44:08 PM	09/18/2019
Heat Detector	1st Girl Gym Girls Locker	Tested	6:44:48 PM	09/18/2019
Heat Detector	1st Girl Gym Girls Locker Exit	Tested	6:55:06 PM	09/18/2019
Heat Detector	1st Girl Gym Girls Locker/Shower	Tested	6:56:17 PM	09/18/2019
Heat Detector	1st Girl Gym Girls Locker/Shower	Tested	6:56:46 PM	09/18/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	1st Girl Gym Girls Locker/Shower	Tested	6:56:55 PM	09/18/2019
Heat Detector	1st Girl Gym Girls Locker/Shower	Tested	6:57:02 PM	09/18/2019
Heat Detector	1st Girl Gym Girls Locker/Shower	Tested	6:57:11 PM	09/18/2019
Heat Detector	1st Girl Gym Girls Locker/Shower	Tested	7:00:17 PM	09/18/2019
Heat Detector	1st Girl Gym Girls Locker/Shower	Tested	7:00:34 PM	09/18/2019
Heat Detector	1st Girl Gym Girls Locker/Shower	Tested	7:00:40 PM	09/18/2019
Heat Detector	1st Girl Gym Girls Locker/Shower	Tested	7:00:52 PM	09/18/2019
Heat Detector	1st Girl Gym Girls Locker/Shower	Tested	7:00:58 PM	09/18/2019
Heat Detector	1st Girl Gym Girls Locker/Shower	Tested	7:01:05 PM	09/18/2019
Heat Detector	1st Girl Gym Girls Locker/Shower	Tested	7:01:18 PM	09/18/2019
Heat Detector	1st Girl Gym Girls Locker/Shower	Tested	7:01:24 PM	09/18/2019
Heat Detector	1st Girl Gym Girls Locker/Shower	Tested	7:02:13 PM	09/18/2019
Heat Detector	1st Girl Gym Girls Locker/Shower	Tested	5:06:46 PM	09/19/2019
Heat Detector	1 st Girl Gym Janitor Rm.	Tested	5:07:15 PM	09/19/2019
Heat Detector	1st Girl Gym Mech. Rm.	Tested	6:55:57 PM	09/18/2019
Heat Detector	1st Girl Gym RR	Tested	6:54:26 PM	09/18/2019
Heat Detector	1st Girl Gym RR	Tested	6:54:45 PM	09/18/2019
Heat Detector	1st Girl Gym RR	Tested	6:55:32 PM	09/18/2019
Heat Detector	1st Girls Gym Boys RR	Tested	6:29:22 PM	09/18/2019
Heat Detector	1 st Girls Gym Girls RR	Tested	6:31:33 PM	09/18/2019
Heat Detector	1st Girls Gym Social Hall	Tested	6:31:52 PM	09/18/2019
Heat Detector	1st Home Arts Boys Toilet Rm. 196	Tested	5:31:14 PM	09/24/2019
Heat Detector	1st Home Arts Classroom 169	Tested	7:12:38 PM	09/24/2019
Heat Detector	1st Home Arts Classroom 170	Tested	7:12:54 PM	09/24/2019
Heat Detector	1st Home Arts Classroom 170	Tested	7:12:34 PM	
Heat Detector	1st Home Arts Classroom 171	Tested	7:13:59 PM	09/24/2019
Heat Detector	1st Home Arts Classroom 171	Tested	7:14:16 PM	09/24/2019
	1st Home Arts Classroom 177	Tested	7:15:25 PM	09/24/2019
Heat Detector	1st Home Arts Classroom 172	Tested	7:15:44 PM	09/24/2019
Heat Detector	1st Home Arts Classroom 172	Tested	7:15:54 PM	09/24/2019
Heat Detector			7:16:05 PM	09/24/2019
Heat Detector	1st Home Arts Classroom 173	Tested Tested	7:16:16 PM	09/24/2019
Heat Detector	1st Home Arts Classroom 174 1st Home Arts Classroom 175		7:17:01 PM	09/24/2019
Heat Detector		Tested	7:17:17 PM	09/24/2019
Heat Detector	1st Home Arts Classroom 175 1st Home Arts Classroom 176	Tested	5:31:33 PM	09/24/2019
Heat Detector		Tested	5:31:51 PM	09/24/2019
Heat Detector	1st Home Arts Classroom 176	Tested		09/24/2019
Heat Detector	1st Home Arts Classroom 177	Tested	5:31:58 PM	09/24/2019
Heat Detector	1st Home Arts Classroom 177	Tested	5:32:09 PM 5:32:17 PM	09/24/2019
Heat Detector	1st Home Arts Classroom 178	Tested	5:32:34 PM	09/24/2019
Heat Detector	1st Home Arts Classroom 178	Tested		09/24/2019
Heat Detector	1st Home Arts Classroom 178	Tested	5:32:39 PM	09/24/2019
Heat Detector	1st Home Arts Classroom 179	Tested	7:12:01 PM	09/24/2019
Heat Detector	1st Home Arts Classroom 179	Tested	7:12:26 PM	09/24/2019
Heat Detector	1st Home Arts Classroom 179	Tested	7:12:31 PM	09/24/2019
Heat Detector	1st Home Arts Classroom 181	Tested	7:16:38 PM	09/24/2019
Heat Detector	1st Home Arts Classroom 181	Tested	7:16:54 PM	09/24/2019
Heat Detector	1st Home Arts Girls Toilet Rm. 195	Tested	5:29:48 PM	09/24/2019
Heat Detector	1st Home Arts Office Rm. 184	Tested	5:33:20 PM	09/24/2019
Heat Detector	1st Home Arts Office Rm. 185	Tested	7:14:24 PM	09/24/2019
Heat Detector	1st Home Arts Toilet Rm. 186	Tested	7:14:55 PM	09/24/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	1st Home Arts Workroom 192	Tested	5:33:42 PM	09/24/2019
Heat Detector	1st Home Arts Workroom 193	Tested	5:32:53 PM	09/24/2019
Heat Detector	1st Main Gym Basketball Weight Rm.	Tested	5:11:15 PM	09/19/2019
Heat Detector	1st Main Gym Basketball Weight Rm.	Tested	5:11:30 PM	09/19/2019
Heat Detector	1st Main Gym Basketball Weight Rm.	Tested	5:11:35 PM	09/19/2019
Heat Detector	1st Main Gym Basketball Weight Rm. RR	Tested	5:11:46 PM	09/19/2019
Heat Detector	1st Main Gym Basketball Weight Rm. Shower	Tested	5:10:46 PM	09/19/2019
Heat Detector	1st Main Gym Boys Locker	Tested	6:03:16 PM	09/19/2019
Heat Detector	1st Main Gym Boys Locker	Tested	6:06:48 PM	09/19/2019
Heat Detector	1st Main Gym Boys Locker	Tested	6:07:00 PM	09/19/2019
Heat Detector	1 st Main Gym Boys Locker	Tested	6:07:07 PM	09/19/2019
Heat Detector	1 st Main Gym Boys Locker	Tested	6:07:12 PM	09/19/2019
Heat Detector	1st Main Gym Boys Locker	Tested	6:07:20 PM	09/19/2019
Heat Detector	1st Main Gym Boys Locker	Tested	6:07:27 PM	09/19/2019
Heat Detector	1st Main Gym Boys Shower	Tested	6:04:00 PM	09/19/2019
Heat Detector	1st Main Gym Boys Shower	Tested	6:04:17 PM	09/19/2019
Heat Detector	1st Main Gym Boys Shower	Tested	6:04:23 PM	09/19/2019
Heat Detector	1st Main Gym Boys Shower	Tested	6:05:45 PM	09/19/2019
Heat Detector	1st Main Gym Boys Shower	Tested	6:06:09 PM	09/19/2019
Heat Detector	1st Main Gym Boys Shower	Tested	6:06:18 PM	09/19/2019
Heat Detector		Tested	6:06:26 PM	09/19/2019
	1st Main Gym By Boys Locker Entry		5:09:47 PM	
Heat Detector	1st Main Gym Closet by Weight Rm. RR	Tested	5:14:00 PM	09/19/2019
Heat Detector	1st Main Gym Closet in Storage Rm.	Tested	6:01:28 PM	09/19/2019
Heat Detector	1st Main Gym Corridor	Tested	6:02:27 PM	09/19/2019
Heat Detector	1st Main Gym Corridor	Tested	5:16:40 PM	09/19/2019
Heat Detector	1 st Main Gym Janitor Closet	Tested	6:09:10 PM	09/19/2019
Heat Detector	1 st Main Gym Janitor Closet	Tested	6:08:56 PM	09/19/2019
Heat Detector	1st Main Gym Laundry	Tested	6:03:37 PM	09/19/2019
Heat Detector	1 st Main Gym Mech Rm.	Tested	5:10:16 PM	09/19/2019
Heat Detector	1st Main Gym Mech. Rm.	Tested	6:09:51 PM	09/19/2019
Heat Detector	1st Main Gym Mech. Rm.	Tested	5:13:03 PM	09/19/2019
Heat Detector	1 st Main Gym Men's RR	Tested		09/19/2019
Heat Detector	1st Main Gym Men's RR	Tested	5:14:52 PM	09/19/2019
Heat Detector	1st Main Gym Office	Tested	5:12:36 PM	09/19/2019
Heat Detector	1 st Main Gym Office	Tested	6:02:07 PM	09/19/2019
Heat Detector	1 st Main Gym Outside Ticket Rm.	Tested	5:15:47 PM	09/19/2019
Heat Detector	1 st Main Gym Outside Workroom	Tested	6:08:40 PM	09/19/2019
Heat Detector	1 st Main Gym Refs Office RR	Tested	5:08:31 PM	09/19/2019
Heat Detector	1st Main Gym Speed Line	Tested	6:02:55 PM	09/19/2019
Heat Detector	1st Main Gym Staff Locker	Tested	6:01:49 PM	09/19/2019
Heat Detector	1st Main Gym Staff Locker Toilet	Tested	5:16:14 PM	09/19/2019
Heat Detector	1st Main Gym Storage	Tested	6:08:11 PM	09/19/2019
Heat Detector	1st Main Gym Storage Lockers	Tested	6:04:32 PM	09/19/2019
Heat Detector	1st Main Gym Storage Rm.	Tested	5:13:34 PM	09/19/2019
Heat Detector	1st Main Gym Storage Rm.	Tested	5:14:34 PM	09/19/2019
Heat Detector	1st Main Gym Team Rm.	Tested	5:12:01 PM	09/19/2019
Heat Detector	1st Main Gym Team Rm.	Tested	6:02:37 PM	09/19/2019
Heat Detector	1st Main Gym Team Rm.	Tested	6:10:55 PM	09/19/2019
Heat Detector	1st Main Gym Ticket Rm.	Tested	5:15:30 PM	09/19/2019
Heat Detector	1st Main Gym Toilet	Tested	6:05:28 PM	09/19/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	1st Main Gym Toilet	Tested	6:08:00 PM	09/19/2019
Heat Detector	1st Main Gym Training	Tested	6:05:00 PM	09/19/2019
Heat Detector	1st Main Gym Weight Rm. RR	Tested	5:09:21 PM	09/19/2019
Heat Detector	1st Main Gym Woman's RR	Tested	5:12:49 PM	09/19/2019
Heat Detector	1 st Main Gym Woman's RR	Tested	5:15:10 PM	09/19/2019
Heat Detector	1st Main Gym Workroom	Tested	6:08:25 PM	09/19/2019
Heat Detector	1st Pool Boys Locker Rm.	Tested	7:09:09 PM	09/23/2019
Heat Detector	1st Pool Boys Locker Rm.	Tested	7:10:12 PM	09/23/2019
Heat Detector	1st Pool Boys Locker Rm. Entry	Tested	7:12:08 PM	09/23/2019
Heat Detector	1 st Pool Boys RR Entry	Tested	4:41:17 PM	09/24/2019
Heat Detector	1 st Pool By Boys Toilets	Tested	4:42:08 PM	09/24/2019
Heat Detector	1 st Pool Drying Rm.	Tested	6:11:13 PM	09/19/2019
Heat Detector	1 st Pool Drying Rm.	Tested	7:08:30 PM	09/23/2019
Heat Detector	1 st Pool Electrical Rm.	Tested	4:44:22 PM	09/24/2019
Heat Detector	1st Pool Equipment Rm.	Tested	4:45:52 PM	09/24/2019
Heat Detector	1st Pool Equipment Rm.	Tested	4:46:12 PM	09/24/2019
Heat Detector	1 st Pool Girls Locker	Tested	4:43:40 PM	09/24/2019
Heat Detector	1 st Pool Girls Locker	Tested	4:43:54 PM	09/24/2019
Heat Detector	1st Pool Girls Locker	Tested	4:44:00 PM	09/24/2019
Heat Detector	1 st Pool Girls Toilets	Tested	4:42:55 PM	09/24/2019
Heat Detector	1st Pool Janitor Rm.	Tested	7:10:30 PM	09/23/2019
Heat Detector	1st Pool Mech. Rm.	Tested	4:42:32 PM	
Heat Detector	1st Pool Staff Locker	Tested	4:41:45 PM	09/24/2019
Heat Detector	1st Pool Staff Locker	Tested	4:43:10 PM	09/24/2019
Heat Detector	1 st Pool Storage	Tested	4:44:06 PM	09/24/2019
	1st Pool Storage Rm.	Tested	7:10:57 PM	09/24/2019
Heat Detector	-	Tested	5:24:20 PM	09/23/2019
Heat Detector	1 st Sims Hall Bldg. C Corridor		5:24:20 PM	09/24/2019
Heat Detector	1st Sims Hall Boys Toilet Rm. 192	Tested Tested	5:29:16 PM	09/24/2019
Heat Detector	1st Sims Hall Classroom 157 Entry		5:27:20 PM	09/24/2019
Heat Detector	1st Sims Hall Classroom 170	Tested	5:27:20 PM	09/24/2019
Heat Detector	1st Sims Hall Classroom 170	Tested	5:27:57 PM	09/24/2019
Heat Detector	1st Sims Hall Classroom 183	Tested	5:28:09 PM	09/24/2019
Heat Detector	1 st Sims Hall Classroom 183	Tested		09/24/2019
Heat Detector	1 st Sims Hall Classroom 183	Tested	5:28:15 PM	09/24/2019
Heat Detector	1 st Sims Hall Classroom 288	Tested	4:46:43 PM	09/24/2019
Heat Detector	1 st Sims Hall Classroom 289/290	Tested	4:47:10 PM	09/24/2019
Heat Detector	1 st Sims Hall Classroom 291	Tested	4:47:26 PM	09/24/2019
Heat Detector	1 st Sims Hall Classroom 292	Tested	4:47:38 PM	09/24/2019
Heat Detector	1st Sims Hall Corridor	Tested	5:26:44 PM	09/24/2019
Heat Detector	1st Sims Hall Girls Toilet Rm. 193	Tested	5:25:56 PM	09/24/2019
Heat Detector	1st Sims Hall Men's Toilet Rm. 169	Tested	5:27:00 PM	09/24/2019
Heat Detector	1st Sims Hall SDC – Classroom 166	Tested	5:28:23 PM	09/24/2019
Heat Detector	1st Sims Hall Storage Rm. 179	Tested	5:28:56 PM	09/24/2019
Heat Detector	1st Sims Hall Womans Toilet Rm. 191	Tested	5:26:16 PM	09/24/2019
Heat Detector	1st Sims Hall Woman's Toilet Rm. 191	Tested	5:25:13 PM	09/24/2019
Heat Detector	1st Sims Hall Workroom 276	Tested	4:48:02 PM	09/24/2019
Heat Detector	1st Classroom G306	Tested	7:17:32 PM	09/24/2019
Heat Detector	1st Classroom G306	Tested	7:17:52 PM	09/24/2019
Heat Detector	1st Classroom G306	Tested	7:18:00 PM	09/24/2019
Heat Detector	1st Classroom G306	Tested	7:18:09 PM	09/24/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	1st Classroom G306 Storage	Tested	7:18:17 PM	09/24/2019
Heat Detector	1st Classroom G307	Tested	7:19:11 PM	09/24/2019
Heat Detector	1st Classroom G307	Tested	7:19:33 PM	09/24/2019
Heat Detector	1st Classroom G307	Tested	7:19:39 PM	09/24/2019
Heat Detector	1st Classroom G307	Tested	7:19:46 PM	09/24/2019
Heat Detector	1st Classroom G308	Tested	7:20:41 PM	09/24/2019
Heat Detector	1st Classroom G308	Tested	7:21:07 PM	09/24/2019
Heat Detector	1st Classroom G308	Tested	7:21:13 PM	09/24/2019
Heat Detector	1st Classroom G308	Tested	7:21:20 PM	09/24/2019
Heat Detector	1st Computer Rm. F302	Tested	4:28:36 PM	09/25/2019
Heat Detector	1st Computer Rm. F302	Tested	4:28:58 PM	09/25/2019
Heat Detector	1st Computer Rm. F303	Tested	4:29:12 PM	09/25/2019
Heat Detector	1st Computer Rm. F303	Tested	4:29:22 PM	09/25/2019
Heat Detector	1st Computer Rm. F304	Tested	4:27:01 PM	09/25/2019
Heat Detector	1st Computer Rm. F304	Tested	4:27:32 PM	09/25/2019
Heat Detector	1st Computer Rm. F304	Tested	4:27:37 PM	09/25/2019
Heat Detector	1st Computer Rm. F304	Tested	4:27:43 PM	09/25/2019
Heat Detector	1st Computer Rm. F304	Tested	4:27:51 PM	09/25/2019
Heat Detector	1st Dodge Hall Classroom B140	Tested	5:11:09 PM	09/25/2019
Heat Detector	1st Dodge Hall Classroom B141	Tested	5:11:34 PM	09/25/2019
Heat Detector	1st Dodge Hall Classroom B141	Tested	5:11:48 PM	09/25/2019
Heat Detector	1st Dodge Hall Classroom B142	Tested	5:08:44 PM	09/25/2019
Heat Detector	1st Dodge Hall Classroom B142	Tested	5:10:20 PM	09/25/2019
Heat Detector	-	Tested	5:10:38 PM	
Heat Detector	1st Dodge Hall Classroom B143	Tested	5:10:53 PM	09/25/2019
	1st Dodge Hall Classroom B143		5:08:08 PM	09/25/2019
Heat Detector	1 st Dodge Hall Classroom B144	Tested Tested	5:08:21 PM	09/25/2019
Heat Detector	1st Dodge Hall Classroom B145		5:08:37 PM	09/25/2019
Heat Detector	1st Dodge Hall Classroom B145	Tested Tested	5:07:43 PM	09/25/2019
Heat Detector	1st Dodge Hall Classroom B147	Tested	5:08:00 PM	09/25/2019
Heat Detector	1st Dodge Hall Classroom B147		5:04:57 PM	09/25/2019
Heat Detector	1st Dodge Hall Classroom B149	Tested	5:05:11 PM	09/25/2019
Heat Detector	1 st Dodge Hall Classroom B149	Tested	5:04:16 PM	09/25/2019
Heat Detector	1 st Dodge Hall Classroom B151	Tested	5:04:37 PM	09/25/2019
Heat Detector	1st Dodge Hall Classroom B151	Tested		09/25/2019
Heat Detector	1st Dodge Hall Classroom B153	Tested	5:03:30 PM	09/25/2019
Heat Detector	1st Dodge Hall Classroom B153	Tested	5:03:48 PM	09/25/2019
Heat Detector	1st Dodge Hall Classroom B154	Tested	5:02:24 PM	09/25/2019
Heat Detector	1st Dodge Hall Elevator Landing	Tested	5:05:27 PM	09/25/2019
Heat Detector	1st Dodge Hall Faculty Office B146	Tested	5:07:23 PM	09/25/2019
Heat Detector	1st Dodge Hall Girls Toilet Rm. B148	Tested	5:06:47 PM	09/25/2019
Heat Detector	1st Dodge Hall Girls Toilet Rm. B148	Tested	5:07:13 PM	09/25/2019
Heat Detector	1st Dodge Hall Math Office B160	Tested	5:01:57 PM	09/25/2019
Heat Detector	1st Dodge Hall Nurse Office B155	Tested	5:05:55 PM	09/25/2019
Heat Detector	1st Dodge Hall Nurse Toilet Rm. B157	Tested	5:06:14 PM	09/25/2019
Heat Detector	1st Dodge Hall Office B176	Tested	5:03:08 PM	09/25/2019
Heat Detector	1st Dodge Hall Special Ed. B162	Tested	5:00:17 PM	09/25/2019
Heat Detector	1st Dodge Hall Special Ed. B162	Tested	5:01:26 PM	09/25/2019
Heat Detector	1st Dodge Hall Toilet B162	Tested	5:01:37 PM	09/25/2019
Heat Detector	1st In-House Sups. Rm. F306	Tested	4:28:03 PM	09/25/2019
Heat Detector	1st In-House Sups. Rm. F306	Tested	4:28:28 PM	09/25/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	1st Office F312	Tested	4:26:43 PM	09/25/2019
Heat Detector	1st Toilet F329	Tested	7:21:27 PM	09/24/2019
Heat Detector	1st Toilet G312	Tested	7:18:41 PM	09/24/2019
Heat Detector	1st Workroom G313	Tested	7:20:11 PM	09/24/2019
Heat Detector	2nd Main Gym By Stairs	Tested	5:07:53 PM	09/19/2019
Heat Detector	2nd Main Gym By Stairs	Tested	5:08:14 PM	09/19/2019
Heat Detector	2nd Sims Hall Classroom 185	Tested	5:23:26 PM	09/24/2019
Heat Detector	2nd Sims Hall Classroom 185	Tested	5:23:38 PM	09/24/2019
Heat Detector	2nd Sims Hall Classroom 185	Tested	5:23:44 PM	09/24/2019
Heat Detector	2nd Sims Hall Classroom 188	Tested	5:23:50 PM	09/24/2019
Heat Detector	2nd Sims Hall Classroom 188	Tested	5:24:02 PM	09/24/2019
Heat Detector	2nd Sims Hall Classroom 280	Tested	5:23:04 PM	09/24/2019
Heat Detector	2nd Sims Hall Classroom 281	Tested	5:22:46 PM	09/24/2019
Heat Detector	2nd Sims Hall Classroom 283	Tested	5:22:29 PM	09/24/2019
Heat Detector	2nd Sims Hall Classroom 284	Tested	4:53:44 PM	09/24/2019
Heat Detector	2nd Sims Hall Classroom 285/286	Tested	4:50:39 PM	09/24/2019
Heat Detector	2nd Sims Hall Classroom 287	Tested	4:50:21 PM	09/24/2019
Heat Detector	2nd Sims Hall Classroom 293	Tested	4:52:02 PM	09/24/2019
Heat Detector	2nd Sims Hall Classroom 294	Tested	4:51:26 PM	09/24/2019
Heat Detector	2nd Sims Hall Classroom 295	Tested	4:51:48 PM	09/24/2019
Heat Detector	2nd Sims Hall Classroom 296	Tested	4:52:45 PM	09/24/2019
Heat Detector	2nd Sims Hall Classroom 297	Tested	4:52:59 PM	09/24/2019
Heat Detector	2nd Sims Hall Classroom 297	Tested	4:53:18 PM	09/24/2019
Heat Detector	2nd Sims Hall Corridor 270	Tested	4:49:06 PM	09/24/2019
Heat Detector	2nd Sims Hall Corridor 270	Tested	4:52:21 PM	09/24/2019
Heat Detector	2nd Sims Hall Corridor 270	Tested	4:52:38 PM	09/24/2019
Heat Detector	2nd Sims Hall Corridor 270	Tested	5:22:05 PM	09/24/2019
Heat Detector	2nd Sims Hall Corridor 271	Tested	4:49:29 PM	09/24/2019
Heat Detector	2nd Sims Hall Corridor 271	Tested	4:49:43 PM	09/24/2019
Heat Detector	2nd Sims Hall Corridor 272	Tested	4:50:05 PM	09/24/2019
Heat Detector	2nd Sims Hall Corridor 272	Tested	4:53:30 PM	09/24/2019
Heat Detector	2nd Beek Building Corridor Center (Above	Tested	9:26:36 PM	09/18/2019
	Ceiling)			
Heat Detector	2nd Beek Building Corridor East (Above Ceiling)	Tested	9:22:04 PM	09/18/2019
Heat Detector	2nd Beek Building Corridor West (Above Ceiling)	Tested	9:28:06 PM	09/18/2019
Heat Detector	2nd Beek Building Restroom Entry D253 (Above	Tested	9:29:45 PM	09/18/2019
	Ceiling)			
Heat Detector	2nd Dodge Hall Boys Toilet Rm. B232	Tested	4:37:47 PM	09/25/2019
Heat Detector	2nd Dodge Hall Boys Toilet Rm. B232	Tested	4:38:05 PM	09/25/2019
Heat Detector	2nd Dodge Hall Classroom B242	Tested	4:36:28 PM	09/25/2019
Heat Detector	2nd Dodge Hall Classroom B243	Tested	4:36:43 PM	09/25/2019
Heat Detector	2nd Dodge Hall Classroom B243	Tested	4:36:55 PM	09/25/2019
Heat Detector	2nd Dodge Hall Classroom B244	Tested	4:35:48 PM	09/25/2019
Heat Detector	2nd Dodge Hall Classroom B244	Tested	4:35:59 PM	09/25/2019
Heat Detector	2nd Dodge Hall Classroom B245	Tested	4:36:08 PM	09/25/2019
Heat Detector	2nd Dodge Hall Classroom B245	Tested	4:36:21 PM	09/25/2019
Heat Detector	2nd Dodge Hall Classroom B246	Tested	4:34:36 PM	09/25/2019
Heat Detector	2nd Dodge Hall Classroom B246	Tested	4:34:47 PM	09/25/2019
Heat Detector	2nd Dodge Hall Classroom B247	Tested	4:35:09 PM	09/25/2019
Heat Detector	2nd Dodge Hall Classroom B247	Tested	4:35:43 PM	09/25/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	2nd Dodge Hall Classroom B249	Tested	4:34:17 PM	09/25/2019
Heat Detector	2nd Dodge Hall Classroom B251	Tested	4:33:02 PM	09/25/2019
Heat Detector	2nd Dodge Hall Classroom B253	Tested	4:32:23 PM	09/25/2019
Heat Detector	2nd Dodge Hall Classroom B253	Tested	4:32:36 PM	09/25/2019
Heat Detector	2nd Dodge Hall Classroom B255	Tested	4:31:51 PM	09/25/2019
Heat Detector	2nd Dodge Hall Classroom B255	Tested	4:32:17 PM	09/25/2019
Heat Detector	2nd Dodge Hall Classroom B257	Tested	4:31:04 PM	09/25/2019
Heat Detector	2nd Dodge Hall Classroom B257	Tested	4:31:43 PM	09/25/2019
Heat Detector	2nd Dodge Hall Elevator Landing	Tested	4:32:42 PM	09/25/2019
Heat Detector	2nd Dodge Hall Faculty Office B248	Tested	4:33:55 PM	09/25/2019
Heat Detector	2nd Dodge Hall Girls Toilet B250	Tested	4:33:29 PM	09/25/2019
Heat Detector	2nd Dodge Hall Girls Toilet B250	Tested	4:33:47 PM	09/25/2019
Heat Detector	2nd Dodge Hall Janitor Rm. B236	Tested	4:37:03 PM	09/25/2019
Heat Detector	2nd Dodge Hall Toilet Rm. B236	Tested	4:37:27 PM	09/25/2019
Heat Detector	Beek Building Boy's Restroom D257 (Above	Tested	9:31:23 PM	09/18/2019
	Ceiling)			
Heat Detector	Beek Building Boy's Restroom D257 (Above	Tested	10:20:40 PM	09/18/2019
	Ceiling)			
Heat Detector	Beek Building Classroom D160 (Above Ceiling)	Tested	9:38:42 PM	09/17/2019
Heat Detector	Beek Building Classroom D161 (Above Ceiling)	Tested	9:36:46 PM	09/17/2019
Heat Detector	Beek Building Classroom D162 (Above Ceiling)	Tested	9:36:08 PM	09/17/2019
Heat Detector	Beek Building Classroom D163 (Above Ceiling)	Tested	9:33:42 PM	09/17/2019
Heat Detector	Beek Building Classroom D164 (Above Ceiling)	Tested	9:32:33 PM	09/17/2019
Heat Detector	Beek Building Classroom D165 (Above Ceiling)	Tested	9:29:58 PM	09/17/2019
Heat Detector	Beek Building Classroom D166 (Above Ceiling)	Tested	9:28:38 PM	09/17/2019
Heat Detector	Beek Building Classroom D260 (Above Ceiling)	Tested	9:29:17 PM	09/18/2019
Heat Detector	Beek Building Classroom D261 (Above Ceiling)	Tested	9:28:52 PM	09/18/2019
Heat Detector	Beek Building Classroom D262 (Above Ceiling)	Tested	9:27:33 PM	09/18/2019
Heat Detector	Beek Building Classroom D263 (Above Ceiling)	Tested	9:27:02 PM	09/18/2019
Heat Detector	Beek Building Classroom D263 (Above Ceiling)	Tested	9:27:22 PM	09/18/2019
Heat Detector	Beek Building Classroom D264 (Above Ceiling)	Tested	9:25:51 PM	09/18/2019
Heat Detector	Beek Building Classroom D264 (Above Ceiling)	Tested	9:26:13 PM	09/18/2019
Heat Detector	Beek Building Classroom D265 (Above Ceiling)	Tested	9:23:05 PM	09/18/2019
Heat Detector	Beek Building Classroom D265 (Above Ceiling)	Tested	9:23:40 PM	09/18/2019
Heat Detector	Beek Building Classroom D266 (Above Ceiling)	Tested	9:14:12 PM	09/18/2019
Heat Detector	Beek Building East Corridor (Above Ceiling)	Tested	9:22:56 PM	09/17/2019
Heat Detector	Beek Building East Corridor Center (Above	Tested	9:31:18 PM	09/17/2019
	Ceiling)			
Heat Detector	Beek Building Girl's Restroom (Above Ceiling)	Tested	9:41:27 PM	09/17/2019
Heat Detector	Beek Building Men's Restroom D259 (Above	Tested	9:30:37 PM	09/18/2019
	Ceiling)			
Heat Detector	Beek Building Restroom Entry (Above Ceiling)	Tested	9:40:22 PM	09/17/2019
Heat Detector	Beek Building West Center Corridor (Above Ceiling)	Tested	9:34:51 PM	09/17/2019
Heat Detector	Beek Building West Corridor (Above Ceiling)	Tested	9:37:25 PM	09/17/2019
Heat Detector	Beek Building Women's Restroom D157 (Above Ceiling)	Tested	9:39:36 PM	09/17/2019
Heat Detector	Beek Building Workroom D167 (Above Ceiling)	Tested	9:27:17 PM	09/17/2019
Heat Detector	Beek Building Workroom D167 (Above Ceiling) Beek Building Workroom D267 (Above Ceiling)	Tested	9:42:06 PM	09/17/2019
			10:21:00 PM	
Heat Detector	Beek/Sims Building Elevator Landing	Tested	10.21.00 PM	09/18/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	Dodge Building Boy's Restroom B138	Tested	10:22:21 PM	09/18/2019
Heat Detector	Dodge Building Boy's Restroom B138	Tested	10:23:21 PM	09/18/2019
Heat Detector	Dodge Building Classroom B141	Tested	10:24:08 PM	09/18/2019
Heat Detector	Dodge Building Classroom B141	Tested	10:24:43 PM	09/18/2019
Heat Detector	Dodge Building NHEF B139	Tested	10:23:29 PM	09/18/2019
Pull Station	Main Gym East Exit	Tested	5:49:55 PM	09/24/2019
Pull Station	Main Gym NW Exit	Tested	5:51:41 PM	09/24/2019
Pull Station	Main Gym SW Exit	Tested	5:48:05 PM	09/24/2019
Pull Station	Main Gym West Exit	Tested	5:54:12 PM	09/24/2019
Pull Station	Robins-Loats Building Stage And Auditorium	Tested	7:01:44 PM	09/23/2019
	Lobby By Ticket Booth			
Pull Station	Small Gym SE Exit	Tested	6:50:19 PM	09/24/2019
Pull Station	Small Gym SW Exit	Tested	6:49:14 PM	09/24/2019
Pull Station	Small Gym SW Exit	Tested	6:49:54 PM	09/24/2019
Pull Station	Building F Communications Room	Tested	4:03:24 PM	09/24/2019
Smoke Detector	1st Dodge Hall Classroom 140	Tested	7:06:31 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom 141	Tested	6:25:00 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom 141	Tested	6:25:06 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom 141-Janitor Rm.	Tested	6:26:59 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom 141-Janitor Rm.	Tested	6:31:20 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom 142	Tested	6:23:31 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom 142	Tested	6:23:41 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom 143	Tested	6:21:38 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom 143	Tested	6:21:49 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom 144	Tested	6:18:30 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom 145	Tested	6:19:45 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom 145	Tested	6:19:57 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom 147	Tested	6:16:05 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom 147	Tested	6:16:14 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom 148	Tested	6:14:03 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom 149	Tested	6:11:28 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom 149	Tested	6:11:45 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom 151	Tested	6:09:18 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom 151	Tested	6:09:34 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom 153	Tested	6:04:43 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom 153	Tested	6:05:21 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom 154	Tested	6:06:52 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom 154	Tested	6:07:05 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom 155 ROP	Tested	6:07:59 PM	09/17/2019
Smoke Detector	1st Dodge Hall Classroom by Classroom 144	Tested	6:17:30 PM	09/17/2019
Smoke Detector	1st Dodge Hall Corridor by Classroom 141	Tested	7:08:21 PM	09/17/2019
Smoke Detector	1st Dodge Hall Corridor by Classroom 141	Tested	7:09:06 PM	09/17/2019
Smoke Detector	1st Dodge Hall Corridor by Classroom 143	Tested	7:09:34 PM	09/17/2019
Smoke Detector	1st Dodge Hall Corridor by Classroom 145	Tested	7:10:10 PM	09/17/2019
Smoke Detector	1st Dodge Hall Corridor by Classroom 147	Tested	7:10:42 PM	09/17/2019
Smoke Detector	1st Dodge Hall Corridor by Classroom 153	Tested	6:03:11 PM	09/17/2019
Smoke Detector	1st Dodge Hall Corridor by Classroom 154	Tested	6:02:06 PM	09/17/2019
Smoke Detector	1st Dodge Hall Mechanical Rm.	Tested	6:13:05 PM	09/17/2019
Smoke Detector	1st Dodge Hall Office 139	Tested	7:07:25 PM	09/17/2019
Smoke Detector	1st Sims Hall ASB Office Storage 179	Tested	5:40:11 PM	09/17/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	1st Sims Hall ASB Office Student Store 180	Tested	5:41:18 PM	09/17/201
Smoke Detector	1st Sims Hall ASB Office	Tested	5:34:55 PM	09/17/201
Smoke Detector	1st Sims Hall ASB Office 176	Tested	5:37:21 PM	09/17/201
Smoke Detector	1st Sims Hall ASB Office 177	Tested	5:38:58 PM	09/17/201
Smoke Detector	1st Sims Hall ASB Office 178	Tested	5:39:13 PM	09/17/201
Smoke Detector	1st Sims Hall Classroom 183 Inside back Office 184	Tested	5:49:59 PM	09/17/201
Smoke Detector	1st Sims Hall Classroom 183	Tested	5:46:38 PM	09/17/201
Smoke Detector	1st Sims Hall Classroom 183	Tested	5:46:57 PM	09/17/201
Smoke Detector	1st Sims Hall Classroom 183	Tested	5:47:03 PM	09/17/201
Smoke Detector	1st Sims Hall Classroom 183	Tested	5:49:14 PM	09/17/201
Smoke Detector	1st Sims Hall Classroom 183 & 185 Work Rm.	Tested	5:53:34 PM	09/17/201
Smoke Detector	1st Sims Hall Classroom 185	Tested	5:55:11 PM	09/17/201
Smoke Detector	1st Sims Hall Classroom 185	Tested	5:55:28 PM	09/17/201
Smoke Detector	1st Sims Hall Classroom 185	Tested	5:55:36 PM	09/17/201
Smoke Detector	1st Sims Hall Classroom 185	Tested	5:55:42 PM	09/17/201
Smoke Detector	1st Sims Hall Corridor by Office 184	Tested	5:08:47 PM	09/17/201
Smoke Detector	1st Sims Hall Corridor by Student Office 175	Tested	5:07:43 PM	09/17/201
Smoke Detector	1st Sims Hall Office 174	Tested	5:30:50 PM	09/17/201
Smoke Detector	1st Sims Hall Office 184	Tested	5:26:37 PM	09/17/201
Smoke Detector	1st Sims Hall Office 184	Tested	5:27:04 PM	09/17/201
Smoke Detector	1st Sims Hall Office 184	Tested	5:27:12 PM	09/17/201
Smoke Detector	1st Sims Hall Office 184 Janitor Rm.	Tested	5:32:35 PM	09/17/201
Smoke Detector	1st Sims Hall Student Leadership Center Electrical Room	Tested	5:19:00 PM	09/17/201
Smoke Detector	1st Sims Hall Student Leadership Center Office 189	Tested	5:17:14 PM	09/17/201
Smoke Detector	1 st Sims Hall Student Leadership Center	Tested	5:14:04 PM	09/17/201
Smoke Detector	1st Sims Hall Student Leadership Center	Tested	5:14:28 PM	09/17/201
Smoke Detector	1st Sims Hall Student Leadership Center	Tested	5:14:35 PM	09/17/201
Smoke Detector	1st Sims Hall Student Leadership Center	Tested	5:14:43 PM	09/17/201
Smoke Detector	1 st Sims Hall Student Leadership Center	Tested	5:14:49 PM	09/17/201
Smoke Detector	1st Sims Hall Student Leadership Center	Tested	5:14:56 PM	09/17/201
Smoke Detector	1st Sims Hall Student Services Rm. 181 Office	Tested	5:45:32 PM	09/17/201
Smoke Detector	1st Sims Hall Student Services Rm. 181	Tested	5:44:32 PM	09/17/201
Smoke Detector	1st Beek Hall Classroom 160	Tested	4:35:49 PM	09/17/201
Smoke Detector	1st Beek Hall Classroom 161	Tested	4:36:56 PM	09/17/201
Smoke Detector	1st Beek Hall Classroom 162	Tested	4:37:28 PM	09/17/201
Smoke Detector	1st Beek Hall Classroom 163	Tested	4:38:31 PM	09/17/201
Smoke Detector	1st Beek Hall Classroom 164	Tested	4:38:42 PM	09/17/201
Smoke Detector	1st Beek Hall Classroom 165	Tested	4:38:51 PM	09/17/201
Smoke Detector	1st Beek Hall Classroom 166	Tested	4:39:01 PM	09/17/201
Smoke Detector	1st Beek Hall Corridor by Classroom 161	Tested	4:30:25 PM	09/17/201
Smoke Detector	1st Beek Hall Corridor by Classroom 163	Tested	4:32:22 PM	09/17/201
Smoke Detector	1st Beek Hall Corridor by Classroom 165	Tested	4:32:58 PM	09/17/201
Smoke Detector	1st Beek Hall Corridor by Classroom 166	Tested	4:33:28 PM	09/17/201
Smoke Detector	1st Beek Hall Janitor Room by Classroom 166	Tested	4:44:49 PM	09/17/201
Smoke Detector	1st Beek Hall Workroom by Classroom 165	Tested	4:43:30 PM	09/17/201
Smoke Detector	1st Machine Room in between Beek Hall & Sims Hall	Tested	5:05:47 PM	09/17/201

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	2nd Dodge Hall Classroom 240	Tested	5:32:59 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Classroom 241	Tested	5:31:49 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Classroom 241	Tested	5:31:57 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Classroom 242	Tested	5:30:10 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Classroom 242	Tested	5:30:19 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Classroom 243	Tested	5:28:39 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Classroom 243	Tested	5:28:49 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Classroom 244	Tested	5:27:03 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Classroom 244	Tested	5:27:13 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Classroom 245	Tested	5:25:23 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Classroom 245	Tested	5:25:45 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Classroom 247	Tested	5:23:10 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Classroom 249	Tested	5:22:14 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Classroom 251	Tested	5:20:34 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Classroom 251	Tested	5:20:44 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Classroom 253	Tested	5:18:36 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Classroom 253	Tested	5:18:46 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Classroom 255	Tested	5:16:21 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Classroom 255	Tested	5:16:45 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Corridor by Classroom 241	Tested	5:08:11 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Corridor by Classroom 241	Tested	5:09:07 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Corridor by Classroom 243	Tested	5:10:02 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Corridor by Classroom 245	Tested	5:11:23 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Corridor by Classroom 247	Tested	5:11:57 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Corridor by Classroom 247	Tested	5:12:52 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Corridor by Classroom 251	Tested	5:13:45 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Corridor by Classroom 253	Tested	5:14:29 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Corridor by Classroom 255	Tested	5:14:47 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Corridor by East Stairs	Tested	5:15:08 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Office 238	Tested	5:34:43 PM	09/18/2019
Smoke Detector	2nd Dodge Hall Office 246	Tested	5:24:01 PM	09/18/2019
Smoke Detector	2nd Main Gym Top Of Stairwell	Tested	7:02:11 PM	09/24/2019
Smoke Detector	2nd Main Gym Wrestling Room Office	Tested	7:05:44 PM	09/24/2019
Smoke Detector	2nd Main Gym Wrestling Room Storage	Tested	7:05:31 PM	09/24/2019
Smoke Detector	2nd Main Gym Wrestling Room	Tested	7:04:12 PM	09/24/2019
Smoke Detector	2nd Main Gym Wrestling Room	Tested	7:04:30 PM	09/24/2019
Smoke Detector	2nd Sims Hall Classroom 280	Tested	4:38:21 PM	09/18/2019
Smoke Detector	2nd Sims Hall Classroom 281	Tested	4:39:55 PM	09/18/2019
Smoke Detector	2nd Sims Hall Classroom 281	Tested	4:40:05 PM	09/18/2019
Smoke Detector	2nd Sims Hall Classroom 283	Tested	4:41:12 PM	09/18/2019
Smoke Detector	2nd Sims Hall Classroom 284	Tested	4:44:49 PM	09/18/2019
Smoke Detector	2nd Sims Hall Classroom 285	Tested	4:45:29 PM	09/18/2019
Smoke Detector	2nd Sims Hall Classroom 285	Tested	4:45:40 PM	09/18/2019
Smoke Detector	2nd Sims Hall Classroom 287	Tested	4:47:34 PM	09/18/2019
Smoke Detector	2nd Sims Hall Classroom 288	Tested	4:49:40 PM	09/18/2019
Smoke Detector	2nd Sims Hall Classroom 289	Tested	4:50:13 PM	09/18/2019
Smoke Detector	2nd Sims Hall Classroom 290	Tested	4:50:51 PM	09/18/2019
Smoke Detector	2nd Sims Hall Classroom 291	Tested	4:51:44 PM	09/18/2019
Smoke Detector	2nd Sims Hall Classroom 292	Tested	4:52:31 PM	09/18/2019
Smoke Detector			4:53:02 PM	09/18/2019
	2nd Sims Hall Classroom 292 2nd Sims Hall Classroom 293	Tested		

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	2nd Sims Hall Classroom 294	Tested	4:48:23 PM	09/18/2019
Smoke Detector	2nd Sims Hall Classroom 294	Tested	4:48:34 PM	09/18/2019
Smoke Detector	2nd Sims Hall Classroom 295	Tested	5:00:16 PM	09/18/2019
Smoke Detector	2nd Sims Hall Classroom 297	Tested	4:43:35 PM	09/18/2019
Smoke Detector	2nd Sims Hall Classroom 297	Tested	4:43:46 PM	09/18/2019
Smoke Detector	2nd Sims Hall Corridor by Classroom 281	Tested	4:35:46 PM	09/18/2019
Smoke Detector	2nd Sims Hall Corridor by Classroom 281	Tested	4:36:21 PM	09/18/2019
Smoke Detector	2nd Sims Hall Corridor by Classroom 284	Tested	4:35:08 PM	09/18/2019
Smoke Detector	2nd Sims Hall Corridor by Classroom 286	Tested	4:34:35 PM	09/18/2019
Smoke Detector	2nd Sims Hall Corridor by Classroom 287	Tested	4:33:55 PM	09/18/2019
Smoke Detector	2nd Sims Hall Corridor by Classroom 289	Tested	4:33:21 PM	09/18/2019
Smoke Detector	2nd Sims Hall Corridor by Classroom 290	Tested	4:32:08 PM	09/18/2019
Smoke Detector	2nd Sims Hall Corridor by Classroom 291	Tested	4:31:35 PM	09/18/2019
Smoke Detector	2nd Sims Hall Corridor by Classroom 293	Tested	4:30:54 PM	09/18/2019
Smoke Detector	2nd Sims Hall Corridor by Classroom 295	Tested	4:30:18 PM	09/18/2019
Smoke Detector	2nd Sims Hall Corridor by Classroom 296	Tested	4:29:28 PM	09/18/2019
Smoke Detector	2nd Sims Hall Staff Lounge	Tested	4:53:50 PM	09/18/2019
Smoke Detector	2nd Sims Hall Staff Lounge back room	Tested	4:54:48 PM	09/18/2019
Smoke Detector	2nd Sims Hall Storage by Classroom 295	Tested	4:56:56 PM	09/18/2019
Smoke Detector	2nd Sims Hall Storage by Staff Lounge	Tested	4:56:04 PM	09/18/2019
Smoke Detector	2nd Sims Hall Workroom by West Entrance	Tested	4:36:55 PM	09/18/2019
Smoke Detector	2nd Beek Hall Classroom 260	Tested	5:02:54 PM	09/17/2019
Smoke Detector	2nd Beek Hall Classroom 261	Tested	4:58:56 PM	09/17/2019
Smoke Detector	2nd Beek Hall Classroom 262	Tested	4:52:16 PM	09/17/2019
Smoke Detector	2nd Beek Hall Classroom 263	Tested	4:50:45 PM	09/17/2019
Smoke Detector	2nd Beek Hall Classroom 263	Tested	4:55:08 PM	09/17/2019
Smoke Detector	2nd Beek Hall Classroom 264	Tested	4:50:30 PM	09/17/2019
Smoke Detector	2nd Beek Hall Classroom 264	Tested	4:53:48 PM	09/17/2019
Smoke Detector	2nd Beek Hall Classroom 265	Tested	4:50:16 PM	09/17/2019
Smoke Detector	2nd Beek Hall Classroom 266	Tested	4:49:55 PM	09/17/2019
Smoke Detector	2nd Beek Hall Corridor by Classroom 261	Tested	5:02:09 PM	09/17/2019
Smoke Detector	2nd Beek Hall Corridor by Classroom 262	Tested	5:01:35 PM	09/17/2019
Smoke Detector	·	Tested	5:00:56 PM	09/17/2019
	2nd Beek Hall Corridor by Classroom 263	Tested	4:46:53 PM	
Smoke Detector Smoke Detector	2nd Beek Hall Corridor by Computer Lab 265 2nd Beek Hall Stairs Corridor	Tested	4:46:15 PM	09/17/2019
Smoke Detector	2nd Beek Hall Workroom by Computer Lab 265	Tested	4:48:09 PM	09/17/2019
	2nd Beek Hall Workroom by Computer Lab 265 2nd Beek Hall Workroom by Computer Lab 265		4:48:52 PM	09/17/2019
Smoke Detector Smoke Detector		Tested	5:30:21 PM	09/17/2019
	2nd Robins-Loats Building Classroom 201	Tested	5:30:35 PM	09/18/2019
Smoke Detector	2nd Robins–Loats Building Classroom 201 2nd Robins–Loats Building Classroom 202	Tested	5:33:30 PM	09/18/2019
Smoke Detector	-	Tested	5:33:40 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Classroom 202	Tested		09/18/2019
Smoke Detector	2nd Robins-Loats Building Classroom 203	Tested	5:34:54 PM 5:35:02 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Classroom 203	Tested	5:41:34 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Classroom 204	Tested	5:41:42 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Classroom 204	Tested		09/18/2019
Smoke Detector	2nd Robins-Loats Building Classroom 205	Tested	5:43:45 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Classroom 205	Tested	5:43:55 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Classroom 206	Tested	5:46:08 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Classroom 206	Tested	5:46:18 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Classroom 207	Tested	5:09:48 PM	09/18/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	2nd Robins-Loats Building Classroom 207	Tested	5:10:03 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Classroom 208	Tested	5:15:38 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Classroom 208	Tested	5:15:55 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Classroom 209	Tested	5:17:08 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Classroom 209	Tested	5:17:17 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Classroom 210	Tested	5:17:45 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Classroom 210	Tested	5:17:55 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Classroom 211	Tested	5:22:49 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Classroom 211	Tested	5:23:04 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Classroom 212	Tested	5:28:00 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Classroom 212	Tested	5:28:10 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Corridor By	Tested	7:10:47 PM	09/17/2019
	Classroom 207			
Smoke Detector	2nd Robins-Loats Building Corridor By	Tested	7:11:34 PM	09/17/2019
	Classroom 207			
Smoke Detector	2nd Robins-Loats Building Corridor By	Tested	7:13:58 PM	09/17/2019
	Classroom 208			
Smoke Detector	2nd Robins-Loats Building Corridor By	Tested	7:14:16 PM	09/17/2019
	Classroom 208			
Smoke Detector	2nd Robins-Loats Building Corridor By	Tested	7:15:02 PM	09/17/2019
	Classroom 209			
Smoke Detector	2nd Robins-Loats Building Corridor By	Tested	7:16:36 PM	09/17/2019
	Classroom 210			
Smoke Detector	2nd Robins-Loats Building Corridor By	Tested	7:17:50 PM	09/17/2019
	Classroom 211			
Smoke Detector	2nd Robins-Loats Building Corridor By	Tested	7:18:23 PM	09/17/2019
	Classroom 211			
Smoke Detector	2nd Robins-Loats Building Corridor By	Tested	7:29:44 PM	09/17/2019
	Classroom 212			
Smoke Detector	2nd Robins-Loats Building Corridor Exit By	Tested	7:17:15 PM	09/17/2019
	Classroom 211			
Smoke Detector	2nd Robins-Loats Building Corridor Exit By	Tested	7:30:27 PM	09/17/2019
	Classroom 212			
Smoke Detector	2nd Robins-Loats Building Corridor Skylight By	Tested	7:12:40 PM	09/17/2019
	Classroom 207			
Smoke Detector	2nd Robins-Loats Building Corridor Skylight By	Tested	7:15:46 PM	09/17/2019
	Classroom 209			
Smoke Detector	2nd Robins-Loats Building Corridor Skylight By	Tested	7:29:09 PM	09/17/2019
	Classroom 211			
Smoke Detector	2nd Robins-Loats Building Prep Room 201A	Tested	5:32:20 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Prep Room 203A	Tested	5:36:44 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Prep Room 205A	Tested	5:44:08 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Prep Room 207/208	Tested	5:13:30 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Prep Room 209/210	Tested	5:17:29 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Prep Room 211A	Tested	5:23:50 PM	09/18/2019
Smoke Detector	2nd Robins-Loats Building Prep Room 211A	Tested	5:25:36 PM	09/18/2019
a	Storage		F 01 1	
Smoke Detector	2nd Robins-Loats Building Science Office Next	Tested	5:21:17 PM	09/18/2019
a	To Classroom 210		F 31 36 54	
Smoke Detector	2nd Robins-Loats Building Science Office	Tested	5:21:38 PM	09/18/2019

Device Type	Location	Service	Time	Date
	Passed			
	Restroom Next To Classroom 210			
Smoke Detector	Gymnasium Small Gym NE Equipment Storage Room	Tested	6:28:41 PM	09/24/2019
Smoke Detector	Gymnasium Small Gym NE Equipment Storage Room	Tested	6:30:25 PM	09/24/2019
Smoke Detector	Gymnasium Social Hall Corridor Exit	Tested	6:11:57 PM	09/24/2019
Smoke Detector	Gymnasium Social Hall Gymnastics Room	Tested	6:22:15 PM	09/24/2019
Smoke Detector	Gymnasium Social Hall Gymnastics Room	Tested	6:22:35 PM	09/24/2019
Smoke Detector	Gymnasium Social Hall Gymnastics Room Storage	Tested	6:24:14 PM	09/24/2019
Smoke Detector	Gymnasium Social Hall Gymnastics Room Water Heater Room	Tested	6:26:05 PM	09/24/2019
Smoke Detector	Gymnasium Social Hall Gymnastics Room Workroom	Tested	6:25:00 PM	09/24/2019
Smoke Detector	Gymnasium Social Hall Gymnastics Room Workroom Foyer	Tested	6:25:35 PM	09/24/2019
Smoke Detector	Gymnasium Social Hall Gymnastics Storage Room	Tested	6:26:23 PM	09/24/2019
Smoke Detector	Gymnasium Social Hall Men's Restroom Custodian Room	Tested	6:10:24 PM	09/24/2019
Smoke Detector	Gymnasium Social Hall Storage By Women's Restroom	Tested	6:13:12 PM	09/24/2019
Smoke Detector	Main Gym Boy's Locker Room Athletic Training Room	Tested	5:36:02 PM	09/24/2019
Smoke Detector	Main Gym Boy's Locker Room Athletic Training Room	Tested	5:37:13 PM	09/24/2019
Smoke Detector	Main Gym Boy's Locker Room Coach's Office Lockers	Tested	5:31:24 PM	09/24/2019
Smoke Detector	Main Gym Boy's Locker Room Coach's Office Lounge	Tested	5:31:36 PM	09/24/2019
Smoke Detector	Main Gym Boy's Locker Room Coach's Office Lounge Storage	Tested	5:33:22 PM	09/24/2019
Smoke Detector	Main Gym Boy's Locker Room Coach's Office Restroom	Tested	5:30:44 PM	09/24/2019
Smoke Detector	Main Gym Boy's Locker Room Outside Water Heater Room	Tested	5:38:59 PM	09/24/2019
Smoke Detector	Main Gym Boy's Locker Room Outside Water Heater Room	Tested	5:39:19 PM	09/24/2019
Smoke Detector	Main Gym Concession Room	Tested	5:44:06 PM	09/24/2019
Smoke Detector	Main Gym Corridor Next To Concession Room	Tested	5:45:04 PM	09/24/2019
Smoke Detector	Main Gym NW Ramp Exit	Tested	5:52:33 PM	09/24/2019
Smoke Detector	Main Gym Storage Room Adjacent To Concession Room	Tested	5:45:49 PM	09/24/2019
Smoke Detector	Main Gym Weight Room Storage Outside SE	Tested	5:41:18 PM	09/24/2019
Smoke Detector	Main Gym Weight Room Storage Outside SE	Tested	5:42:04 PM	09/24/2019
Smoke Detector	Main Gym West Corridor Exit	Tested	5:55:53 PM	09/24/2019
Smoke Detector	Main Gym West Shower Room Office	Tested	6:02:36 PM	09/24/2019
Smoke Detector	Main Gym West Shower Room Storage	Tested	6:01:21 PM	09/24/2019
Smoke Detector	Main Gym West Team Locker Room	Tested	5:56:37 PM	09/24/2019
Smoke Detector	Main Gym West Team Office Room	Tested	5:57:47 PM	09/24/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Main Gym West Weight Room	Tested	5:59:35 PM	09/24/2019
Smoke Detector	Robins-Loats Building Stage And Auditorium By	Tested	6:50:19 PM	09/23/2019
Shioke Detector	Wheel Chair Lift	resteu	0.001.01	05/25/2015
Smoke Detector	Robins–Loats Building Stage And Auditorium Control Room	Tested	6:52:26 PM	09/23/2019
Smoke Detector	Robins–Loats Building Stage And Auditorium Control Room	Tested	6:52:40 PM	09/23/2019
Smoke Detector	Robins–Loats Building Stage And Auditorium Corridor By Storage 102A	Tested	6:42:43 PM	09/23/2019
Smoke Detector	Robins-Loats Building Stage And Auditorium Corridor Exit Adjacent To Control Room	Tested	6:55:41 PM	09/23/2019
Smoke Detector	Robins–Loats Building Stage And Auditorium East Trap Pit	Tested	6:47:35 PM	09/23/2019
Smoke Detector	Robins-Loats Building Stage And Auditorium Lobby Custodian Room	Tested	6:58:31 PM	09/23/2019
Smoke Detector	Robins–Loats Building Stage And Auditorium Lobby Entrance	Tested	6:56:50 PM	09/23/2019
Smoke Detector	Robins–Loats Building Stage And Auditorium Lobby Entrance	Tested	6:57:06 PM	09/23/2019
Smoke Detector	Robins–Loats Building Stage And Auditorium Lobby Entrance	Tested	6:57:14 PM	09/23/2019
Smoke Detector	Robins-Loats Building Stage And Auditorium Lobby Ticket Booth	Tested	7:01:53 PM	09/23/2019
Smoke Detector	Robins-Loats Building Stage And Auditorium Lobby Ticket Booth	Tested	7:02:21 PM	09/23/2019
Smoke Detector	Robins–Loats Building Stage And Auditorium Storage 102A	Tested	6:46:57 PM	09/23/2019
Smoke Detector	Robins-Loats Building Stage And Auditorium Wheel Chair Lift	Tested	6:49:56 PM	09/23/2019
Smoke Detector	Small Gym Girl's Locker Room Coach's Office	Tested	6:41:02 PM	09/24/2019
Smoke Detector	Small Gym Girl's Locker Room Coach's Office Restroom	Tested	6:41:24 PM	09/24/2019
Smoke Detector	Small Gym Girl's Locker Room Coach's Office Storage Room	Tested	6:41:47 PM	09/24/2019
Smoke Detector	Small Gym Girl's Locker Room Exit	Tested	6:35:15 PM	09/24/2019
Smoke Detector	Small Gym Girl's Locker Room Office	Tested	6:34:43 PM	09/24/2019
Smoke Detector	Small Gym Girl's Locker Room Office Storage Room	Tested	6:33:58 PM	09/24/2019
Smoke Detector	Small Gym Girl's Locker Room Office Storage Room	Tested	6:35:44 PM	09/24/2019
Smoke Detector	Small Gym Girl's Locker Room Storage Exit	Tested	6:36:13 PM	09/24/2019
Smoke Detector	Small Gym Girl's Locker Room Storage Exit Restroom	Tested	6:37:03 PM	09/24/2019
Smoke Detector	Small Gym Girl's Locker Room SW Foyer Exit	Tested	6:39:36 PM	09/24/2019
Smoke Detector	Small Gym Gym Storage Room	Tested	6:50:49 PM	09/24/2019
Smoke Detector	Small Gym SE Corridor By Girl's Locker Room	Tested	6:45:43 PM	09/24/2019
Smoke Detector	Small Gym Volleyball Office	Tested	6:47:08 PM	09/24/2019
Smoke Detector	Building F Classroom 302	Tested	4:13:40 PM	09/24/2019
Smoke Detector	Building F Classroom 302	Tested	4:13:56 PM	09/24/2019
Smoke Detector	Building F Classroom 302	Tested	4:14:01 PM	09/24/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building F Classroom 302	Tested	4:14:07 PM	09/24/2019
Smoke Detector	Building F Classroom 302	Tested	4:14:12 PM	09/24/2019
Smoke Detector	Building F Classroom 302 Storage Room	Tested	4:14:19 PM	09/24/2019
Smoke Detector	Building F Classroom 302 Storage Room	Tested	4:18:04 PM	09/24/2019
Smoke Detector	Building F Classroom 303	Tested	4:19:16 PM	09/24/2019
Smoke Detector	Building F Classroom 303	Tested	4:21:14 PM	09/24/2019
Smoke Detector	Building F Classroom 303	Tested	4:21:18 PM	09/24/2019
Smoke Detector	Building F Classroom 303	Tested	4:21:23 PM	09/24/2019
Smoke Detector	Building F Classroom 304	Tested	4:05:17 PM	09/24/2019
Smoke Detector	Building F Classroom 304	Tested	4:08:46 PM	09/24/2019
Smoke Detector	Building F Classroom 304	Tested	4:08:51 PM	09/24/2019
Smoke Detector	Building F Classroom 304	Tested	4:08:56 PM	09/24/2019
Smoke Detector	Building F Classroom 304 Work Area	Tested	4:09:02 PM	09/24/2019
Smoke Detector	Building F Classroom 306	Tested	4:11:12 PM	09/24/2019
Smoke Detector	Building F Classroom 306 Storage Room	Tested	4:11:55 PM	09/24/2019
Smoke Detector	Building F Conference Room 326	Tested	4:28:50 PM	09/24/2019
Smoke Detector	Building F Conference Room 326	Tested	4:29:12 PM	09/24/2019
Smoke Detector	Building F Conference Room 327	Tested	4:27:20 PM	09/24/2019
Smoke Detector	Building F Entry To Room 324	Tested	4:32:51 PM	09/24/2019
Smoke Detector	Building F Equipment Storage Outside Of	Tested	4:24:22 PM	09/24/2019
SHOKE DELECTOR	Classroom 303	resteu		05/24/2015
Smoke Detector	Building F Equipment Storage Outside Of	Tested	4:24:46 PM	09/24/2019
Shoke Detector	Classroom 303	resteu		05/24/2015
Smoke Detector	Building F Office Room 325	Tested	4:33:35 PM	09/24/2019
Smoke Detector	Building F Storage Room 328	Tested	4:31:09 PM	09/24/2019
Smoke Detector	Building F Weight Room	Tested	4:36:15 PM	09/24/2019
Smoke Detector	Building F Weight Room	Tested	4:37:06 PM	09/24/2019
Smoke Detector	Building F Weight Room	Tested	4:37:10 PM	09/24/2019
Smoke Detector	Building F Weight Room	Tested	4:37:16 PM	09/24/2019
Smoke Detector	Building F Weight Room	Tested	4:37:21 PM	09/24/2019
Smoke Detector	Building F Weight Room	Tested	4:37:26 PM	09/24/2019
Smoke Detector	Building F Weight Room 315	Tested	4:50:29 PM	09/24/2019
Smoke Detector	Building F Weight Room 315	Tested	4:50:40 PM	09/24/2019
Smoke Detector	Building F Weight Room 315 Storage	Tested	4:47:00 PM	09/24/2019
Smoke Detector	Building F Weight Room 315 Storage	Tested	4:47:33 PM	09/24/2019
Smoke Detector	Building F Weight Room 315 Vestibule	Tested	4:49:02 PM	09/24/2019
Smoke Detector	Building F Weight Room Equipment Storage	Tested	4:43:11 PM	09/24/2019
Smoke Detector	Building F Weight Room Office 312	Tested	4:54:33 PM	09/24/2019
Smoke Detector	Building F Weight Room Storage	Tested	4:42:57 PM	09/24/2019
Smoke Detector	Building H Janitor's Room	Tested	7:38:06 PM	09/24/2019
Smoke Detector	Building H Mechanical	Tested	7:28:42 PM	09/24/2019
Smoke Detector	Classroom 169	Tested	7:53:37 PM	09/24/2019
Smoke Detector	Classroom 170	Tested	7:55:11 PM	09/24/2019
Smoke Detector	Classroom 170	Tested	7:55:20 PM	09/24/2019
Smoke Detector	Classroom 171	Tested	7:59:09 PM	09/24/2019
Smoke Detector	Classroom 171	Tested	7:59:19 PM	09/24/2019
Smoke Detector	Classroom 172	Tested	7:31:07 PM	09/24/2019
Smoke Detector	Classroom 172	Tested	7:31:22 PM	09/24/2019
Smoke Detector	Classroom 172 Classroom 174 Storage Room	Tested	7:34:37 PM	09/24/2019
Smoke Detector	Classroom 174	Tested	7:34:29 PM	
SHIDKE DELECTOR		resteu	7.37.23 FM	09/24/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Classroom 175A	Tested	7:35:49 PM	09/24/2019
Smoke Detector	Classroom 175A	Tested	7:35:59 PM	09/24/2019
Smoke Detector	Classroom 175B	Tested	7:36:04 PM	09/24/2019
Smoke Detector	Classroom 175B	Tested	7:36:14 PM	09/24/2019
Smoke Detector	Classroom 176 Storage Room	Tested	7:41:26 PM	09/24/2019
Smoke Detector	Classroom 176 Workroom	Tested	7:42:29 PM	09/24/2019
Smoke Detector	Classroom 176	Tested	7:40:08 PM	09/24/2019
Smoke Detector	Classroom 176	Tested	7:40:19 PM	09/24/2019
Smoke Detector	Classroom 177 Storage Room	Tested	7:43:22 PM	09/24/2019
Smoke Detector	Classroom 177	Tested	7:43:38 PM	09/24/2019
Smoke Detector	Classroom 177	Tested	7:43:49 PM	09/24/2019
Smoke Detector	Classroom 178 Chemical Storage Room	Tested	7:46:42 PM	09/24/2019
Smoke Detector	Classroom 178 Storage Room	Tested	7:47:29 PM	09/24/2019
Smoke Detector	Classroom 178	Tested	7:45:34 PM	09/24/2019
Smoke Detector	Classroom 178	Tested	7:45:44 PM	09/24/2019
Smoke Detector	Classroom 179 Storage Room	Tested	7:51:02 PM	09/24/2019
Smoke Detector	Classroom 179	Tested	7:51:55 PM	09/24/2019
Smoke Detector	Classroom 179	Tested	7:52:05 PM	09/24/2019
Smoke Detector	Classroom 306 Office	Tested	7:19:35 PM	09/24/2019
Smoke Detector	Classroom 306 Workroom 310	Tested	7:19:45 PM	09/24/2019
Smoke Detector	Classroom 306	Tested	7:17:21 PM	09/24/2019
Smoke Detector	Classroom 306	Tested	7:17:30 PM	09/24/2019
Smoke Detector	Classroom 306	Tested	7:17:35 PM	09/24/2019
Smoke Detector	Classroom 306	Tested	7:17:42 PM	09/24/2019
Smoke Detector	Classroom 307	Tested	7:12:42 PM	09/24/2019
Smoke Detector	Classroom 307	Tested	7:12:51 PM	09/24/2019
Smoke Detector	Classroom 307	Tested	7:12:56 PM	09/24/2019
Smoke Detector	Classroom 307	Tested	7:13:01 PM	09/24/2019
Smoke Detector	Classroom 307 And 308 Workroom	Tested	7:12:19 PM	09/24/2019
Smoke Detector	Classroom 308	Tested	7:11:44 PM	09/24/2019
Smoke Detector	Classroom 308	Tested	7:12:04 PM	09/24/2019
Smoke Detector	Classroom 308	Tested	7:12:09 PM	09/24/2019
Smoke Detector	Classroom 308	Tested	7:12:14 PM	09/24/2019
Smoke Detector	Main Gym Athletics Office	Tested	5:17:28 PM	09/24/2019
Smoke Detector	Main Gym Athletics Office	Tested	5:18:49 PM	09/24/2019
Smoke Detector	Main Gym Athletics Office	Tested	5:19:04 PM	09/24/2019
Smoke Detector	Main Gym Athletics Office	Tested	5:20:30 PM	09/24/2019
Smoke Detector	Main Gym Athletics Office Storage	Tested	5:17:08 PM	09/24/2019
Smoke Detector	Main Gym Boy's Locker Room	Tested	5:28:43 PM	09/24/2019
Smoke Detector	Main Gym East Storage Next To Athletics Office	Tested	5:10:24 PM	09/24/2019
Smoke Detector	Main Gym East Storage Next To Athletics Office	Tested	5:10:46 PM	09/24/2019
Smoke Detector	Main Gym East Storage Next To Athletics Office	Tested	5:10:54 PM	09/24/2019
Smoke Detector	Main Gym Electrical Room Corridor Near Boy's Showers	Tested	5:23:20 PM	09/24/2019
Smoke Detector	Main Gym Entrance Foyer	Tested	5:05:24 PM	09/24/2019
Smoke Detector	Main Gym Entrance Foyer	Tested	5:07:22 PM	09/24/2019
Smoke Detector	Main Gym Wrestling Office	Tested	5:24:24 PM	09/24/2019
Smoke Detector	Main Gym Wrestling Office Storage Room	Tested	5:25:37 PM	09/24/2019
Smoke Detector	Mechanical Room Behind Classroom 306	Tested	7:25:34 PM	09/24/2019
Smoke Detector	Office 185A	Tested	7:29:57 PM	09/24/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Robins-Loats Building Admin Reception	Tested	6:21:27 PM	09/17/2019
Smoke Detector	Robins-Loats Building Admin-Counseling Reception	Tested	6:23:33 PM	09/17/2019
Smoke Detector	Robins-Loats Building Admin-Counseling Work Area	Tested	6:36:35 PM	09/17/2019
Smoke Detector	Robins-Loats Building Admin/Counseling Office By Restroom	Tested	6:29:55 PM	09/17/2019
Smoke Detector	Robins-Loats Building Admin/Counseling SE Corner Office	Tested	6:28:10 PM	09/17/2019
Smoke Detector	Robins-Loats Building Administration 100 Corridor	Tested	6:39:43 PM	09/17/2019
Smoke Detector	Robins-Loats Building Administration 100 Corridor Entrance	Tested	6:37:57 PM	09/17/2019
Smoke Detector	Robins-Loats Building Band Storage Room	Tested	7:41:09 PM	09/19/2019
Smoke Detector	Robins-Loats Building Black Box Tech Booth	Tested	6:40:24 PM	09/23/2019
Smoke Detector	Robins-Loats Building Boy's Restroom Next To Music Hall 105-107	Tested	6:07:27 PM	09/18/2019
Smoke Detector	Robins-Loats Building Computer Room 134	Tested	5:35:40 PM	09/17/2019
Smoke Detector	Robins-Loats Building Computer Room 134	Tested	5:37:10 PM	09/17/2019
Smoke Detector	Robins–Loats Building Corridor By Band Storage Room	Tested	6:17:19 PM	09/18/2019
Smoke Detector	Robins–Loats Building Corridor By Costume Storage Room	Tested	6:16:25 PM	09/18/2019
Smoke Detector	Robins-Loats Building Corridor By Green Room	Tested	6:23:14 PM	09/18/2019
Smoke Detector	Robins–Loats Building Corridor By Health Office 132	Tested	5:52:59 PM	09/17/2019
Smoke Detector	Robins–Loats Building Corridor By Instrumental 105	Tested	6:19:42 PM	09/18/2019
Smoke Detector	Robins–Loats Building Corridor By Instrumental 105	Tested	6:20:57 PM	09/18/2019
Smoke Detector	Robins-Loats Building Corridor By Office 111	Tested	6:24:41 PM	09/17/2019
Smoke Detector	Robins-Loats Building Corridor By Office 115	Tested	6:25:25 PM	09/17/2019
Smoke Detector	Robins-Loats Building Corridor By Office 115/Restroom	Tested	6:26:05 PM	09/17/2019
Smoke Detector	Robins-Loats Building Corridor By Office 135	Tested	6:58:10 PM	09/17/2019
Smoke Detector	Robins–Loats Building Corridor By Security Office	Tested	6:52:26 PM	09/17/2019
Smoke Detector	Robins-Loats Building Corridor By Server Room	Tested	6:57:16 PM	09/17/2019
Smoke Detector	Robins–Loats Building Corridor By Stage 102 Roll Doors	Tested	6:21:38 PM	09/18/2019
Smoke Detector	Robins–Loats Building Corridor By Stage 102 Roll Doors	Tested	6:22:39 PM	09/18/2019
Smoke Detector	Robins–Loats Building Corridor By Textbook Storage Room	Tested	5:28:36 PM	09/17/2019
Smoke Detector	Robins-Loats Building Corridor By Vocal 106	Tested	6:18:09 PM	09/18/2019
Smoke Detector	Robins–Loats Building Corridor Dining Room 138	Tested	4:59:48 PM	09/17/2019
Smoke Detector	Robins–Loats Building Corridor Dining Room 138	Tested	5:00:03 PM	09/17/2019
Smoke Detector	Robins-Loats Building Corridor Dining Room	Tested	5:00:10 PM	09/17/2019

Device Type	Location	Service	Time	Date
	Passed			
	138			
Smoke Detector	Robins-Loats Building Corridor Exit By Office 115	Tested	6:26:27 PM	09/17/2019
Smoke Detector	Robins-Loats Building Corridor Outside Heritage Hall	Tested	5:55:59 PM	09/17/2019
Smoke Detector	Robins–Loats Building Corridor Restroom By Black Box Tech Booth	Tested	6:24:49 PM	09/18/2019
Smoke Detector	Robins–Loats Building Corridor Restroom By Green Room	Tested	6:24:23 PM	09/18/2019
Smoke Detector	Robins-Loats Building Costume Storage Room	Tested	6:13:50 PM	09/18/2019
Smoke Detector	Robins-Loats Building Data Room By Vocal 106	Tested	7:44:03 PM	09/19/2019
Smoke Detector	Robins-Loats Building Dining Room 138	Tested	4:58:01 PM	09/17/2019
Smoke Detector	Robins-Loats Building Dining Room 138	Tested	4:58:34 PM	09/17/2019
Smoke Detector	Robins-Loats Building Electrical Room By Office	Tested	6:16:22 PM	09/17/2019
Smoke Detector	Robins-Loats Building Electrical Room By Vocal 106	Tested	7:42:43 PM	09/19/2019
Smoke Detector	Robins-Loats Building Electrical Room Next To FACP	Tested	4:54:20 PM	09/17/2019
Smoke Detector	Robins-Loats Building Electrical Room Next To FACP	Tested	4:54:53 PM	09/17/2019
Smoke Detector	Robins-Loats Building Elevator Machine Room	Inspected	7:33:28 PM	09/17/2019
Smoke Detector	Robins-Loats Building FACP Room Inside Dining Room 138	Tested	4:53:19 PM	09/17/2019
Smoke Detector	Robins–Loats Building Girl's Restroom Next To Music Hall 105–107	Tested	6:06:54 PM	09/18/2019
Smoke Detector	Robins–Loats Building Green Room	Tested	6:29:38 PM	09/23/2019
Smoke Detector	Robins-Loats Building Green Room	Tested	6:30:01 PM	09/23/2019
Smoke Detector	Robins–Loats Building Green Room Boy's Dressing Room	Tested	6:34:58 PM	09/23/2019
Smoke Detector	Robins–Loats Building Green Room Girl's Dressing Room	Tested	6:33:21 PM	09/23/2019
Smoke Detector	Robins-Loats Building Green Room Restroom	Tested	6:35:59 PM	09/23/2019
Smoke Detector	Robins–Loats Building Green Room Restroom	Tested	6:40:16 PM	09/23/2019
Smoke Detector	Robins-Loats Building Health Office 132	Tested	5:54:05 PM	09/17/2019
Smoke Detector	Robins–Loats Building Health Office 132 Restroom	Tested	5:54:44 PM	09/17/2019
Smoke Detector	Robins-Loats Building Heritage Hall	Tested	6:00:16 PM	09/17/2019
Smoke Detector	Robins-Loats Building Heritage Hall	Tested	6:00:31 PM	09/17/2019
Smoke Detector	Robins-Loats Building Heritage Hall Workroom/Office	Tested	6:01:49 PM	09/17/2019
Smoke Detector	Robins-Loats Building Heritage Hall Workroom/Office	Tested	6:02:15 PM	09/17/2019
Smoke Detector	Robins-Loats Building Instrument Storage	Tested	7:19:44 PM	09/19/2019
Smoke Detector	Robins-Loats Building Instrument Storage	Tested	7:20:00 PM	09/19/2019
Smoke Detector	Robins-Loats Building Instrumental Classroom 105	Tested	7:08:52 PM	09/19/2019
Smoke Detector	Robins-Loats Building Instrumental Classroom 105	Tested	7:09:22 PM	09/19/2019
Smoke Detector	Robins-Loats Building Instrumental Classroom	Tested	7:09:27 PM	09/19/2019

Device Type	Location	Service	Time	Date
	Passed			
	105			
Smoke Detector	Robins-Loats Building Instrumental Classroom 105	Tested	7:09:32 PM	09/19/2019
Smoke Detector	Robins–Loats Building Instrumental Classroom 105 Storage	Tested	7:09:38 PM	09/19/2019
Smoke Detector	Robins–Loats Building Kitchen	Tested	5:07:04 PM	09/17/2019
Smoke Detector	Robins-Loats Building Kitchen	Tested	5:08:13 PM	09/17/2019
Smoke Detector	Robins-Loats Building Kitchen	Tested	5:08:36 PM	09/17/2019
Smoke Detector	Robins-Loats Building Kitchen	Tested	5:08:41 PM	09/17/2019
Smoke Detector	Robins-Loats Building Kitchen	Tested	5:10:02 PM	09/17/2019
Smoke Detector	Robins-Loats Building Kitchen Corridor	Tested	5:11:53 PM	09/17/2019
Smoke Detector	Robins–Loats Building Kitchen Custodian Room	Tested	5:15:28 PM	09/17/2019
Smoke Detector	Robins-Loats Building Kitchen Dressing Room	Tested	5:16:24 PM	09/17/2019
Smoke Detector	Robins-Loats Building Kitchen Dry Storage Room	Tested	5:17:29 PM	09/17/2019
Smoke Detector	Robins-Loats Building Kitchen Office	Tested	5:12:53 PM	09/17/2019
Smoke Detector	Robins–Loats Building Kitchen Outside Receiving Dock	Tested	5:18:37 PM	09/17/2019
Smoke Detector	Robins-Loats Building Kitchen Outside Receiving Dock	Tested	5:19:02 PM	09/17/2019
Smoke Detector	Robins-Loats Building Kitchen Serving Area A	Tested	5:25:20 PM	09/17/2019
Smoke Detector	Robins-Loats Building Kitchen Serving Area A	Tested	5:25:28 PM	09/17/2019
Smoke Detector	Robins-Loats Building Kitchen Serving Area B	Tested	5:24:52 PM	09/17/2019
Smoke Detector	Robins-Loats Building Kitchen Serving Area C	Tested	5:22:02 PM	09/17/2019
Smoke Detector	Robins-Loats Building Kitchen Serving Area C	Tested	5:24:39 PM	09/17/2019
Smoke Detector	Robins-Loats Building Library Conference Room	Tested	5:45:40 PM	09/17/2019
Smoke Detector	Robins-Loats Building Library Lounge	Tested	5:40:12 PM	09/17/2019
Smoke Detector	Robins-Loats Building Library Office	Tested	5:42:01 PM	09/17/2019
Smoke Detector	Robins-Loats Building Library Reception	Tested	5:41:06 PM	09/17/2019
Smoke Detector	Robins-Loats Building Lounge Room	Tested	5:02:18 PM	09/17/2019
Smoke Detector	Robins-Loats Building Lounge Room	Tested	5:02:38 PM	09/17/2019
Smoke Detector	Robins-Loats Building Main Admin/Library Corridor	Tested	5:50:53 PM	09/17/2019
Smoke Detector	Robins–Loats Building Main Admin/Library Corridor	Tested	5:51:16 PM	09/17/2019
Smoke Detector	Robins-Loats Building Main Admin/Library Corridor	Tested	5:51:20 PM	09/17/2019
Smoke Detector	Robins-Loats Building Main Admin/Library Corridor Entrance	Tested	5:49:44 PM	09/17/2019
Smoke Detector	Robins-Loats Building Main Attendance Office	Tested	6:35:39 PM	09/17/2019
Smoke Detector	Robins–Loats Building Main Counseling Office 110 High Ceiling	Tested	6:05:05 PM	09/17/2019
Smoke Detector	Robins–Loats Building Main Counseling Office 110 High Ceiling	Tested	6:05:34 PM	09/17/2019
Smoke Detector	Robins–Loats Building Main Counseling Office 110 High Ceiling	Tested	6:05:40 PM	09/17/2019
Smoke Detector	Robins-Loats Building Main Library	Tested	5:37:15 PM	09/17/2019
Smoke Detector	Robins-Loats Building Main Library	Tested	5:37:36 PM	09/17/2019
Smoke Detector	Robins-Loats Building Main Library	Tested	5:37:40 PM	09/17/2019
Smoke Detector	Robins-Loats Building Main Library	Tested	5:37:45 PM	09/17/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Robins-Loats Building Main Library Reading	Tested	5:44:02 PM	09/17/2019
Smoke Detector	Area	lested		00,11,2010
Smoke Detector	Robins-Loats Building Main Library Reading	Tested	5:44:35 PM	09/17/2019
	Area			
Smoke Detector	Robins-Loats Building Main Library Reading	Tested	5:44:39 PM	09/17/2019
	Area			
Smoke Detector	Robins-Loats Building Main Library Reading	Tested	5:44:43 PM	09/17/2019
	Area			
Smoke Detector	Robins-Loats Building Main Library Reading	Tested	5:44:50 PM	09/17/2019
	Area			
Smoke Detector	Robins-Loats Building Main Library Reading	Tested	5:44:55 PM	09/17/2019
	Area		5 46 22 PM	
Smoke Detector	Robins-Loats Building Multi-Media Room 133	Tested	5:46:32 PM	09/17/2019
Smoke Detector	Robins-Loats Building Multi-Media Room 133	Tested	5:46:53 PM	09/17/2019
Smoke Detector	Robins-Loats Building Museum Conference	Tested	5:58:03 PM	09/17/2019
Smoke Detector	Room Robins, Leats Ruilding Music Library Room	Tested	7:39:07 PM	09/19/2019
Smoke Detector	Robins-Loats Building Music Library Room Robins-Loats Building Music Office (106)	Tested	7:05:35 PM	09/19/2019
Smoke Detector	Robins-Loats Building Network Office	Tested	7:04:19 PM	09/17/2019
Smoke Detector	Robins-Loats Building Non-Food Storage Room	Tested	5:04:50 PM	09/17/2019
Smoke Detector	Robins-Loats Building Office 111	Tested	6:31:57 PM	09/17/2019
Smoke Detector	Robins-Loats Building Office 112	Tested	6:31:45 PM	09/17/2019
Smoke Detector	Robins-Loats Building Office 113	Tested	6:31:35 PM	09/17/2019
Smoke Detector	Robins-Loats Building Office 114	Tested	6:31:26 PM	09/17/2019
Smoke Detector	Robins-Loats Building Office 115	Tested	6:31:15 PM	09/17/2019
Smoke Detector	Robins-Loats Building Office 116	Tested	6:06:18 PM	09/17/2019
Smoke Detector	Robins-Loats Building Office 117	Tested	6:06:38 PM	09/17/2019
Smoke Detector	Robins-Loats Building Office 118	Tested	6:08:36 PM	09/17/2019
Smoke Detector	Robins-Loats Building Office 119	Tested	6:10:18 PM	09/17/2019
Smoke Detector	Robins-Loats Building Office 120	Tested	6:10:29 PM	09/17/2019
Smoke Detector	Robins-Loats Building Office 121	Tested	6:10:40 PM	09/17/2019
Smoke Detector	Robins-Loats Building Office 122	Tested	6:11:00 PM	09/17/2019
Smoke Detector	Robins-Loats Building Office 123	Tested	6:11:14 PM	09/17/2019
Smoke Detector	Robins-Loats Building Office 124	Tested	6:11:24 PM	09/17/2019
Smoke Detector	Robins-Loats Building Office 135	Tested	6:59:16 PM	09/17/2019
Smoke Detector	Robins-Loats Building Piano Lab Classroom 107	Tested	6:51:02 PM	09/19/2019
Smoke Detector	Robins-Loats Building Piano Lab Classroom 107	Tested	6:51:28 PM	09/19/2019
Smoke Detector	Robins-Loats Building Practice 105A	Tested	7:11:11 PM	09/19/2019
Smoke Detector	Robins-Loats Building Practice 105B	Tested	7:10:17 PM	09/19/2019
Smoke Detector	Robins-Loats Building Practice 105C	Tested	7:09:52 PM	09/19/2019
Smoke Detector	Robins-Loats Building Practice Classroom 106A	Tested	7:04:33 PM	09/19/2019
Smoke Detector	Robins-Loats Building Practice Classroom 106B	Tested	7:02:39 PM	09/19/2019
Smoke Detector	Robins-Loats Building Principal's Office	Tested	6:20:13 PM	09/17/2019
Smoke Detector	Robins-Loats Building Records Room By Office 122	Tested	6:19:11 PM	09/17/2019
Smoke Detector	Robins-Loats Building Screen Room 104	Tested	6:31:53 PM	09/23/2019
Smoke Detector	Robins-Loats Building Screen Room 104	Tested	6:32:08 PM	09/23/2019
Smoke Detector	Robins-Loats Building Security Office	Tested	7:07:03 PM	09/17/2019
Smoke Detector	Robins-Loats Building Security Office	Tested	7:07:18 PM	09/17/2019
Smoke Detector	Robins-Loats Building Server Room By Lounge	Tested	7:03:00 PM	09/17/2019

Device Type	Location	Service	Time	Date	
	Passed				
	136				
Smoke Detector	Robins-Loats Building Staff Restroom By Office 124	Tested	6:14:10 PM	09/17/2019	
Smoke Detector	Robins–Loats Building Staff Workroom In Library	Tested	5:30:49 PM	09/17/2019	
Smoke Detector	Robins–Loats Building Staff Workroom In Library	-			
Smoke Detector	Robins–Loats Building Textbook Storage Room In Library	Tested	5:31:31 PM	09/17/2019	
Smoke Detector	Robins–Loats Building Theater Operations Office	Tested	6:27:50 PM	09/23/2019	
Smoke Detector	Robins-Loats Building Vocal Classroom 106	Tested	6:58:01 PM	09/19/2019	
Smoke Detector	Robins-Loats Building Vocal Classroom 106	Tested	6:58:22 PM	09/19/2019	
Smoke Detector	Robins-Loats Building Water/Heater Room Next To FACP	Tested	4:56:07 PM	09/17/2019	
Smoke Detector	Robins-Loats Building Workability Office	Tested	7:00:28 PM	09/17/2019	
Smoke Detector	Robins-Loats Building Workroom 137	Tested	7:05:25 PM	09/17/2019	
Waterflow Switch	Gymnasium West Outside Off Irvine Blvd.	Tested	5:11:17 PM	09/19/2019	
Waterflow Switch	Robins-Loats Building Mechanical/Riser Room By Elevator	Tested	4:39:03 PM	09/19/2019	
Waterflow Switch	Robins-Loats Building Mechanical/Riser Room Tested By Elevator		4:45:32 PM	09/19/2019	
Waterflow Switch	Robins–Loats Building Mechanical/Riser Room Tested By Elevator		4:45:38 PM	09/19/2019	
Waterflow Switch	, Robins-Loats Building Mechanical/Riser Room By Elevator	Tested	4:48:16 PM	09/19/2019	
Waterflow Switch	Robins-Loats Building Mechanical/Riser Room By Elevator	Tested	4:50:59 PM	09/19/2019	
Supervisory					
Tamper Switch	Outside Gymnasium Off Irvine Blvd. OS&Y	Tested	5:06:44 PM	09/19/2019	
Tamper Switch	Outside Gymnasium Off Irvine Blvd. OS&Y	Tested	5:07:57 PM	09/19/2019	
Tamper Switch	Outside Gymnasium Off Irvine Blvd. PIV	Tested	5:17:15 PM	09/19/2019	
Tamper Switch	Robins-Loats Building Mechanical/Riser Room By Elevator	Tested	5:00:30 PM	09/19/2019	
Tamper Switch	Robins-Loats Building Mechanical/Riser Room By Elevator	Tested	5:00:39 PM	09/19/2019	
Tamper Switch	Robins-Loats Building Mechanical/Riser Room By Elevator	Tested	5:01:13 PM	09/19/2019	
Tamper Switch	Robins-Loats Building Mechanical/Riser Room By Elevator	Tested	5:01:40 PM	09/19/2019	
Tamper Switch	Robins-Loats Building Mechanical/Riser Room By Elevator	Tested	5:02:08 PM	09/19/2019	
Device Type	Location	Service	Time	Date	
	Failed/Other				
Supervisory					
Tamper Switch	Gymnasium West Outside Off Irvine Blvd. OS&Y	Tested	5:16:59 PM	09/19/2019	

Building: NMUSD - Newport Harbor High School

Control Panel: 2 - Simplex 4100U

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Control Panel	Tech Building FACP/Communications Room	Tested	4:40:45 PM	09/17/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Newport Harbor High School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity				
	Failed/Other					
Tamper Switch	Tested	1				
Total		1				
	Passed					
Annunciator	Inspected	2				
Battery	Tested	28				
Control Panel	Tested	2				
Heat Detector	Tested	323				
Power Supply	Inspected	8				
Power Supply	Tested	4				
Pull Station	Tested	9				
Smoke Detector	Inspected	1				
Smoke Detector	Tested	525				
Tamper Switch	Tested	8				
Waterflow Switch	Tested	6				
Total		917				

Auxiliary Functions Testing Generated by: BuildingReports.com

Building: NMUSD - Newport Harbor High SchoolControl Panel: 1 - Silent Knight IFP-1000							
The Auxiliary Functions Testing section lists each of the ancillary items, systems, and emergency equipment that are controlled by the system control unit. Items are grouped by Passed or Failed/Other. The items are listed by device type, and a check box is provided to indicate if the test conducted was simulated.							
Туре	Location	Comment	ScanID	Simulated			
Туре	Location Passed	Comment	ScanID	Simulated			
Type Smoke Detector		Comment	ScanID	Simulated			

Passed

58091727

Robins-Loats Building Elevator Machine Room

Elevator Recall

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - Newport Harbor High School

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

			Ambient	Alarm	🦻 Intell	igibility	Sound
Location		Comment	◀ dB	◀ dB	Voice	STI	Test
Failed/Other							
Sound Test Points							
Entire Campus							0001

Time, Temperature & Level Testing

Generated by: BuildingReports.com

Building: NMUSD - Newport Harbor High School

Control Panel: 1 - Silent Knight IFP-1000

The Time, Temperature, & Level Testing section details the measurements taken from various devices that are designed to respond in a certain amount of time, respond at a certain temperature, or respond within the acceptable range of volume or level. Items are grouped by Passed or Failed/Other.

Туре	Location	Comment	Sec	Deg	Lvl	ScanID
	Passe	ed and				
Waterflow	v Switch					
	Gymnasium West Outside Off Irvine Blvd.	Passed	77	n/a	n/a	58092106
	Robins-Loats Building Mechanical/Riser	Passed	50	n/a	n/a	58091728
	Room By Elevator					
	Robins-Loats Building Mechanical/Riser	Passed	58	n/a	n/a	58091729
	Room By Elevator					
	Robins-Loats Building Mechanical/Riser	Passed	45	n/a	n/a	58091730
	Room By Elevator					
	Robins-Loats Building Mechanical/Riser	Passed	60	n/a	n/a	58091731
	Room By Elevator					
	Robins-Loats Building Mechanical/Riser	Passed	44	n/a	n/a	58091732
	Room By Elevator					

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: NMUSD - Newport Harbor High	Control Panel: 1 - Silent Knight
School	IFP-1000

The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.

		Rated	Rated	Pre	Post	Min	Tested
Туре	Location	Ah	Volts	Test	Test	Ah	Ah
		Passe	ed				
Battery							
Sealed Lead Acid	1st Dodge Hall Classroom 141–Janitor Rm.	7	12				
Sealed Lead Acid	1st Dodge Hall Classroom 141–Janitor Rm.	7	12				
Sealed Lead Acid	1st Dodge Hall Classroom 141–Janitor Rm.	7	12				
Sealed Lead Acid	1st Dodge Hall Classroom 141–Janitor Rm.	7	12				
Sealed Lead Acid	1st Sims Hall Student Leadership Center By Entrance	7	12				
Sealed Lead Acid	1st Sims Hall Student Leadership Center By Entrance	7	12				
Sealed Lead Acid	2nd Sims Hall Storage by Classroom 295	7	12				
Sealed Lead Acid	2nd Sims Hall Storage by Classroom 295	7	12				

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Newport Harbor High School

Control Panel: 1 - Silent Knight IFP-1000

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type		Category	% of Inventory	Quantity
Control Panel		Control	0.22%	2
Smoke Detector		Initiating	57.30%	526
Battery		Control	3.05%	28
Power Supply		Control	1.31%	12
Annunciator		Control	0.22%	2
Heat Detector		Initiating	35.19%	323
Sound Test		Sound Test	0.11%	1
Waterflow Switch		Initiating	0.65%	6
Tamper Switch Pull Station		Supervisory Initiating	0.98% 0.98%	9 9
	Qt	initiating		
Туре	y	Model #	Description	Install Date
		New	(under 90 days)	
Simplex			· · · · ·	
Heat Detector	28 4	4098-9734	Rate-of-Rise	09/18/2019
Global Safety Proc	duc			
Tamper Switch	5	BO-G 300		09/17/2019
Potter				
Tamper Switch	1			09/17/2019
Tamper Switch	2	OSYSU-2		09/17/2019
Waterflow Switch	6	VSR		09/17/2019
Silent Knight				
Annunciator	1			09/17/2019
Control Panel	1	IFP-1000		09/17/2019
Power Supply	3	RPS-1000		09/17/2019
Pull Station	1	SD500-PS	Keyed	09/17/2019
Smoke Detector	21	SD505-APS	Photoelectric	09/17/2019
	3	02000 / 0		00,,20.0
Simplex				
Annunciator	1			09/17/2019
Heat Detector	1	4098-9734		09/17/2019
Heat Detector	38	4098-9734	Rate-of-Rise	09/17/2019
Power Supply	5	4009		09/17/2019
Power Supply	4	4009 TrueAlert		09/17/2019
Pull Station	8	4099-9001	Keyed	09/17/2019
Pull Station		4033-3001	Neveu	09/17/2019

Cal Building Systems

10/03/2019

	0						
System Sensor							
Tamper Switch	1	OSY2		09/17/2019			
Battery	4	12V7AH	Sealed Lead Acid	07/17/2019			
	In Service - 1 Year to 2 Years						
Battery	4	12V18AH	Sealed Lead Acid	07/17/2018			
Battery	2	12V26AH	Sealed Lead Acid	07/17/2018			
Battery	10	12V7AH	Sealed Lead Acid	07/17/2018			
12V7Ah							
Battery	8	12V7Ah	Sealed Lead Acid	07/17/2018			
In Service - 5 Years to 10 Years							
Simplex							
Smoke Detector	13	4098-9714	Photoelectric	10/17/2012			
Building: NMUS High School	SD - New	vport Harbor	Control Panel: 2	- Simplex 4100U			
The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.							
_	Qt						
Туре	y y	Model #	Description	Install Date			
	New (under 90 days)						
Simplex							
Control Panel	1	4100U		09/17/2019			

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Newport Heights Elementary 300 E 15th Street Newport Beach, CA 92663

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Sep 10, 2019

Building: NMUSD - Newport Heights Elementary Contact: Tim Waller Title: Maintenance & Operations Manager Company: Cal Building Systems Contact: Chris Ferreira Title: Service

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD – Newport Heights Elementary	Contact: Tim W	/aller
Address: 300 E 15th Street	Phone: 714 23	1-0363
Address:	Fax:	
City/State/Zip: Newport Beach, CA 92663	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Chri	s Ferreira
Address: 2903 Saturn Street	Phone: 714–99	3-9650
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: chrisferr	eira@calbuildingsystems.com
System Control Unit		
Manufacturer: SimplexGrinnell	Inspection Date	e: 09/10/2019 IDC Style:
Model Number: 4100U	Install Date: 09	/10/2019 SLC Style:
Software Version:	Version Date: (09/10/2019 NAC Style:
Location: Building F Main Custodian Room	Current Protect	i on: Breaker
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Catalogue	Total	ltems	Ser	viced	Pa	ssed	Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Control	9	5.62%	9	100.00%	9	100.00%	0	0%
Initiating	151	94.38%	151	100.00%	150	99.34%	1	0.66%
Totals	160	100%	160	100.00%	159	99.38%	1	0.62%
Certification								
Company: Cal Building Systems			Bı	ilding: NMU	ISD – Nev	vport Heigh	its Elemer	itary
Inspector: Chris Ferreira			Co	ontact: Tim V	Waller			
Signed:			Si	gned:				

Discrepancy Report Generated by: BuildingReports.com

Building: N	Building: NMUSD - Newport Heights			Control Panel: 1 - SimplexGrinnell			
Elementary			4100U				
The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.					and where		
Device Type		Manufacturer	ModelNumber	Da	ıte	Qty	
		Items listed for Recall	by Manufacture	e r			
		No recalled items found d	ring this inspection.				
8 ScanID	C3 Location		Problem	Address	🖾 Ref	erence	
Initiating							
Heat Detector							
58094249	Building B FAU	Room 9	Head Missing	1			

Proposed Solutions Report Generated by: BuildingReports.com

Building: NMUSD - Newport Heights Elementary		Control Panel: 1	- SimplexG	rinnell 41	00U	
The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.						
ScanID	Location	Solution	Model #	Cost	Fix	
Initiating						
	Initiat	ing				
Heat Detec		ing				
Heat Detec		ing Replace	4098-9403	T/M		

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Newport Heights Elementary

Control Panel: 1 - SimplexGrinnell 4100U

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Battery	Building C Custodial Closet	Tested	5:23:41 PM	09/10/2019
Battery	Building C Custodial Closet	Tested	5:23:58 PM	09/10/2019
Battery	Building F Main Custodian Room	Inspected	4:10:04 PM	09/10/2019
Battery	Building F Main Custodian Room	Inspected	4:10:16 PM	09/10/2019
Battery	Building G MPR Storage	Tested	4:32:24 PM	09/10/2019
Battery	Building G MPR Storage	Tested	4:33:01 PM	09/10/2019
Control Panel	Building F Main Custodian Room	Tested	3:28:06 PM	09/10/2019
Power Supply	Building C Custodial Closet	Tested	5:22:49 PM	09/10/2019
Power Supply	Building G MPR Storage	Tested	4:30:50 PM	09/10/2019
Initiating				
Heat Detector	Building A Boys Toilet	Tested	5:24:54 PM	09/10/2019
Heat Detector	Building A Custodial Closet	Tested	5:25:12 PM	09/10/2019
Heat Detector	Building A FAU Room 1	Tested	5:25:39 PM	09/10/2019
Heat Detector	Building A FAU Room 2	Tested	5:25:57 PM	09/10/2019
Heat Detector	Building A FAU Room 3	Tested	5:26:21 PM	09/10/2019
Heat Detector	Building A FAU Room 4	Tested	5:26:30 PM	09/10/2019
Heat Detector	Building A Girls Toilet	Tested	5:24:36 PM	09/10/2019
Heat Detector	Building B Boys Toilet	Tested	5:11:54 PM	09/10/2019
Heat Detector	Building B Custodial Closet	Tested	5:11:21 PM	09/10/2019
Heat Detector	Building B FAU Room 10	Tested	5:10:33 PM	09/10/2019
Heat Detector	Building B FAU Room 7	Tested	5:09:39 PM	09/10/2019
Heat Detector	Building B FAU Room 8	Tested	5:10:08 PM	09/10/2019
Heat Detector	Building B Girls Toilet	Tested	5:10:48 PM	09/10/2019
Heat Detector	Building C Boys Toilet	Tested	5:33:28 PM	09/10/2019
Heat Detector	Building C Custodial Closet	Tested	5:32:54 PM	09/10/2019
Heat Detector	Building C FAU Room 13	Tested	5:38:55 PM	09/10/2019
Heat Detector	Building C FAU Room 14	Tested	5:39:13 PM	09/10/2019
Heat Detector	Building C FAU Room 15	Tested	5:39:22 PM	09/10/2019
Heat Detector	Building C FAU Room 16	Tested	5:39:41 PM	09/10/2019
Heat Detector	Building C Girls Toilet	Tested	5:38:12 PM	09/10/2019
Heat Detector	Building D FAU Room 11	Tested	5:09:25 PM	09/10/2019
Heat Detector	Building D FAU Room 12	Tested	5:07:54 PM	09/10/2019
Heat Detector	Building E FAU Room 5	Tested	5:12:53 PM	09/10/2019
Heat Detector	Building E FAU Room 6	Tested	5:12:27 PM	09/10/2019
Heat Detector	Building F FAC Storage	Tested	5:24:02 PM	09/10/2019
Heat Detector	Building F FAC Toilet	Tested	5:23:29 PM	09/10/2019
Heat Detector	Building F FAC Toilet	Tested	5:23:54 PM	09/10/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	Building F Nurse Toilet	Tested	5:24:16 PM	09/10/2019
Heat Detector	Building G Custodial Closet	Tested	5:30:34 PM	09/10/2019
Heat Detector	Building G Kinder A FAC Toilet	Tested	5:29:21 PM	09/10/2019
Heat Detector	Building G Kinder A Toilet	Tested	5:29:41 PM	09/10/2019
Heat Detector	Building G Kinder B FAC Toilet	Tested	5:28:20 PM	09/10/2019
Heat Detector	Building G Kinder B Toilet	Tested	5:30:06 PM	09/10/2019
Heat Detector	Building G Kitchen	Tested	5:31:12 PM	09/10/2019
Heat Detector	Building G Kitchen	Tested	5:32:27 PM	09/10/2019
Heat Detector	Building G Kitchen Toilet	Tested	5:32:00 PM	09/10/2019
Heat Detector	Building G Men's Toilet	Tested	5:27:29 PM	09/10/2019
Heat Detector	Building G MPR	Tested	5:31:35 PM	09/10/2019
Heat Detector	Building G MPR Storage	Tested	5:26:41 PM	09/10/2019
Heat Detector	Building G Women's Toilet	Tested	5:27:49 PM	09/10/2019
Heat Detector	Building H FAU Rooms 17 & 18	Tested	5:15:07 PM	09/10/2019
Heat Detector	Building H FAU Rooms 19 & 20	Tested	5:14:41 PM	09/10/2019
Heat Detector	Building I Boys Toilet	Tested	5:13:14 PM	09/10/2019
Heat Detector	Building I Custodial Closet	Tested	5:14:13 PM	09/10/2019
Heat Detector	Building I Girls Toilet	Tested	5:13:51 PM	09/10/2019
Heat Detector	Building J FAU Rooms 22 & 23	Tested	5:15:38 PM	09/10/2019
Heat Detector	Portable Classroom 26	Tested	5:18:05 PM	09/10/2019
Heat Detector	Portable Classroom 26	Tested	5:18:14 PM	09/10/2019
Heat Detector	Portable Classroom 27	Tested	5:17:34 PM	09/10/2019
Heat Detector	Portable Classroom 27	Tested	5:17:59 PM	09/10/2019
Heat Detector	Portable Classroom 28	Tested	5:17:19 PM	09/10/2019
Heat Detector	Portable Classroom 28	Tested	5:17:28 PM	09/10/2019
Heat Detector	Portable Classroom 29	Tested	5:17:04 PM	09/10/2019
Heat Detector	Portable Classroom 29	Tested	5:17:13 PM	09/10/2019
Heat Detector	Portable Classroom 30	Tested	5:16:21 PM	09/10/2019
Heat Detector	Portable Classroom 30	Tested	5:17:00 PM	09/10/2019
Pull Station	Building F Admin Entrance	Tested	3:58:20 PM	09/10/2019
Pull Station	Building G MPR Exit	Tested	4:27:47 PM	09/10/2019
Pull Station	Building G MPR Exit	Tested	4:28:40 PM	09/10/2019
Pull Station	Building G MPR Exit	Tested	4:29:10 PM	09/10/2019
Pull Station	Building G MPR Exit by Stage	Tested	4:26:34 PM	09/10/2019
Pull Station	Portable 29	Tested	4:44:45 PM	09/10/2019
Smoke Detector	Building A Room 1	Tested	5:53:27 PM	09/10/2019
Smoke Detector	Building A Room 1	Tested	5:53:42 PM	09/10/2019
Smoke Detector	Building A Room 2	Tested	5:55:02 PM	09/10/2019
Smoke Detector	Building A Room 2	Tested	5:55:13 PM	09/10/2019
Smoke Detector	Building A Room 3	Tested	5:56:36 PM	09/10/2019
Smoke Detector	Building A Room 3	Tested	5:56:46 PM	09/10/2019
Smoke Detector	Building A Room 4	Tested	5:58:41 PM	09/10/2019
Smoke Detector	Building B Room 10	Tested	5:38:52 PM	09/10/2019
Smoke Detector	Building B Room 10	Tested	5:39:05 PM	09/10/2019
Smoke Detector	Building B Room 7	Tested	5:44:49 PM	09/10/2019
Smoke Detector	Building B Room 7	Tested	5:46:26 PM	09/10/2019
Smoke Detector	Building B Room 9	Tested	5:40:21 PM	09/10/2019
Smoke Detector	-	Tested	5:40:32 PM	
	Building B Room 9 Building B Storage Room		5:37:07 PM	09/10/2019
Smoke Detector	Building B Storage Room	Tested	5:27:23 PM	09/10/2019
Smoke Detector	Building C Room 13	Tested	J.27.23 FIVI	09/10/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building C Room 13	Tested	5:27:36 PM	09/10/2019
Smoke Detector	Building C Room 14	Tested	5:29:07 PM	09/10/2019
Smoke Detector	Building C Room 14	Tested	5:29:22 PM	09/10/2019
Smoke Detector	Building C Room 15	Tested	5:30:51 PM	09/10/2019
Smoke Detector	Building C Room 15	Tested	5:31:03 PM	09/10/2019
Smoke Detector	Building C Room 16	Tested	5:31:12 PM	09/10/2019
Smoke Detector	Building C Room 16	Tested	5:31:22 PM	09/10/2019
Smoke Detector	Building D Room 11	Tested	5:17:40 PM	09/10/2019
Smoke Detector	Building D Room 11	Tested	5:17:57 PM	09/10/2019
Smoke Detector	Building D Room 12	Tested	5:20:20 PM	09/10/2019
Smoke Detector	Building D Room 12	Tested	5:20:32 PM	09/10/2019
Smoke Detector	Building E Room 5	Tested	5:48:30 PM	09/10/2019
Smoke Detector	Building E Room 5	Tested	5:48:42 PM	09/10/2019
Smoke Detector	Building E Room 6	Tested	5:46:34 PM	09/10/2019
Smoke Detector	Building E Room 6	Tested	5:46:46 PM	09/10/2019
Smoke Detector	Building F Admin Entrance	Tested	3:56:45 PM	09/10/2019
Smoke Detector	Building F Assistant Principal Office	Tested	4:04:24 PM	09/10/2019
Smoke Detector	Building F Conference Room	Tested	4:00:41 PM	09/10/2019
Smoke Detector	Building F Corridor by Conference room	Tested	4:02:34 PM	09/10/2019
Smoke Detector	Building F Corridor by Nurse Office	Tested	4:05:10 PM	09/10/2019
Smoke Detector	Building F Counselor Office	Tested	4:05:54 PM	09/10/2019
Smoke Detector	Building F Custodian Electrical Room	Tested	3:54:14 PM	09/10/2019
Smoke Detector	Building F Custodian Room	Tested	3:52:00 PM	09/10/2019
Smoke Detector	Building F Nurse Office	Tested	4:03:09 PM	09/10/2019
Smoke Detector	Building F Principal Office	Tested	3:59:37 PM	09/10/2019
Smoke Detector	Building F Staff Lounge	Tested	4:06:54 PM	09/10/2019
Smoke Detector	Building F Utility Work Room	Tested	4:07:40 PM	09/10/2019
Smoke Detector	Building G Kindergarten A	Tested	4:13:57 PM	09/10/2019
Smoke Detector	Building G Kindergarten A	Tested	4:14:11 PM	09/10/2019
Smoke Detector	Building G Kindergarten A Storage	Tested	4:13:40 PM	09/10/2019
Smoke Detector	Building G Kindergarten B	Tested	4:10:24 PM	09/10/2019
Smoke Detector	Building G Kindergarten B	Tested	4:10:44 PM	09/10/2019
Smoke Detector	Building G Kindergarten B Storage	Tested	4:12:55 PM	09/10/2019
Smoke Detector	Building G Kitchen	Tested	4:35:20 PM	09/10/2019
Smoke Detector	Building G Kitchen Corridor	Tested	4:38:20 PM	09/10/2019
Smoke Detector	Building G Kitchen Office	Tested	4:39:44 PM	09/10/2019
Smoke Detector	Building G Kitchen Toilet Entry	Tested	4:36:54 PM	09/10/2019
Smoke Detector	Building G MPR	Tested	4:18:15 PM	09/10/2019
Smoke Detector	Building G MPR	Tested	4:19:13 PM	09/10/2019
Smoke Detector	Building G MPR	Tested	4:19:20 PM	09/10/2019
Smoke Detector	Building G MPR	Tested	4:19:30 PM	09/10/2019
Smoke Detector	Building G MPR	Tested	4:19:38 PM	09/10/2019
Smoke Detector	Building G MPR	Tested	4:19:46 PM	09/10/2019
Smoke Detector	Building G MPR on Stage	Tested	4:23:29 PM	09/10/2019
Smoke Detector	Building G MPR on Stage	Tested	4:23:38 PM	09/10/2019
Smoke Detector	Building G MPR on Stage Storage	Tested	4:25:09 PM	09/10/2019
Smoke Detector	Building H Room 17	Tested	5:15:22 PM	09/10/2019
Smoke Detector	Building H Room 17	Tested	5:15:32 PM	09/10/2019
Smoke Detector	Building H Room 19	Tested	5:13:24 PM	09/10/2019
1	-			

Device Type	Location	Service	Time	Date	
Passed					
Smoke Detector	Building H Room 20	Tested	5:11:11 PM	09/10/2019	
Smoke Detector	Building H Room 20	Tested	5:12:05 PM	09/10/2019	
Smoke Detector	Building I Mechanical Room	Tested	5:04:43 PM	09/10/2019	
Smoke Detector	Building I North Workroom	Tested	5:10:05 PM	09/10/2019	
Smoke Detector	Building I Room 21	Tested	5:07:06 PM	09/10/2019	
Smoke Detector	Building I Room 21	Tested	5:07:45 PM	09/10/2019	
Smoke Detector	Building I South Workroom	Tested	5:09:08 PM	09/10/2019	
Smoke Detector	Building J Library	Tested	4:58:12 PM	09/10/2019	
Smoke Detector	Building J Library	Tested	4:58:31 PM	09/10/2019	
Smoke Detector	Building J Library	Tested	4:58:39 PM	09/10/2019	
Smoke Detector	Building J Library	Tested	4:58:50 PM	09/10/2019	
Smoke Detector	Building J Room 25	Tested	4:54:44 PM	09/10/2019	
Smoke Detector	Building J Room 25	Tested	4:55:22 PM	09/10/2019	
Smoke Detector	Portable 26	Tested	4:52:11 PM	09/10/2019	
Smoke Detector	Portable 26	Tested	4:52:29 PM	09/10/2019	
Smoke Detector	Portable 27	Tested	4:50:54 PM	09/10/2019	
Smoke Detector	Portable 27	Tested	4:51:08 PM	09/10/2019	
Smoke Detector	Portable 28	Tested	4:48:29 PM	09/10/2019	
Smoke Detector	Portable 28	Tested	4:48:41 PM	09/10/2019	
Smoke Detector	Portable 29	Tested	4:44:23 PM	09/10/2019	
Smoke Detector	Portable 29	Tested	4:44:33 PM	09/10/2019	
Smoke Detector	Portable 30	Tested	4:41:59 PM	09/10/2019	
Smoke Detector	Portable 30	Tested	4:42:24 PM	09/10/2019	
Device Type	Location	Service	Time	Date	
	Failed/O	other			
Initiating					
Heat Detector	Building B FAU Room 9	Tested	5:44:26 PM	09/10/2019	

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Newport Heights Elementary

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity			
Failed/Other					
Heat Detector	Tested	1			
Total		1			
	Passed				
Battery	Inspected	2			
Battery	Tested	4			
Control Panel	Tested	1			
Heat Detector	Tested	56			
Power Supply	Tested	2			
Pull Station	Tested	6			
Smoke Detector	Tested	88			
Total		160			

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: NMUSD - Newport HeightsControl Panel: 1 - SimplexGrinnellElementary4100U

The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.

Туре	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
		Passe	ed				
Battery							
Sealed Lead Acid	Building C Custodial Closet	7	12				
Sealed Lead Acid	Building C Custodial Closet	7	12				
Sealed Lead Acid	Building G MPR Storage	7	12				
Sealed Lead Acid	Building G MPR Storage	7	12				

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Newport Heights Elementary

Control Panel: 1 - SimplexGrinnell 4100U

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type		Category	% of Inventory	Quantity
Control Panel		Control	0.62%	1
Smoke Detector		Initiating	55.00%	88
Pull Station		Initiating	3.75%	6
Battery		Control	3.75%	6
Power Supply		Control	1.25%	2
Heat Detector		Initiating	35.62%	57
	Qt			
Туре	у	Model #	Description	Install Date
		New (i	under 90 days)	
Simplex				
Power Supply	2	4009		09/10/2019
Pull Station	6	4099-9001		09/10/2019
Smoke Detector	3	4098-9714	Photoelectric	09/10/2019
Smoke Detector	85	4099-9001		09/10/2019
SimplexGrinnell				
Control Panel	1	4100U		09/10/2019
		In Service	- 2 Years to 3 Years	
12V7Ah				
Battery	4	12V7Ah	Sealed Lead Acid	08/10/2017
Battery	2	12v26ah	Sealed Lead Acid	08/08/2017
SimplexGrinnell				
Heat Detector	57	4098-9403	Fixed Temperature	08/08/2017

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Paularino Elementary School 1060 Paularino Avenue Costa Mesa, CA 92626

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Aug 16, 2019

> Building: NMUSD - Paularino Elementary School Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Michael Cannon Title: Service Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD - Paularino Elementary School	Contact: Tim V	Waller
Address: 1060 Paularino Avenue	Phone: 714-23	31-0363
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92626	Mobile:	
Country: United States of America	Email: twaller@	@nmusd.us
Inspection Performed By		
Company: Cal Building Systems	Inspector: Mic	hael Cannon
Address: 2903 Saturn Street	Phone: 714-7	15-1223
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: mcanne	on@calbuildingsystems.com
System Control Unit		
Manufacturer: Silent Knight	Inspection Dat	te: 08/16/2019 IDC Style:
Model Number: IFP-1000	Install Date: 0	8/16/2019 SLC Style:
Software Version:	Version Date:	08/16/2019 NAC Style:
Location: Admin Bldg Nurse Office MDF Closet	Current Protec	ction:
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Catalana	Tota	Items	Serviced		Passed		Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.49%	1	100.00%	0	0%	1	100.00%
Control	40	19.51%	40	100.00%	40	100.00%	0	0%
Initiating	164	80.00%	164	100.00%	164	100.00%	0	0%
Totals	205	100%	205	100.00%	204	99.51%	1	0.49%
Certification								
Company: Cal Building Systems			Bu	uilding: NMU	SD – Pau	Ilarino Elemo	entary Sc	hool
Inspector: Michael Cannon			C	ontact: Tim \	Waller			
- Judil Camm								
Signed: Aug 16, 2019 8:00:35	PM		Si	gned:				

Discrepancy Report Generated by: BuildingReports.com

Control Panel: n/a							
School							
The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.							
Device Type Manufacturer ModelNumber Date	Qty						
Items listed for Recall by Manufacturer							
No recalled items found during this inspection.							
Sound Test 🖸 Location 🕴 Problem Device 🚇 Refere	rence						
Sound Testing							
Sound Test 🖸 Location 😗 Problem Device 🕮 Reference							
Sound Test Points							
0001 Sound Test							

Proposed Solutions Report

Generated by: BuildingReports.com

Building: NMUSD - Paularino Elementary Control Panel: n/a School The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis. Solution Location Description Fix ScanID Cost Sound Testing Sound Test 0001 T/MPO #: (none) T/M

Notes & Recommendations

Generated by: BuildingReports.com

Building: NMUSD - Paularino Elementary School

Control Panel: n/a

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

ScanID	Note	Device Type	Location	Comment	
0001	1	Sound Test			
Horn outside of classroom 15 and 20 did not work.					

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Paularino Elementary School

Control Panel: 1 - Silent Knight IFP-1000

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Admin Bldg	Tested	7:33:50 AM	08/16/2019
Battery	Admin Bldg Nurse Office MDF Closet	Tested	7:25:31 AM	08/16/2019
Battery	Admin Bldg Nurse Office MDF Closet	Tested	7:26:04 AM	08/16/2019
Battery	Admin Bldg Nurse Office MDF Closet	Tested	7:26:55 AM	08/16/2019
Battery	Admin Bldg Nurse Office MDF Closet	Tested	7:27:02 AM	08/16/2019
Battery	Classroom 21A	Tested	9:40:34 AM	08/16/2019
Battery	Classroom 21A	Tested	9:40:46 AM	08/16/2019
Battery	Classroom 27	Tested	9:04:04 AM	08/16/2019
Battery	Classroom 27	Tested	9:04:30 AM	08/16/2019
Battery	Electrical Room Behind Classroom 28	Tested	8:51:16 AM	08/16/2019
Battery	Electrical Room Behind Classroom 28	Tested	8:51:39 AM	08/16/2019
Battery	IDF Closet Behind Classroom 3	Tested	8:02:08 AM	08/16/2019
Battery	IDF Closet Behind Classroom 3	Tested	8:02:29 AM	08/16/2019
Battery	IDF Closet Behind Library	Tested	8:05:41 AM	08/16/2019
Battery	IDF Closet Behind Library	Tested	8:05:49 AM	08/16/2019
Battery	IDF Room Outside Between Kindergarten	Tested	8:30:22 AM	08/16/2019
	Classrooms			
Battery	IDF Room Outside Between Kindergarten	Tested	8:31:03 AM	08/16/2019
Datta	Classrooms	T	0.10.50	00/10/005
Battery	MPR Building Outside Custodian/Mechanical Room	Tested	8:10:59 AM	08/16/2019
Battery	MPR Building Outside Custodian/Mechanical	Tested	8:11:25 AM	08/16/2019
	Room			
Battery	Portable 20 Casa Algeria	Tested	9:33:42 AM	08/16/2019
Battery	Portable 20 Casa Algeria	Tested	12:39:18 PM	08/16/2019
Battery	Portables Classroom 6	Tested	8:22:13 AM	08/16/2019
Battery	Portables Classroom 6	Tested	8:22:29 AM	08/16/2019
Battery	Storage Closet Behind Classroom 17A	Tested	9:15:23 AM	08/16/2019
Battery	Storage Closet Behind Classroom 17A	Tested	9:15:46 AM	08/16/2019
Battery	Classroom 14A	Tested	8:47:57 AM	08/16/2019
Battery	Classroom 14A	Tested	8:48:15 AM	08/16/2019
Control Panel	Admin Bldg Nurse Office MDF Closet	Tested	7:24:37 AM	08/16/2019
Power Supply	Admin Bldg Nurse Office MDF Closet	Tested	7:26:22 AM	08/16/2019
Power Supply	Classroom 21A	Inspected	9:39:42 AM	08/16/2019
Power Supply	Classroom 27	Inspected	9:03:31 AM	08/16/2019
Power Supply	Electrical Room Behind Classroom 28	Inspected	8:50:33 AM	08/16/2019
Power Supply	IDF Closet Behind Classroom 3	Tested	8:01:43 AM	08/16/2019
Power Supply	IDF Closet Library	Tested	8:05:27 AM	08/16/2019

Cal Building Systems

Device Type	Location	Service	Time	Date
	Passed			
Power Supply	IDF Room Outside Between Kindergarten	Inspected	8:29:28 AM	08/16/2019
Stree Supply	Classrooms	mapeeted		
Power Supply	MPR Building Outside Custodian/Mechanical	Inspected	8:10:31 AM	08/16/2019
i oli ol ouppi)	Room	mpetter		00,10,2010
Power Supply	Portable 20 Casa Algeria	Inspected	9:33:17 AM	08/16/2019
Power Supply	Portables Classroom 6	Tested	8:21:58 AM	08/16/2019
Power Supply	Storage Closet Behind Classroom 17A	Tested	9:15:02 AM	08/16/2019
Power Supply	Classroom 14A	Tested	8:47:32 AM	08/16/2019
Initiating				
Heat Detector	East Ability 1st	Tested	10:45:22 AM	08/16/2019
Heat Detector	East Classroom 11 Attic	Tested	10:48:45 AM	08/16/2019
Heat Detector	East Classroom 22 Attic	Tested	10:42:21 AM	08/16/2019
Heat Detector	East Classroom 23 Attic	Tested	10:42:42 AM	08/16/2019
Heat Detector	East Classroom 24 Attic	Tested	10:45:43 AM	08/16/2019
Heat Detector	East Classroom 24 Attic	Tested	10:46:05 AM	08/16/2019
Heat Detector	East Classroom 26 Attic	Tested	10:43:06 AM	08/16/2019
Heat Detector	East Classroom 27 Attic	Tested	10:43:30 AM	08/16/2019
Heat Detector	East Classroom 6 Attic	Tested	10:51:09 AM	08/16/2019
Heat Detector	East Classroom 7 Attic	Tested	10:51:32 AM	
			10:52:18 AM	08/16/2019
Heat Detector	East Classroom 8 Attic	Tested	10:47:54 AM	08/16/2019
Heat Detector	East Classroom 9 Attic	Tested	10:44:07 AM	08/16/2019
Heat Detector	North Classroom 31 Attic	Tested	10:44:07 AM	08/16/2019
Heat Detector	North Classroom 32 Attic	Tested	10:31:26 AM	08/16/2019
Heat Detector	Northeast Multi-Purpose Room Attic	Tested		08/16/2019
Heat Detector	South Classroom 29	Tested	10:34:05 AM	08/16/2019
Heat Detector	South Classroom 31 Attic	Tested	10:43:51 AM	08/16/2019
Heat Detector	South Classroom 32 Attic	Tested	10:44:18 AM	08/16/2019
Heat Detector	Southeast Multi-Purpose Room Attic	Tested	10:31:53 AM	08/16/2019
Heat Detector	West Ability 1st	Tested	10:44:44 AM	08/16/2019
Heat Detector	West Classroom 10 Attic	Tested	10:48:09 AM	08/16/2019
Heat Detector	West Classroom 10 Attic	Tested	10:48:23 AM	08/16/2019
Heat Detector	West Classroom 22 Attic	Tested	10:42:31 AM	08/16/2019
Heat Detector	West Classroom 23 Attic	Tested	10:42:53 AM	08/16/2019
Heat Detector	West Classroom 24 Attic	Tested	10:45:52 AM	08/16/2019
Heat Detector	West Classroom 25 Attic	Tested	10:46:16 AM	08/16/2019
Heat Detector	West Classroom 26 Attic	Tested	10:43:21 AM	08/16/2019
Heat Detector	West Classroom 27 Attic	Tested	10:43:42 AM	08/16/2019
Heat Detector	West Classroom 6 Attic	Tested	10:51:21 AM	08/16/2019
Heat Detector	West Classroom 7 Attic	Tested	10:52:09 AM	08/16/2019
Heat Detector	West Classroom 8 Attic	Tested	10:53:59 AM	08/16/2019
Heat Detector	West Classroom 9 Attic	Tested	10:47:42 AM	08/16/2019
Heat Detector	West Restroom By Classroom 14	Tested	10:47:12 AM	08/16/2019
Heat Detector	Admin Bldg Nurse Restroom	Tested	10:46:41 AM	08/16/2019
Heat Detector	Admin Bldg Teachers Lounge Restroom Attic	Tested	10:54:25 AM	08/16/2019
Heat Detector	Boys Restroom By Classroom 21	Tested	10:33:24 AM	08/16/2019
Heat Detector	Boy's Portable Restroom Attic	Tested	10:50:48 AM	08/16/2019
Heat Detector	Classroom 18 Heater Room	Tested	10:36:27 AM	08/16/2019
Heat Detector	Classroom 19 Heater Room	Tested	10:35:53 AM	08/16/2019
Heat Detector	Custodian Closet By Classroom 17A	Tested	9:12:32 AM	08/16/2019
Heat Detector	Girl's Portable Restroom Attic	Tested	10:50:03 AM	08/16/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	IDF Closet Behind Classroom 3	Tested	7:59:52 AM	08/16/2019
Heat Detector	IDF Closet Behind Library	Tested	8:07:08 AM	08/16/2019
Heat Detector	Kinder Bldg Staff Restroom	Tested	10:35:29 AM	08/16/2019
Heat Detector	Kinder Bldg Staff Restroom	Tested	10:36:41 AM	08/16/2019
Heat Detector	Multi-Purpose Room Kitchen	Tested	10:32:14 AM	08/16/2019
Heat Detector	Staff Portable Restroom Attic	Tested	10:50:24 AM	08/16/2019
Heat Detector	Storage Room Behind Classroom 29	Tested	8:53:18 AM	08/16/2019
Pull Station	Admin Bldg Entrance	Tested	7:40:28 AM	08/16/2019
Pull Station	Admin Bldg Teachers Lounge	Tested	7:34:58 AM	08/16/2019
Pull Station	Library	Tested	8:10:51 AM	08/16/2019
Pull Station	Library	Tested	8:11:04 AM	08/16/2019
Pull Station	MPR Building Corridor Exit	Tested	8:00:06 AM	08/16/2019
Pull Station	MPR Building Main Hall Exit	Tested	8:00:31 AM	08/16/2019
Pull Station	MPR Building Main Hall Exit	Tested	8:01:05 AM	08/16/2019
Pull Station	MPR Building Stage Exit	Tested	8:01:21 AM	08/16/2019
Smoke Detector	Admin Bldg Administrator Office	Tested	7:41:05 AM	08/16/2019
Smoke Detector	Admin Bldg Entrance	Tested	7:38:50 AM	08/16/2019
Smoke Detector	Admin Bldg Nurse Office MDF Closet	Tested	7:31:28 AM	08/16/2019
Smoke Detector	Admin Bldg Nurse Office Restroom	Tested	7:31:36 AM	08/16/2019
Smoke Detector	Admin Bldg Nurse Office	Tested	7:31:52 AM	08/16/2019
Smoke Detector	Admin Bldg Principal's Office	Tested	7:42:03 AM	08/16/2019
Smoke Detector	Admin Bldg Staff Restroom	Tested	7:46:20 AM	08/16/2019
Smoke Detector	Admin Bldg Teachers Lounge Restroom	Tested	7:36:04 AM	08/16/2019
Smoke Detector	Admin Bldg Teachers Lounge	Tested	7:36:17 AM	08/16/2019
Smoke Detector	Admin Bldg Teachers Lounge	Tested	7:36:36 AM	08/16/2019
Smoke Detector	Boy's Restroom Behind Classroom 14A	Tested	8:53:45 AM	08/16/2019
Smoke Detector	Boy's Restroom Behind Classroom 17A	Tested	9:16:06 AM	08/16/2019
Smoke Detector	Boy's Restroom Behind Classroom 21A	Tested	9:47:41 AM	08/16/2019
Smoke Detector	Classroom 1	Tested	7:49:53 AM	08/16/2019
Smoke Detector	Classroom 1	Tested	7:50:10 AM	08/16/2019
Smoke Detector	Classroom 2	Tested	7:50:55 AM	08/16/2019
Smoke Detector	Classroom 2	Tested	7:51:04 AM	08/16/2019
Smoke Detector	Classroom 20	Tested	9:50:14 AM	08/16/2019
Smoke Detector	Classroom 20	Tested	9:50:25 AM	08/16/2019
Smoke Detector	Classroom 21	Tested	9:36:18 AM	08/16/2019
Smoke Detector	Classroom 21	Tested	9:36:28 AM	08/16/2019
Smoke Detector	Classroom 21A	Tested	9:38:10 AM	08/16/2019
Smoke Detector	Classroom 28	Tested	8:45:47 AM	08/16/2019
Smoke Detector	Classroom 28	Tested	8:45:56 AM	08/16/2019
Smoke Detector	Classroom 29	Tested	8:43:17 AM	08/16/2019
Smoke Detector	Classroom 29	Tested	8:43:28 AM	08/16/2019
Smoke Detector	Classroom 3	Tested	7:54:03 AM	08/16/2019
Smoke Detector	Classroom 3	Tested	7:54:10 AM	08/16/2019
Smoke Detector	Classroom 30	Tested	8:40:20 AM	08/16/2019
Smoke Detector	Classroom 30	Tested	8:40:37 AM	08/16/2019
Smoke Detector	Classroom 5	Tested	8:16:05 AM	08/16/2019
Smoke Detector	Classroom 5	Tested	8:16:12 AM	08/16/2019
Smoke Detector	Electrical Closet Behind Classroom 1	Tested	7:57:18 AM	08/16/2019
Smoke Detector	Electrical Closet Behind Library	Tested	8:04:07 AM	08/16/2019
Smoke Detector	Electrical Room Behind Classroom 28	Tested	8:49:03 AM	08/16/2019
SHICKE DELECTOR	Lieutitai kooni beninu Classiooni 28	resteu	0.19.09 AM	00/10/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Girl's Restroom By Classroom 14A	Tested	8:48:46 AM	08/16/2019
Smoke Detector	Girl's Restroom By Classroom 17A	Tested	9:11:41 AM	08/16/2019
Smoke Detector	Girl's Restroom Near Classroom 21A	Tested	9:42:03 AM	08/16/2019
Smoke Detector	IDF Room Outside Between Kindergarten	Tested	8:20:13 AM	08/16/2019
	Classrooms			
Smoke Detector	Library	Tested	8:10:23 AM	08/16/2019
Smoke Detector	Library	Tested	8:10:38 AM	08/16/2019
Smoke Detector	Library	Tested	8:10:41 AM	08/16/2019
Smoke Detector	MPR Building Chair Storage Room	Tested	7:55:14 AM	08/16/2019
Smoke Detector	MPR Building Chair Storage Room	Tested	7:55:28 AM	08/16/2019
Smoke Detector	MPR Building Corridor Exit	Tested	7:56:21 AM	08/16/2019
Smoke Detector	MPR Building Kitchen Dining Room	Tested	8:03:19 AM	08/16/2019
Smoke Detector	MPR Building Main Hall	Tested	7:48:31 AM	08/16/2019
Smoke Detector	MPR Building Main Hall	Tested	7:50:53 AM	08/16/2019
Smoke Detector	MPR Building Main Hall	Tested	7:50:59 AM	08/16/2019
Smoke Detector	MPR Building Main Hall	Tested	7:51:06 AM	08/16/2019
Smoke Detector	MPR Building Outside Custodian Room	Tested	8:06:19 AM	08/16/2019
Smoke Detector	MPR Building Outside Custodian/Mechanical	Tested	8:09:06 AM	08/16/2019
	Room			
Smoke Detector	MPR Building Stage	Tested	7:53:47 AM	08/16/2019
Smoke Detector	MPR Building Stage	Tested	7:54:07 AM	08/16/2019
Smoke Detector	MPR Building Unisex Restroom	Tested	7:57:40 AM	08/16/2019
Smoke Detector	MPR Building Unisex Restroom	Tested	7:57:58 AM	08/16/2019
Smoke Detector	Portable Boy's Restroom	Tested	9:14:34 AM	08/16/2019
Smoke Detector	Portable Girl's Restroom	Tested	9:15:11 AM	08/16/2019
Smoke Detector	Portable Unisex Restroom	Tested	9:14:58 AM	08/16/2019
Smoke Detector	Portable 20 Casa Algeria	Tested	9:29:55 AM	08/16/2019
Smoke Detector	Portable 20 Casa Algeria	Tested	9:30:04 AM	08/16/2019
Smoke Detector	Portable 21 Casa Alegria	Tested	9:26:26 AM	08/16/2019
Smoke Detector	Portable 21 Casa Algeria	Tested	9:26:34 AM	08/16/2019
Smoke Detector	Portable 22	Tested	9:23:46 AM	08/16/2019
Smoke Detector	Portable 22	Tested	9:23:54 AM	08/16/2019
Smoke Detector	Portable 23	Tested	9:20:25 AM	08/16/2019
Smoke Detector	Portable 23	Tested	9:20:43 AM	08/16/2019
Smoke Detector	Portable 24	Tested	9:06:34 AM	08/16/2019
Smoke Detector	Portable 24	Tested	9:06:43 AM	08/16/2019
Smoke Detector	Portable 25	Tested	9:06:17 AM	08/16/2019
Smoke Detector	Portable 25	Tested	9:06:29 AM	08/16/2019
Smoke Detector	Portable 26	Tested	8:56:08 AM	08/16/2019
Smoke Detector	Portable 26	Tested	8:56:17 AM	08/16/2019
Smoke Detector	Portable 27	Tested	9:00:16 AM	08/16/2019
Smoke Detector	Portable 27	Tested	9:01:01 AM	08/16/2019
Smoke Detector	Portable 31	Tested	8:32:55 AM	08/16/2019
Smoke Detector	Portable 31	Tested	8:33:12 AM	08/16/2019
Smoke Detector	Portable 32	Tested	8:36:37 AM	08/16/2019
Smoke Detector	Portable 32	Tested	8:36:46 AM	08/16/2019
Smoke Detector	Portables Classroom 10	Tested	8:33:40 AM	08/16/2019
Smoke Detector	Portables Classroom 10	Tested	8:33:48 AM	08/16/2019
Smoke Detector	Portables Classroom 11	Tested	8:36:05 AM	08/16/2019
			8:36:12 AM	
Smoke Detector	Portables Classroom 11	Tested	0.30.12 AW	08/16/2019

Device Type	Location	Service	Time	Date			
Passed							
Smoke Detector	Portables Classroom 6	Tested	8:18:34 AM	08/16/2019			
Smoke Detector	Portables Classroom 6	Tested	8:18:47 AM	08/16/2019			
Smoke Detector	Portables Classroom 7	Tested	8:23:08 AM	08/16/2019			
Smoke Detector	Portables Classroom 7	Tested	8:23:15 AM	08/16/2019			
Smoke Detector	Portables Classroom 8	Tested	8:26:02 AM	08/16/2019			
Smoke Detector	Portables Classroom 8	Tested	8:26:20 AM	08/16/2019			
Smoke Detector	Portables Classroom 9	Tested	8:32:03 AM	08/16/2019			
Smoke Detector	Portables Classroom 9	Tested	8:32:12 AM	08/16/2019			
Smoke Detector	Staff Restroom By Classroom 14A	Tested	8:49:12 AM	08/16/2019			
Smoke Detector	Staff Restroom By Classroom 14A	Tested	8:49:25 AM	08/16/2019			
Smoke Detector	Stand Alone Building Storage Room Near MPR	Tested	8:14:14 AM	08/16/2019			
Smoke Detector	Stand Alone Building Storage Room Near MPR	Tested	8:14:53 AM	08/16/2019			
Smoke Detector	Storage Closet Behind Classroom 17A	Tested	9:13:47 AM	08/16/2019			
Smoke Detector	Unisex Restroom Near Classroom 21A	Tested	9:42:42 AM	08/16/2019			
Smoke Detector	Unisex Restroom Near Classroom 21A	Tested	9:42:56 AM	08/16/2019			
Smoke Detector	Classroom 14	Tested	8:40:18 AM	08/16/2019			
Smoke Detector	Classroom 14	Tested	8:40:30 AM	08/16/2019			
Smoke Detector	Classroom 14A	Tested	8:42:42 AM	08/16/2019			
Smoke Detector	Classroom 15	Tested	8:56:22 AM	08/16/2019			
Smoke Detector	Classroom 15	Tested	8:56:29 AM	08/16/2019			
Smoke Detector	Classroom 16	Tested	8:58:21 AM	08/16/2019			
Smoke Detector	Classroom 16	Tested	8:58:28 AM	08/16/2019			
Smoke Detector	Classroom 17	Tested	9:01:04 AM	08/16/2019			
Smoke Detector	Classroom 17	Tested	9:01:10 AM	08/16/2019			
Smoke Detector	Classroom 17A	Tested	9:00:47 AM	08/16/2019			

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Paularino Elementary School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Annunciator	Tested	1
Battery	Tested	26
Control Panel	Tested	1
Heat Detector	Tested	48
Power Supply	Inspected	6
Power Supply	Tested	6
Pull Station	Tested	8
Smoke Detector	Tested	108
Total		204

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - Paularino Elementary School

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

		Ambient	Alarm	🦻 Intell	igibility	Sound
C Location	 Comment 	◀ dB	◀ dB	Voice	STI	Test
Failed/Other						
Sound Test Points						
						0001

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Paularino Elementary School

Control Panel: 1 - Silent Knight IFP-1000

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category	% of Ir	nventory	Quantity
Control Panel		Control		0.49%	1
Battery		Control		12.68%	26
Power Supply		Control		5.85%	12
Smoke Detector		Initiating		52.68%	108
Annunciator		Control		0.49%	1
Pull Station		Initiating		3.90%	8
Heat Detector		Initiating	Γ	23.41%	48
Туре	Qty	Model #	Description		Install Date
		New (under 90 days)		
FCI					
Power Supply	2	SNAC-6			08/16/2019
Silent Knight					
Annunciator	1	SK-5860			08/16/2019
Control Panel	1	IFP-1000			08/16/2019
Heat Detector	1	SD505-AHS			08/16/2019
Power Supply	1	5495			08/16/2019
Pull Station	4	SD500-PS	Single Action		08/16/2019
Smoke Detector	56	SD505-APS	Photoelectric		08/16/2019
Wheelock					
Power Supply	5	PS-12/24-8CP			08/16/2019
Power Supply	4	PS-12/24-8MP			08/16/2019
		In Service	- 2 Years to 3 Year	S	
Battery	14	12v 7ah	Sealed Lead Acid		08/03/2017
Battery	10	12V7AH	Sealed Lead Acid		08/03/2017
Silent Knight					
Heat Detector	45	SD505-AHS	Fixed Temperature		08/03/2017
Heat Detector	2	SD505-HEAT	Fixed Temperature		08/03/2017
Pull Station	4	SD500-PS	Keyed		08/03/2017
Smoke Detector	51	SD505-APS	Photoelectric		08/03/2017
Smoke Detector	1	SD505-PHOTO	Photoelectric		08/03/2017
Battery	2	12V7AH	Sealed Lead Acid		12/16/2016

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Pomona Elementary School 2051 Pomona Avenue Costa Mesa, CA 92727

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Sep 11, 2019

> Building: NMUSD - Pomona Elementary School Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Michael Cannon Title: Service Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD – Pomona Elementary School	Contact: Tim Waller	
Address: 2051 Pomona Avenue	Phone: 714-231-0363	
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92727	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Michael Cannon	
Address: 2903 Saturn Street	Phone: 714-715-1223	
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: mcannon@calbuildingsy	stems.com
System Control Unit		
Manufacturer: Silent Knight	Inspection Date: 09/11/2019	IDC Style:
Model Number: IFP-1000	Install Date: 09/11/2019	SLC Style:
Software Version:	Version Date: 12/31/1969	NAC Style:
Location: Admin Building MDF Room Inside Nurse's Office	Current Protection:	
Monitoring		
Company: Pho	one: Acco	unt #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Catalogue	Tota	ltems	Ser	viced	Passed		Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.54%	1	100.00%	1	100.00%	0	0%
Control	28	15.05%	28	100.00%	28	100.00%	0	0%
Initiating	157	84.41%	157	100.00%	157	100.00%	0	0%
Totals	186	100%	186	100.00%	186	100.00%	0	0%
Certification								
Company: Cal Building Systems			Bu	ilding: NML	JSD – Pon	nona Elemei	ntary Scho	ol
Inspector: Michael Cannon			Co	ontact: Tim	Waller			
Jon Comm								
Signed: Sep 11, 2019 8:47:11	PM		Sig	gned:				

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Pomona Elementary School

Control Panel: 1 - Silent Knight IFP-1000

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Admin Building Behind Reception	Inspected	3:48:59 PM	09/11/2019
Battery	IDF RM behind Classroom 23	Tested	5:32:11 PM	09/11/2019
Battery	IDF RM behind Classroom 23	Tested	5:32:39 PM	09/11/2019
Battery	Admin Building MDF Room Inside Nurse's Office	Tested	3:15:57 PM	09/11/2019
Battery	Admin Building MDF Room Inside Nurse's Office	Tested	3:16:44 PM	09/11/2019
Battery	Building 7 IDF Closet	Tested	4:19:34 PM	09/11/2019
Battery	Building 7 IDF Closet	Tested	4:20:41 PM	09/11/2019
Battery	Heater Room Behind Classroom 5	Tested	4:47:06 PM	09/11/2019
Battery	Heater Room Behind Classroom 5	Tested	4:47:29 PM	09/11/2019
Battery	IDF Room Behind Classroom 20	Tested	5:23:00 PM	09/11/2019
Battery	IDF Room Behind Classroom 20	Tested	5:23:20 PM	09/11/2019
Battery	Kindergarten Building IDF/Storage Room	Tested	4:33:38 PM	09/11/2019
Battery	Kindergarten Building IDF/Storage Room	Tested	4:34:33 PM	09/11/2019
Battery	MPR Building Outside Custodian Room	Tested	5:16:39 PM	09/11/2019
Battery	MPR Building Outside Custodian Room	Tested	5:17:06 PM	09/11/2019
Battery	Portable 14	Tested	4:59:12 PM	09/11/2019
Battery	Portable 14	Tested	4:59:28 PM	09/11/2019
Battery	Portable 26	Tested	5:32:55 PM	09/11/2019
Battery	Portable 26	Tested	5:33:05 PM	09/11/2019
Control Panel	Admin Building MDF Room Inside Nurse's Office	Tested	3:15:04 PM	09/11/2019
Power Supply	IDF RM behind Classroom 23	Tested	5:31:22 PM	09/11/2019
Power Supply	Building 7 IDF Closet	Inspected	4:19:03 PM	09/11/2019
Power Supply	Heater Room Behind Classroom 5	Inspected	4:47:55 PM	09/11/2019
Power Supply	IDF Room Behind Classroom 20	Inspected	5:22:29 PM	09/11/2019
Power Supply	Kindergarten Building IDF/Storage Room	Inspected	4:31:01 PM	09/11/2019
Power Supply	MPR Building Outside Custodian Room	Inspected	5:15:26 PM	09/11/2019
Power Supply	Portable 14	Inspected	4:58:42 PM	09/11/2019
Power Supply	Portable 26	Inspected	5:32:33 PM	09/11/2019
Initiating				
Heat Detector	East Portable 11	Tested	4:14:40 PM	09/11/2019
Heat Detector	East Portable 12	Tested	4:13:38 PM	09/11/2019
Heat Detector	East Portable 13	Tested	4:12:58 PM	09/11/2019
Heat Detector	East Portable 14	Tested	4:12:26 PM	09/11/2019
Heat Detector	East Portable 28	Tested	4:23:06 PM	09/11/2019
Heat Detector	East Portable 29	Tested	4:22:39 PM	09/11/2019
Heat Detector	East Portable 30	Tested	4:20:31 PM	09/11/2019
Heat Detector	North MPR Attic	Tested	4:16:46 PM	09/11/2019

Cal Building Systems

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	North Portable 26	Tested	4:21:18 PM	09/11/2019
Heat Detector	North Portable 27	Tested	4:21:55 PM	09/11/2019
Heat Detector	North Portable P1	Tested	4:14:52 PM	09/11/2019
Heat Detector	North Portable P2	Tested	4:15:26 PM	09/11/2019
Heat Detector	Northeast MPR Attic	Tested	4:18:13 PM	09/11/2019
Heat Detector	Northwest MPR Attic	Tested	4:17:59 PM	09/11/2019
Heat Detector	South Portable 26	Tested	4:21:42 PM	09/11/2019
Heat Detector	South Portable 27	Tested	4:22:08 PM	09/11/2019
Heat Detector	South Portable P1	Tested	4:15:09 PM	09/11/2019
Heat Detector	South Portable P2	Tested	4:15:41 PM	09/11/2019
Heat Detector	Southeast MPR Attic	Tested	4:18:41 PM	09/11/2019
Heat Detector	Southwest MPR Attic	Tested	4:18:26 PM	09/11/2019
Heat Detector	West Portable 11	Tested	4:14:02 PM	09/11/2019
Heat Detector	West Portable 12	Tested	4:13:16 PM	09/11/2019
Heat Detector	West Portable 13	Tested	4:12:40 PM	09/11/2019
Heat Detector	West Portable 14	Tested	4:12:00 PM	09/11/2019
Heat Detector	West Portable 28	Tested	4:22:51 PM	09/11/2019
Heat Detector	West Portable 29	Tested	4:22:21 PM	09/11/2019
Heat Detector	West Portable 30	Tested	4:20:54 PM	09/11/2019
Heat Detector	Admin Nurse RR	Tested	4:23:52 PM	09/11/2019
Heat Detector	Admin Woman's RR	Tested	4:23:28 PM	09/11/2019
Heat Detector	Bldg. 10 Electrical Rm	Tested	4:20:03 PM	09/11/2019
Heat Detector	Bldg. 11 Janitor Closet	Tested	4:24:10 PM	09/11/2019
Heat Detector	Bldg. 3 Electrical Rm	Tested	4:15:58 PM	09/11/2019
Heat Detector	Bldg. 4 Janitor Electrical Rm	Tested	4:16:28 PM	09/11/2019
Heat Detector	Bldg. 5 Electrical Rm	Tested	4:19:39 PM	09/11/2019
Heat Detector	Bldg. 6 Electrical Rm	Tested	4:20:18 PM	09/11/2019
Heat Detector	Bldg. 9 Adult RR Attic	Tested	4:10:36 PM	09/11/2019
Heat Detector	Bldg. 9 Heater Closet	Tested	4:11:25 PM	09/11/2019
Heat Detector	Bldg. 9 Heater Closet	Tested	4:11:50 PM	09/11/2019
Heat Detector	Kitchen	Tested	4:18:53 PM	09/11/2019
Heat Detector	MPR Janitor Closet	Tested	4:19:15 PM	09/11/2019
Heat Detector	RM 1 RR Attic	Tested	4:10:05 PM	09/11/2019
Heat Detector	RM 2 RR Attic	Tested	4:07:21 PM	09/11/2019
Pull Station	North MPR Exit	Tested	4:42:47 PM	09/11/2019
Pull Station	South MPR Exit	Tested	4:53:22 PM	09/11/2019
Pull Station	West MPR Exit	Tested	4:50:58 PM	09/11/2019
Pull Station	Admin Building Reception	Tested	3:43:21 PM	09/11/2019
Pull Station	Admin Building Staff Lounge	Tested	3:46:40 PM	09/11/2019
Pull Station	MPR Stage Exit	Tested	4:53:59 PM	09/11/2019
Pull Station	Portable 11	Tested	4:50:23 PM	09/11/2019
Pull Station	Portable 13	Tested	4:55:06 PM	09/11/2019
Smoke Detector	IDF RM behind Classroom 23	Tested	5:33:02 PM	09/11/2019
Smoke Detector	North MPR Exit	Tested	4:45:57 PM	09/11/2019
Smoke Detector	Storage Rm by Boys RR	Tested	5:02:18 PM	09/11/2019
Smoke Detector	Admin Building Administrator's Office	Tested	3:49:52 PM	09/11/2019
Smoke Detector	Admin Building MDF Room Inside Nurse's Office	Tested	3:25:15 PM	09/11/2019
Smoke Detector	Admin Building Nurse's Office	Tested	3:37:39 PM	09/11/2019
	-		3:26:53 PM	
Smoke Detector	Admin Building Nurse's Restroom	Tested	5.20.55114	09/11/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Admin Building Principal's Office	Tested	3:51:12 PM	09/11/2019
Smoke Detector	Admin Building Reception	Tested	3:41:49 PM	09/11/2019
Smoke Detector	Admin Building Staff Lounge	Tested	3:44:13 PM	09/11/2019
Smoke Detector	Admin Building Staff Lounge	Tested	3:45:59 PM	09/11/2019
Smoke Detector	Admin Building Staff Lounge Restroom	Tested	3:47:08 PM	09/11/2019
Smoke Detector	Boys RR	Tested	5:01:19 PM	09/11/2019
Smoke Detector	Boys RR	Tested	5:13:36 PM	09/11/2019
Smoke Detector	Boy's Restroom Near Classroom 5	Tested	4:43:34 PM	09/11/2019
Smoke Detector	Building 7 IDF Closet	Tested	4:18:08 PM	09/11/2019
Smoke Detector	Building 8 Boy's Restroom	Tested	3:58:22 PM	09/11/2019
Smoke Detector	Building 8 Girl's Restroom	Tested	4:00:54 PM	09/11/2019
Smoke Detector	Building 8 Storage Room	Tested	3:59:24 PM	09/11/2019
Smoke Detector	Classroom 10	Tested	4:04:33 PM	09/11/2019
Smoke Detector	Classroom 10	Tested	4:04:42 PM	09/11/2019
Smoke Detector	Classroom 10A	Tested	4:02:53 PM	09/11/2019
Smoke Detector	Classroom 16	Tested	5:05:23 PM	09/11/2019
Smoke Detector	Classroom 16	Tested	5:05:35 PM	09/11/2019
Smoke Detector	Classroom 16A	Tested	5:07:41 PM	09/11/2019
Smoke Detector	Classroom 17	Tested	5:08:41 PM	09/11/2019
Smoke Detector	Classroom 17	Tested	5:08:52 PM	09/11/2019
Smoke Detector	Classroom 20	Tested	5:25:34 PM	
Smoke Detector	Classroom 20	Tested	5:25:50 PM	09/11/2019
Smoke Detector	Classroom 21	Tested	5:10:42 PM	09/11/2019
Smoke Detector	Classroom 21	Tested	5:10:54 PM	09/11/2019
Smoke Detector	Classroom 22	Tested	5:15:47 PM	09/11/2019
Smoke Detector	Classroom 22	Tested	5:15:58 PM	09/11/2019
Smoke Detector	Classroom 22A	Tested	5:15:05 PM	09/11/2019
	Classroom 23		5:28:15 PM	09/11/2019
Smoke Detector Smoke Detector	Classroom 23	Tested Tested	5:28:25 PM	09/11/2019
			5:26:48 PM	09/11/2019
Smoke Detector	Classroom 24	Tested	5:26:59 PM	09/11/2019
Smoke Detector	Classroom 24 Classroom 25	Tested	5:25:21 PM	09/11/2019
Smoke Detector Smoke Detector		Tested	5:25:36 PM	09/11/2019
	Classroom 25	Tested	4:38:41 PM	09/11/2019
Smoke Detector	Classroom 3	Tested	4:38:53 PM	09/11/2019
Smoke Detector	Classroom 3	Tested		09/11/2019
Smoke Detector	Classroom 4	Tested	4:40:08 PM 4:40:18 PM	09/11/2019
Smoke Detector	Classroom 4	Tested		09/11/2019
Smoke Detector	Classroom 5	Tested	4:40:22 PM	09/11/2019
Smoke Detector	Classroom 5	Tested	4:40:31 PM	09/11/2019
Smoke Detector	Classroom 6	Tested	4:12:05 PM	09/11/2019
Smoke Detector	Classroom 6	Tested	4:12:15 PM	09/11/2019
Smoke Detector	Classroom 7	Tested	4:09:16 PM	09/11/2019
Smoke Detector	Classroom 7	Tested	4:09:24 PM	09/11/2019
Smoke Detector	Classroom 8	Tested	4:06:58 PM	09/11/2019
Smoke Detector	Classroom 8	Tested	4:07:09 PM	09/11/2019
Smoke Detector	Classroom 9	Tested	5:08:46 PM	09/11/2019
Smoke Detector	Classroom 9	Tested	5:09:00 PM	09/11/2019
Smoke Detector	Classrooms 18 And 19	Tested	5:27:48 PM	09/11/2019
Smoke Detector	Classrooms 18 And 19	Tested	5:28:04 PM	09/11/2019
Smoke Detector	Classrooms 18 And 19	Tested	5:28:09 PM	09/11/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Classrooms 18 And 19	Tested	5:28:15 PM	09/11/2019
Smoke Detector	Girls RR	Tested	5:04:00 PM	09/11/2019
Smoke Detector	Girl's Restroom Near Classroom 5	Tested	4:44:32 PM	09/11/2019
Smoke Detector	Heater Room Behind Classroom 5	Tested	4:45:52 PM	09/11/2019
Smoke Detector	IDF Room Behind Classroom 20	Tested	5:23:32 PM	09/11/2019
Smoke Detector	IDF Room Behind Classroom 3	Tested	5:00:47 PM	09/11/2019
Smoke Detector	Kindergarten Building IDF/Storage Room	Tested	4:34:53 PM	09/11/2019
Smoke Detector	Kindergarten Classroom 1 Restrooms	Tested	4:21:42 PM	09/11/2019
Smoke Detector	Kindergarten Classroom 1	Tested	4:21:10 PM	09/11/2019
Smoke Detector	Kindergarten Classroom 1	Tested	4:21:37 PM	09/11/2019
Smoke Detector	Kindergarten Classroom 2 Restroom	Tested	4:28:05 PM	09/11/2019
Smoke Detector	Kindergarten Classroom 2	Tested	4:27:52 PM	09/11/2019
Smoke Detector	Kindergarten Classroom 2	Tested	4:28:01 PM	09/11/2019
Smoke Detector	Kindergarten Unisex Restroom	Tested	4:27:00 PM	09/11/2019
Smoke Detector	Kindergarten Workroom	Tested	4:26:04 PM	09/11/2019
Smoke Detector	MPR	Tested	4:49:27 PM	09/11/2019
Smoke Detector	MPR	Tested	4:49:41 PM	09/11/2019
Smoke Detector	MPR	Tested	4:49:48 PM	09/11/2019
Smoke Detector	MPR	Tested	4:49:57 PM	09/11/2019
Smoke Detector	MPR Building Outside Custodian Room	Tested	5:17:40 PM	09/11/2019
Smoke Detector	MPR Building Storage Room	Tested	5:52:55 PM	09/11/2019
Smoke Detector	MPR Men RR	Tested	4:47:24 PM	09/11/2019
Smoke Detector	MPR Office	Tested	4:52:04 PM	09/11/2019
Smoke Detector	MPR Stage	Tested	4:54:20 PM	09/11/2019
Smoke Detector	MPR Stage	Tested	4:54:39 PM	09/11/2019
Smoke Detector	MPR Woman RR	Tested	4:48:43 PM	09/11/2019
Smoke Detector	Portable 11	Tested	4:51:13 PM	09/11/2019
Smoke Detector	Portable 11	Tested	4:51:33 PM	09/11/2019
Smoke Detector	Portable 12	Tested	4:53:12 PM	09/11/2019
Smoke Detector	Portable 12	Tested	4:53:21 PM	09/11/2019
Smoke Detector	Portable 13	Tested	4:54:45 PM	09/11/2019
Smoke Detector	Portable 13	Tested	4:54:55 PM	09/11/2019
Smoke Detector	Portable 14	Tested	4:56:53 PM	09/11/2019
Smoke Detector	Portable 14	Tested	4:57:51 PM	09/11/2019
Smoke Detector	Portable 26	Tested	5:23:23 PM	09/11/2019
Smoke Detector	Portable 26	Tested	5:23:35 PM	09/11/2019
Smoke Detector	Portable 27	Tested	5:21:36 PM	09/11/2019
Smoke Detector	Portable 27	Tested	5:21:46 PM	09/11/2019
Smoke Detector	Portable 29		5:19:50 PM	
Smoke Detector	Portable 29 Portable 29	Tested Tested	5:20:01 PM	09/11/2019
		Tested	5:18:00 PM	09/11/2019
Smoke Detector	Portable 30		5:18:15 PM	09/11/2019
Smoke Detector	Portable 30 Portable P1	Tested	5:03:07 PM	09/11/2019
Smoke Detector	Portable P1	Tested		09/11/2019
Smoke Detector	Portable P1	Tested	5:03:51 PM 5:05:11 PM	09/11/2019
Smoke Detector	Portable P2	Tested		09/11/2019
Smoke Detector	Portable P2 Storage Bm by MPB	Tested	5:05:22 PM	09/11/2019
Smoke Detector	Storage Rm by MPR	Tested	4:58:46 PM	09/11/2019
Smoke Detector	Unisex RR	Tested	5:12:42 PM	09/11/2019
Smoke Detector	Unisex RR	Tested	5:12:58 PM	09/11/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Pomona Elementary School

The Service Summary section provides an overview of the services performed in this report.

	I	Т
Device Type	Service	Quantity
	Passed	
Annunciator	Inspected	1
Battery	Tested	18
Control Panel	Tested	1
Heat Detector	Tested	42
Power Supply	Inspected	7
Power Supply	Tested	1
Pull Station	Tested	8
Smoke Detector	Tested	107
Total		185

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - Pomona Elementary School

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

			Ambient	Alarm	🦻 Intell	igibility	Sound
C Location	🗨 Co	omment	◀ dB	◀ dB	Voice	STI	Test
		Passed					
Sound Test Points							
Entire Campus	Passed						0001

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: NMUSD - Pomona Elementary	
School	

Control Panel: 1 - Silent Knight IFP-1000

The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.

Туре	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
		Passe	d				
Battery							
Sealed Lead Acid	IDF RM behind Classroom 23	12	7				
Sealed Lead Acid	IDF RM behind Classroom 23	12	7				

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Pomona Elementary School

Control Panel: 1 - Silent Knight IFP-1000

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type		Category	% of Inventory	Quantity
Control Panel		Control	0.54%	1
Battery		Control	9.68%	18
Smoke Detector		Initiating	57.53%	107
Pull Station		Initiating	4.30%	8
Annunciator		Control	0.54%	1
Heat Detector		Initiating	22.58%	42
Power Supply		Control	4.30%	8
Sound Test		Sound Test	0.54%	1
	Qt			
Туре	y	Model #	Description	Install Date
		New	(under 90 days)	
12V7Ah			· · · · · · · · · · · · · · · · · · ·	
Battery	2	12V7Ah	Sealed Lead Acid	09/11/2019
Silent Knight				
Annunciator	1			09/11/2019
Control Panel	1	IFP-1000		09/11/2019
Heat Detector	42	SD505-AHS	Rate-of-Rise	09/11/2019
Power Supply	7	RPS-1000		09/11/2019
Power Supply	1	RSP-1000		09/11/2019
Pull Station	8	SD500-PS	Keyed	09/11/2019
Smoke Detector	41	SD500-PS	Photoelectric	09/11/2019
Smoke Detector	1	SD505-AHS	Photoelectric	09/11/2019
Smoke Detector	65	SD505-APS	Photoelectric	09/11/2019
		In Servic	e - 2 Years to 3 Years	
Battery	14	12V7AH	Sealed Lead Acid	07/11/2017
Battery	2	12V18AH	Sealed Lead Acid	07/01/2017

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Rea Elementary School 661 Hamilton Street Costa Mesa, CA 92627

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Aug 27, 2019

> Building: NMUSD - Rea Elementary School Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Michael Cannon Title: Service Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD – Rea Elementary School	Contact: Tim Waller	
Address: 661 Hamilton Street	Phone: 714-231-0363	
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92627	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Michael Cannon	
Address: 2903 Saturn Street	Phone: 714-715-1223	
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: mcannon@calbuildingsy	stems.com
System Control Unit		
Manufacturer: Silent Knight	Inspection Date: 08/27/2019	IDC Style:
Model Number: IFP-1000	Install Date: 07/01/2017	SLC Style:
Software Version:	Version Date: 08/27/2019	NAC Style:
Location: Admin Building FACP Electrical Room By Staff Restrooms	Current Protection:	
Monitoring		
Company: Pho	one: Acco	ount #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
	Total	ltems	Serv	/iced	Pas	ssed	Failed	/Other
Category	Qty	%	Qty	%	Qty	%	Qty	%
Control	16	15.53%	16	100.00%	16	100.00%	0	0%
Initiating	87	84.47%	87	100.00%	87	100.00%	0	0%
Totals	103	100%	103	100.00%	103	100.00%	0	0%
Certification								
Company: Cal Building Systems			Bu	ilding: NML	JSD – Rea	Elementary	/ School	
Inspector: Michael Cannon			Co	ntact: Tim	Waller			
The Common								
Signed: Aug 26, 2019 3:26:39	PM		Sig	jned:				

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Rea Elementary School

Control Panel: 1 - Silent Knight IFP-1000

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator Battery	Admin Building Reception Admin Building FACP Electrical Room By Staff Restrooms	Inspected Tested	10:08:30 AM 9:55:17 AM	08/27/2019 08/27/2019
Battery	Admin Building FACP Electrical Room By Staff Restrooms	Tested	9:56:08 AM	08/27/2019
Battery	Boy's Restroom Janitor's Room Near Classroom 17	Tested	12:12:53 PM	08/27/2019
Battery	Boy's Restroom Janitor's Room Near Classroom 17	Tested	12:13:06 PM	08/27/2019
Battery	Boy's Restroom Janitor's Room Near Classroom 22	Tested	12:27:56 PM	08/27/2019
Battery	Boy's Restroom Janitor's Room Near Classroom 22	Tested	12:28:09 PM	08/27/2019
Battery	Boy's Restroom Janitor's Room Near Classroom 5	Tested	11:54:59 AM	08/27/2019
Battery	Boy's Restroom Janitor's Room Near Classroom 5	Tested	11:55:23 AM	08/27/2019
Battery	Boy's Restroom Storage Near Classroom 5	Tested	11:42:57 AM	08/27/2019
Battery	Boy's Restroom Storage Near Classroom 5	Tested	11:43:47 AM	08/27/2019
Control Panel	Admin Building FACP Electrical Room By Staff Restrooms	Inspected	9:54:01 AM	08/27/2019
Power Supply	Boy's Restroom Janitor's Room Next To Classroom 12	Inspected	11:54:22 AM	08/27/2019
Power Supply	Boy's Restroom Janitor's Room Next To Classroom 17	Inspected	12:12:36 PM	08/27/2019
Power Supply	Boy's Restroom Janitor's Room Next To Classroom 22	Inspected	12:27:21 PM	08/27/2019
Power Supply	Boy's Restroom Storage Next To Classroom 5	Inspected	11:40:51 AM	08/27/2019
Initiating				
Heat Detector	Portables Rm 27	Tested	9:58:38 AM	08/27/2019
Heat Detector	Portables Rm 27	Tested	10:04:35 AM	08/27/2019
Heat Detector	Portables Rm 28	Tested	10:05:03 AM	08/27/2019
Heat Detector	Portables Rm 28	Tested	10:05:37 AM	08/27/2019
Heat Detector	Portables Rm 29	Tested	10:06:02 AM	08/27/2019
Heat Detector	Portables Rm 29	Tested	10:07:08 AM	08/27/2019
Heat Detector	Portables Rm 30	Tested	10:07:17 AM	08/27/2019
Heat Detector	Portables Rm 30	Tested	10:07:59 AM	08/27/2019

Cal Building Systems

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	Portables Rm 31	Tested	10:08:08 AM	08/27/2019
Heat Detector	Portables Rm 31	Tested	10:09:04 AM	08/27/2019
Pull Station	Admin Building Corridor Next To Restrooms	Tested	10:07:03 AM	08/27/2019
Pull Station	Admin Building Reception Entrance	Tested	11:00:24 AM	08/27/2019
Pull Station	Admin Building Reception South Exit	Tested	10:59:13 AM	08/27/2019
Pull Station	Classroom 1	Tested	11:05:33 AM	08/27/2019
Pull Station	Classroom 12	Tested	11:57:18 AM	08/27/2019
Pull Station	Classroom 13	Tested	12:01:14 PM	08/27/2019
Pull Station	Classroom 14	Tested	12:02:21 PM	08/27/2019
Pull Station	Classroom 15	Tested	12:02:32 PM	08/27/2019
Pull Station	Classroom 16	Tested	12:04:17 PM	08/27/2019
Pull Station	Classroom 17	Tested	12:09:22 PM	08/27/2019
Pull Station	Classroom 18	Tested	12:08:37 PM	08/27/2019
Pull Station	Classroom 19	Tested	12:06:28 PM	08/27/2019
Pull Station	Classroom 2	Tested	11:06:05 AM	08/27/2019
Pull Station	Classroom 20	Tested	12:05:55 PM	08/27/2019
Pull Station	Classroom 21	Tested	12:05:28 PM	08/27/2019
Pull Station	Classroom 22	Tested	12:38:25 PM	08/27/2019
Pull Station	Classroom 23	Tested	12:39:16 PM	08/27/2019
Pull Station	Classroom 24	Tested	12:39:37 PM	08/27/2019
Pull Station	Classroom 25	Tested	12:41:05 PM	08/27/2019
Pull Station	Classroom 26	Tested	12:41:15 PM	08/27/2019
Pull Station	Classroom 3	Tested	11:12:19 AM	08/27/2019
Pull Station	Classroom 4	Tested	11:24:54 AM	08/27/2019
Pull Station	Classroom 5	Tested	11:33:01 AM	08/27/2019
Pull Station	Classroom 6	Tested	11:32:07 AM	08/27/2019
Pull Station	Classroom 7	Tested	11:30:15 AM	08/27/2019
Pull Station	Classroom 8	Tested	11:28:43 AM	08/27/2019
Pull Station	Classroom 9	Tested	11:27:54 AM	08/27/2019
Pull Station	Corridor Exit Next To Classroom 5	Tested	11:45:34 AM	08/27/2019
Pull Station	Corridor Exit Next To Classroom 8	Tested	11:47:15 AM	08/27/2019
Pull Station	Library East Exit	Tested	1:31:10 PM	08/27/2019
Pull Station	Library SE Exit	Tested	1:28:30 PM	08/27/2019
Pull Station	Library	Tested	1:24:11 PM	08/27/2019
Pull Station	Library	Tested	1:25:02 PM	08/27/2019
Pull Station	Multipurpose Room Kitchen	Tested	1:44:52 PM	08/27/2019
Pull Station	Multipurpose Room Stage	Tested	1:40:45 PM	08/27/2019
Pull Station	Multipurpose Room	Tested	1:38:32 PM	08/27/2019
Pull Station	Multipurpose Room	Tested	1:39:25 PM	08/27/2019
Pull Station	Multipurpose Room	Tested	1:39:55 PM	08/27/2019
Smoke Detector	Admin Building Nurse's Restroom	Tested	11:01:41 AM	08/27/2019
Smoke Detector	Admin Building Staff Restroom	Tested	10:06:18 AM	08/27/2019
Smoke Detector	Admin Building Staff Restroom	Tested	10:07:52 AM	08/27/2019
Smoke Detector	Boy's Restroom Next To Classroom 12	Tested	11:52:19 AM	08/27/2019
Smoke Detector	Boy's Restroom Next To Classroom 17	Tested	12:11:10 PM	08/27/2019
Smoke Detector	Boy's Restroom Next To Classroom 22	Tested	12:26:22 PM	08/27/2019
Smoke Detector	Boy's Restroom Next To Classroom 5	Tested	11:39:01 AM	08/27/2019
Smoke Detector	Boy's Restroom Janitor's Room Next To	Tested	11:53:47 AM	08/27/2019
	Classroom 12			
Smoke Detector	Boy's Restroom Janitor's Room Next To	Tested	12:11:24 PM	08/27/2019

Device Type	Location	Service	Time	Date
	Passed			
	Classroom 17			
Smoke Detector	Boy's Restroom Janitor's Room Next To Classroom 22	Tested	12:26:40 PM	08/27/2019
Smoke Detector	Boy's Restroom Storage Next To Classroom 5	Tested	11:39:47 AM	08/27/2019
Smoke Detector	Classroom 1	Tested	10:55:01 AM	08/27/2019
Smoke Detector	Classroom 1	Tested	10:56:54 AM	08/27/2019
Smoke Detector	Classroom 2	Tested	11:06:26 AM	08/27/2019
Smoke Detector	Classroom 2	Tested	11:06:44 AM	08/27/2019
Smoke Detector	Girl's Restroom Next To Classroom 12	Tested	11:50:36 AM	08/27/2019
Smoke Detector	Girl's Restroom Next To Classroom 17	Tested	12:17:49 PM	08/27/2019
Smoke Detector	Girl's Restroom Next To Classroom 22	Tested	12:20:36 PM	08/27/2019
Smoke Detector	Girl's Restroom Next To Classroom 5	Tested	11:33:57 AM	08/27/2019
Smoke Detector	Library Storage Room Between Unisex	Tested	1:33:13 PM	08/27/2019
	Restrooms			
Smoke Detector	Library Unisex Restroom Janitor's Room	Tested	1:31:55 PM	08/27/2019
Smoke Detector	Library Unisex Restroom	Tested	1:34:34 PM	08/27/2019
Smoke Detector	Library Unisex Restroom	Tested	1:36:57 PM	08/27/2019
Smoke Detector	Portable 27	Tested	12:45:05 PM	08/27/2019
Smoke Detector	Portable 27	Tested	12:45:20 PM	08/27/2019
Smoke Detector	Portable 28	Tested	12:45:26 PM	08/27/2019
Smoke Detector	Portable 28	Tested	12:45:37 PM	08/27/2019
Smoke Detector	Portable 29	Tested	12:45:45 PM	08/27/2019
Smoke Detector	Portable 29	Tested	12:45:59 PM	08/27/2019
Smoke Detector	Portable 30	Tested	12:46:05 PM	08/27/2019
Smoke Detector	Portable 30	Tested	12:46:25 PM	08/27/2019
Smoke Detector	Portable 31	Tested	12:46:38 PM	08/27/2019
Smoke Detector	Portable 31	Tested	12:46:48 PM	08/27/2019
Smoke Detector	Unisex Restroom Next To Classroom 17	Tested	12:14:47 PM	08/27/2019
Smoke Detector	Unisex Restroom Next To Classroom 17	Tested	12:15:03 PM	08/27/2019
Smoke Detector	Unisex Restroom Next To Classroom 22	Tested	12:22:01 PM	08/27/2019
Smoke Detector	Unisex Restroom Next To Classroom 22	Tested	12:23:25 PM	08/27/2019
Smoke Detector	Unisex Restroom Next To Classroom 5	Tested	11:36:04 AM	08/27/2019
Smoke Detector	Unisex Restroom Next To Classroom 5	Tested	11:37:21 AM	08/27/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Rea Elementary School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Annunciator	Inspected	1
Battery	Tested	10
Control Panel	Inspected	1
Heat Detector	Tested	10
Power Supply	Inspected	4
Pull Station	Tested	38
Smoke Detector	Tested	39
Total		103

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Rea Elementary School

Control Panel: 1 - Silent Knight IFP-1000

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category	%	of Inventory	Quantity	
Control Panel		Control		0.97%	1	
Battery		Control		9.71%	10	
Heat Detector		Initiating		9.71%	10	
Smoke Detector		Initiating		37.86%	39	
Pull Station		Initiating		36.89%	38	
Annunciator		Control		0.97%	1	
Power Supply		Control		3.88%	4	
Туре	Qty	Model #	Description		Install Date	
New (under 90 days)						
Silent Knight						
Heat Detector	10	HD5602	Rate-of-Rise		08/27/2019	
		In Service	e - 2 Years to 3 Y	<i>ears</i>		
Battery	10	12V7AH	Sealed Lead Acid		07/01/2017	
Silent Knight						
Annunciator	1				07/01/2017	
Control Panel	1	IFP-1000			07/01/2017	
Power Supply	4	RPS-1000			07/01/2017	
Pull Station	2	SD500-PS	Dual Action		07/01/2017	
Smoke Detector	39	SD505-APS	Photoelectric		07/01/2017	
Simplex						
Pull Station	36	2099-9101	Single Action		07/01/2017	

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Sanborn Building (District) 2985 Bear Street Costa Mesa, CA 92626

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Sep 13, 2019

> Building: NMUSD - Sanborn Building (District) Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Michael Cannon Title: Service Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD – Sanborn Building (District)	Contact: Tim Waller	
Address: 2985 Bear Street	Phone: 714-231-0363	
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92626	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Michael Cannon	
Address: 2903 Saturn Street	Phone: 714-715-1223	
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: mcannon@calbuildin	gsystems.com
System Control Unit		
Manufacturer: Silent Knight	Inspection Date: 09/13/20	19 IDC Style:
Model Number: IFP-2000	Install Date: 09/13/2019	SLC Style:
Software Version:	Version Date: 09/13/2019	NAC Style:
Location: Electrical Rm. by Information Technology	Current Protection:	
Monitoring		
Company: Pho	one: A	ccount #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
	Total	ltems	Sen	/iced	Pas	ssed	Failed	/Other
Category	Qty	%	Qty	%	Qty	%	Qty	%
Control	7	3.89%	7	100.00%	7	100.00%	0	0%
Initiating	173	96.11%	173	100.00%	173	100.00%	0	0%
Totals	180	100%	180	100.00%	180	100.00%	0	0%
Certification								
Company: Cal Building Systems			Bu	ilding: NML	JSD – San	born Buildi	ng (Distric	t)
Inspector: Michael Cannon			Co	ntact: Tim	Waller			
Signed:			Sig	gned:				

Notes & Recommendations

Generated by: BuildingReports.com

Building: NMUSD - Sanborn Building		SD - Sanborn Building	Control Panel: 1 - Silent	Knight
(District) IFP-2000				
The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.				
ScanID	Note	Device Type	Location	Comment
			Control	
58095750	1	Control Panel	Electrical Rm. by Information Technology	Passed
Panel	LCD scra	mbles when alarms are sent to pa	nel or you push any buttons on the FACP. You can	i't see
anyth	ing that tl	he LCD displays. Devices still repo	ort to panel.	

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Sanborn Building (District)

Control Panel: 1 - Silent Knight IFP-2000

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Front Lobby	Inspected	4:54:24 PM	09/13/2019
Battery	Electrical Rm. by Information Technology	Tested	4:48:52 PM	09/13/2019
Battery	Electrical Rm. by Information Technology	Tested	4:49:48 PM	09/13/2019
Battery	Electrical Rm. by Information Technology	Tested	4:50:37 PM	09/13/2019
Battery	Electrical Rm. by Information Technology	Tested	4:51:08 PM	09/13/2019
Control Panel	Electrical Rm. by Information Technology	Tested	4:45:00 PM	09/13/2019
Initiating				
Heat Detector	Center Corridor 120	Tested	9:49:04 PM	09/13/2019
Heat Detector	Center Corridor 151	Tested	9:25:07 PM	09/13/2019
Heat Detector	East (E) Print Shop 160	Tested	9:27:01 PM	09/13/2019
Heat Detector	East Central Index Storage Room 154	Tested	9:39:34 PM	09/13/2019
Heat Detector	East Corridor 133	Tested	9:38:46 PM	09/13/2019
Heat Detector	East IT Operations	Tested	8:41:49 PM	09/13/2019
Heat Detector	East IT Technicians	Tested	9:24:25 PM	09/13/2019
Heat Detector	East Storage Room 1–122	Tested	8:09:32 PM	09/13/2019
Heat Detector	North Corridor 120	Tested	8:07:44 PM	09/13/2019
Heat Detector	North Corridor 120	Tested	9:51:29 PM	09/13/2019
Heat Detector	North Corridor 151	Tested	9:39:51 PM	09/13/2019
Heat Detector	North Office 145	Tested	9:41:52 PM	09/13/2019
Heat Detector	North Office 146	Tested	9:41:32 PM	09/13/2019
Heat Detector	North Storage Room 1–122	Tested	8:08:08 PM	09/13/2019
Heat Detector	North Testing Assessment Storage 152	Tested	8:25:01 PM	09/13/2019
Heat Detector	Northeast Assembly Room 121	Tested	8:05:35 PM	09/13/2019
Heat Detector	Northeast Central Index Storage Room 154	Tested	9:50:31 PM	09/13/2019
Heat Detector	Northeast Office 138	Tested	9:48:51 PM	09/13/2019
Heat Detector	Northeast Office 140	Tested	9:48:28 PM	09/13/2019
Heat Detector	Northwest Assembly Room 121	Tested	8:05:01 PM	09/13/2019
Heat Detector	Northwest Central Index Storage Room 154	Tested	9:50:00 PM	09/13/2019
Heat Detector	South Corridor 120	Tested	8:04:29 PM	09/13/2019
Heat Detector	South Corridor 120	Tested	9:28:04 PM	09/13/2019
Heat Detector	South Corridor 151	Tested	9:24:32 PM	09/13/2019
Heat Detector	South Office 145	Tested	9:42:06 PM	09/13/2019
Heat Detector	South Office 146	Tested	9:41:45 PM	09/13/2019
Heat Detector	South Scannings/Storage Room 153	Tested	9:49:26 PM	09/13/2019
Heat Detector	South Storage Room 1-122	Tested	8:09:17 PM	09/13/2019
Heat Detector	South Testing Assessment Storage 152	Tested	8:25:33 PM	09/13/2019
Heat Detector	Southeast Assembly Room 121	Tested	8:04:14 PM	09/13/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	Southeast Storage Room 5–134	Tested	9:50:55 PM	09/13/2019
Heat Detector	Southwest Assembly Room 121	Tested	8:02:06 PM	09/13/2019
Heat Detector	West (E) Print Shop 160	Tested	9:26:32 PM	09/13/2019
Heat Detector	West Central Index Storage Room 154	Tested	9:39:01 PM	09/13/2019
Heat Detector	West Corridor 133	Tested	9:38:24 PM	09/13/2019
Heat Detector	West IT Operations	Tested	8:41:33 PM	09/13/2019
Heat Detector	West IT Technicians	Tested	8:41:59 PM	09/13/2019
Heat Detector	West Scanning Storage Room 153	Tested	9:40:16 PM	09/13/2019
Heat Detector	West Scanning Storage Room 153	Tested	9:40:43 PM	09/13/2019
Heat Detector	(E) Computer Room 143	Tested	9:26:07 PM	09/13/2019
Heat Detector	Conference Room A	Tested	8:35:51 PM	09/13/2019
Heat Detector	Conference Room B	Tested	8:36:26 PM	09/13/2019
Heat Detector	Conference Room D-123	Tested	8:21:45 PM	09/13/2019
Heat Detector	Conference Room E-132	Tested	9:36:15 PM	09/13/2019
Heat Detector	Copy Room 155	Tested	8:24:45 PM	09/13/2019
Heat Detector	Corridor 144	Tested	9:25:28 PM	09/13/2019
Heat Detector	Corridor By Conference Rooms	Tested	8:37:18 PM	09/13/2019
Heat Detector	Corridor By IT Entrance	Tested	8:37:49 PM	09/13/2019
Heat Detector	Electrical Room	Tested	8:36:48 PM	09/13/2019
Heat Detector	Foyer 124	Tested	8:21:13 PM	09/13/2019
Heat Detector	Hall 135	Tested	9:29:09 PM	09/13/2019
Heat Detector	IT Break Room	Tested	8:40:19 PM	09/13/2019
Heat Detector	IT Conference Room	Tested	8:39:35 PM	09/13/2019
Heat Detector	IT Entrance	Tested	8:40:04 PM	09/13/2019
Heat Detector	IT Help 159	Tested	9:25:47 PM	09/13/2019
Heat Detector	IT Help Desk	Tested	8:40:39 PM	09/13/2019
Heat Detector	IT Operations Office #1	Tested	8:41:11 PM	09/13/2019
Heat Detector	IT Operations Office #2	Tested	8:40:55 PM	09/13/2019
Heat Detector	IT Operations Office #3	Tested	8:38:16 PM	09/13/2019
Heat Detector	IT Operations Office #4	Tested	8:38:59 PM	09/13/2019
Heat Detector	IT Operations Office #5	Tested	8:39:10 PM	09/13/2019
Heat Detector	IT Operations Office #6	Tested	8:39:22 PM	09/13/2019
Heat Detector	IT Storage Room	Tested	8:42:19 PM	09/13/2019
Heat Detector	Janitor's Storage Room 127	Tested	8:07:11 PM	09/13/2019
Heat Detector	Lobby 128	Tested	8:23:30 PM	09/13/2019
Heat Detector	Lounge Room 150	Tested	9:40:51 PM	09/13/2019
Heat Detector	Mechanical Room 156	Tested	8:06:44 PM	09/13/2019
Heat Detector	Men's Restroom	Tested	8:06:06 PM	09/13/2019
Heat Detector	Office 138	Tested	9:28:56 PM	09/13/2019
Heat Detector	Office 139	Tested	9:28:44 PM	09/13/2019
Heat Detector	Office 140	Tested	9:28:26 PM	09/13/2019
Heat Detector	Office 149	Tested	9:41:14 PM	09/13/2019
Heat Detector	Print Equipment Room 142	Tested	9:27:15 PM	09/13/2019
Heat Detector	Print Office	Tested	9:27:45 PM	09/13/2019
Heat Detector	Storage Room 131	Tested	9:37:01 PM	09/13/2019
Heat Detector	Storage Room 2-125	Tested	8:22:13 PM	09/13/2019
Heat Detector	Storage Room 3–126	Tested	8:22:38 PM	09/13/2019
Heat Detector	Storage Room 5–134	Tested	9:29:27 PM	09/13/2019
Heat Detector	Storage Room 6-147	Tested	8:26:10 PM	09/13/2019
Heat Detector	Storage Room 7–148	Tested	8:25:47 PM	09/13/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	Student Services Admin Room 129	Tested	9:37:53 PM	09/13/2019
Heat Detector	Student Services Room	Tested	9:37:23 PM	09/13/2019
Heat Detector	Women's Restroom	Tested	8:24:23 PM	09/13/2019
Pull Station	East Hall Corridor Exit	Tested	5:09:56 PM	09/13/2019
Pull Station	Front Lobby	Tested	4:55:48 PM	09/13/2019
Pull Station	South Corridor Exit	Tested	5:31:34 PM	09/13/2019
Smoke Detector	Assembly Rm. Inside Skylight	Tested	5:20:58 PM	09/13/2019
Smoke Detector	Assembly Rm. Inside Skylight	Tested	5:21:33 PM	09/13/2019
Smoke Detector	Assembly Rm. Inside Skylight	Tested	5:21:44 PM	09/13/2019
Smoke Detector	Assembly Rm. Inside Skylight	Tested	5:21:53 PM	09/13/2019
Smoke Detector	Assembly Rm.	Tested	5:18:58 PM	09/13/2019
Smoke Detector	Assembly Rm.	Tested	5:19:15 PM	09/13/2019
Smoke Detector	Assembly Rm.	Tested	5:19:22 PM	09/13/2019
Smoke Detector	Assembly Rm.	Tested	5:19:29 PM	09/13/2019
Smoke Detector	Central East Office	Tested	5:23:37 PM	09/13/2019
Smoke Detector	Central Mechanical Room	Tested	5:35:05 PM	09/13/2019
Smoke Detector	Central South Office	Tested	5:27:22 PM	09/13/2019
Smoke Detector	Central South Office	Tested	5:28:11 PM	
Smoke Detector	Conference Rm. B	Tested	5:01:41 PM	09/13/2019 09/13/2019
Smoke Detector	Conference Rm. D	Tested	4:58:59 PM	09/13/2019
Smoke Detector	Conference Room A	Tested	5:02:49 PM	
Smoke Detector	Copy Room C	Tested	5:43:40 PM	09/13/2019 09/13/2019
Smoke Detector		Tested	5:23:18 PM	
Smoke Detector	Corridor by Assembly Rm.	Tested	5:27:31 PM	09/13/2019
Smoke Detector	Corridor by Assembly Rm.	Tested	5:28:20 PM	09/13/2019
Smoke Detector	Corridor by Assembly Rm.	Tested	5:00:28 PM	09/13/2019
	Corridor by Conference Rm. D		5:16:36 PM	09/13/2019
Smoke Detector Smoke Detector	Corridor by Information Technology	Tested	5:38:52 PM	09/13/2019
	Corridor Near Staff Lounge Corridor Next To Central Mechanical Room	Tested	5:36:55 PM	09/13/2019
Smoke Detector		Tested	5:26:34 PM	09/13/2019
Smoke Detector	Custodian Rm. by Assembly Rm.	Tested	5:17:30 PM	09/13/2019
Smoke Detector	Duplications Office Cubicles East Corridor	Tested	5:20:37 PM	09/13/2019
Smoke Detector Smoke Detector		Tested Tested	5:16:20 PM	09/13/2019 09/13/2019
	East Duplications Office		5:11:23 PM	
Smoke Detector	East Electrical Room East Hall Corridor	Tested	5:08:38 PM	09/13/2019
Smoke Detector Smoke Detector	East Office	Tested	5:07:52 PM	09/13/2019
		Tested	5:13:43 PM	09/13/2019
Smoke Detector	East Office	Tested	5:14:44 PM	09/13/2019
Smoke Detector	East Office	Tested	5:14:48 PM	09/13/2019
Smoke Detector	East Office	Tested	5:29:49 PM	09/13/2019
Smoke Detector	Ed. Tech Office	Tested	5:30:06 PM	09/13/2019
Smoke Detector	Ed. Tech Office	Tested		09/13/2019
Smoke Detector	Electrical Rm. by Information Technology	Tested	4:52:05 PM	09/13/2019
Smoke Detector	Front Lobby	Tested	4:58:23 PM	09/13/2019
Smoke Detector	Information Technology IT Operations	Tested	5:10:27 PM	09/13/2019
Smoke Detector	Information Technology IT Operations	Tested	5:10:51 PM	09/13/2019
Smoke Detector	Information Technology IT Operations-	Tested	5:11:37 PM	09/13/2019
	Charging Office	—	E 10.05 PV	
Smoke Detector	Information Technology IT Operations- Office	Tested	5:12:25 PM	09/13/2019
Smoke Detector	Information Technology IT Operations- Office	Tested	5:13:27 PM	09/13/2019
Smoke Detector	Information Technology IT Operations- Office	Tested	5:14:03 PM	09/13/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Information Technology IT Operations- Office	Tested	5:15:00 PM	09/13/2019
Smoke Detector	Information Technology IT Operations- Office	Tested	5:15:35 PM	09/13/2019
Smoke Detector	Information Technology Office by Reception	Tested	5:09:30 PM	09/13/2019
Smoke Detector	Information Technology Reception	Tested	5:03:16 PM	09/13/2019
Smoke Detector	Information Technology Technical Support	Tested	5:04:22 PM	09/13/2019
Smoke Detector	Information Technology Technical Support	Tested	5:04:54 PM	09/13/2019
Smoke Detector	Information Technology Technical Support	Tested	5:05:03 PM	09/13/2019
Smoke Detector	Information Technology Technical Support	Tested	5:05:11 PM	09/13/2019
Smoke Detector	Information Technology Technical Support Storage	Tested	5:06:47 PM	09/13/2019
Smoke Detector	Men's RR by Assembly Rm.	Tested	5:25:20 PM	09/13/2019
Smoke Detector	Network Support Office	Tested	5:30:09 PM	09/13/2019
Smoke Detector	North Corridor	Tested	5:20:51 PM	09/13/2019
Smoke Detector	North Corridor	Tested	5:22:34 PM	
Smoke Detector	North Office	Tested	4:59:25 PM	09/13/2019 09/13/2019
Smoke Detector	North Office	Tested	5:01:36 PM	09/13/2019
Smoke Detector	North Office	Tested	5:02:19 PM	09/13/2019
Smoke Detector	Office Near Women's Restroom	Tested	5:04:44 PM	09/13/2019
Smoke Detector	Outside East Electrical Room	Tested	5:48:03 PM	09/13/2019
Smoke Detector	Skylight by Admin. Assistant Secondary Ed.	Tested	5:40:05 PM	09/13/2019
Smoke Detector	Skylight by Administrative Assistant Office	Tested	5:38:03 PM	09/13/2019
Smoke Detector	Skylight by Conference Rm. A	Tested	5:39:24 PM	09/13/2019
Smoke Detector	Skylight by Copy Rm. C	Tested	5:41:48 PM	09/13/2019
Smoke Detector	Skylight by Copy kill. C Skylight by Director of After School Program	Tested	5:38:50 PM	09/13/2019
Smoke Detector	Skylight by Director Office	Tested	5:37:33 PM	09/13/2019
Smoke Detector	Skylight by TOSA World	Tested	5:40:59 PM	09/13/2019
Smoke Detector	Skylight by Woman's RR	Tested	5:41:16 PM	09/13/2019
Smoke Detector	Skylight in Main Lobby	Tested	5:43:36 PM	09/13/2019
Smoke Detector	Skylight in Main Lobby Skylight in Main Lobby	Tested	5:43:55 PM	09/13/2019
Smoke Detector	Skylight in TOSA World	Tested	5:42:46 PM	09/13/2019
Smoke Detector	Skylight in TOSA World	Tested	5:43:08 PM	09/13/2019
Smoke Detector	South Corridor	Tested	5:26:29 PM	09/13/2019
Smoke Detector	South Office	Tested	5:28:55 PM	09/13/2019
Smoke Detector	Southeast Corridor	Tested	5:20:10 PM	09/13/2019
Smoke Detector	Special Projects Office	Tested	5:25:21 PM	09/13/2019
Smoke Detector	Staff Lounge	Tested	5:37:52 PM	09/13/2019
Smoke Detector	Storage by Entrance	Tested	5:34:08 PM	09/13/2019
Smoke Detector	Tech Cafe Office	Tested	5:31:49 PM	09/13/2019
Smoke Detector	Tech Cafe Office	Tested	5:32:07 PM	09/13/2019
Smoke Detector	Tech Cafe Office	Tested	5:32:13 PM	09/13/2019
Smoke Detector	TOSA Office Storage 6	Tested	5:40:34 PM	09/13/2019
Smoke Detector	TOSA Office Storage 7	Tested	5:40:22 PM	09/13/2019
Smoke Detector	TOSA Office	Tested	5:39:58 PM	09/13/2019
Smoke Detector	TOSA Office	Tested	5:40:15 PM	09/13/2019
Smoke Detector	Women's Restroom Next To Copy Room C	Tested	5:44:50 PM	09/13/2019

Building: NMUSD - Sanborn Building (District)

Control Panel: 2

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Power Supply	Electrical Rm. by Information Technology	Tested	4:49:58 PM	09/13/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Sanborn Building (District)

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity			
Passed					
Annunciator	Inspected	1			
Battery	Tested	4			
Control Panel	Tested	1			
Heat Detector	Tested	83			
Power Supply	Tested	1			
Pull Station	Tested	3			
Smoke Detector	Tested	87			
Total		180			

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: NMUSD - Sanborn Building	Control Panel: 1 - Silent Knight
(District)	IFP-2000

The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.

Туре	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah	
Passed								
Battery								
Sealed Lead Acid	Electrical Rm. by Information Technology	18	12					
Sealed Lead Acid	Electrical Rm. by Information Technology	18	12					
Sealed Lead Acid	Electrical Rm. by Information Technology	7	12					
Sealed Lead Acid	Electrical Rm. by Information Technology	7	12					

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Sanborn Building (District)

Control Panel: 1 - Silent Knight IFP-2000

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type		Category	% of Inventory	Quantity	
Control Panel		Control	0.56%		
Battery		Control	2.22%	4	
Power Supply		Control	0.56%	1	
Smoke Detector		Initiating	48.33%	87	
Annunciator		Control	0.56%	1	
Pull Station		Initiating	1.67%	3	
Heat Detector		Initiating	46.11%	83	
	Qt				
Туре	v	Model #	Description	Install Date	
		New	(under 90 days)	I	
Silent Knight					
Annunciator	1	RA-2000		09/13/2019	
Control Panel	1	IFP-2000		09/13/2019	
Heat Detector	83	SD505-AHS	Fixed Temperature	09/13/2019	
Pull Station	3	SD500-PS	Dual Action	09/13/2019	
Smoke Detector	36	SD505-APS	Photoelectric	09/13/2019	
			e - 2 Years to 3 Years		
12V18Ah					
Battery	2	12V18Ah	Sealed Lead Acid	08/19/2017	
12V7Ah	L	12 1 10/11		00,19,2017	
Battery	2	12V7Ah	Sealed Lead Acid	08/19/2017	
Silent Knight					
Smoke Detector	51	SD505-APS	Photoelectric	08/19/2017	
Building: NMUSI (District)	D - Sa	nborn Building	7	Control Panel: 2	
The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.					
	Qt				

	Qt					
Туре	У	Model #	Description	Install Date		
New (under 90 days)						
Silent Knight						
Power Supply	1	RPS-1000		09/13/2019		

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Sonora Elementary 966 Sonora Rd Costa Mesa, CA 92626

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Aug 19, 2019

> Building: NMUSD - Sonora Elementary Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Michael Cannon Title: Service Technician

Executive Summary Generated by: BuildingReports.com

Building Information	
Building: NMUSD – Sonora Elementary	Contact: Tim Waller
Address: 966 Sonora Rd	Phone: 714-231-0363
Address:	Fax:
City/State/Zip: Costa Mesa, CA 92626	Mobile:
Country: United States of America	Email:
Inspection Performed By	
Company: Cal Building Systems	Inspector: Michael Cannon
Address: 2903 Saturn Street	Phone: 714-715-1223
Address: Suite F	Fax:
City/State/Zip: Brea, CA 92821	Mobile:
Country: United States of America	Email: mcannon@calbuildingsystems.com
System Control Unit	
Manufacturer: Silent Knight	Inspection Date: 08/19/2019 IDC Style:
Model Number: 5820XL	Install Date: 08/19/2019 SLC Style:
Software Version:	Version Date: 12/31/1969 NAC Style:
Location: Admin Building Nurse's Office MDF Room	Current Protection:
Monitoring	
Company: AceTec Pho	ne: 1-800-634-3915 Account #: 21-1116
Central Station Signal Verification	
Туре:	Mfg: Model #:
Test Time/Date:	Restore Time

Inspection Summary								
Category	Total	ltems	Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.47%	1	100.00%	0	0%	1	100.00%
Control	28	13.08%	28	100.00%	28	100.00%	0	0%
Initiating	185	86.45%	185	100.00%	185	100.00%	0	0%
Totals	214	100%	214	100.00%	213	99.53%	1	0.47%
Certification								
Company: Cal Building Systems			Bu	ilding: NML	JSD – Son	ora Elemen	tary	
Inspector: Michael Cannon			Co	ontact: Tim	Waller			
Signed:			Sig	gned:				

Discrepancy Report Generated by: BuildingReports.com

Building: N	Building: NMUSD - Sonora ElementaryControl Panel: n/a							
The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.								
Device Type		Manufacturer	ModelNur	nber	Date	Qty		
	Items listed for Recall by Manufacturer							
		No recalled items four	nd during this inspection	on.				
Sound Test	E Location		Problem	Device	Ref	erence		
Sound Testing								
Sound Test	C Location		Problem	Device	Ref	erence		
Sound Test Points								
0001	Entire Campus			Sound Te	st			

Proposed Solutions Report Generated by: BuildingReports.com

Building: N	Building: NMUSD - Sonora Elementary Contro							
The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.								
ScanID	Location Solution Description Cost							
Sound Testing								
Sound Test								
0001	Entire Campus			T/M				
			PO #: (none)	T/M				

Notes & Recommendations

Generated by: BuildingReports.com

Building: NMUSD - Sonora Elementary

Control Panel: n/a

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

ScanID	Note	Device Type		Location	Comment
0001	1	Sound Test		Entire Campus	
The st	trobe insi	de the MPR Building,	located in t	the corridor Exit next to the restrooms, failed to ac	tivate
during	g our insp	pection.			

Building: NMUSD - Sonora Elementary

Control Panel: 1 - Silent Knight 5820XL

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

ScanID	Note	Device Type	Location	Comment		
		i	Initiating			
61336928	2	Smoke Detector	MPR Building Stage	Passed		
Devic	Device is still operational but has been painted over with black paint 80–100%.					
61336929	3	Smoke Detector	MPR Building Stage	Passed		
Devic	Device is still operational but has been painted over with black paint 80-100%.					

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Sonora Elementary

Control Panel: 1 - Silent Knight 5820XL

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date				
Passed								
Control								
Annunciator	Admin Building Reception Area	Inspected	7:40:39 AM	08/19/2019				
Battery	Admin Building Nurse's Office MDF Room	Tested	7:36:07 AM	08/19/2019				
Battery	Admin Building Nurse's Office MDF Room	Tested	7:36:32 AM	08/19/2019				
Battery	Classroom 19A	Tested	9:15:34 AM	08/19/2019				
Battery	Classroom 19A	Tested	9:15:55 AM	08/19/2019				
Battery	Classroom 7A	Tested	10:59:27 AM	08/19/2019				
Battery	Classroom 7A	Tested	10:59:39 AM	08/19/2019				
Battery	IDF/Electrical Room Behind Classroom 15	Tested	8:30:08 AM	08/19/2019				
Battery	IDF/Electrical Room Behind Classroom 15	Tested	8:30:33 AM	08/19/2019				
Battery	IDF/Electrical Room Behind Classroom 18	Tested	8:47:15 AM	08/19/2019				
Battery	IDF/Electrical Room Behind Classroom 18	Tested	8:47:27 AM	08/19/2019				
Battery	IDF/Electrical Room Behind Classroom 3	Tested	11:56:31 AM	08/19/2019				
Battery	IDF/Electrical Room Behind Classroom 3	Tested	11:56:41 AM	08/19/2019				
Battery	Kindergarten Outside Storage Room	Tested	10:40:35 AM	08/19/2019				
Battery	Kindergarten Outside Storage Room	Tested	10:40:59 AM	08/19/2019				
Battery	MPR Building Custodian Storage (Double Door)	Tested	10:19:20 AM	08/19/2019				
Battery	MPR Building Custodian Storage (Double Door)	Tested	10:19:34 AM	08/19/2019				
Battery	Storage Room Behind Classroom 12A	Tested	8:04:48 AM	08/19/2019				
Battery	Storage Room Behind Classroom 12A	Tested	8:05:26 AM	08/19/2019				
Control Panel	Admin Building Nurse's Office MDF Room	Inspected	7:35:24 AM	08/19/2019				
Power Supply	Classroom 19A	Inspected	9:15:03 AM	08/19/2019				
Power Supply	Classroom 7A	Inspected	10:59:04 AM	08/19/2019				
Power Supply	IDF/Electrical Room Behind Classroom 15	Inspected	8:29:03 AM	08/19/2019				
Power Supply	IDF/Electrical Room Behind Classroom 18	Inspected	8:48:24 AM	08/19/2019				
Power Supply	IDF/Electrical Room Behind Classroom 3	Inspected	11:56:10 AM	08/19/2019				
Power Supply	Kindergarten Outside Storage Room	Inspected	10:40:04 AM	08/19/2019				
Power Supply	MPR Building Custodian Storage (Double Door)	Inspected	10:18:22 AM	08/19/2019				
Power Supply	Storage Room Behind Classroom 12A	Inspected	8:04:10 AM	08/19/2019				
Initiating								
Heat Detector	BLDG 2 IDF ATTIC	Tested	3:59:19 PM	08/19/2019				
Heat Detector	BLDG 2 Kitchen	Tested	3:52:54 PM	08/19/2019				
Heat Detector	BLDG 2 Men's RR ATTIC	Tested	4:00:19 PM	08/19/2019				
Heat Detector	BLDG 2 MPR ATTIC NE	Tested	3:58:07 PM	08/19/2019				
Heat Detector	BLDG 2 MPR ATTIC NW	Tested	3:55:10 PM	08/19/2019				
Heat Detector	BLDG 2 MPR ATTIC SE	Tested	3:58:45 PM	08/19/2019				
Heat Detector	BLDG 2 MPR ATTIC SW	Tested	3:56:47 PM	08/19/2019				
Heat Detector	BLDG 8 Boys HC RR	Tested	4:01:41 PM	08/19/2019				

Device Type	Location	Service	Time	Date
	Pass			
Heat Detector	BLDG 8 Boys HC RR	Tested	4:02:52 PM	08/19/2019
Heat Detector	BLDG 8 Girls HC RR	Tested	4:03:19 PM	08/19/2019
Heat Detector	Boys RR Room 1 BLDG 9	Tested	3:33:45 PM	08/19/2019
Heat Detector	Boys RR Room 2 BLDG 9	Tested	3:38:22 PM	08/19/2019
Heat Detector	Men's RR Admin	Tested	3:55:02 PM	08/19/2019
Heat Detector	N Boys RR	Tested	4:08:52 PM	08/19/2019
Heat Detector	N Girls RR	Tested	4:07:31 PM	08/19/2019
Heat Detector	N Staff RR	Tested	4:08:21 PM	08/19/2019
Heat Detector	Portable 10 N	Tested	12:27:58 PM	08/19/2019
Heat Detector	Portable 10 S	Tested	12:29:26 PM	08/19/2019
Heat Detector	Portable 11 N	Tested	12:31:23 PM	08/19/2019
Heat Detector	Portable 11 S	Tested	12:32:36 PM	08/19/2019
Heat Detector	Portable 21 N	Tested	12:59:40 PM	08/19/2019
Heat Detector	Portable 21 S	Tested	12:49:46 PM	08/19/2019
Heat Detector	Portable 22 N	Tested	12:50:23 PM	08/19/2019
Heat Detector	Portable 22 S	Tested	12:52:20 PM	08/19/2019
Heat Detector	Portable 23 N	Tested	12:53:12 PM	08/19/2019
Heat Detector	Portable 23 S	Tested	12:54:08 PM	08/19/2019
Heat Detector	Portable 24 N	Tested	12:55:11 PM	08/19/2019
Heat Detector	Portable 24 S	Tested	12:56:07 PM	08/19/2019
Heat Detector	Portable 25 N	Tested	1:02:22 PM	08/19/2019
Heat Detector	Portable 25 S	Tested	1:03:22 PM	08/19/2019
Heat Detector	Portable 26 E	Tested	12:43:54 PM	08/19/2019
Heat Detector	Portable 26 W	Tested	12:42:55 PM	08/19/2019
Heat Detector	Portable 27 N	Tested	1:05:01 PM	08/19/2019
Heat Detector	Portable 27 S	Tested	1:06:11 PM	08/19/2019
Heat Detector	Portable 28 E	Tested	1:08:32 PM	08/19/2019
Heat Detector	Portable 28 W	Tested	1:06:42 PM	08/19/2019
Heat Detector	Portable 29 E	Tested	12:47:01 PM	08/19/2019
Heat Detector	Portable 29 W	Tested	12:45:59 PM	08/19/2019
Heat Detector	Portable 30 E	Tested	4:04:36 PM	08/19/2019
Heat Detector	Portable 30 W	Tested	4:05:27 PM	08/19/2019
Heat Detector	Portable 31 E	Tested	4:06:02 PM	08/19/2019
Heat Detector	Portable 31 W	Tested	4:06:49 PM	08/19/2019
Heat Detector	Portable 32	Tested	11:34:00 AM	08/19/2019
Heat Detector	Portable 32 N	Tested	12:33:30 PM	08/19/2019
Heat Detector	Portable 32 S	Tested	12:34:49 PM	08/19/2019
Heat Detector	Portable 33 N	Tested	12:35:45 PM	08/19/2019
Heat Detector	Portable 33 S	Tested	12:37:12 PM	08/19/2019
Heat Detector	Portable 34 N	Tested	12:38:04 PM	08/19/2019
Heat Detector	Portable 34 S	Tested	12:38:46 PM	08/19/2019
			12:42:14 PM	
Heat Detector Heat Detector	Portable 35 N Portable 35 S	Tested Tested	12:40:12 PM	08/19/2019 08/19/2019
Heat Detector	Portable 8 N	Tested	12:21:10 PM	08/19/2019
Heat Detector	Portable 8 S		12:22:43 PM	
		Tested	12:24:43 PM	08/19/2019
Heat Detector	Portable 9 N Portable 9 s	Tested	12:29:11 PM	08/19/2019
Heat Detector	Portable 9 s	Tested		08/19/2019
Heat Detector	Staff RR BLDG 9	Tested	1:10:41 PM 3:43:30 PM	08/19/2019
Heat Detector	Unisex RR	Tested	3:43:30 PM	08/19/2019
Heat Detector	Women's RR Admin	Tested	3:51:25 PM	08/19/2019

Device Type	Location	Service	Time	Date
	Passed			
Pull Station	Admin Building Front Entrance	Tested	7:45:11 AM	08/19/2019
Pull Station	Admin Building Staff Lounge	Tested	7:40:06 AM	08/19/2019
Pull Station	Kindergarten Classroom 1	Tested	10:37:16 AM	08/19/2019
Pull Station	MPR Building Back Stage Exit	Tested	10:05:56 AM	08/19/2019
Pull Station	MPR Building Corridor Exit	Tested	9:52:43 AM	08/19/2019
Pull Station	MPR Building Main Hall Entrance	Tested	9:53:57 AM	08/19/2019
Pull Station	MPR Building Main Hall Exit	Tested	9:54:41 AM	08/19/2019
Pull Station	Portable 8	Tested	11:08:33 AM	08/19/2019
Smoke Detector	Admin Building Administrative Assistant's Office	Tested	7:47:30 AM	08/19/2019
Smoke Detector	Admin Building Nurse's Office	Tested	7:37:55 AM	08/19/2019
Smoke Detector	Admin Building Nurse's Office MDF Room	Tested	7:37:02 AM	08/19/2019
Smoke Detector	Admin Building Outside Staff Restroom	Tested	7:51:56 AM	08/19/2019
Smoke Detector	Admin Building Principal's Office	Tested	7:48:03 AM	08/19/2019
Smoke Detector	Admin Building Reception	Tested	7:43:50 AM	08/19/2019
Smoke Detector	Admin Building Staff Lounge	Tested	7:41:14 AM	08/19/2019
Smoke Detector	Admin Building Staff Lounge	Tested	7:41:28 AM	08/19/2019
Smoke Detector	Admin Building Staff Lounge Restroom	Tested	7:42:56 AM	08/19/2019
Smoke Detector	Boy's Portable Restroom	Tested	11:18:11 AM	08/19/2019
Smoke Detector	Boy's Restroom Behind Classroom 19A	Tested	9:06:23 AM	08/19/2019
Smoke Detector	Boy's Restroom Behind Classroom 7A	Tested	10:53:52 AM	08/19/2019
Smoke Detector	Classroom 12	Tested	8:11:42 AM	08/19/2019
Smoke Detector	Classroom 12	Tested	8:11:51 AM	08/19/2019
Smoke Detector	Classroom 12A	Tested	8:11:21 AM	08/19/2019
Smoke Detector	Classroom 13	Tested	8:17:41 AM	08/19/2019
Smoke Detector	Classroom 13	Tested	8:18:02 AM	08/19/2019
Smoke Detector	Classroom 14	Tested	8:58:46 AM	08/19/2019
Smoke Detector	Classroom 14	Tested	8:58:57 AM	08/19/2019
Smoke Detector	Classroom 16	Tested	8:52:27 AM	08/19/2019
Smoke Detector	Classroom 16	Tested	8:52:38 AM	08/19/2019
Smoke Detector	Classroom 17	Tested	8:35:16 AM	08/19/2019
Smoke Detector	Classroom 17	Tested	8:36:15 AM	08/19/2019
Smoke Detector	Classroom 18	Tested	8:36:26 AM	08/19/2019
Smoke Detector	Classroom 18	Tested	12:10:04 PM	08/19/2019
Smoke Detector	Classroom 19	Tested	9:02:50 AM	08/19/2019
Smoke Detector	Classroom 19	Tested	9:03:00 AM	08/19/2019
Smoke Detector	Classroom 19A	Tested	9:04:08 AM	08/19/2019
Smoke Detector	Classroom 20	Tested	8:36:48 AM	08/19/2019
Smoke Detector	Classroom 20	Tested	8:37:02 AM	08/19/2019
Smoke Detector	Classroom 3	Tested	10:43:29 AM	08/19/2019
Smoke Detector	Classroom 3	Tested	10:43:39 AM	08/19/2019
Smoke Detector	Classroom 4	Tested	10:43:57 AM	08/19/2019
Smoke Detector	Classroom 4	Tested	10:44:07 AM	08/19/2019
Smoke Detector	Classroom 5	Tested	10:44:41 AM	08/19/2019
Smoke Detector	Classroom 5	Tested	10:44:56 AM	08/19/2019
Smoke Detector	Classroom 6	Tested	10:45:17 AM	08/19/2019
Smoke Detector	Classroom 6	Tested	10:45:32 AM	08/19/2019
Smoke Detector	Classroom 7	Tested	10:59:51 AM	08/19/2019
Smoke Detector	Classroom 7	Tested	11:00:01 AM	08/19/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Classrooms 14/15	Tested	8:18:25 AM	08/19/2019
Smoke Detector	Classrooms 14/15	Tested	8:18:41 AM	08/19/2019
Smoke Detector	Classrooms 14/15	Tested	8:18:47 AM	08/19/2019
Smoke Detector	Classrooms 14/15	Tested	8:18:54 AM	08/19/2019
Smoke Detector	Electrical Room Behind Classroom 13	Tested	8:32:18 AM	08/19/2019
Smoke Detector	Electrical Room Behind Classroom 20	Tested	8:50:26 AM	08/19/2019
Smoke Detector	Electrical Room Behind Classroom 6	Tested	11:58:43 AM	08/19/2019
Smoke Detector	Electrical Room Near Classroom 12A	Tested	8:02:59 AM	08/19/2019
Smoke Detector	Girl's Portable Restroom	Tested	11:16:46 AM	08/19/2019
Smoke Detector	Girl's Restroom Near Classroom 12A	Tested	8:02:15 AM	08/19/2019
Smoke Detector	Girl's Restroom Near Classroom 19A	Tested	9:04:35 AM	08/19/2019
Smoke Detector	Girl's Restroom Near Classroom 7A	Tested	10:52:41 AM	08/19/2019
Smoke Detector	IDF/Electrical Room Behind Classroom 15	Tested	8:28:27 AM	08/19/2019
Smoke Detector	IDF/Electrical Room Behind Classroom 18	Tested	8:46:31 AM	08/19/2019
Smoke Detector	IDF/Electrical Room Behind Classroom 3	Tested	11:56:53 AM	08/19/2019
Smoke Detector	Kindergarten Classroom 1	Tested	10:26:26 AM	08/19/2019
Smoke Detector	Kindergarten Classroom 1	Tested	10:26:46 AM	08/19/2019
Smoke Detector	Kindergarten Classroom 1 Restroom	Tested	10:26:53 AM	08/19/2019
Smoke Detector	Kindergarten Classroom 2	Tested	10:28:20 AM	08/19/2019
Smoke Detector	Kindergarten Classroom 2	Tested	10:28:55 AM	08/19/2019
Smoke Detector	Kindergarten Classroom 2 Restroom	Tested	10:29:03 AM	08/19/2019
Smoke Detector	Kindergarten 1 And 2 Outside Storage Room	Tested	10:38:40 AM	08/19/2019
Smoke Detector	Kindergarten 1 And 2 Workroom Corridor	Tested	10:27:07 AM	08/19/2019
Smoke Detector	Kindergarten 1 And 2 Workroom Restroom	Tested	10:28:09 AM	08/19/2019
Smoke Detector	MPR Building Corridor Exit	Tested	9:50:23 AM	08/19/2019
Smoke Detector	MPR Building Custodian Storage	Tested	10:15:34 AM	08/19/2019
Smoke Detector	MPR Building Custodian Storage (Double Door)	Tested	10:17:57 AM	08/19/2019
Smoke Detector	MPR Building Kitchen Office	Tested	10:12:14 AM	08/19/2019
Smoke Detector	MPR Building Main Hall	Tested	9:49:18 AM	08/19/2019
Smoke Detector	MPR Building Main Hall	Tested	9:49:39 AM	08/19/2019
Smoke Detector	MPR Building Main Hall	Tested	9:49:48 AM	08/19/2019
Smoke Detector	MPR Building Main Hall	Tested	9:49:54 AM	08/19/2019
Smoke Detector	MPR Building Main Hall Chair Storage	Tested	10:05:29 AM	08/19/2019
Smoke Detector	MPR Building Stage	Tested	9:50:01 AM	08/19/2019
Smoke Detector	MPR Building Stage	Tested	9:50:14 AM	08/19/2019
Smoke Detector	Portable 10	Tested	11:10:14 AM	08/19/2019
Smoke Detector	Portable 10	Tested	11:10:25 AM	08/19/2019
Smoke Detector	Portable 11	Tested	11:10:41 AM	08/19/2019
Smoke Detector	Portable 11	Tested	11:11:13 AM	08/19/2019
Smoke Detector	Portable 21	Tested	9:21:28 AM	08/19/2019
Smoke Detector	Portable 21	Tested	9:21:43 AM	08/19/2019
Smoke Detector	Portable 22	Tested	9:21:58 AM	08/19/2019
Smoke Detector	Portable 22	Tested	9:22:08 AM	08/19/2019
Smoke Detector	Portable 23	Tested	9:22:35 AM	08/19/2019
Smoke Detector	Portable 23	Tested	9:22:44 AM	08/19/2019
Smoke Detector	Portable 24	Tested	9:23:22 AM	08/19/2019
Smoke Detector	Portable 24	Tested	9:23:33 AM	08/19/2019
Smoke Detector	Portable 25	Tested	9:24:05 AM	08/19/2019
Smoke Detector	Portable 25	Tested	9:24:14 AM	08/19/2019
Smoke Detector	Portable 26	Tested	9:24:53 AM	08/19/2019

Device Type	Location	Service	Time	Date				
Passed								
Smoke Detector	Portable 26	Tested	9:25:03 AM	08/19/2019				
Smoke Detector	Portable 27	Tested	9:25:09 AM	08/19/2019				
Smoke Detector	Portable 27	Tested	9:25:19 AM	08/19/2019				
Smoke Detector	Portable 28	Tested	9:25:34 AM	08/19/2019				
Smoke Detector	Portable 28	Tested	9:25:44 AM	08/19/2019				
Smoke Detector	Portable 29	Tested	9:25:51 AM	08/19/2019				
Smoke Detector	Portable 29	Tested	9:26:01 AM	08/19/2019				
Smoke Detector	Portable 30	Tested	11:19:53 AM	08/19/2019				
Smoke Detector	Portable 30	Tested	11:20:04 AM	08/19/2019				
Smoke Detector	Portable 31	Tested	11:19:16 AM	08/19/2019				
Smoke Detector	Portable 31	Tested	11:19:26 AM	08/19/2019				
Smoke Detector	Portable 32	Tested	11:15:17 AM	08/19/2019				
Smoke Detector	Portable 33	Tested	11:14:38 AM	08/19/2019				
Smoke Detector	Portable 33	Tested	11:14:49 AM	08/19/2019				
Smoke Detector	Portable 34	Tested	11:13:37 AM	08/19/2019				
Smoke Detector	Portable 34	Tested	11:13:46 AM	08/19/2019				
Smoke Detector	Portable 35	Tested	11:11:20 AM	08/19/2019				
Smoke Detector	Portable 35	Tested	11:12:55 AM	08/19/2019				
Smoke Detector	Portable 8	Tested	11:07:05 AM	08/19/2019				
Smoke Detector	Portable 8	Tested	11:07:17 AM	08/19/2019				
Smoke Detector	Portable 9	Tested	11:09:42 AM	08/19/2019				
Smoke Detector	Portable 9	Tested	11:10:01 AM	08/19/2019				
Smoke Detector	Portable Unisex Restroom	Tested	11:17:28 AM	08/19/2019				
Smoke Detector	Storage Room Behind Classroom 12A	Tested	8:03:38 AM	08/19/2019				
Smoke Detector	Unisex Restroom Near Classroom 19A	Tested	9:05:21 AM	08/19/2019				
Smoke Detector	Unisex Restroom Near Classroom 19A	Tested	9:06:17 AM	08/19/2019				
Smoke Detector	Unisex Restroom Near Classroom 7A	Tested	10:53:17 AM	08/19/2019				
Smoke Detector	Unisex Restroom Near Classroom 7A	Tested	10:53:41 AM	08/19/2019				

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Sonora Elementary

The Service Summary section provides an overview of the services performed in this report.

Device Type	Device Type Service			
	Passed			
Annunciator	Inspected	1		
Battery	Tested	18		
Control Panel	Inspected	1		
Heat Detector	Tested	58		
Power Supply	Inspected	8		
Pull Station	Tested	8		
Smoke Detector	Tested	119		
Total		213		

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - Sonora Elementary

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

			Ambient	Alarm	🦻 Intell	igibility	Sound
C Location		Comment	◀ dB	◀ dB	Voice	STI	Test
Failed/Other							
Sound Test Points							
Entire Campus							0001

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Sonora Elementary

Control Panel: 1 - Silent Knight 5820XL

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category		% of Inventory	Quantity	
Control Panel		Control		0.47%	1	
Battery		Control		8.41%	18	
Smoke Detector		Initiating		55.61%	119	
Pull Station		Initiating		3.74%	8	
Annunciator		Control		0.47%	1	
Power Supply		Control		3.74%	8	
Heat Detector		Initiating		27.10%	58	
Туре	Qty	Model #	Description		Install Date	
New (under 90 days)						
Silent Knight						
Annunciator	1	5820XL			08/19/2019	
Control Panel	1	5820XL			08/19/2019	
Heat Detector	57	SD505-AHS			08/19/2019	
		In Service	e - 2 Years to 3	Years		
Battery	2	12V18AH			07/31/2017	
Battery	16	12V7AH	Sealed Lead Acid		07/31/2017	
Silent Knight						
Heat Detector	1	SD505-AHS			07/31/2017	
Power Supply	8	5895XL			07/31/2017	
Pull Station	8	SD500-PS	Single Action		07/31/2017	
Smoke Detector	119	SD505-APS	Photoelectric		07/31/2017	

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD -TeWinkle Middle 3224 California St Costa Mesa, CA 92626

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Aug 21, 2019

> Building: NMUSD -TeWinkle Middle Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Thomas Galaz Title: Technician

Executive Summary Generated by: BuildingReports.com

Building Information			
Building: NMUSD – TeWinkle Middle	Contact: Tim W	/aller	
Address: 3224 California St	Phone: 714-23	1-0363	
Address:	Fax:		
City/State/Zip: Costa Mesa, CA 92626	Mobile:		
Country: United States of America	Email:		
Inspection Performed By			
Company: Cal Building Systems	Inspector: Tho	mas Galaz	
Address: 2903 Saturn Street	Phone: 714993	9650	
Address: Suite F	Fax:		
City/State/Zip: Brea, CA 92821	Mobile: 71421	58050	
Country: United States of America	Email: cbs@calbuildingsystems.com		
Monitoring			
Company:	Phone:	Account #:	
Central Station Signal Verification			
Туре:	Mfg:	Model #:	
Test Time/Date:	Restore Time		

Inspection Summary								
Cotoson	Total	Items	Ser	viced	Pa	ssed	Failed,	/Other
Category	Qty	%	Qty	%	Qty	%	Qty	%
Control	12	5.58%	12	100.00%	12	100.00%	0	0%
Initiating	203	94.42%	203	100.00%	203	100.00%	0	0%
Totals	215	100%	215	100.00%	215	100.00%	0	0%
Certification								
Company: Cal Building Systems			Bu	ilding: NML	JSD –TeW	inkle Middl	e	
Inspector: Thomas Galaz			Co	ontact: Tim	Waller			
Signed:			Sie	gned:				

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD -TeWinkle Middle

Control Panel: 1

Device Type	Location	Service	Time	Date
	Passed			
Control				
Battery	Bldg D. Pinny Computer Lab	Tested	12:07:50 PM	08/21/2019
Battery	Bldg D. Pinny Computer Lab	Tested	12:08:13 PM	08/21/2019
Battery	Bldg F. Classroom 32 Electrical Room	Tested	9:12:25 AM	08/21/2019
Battery	Bldg F. Classroom 32 Electrical Room	Tested	9:12:56 AM	08/21/2019
Battery	Gymnasium. Southeast Electrical Room	Tested	8:49:15 AM	08/21/2019
Battery	Gymnasium. Southeast Electrical Room	Tested	8:49:36 AM	08/21/2019
Battery	Gymnasium. Southeast Electrical Room	Tested	8:49:57 AM	08/21/2019
Battery	Gymnasium. Southeast Electrical Room	Tested	8:50:04 AM	08/21/2019
Power Supply	Bldg D. Pinny Computer Lab	Tested	12:07:09 PM	08/21/2019
Power Supply	Bldg F. Classroom 32 Electrical Room	Tested	9:11:34 AM	08/21/2019
Power Supply	Gymnasium. Southeast Electrical Room	Tested	8:48:19 AM	08/21/2019
Power Supply	Gymnasium. Southeast Electrical Room	Tested	8:49:01 AM	08/21/2019
Initiating				
Pull Station	Bldg D. Library	Tested	12:13:43 PM	08/21/2019
Pull Station	Bldg D. Library	Tested	12:14:06 PM	08/21/2019
Pull Station	Bldg D. Library	Tested	12:14:16 PM	08/21/2019
Pull Station	Bldg D. Library	Tested	12:14:23 PM	08/21/2019
Pull Station	Bldg E. Hallway	Tested	9:58:04 AM	08/21/2019
Pull Station	Bldg E. Hallway	Tested	9:58:12 AM	08/21/2019
Pull Station	Bldg E. Hallway	Tested	9:58:20 AM	08/21/2019
Pull Station	Bldg K. Boswell Hall	Tested	1:09:17 PM	08/21/2019
Pull Station	Bldg K. Boswell Hall	Tested	1:09:46 PM	08/21/2019
Pull Station	Gymnasium. East Entrance	Tested	8:24:44 AM	08/21/2019
Pull Station	Gymnasium. South Entrance	Tested	8:19:34 AM	08/21/2019
Pull Station	Gymnasium. South Entrance	Tested	8:19:55 AM	08/21/2019
Pull Station	Gymnasium. West Entrance	Tested	8:25:21 AM	08/21/2019
Smoke Detector	Admin Bldg. Teachers Lounge	Tested	7:44:38 AM	08/21/2019
Smoke Detector	Admin Bldg. Teachers Lounge	Tested	7:49:05 AM	08/21/2019
Smoke Detector	Bldg A. Classroom 5	Tested	10:31:43 AM	08/21/2019
Smoke Detector	Bldg A. Classroom 5	Tested	10:31:58 AM	08/21/2019
Smoke Detector	Bldg A. Classroom 6	Tested	10:26:55 AM	08/21/2019
Smoke Detector	Bldg A. Classroom 6	Tested	10:27:20 AM	08/21/2019
Smoke Detector	Bldg A. Classroom 6 Storage	Tested	10:28:42 AM	08/21/2019
Smoke Detector	Bldg A. Classroom 6 Storage	Tested	10:28:58 AM	08/21/2019
Smoke Detector	Bldg A. Classroom 7	Tested	10:25:31 AM	08/21/2019
Smoke Detector	Bldg A. Classroom 7	Tested	10:25:47 AM	08/21/2019
Smoke Detector	Bldg A. Classroom 8	Tested	10:22:12 AM	08/21/2019
Smoke Detector	Bldg A. Classroom 8	Tested	10:22:34 AM	08/21/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Bldg A. Classroom 8	Tested	10:22:42 AM	08/21/2019
Smoke Detector	Bldg A. Classroom 8 Storage	Tested	10:23:08 AM	08/21/2019
Smoke Detector	Bldg A. Classroom 8 Storage	Tested	10:23:22 AM	08/21/2019
Smoke Detector	Bldg A. Workroom Between Classroom 6 and 5	Tested	10:30:42 AM	08/21/2019
Smoke Detector	Bldg A. Workroom Between Classroom 6 and 5	Tested	10:31:13 AM	08/21/2019
Smoke Detector	Bldg B. Classroom 37	Tested	12:36:16 PM	08/21/2019
Smoke Detector	Bldg B. Classroom 37	Tested	12:36:43 PM	08/21/2019
Smoke Detector	Bldg B. Classroom 38	Tested	12:37:28 PM	08/21/2019
Smoke Detector	Bldg B. Classroom 38	Tested	12:38:16 PM	08/21/2019
Smoke Detector	Bldg B. Classroom 39	Tested	12:38:54 PM	08/21/2019
Smoke Detector	Bldg B. Classroom 39	Tested	12:39:51 PM	08/21/2019
Smoke Detector	Bldg B. Classroom 40	Tested	12:40:11 PM	08/21/2019
Smoke Detector	Bldg B. Classroom 40	Tested	12:40:24 PM	08/21/2019
Smoke Detector	Bldg B. Classroom 40 Workroom	Tested	12:41:20 PM	08/21/2019
Smoke Detector	Bldg B. Classroom 40 Workroom	Tested	12:41:42 PM	08/21/2019
Smoke Detector	Bldg B. Classroom 41	Tested	12:42:34 PM	08/21/2019
Smoke Detector	Bldg B. Classroom 41	Tested	12:42:48 PM	08/21/2019
Smoke Detector	Bldg C. Boys Restroom	Tested	11:50:07 AM	08/21/2019
Smoke Detector	Bldg C. Classroom 1–2	Tested	10:35:20 AM	08/21/2019
Smoke Detector	Bldg C. Classroom 1–2	Tested	10:35:52 AM	08/21/2019
Smoke Detector	Bldg C. Classroom 1–2	Tested	10:36:00 AM	08/21/2019
Smoke Detector	Bldg C. Classroom 1–2	Tested	10:36:07 AM	08/21/2019
Smoke Detector	Bldg C. Classroom 1–2	Tested	10:36:16 AM	08/21/2019
Smoke Detector	Bldg C. Classroom 1–2 Computer Room	Tested	10:38:18 AM	08/21/2019
Smoke Detector	Bldg C. Classroom 1–2 Computer Room	Tested	10:39:05 AM	08/21/2019
Smoke Detector	Bldg C. Classroom 1–2 Computer Room	Tested	10:41:15 AM	08/21/2019
Smoke Detector	Bldg C. Classroom 1–2 Computer Room	Tested	10:41:25 AM	08/21/2019
Smoke Detector	Bldg C. Classroom 1–2 Storage	Tested	10:37:32 AM	08/21/2019
Smoke Detector	Bldg C. Classroom 3	Tested	11:56:12 AM	08/21/2019
Smoke Detector	Bldg C. Classroom 3	Tested	11:56:33 AM	08/21/2019
Smoke Detector	Bldg C. Classroom 3 Storage Room	Tested	11:57:02 AM	08/21/2019
Smoke Detector	Bldg C. Classroom 4	Tested	11:52:38 AM	08/21/2019
Smoke Detector	Bldg C. Classroom 4	Tested	11:52:57 AM	08/21/2019
Smoke Detector	Bldg C. Classroom 4 Kitchen	Tested	11:53:29 AM	08/21/2019
Smoke Detector	Bldg C. Classroom 4 Server Room	Tested	11:54:51 AM	08/21/2019
Smoke Detector	Bldg C. Girls Restroom	Tested	11:50:33 AM	08/21/2019
Smoke Detector	Bldg D. Assistant Pricipal Office	Tested	12:29:56 PM	08/21/2019
Smoke Detector	Bldg D. Boys Restroom	Tested	12:47:34 PM	08/21/2019
Smoke Detector	Bldg D. Counseling Office	Tested	12:22:26 PM	08/21/2019
Smoke Detector	Bldg D. Counseling Office	Tested	12:29:38 PM	08/21/2019
Smoke Detector	Bldg D. Girls Restroom	Tested	12:45:44 PM	08/21/2019
Smoke Detector	Bldg D. library	Tested	12:11:44 PM	08/21/2019
Smoke Detector	Bldg D. library	Tested	12:12:05 PM	08/21/2019
Smoke Detector	Bldg D. library	Tested	12:12:13 PM	08/21/2019
Smoke Detector	Bldg D. library	Tested	12:12:20 PM	08/21/2019
Smoke Detector	Bldg D. library	Tested	12:12:29 PM	08/21/2019
Smoke Detector	Bldg D. library	Tested	12:12:44 PM	08/21/2019
Smoke Detector	Bldg D. library Back Hallway	Tested	12:19:50 PM	08/21/2019
Smoke Detector	Bldg D. library Back Room	Tested	12:16:35 PM	08/21/2019
Smoke Detector	Bldg D. library Community Facilitator Office	Tested	12:19:00 PM	08/21/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Bldg D. Library Office	Tested	12:31:09 PM	08/21/2019
Smoke Detector	Bldg D. library Psychologist Office	Tested	12:20:36 PM	08/21/2019
Smoke Detector	Bldg D. library Registrar Office	Tested	12:17:09 PM	08/21/2019
Smoke Detector	Bldg D. Office	Tested	12:11:14 PM	08/21/2019
Smoke Detector	Bldg D. Pinny Computer Lab	Tested	12:05:21 PM	08/21/2019
Smoke Detector	Bldg D. Pinny Computer Lab	Tested	12:05:56 PM	08/21/2019
Smoke Detector	Bldg D. Pinny Computer Lab	Tested	12:06:03 PM	08/21/2019
Smoke Detector	Bldg D. Pinny Computer Lab	Tested	12:06:37 PM	08/21/2019
Smoke Detector	Bldg D. Restroom	Tested	12:03:33 PM	08/21/2019
Smoke Detector	Bldg D. Restroom	Tested	12:46:16 PM	08/21/2019
Smoke Detector	Bldg D. Teacher Workroom	Tested	12:09:22 PM	08/21/2019
Smoke Detector	Bldg D. Teacher Workroom	Tested	12:09:46 PM	08/21/2019
Smoke Detector	Bldg D. Teacher Workroom Storage	Tested	12:10:37 PM	08/21/2019
Smoke Detector	Bldg E. Classroom 10	Tested	10:11:11 AM	08/21/2019
Smoke Detector	Bldg E. Classroom 10	Tested	10:11:44 AM	08/21/2019
Smoke Detector	Bldg E. Classroom 10	Tested	10:12:13 AM	08/21/2019
Smoke Detector	Bldg E. Classroom 11	Tested	10:10:27 AM	08/21/2019
Smoke Detector	Bldg E. Classroom 12	Tested	10:09:11 AM	08/21/2019
Smoke Detector	Bldg E. Classroom 13	Tested	10:08:24 AM	08/21/2019
Smoke Detector	Bldg E. Classroom 13	Tested	10:08:52 AM	08/21/2019
Smoke Detector	Bldg E. Classroom 14	Tested	10:10:06 AM	08/21/2019
Smoke Detector	Bldg E. Classroom 14.5	Tested	10:13:35 AM	08/21/2019
Smoke Detector	Bldg E. Classroom 14.5	Tested	10:14:07 AM	08/21/2019
Smoke Detector	Bldg E. Classroom 15	Tested	10:03:47 AM	08/21/2019
Smoke Detector	Bldg E. Classroom 16	Tested	10:06:29 AM	08/21/2019
Smoke Detector	Bldg E. Classroom 16	Tested	10:07:02 AM	08/21/2019
Smoke Detector	Bldg E. Classroom 9	Tested	10:17:58 AM	08/21/2019
Smoke Detector	Bldg E. Classroom 9	Tested	10:18:19 AM	08/21/2019
Smoke Detector	Bldg E. Hallway	Tested	9:55:46 AM	08/21/2019
Smoke Detector	Bldg E. Hallway	Tested	9:56:31 AM	08/21/2019
Smoke Detector	Bldg E. Hallway	Tested	9:56:44 AM	08/21/2019
Smoke Detector	Bldg E. Hallway	Tested	9:56:51 AM	08/21/2019
Smoke Detector	Bldg E. Hallway	Tested	9:57:00 AM	08/21/2019
Smoke Detector	Bldg E. Hallway	Tested	9:57:09 AM	08/21/2019
Smoke Detector	Bldg E. Hallway	Tested	10:15:05 AM	08/21/2019
Smoke Detector	Bldg F. Classroom 27	Tested	9:18:31 AM	08/21/2019
Smoke Detector	Bldg F. Classroom 27	Tested	9:18:56 AM	08/21/2019
Smoke Detector	Bldg F. Classroom 28	Tested	9:20:14 AM	08/21/2019
Smoke Detector	Bldg F. Classroom 28	Tested	9:20:29 AM	08/21/2019
Smoke Detector	Bldg F. Classroom 29	Tested	9:20:48 AM	08/21/2019
Smoke Detector	Bldg F. Classroom 30	Tested	9:16:51 AM	08/21/2019
Smoke Detector	Bldg F. Classroom 30	Tested	9:17:12 AM	08/21/2019
Smoke Detector	Bldg F. Classroom 30.5	Tested	9:07:49 AM	08/21/2019
Smoke Detector	Bldg F. Classroom 31	Tested	9:05:43 AM	08/21/2019
Smoke Detector	Bldg F. Classroom 31	Tested	9:06:15 AM	08/21/2019
Smoke Detector	Bldg F. Classroom 32	Tested	9:09:08 AM	08/21/2019
Smoke Detector	Bldg F. Classroom 32	Tested	9:09:34 AM	08/21/2019
Smoke Detector	Bldg F. Classroom 32 Electrical Room	Tested	9:11:00 AM	08/21/2019
Smoke Detector	Bldg F. Classroom 32 Electrical Room	Tested	9:13:56 AM	08/21/2019
Smoke Detector	Bldg F. Classroom 32 Storage Room	Tested	9:13:38 AM	08/21/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Bldg F. Classroom 33	Tested	9:04:19 AM	08/21/2019
Smoke Detector	Bldg F. Classroom 34	Tested	8:55:28 AM	08/21/2019
Smoke Detector	Bldg F. Classroom 35	Tested	8:54:06 AM	08/21/2019
Smoke Detector	Bldg F. Classroom 35	Tested	8:54:57 AM	08/21/2019
Smoke Detector	Bldg F. Classroom 36	Tested	8:57:47 AM	08/21/2019
Smoke Detector	Bldg F. Classroom 36	Tested	8:58:35 AM	08/21/2019
Smoke Detector	Bldg F. Hallway	Tested	8:56:49 AM	08/21/2019
Smoke Detector	Bldg F. Hallway	Tested	8:57:13 AM	08/21/2019
Smoke Detector	Bldg F. Hallway	Tested	9:05:10 AM	08/21/2019
Smoke Detector	Bldg F. Hallway	Tested	9:05:32 AM	08/21/2019
Smoke Detector	Bldg F. Hallway	Tested	9:15:37 AM	08/21/2019
Smoke Detector	Bldg F. Hallway	Tested	9:16:01 AM	08/21/2019
Smoke Detector	Bldg K. Boswell Hall Stage Access	Tested	1:11:35 PM	08/21/2019
Smoke Detector	Bldg K. Choir Room	Tested	1:25:59 PM	08/21/2019
Smoke Detector	Bldg K. Choir Room	Tested	1:26:24 PM	08/21/2019
Smoke Detector	Bldg K. Choir Room Storage	Tested	1:27:38 PM	08/21/2019
Smoke Detector	Bldg K. Choir Room Storage	Tested	1:29:56 PM	08/21/2019
Smoke Detector	Bldg K. Classroom 42 Band	Tested	1:15:06 PM	08/21/2019
Smoke Detector	Bldg K. Classroom 42 Band	Tested	1:15:44 PM	08/21/2019
Smoke Detector	Bldg K. Classroom 42 Band	Tested	1:15:58 PM	08/21/2019
Smoke Detector	Bldg K. Classroom 42 Band	Tested	1:16:11 PM	08/21/2019
Smoke Detector	Bldg K. Classroom 42 Band	Tested	1:16:26 PM	08/21/2019
Smoke Detector	Bldg K. Classroom 42 Band	Tested	1:16:36 PM	08/21/2019
Smoke Detector	Bldg K. Classroom 42 Band Office	Tested	1:17:49 PM	08/21/2019
Smoke Detector	Bldg K. Classroom 42 Band Storage	Tested	1:20:26 PM	08/21/2019
Smoke Detector	Bldg K. Classroom 42 Band Storage	Tested	1:21:48 PM	08/21/2019
Smoke Detector	Bldg K. Classroom 43	Tested	1:31:23 PM	08/21/2019
Smoke Detector	Bldg K. Custodian Closet	Tested	1:33:23 PM	08/21/2019
Smoke Detector	Bldg K. Hallway	Tested	1:25:40 PM	08/21/2019
Smoke Detector	Bldg K. Kitchen	Tested	1:34:28 PM	08/21/2019
Smoke Detector	Bldg K. Kitchen	Tested	1:34:57 PM	08/21/2019
Smoke Detector	Bldg K. Kitchen Cold Drink Storage	Tested	1:47:00 PM	08/21/2019
Smoke Detector	Bldg K. Kitchen Freezer Storage	Tested	1:46:17 PM	08/21/2019
Smoke Detector	Bldg K. Kitchen Office	Tested	1:43:12 PM	08/21/2019
Smoke Detector	Bldg K. Kitchen Snack Stand	Tested	1:47:42 PM	08/21/2019
Smoke Detector	Bldg K. Kitchen Storage	Tested	1:36:37 PM	08/21/2019
Smoke Detector	Bldg K. Kitchen Storage	Tested	1:40:15 PM	08/21/2019
Smoke Detector	Bldg K. Kitchen Storage Restroom	Tested	1:41:23 PM	08/21/2019
Smoke Detector	Bldg K. Mechanical Room	Tested	1:13:40 PM	08/21/2019
Smoke Detector	Gymnasium. Boys Locker Room	Tested	8:36:37 AM	08/21/2019
Smoke Detector	Gymnasium. Boys Locker Room	Tested	8:37:05 AM	08/21/2019
Smoke Detector	Gymnasium. Boys Locker Room	Tested	8:37:24 AM	08/21/2019
Smoke Detector	Gymnasium. Boys Locker Room	Tested	8:37:50 AM	08/21/2019
Smoke Detector	Gymnasium. Boys Locker Room	Tested	8:39:06 AM	08/21/2019
Smoke Detector	Gymnasium. Boys Locker Room Coaches Office	Tested	8:40:46 AM	08/21/2019
Smoke Detector	Gymnasium. Boys Locker Room Coaches Office	Tested	8:41:27 AM	08/21/2019
	Restroom	-		
Smoke Detector	Gymnasium. Boys Locker Room Exit Route	Tested	8:42:05 AM	08/21/2019
Smoke Detector	Gymnasium. Boys Locker Room Restroom	Tested	8:39:20 AM	08/21/2019
Smoke Detector	Gymnasium. Boys Locker Room Restroom	Tested	8:39:49 AM	08/21/2019
SHOKE DEIELIUI	Gymnasiam, buys Locker Routh Restroom	i Coleu	5.55. 15 AM	55/21/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Gymnasium. Girls Locker Room	Tested	8:27:44 AM	08/21/2019
Smoke Detector	Gymnasium. Girls Locker Room	Tested	8:31:40 AM	08/21/2019
Smoke Detector	Gymnasium. Girls Locker Room	Tested	8:31:52 AM	08/21/2019
Smoke Detector	Gymnasium. Girls Locker Room	Tested	8:33:01 AM	08/21/2019
Smoke Detector	Gymnasium. Girls Locker Room Restroom	Tested	8:28:56 AM	08/21/2019
Smoke Detector	Gymnasium. Girls Locker Room Restroom	Tested	8:29:13 AM	08/21/2019
Smoke Detector	Gymnasium. Girls Locker Room Teachers Office	Tested	8:33:37 AM	08/21/2019
Smoke Detector	Gymnasium. Girls Locker Room Teachers Office Restroom	Tested	8:34:37 AM	08/21/2019
Smoke Detector	Gymnasium. South Entrance	Tested	8:17:41 AM	08/21/2019
Smoke Detector	Gymnasium. Southeast Electrical Room	Tested	8:45:52 AM	08/21/2019
Smoke Detector	Gymnasium. Southeast Storage Room	Tested	8:44:48 AM	08/21/2019
Smoke Detector	Gymnasium. Storage Equipment Room	Tested	8:13:10 AM	08/21/2019
Smoke Detector	Portables. Classroom 22	Tested	9:52:36 AM	08/21/2019
Smoke Detector	Portables. Classroom 22	Tested	9:54:13 AM	08/21/2019
Smoke Detector	Portables. Classroom 23	Tested	9:51:47 AM	08/21/2019
Smoke Detector	Portables. Classroom 23	Tested	9:52:24 AM	08/21/2019
Smoke Detector	Portables. Equipment Room	Tested	9:40:04 AM	08/21/2019
Smoke Detector	Portables. Equipment Room	Tested	9:40:30 AM	08/21/2019
Smoke Detector	Portables. Equipment Room	Tested	9:40:41 AM	08/21/2019
Smoke Detector	Portables. Equipment Room	Tested	9:40:51 AM	08/21/2019
Smoke Detector	Portables. Equipment Room Office	Tested	9:42:25 AM	08/21/2019
Smoke Detector	Portables. Fitness Room	Tested	9:46:53 AM	08/21/2019
Smoke Detector	Portables. Fitness Room	Tested	9:47:14 AM	08/21/2019
Smoke Detector	Portables. Fitness Room	Tested	9:47:21 AM	08/21/2019
Smoke Detector	Portables. Fitness Room	Tested	9:47:28 AM	08/21/2019
Smoke Detector	Portables. Fitness Room Office	Tested	9:47:48 AM	08/21/2019
Smoke Detector	Portables. Men's Restroom	Tested	9:35:00 AM	08/21/2019
Smoke Detector	Portables. Women's Restroom	Tested	9:35:32 AM	08/21/2019
Waterflow Switch	Gymnasium. Storage Equipment Room	Tested	8:14:47 AM	08/21/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD -TeWinkle Middle

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Battery	Tested	8
Power Supply	Tested	4
Pull Station	Tested	13
Smoke Detector	Tested	189
Waterflow Switch	Tested	1
Total		215

Time, Temperature & Level Testing Generated by: BuildingReports.com

Building: NMU	JSD -TeWinkle Middle	Control Pane	1:1						
respond in a certain	rre, & Level Testing section details the measu amount of time, respond at a certain tempera ouped by Passed or Failed/Other.								
Туре	Location	Comment	Sec	Deg	Lvl	ScanID			
Passed									
Waterflow Swit	ch								
	Gymnasium. Storage Equipment Room	Passed	23	n/a	n/a	47353341			

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD -TeWinkle Middle

Control Panel: 1

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category		% of Inventory	Quantity			
Smoke Detector		Initiating		87.91%	189			
Waterflow Switch		Initiating		0.47%	1			
Pull Station		Initiating		6.05%	13			
Power Supply		Control		1.86%	4			
Battery		Control	1	3.72%	8			
Туре	Qty	Model #	Description		Install Date			
New (under 90 days)								
Battery	8	12v 7ah	x		08/21/2019			
Potter Electric								
Waterflow Switch	1	VSR			08/21/2019			
Silent Knight								
Power Supply	4	RPS-1000			08/21/2019			
Pull Station	13	SD500-PS			08/21/2019			
Smoke Detector	189	SD505APS	Photoelectric		08/21/2019			

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD -TeWinkle Middle 3224 California St Costa Mesa, CA 92626

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Aug 21, 2019

> Building: NMUSD -TeWinkle Middle Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Beeri Martinez Title: Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD – TeWinkle Middle	Contact: Tim	Waller
Address: 3224 California St	Phone: 714-2	31-0363
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92626	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Bee	eri Martinez
Address: 2903 Saturn Street	Phone: 714–9	1313100
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: beerim	artinez@calbuildingsystems.com
System Control Unit		
Manufacturer: Silent Knight	Inspection Da	te: 08/21/2019 IDC Style:
Model Number: 5820XL	Install Date: 0	8/21/2019 SLC Style:
Software Version:	Version Date:	08/21/2019 NAC Style:
Location: Admin Bldg. Files Room	Current Prote	ction:
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Cohomony	Total	ltems	Ser	viced	Pa	ssed	Failed	/Other
Category	Qty	%	Qty	%	Qty	%	Qty	%
Control	4	4.21%	4	100.00%	4	100.00%	0	0%
Initiating	91	95.79%	91	100.00%	91	100.00%	0	0%
Totals	95	100%	95	100.00%	95	100.00%	0	0%
Certification								
Company: Cal Building Systems			Bu	ilding: NMU	ISD –TeW	inkle Middl	e	
Inspector: Beeri Martinez			Co	ontact: Tim V	Waller			
Signed:			Sie	gned:				

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD -TeWinkle Middle

Control Panel: 1 - Silent Knight 5820XL

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Admin Bldg. Entrance	Tested	7:47:42 AM	08/21/2019
Battery	Admin Bldg. Files Room	Tested	7:40:41 AM	08/21/2019
Battery	Admin Bldg. Files Room	Tested	7:41:20 AM	08/21/2019
Control Panel	Admin Bldg. Files Room	Tested	7:38:26 AM	08/21/2019
Initiating				
Heat Detector	Center Bldg. F Corridor	Tested	9:31:13 AM	08/21/2019
Heat Detector	Center Library	Tested	9:28:00 AM	08/21/2019
Heat Detector	East Shop	Tested	9:58:02 AM	08/21/2019
Heat Detector	East Kitchen	Tested	10:35:03 AM	08/21/2019
Heat Detector	East Library	Tested	9:27:40 AM	08/21/2019
Heat Detector	North Shop Workroom	Tested	9:57:35 AM	08/21/2019
Heat Detector	North Shop Workroom	Tested	9:57:52 AM	08/21/2019
Heat Detector	West Bldg. F Corridor	Tested	9:29:23 AM	08/21/2019
Heat Detector	West Shop	Tested	9:42:49 AM	08/21/2019
Heat Detector	West Kitchen	Tested	10:35:20 AM	08/21/2019
Heat Detector	West Library	Tested	9:28:10 AM	08/21/2019
Heat Detector	Admin Bldg. Attic Admin Restroom	Tested	10:18:16 AM	08/21/2019
Heat Detector	Admin Bldg. Attic Nurse Restroom	Tested	10:20:18 AM	08/21/2019
Heat Detector	Admin Bldg. Mechanical Room	Tested	8:00:26 AM	08/21/2019
Heat Detector	Bldg. B Electrical Closet	Tested	10:04:39 AM	08/21/2019
Heat Detector	Bldg. C Office	Tested	9:58:38 AM	08/21/2019
Heat Detector	Bldg. E Corridor	Tested	9:11:33 AM	08/21/2019
Heat Detector	Bldg. E Corridor	Tested	9:11:51 AM	08/21/2019
Heat Detector	Bldg. E Corridor	Tested	9:11:58 AM	08/21/2019
Heat Detector	Bldg. E Electrical Room	Tested	9:10:53 AM	08/21/2019
Heat Detector	Bldg. E Storage	Tested	9:09:01 AM	08/21/2019
Heat Detector	Bldg. E Sub Resource	Tested	9:09:39 AM	08/21/2019
Heat Detector	Bldg. G Utility Closet	Tested	10:26:42 AM	08/21/2019
Heat Detector	Gymnasium Custodian Closet M105	Tested	9:42:16 AM	08/21/2019
Heat Detector	Gymnasium Custodian Room	Tested	8:23:25 AM	08/21/2019
Heat Detector	Gymnasium Girl's Locker Room M107	Tested	9:41:30 AM	08/21/2019
Heat Detector	MPR Attic	Tested	10:30:38 AM	08/21/2019
Heat Detector	MPR Dressing Attic	Tested	10:29:04 AM	08/21/2019
Heat Detector	MPR Girl's Restroom Attic	Tested	10:27:54 AM	08/21/2019
Heat Detector	MPR Stage Attic	Tested	10:31:07 AM	08/21/2019
Heat Detector	Portables Boys Restroom	Tested	10:25:23 AM	08/21/2019
Heat Detector	Portables Girls Restroom	Tested	10:38:53 AM	08/21/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	Classroom 10	Tested	9:07:29 AM	08/21/2019
Heat Detector	Classroom 11	Tested	9:07:21 AM	08/21/2019
Heat Detector	Classroom 12	Tested	9:07:09 AM	08/21/2019
Heat Detector	Classroom 13	Tested	9:06:38 AM	08/21/2019
Heat Detector	Classroom 14	Tested	9:06:17 AM	08/21/2019
Heat Detector	Classroom 14.5	Tested	9:10:25 AM	08/21/2019
Heat Detector	Classroom 15	Tested	9:05:55 AM	08/21/2019
Heat Detector	Classroom 16	Tested	9:05:18 AM	08/21/2019
Heat Detector	Classroom 3	Tested	9:58:47 AM	08/21/2019
Heat Detector	Classroom 30	Tested	9:40:30 AM	08/21/2019
Heat Detector	Classroom 32	Tested	9:30:42 AM	08/21/2019
Heat Detector	Classroom 33	Tested	9:30:04 AM	08/21/2019
Heat Detector	Classroom 34	Tested	9:29:54 AM	08/21/2019
Heat Detector	Classroom 35	Tested	9:29:00 AM	08/21/2019
Heat Detector	Classroom 36	Tested	9:29:11 AM	08/21/2019
Heat Detector	Classroom 4	Tested	9:59:00 AM	08/21/2019
Heat Detector	Classroom 42 Practice Room	Tested	10:33:07 AM	08/21/2019
Heat Detector	Classroom 9	Tested	9:07:55 AM	08/21/2019
Heat Detector	Kitchen Restroom	Tested	10:36:03 AM	08/21/2019
Smoke Detector	Center Gymnasium High Ceiling Row 3-A	Tested	8:29:05 AM	08/21/2019
Smoke Detector	Center Gymnasium High Ceiling Row 3-B	Tested	8:32:38 AM	08/21/2019
Smoke Detector	Center Gymnasium High Ceiling Row 3-C	Tested	8:35:44 AM	08/21/2019
Smoke Detector	Center Gymnasium High Ceiling Row 3-D	Tested	8:41:31 AM	08/21/2019
Smoke Detector	Center Gymnasium High Ceiling Row 3-E	Tested	8:44:36 AM	08/21/2019
Smoke Detector	Center Gymnasium High Ceiling Row 3-F	Tested	8:47:08 AM	08/21/2019
Smoke Detector	North Gymnasium High Ceiling Row 1-A	Tested	8:27:39 AM	08/21/2019
Smoke Detector	North Gymnasium High Ceiling Row 1-B	Tested	8:33:15 AM	08/21/2019
Smoke Detector	North Gymnasium High Ceiling Row 1-D	Tested	8:38:16 AM	08/21/2019
Smoke Detector	North Gymnasium High Ceiling Row 1-E	Tested	8:43:58 AM	08/21/2019
Smoke Detector	North Gymnasium High Ceiling Row 1-F	Tested	8:47:51 AM	08/21/2019
Smoke Detector	North Gymnasium High Ceiling Row 2-A	Tested	8:28:47 AM	08/21/2019
Smoke Detector	North Gymnasium High Ceiling Row 2-B	Tested	8:32:52 AM	08/21/2019
Smoke Detector	North Gymnasium High Ceiling Row 2-C	Tested	8:35:00 AM	08/21/2019
Smoke Detector	North Gymnasium High Ceiling Row 2-D	Tested	8:41:17 AM	08/21/2019
Smoke Detector	North Gymnasium High Ceiling Row 2-E	Tested	8:44:24 AM	08/21/2019
Smoke Detector	North Gymnasium High Ceiling Row 2-F	Tested	8:47:32 AM	08/21/2019
Smoke Detector	South Gymnasium High Ceiling Row 4-A	Tested	8:29:41 AM	08/21/2019
Smoke Detector	South Gymnasium High Ceiling Row 4-B	Tested	8:32:19 AM	08/21/2019
Smoke Detector	South Gymnasium High Ceiling Row 4-C	Tested	8:36:01 AM	08/21/2019
Smoke Detector	South Gymnasium High Ceiling Row 4-D	Tested	8:42:42 AM	08/21/2019
Smoke Detector	South Gymnasium High Ceiling Row 4-E	Tested	8:45:22 AM	08/21/2019
Smoke Detector	South Gymnasium High Ceiling Row 4-F	Tested	8:46:42 AM	08/21/2019
Smoke Detector	South Gymnasium High Ceiling Row 5-A	Tested	8:30:03 AM	08/21/2019
Smoke Detector	South Gymnasium High Ceiling Row 5-B	Tested	8:31:12 AM	08/21/2019
Smoke Detector	South Gymnasium High Ceiling Row 5-C	Tested	8:37:54 AM	08/21/2019
Smoke Detector	South Gymnasium High Ceiling Row 5-D	Tested	8:43:40 AM	08/21/2019
Smoke Detector	South Gymnasium High Ceiling Row 5-E	Tested	8:45:46 AM	08/21/2019
Smoke Detector	South Gymnasium High Ceiling Row 5-F	Tested	8:46:01 AM	08/21/2019
Smoke Detector	South Gymnasium High Ceiling Row 5-F	Tested	8:46:36 AM	08/21/2019
Smoke Detector	Admin Bldg. Above Reception Desk	Tested	7:45:23 AM	08/21/2019

Device Type	Location	Service	Time	Date		
Passed						
Smoke Detector	Admin Bldg. Admin Assistant	Tested	7:53:03 AM	08/21/2019		
Smoke Detector	Admin Bldg. ASB Office	Tested	7:58:11 AM	08/21/2019		
Smoke Detector	Admin Bldg. Files Room	Tested	7:42:56 AM	08/21/2019		
Smoke Detector	Admin Bldg. Nurse Office Restroom	Tested	7:54:56 AM	08/21/2019		
Smoke Detector	Admin Bldg. Nurse Office	Tested	7:54:20 AM	08/21/2019		
Smoke Detector	Admin Bldg. Principals Office	Tested	7:49:37 AM	08/21/2019		
Smoke Detector	Admin Bldg. Teachers Lounge Corridor	Tested	7:55:58 AM	08/21/2019		
Smoke Detector	Admin Bldg. Teachers Lounge Staff Restroom	Tested	7:57:27 AM	08/21/2019		
Smoke Detector	Admin Bldg. Teachers Lounge Women's	Tested	7:56:38 AM	08/21/2019		
	Restroom					

Service Summary

Generated by: BuildingReports.com

Building: NMUSD -TeWinkle Middle

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Annunciator	Tested	1
Battery	Tested	2
Control Panel	Tested	1
Heat Detector	Tested	51
Smoke Detector	Tested	40
Total		95

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD -TeWinkle Middle

Control Panel: 1 - Silent Knight 5820XL

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category		% of Inventory	Quantity	
Control Panel		Control		1.05%	1	
Battery		Control		2.11%	2	
Smoke Detector		Initiating		42.11%	40	
Annunciator		Control		1.05%	1	
Heat Detector		Initiating		53.68%	51	
Туре	Qty	Model #	Description		Install Date	
New (under 90 days)						
Silent Knight						
Annunciator	1	5860	LCD Display		08/21/2019	
Control Panel	1	5820XL			08/21/2019	
Heat Detector	51	SD505-AHS	Fixed Temperate	ure	08/21/2019	
Smoke Detector	40	SD505-APS	Photoelectric		08/21/2019	
	In Service - 2 Years to 3 Years					
Battery	2	12v 24ah	Sealed Lead Acid	k	08/26/2017	

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Victoria Elementary School 1025 Victoria Street Costa Mesa, CA 92627

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Aug 23, 2019

> Building: NMUSD - Victoria Elementary School Contact: Tim Waller Title: District Manager

Company: Cal Building Systems Contact: JD Torres Title: Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD - Victoria Elementary School	Contact: Tim W	aller
Address: 1025 Victoria Street	Phone: 714–23	1-0363
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92627	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: JD Te	orres
Address: 2903 Saturn Street	Phone: 909–34	8-3402
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: jdtorres@	<pre>Pcalbuildingsystems.com</pre>
System Control Unit		
Manufacturer: SimplexGrinnell	Inspection Date	:: 08/23/2019 IDC Style :
Model Number: 4020	Install Date: 08	/23/2019 SLC Style:
Software Version:	Version Date: 0	8/23/2019 NAC Style:
Location: Admin Electrical Room	Current Protect	ion: Breaker
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
	Tota	Items	Ser	viced	Pa	ssed	Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Control	10	14.71%	10	100.00%	8	80.00%	2	20.00%
Initiating	58	85.29%	58	100.00%	58	100.00%	0	0%
Totals	68	100%	68	100.00%	66	97.06%	2	2.94%
Certification								
Company: Cal Building Systems			Βι	uilding: NMU	ISD – Vic	toria Elemer	ntary Scho	bol
Inspector: JD Torres			C	ontact: Tim \	Waller			
Signed:			Si	gned:				

Discrepancy Report Generated by: BuildingReports.com

Building: NMUSD - Victoria Elementary			(Control Panel	: 1 - Sim	plexGri	nnell
School			4	020			
The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.							
Device Type		Manufacturer	N	odelNumber	Da	te	Qty
	I	tems listed for Re	ecall by M	lanufacture	r		
		No recalled items fou	und during th	is inspection.			
8 ScanID	C Location		୧ Pr	oblem	Address	🛄 Ref	erence
Control							
Battery							
58093494	Admin Electrical F	Room (Power Supply)	Out O	Date	1		
58093495	Admin Electrical F	Room (Power Supply)	Out O	Date	1		

Proposed Solutions Report

Generated by: BuildingReports.com

Building: NMUSD - Victoria Elementary School

Control Panel: 1 - SimplexGrinnell 4020

The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.

ScanID	Location	Solution	Model #	Cost	Fix	
Control						
Battery						
58093494	Admin Electrical Room (Power Supply)	Replace	12v7ah	T/M		
58093495	Admin Electrical Room (Power Supply)	Replace	12v7ah	T/M		
			PO #: (none)	T/M		

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Victoria Elementary School

Control Panel: 1 - SimplexGrinnell 4020

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Admin Reception	Tested	10:22:28 AM	08/23/2019
Battery	Admin Electrical Room (Main Panel)	Inspected	10:54:01 AM	08/23/2019
Battery	Admin Electrical Room (Main Panel)	Inspected	10:54:52 AM	08/23/2019
Battery	Portable Classroom 18	Inspected	8:17:03 AM	08/23/2019
Battery	Portable Classroom 18	Inspected	8:17:16 AM	08/23/2019
Control Panel	Admin Electrical Room	Tested	10:51:31 AM	08/23/2019
Power Supply	Admin Electrical Room	Tested	10:51:59 AM	08/23/2019
Power Supply	Portable Classroom 18	Tested	8:16:18 AM	08/23/2019
Initiating				
Pull Station	Admin Reception	Tested	10:20:16 AM	08/23/2019
Pull Station	Admin Reception By Annunciator	Tested	10:21:45 AM	08/23/2019
Pull Station	Admin Staff Lounge	Tested	8:07:17 AM	08/23/2019
Pull Station	Building B Kitchen	Tested	9:19:38 AM	08/23/2019
Pull Station	Building B Multipurpose Room Entry	Tested	9:25:15 AM	08/23/2019
Pull Station	Building B Multipurpose Room North	Tested	9:21:29 AM	08/23/2019
Pull Station	Building B Multipurpose Room South	Tested	9:20:33 AM	08/23/2019
Pull Station	Building B Multipurpose Room Stage	Tested	9:22:46 AM	08/23/2019
Pull Station	Building B Workroom By Workroom	Tested	9:14:31 AM	08/23/2019
Pull Station	Building D Classroom 10	Tested	9:02:50 AM	08/23/2019
Pull Station	Building D Classroom 11	Tested	9:03:57 AM	08/23/2019
Pull Station	Building D Classroom 9	Tested	9:00:07 AM	08/23/2019
Pull Station	Building E Classroom 1	Tested	10:04:09 AM	08/23/2019
Pull Station	Building E Classroom 2	Tested	10:02:34 AM	08/23/2019
Pull Station	Building E Classroom 3	Tested	9:59:49 AM	08/23/2019
Pull Station	Building F Classroom 4	Tested	10:16:40 AM	08/23/2019
Pull Station	Building F Classroom 5	Tested	10:15:18 AM	08/23/2019
Pull Station	Building F Classroom 6	Tested	10:14:28 AM	08/23/2019
Pull Station	Building G Classroom 7	Tested	9:06:54 AM	08/23/2019
Pull Station	Building G Classroom 8	Tested	9:09:05 AM	08/23/2019
Pull Station	Building H Main Electrical Room	Tested	9:10:39 AM	08/23/2019
Smoke Detector	Admin Electrical Room	Tested	8:21:33 AM	08/23/2019
Smoke Detector	Admin Nurse Restroom	Tested	10:19:09 AM	08/23/2019
Smoke Detector	Admin Staff Lounge Restroom	Tested	8:08:06 AM	08/23/2019
Smoke Detector	Building B Kitchen	Tested	9:17:41 AM	08/23/2019
Smoke Detector	Building B Storage Room West	Tested	9:29:45 AM	08/23/2019
Smoke Detector	Building D Mechanical Room	Tested	8:54:07 AM	08/23/2019
Smoke Detector	Building D Mechanical Room	Tested	8:58:42 AM	08/23/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building E Custodian Room	Tested	9:58:39 AM	08/23/2019
Smoke Detector	Building F Custodian Room	Tested	9:55:45 AM	08/23/2019
Smoke Detector	Building H Main Electrical Room	Tested	9:11:14 AM	08/23/2019
Smoke Detector	Building J Classroom 17	Tested	9:46:05 AM	08/23/2019
Smoke Detector	Building J Classroom 17	Tested	9:47:10 AM	08/23/2019
Smoke Detector	Building J Classroom 25	Tested	9:49:42 AM	08/23/2019
Smoke Detector	Building J Classroom 25	Tested	9:49:53 AM	08/23/2019
Smoke Detector	Building K Classroom 22	Tested	9:39:36 AM	08/23/2019
Smoke Detector	Building K Classroom 23	Tested	9:37:31 AM	08/23/2019
Smoke Detector	Building K Classroom 32	Tested	9:41:21 AM	08/23/2019
Smoke Detector	Building K Library	Tested	9:42:20 AM	08/23/2019
Smoke Detector	Building K Library	Tested	9:43:59 AM	08/23/2019
Smoke Detector	Building L Classroom 15	Tested	9:33:06 AM	08/23/2019
Smoke Detector	Building L Classroom 15	Tested	9:34:01 AM	08/23/2019
Smoke Detector	Building L Classroom 16	Tested	9:35:21 AM	08/23/2019
Smoke Detector	Building L Classroom 16	Tested	9:35:30 AM	08/23/2019
Smoke Detector	Portable Classroom 12	Tested	8:47:46 AM	08/23/2019
Smoke Detector	Portable Classroom 12	Tested	8:48:50 AM	08/23/2019
Smoke Detector	Portable Classroom 13	Tested	8:45:24 AM	08/23/2019
Smoke Detector	Portable Classroom 13	Tested	8:46:54 AM	08/23/2019
Smoke Detector	Portable Classroom 14	Tested	8:43:03 AM	08/23/2019
Smoke Detector	Portable Classroom 14	Tested	8:44:22 AM	08/23/2019
Smoke Detector	Portable Classroom 18	Tested	8:17:37 AM	08/23/2019
Smoke Detector	Portable Classroom 18	Tested	8:18:05 AM	08/23/2019
Smoke Detector	Portable Classroom 19	Tested	8:33:45 AM	08/23/2019
Smoke Detector	Portable Classroom 19	Tested	8:33:54 AM	08/23/2019
Smoke Detector	Portable Classroom 20	Tested	8:36:06 AM	08/23/2019
Smoke Detector	Portable Classroom 20	Tested	8:36:17 AM	08/23/2019
Smoke Detector	Portable Classroom 21	Tested	8:39:16 AM	08/23/2019
Smoke Detector	Portable Classroom 21	Tested	8:39:25 AM	08/23/2019
Device Type	Location	Service	Time	Date
	Failed/Othe	r		
Control				
Battery	Admin Electrical Room (Power Supply)	Inspected	10:53:12 AM	08/23/2019
Battery	Admin Electrical Room (Power Supply)	Inspected	10:53:46 AM	08/23/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Victoria Elementary School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity			
Failed/Other					
Battery	Inspected	2			
Total		2			
	Passed				
Annunciator	Tested	1			
Battery	Inspected	4			
Control Panel	Tested	1			
Power Supply	Tested	2			
Pull Station	Tested	21			
Smoke Detector	Tested	37			
Total		68			

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Victoria Elementary	Control Panel: 1 - SimplexGrinnell
School	4020

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category	% of Ir	nventory	Quantity
Pull Station		Initiating		30.88%	21
Smoke Detector		Initiating		54.41%	37
Power Supply		Control		2.94%	2
Battery		Control		8.82%	6
Annunciator		Control		1.47%	1
Control Panel		Control		1.47%	1
Туре	Qty	Model #	Description		Install Date
		New	(under 90 days)		
SimplexGrinnell					
Annunciator	1		LCD Display		08/23/2019
Control Panel	1	4020			08/23/2019
Power Supply	2	4009			08/23/2019
Pull Station	21	2099-9795	Single Action		08/23/2019
Smoke Detector	37	4098-9714	Photoelectric		08/23/2019
		In Service	- 2 Years to 3 Years	S	
Battery	2	12v18ah	Sealed Lead Acid		04/01/2017
		In Service	- 3 Years to 5 Years	S	
Battery	2	12v7ah	Sealed Lead Acid		09/01/2016
		In Service	- 5 Years to 10 Year	rs	
Battery	2	12v7ah	Sealed Lead Acid		08/01/2013

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Waldorf Elementary Schooll 2350 Canyon Drive Costa Mesa, CA 92627

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Sep 18, 2019

Building: NMUSD - Waldorf Elementary Schooll Contact: Tim Waller Title: Maintenance & Operations Manager Company: Cal Building Systems Contact: Andrew Partida Title: Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD – Waldorf Elementary Schooll	Contact: Tim W	aller
Address: 2350 Canyon Drive	Phone: 714-23	1-0363
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92627	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Andr	ew Partida
Address: 2903 Saturn Street	Phone: 909–52	7–5523
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: andrewp	artida@calbuildingsystems.com
System Control Unit		
Manufacturer: Silent Knight	Inspection Date	: 09/18/2019 IDC Style :
Model Number: IFP-2000ECS	Install Date: 09	/16/2019 SLC Style:
Software Version:	Version Date: 1	2/31/1969 NAC Style:
Location: Meadows Hall Closet	Current Protect	ion:
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
C. I.	Total Items		Serviced		Passed		Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Control	24	20.00%	24	100.00%	24	100.00%	0	0%
Initiating	95	79.17%	95	100.00%	95	100.00%	0	0%
Supervisory	1	0.83%	1	100.00%	1	100.00%	0	0%
Totals	120	100%	120	100.00%	120	100.00%	0	0%
Certification								
Company: Cal Building Systems			Bu	ilding: NML	JSD – Wal	dorf Elemen	itary Scho	oll
Inspector: Andrew Partida			Co	ntact: Tim	Waller			
Signadi			C :-	an a di				
Signed:	Signed:							

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Waldorf Elementary Schooll

Control Panel: 1 - Silent Knight IFP-2000ECS

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	High School Admin	Tested	4:48:11 PM	09/18/2019
Battery	Building A Nurses Office	Tested	6:30:07 PM	09/18/2019
Battery	Building H Storage Closet	Tested	5:50:39 PM	09/18/2019
Battery	Building H Storage Closet	Tested	5:51:03 PM	09/18/2019
Battery	Building H Storage Closet	Tested	5:51:09 PM	09/18/2019
Battery	Building H Storage Closet	Tested	5:51:14 PM	09/18/2019
Battery	Building J Classroom 8	Tested	4:20:14 PM	09/18/2019
Battery	Building J Classroom 8	Tested	4:21:16 PM	09/18/2019
Battery	Building J Classroom 8	Tested	4:21:22 PM	09/18/2019
Battery	Building J Classroom 8	Tested	4:21:28 PM	09/18/2019
Battery	Portable N Administrative Offices	Tested	3:49:37 PM	09/18/2019
Battery	Portable N Administrative Offices	Tested	3:49:53 PM	09/18/2019
Battery	Portable N Administrative Offices	Tested	3:49:59 PM	09/18/2019
Battery	Portable N Administrative Offices	Tested	3:53:41 PM	09/18/2019
Control Panel	Meadows Hall Closet	Tested	4:56:10 PM	09/18/2019
Power Supply	Building A Nurses Office	Tested	6:29:26 PM	09/18/2019
Power Supply	Building H Storage Closet	Tested	5:49:32 PM	09/18/2019
Power Supply	Building H Storage Closet	Tested	5:50:03 PM	09/18/2019
Power Supply	Building J Classroom 8	Tested	4:22:13 PM	09/18/2019
Power Supply	Building J Classroom 8	Tested	4:22:35 PM	09/18/2019
Power Supply	Portable N Administrative Offices	Tested	3:50:56 PM	09/18/2019
Power Supply	Portable N Administrative Offices	Tested	3:51:11 PM	09/18/2019
Initiating				
Pull Station	Bldg. A Admin Lounge	Tested	3:30:19 PM	09/16/2019
Pull Station	Brendan Mann Science Lab Entrance	Tested	5:04:25 PM	09/18/2019
Pull Station	Brendan Mann Science Lab Entrance	Tested	5:06:02 PM	09/18/2019
Pull Station	Sun Studio	Tested	5:02:53 PM	09/18/2019
Pull Station	The Juniper Room Entrance	Tested	5:08:09 PM	09/18/2019
Pull Station	The Linden Room Entrance	Tested	5:10:11 PM	09/18/2019
Pull Station	The Sequoia Room Entrance	Tested	5:11:42 PM	09/18/2019
Smoke Detector	East Bldg. A Exit	Tested	3:41:42 PM	09/16/2019
Smoke Detector	Bldg. A Admin Lounge	Tested	3:32:12 PM	09/16/2019
Smoke Detector	Bldg. A Attendance Office	Tested	3:35:31 PM	09/16/2019
Smoke Detector	Bldg. A Attendance Office	Tested	3:36:11 PM	09/16/2019
Smoke Detector	Bldg. A Conference Rm.	Tested	3:53:18 PM	09/16/2019
Smoke Detector	Bldg. A Entrance	Tested	3:49:03 PM	09/16/2019
Smoke Detector	Bldg. A Nurse Office	Tested	3:43:16 PM	09/16/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Bldg. A Nurse Office RR	Tested	3:45:17 PM	09/16/2019
Smoke Detector	Bldg. A Office 104	Tested	3:33:41 PM	09/16/2019
Smoke Detector	Bldg. A Office 104	Tested	3:36:40 PM	09/16/2019
Smoke Detector	Bldg. A Office by Reception	Tested	3:53:57 PM	09/16/2019
Smoke Detector	Bldg. A Reception	Tested	3:48:04 PM	09/16/2019
Smoke Detector	Bldg. A RR	Tested	3:37:49 PM	09/16/2019
Smoke Detector	Bldg. A Vault Rm. 112	Tested	3:50:03 PM	09/16/2019
Smoke Detector	Bldg. A Vault Rm. 112	Tested	3:52:21 PM	09/16/2019
Smoke Detector	Brendan Mann Science Lab	Tested	5:05:27 PM	09/18/2019
Smoke Detector	Building A Near Water heater Room	Tested	6:27:27 PM	09/18/2019
Smoke Detector	Building A Water heater Room	Tested	6:26:20 PM	09/18/2019
Smoke Detector	Building B Art Room	Tested	6:07:53 PM	09/18/2019
Smoke Detector	Building B Art Room	Tested	6:09:04 PM	09/18/2019
Smoke Detector	Building B Closet Near Custodian Room	Tested	5:57:05 PM	09/18/2019
Smoke Detector	Building B Custodian Room	Tested	5:56:25 PM	09/18/2019
Smoke Detector	Building B MPR	Tested	6:03:06 PM	09/18/2019
Smoke Detector	Building B MPR	Tested	6:03:25 PM	09/18/2019
Smoke Detector	Building B MPR	Tested	6:03:33 PM	09/18/2019
Smoke Detector	Building B MPR	Tested	6:03:43 PM	09/18/2019
Smoke Detector	Building B MPR Corridor	Tested	5:58:31 PM	09/18/2019
Smoke Detector	Building B MPR Janitors closet in Corridor	Tested	6:00:17 PM	09/18/2019
Smoke Detector	Building B MPR Restroom in Corridor	Tested	5:59:24 PM	09/18/2019
Smoke Detector	Building C Closet Next to Main Electrical	Tested	5:54:44 PM	09/18/2019
Smoke Detector	Building C Main Electrical	Tested/Cleaned	5:53:14 PM	09/18/2019
Smoke Detector	Building D K1	Tested	5:30:43 PM	09/18/2019
Smoke Detector	Building D K1	Tested	5:31:29 PM	09/18/2019
Smoke Detector	Building D K1 Restroom Area	Tested	5:32:31 PM	09/18/2019
Smoke Detector	Building D Teachers Storage Between K1 & K2	Tested	5:33:37 PM	09/18/2019
Smoke Detector	Building D Restroom Teachers Storage Between K1 & K2	Tested	5:34:35 PM	09/18/2019
Smoke Detector	Building E Classroom	Tested	5:20:34 PM	09/18/2019
Smoke Detector	Building E Classroom	Tested	5:21:25 PM	09/18/2019
Smoke Detector	Building E Classroom 1	Tested	5:22:31 PM	09/18/2019
Smoke Detector	Building E Classroom 1	Tested	5:22:59 PM	09/18/2019
Smoke Detector	Building E Classroom N2	Tested	5:25:12 PM	09/18/2019
Smoke Detector	Building E Classroom N2	Tested	5:25:24 PM	09/18/2019
Smoke Detector	Building E Classroom N2 Restroom	Tested	5:26:52 PM	09/18/2019
Smoke Detector	Building E Rear Storage Closet	Tested	5:16:41 PM	09/18/2019
Smoke Detector	Building E Rear Storage Closet	Tested	5:17:11 PM	09/18/2019
Smoke Detector	Building E Rear Storage Closet	Tested	5:18:53 PM	09/18/2019
Smoke Detector	Building E Rear Storage Closet	Tested	5:18:57 PM	09/18/2019
Smoke Detector	Building F WoodWork	Tested	5:40:18 PM	09/18/2019
Smoke Detector	Building F WoodWork	Tested	5:41:37 PM	09/18/2019
Smoke Detector	Building G Handwork	Tested	5:42:22 PM	09/18/2019
Smoke Detector	Building G Handwork	Tested	5:42:39 PM	09/18/2019
Smoke Detector	Building G Handwork Storage	Tested	5:43:54 PM	09/18/2019
Smoke Detector	Building H Laundry Room	Tested/Cleaned	5:48:23 PM	09/18/2019
Smoke Detector	Building I Kitchen Area	Tested	4:29:21 PM	09/18/2019
Smoke Detector	Building I Library Area	Tested	4:30:29 PM	09/18/2019
Smoke Detector	Building I Library Area	Tested	4:30:58 PM	09/18/2019

Device Type	Location	Service	Time	Date	
Passed					
Smoke Detector	Building I Office	Tested	4:32:24 PM	09/18/2019	
Smoke Detector	Building I	Tested	4:28:20 PM	09/18/2019	
Smoke Detector	Building I	Tested	4:29:55 PM	09/18/2019	
Smoke Detector	Building J Classroom 4	Tested	4:16:38 PM	09/18/2019	
Smoke Detector	Building J Classroom 4	Tested	4:17:31 PM	09/18/2019	
Smoke Detector	Building J Janitors Closet Near Girls Restroom	Tested	4:24:31 PM	09/18/2019	
Smoke Detector	Building J Storage	Tested	4:14:26 PM	09/18/2019	
Smoke Detector	Building K Classroom 6	Tested	4:11:54 PM	09/18/2019	
Smoke Detector	Building K Classroom 6	Tested	4:12:05 PM	09/18/2019	
Smoke Detector	Building K Classroom 7	Tested	4:08:08 PM	09/18/2019	
Smoke Detector	Building K Classroom 7	Tested	4:10:50 PM	09/18/2019	
Smoke Detector	Company of Angels Portable	Tested	4:00:18 PM	09/18/2019	
Smoke Detector	Company of Angels Portable	Tested	4:01:54 PM	09/18/2019	
Smoke Detector	High School Admin	Tested	4:47:54 PM	09/18/2019	
Smoke Detector	High School Admin Corridor	Tested	4:52:26 PM	09/18/2019	
Smoke Detector	High School Admin Lounge Area	Tested	4:49:32 PM	09/18/2019	
Smoke Detector	High School Admin Office	Tested	4:49:03 PM	09/18/2019	
Smoke Detector	High School Admin Office Near Work Room	Tested	4:51:57 PM	09/18/2019	
Smoke Detector	High School Admin Work Room	Tested	4:50:11 PM	09/18/2019	
Smoke Detector	Meadows Hall FACP Room	Tested	4:58:15 PM	09/18/2019	
Smoke Detector	Portable L	Tested	3:56:49 PM	09/18/2019	
Smoke Detector	Portable N Administrative Offices	Tested	3:53:28 PM	09/18/2019	
Smoke Detector	Portable N Administrative Offices	Tested	3:53:34 PM	09/18/2019	
Smoke Detector	Portable N Administrative Offices	Tested	3:54:25 PM	09/18/2019	
Smoke Detector	Sun Studio	Tested	5:00:36 PM	09/18/2019	
Smoke Detector	Sun Studio	Tested	5:01:17 PM	09/18/2019	
Smoke Detector	Sun Studio	Tested	5:01:57 PM	09/18/2019	
Smoke Detector	The Juniper Room	Tested	5:08:41 PM	09/18/2019	
Smoke Detector	The Linden Room	Tested	5:10:35 PM	09/18/2019	
Smoke Detector	The Oak Room	Tested	6:21:05 PM	09/18/2019	
Smoke Detector	The Oak Room	Tested	6:21:28 PM	09/18/2019	
Smoke Detector	The Sequoia Room	Tested	5:12:40 PM	09/18/2019	
Supervisory					
Tamper Switch	Behind Meadows Hall P.I.V.	Tested	6:35:36 PM	09/18/2019	

Building: NMUSD - Waldorf Elementary Schooll

Control Panel: 2

Device Type	Location	Service	Time	Date
	Passe	d		
Control				
Battery	Meadows Hall Closet FACP	Tested	4:57:24 PM	09/18/2019
Battery	Meadows Hall Closet FACP	Tested	4:57:51 PM	09/18/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Waldorf Elementary Schooll

The Service Summary section provides an overview of the services performed in this report.

	T	
Device Type	Service	Quantity
	Passed	
Annunciator	Tested	1
Battery	Tested	15
Control Panel	Tested	1
Power Supply	Tested	7
Pull Station	Tested	7
Smoke Detector	Tested	86
Smoke Detector	Tested/Cleaned	2
Tamper Switch	Tested	1
Total		120

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Waldorf Elementary Schooll

Control Panel: 1 - Silent Knight IFP-2000ECS

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type		Category		% of Inventory	Quantity
Pull Station		Initiating		5.83%	7
Smoke Detector		Initiating		73.33%	88
Battery		Control		12.50%	15
Power Supply		Control		5.83%	7
Annunciator		Control		0.83%	1
Control Panel		Control		0.83%	1
Tamper Switch		Supervisory	_	0.83%	1
	Qt				
Туре	y	Model #	Descript	ion	Install Date
		New	, (under 9	00 days)	
Battery	4	12V 7AH		•	09/18/2019
Power Supply	1	RPS-100"			09/18/2019
Power Supply	1	RPS-1000			09/18/2019
Smoke Detector	1				09/18/2019
Smoke Detector	13	IDP-PHOTO			09/18/2019
Potter					
Tamper Switch	1				09/16/2019
Silent Knight					
Annunciator	1	RA-2000			09/16/2019
Battery	1	IDP-Photo			09/16/2019
Control Panel	1	IFP-2000ECS			09/16/2019
Power Supply	1	IDP-Photo			09/16/2019
Pull Station	1	IDP-PULL-DA	Keyed		09/16/2019
Pull Station	6	SD500-PSDA			09/16/2019
Smoke Detector	60	IDP-Photo			09/16/2019
Smoke Detector	14	SD505-APS			09/16/2019
		In Servie	ce - 1 Yea	er to 2 Years	
Silent Knight					
Battery	8	12V 7AH			02/19/2018
Power Supply	1	ECS-50W			02/19/2018
Power Supply	3	RPS-1000			02/19/2018
Building: NMUSI) - Wa	aldorf Elemen	tary		Control Panel:
Schooll					Control 1 uncl.

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Туре	Qt V	Model #	Description	Install Date			
New (under 90 days)							
Silent Knight	Silent Knight						
Battery	2	12V 18AH		09/16/2019			

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Waldorf Elementary Schooll 2350 Canyon Drive Costa Mesa, CA 92627

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Sep 16, 2019

Building: NMUSD - Waldorf Elementary Schooll Contact: Tim Waller Title: Maintenance & Operations Manager Company: Cal Building Systems Contact: Chris Ferreira Title: Service

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD – Waldorf Elementary Schooll	Contact: Tim W	/aller
Address: 2350 Canyon Drive	Phone: 714-23	1–0363
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92627	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Chri	s Ferreira
Address: 2903 Saturn Street	Phone: 714–99	93-9650
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: chrisfer	reira@calbuildingsystems.com
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Category	Tota	ltems	Serv	viced	Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Initiating	16	100.00%	16	100.00%	16	100.00%	0	0%
Totals	16	100%	16	100.00%	16	100.00%	0	0%
Certification								
Company: Cal Building Systems			Bu	ilding: NMU	ISD – Wale	dorf Elemer	itary Scho	oll
Inspector: Chris Ferreira			Co	ntact: Tim V	Waller			
-								

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Waldorf Elementary Schooll

Control Panel: 1

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passe			
Initiating				
Pull Station	Bldg. A Admin Lounge	Tested	3:30:19 PM	09/16/2019
Smoke Detector	East Bldg. A Exit	Tested	3:41:42 PM	09/16/2019
Smoke Detector	Bldg. A Admin Lounge	Tested	3:32:12 PM	09/16/2019
Smoke Detector	Bldg. A Attendance Office	Tested	3:35:31 PM	09/16/2019
Smoke Detector	Bldg. A Attendance Office	Tested	3:36:11 PM	09/16/2019
Smoke Detector	Bldg. A Conference Rm.	Tested	3:53:18 PM	09/16/2019
Smoke Detector	Bldg. A Entrance	Tested	3:49:03 PM	09/16/2019
Smoke Detector	Bldg. A Nurse Office	Tested	3:43:16 PM	09/16/2019
Smoke Detector	Bldg. A Nurse Office RR	Tested	3:45:17 PM	09/16/2019
Smoke Detector	Bldg. A Office 104	Tested	3:33:41 PM	09/16/2019
Smoke Detector	Bldg. A Office 104	Tested	3:36:40 PM	09/16/2019
Smoke Detector	Bldg. A Office by Reception	Tested	3:53:57 PM	09/16/2019
Smoke Detector	Bldg. A Reception	Tested	3:48:04 PM	09/16/2019
Smoke Detector	Bldg. A RR	Tested	3:37:49 PM	09/16/2019
Smoke Detector	Bldg. A Vault Rm. 112	Tested	3:50:03 PM	09/16/2019
Smoke Detector	Bldg. A Vault Rm. 112	Tested	3:52:21 PM	09/16/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Waldorf Elementary Schooll

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity				
Passed						
Pull Station	Tested	1				
Smoke Detector	Tested	15				
Total		16				

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Waldorf Elementary Schooll

Control Panel: 1

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type		Category		% of Inventory	Quantity
Pull Station		Initiating		6.25%	1
Smoke Detector		Initiating		93.75%	15
(Qt				
Туре	y	Model #	Desc	ription	Install Date
		New	(unde	e r 90 day s)	
Silent Knight					
Pull Station	1	IDP-PULL-DA	Keyed		09/16/2019
Smoke Detector	15	IDP-PHOTO			09/16/2019

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Waldorf Elementary Schooll 2350 Canyon Drive Costa Mesa, CA 92627

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Sep 18, 2019

Building: NMUSD - Waldorf Elementary Schooll Contact: Tim Waller Title: Maintenance & Operations Manager Company: Cal Building Systems Contact: Phillip Burton Title: Inspector

Executive Summary Generated by: BuildingReports.com

Building Information				
Building: NMUSD – Waldorf Elementary Schooll	Contact: Tim Wa	aller		
Address: 2350 Canyon Drive	Phone: 714-231	-0363		
Address:	Fax:			
City/State/Zip: Costa Mesa, CA 92627	Mobile:			
Country: United States of America	Country: United States of America Email:			
Inspection Performed By				
Company: Cal Building Systems	Inspector: Phillip	o Burton		
Address: 2903 Saturn Street	Phone: 714-345	5-1252		
Address: Suite F	Fax:			
City/State/Zip: Brea, CA 92821	Mobile:			
Country: United States of America	Email: phillipbu	rton@calbuildingsystems.com		
Monitoring				
Company:	Phone:	Account #:		
Central Station Signal Verification				
Туре:	Mfg:	Model #:		
Test Time/Date:	Restore Time			

Total Items Serviced Passed Failed/Other								
Category	Qty	%		%	Pa: Qty	%		%
Initiating	<u> </u>	100.00%	Qty 91	100.00%	<u> </u>	100.00%	Qty 0	7 0 0%
Totals	91	100.00%	91 91	100.00%	91 91	100.00%	0	0%
Certification		<u> </u>		<u> </u>		<u> </u>		
Company: Cal Building Systems			Bu	ilding: NMU	ISD – Wal	dorf Elemen	itary Scho	oll
Inspector: Phillip Burton			Co	ontact: Tim V	Waller			
Signed:			Sic	gned:				

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Waldorf Elementary Schooll

Control Panel: 1

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed	!		
Initiating				
Heat Detector	Band Storage B109	Tested	10:35:20 PM	09/18/2019
Heat Detector	Classroom G101	Tested	10:45:31 PM	09/18/2019
Heat Detector	Classroom G101	Tested	10:45:56 PM	09/18/2019
Heat Detector	Daycare I101	Tested	10:38:40 PM	09/18/2019
Heat Detector	Daycare I101	Tested	10:39:40 PM	09/18/2019
Heat Detector	Daycare I101	Tested	10:48:06 PM	09/18/2019
Heat Detector	Daycare Kitchen 1102	Tested	10:43:54 PM	09/18/2019
Heat Detector	Daycare office Rm I106	Tested	10:40:59 PM	09/18/2019
Heat Detector	Daycare office Rm I106	Tested	10:42:30 PM	09/18/2019
Heat Detector	Daycare office Rm 1108	Tested	10:42:59 PM	09/18/2019
Heat Detector	Daycare office Rm 1109	Tested	10:43:17 PM	09/18/2019
Heat Detector	Daycare office Rm I110	Tested	10:43:28 PM	09/18/2019
Heat Detector	Daycare Rm 1103	Tested	10:44:22 PM	09/18/2019
Heat Detector	Daycare Rm 1104	Tested	10:44:43 PM	09/18/2019
Heat Detector	Eurytmics Hall	Tested	10:36:46 PM	09/18/2019
Heat Detector	Eurytmics Hall	Tested	10:37:09 PM	09/18/2019
Heat Detector	Eurytmics Hall	Tested	10:37:16 PM	09/18/2019
Heat Detector	Eurytmics Hall	Tested	10:37:26 PM	09/18/2019
Heat Detector	Eurytmics Hall	Tested	10:49:07 PM	09/18/2019
Heat Detector	Eurytmics Hall RR Hallway	Tested	10:35:55 PM	09/18/2019
Heat Detector	MPR STAGE Under Stage	Tested	10:34:20 PM	09/18/2019
Heat Detector	Preschool L-101	Tested	10:46:13 PM	09/18/2019
Heat Detector	Storage G102	Tested	10:44:59 PM	09/18/2019
Heat Detector	Storage G102	Tested	10:45:21 PM	09/18/2019
Heat Detector	Storage Rm 1105	Tested	10:40:09 PM	09/18/2019
Heat Detector	Storage Rm L102	Tested	10:46:40 PM	09/18/2019
Heat Detector	Storage Rm L103	Tested	10:47:12 PM	09/18/2019
Pull Station	Bldg B Art Room Side Storage	Tested	6:21:14 PM	09/18/2019
Pull Station	Bldg B MPR	Tested	6:02:35 PM	09/18/2019
Pull Station	Bldg B MPR	Tested	6:02:48 PM	09/18/2019
Pull Station	Bldg B MPR Corridor	Tested	5:59:45 PM	09/18/2019
Pull Station	Bldg B MPR Side Storage	Tested	6:05:07 PM	09/18/2019
Pull Station	Bldg B MPR Stage	Tested	6:04:01 PM	09/18/2019
Pull Station	Bldg. A Admin Lounge	Tested	3:30:19 PM	09/16/2019
Pull Station	High School Admin Front door	Tested	4:47:35 PM	09/18/2019
Pull Station	High School Admin Workroom	Tested	4:51:49 PM	09/18/2019
Pull Station	Meadows Hall	Tested	4:55:27 PM	09/18/2019
Pull Station	Meadows Hall	Tested	4:56:07 PM	09/18/2019

Cal Building Systems

Device Type	Location	Service	Time	Date
	Passed			
Pull Station	Meadows Hall	Tested	4:56:48 PM	09/18/2019
Smoke Detector	East Bldg. A Exit	Tested	3:41:42 PM	09/16/2019
Smoke Detector	Admin Bldg Side Storage next to Faculty Door	Tested/Cleaned	6:26:37 PM	09/18/2019
Smoke Detector	Bldg B Art Room Side Storage	Tested/Cleaned	6:08:50 PM	09/18/2019
Smoke Detector	Bldg D K2	Tested/Cleaned	5:32:31 PM	09/18/2019
Smoke Detector	Bldg D K2	Tested/Cleaned	5:33:04 PM	09/18/2019
Smoke Detector	Bldg D K2	Tested/Cleaned	5:35:24 PM	09/18/2019
Smoke Detector	Bldg D K2 RR	Tested/Cleaned	5:35:47 PM	09/18/2019
Smoke Detector	Bldg D K2 Side Storage	Tested/Cleaned	5:36:55 PM	09/18/2019
Smoke Detector	Bldg H Electrical	Tested/Cleaned	5:46:23 PM	09/18/2019
Smoke Detector	Bldg I Aftercare	Tested/Cleaned	4:28:46 PM	09/18/2019
Smoke Detector	Bldg I Aftercare back office	Tested/Cleaned	4:31:03 PM	09/18/2019
Smoke Detector	Bldg I Aftercare Front office	Tested/Cleaned	4:32:49 PM	09/18/2019
Smoke Detector	Bldg J Storage Closet next to Boys RR	Tested/Cleaned	4:25:19 PM	09/18/2019
Smoke Detector	Bldg J	Tested/Cleaned	4:17:33 PM	09/18/2019
Smoke Detector	Bldg K Rm 5	Tested/Cleaned	4:13:15 PM	09/18/2019
Smoke Detector	Bldg. A Admin Lounge	Tested	3:32:12 PM	09/16/2019
Smoke Detector	Bldg. A Attendance Office	Tested	3:35:31 PM	09/16/2019
Smoke Detector	Bldg. A Attendance Office	Tested	3:36:11 PM	09/16/2019
Smoke Detector	Bldg. A Conference Rm.	Tested	3:53:18 PM	09/16/2019
Smoke Detector	Bldg. A Entrance	Tested	3:49:03 PM	09/16/2019
Smoke Detector	Bldg. A Nurse Office	Tested	3:43:16 PM	09/16/2019
Smoke Detector	Bldg. A Nurse Office RR	Tested	3:45:17 PM	09/16/2019
Smoke Detector	Bldg. A Office 104	Tested	3:33:41 PM	09/16/2019
Smoke Detector	Bldg. A Office 104	Tested	3:36:40 PM	09/16/2019
Smoke Detector	Bldg. A Office by Reception	Tested	3:53:57 PM	09/16/2019
Smoke Detector	Bldg. A Reception	Tested	3:48:04 PM	09/16/2019
Smoke Detector	Bldg. A RR	Tested	3:37:49 PM	09/16/2019
Smoke Detector	Bldg. A Vault Rm. 112	Tested	3:50:03 PM	09/16/2019
Smoke Detector	Bldg. A Vault Rm. 112	Tested	3:52:21 PM	09/16/2019
Smoke Detector	Bldg. N Admin Corner Closed office Attendance Office	Tested/Cleaned	3:54:11 PM	09/18/2019
Smoke Detector	Bldg. N Admin Corner open office Attendance Office	Tested/Cleaned	3:53:09 PM	09/18/2019
Smoke Detector	Bldg. N Admin Corridor Attendance Office	Tested/Cleaned	3:49:20 PM	09/18/2019
Smoke Detector	Bldg. N Admin office Attendance Office	Tested/Cleaned	3:47:25 PM	09/18/2019
Smoke Detector	Brenden Mann Science Lab	Tested/Cleaned	5:04:44 PM	09/18/2019
Smoke Detector	Brenden Mann Science Lab	Tested/Cleaned	5:05:55 PM	09/18/2019
Smoke Detector	Brenden Mann Science Lab	Tested/Cleaned	5:08:10 PM	09/18/2019
Smoke Detector	Company of Angels Portable next to Portable L	Tested/Cleaned	4:01:12 PM	09/18/2019
Smoke Detector	Company of Angels Portable next to Portable L (Storage)	Tested/Cleaned	4:03:22 PM	09/18/2019
Smoke Detector	HS Juniper Room	Tested/Cleaned	5:08:20 PM	09/18/2019
Smoke Detector	HS Linden Room	Tested/Cleaned	5:10:03 PM	09/18/2019
Smoke Detector	HS Sequoia Room	Tested/Cleaned	5:12:04 PM	09/18/2019
Smoke Detector	Kindergarten N1	Tested/Cleaned	5:17:54 PM	09/18/2019
Smoke Detector	Kindergarten N1	Tested/Cleaned	5:27:37 PM	09/18/2019
Smoke Detector	Kindergarten N1 RR	Tested/Cleaned	5:28:03 PM	09/18/2019
Smoke Detector	Kindergarten N1 Side Storage Closet	Tested/Cleaned	5:29:29 PM	09/18/2019
Smoke Detector	Meadows Hall High Ceiling	Tested/Cleaned	4:57:48 PM	09/18/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Meadows Hall High Ceiling	Tested/Cleaned	4:59:17 PM	09/18/2019
Smoke Detector	Meadows Hall High Ceiling	Tested/Cleaned	4:59:36 PM	09/18/2019
Smoke Detector	Meadows Hall High Ceiling	Tested/Cleaned	4:59:54 PM	09/18/2019
Smoke Detector	Portable L Right back workstation	Tested/Cleaned	3:56:39 PM	09/18/2019
Smoke Detector	Portable L	Tested/Cleaned	3:57:48 PM	09/18/2019
Smoke Detector	Sun Studio	Tested/Cleaned	5:02:21 PM	09/18/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Waldorf Elementary Schooll

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Heat Detector	Tested	27
Pull Station	Tested	12
Smoke Detector	Tested	15
Smoke Detector	Tested/Cleaned	37
Total		91

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Waldorf Elementary Schooll

Control Panel: 1

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type		Category	% of Inventory	Quantity		
Pull Station		Initiating	13.19%	12		
Smoke Detector		Initiating	57.14%	52		
Heat Detector		Initiating	29.67%	27		
	Qt					
Туре	У	Model # [Description	Install Date		
New (under 90 days)						
Silent Knight						
Heat Detector	27	SD505-AHS		09/16/2019		
Pull Station	5	IDP-Pull-DA		09/16/2019		
Pull Station	1	IDP-PULL-DA k	Keyed	09/16/2019		
Pull Station	5	SD500-PSDA		09/16/2019		
Pull Station	1	SD500-PSDA		09/16/2019		
Smoke Detector	41	IDP-Photo		09/16/2019		
Smoke Detector	11	SD505-APS		09/16/2019		

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Whittier Elementary School 1800 Whittier Avenue Costa Mesa, CA 92627

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Sep 20, 2019

> Building: NMUSD - Whittier Elementary School Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Michael Cannon Title: Service Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
U	6 • • - • •	
Building: NMUSD – Whittier Elementary School	Contact: Tim W	
Address: 1800 Whittier Avenue	Phone: 714-23	1-0363
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92627	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Mich	ael Cannon
Address: 2903 Saturn Street	Phone: 714–71	5-1223
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: mcannoi	n@calbuildingsystems.com
System Control Unit		
Manufacturer: Simplex	Inspection Date	e: 09/12/2019 IDC Style:
Model Number: 4100U	Install Date: 09	/12/2019 SLC Style:
Software Version:	Version Date: 0	9/12/2019 NAC Style:
Location: Bldg. 1 Nurse MDF Rm.	Current Protect	ion:
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
	Tota	Items	Ser	viced	Passed		Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.46%	1	100.00%	1	100.00%	0	0%
Control	21	9.68%	21	100.00%	21	100.00%	0	0%
Initiating	195	89.86%	193	98.97%	193	100.00%	0	0%
Totals	217	100%	215	99.08%	215	100.00%	0	0%
Certification								
Company: Cal Building Systems			Bu	uilding: NML	ISD – Wh	ittier Elemer	ntary Scho	lool
Inspector: Michael Cannon			C	ontact: Tim V	Waller			
Mar Com								
Signed: Sep 25, 2019 6:05:31	PM		Si	gned:				

Notes & Recommendations

Generated by: BuildingReports.com

Building: NMUSD - Whittier Elementary School

Control Panel: 1 - Simplex 4100U

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

ScanID	Note	Device Type	Location	Comment	
			Initiating		
58092349	1	Smoke Detector	Portable 45		
Could	not test	because the device head is missir	ng; also does not show as a trouble on the FACP.		
58092350	2	Smoke Detector	Portable 45		
Could	Could not test because the device head is missing; also does not show as a trouble on the FACP.				

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Whittier Elementary School

Control Panel: 1 - Simplex 4100U

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Battery	Bldg. 3 IDK Rm. Behind Classroom 42	Tested	4:22:48 PM	09/20/2019
Battery	Bldg. 3 IDK Rm. Behind Classroom 42	Tested	4:23:34 PM	09/20/2019
Battery	Bldg. 7 IDF Rm. Behind Classroom 13	Tested	5:36:26 PM	09/20/2019
Battery	Bldg. 7 IDF Rm. Behind Classroom 13	Tested	5:37:00 PM	09/20/2019
Battery	Bldg. 9 Classroom 4 And 5 Storage Room	Tested	5:13:22 PM	09/20/2019
Battery	Bldg. 9 Classroom 4 And 5 Storage Room	Tested	5:14:03 PM	09/20/2019
Battery	Bldg. 1 Nurse MDF Rm.	Tested	3:29:36 PM	09/12/2019
Battery	Bldg. 1 Nurse MDF Rm.	Tested	3:32:48 PM	09/12/2019
Battery	Bldg. 1 Nurse MDF Rm.	Tested	3:34:01 PM	09/12/2019
Battery	Bldg. 1 Nurse MDF Rm.	Tested	3:35:00 PM	09/12/2019
Battery	Bldg. 3 Electrical Rm.	Tested	4:33:40 PM	09/12/2019
Battery	Bldg. 3 Electrical Rm.	Tested	4:34:02 PM	09/12/2019
Battery	Portable 1	Tested	4:45:43 PM	09/20/2019
Battery	Portable 1	Tested	4:45:51 PM	09/20/2019
Control Panel	Bldg. 1 Nurse MDF Rm.	Tested	3:27:06 PM	09/12/2019
Power Supply	Bldg. 3 IDK Rm. Behind Classroom 42	Tested	4:22:40 PM	09/20/2019
Power Supply	Bldg. 7 IDF Rm. Behind Classroom 13	Tested	5:36:02 PM	09/20/2019
Power Supply	Bldg. 1 Nurse MDF Rm.	Tested	3:36:16 PM	09/12/2019
Power Supply	Bldg. 3 Electrical Rm.	Tested	4:32:48 PM	09/12/2019
Power Supply	Classroom 4 And 5 Storage Room	Inspected	5:14:58 PM	09/20/2019
Power Supply	Portable 1	Inspected	4:44:31 PM	09/20/2019
Initiating				
Heat Detector	Bldg. 1 Faculty Lounge Restroom	Tested	4:07:59 PM	09/20/2019
Heat Detector	Bldg. 1 Nurse's Restroom	Tested	4:08:49 PM	09/20/2019
Heat Detector	Bldg. 2 MPR Attic	Tested	4:14:06 PM	09/20/2019
Heat Detector	Bldg. 2 MPR Attic	Tested	4:14:24 PM	09/20/2019
Heat Detector	Bldg. 2 MPR Kitchen	Tested	4:13:47 PM	09/20/2019
Heat Detector	Bldg. 3 IDF Room	Tested	4:12:20 PM	09/20/2019
Heat Detector	Bldg. 5 Electrical Room	Tested	4:13:34 PM	09/20/2019
Heat Detector	Bldg. 5 IDF/Electrical Room	Tested	4:12:57 PM	09/20/2019
Heat Detector	Bldg. 6 Handicap Girl's Restroom	Tested	4:09:14 PM	09/20/2019
Heat Detector	Bldg. 7 Electrical Room	Tested	4:14:29 PM	09/20/2019
Heat Detector	Bldg. 8 Handicap Boy's Restroom	Tested	4:09:44 PM	09/20/2019
Heat Detector	Bldg. 9 Faculty Restroom	Tested	4:06:26 PM	09/20/2019
Heat Detector	Bldg. 9 Heater Room 4	Tested	4:06:45 PM	09/20/2019
Heat Detector	Bldg. 9 Heater Room 5	Tested	4:07:18 PM	09/20/2019
Heat Detector	Bldg. 9 Room 4 Restroom	Tested	4:07:40 PM	09/20/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	Bldg. 9 Room 5 Restroom	Tested	4:05:20 PM	09/20/2019
Heat Detector	Portable 1	Tested	4:14:45 PM	09/20/2019
Heat Detector	Portable 1	Tested	4:15:01 PM	09/20/2019
Heat Detector	Portable 10	Tested	4:21:20 PM	09/20/2019
Heat Detector	Portable 14	Tested	4:17:24 PM	09/20/2019
Heat Detector	Portable 14	Tested	4:17:35 PM	09/20/2019
Heat Detector	Portable 15	Tested	4:17:40 PM	09/20/2019
Heat Detector	Portable 15	Tested	4:18:06 PM	09/20/2019
Heat Detector	Portable 16	Tested	4:18:16 PM	09/20/2019
Heat Detector	Portable 16	Tested	4:18:24 PM	09/20/2019
Heat Detector	Portable 17	Tested	4:18:30 PM	09/20/2019
Heat Detector	Portable 17	Tested	4:18:51 PM	09/20/2019
Heat Detector	Portable 18	Tested	4:20:09 PM	09/20/2019
Heat Detector	Portable 18	Tested	4:20:21 PM	09/20/2019
Heat Detector	Portable 2	Tested	4:16:36 PM	09/20/2019
Heat Detector	Portable 2	Tested	4:16:47 PM	09/20/2019
Heat Detector	Portable 21	Tested	4:24:25 PM	09/20/2019
Heat Detector	Portable 22	Tested	4:24:36 PM	09/20/2019
Heat Detector	Portable 23	Tested	4:24:47 PM	09/20/2019
Heat Detector	Portable 24	Tested	4:25:35 PM	09/20/2019
Heat Detector	Portable 25	Tested	4:25:27 PM	09/20/2019
Heat Detector	Portable 26	Tested	4:25:19 PM	09/20/2019
Heat Detector	Portable 27	Tested	4:25:12 PM	09/20/2019
Heat Detector	Portable 28	Tested	4:24:15 PM	09/20/2019
Heat Detector	Portable 29	Tested	4:24:04 PM	09/20/2019
Heat Detector	Portable 3	Tested	4:16:54 PM	09/20/2019
Heat Detector	Portable 3	Tested	4:17:05 PM	09/20/2019
Heat Detector	Portable 30	Tested	4:23:52 PM	09/20/2019
Heat Detector	Portable 31 Library	Tested	4:22:44 PM	09/20/2019
Heat Detector	Portable 31 Library	Tested	4:22:58 PM	09/20/2019
Heat Detector	Portable 31 Library	Tested	4:23:03 PM	09/20/2019
Heat Detector	Portable 31 Library	Tested	4:23:09 PM	09/20/2019
Heat Detector	Portable 32	Tested	4:22:21 PM	09/20/2019
Heat Detector	Portable 33	Tested	4:22:35 PM	09/20/2019
Heat Detector	Portable 6	Tested	4:20:27 PM	09/20/2019
Heat Detector	Portable 7	Tested	4:20:35 PM	09/20/2019
Heat Detector	Portable 8	Tested	4:20:44 PM	09/20/2019
Heat Detector	Portable 8A	Tested	4:20:55 PM	09/20/2019
Heat Detector	Portable 9	Tested	4:21:10 PM	09/20/2019
Heat Detector	Portable J Restroom	Tested	4:23:16 PM	09/20/2019
Heat Detector	Portable K Restroom	Tested	4:23:32 PM	09/20/2019
Heat Detector	Portable L Restroom	Tested	4:23:42 PM	09/20/2019
Pull Station	East Bldg. 2 MPR Exit	Tested	4:03:31 PM	09/12/2019
Pull Station	North Bldg. 2 MPR Exit	Tested	4:19:05 PM	09/12/2019
Pull Station	South Bldg. 2 MPR Exit	Tested	4:16:07 PM	09/12/2019
Pull Station	Bldg. 1 Admin Entrance	Tested	3:42:23 PM	09/12/2019
Smoke Detector	Bldg. 3 IDF Rm. Behind Classroom 42	Tested	4:20:07 PM	09/20/2019
Smoke Detector	Bldg. 6 Boys RR by Classroom 38	Tested	5:06:45 PM	09/20/2019
Smoke Detector	Bldg. 6 Girls RR by Classroom 38	Tested	5:06:39 PM	09/20/2019
Smoke Detector	Bldg. 6 Staff RR Behind Classroom 38	Tested	5:07:50 PM	09/20/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Bldg. 6 Staff RR by Classroom 38	Tested	5:07:00 PM	09/20/2019
Smoke Detector	Bldg. 7 Classroom 11	Tested	5:36:12 PM	09/20/2019
Smoke Detector	Bldg. 7 Classroom 11	Tested	5:36:17 PM	09/20/2019
Smoke Detector	Bldg. 7 Classroom 12	Tested	5:35:30 PM	09/20/2019
Smoke Detector	Bldg. 7 Classroom 12	Tested	5:35:55 PM	09/20/2019
Smoke Detector	Bldg. 7 Classroom 13	Tested	5:35:08 PM	09/20/2019
Smoke Detector	Bldg. 7 Classroom 13	Tested	5:35:20 PM	09/20/2019
Smoke Detector	Bldg. 7 IDF Rm. Behind Classroom 13	Tested	5:35:25 PM	09/20/2019
Smoke Detector	Bldg. 8 Boys RR by Classroom 19	Tested	5:24:23 PM	09/20/2019
Smoke Detector	Bldg. 8 Classroom 19	Tested	5:30:06 PM	09/20/2019
Smoke Detector	Bldg. 8 Classroom 19	Tested	5:30:28 PM	09/20/2019
Smoke Detector	Bldg. 8 Classroom 20	Tested	5:21:04 PM	09/20/2019
Smoke Detector	Bldg. 8 Classroom 20	Tested	5:21:29 PM	09/20/2019
Smoke Detector	Bldg. 8 Girls RR by Classroom 19	Tested	5:24:08 PM	09/20/2019
Smoke Detector	Bldg. 8 Staff RR Behind Classroom 19	Tested	5:24:47 PM	09/20/2019
Smoke Detector	Bldg. 8 Staff RR by Classroom 19	Tested	5:23:48 PM	09/20/2019
Smoke Detector	Bldg. 9 Classroom 4 Restroom	Tested	4:56:59 PM	09/20/2019
Smoke Detector	Bldg. 9 Classroom 4	Tested	4:56:34 PM	09/20/2019
Smoke Detector	Bldg. 9 Classroom 4	Tested	4:56:50 PM	09/20/2019
Smoke Detector	Bldg. 9 Classroom 4 And 5 Storage Room	Tested	5:12:27 PM	09/20/2019
Smoke Detector	Bldg. 9 Classroom 4 And 5 Workroom	Tested	5:00:06 PM	09/20/2019
Smoke Detector	Bldg. 9 Classroom 4 And 5 Workroom Restroom	Tested	5:00:23 PM	09/20/2019
Smoke Detector	Bldg. 9 Classroom 5 Restroom	Tested	5:03:21 PM	09/20/2019
Smoke Detector	Bldg. 9 Classroom 5	Tested	5:03:05 PM	09/20/2019
Smoke Detector	Bldg. 9 Classroom 5	Tested	5:03:15 PM	09/20/2019
Smoke Detector	Portable Boys RR- J	Tested	4:53:53 PM	09/20/2019
Smoke Detector	Portable Girls RR- L	Tested	4:56:37 PM	09/20/2019
Smoke Detector	Portable Unisex RR- K	Tested	4:55:33 PM	09/20/2019
Smoke Detector	South Bldg. 2 MPR Exit	Tested	4:16:57 PM	09/12/2019
Smoke Detector	South Bldg. 2 MPR Exit Unisex RR	Tested	4:17:53 PM	09/12/2019
Smoke Detector	South Bldg. 2 MPR Exit Unisex RR	Tested	4:18:29 PM	09/12/2019
Smoke Detector	South Bldg. 2 MPR Kitchen	Tested	4:21:39 PM	09/12/2019
Smoke Detector	South Bldg. 2 MPR Outside Janitor Closet	Tested	4:23:07 PM	09/12/2019
Smoke Detector	South Bldg. 2 MPR Outside Janitor Office	Tested	4:24:28 PM	09/12/2019
Smoke Detector	South Bldg. 2 MPR Stage	Tested	4:19:50 PM	09/12/2019
Smoke Detector	South Bldg. 2 MPR Stage	Tested	4:20:03 PM	09/12/2019
Smoke Detector	Bldg. 1 Admin Entrance	Tested	3:43:26 PM	09/12/2019
Smoke Detector	Bldg. 1 By Principal's Office	Tested	3:44:09 PM	09/12/2019
Smoke Detector	Bldg. 1 Nurse MDF Rm.	Tested	3:39:25 PM	09/12/2019
Smoke Detector	Bldg. 1 Nurse Office	Tested	3:40:14 PM	09/12/2019
Smoke Detector	Bldg. 1 Office by Reception Desk	Tested	3:45:47 PM	09/12/2019
Smoke Detector	Bldg. 1 Workroom	Tested	3:49:16 PM	09/12/2019
Smoke Detector	Bldg. 1 Workroom	Tested	3:49:33 PM	09/12/2019
Smoke Detector	Bldg. 1 Workroom RR	Tested	3:51:45 PM	09/12/2019
Smoke Detector	Bldg. 10 Electrical Rm.	Tested	4:26:25 PM	09/12/2019
Smoke Detector	Bldg. 3 Classroom 42	Tested	4:16:35 PM	09/20/2019
Smoke Detector	Bldg. 3 Classroom 42	Tested	4:16:46 PM	09/20/2019
Smoke Detector	Bldg. 3 Classroom 43	Tested	4:16:15 PM	09/20/2019
Smoke Detector	Bldg. 3 Classroom 43	Tested	4:16:28 PM	09/20/2019
Smoke Detector	Bldg. 3 Classroom 44	Tested	4:14:25 PM	09/20/2019
SHIDKE DELECTOR	Blug. 5 Classi 0011 44	resteu		09/20/2019

Device Type	Location	Service	Time	Date
	Passed	ł		
Smoke Detector	Bldg. 3 Classroom 44	Tested	4:15:10 PM	09/20/2019
Smoke Detector	Bldg. 3 Custodian Closet	Tested	4:29:46 PM	09/12/2019
Smoke Detector	Bldg. 3 Electrical Rm.	Tested	4:31:29 PM	09/12/2019
Smoke Detector	Bldg. 4 Boys RR	Tested	4:02:52 PM	09/20/2019
Smoke Detector	Bldg. 4 Classroom 35	Tested	4:05:36 PM	09/20/2019
Smoke Detector	Bldg. 4 Classroom 35	Tested	4:05:51 PM	09/20/2019
Smoke Detector	Bldg. 4 Classroom 36	Tested	4:07:04 PM	09/20/2019
Smoke Detector	Bldg. 4 Classroom 36	Tested	4:07:19 PM	09/20/2019
Smoke Detector	Bldg. 4 Girls RR	Tested	4:03:41 PM	09/20/2019
Smoke Detector	Bldg. 5 Classroom 39	Tested	4:34:10 PM	09/20/2019
Smoke Detector	Bldg. 5 Classroom 39	Tested	4:34:22 PM	09/20/2019
Smoke Detector	Bldg. 5 Classroom 40	Tested	4:31:44 PM	09/20/2019
Smoke Detector	Bldg. 5 Classroom 40	Tested	4:31:59 PM	09/20/2019
Smoke Detector	Bldg. 5 Classroom 41	Tested	4:26:20 PM	09/20/2019
Smoke Detector	Bldg. 5 Classroom 41	Tested	4:26:31 PM	09/20/2019
Smoke Detector	Bldg. 6 Classroom 37	Tested	4:28:25 PM	09/20/2019
Smoke Detector	Bldg. 6 Classroom 37	Tested	4:28:39 PM	09/20/2019
Smoke Detector	Bldg. 6 Classroom 38	Tested	4:29:41 PM	09/20/2019
Smoke Detector	Bldg. 6 Classroom 38	Tested	4:29:52 PM	09/20/2019
Smoke Detector	Boy's Restroom By Portable 3	Tested	4:52:25 PM	09/20/2019
Smoke Detector	Girl's Restroom By Portable 3	Tested	4:52:54 PM	09/20/2019
Smoke Detector	Portable 1	Tested	4:46:52 PM	09/20/2019
Smoke Detector	Portable 1	Tested	4:47:08 PM	09/20/2019
Smoke Detector	Portable 10	Tested	5:20:01 PM	09/20/2019
Smoke Detector	Portable 10	Tested	5:20:10 PM	09/20/2019
Smoke Detector	Portable 14	Tested	5:23:40 PM	09/20/2019
Smoke Detector	Portable 14	Tested	5:23:51 PM	09/20/2019
Smoke Detector	Portable 15	Tested	5:23:56 PM	09/20/2019
Smoke Detector	Portable 15	Tested	5:24:11 PM	09/20/2019
Smoke Detector	Portable 16	Tested	5:24:16 PM	09/20/2019
Smoke Detector	Portable 16	Tested	5:24:27 PM	09/20/2019
Smoke Detector	Portable 17	Tested	5:24:33 PM	09/20/2019
Smoke Detector	Portable 17	Tested	5:24:45 PM	09/20/2019
Smoke Detector	Portable 18	Tested	5:24:50 PM	09/20/2019
Smoke Detector	Portable 18	Tested	5:25:01 PM	09/20/2019
Smoke Detector	Portable 2	Tested	4:48:30 PM	09/20/2019
Smoke Detector	Portable 2	Tested	4:48:39 PM	09/20/2019
Smoke Detector	Portable 21	Tested	4:50:17 PM	09/20/2019
Smoke Detector	Portable 21	Tested	4:50:27 PM	09/20/2019
Smoke Detector	Portable 22	Tested	4:49:55 PM	09/20/2019
Smoke Detector	Portable 22	Tested	4:50:08 PM	09/20/2019
Smoke Detector	Portable 23	Tested	4:49:33 PM	09/20/2019
Smoke Detector	Portable 23	Tested	4:49:49 PM	09/20/2019
Smoke Detector	Portable 24	Tested	4:46:13 PM	09/20/2019
Smoke Detector	Portable 24	Tested	4:46:23 PM	09/20/2019
Smoke Detector	Portable 25	Tested	4:43:46 PM	09/20/2019
Smoke Detector	Portable 25	Tested	4:43:57 PM	09/20/2019
Smoke Detector	Portable 26	Tested	4:43:22 PM	09/20/2019
Smoke Detector	Portable 26	Tested	4:43:39 PM	09/20/2019
Smoke Detector	Portable 27	Tested	4:42:19 PM	09/20/2019

Device Type	Location	Service	Time	Date
	Passed	!		
Smoke Detector	Portable 27	Tested	4:42:30 PM	09/20/2019
Smoke Detector	Portable 28	Tested	4:40:21 PM	09/20/2019
Smoke Detector	Portable 28	Tested	4:40:32 PM	09/20/2019
Smoke Detector	Portable 29	Tested	4:38:12 PM	09/20/2019
Smoke Detector	Portable 29	Tested	4:38:44 PM	09/20/2019
Smoke Detector	Portable 3	Tested	4:49:55 PM	09/20/2019
Smoke Detector	Portable 3	Tested	4:50:05 PM	09/20/2019
Smoke Detector	Portable 30	Tested	4:35:57 PM	09/20/2019
Smoke Detector	Portable 30	Tested	4:36:40 PM	09/20/2019
Smoke Detector	Portable 31	Tested	4:57:40 PM	09/20/2019
Smoke Detector	Portable 31	Tested	4:57:49 PM	09/20/2019
Smoke Detector	Portable 31	Tested	4:58:11 PM	09/20/2019
Smoke Detector	Portable 31	Tested	4:58:18 PM	09/20/2019
Smoke Detector	Portable 32	Tested	5:02:39 PM	09/20/2019
Smoke Detector	Portable 32	Tested	5:02:51 PM	09/20/2019
Smoke Detector	Portable 33	Tested	5:04:32 PM	09/20/2019
Smoke Detector	Portable 33	Tested	5:04:49 PM	09/20/2019
Smoke Detector	Portable 6	Tested	5:06:18 PM	09/20/2019
Smoke Detector	Portable 6	Tested	5:06:28 PM	09/20/2019
Smoke Detector	Portable 7	Tested	5:06:33 PM	09/20/2019
Smoke Detector	Portable 7	Tested	5:06:42 PM	09/20/2019
Smoke Detector	Portable 8	Tested	5:06:49 PM	09/20/2019
Smoke Detector	Portable 8	Tested	5:06:59 PM	09/20/2019
Smoke Detector	Portable 8A	Tested	5:19:23 PM	09/20/2019
Smoke Detector	Portable 8A	Tested	5:19:33 PM	09/20/2019
Smoke Detector	Portable 9	Tested	5:19:38 PM	09/20/2019
Smoke Detector	Portable 9	Tested	5:19:54 PM	09/20/2019
Smoke Detector	Unisex Restroom By Portable 3	Tested	4:53:09 PM	09/20/2019
Device Type	Location	Service	Time	Date
	Unteste	d		
Initiating				
Smoke Detector	Portable 45			
Smoke Detector	Portable 45			

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Whittier Elementary School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity		
	Passed			
Battery	Tested	14		
Control Panel	Tested	1		
Heat Detector	Tested	57		
Power Supply	Inspected	2		
Power Supply	Tested	4		
Pull Station	Tested	4		
Smoke Detector	Tested	132		
Total		214		
Untested				
Smoke Detector		2		
Total		216		

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - Whittier Elementary School

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

		Ambient	Alarm	🦻 Intell	igibility	Sound
C Location	 Comment 	◀ dB	◀ dB	Voice	STI	Test
Passed						
Sound Test Points						
Entire Campus	Passed					0001

Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: NMUSD - Whittier Elementary School

Control Panel: 1 - Simplex 4100U

The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.

		Rated	Rated	Pre	Post	Min	Tested
Туре	Location	Ah	Volts	Test	Test	Ah	Ah
		Passe	d				
Battery							
Sealed Lead Acid	Bldg. 3 IDK Rm. Behind Classroom 42	7	12				ľ
Sealed Lead Acid	Bldg. 3 IDK Rm. Behind Classroom 42	7	12				
Sealed Lead Acid	Bldg. 7 IDF Rm. Behind Classroom 13	7	12				
Sealed Lead Acid	Bldg. 7 IDF Rm. Behind Classroom 13	7	12				
Sealed Lead Acid	Bldg. 1 Nurse MDF Rm.	18	12				
Sealed Lead Acid	Bldg. 1 Nurse MDF Rm.	18	12				
Sealed Lead Acid	Bldg. 1 Nurse MDF Rm.	7	12				
Sealed Lead Acid	Bldg. 1 Nurse MDF Rm.	7	12				
Sealed Lead Acid	Bldg. 3 Electrical Rm.	7	12				
Sealed Lead Acid	Bldg. 3 Electrical Rm.	7	12				

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Whittier Elementary School

Control Panel: 1 - Simplex 4100U

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category	%	of Inventory	Quantity
Smoke Detector		Initiating		61.75%	134
Control Panel		Control		0.46%	1
Battery		Control		6.45%	14
Power Supply		Control		2.76%	6
Pull Station		Initiating		1.84%	4
Heat Detector		Initiating		26.27%	57
Туре	Qty	Model #	Description		Install Date
		New	(under 90 days)		
12V18Ah					
Battery	2	12V18Ah	Sealed Lead Acid		09/12/2019
12V7Ah					
Battery	2	12V7Ah	Sealed Lead Acid		09/12/2019
Silent Knight					
Power Supply	1	5495			09/12/2019
Simplex					
Control Panel	1	4100U			09/12/2019
Heat Detector	57	4098-9734			09/12/2019
Power Supply	1	4009			09/12/2019
Power Supply	3	4009 IDNET			09/12/2019
Pull Station	4	4099-9001	Keyed		09/12/2019
Smoke Detector	134	4098-9714	Photoelectric		09/12/2019
		In Service	e - 2 Years to 3 Y	ears	
12V7Ah					
Battery	2	12V7Ah	Sealed Lead Acid		08/12/2017
Battery	2	12V7Ah	Sealed Lead Acid		02/12/2017
Battery	2	12V7AH	Sealed Lead Acid		11/12/2016
Simplex					
Power Supply	1	4009			11/12/2016
		In Service	e - 3 Years to 5 Y	<i>ears</i>	
12V7Ah					
Battery	2	12V7Ah	Sealed Lead Acid		06/12/2016

1		
	Battery	

2

12V7AH

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Wilson Elementary 801 Wilson Street Costa Mesa, CA 92627

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Aug 26, 2019

> Building: NMUSD - Wilson Elementary Contact: Tim Waller Title: Maintenance & Operations Manager

Company: Cal Building Systems Contact: Michael Cannon Title: Service Technician

Executive Summary Generated by: BuildingReports.com

Building Information				
Building: NMUSD - Wilson Elementary	Contact: Tim Waller			
Address: 801 Wilson Street	Phone: 714-231-0363			
Address:	Fax:			
City/State/Zip: Costa Mesa, CA 92627	Mobile:			
Country: United States of America	Email:			
Inspection Performed By				
Company: Cal Building Systems	Inspector: Michael Can	non		
Address: 2903 Saturn Street	Phone: 714-715-1223			
Address: Suite F	Fax:			
City/State/Zip: Brea, CA 92821	Mobile:			
Country: United States of America	Country: United States of America Email: mcannon@calbuildingsystems.com			
System Control Unit				
Manufacturer: Simplex	Inspection Date: 08/26	5/2019 IDC Style:		
Model Number: 4100U	Install Date: 08/26/20	19 SLC Style:		
Software Version:	Version Date: 12/31/1	969 NAC Style:		
Location: Building C FACP Room	Current Protection:			
Monitoring				
Company:	Phone: 1-800-634-3915	Account #: 21-1113		
Central Station Signal Verification				
Туре:	Mfg:	Model #:		
Test Time/Date:	Restore Time			

Inspection Summary								
Catalana	Total Items		Serviced		Passed		Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Control	19	7.51%	19	100.00%	19	100.00%	0	0%
Initiating	234	92.49%	234	100.00%	234	100.00%	0	0%
Totals	253	100%	253	100.00%	253	100.00%	0	0%
Certification								
Company: Cal Building Systems			Bu	ilding: NML	JSD – Wils	on Element	tary	
Inspector: Michael Cannon			Co	ntact: Tim	Waller			
Made Common								
Signed: Aug 26, 2019 3:25:43	PM		Sig	jned:				

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Wilson Elementary

Control Panel: 1 - Simplex 4100U

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Building A Reception Waiting Area	Inspected	10:22:32 AM	08/26/2019
Battery	Building B Custodial Room	Tested	9:40:01 AM	08/26/2019
Battery	Building B Custodial Room	Tested	9:40:30 AM	08/26/2019
Battery	Building C FACP Room	Tested	8:45:52 AM	08/26/2019
Battery	Building C FACP Room	Tested	8:46:24 AM	08/26/2019
Battery	Building C FACP Room	Tested	8:50:06 AM	08/26/2019
Battery	Building C FACP Room	Tested	8:50:25 AM	08/26/2019
Battery	Building E Custodial Room	Tested	11:27:27 AM	08/26/2019
Battery	Building E Custodial Room	Tested	11:27:55 AM	08/26/2019
Battery	Building F Kindergarten Workroom	Tested	10:03:23 AM	08/26/2019
Battery	Building F Kindergarten Workroom	Tested	10:03:52 AM	08/26/2019
Battery	Building G MPR Stage	Tested	10:53:13 AM	08/26/2019
Battery	Building G MPR Stage	Tested	10:53:32 AM	08/26/2019
Control Panel	Building C FACP Room	Inspected	8:44:30 AM	08/26/2019
Power Supply	Building B Custodial Room	Inspected	9:39:11 AM	08/26/2019
Power Supply	Building C FACP Room	Inspected	8:49:38 AM	08/26/2019
Power Supply	Building E Custodial Room	Inspected	11:27:06 AM	08/26/2019
Power Supply	Building F Kindergarten Workroom	Inspected	10:02:39 AM	08/26/2019
Power Supply	Building G MPR Stage	Inspected	10:52:49 AM	08/26/2019
Initiating				
Heat Detector	BLDG A Mechanical RM	Tested	11:31:04 AM	08/26/2019
Heat Detector	BLDG A Men's RR	Tested	11:33:08 AM	08/26/2019
Heat Detector	BLDG A Nurse RR	Tested	11:27:30 AM	08/26/2019
Heat Detector	BLDG A Women's RR	Tested	11:30:37 AM	08/26/2019
Heat Detector	BLDG B Girls RR	Tested	9:36:26 PM	08/26/2019
Heat Detector	BLDG B RM 28 ABV Ceiling	Tested	9:37:11 PM	08/26/2019
Heat Detector	BLDG B RM 28 ABV Ceiling	Tested	9:37:54 PM	08/26/2019
Heat Detector	BLDG B RM 28 ABV Ceiling	Tested	9:38:05 PM	08/26/2019
Heat Detector	BLDG B RM 28 ABV Ceiling	Tested	9:38:24 PM	08/26/2019
Heat Detector	BLDG B RM 28 Furnace	Tested	9:38:46 PM	08/26/2019
Heat Detector	BLDG B RM 29 ABV Ceiling	Tested	9:39:31 PM	08/26/2019
Heat Detector	BLDG B RM 29 ABV Ceiling	Tested	9:41:48 PM	08/26/2019
Heat Detector	BLDG B RM 29 ABV Ceiling	Tested	9:42:01 PM	08/26/2019
Heat Detector	BLDG B RM 30 ABV Ceiling	Tested	9:42:29 PM	08/26/2019
Heat Detector	BLDG B RM 30 ABV Ceiling	Tested	9:44:00 PM	08/26/2019
Heat Detector	BLDG B RM 30 ABV Ceiling	Tested	9:44:28 PM	08/26/2019
Heat Detector	BLDG B RM 30 Furnace	Tested	9:45:15 PM	08/26/2019
Heat Detector	BLDG B RM 31 ABV Ceiling	Tested	9:43:15 PM	08/26/2019

Device Type	Location	Service	Time	Date
	Passe	d		
Heat Detector	BLDG B RM 31 ABV Ceiling	Tested	9:46:09 PM	08/26/2019
Heat Detector	BLDG B RM 31 ABV Ceiling	Tested	9:47:50 PM	08/26/2019
Heat Detector	BLDG B RM 32 ABV Ceiling	Tested	9:26:29 PM	08/26/2019
Heat Detector	BLDG B RM 32 ABV Ceiling	Tested	9:48:37 PM	08/26/2019
Heat Detector	BLDG B RM 32 ABV Ceiling	Tested	9:49:34 PM	08/26/2019
Heat Detector	BLDG B RM 32 Furnace	Tested	9:49:52 PM	08/26/2019
Heat Detector	BLDG C 26 ABV Ceiling	Tested	11:53:39 AM	08/26/2019
Heat Detector	BLDG C Boys RR	Tested	11:44:51 AM	08/26/2019
Heat Detector	BLDG C C101 ABV Ceiling	Tested	11:47:12 AM	08/26/2019
Heat Detector	BLDG C RM 23 ABV Ceiling	Tested	11:45:56 AM	08/26/2019
Heat Detector	BLDG C RM 23 ABV Ceiling	Tested	11:46:51 AM	08/26/2019
Heat Detector	BLDG C RM 23 Furnace	Tested	11:47:38 AM	08/26/2019
Heat Detector	BLDG C RM 24 ABV Ceiling	Tested	11:50:55 AM	08/26/2019
Heat Detector	BLDG C RM 24 ABV Ceiling	Tested	11:51:21 AM	08/26/2019
Heat Detector	BLDG C RM 24 ABV Ceiling	Tested	11:51:23 AM	08/26/2019
Heat Detector	BLDG C RM 25 ABV Ceiling	Tested	11:51:04 AM	08/26/2019
Heat Detector	BLDG C RM 25 ABV Ceiling	Tested	11:51:45 AM	08/26/2019
Heat Detector	BLDG C RM 25 ABV Ceiling	Tested	11:52:03 AM	08/26/2019
Heat Detector	BLDG C RM 25 Furnace	Tested	11:52:12 AM	08/26/2019
Heat Detector	BLDG C RM 26 ABV Ceiling	Tested	11:53:10 AM	08/26/2019
Heat Detector	BLDG C RM 26 ABV Ceiling	Tested	11:53:49 AM	08/26/2019
Heat Detector	BLDG C Rm 27 ABV Ceiling	Tested	11:55:30 AM	08/26/2019
Heat Detector	BLDG C RM 27 ABV Ceiling	Tested	11:56:00 AM	08/26/2019
Heat Detector	BLDG C RM 27 ABV Ceiling	Tested	11:56:08 AM	08/26/2019
Heat Detector	BLDG C RM 27 Furnace	Tested	9:28:19 PM	08/26/2019
Heat Detector	BLDG D Boys RR	Tested	9:53:49 PM	08/26/2019
Heat Detector	BLDG D RM 1 ABV Ceiling	Tested	9:54:36 PM	08/26/2019
Heat Detector	BLDG D RM 1 ABV Ceiling	Tested	9:56:36 PM	08/26/2019
Heat Detector	BLDG D RM 1 ABV Ceiling	Tested	9:56:42 PM	08/26/2019
Heat Detector	BLDG D RM 1 Furnace	Tested	9:56:51 PM	08/26/2019
Heat Detector	BLDG D RM 2 ABV Ceiling	Tested	9:57:15 PM	08/26/2019
Heat Detector	BLDG D RM 2 ABV Ceiling	Tested	9:57:40 PM	08/26/2019
Heat Detector	BLDG D RM 2 ABV Ceiling	Tested	9:57:46 PM	08/26/2019
Heat Detector	BLDG D RM 3 ABV Ceiling	Tested	9:58:06 PM	08/26/2019
Heat Detector	BLDG D RM 3 ABV Ceiling	Tested	9:58:34 PM	08/26/2019
Heat Detector	BLDG D RM 3 ABV Ceiling	Tested	9:58:56 PM	08/26/2019
Heat Detector	BLDG D RM 3 Furnace	Tested	9:59:11 PM	08/26/2019
Heat Detector	BLDG D RM 4 ABV Ceiling	Tested	10:00:13 PM	08/26/2019
Heat Detector	BLDG D RM 4 ABV Ceiling	Tested	10:00:44 PM	08/26/2019
Heat Detector	BLDG D RM 4 ABV Ceiling	Tested	10:00:53 PM	08/26/2019
Heat Detector	BLDG D RM 5 ABV Ceiling	Tested	10:01:17 PM	08/26/2019
Heat Detector	BLDG D RM 5 ABV Ceiling	Tested	10:01:54 PM	08/26/2019
Heat Detector	BLDG D RM 5 ABV Ceiling	Tested	10:02:03 PM	08/26/2019
Heat Detector	BLDG D RM 5 ABV Furnace	Tested	10:02:14 PM	08/26/2019
Heat Detector	BLDG E RM 10 ABV Ceiling	Tested	11:34:23 AM	08/26/2019
Heat Detector	BLDG E RM 10 ABV Ceiling	Tested	11:35:03 AM	08/26/2019
Heat Detector	BLDG E RM 10 ABV Ceiling	Tested	11:35:16 AM	08/26/2019
Heat Detector	BLDG E RM 10 Furnace	Tested	11:33:34 AM	08/26/2019
Heat Detector	BLDG E RM 6 ABV Ceiling	Tested	11:40:41 AM	08/26/2019
Heat Detector	BLDG E RM 6 ABV Ceiling	Tested	11:41:06 AM	08/26/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	BLDG E RM 6 ABV Ceiling	Tested	11:41:12 AM	08/26/2019
Heat Detector	BLDG E RM 6 Furnace	Tested	11:40:10 AM	08/26/2019
Heat Detector	BLDG E RM 7 ABV Ceiling	Tested	11:38:29 AM	08/26/2019
Heat Detector	BLDG E RM 7 ABV Ceiling	Tested	11:39:36 AM	08/26/2019
Heat Detector	BLDG E RM 7 ABV Ceiling	Tested	11:45:26 AM	08/26/2019
Heat Detector	BLDG E RM 8 ABV Ceiling	Tested	11:37:07 AM	08/26/2019
Heat Detector	BLDG E RM 8 ABV Ceiling	Tested	11:37:35 AM	08/26/2019
Heat Detector	BLDG E RM 8 ABV Ceiling	Tested	11:37:43 AM	08/26/2019
Heat Detector	BLDG E RM 8 Furnace	Tested	11:36:38 AM	08/26/2019
Heat Detector	BLDG E RM 9 ABV Ceiling	Tested	11:35:46 AM	08/26/2019
Heat Detector	BLDG E RM 9 ABV Ceiling	Tested	11:36:06 AM	08/26/2019
Heat Detector	BLDG E RM 9 ABV Ceiling	Tested	11:36:27 AM	08/26/2019
Heat Detector	BLDG F Kinder RM 33 ABV Ceiling	Tested	9:50:26 PM	08/26/2019
Heat Detector	BLDG F Kinder RM 33 ABV Ceiling	Tested	9:51:14 PM	08/26/2019
Heat Detector	BLDG F Kinder RM 33 ABV Ceiling	Tested	9:51:27 PM	08/26/2019
Heat Detector	BLDG F Kinder RM 33 RR	Tested	9:51:38 PM	08/26/2019
Heat Detector	BLDG F Kinder RM 34 ABV Ceiling	Tested	9:52:36 PM	08/26/2019
Heat Detector	BLDG F Kinder RM 34 ABV Ceiling	Tested	9:53:16 PM	08/26/2019
Heat Detector	BLDG F Kinder RM 34 ABV Ceiling	Tested	9:53:26 PM	08/26/2019
Heat Detector	BLDG F Kinder RM 34 RR	Tested	9:52:10 PM	08/26/2019
Heat Detector	BLDG G Kitchen	Tested	11:44:24 AM	08/26/2019
Heat Detector	BLDG G Mechanical RM	Tested	11:41:25 AM	08/26/2019
Heat Detector	BLDG G Men's RR	Tested	11:42:36 AM	08/26/2019
Heat Detector	BLDG G Women's RR	Tested	11:42:09 AM	08/26/2019
Heat Detector	BLDG H RM 11 ABV Ceiling	Tested	10:04:16 PM	08/26/2019
Heat Detector	BLDG H RM 11 ABV Ceiling	Tested	10:04:47 PM	08/26/2019
Heat Detector	BLDG H RM 12 ABV Ceiling	Tested	10:03:32 PM	08/26/2019
Heat Detector	BLDG H RM 12 ABV Ceiling	Tested	10:04:02 PM	08/26/2019
Heat Detector	BLDG H RM 13 ABV Ceiling	Tested	10:02:39 PM	08/26/2019
Heat Detector	BLDG H RM 13 ABV Ceiling	Tested	10:03:18 PM	08/26/2019
Heat Detector	BLDG H RM 35 Attic	Tested	10:23:00 PM	08/26/2019
Heat Detector	BLDG H RM 36 Attic	Tested	10:23:34 PM	08/26/2019
Heat Detector	BLDG I 14 ABV Ceiling	Tested	10:09:53 PM	08/26/2019
Heat Detector	BLDG I 14 ABV Ceiling	Tested	10:10:39 PM	08/26/2019
Heat Detector	BLDG I 15 ABV Ceiling	Tested	10:06:45 PM	08/26/2019
Heat Detector	BLDG I 15 ABV Ceiling	Tested	10:07:39 PM	08/26/2019
Heat Detector	BLDG I 16 ABV Ceiling	Tested	10:05:06 PM	08/26/2019
Heat Detector	BLDG I 16 ABV Ceiling	Tested	10:06:08 PM	08/26/2019
Heat Detector	BLDG I RM 37 Attic	Tested	10:26:58 PM	08/26/2019
Heat Detector	BLDG J 17 ABV Ceiling	Tested	10:11:03 PM	08/26/2019
Heat Detector	BLDG J 17 ABV Ceiling	Tested	10:12:54 PM	08/26/2019
Heat Detector	BLDG J 18 ABV Ceiling	Tested	10:13:55 PM	08/26/2019
Heat Detector	BLDG J 18 ABV Ceiling	Tested	10:14:23 PM	08/26/2019
Heat Detector	BLDG J 19 ABV Ceiling	Tested	10:19:22 PM	08/26/2019
Heat Detector	BLDG J 21 ABV Ceiling	Tested	10:21:23 PM	08/26/2019
Heat Detector	BLDG J 21 ABV Ceiling BLDG J 21 ABV Ceiling	Tested	10:21:51 PM	08/26/2019
Heat Detector	BLDG J 22 ABV Ceiling BLDG J 22 ABV Ceiling	Tested	10:22:02 PM	08/26/2019
Heat Detector	BLDG J 22 ABV Ceiling BLDG J 22 ABV Ceiling	Tested	10:22:47 PM	08/26/2019
Heat Detector	BLDG J ZZ ABV Ceiling BLDG J RM 19 ABV Ceiling	Tested	10:19:30 PM	08/26/2019
Heat Detector	BLDG J RM 20 ABV Ceiling	Tested	10:19:41 PM	08/26/2019
neal Delector	DLDG J KIM ZU ADV CEIIITIG	rested	10.1 <i>9</i> . 4 1 FM	00/20/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	BLDG J RM 20 ABV Ceiling	Tested	10:20:22 PM	08/26/2019
Heat Detector	Portable Boys RR Attic	Tested	10:26:28 PM	08/26/2019
Heat Detector	Portable Disabled RR Attic	Tested	10:24:53 PM	08/26/2019
Heat Detector	Portable Girls RR Attic	Tested	10:25:40 PM	08/26/2019
Pull Station	Building A Reception Waiting Area	Tested	10:24:11 AM	08/26/2019
Pull Station	Building G MPR Foyer Exit	Tested	10:36:26 AM	08/26/2019
Pull Station	Building G MPR North Exit	Tested	10:46:42 AM	08/26/2019
Pull Station	Building G MPR West Exit	Tested	10:44:04 AM	08/26/2019
Smoke Detector	East Building F Kindergarten Equipment Storage	Tested	10:09:52 AM	08/26/2019
	Room			
Smoke Detector	West Building F Kindergarten Equipment Storage Room	Tested	10:07:55 AM	08/26/2019
Smoke Detector	Boy's Portable Restroom	Tested	11:38:24 AM	08/26/2019
Smoke Detector	Building A Corridor Near Restrooms	Tested	10:14:52 AM	08/26/2019
Smoke Detector	Building A Faculty Lounge	Tested	10:15:49 AM	08/26/2019
Smoke Detector	Building A Faculty Lounge	Tested	10:16:10 AM	08/26/2019
Smoke Detector	Building A Nurse's Office	Tested	10:18:23 AM	08/26/2019
Smoke Detector	Building A Nurse's Room	Tested	10:17:12 AM	08/26/2019
Smoke Detector	Building A Office Storage	Tested	10:19:55 AM	08/26/2019
Smoke Detector	Building A Outside Electrical Room	Tested	10:13:28 AM	08/26/2019
Smoke Detector	Building A Principal's Office	Tested	10:21:20 AM	08/26/2019
Smoke Detector	Building A Reception	Tested	10:20:33 AM	08/26/2019
Smoke Detector	Building A Reception Waiting Area	Tested	10:23:27 AM	08/26/2019
Smoke Detector	Building B Classroom 29	Tested	9:50:07 AM	08/26/2019
Smoke Detector	Building B Classroom 29	Tested	9:50:24 AM	08/26/2019
Smoke Detector	Building B Classroom 30	Tested	9:51:50 AM	08/26/2019
Smoke Detector	Building B Classroom 30	Tested	9:51:59 AM	08/26/2019
Smoke Detector	Building B Classroom 31	Tested	9:52:06 AM	08/26/2019
Smoke Detector	Building B Classroom 31	Tested	9:52:17 AM	08/26/2019
Smoke Detector	Building B Classroom 32	Tested	9:52:32 AM	08/26/2019
Smoke Detector	Building B Classroom 32	Tested	9:52:43 AM	08/26/2019
Smoke Detector	Building B Custodial Room	Tested	9:38:05 AM	08/26/2019
Smoke Detector	Building B Electrical Room	Tested	9:42:35 AM	08/26/2019
Smoke Detector	Building B Faculty Lounge (Classroom 28)	Tested	9:46:04 AM	08/26/2019
Smoke Detector	Building B Faculty Lounge (Classroom 28)	Tested	9:46:19 AM	08/26/2019
Smoke Detector	Building B Faculty Lounge Office (Classroom 28)	Tested	9:48:19 AM	08/26/2019
Smoke Detector	Building C Classroom 23	Tested	9:04:42 AM	08/26/2019
Smoke Detector	Building C Classroom 23	Tested	9:04:56 AM	08/26/2019
Smoke Detector	Building C Classroom 24	Tested	9:06:55 AM	08/26/2019
Smoke Detector	Building C Classroom 24	Tested	9:07:06 AM	08/26/2019
Smoke Detector	Building C Classroom 25	Tested	9:08:36 AM	08/26/2019
Smoke Detector	Building C Classroom 25	Tested	9:08:45 AM	08/26/2019
Smoke Detector	Building C Classroom 26	Tested	9:10:12 AM	08/26/2019
Smoke Detector	Building C Classroom 26	Tested	9:10:23 AM	08/26/2019
Smoke Detector	Building C Classroom 27	Tested	9:11:55 AM	08/26/2019
Smoke Detector	Building C Classroom 27	Tested	9:12:10 AM	08/26/2019
Smoke Detector	Building C FACP Room	Tested	8:48:13 AM	08/26/2019
Smoke Detector	Building D Classroom 1 Library	Tested	11:04:12 AM	08/26/2019
Smoke Detector	Building D Classroom 1 Library	Tested	11:04:32 AM	08/26/2019
Smoke Detector	Building D Classroom 2	Tested	11:05:42 AM	08/26/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Building D Classroom 2	Tested	11:05:54 AM	08/26/2019
Smoke Detector	Building D Classroom 3	Tested	11:07:15 AM	08/26/2019
Smoke Detector	Building D Classroom 3	Tested	11:07:27 AM	08/26/2019
Smoke Detector	Building D Classroom 4	Tested	11:07:32 AM	08/26/2019
Smoke Detector	Building D Classroom 4	Tested	11:07:44 AM	08/26/2019
Smoke Detector	Building D Classroom 5	Tested	11:07:51 AM	08/26/2019
Smoke Detector	Building D Classroom 5	Tested	11:08:02 AM	08/26/2019
Smoke Detector	Building D Custodial Room	Tested	11:01:14 AM	08/26/2019
Smoke Detector	Building E Classroom 10	Tested	11:11:54 AM	08/26/2019
Smoke Detector	Building E Classroom 10	Tested	11:12:03 AM	08/26/2019
Smoke Detector	Building E Classroom 6	Tested	11:16:45 AM	08/26/2019
Smoke Detector	Building E Classroom 6	Tested	11:16:56 AM	08/26/2019
Smoke Detector	Building E Classroom 7	Tested	11:16:28 AM	08/26/2019
Smoke Detector	Building E Classroom 7	Tested	11:16:38 AM	08/26/2019
Smoke Detector	Building E Classroom 8	Tested	11:16:13 AM	08/26/2019
Smoke Detector	Building E Classroom 8	Tested	11:16:23 AM	08/26/2019
Smoke Detector	Building E Classroom 9	Tested	11:12:08 AM	08/26/2019
Smoke Detector	Building E Classroom 9	Tested	11:12:19 AM	08/26/2019
Smoke Detector	Building E Custodial Room	Tested	11:25:52 AM	08/26/2019
Smoke Detector	Building E Girl's Restroom	Tested	11:23:43 AM	08/26/2019
Smoke Detector	Building F Kindergarten Classroom 33	Tested	9:58:52 AM	08/26/2019
Smoke Detector	Building F Kindergarten Classroom 33	Tested	9:59:55 AM	08/26/2019
Smoke Detector	Building F Kindergarten Classroom 34	Tested	10:04:45 AM	08/26/2019
Smoke Detector	Building F Kindergarten Classroom 34	Tested	10:04:56 AM	08/26/2019
Smoke Detector	Building F Kindergarten Workroom	Tested	10:01:42 AM	08/26/2019
Smoke Detector	Building G Faculty Dining	Tested	10:27:59 AM	08/26/2019
Smoke Detector	Building G Kitchen Food Storage	Tested	10:29:34 AM	08/26/2019
Smoke Detector	Building G MPR Foyer Exit	Tested	10:37:50 AM	08/26/2019
Smoke Detector	Building G MPR Main Auditorium	Tested	10:38:39 AM	08/26/2019
Smoke Detector	Building G MPR Main Auditorium	Tested	10:40:21 AM	08/26/2019
Smoke Detector	Building G MPR Main Auditorium	Tested	10:40:27 AM	08/26/2019
Smoke Detector	Building G MPR Main Auditorium	Tested	10:40:34 AM	08/26/2019
Smoke Detector	Building G MPR Main Auditorium	Tested	10:40:39 AM	08/26/2019
Smoke Detector	Building G MPR Main Auditorium	Tested	10:40:43 AM	08/26/2019
Smoke Detector	Building G MPR Stage	Tested	10:50:26 AM	08/26/2019
Smoke Detector	Building G MPR Stage	Tested	10:51:30 AM	08/26/2019
Smoke Detector	Girl's Portable Restroom	Tested	11:37:52 AM	08/26/2019
Smoke Detector	Portable 11	Tested	11:42:57 AM	08/26/2019
Smoke Detector	Portable 11	Tested	11:43:08 AM	08/26/2019
Smoke Detector	Portable 12	Tested	11:42:27 AM	08/26/2019
Smoke Detector	Portable 12	Tested	11:42:40 AM	08/26/2019
Smoke Detector	Portable 13	Tested	11:42:08 AM	08/26/2019
Smoke Detector	Portable 13	Tested	11:42:20 AM	08/26/2019
Smoke Detector	Portable 14	Tested	11:29:50 AM	08/26/2019
Smoke Detector	Portable 14	Tested	11:30:03 AM	08/26/2019
Smoke Detector	Portable 15	Tested	11:31:15 AM	08/26/2019
Smoke Detector	Portable 15	Tested	11:31:25 AM	08/26/2019
Smoke Detector	Portable 16	Tested	11:31:30 AM	08/26/2019
Smoke Detector	Portable 16	Tested	11:31:42 AM	08/26/2019
			9:32:51 AM	
Smoke Detector	Portable 17	Tested	J.JL.JI AN	08/26/2019

Device Type	Location	Service	Time	Date
	Passe	ed and a second s		
Smoke Detector	Portable 17	Tested	9:33:03 AM	08/26/2019
Smoke Detector	Portable 18	Tested	9:30:54 AM	08/26/2019
Smoke Detector	Portable 18	Tested	9:31:12 AM	08/26/2019
Smoke Detector	Portable 19	Tested	9:28:42 AM	08/26/2019
Smoke Detector	Portable 19	Tested	9:28:53 AM	08/26/2019
Smoke Detector	Portable 20	Tested	9:28:26 AM	08/26/2019
Smoke Detector	Portable 20	Tested	9:28:36 AM	08/26/2019
Smoke Detector	Portable 21	Tested	9:26:54 AM	08/26/2019
Smoke Detector	Portable 21	Tested	9:27:05 AM	08/26/2019
Smoke Detector	Portable 22	Tested	9:25:13 AM	08/26/2019
Smoke Detector	Portable 22	Tested	9:25:31 AM	08/26/2019
Smoke Detector	Portable 35	Tested	11:41:33 AM	08/26/2019
Smoke Detector	Portable 35	Tested	11:41:43 AM	08/26/2019
Smoke Detector	Portable 36	Tested	11:41:17 AM	08/26/2019
Smoke Detector	Portable 36	Tested	11:41:27 AM	08/26/2019
Smoke Detector	Portable 37	Tested	11:31:48 AM	08/26/2019
Smoke Detector	Portable 37	Tested	11:32:00 AM	08/26/2019
Smoke Detector	Unisex Portable Restroom	Tested	11:38:11 AM	08/26/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Wilson Elementary

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Annunciator	Inspected	1
Battery	Tested	12
Control Panel	Inspected	1
Heat Detector	Tested	122
Power Supply	Inspected	5
Pull Station	Tested	4
Smoke Detector	Tested	108
Total		253

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Wilson Elementary

Control Panel: 1 - Simplex 4100U

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category		% of Inventory	Quantity
Control Panel		Control		0.40%	1
Battery		Control		4.74%	12
Smoke Detector		Initiating		42.69%	108
Power Supply		Control		1.98%	5
Annunciator		Control		0.40%	1
Pull Station		Initiating		1.58%	4
Heat Detector		Initiating	_	48.22%	122
Туре	Qty	Model #	Description		Install Date
		New	(under 90 days)	
Simplex			Ť.		
Annunciator	1	4100U			08/26/2019
Control Panel	1	4100U			08/26/2019
Heat Detector	122	4098-9733			08/26/2019
Power Supply	5	4009			08/26/2019
		In Service	e - 2 Years to 3	Years	
Battery	2	12V18AH	Sealed Lead Acid		07/24/2017
Battery	2	12V7AH	Sealed Lead Acid		07/24/2017
Simplex					
Pull Station	4	4099-9001			07/24/2017
Smoke Detector	108	4098-9714	Photoelectric		07/24/2017
Battery	8	12V7AH	Sealed Lead Acid		07/14/2017

Fire Alarm and Life Safety System Inspection Certificate

For

NMUSD - Woodland Elementary 2025 Garden Ln Costa Mesa, CA 92627

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Aug 30, 2019

> Building: NMUSD - Woodland Elementary Contact: Tim Waller Title: M&O Manager

Company: Cal Building Systems Contact: Beeri Martinez Title: Technician

Executive Summary Generated by: BuildingReports.com

Building Information		
Building: NMUSD - Woodland Elementary	Contact: Tim	Waller
Address: 2025 Garden Ln	Phone: 71442	247556
Address:	Fax:	
City/State/Zip: Costa Mesa, CA 92627	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: Cal Building Systems	Inspector: Be	eri Martinez
Address: 2903 Saturn Street	Phone: 714–9	91313100
Address: Suite F	Fax:	
City/State/Zip: Brea, CA 92821	Mobile:	
Country: United States of America	Email: beerim	artinez@calbuildingsystems.com
System Control Unit		
Manufacturer: Simplex	Inspection Da	IDC Style:
Model Number: 4100U	Install Date: (08/30/2019 SLC Style:
Software Version:	Version Date	08/30/2019 NAC Style:
Location: Admin Bldg. Nurse Office MDF Room	Current Prote	ction: Breaker
Monitoring		
Company:	Phone:	Account #:
Central Station Signal Verification		
Туре:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
C	Total	Total Items		Serviced		ssed	Failed/Other	
Category	Qty	%	Qty	%	Qty	%	Qty	%
Sound Test	1	0.63%	1	100.00%	1	100.00%	0	0%
Control	19	11.95%	19	100.00%	19	100.00%	0	0%
Initiating	139	87.42%	139	100.00%	139	100.00%	0	0%
Totals	159	100%	159	100.00%	159	100.00%	0	0%
Certification Company: Cal Building Systems Building: NMUSD – Woodland Elementary								
Inspector: Beeri Martinez			Co	ntact: Tim	Waller			
UÚ								
Signed: Aug 30, 2019 5:09:37	7 PM		Sig	jned:				

Notes & Recommendations

Generated by: BuildingReports.com

Building: NMUSD - Woodland Elementary Control Panel: 1 - Simplex 4100U

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

ScanID	Note	Device Type	Location	Comment	
Initiating					
58095070	1	Smoke Detector	Classroom 9	Passed	
Functional but is missing head cover.					

Inspection & Testing

Generated by: BuildingReports.com

Building: NMUSD - Woodland Elementary

Control Panel: 1 - Simplex 4100U

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Passed			
Control				
Annunciator	Admin Bldg. Corridor By Teachers Lounge	Tested	8:56:35 AM	08/30/2019
Battery	Admin Bldg. Nurse Office MDF Room	Tested	7:13:01 AM	08/30/2019
Battery	Admin Bldg. Nurse Office MDF Room	Tested	7:13:33 AM	08/30/2019
Battery	Kindergarten Bldg. Outside Storage	Tested	7:52:00 AM	08/30/2019
Battery	Kindergarten Bldg. Outside Storage	Tested	7:52:09 AM	08/30/2019
Battery	Electrical Behind Classroom 16	Tested	8:38:37 AM	08/30/2019
Battery	Electrical Behind Classroom 16	Tested	8:38:48 AM	08/30/2019
Battery	Electrical Behind Classroom 17	Tested	8:52:34 AM	08/30/2019
Battery	Electrical Behind Classroom 17	Tested	8:52:41 AM	08/30/2019
Battery	Workroom By Classroom 13	Tested	8:24:38 AM	08/30/2019
Battery	Workroom By Classroom 13	Tested	8:24:44 AM	08/30/2019
Battery	Workroom By Classroom 8	Tested	8:07:36 AM	08/30/2019
Battery	Workroom By Classroom 8	Tested	8:07:54 AM	08/30/2019
Control Panel	Admin Bldg. Nurse Office MDF Room	Tested	7:11:44 AM	08/30/2019
Power Supply	Kindergarten Bldg. Outside Storage	Tested	7:50:54 AM	08/30/2019
Power Supply	Electrical Behind Classroom 16	Tested	8:38:24 AM	08/30/2019
Power Supply	Electrical Behind Classroom 17	Tested	8:51:24 AM	08/30/2019
Power Supply	Workroom By Classroom 13	Tested	8:24:27 AM	08/30/2019
Power Supply	Workroom By Classroom 8	Tested	8:07:14 AM	08/30/2019
Initiating				
Heat Detector	Bldg. 1 Storage	Tested	5:01:43 PM	08/30/2019
Heat Detector	Bldg. 8 Girl's Restroom	Tested	9:56:54 AM	08/30/2019
Heat Detector	IDF Room 17	Tested	5:02:06 PM	08/30/2019
Heat Detector	Kindergarten Bldg. Restroom Attic K1	Tested	4:59:02 PM	08/30/2019
Heat Detector	Kindergarten Bldg. Restroom Attic K2	Tested	4:58:10 PM	08/30/2019
Heat Detector	Kindergarten Bldg. Unisex Restroom	Tested	4:57:36 PM	08/30/2019
Heat Detector	Electrical Room Library	Tested	4:59:39 PM	08/30/2019
Heat Detector	Electrical Room 10	Tested	5:02:25 PM	08/30/2019
Heat Detector	Electrical Room 5	Tested	9:56:31 AM	08/30/2019
Heat Detector	IDF Room Library	Tested	5:01:11 PM	08/30/2019
Heat Detector	IDF Room 3	Tested	9:56:37 AM	08/30/2019
Heat Detector	Kitchen MPR Attic	Tested	5:03:08 PM	08/30/2019
Heat Detector	Kitchen MPR Attic	Tested	5:03:21 PM	08/30/2019
Heat Detector	Kitchen MPR	Tested	5:02:51 PM	08/30/2019
Heat Detector	M.D.F Room	Tested	5:01:18 PM	08/30/2019
Heat Detector	Mechanical Room K1	Tested	4:56:47 PM	08/30/2019
Heat Detector	Mechanical Room K2	Tested	4:57:22 PM	08/30/2019
Heat Detector	Mechanical Room MPR Attic	Tested	5:03:25 PM	08/30/2019

Device Type	Location	Service	Time	Date
	Passed			
Heat Detector	Portables 20	Tested	5:04:15 PM	08/30/2019
Heat Detector	Portables 21	Tested	5:04:55 PM	08/30/2019
Heat Detector	Portables 22	Tested	5:05:10 PM	08/30/2019
Heat Detector	Portables 23	Tested	5:05:21 PM	08/30/2019
Heat Detector	Portables 24	Tested	5:05:31 PM	08/30/2019
Heat Detector	Portables 25	Tested	5:05:44 PM	08/30/2019
Heat Detector	Portables 26	Tested	5:08:35 PM	08/30/2019
Heat Detector	Portables 26	Tested	5:08:46 PM	08/30/2019
Heat Detector	Portables 6	Tested	5:05:54 PM	08/30/2019
Heat Detector	Portables 7	Tested	5:06:03 PM	08/30/2019
Heat Detector	Portables Kinder Disabled RR	Tested	5:08:15 PM	08/30/2019
Heat Detector	Portables Kinder Men's RR	Tested	5:07:38 PM	08/30/2019
Heat Detector	Portables Kinder Women's RR	Tested	5:08:02 PM	08/30/2019
Heat Detector	Portables PK1	Tested	5:06:54 PM	08/30/2019
Heat Detector	Portables PK2	Tested	5:07:14 PM	08/30/2019
Heat Detector	Portables PK3	Tested	5:07:28 PM	08/30/2019
Pull Station	Admin Bldg. Admin Entrance	Tested	7:21:46 AM	08/30/2019
Pull Station	Admin Bldg. Teachers Lounge	Tested	7:20:49 AM	08/30/2019
Pull Station	MPR Bldg. MPR Exit	Tested	7:28:28 AM	08/30/2019
Pull Station	MPR Bldg. MPR Exit	Tested	7:28:54 AM	08/30/2019
Pull Station	MPR Bldg. MPR Exit	Tested	7:29:16 AM	08/30/2019
Smoke Detector	Admin Bldg. Front Desk	Tested	7:21:17 AM	08/30/2019
Smoke Detector	Admin Bldg. Nurse Office MDF Room	Tested	7:14:26 AM	08/30/2019
Smoke Detector	Admin Bldg. Nurse Office Restroom	Tested	7:18:49 AM	08/30/2019
Smoke Detector	Admin Bldg. Nurse Office	Tested	7:18:37 AM	08/30/2019
Smoke Detector	Admin Bldg. Outside Staff Restroom	Tested	7:23:57 AM	08/30/2019
Smoke Detector	Admin Bldg. Principals Office	Tested	7:22:57 AM	08/30/2019
Smoke Detector	Admin Bldg. Teachers Lounge Restroom	Tested	7:19:35 AM	08/30/2019
Smoke Detector	Admin Bldg. Teachers Lounge	Tested	7:19:56 AM	08/30/2019
Smoke Detector	Admin Bldg. Teachers Lounge	Tested	7:20:04 AM	08/30/2019
Smoke Detector	Admin Bldg. Workroom	Tested	7:22:25 AM	08/30/2019
Smoke Detector	Kindergarten Bldg. Classroom 1 Restroom	Tested	7:42:27 AM	08/30/2019
Smoke Detector	Kindergarten Bldg. Classroom 1	Tested	7:41:20 AM	08/30/2019
Smoke Detector	Kindergarten Bldg. Classroom 1	Tested	7:41:58 AM	08/30/2019
Smoke Detector	Kindergarten Bldg. Classroom 2 Restroom	Tested	7:44:22 AM	08/30/2019
Smoke Detector	Kindergarten Bldg. Classroom 2	Tested	7:43:33 AM	08/30/2019
Smoke Detector	Kindergarten Bldg. Classroom 2	Tested	7:43:40 AM	08/30/2019
Smoke Detector	Kindergarten Bldg. Outside Storage	Tested	7:45:56 AM	08/30/2019
Smoke Detector	Kindergarten Bldg. Teachers Workroom Restroom	Tested	7:42:55 AM	08/30/2019
Smoke Detector	Kindergarten Bldg. Teachers Workroom	Tested	7:43:17 AM	08/30/2019
Smoke Detector	MPR Bldg. MPR Community Coordinator	Tested	7:36:35 AM	08/30/2019
Smoke Detector	MPR Bldg. MPR Corridor By Restroom	Tested	7:34:32 AM	08/30/2019
Smoke Detector	MPR Bldg. MPR Main Dinning	Tested	7:29:54 AM	08/30/2019
Smoke Detector	MPR Bldg. MPR Main Dinning MPR Bldg. MPR Main Dinning	Tested	7:30:32 AM	
Smoke Detector	MPR Bldg. MPR Main Dinning MPR Bldg. MPR Main Dinning	Tested	7:30:35 AM	08/30/2019 08/30/2019
Smoke Detector	MPR Bldg. MPR Main Dinning MPR Bldg. MPR Main Dinning	Tested	7:30:39 AM	08/30/2019
Smoke Detector		Tested	7:32:59 AM	
	MPR Bldg. MPR Main Stage		7:33:10 AM	08/30/2019
Smoke Detector	MPR Bldg. MPR Main Stage	Tested	7:32:19 AM	08/30/2019
Smoke Detector	MPR Bldg. MPR Telecom Room	Tested	1.52.19 AM	08/30/2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	MPR Bldg. MPR Uni-Sex Restroom	Tested	7:35:03 AM	08/30/2019
Smoke Detector	MPR Bldg. MPR Uni-Sex Restroom	Tested	7:35:26 AM	08/30/2019
Smoke Detector	Portables Boy's Restroom	Tested	7:54:49 AM	08/30/2019
Smoke Detector	Portables Classroom 20	Tested	8:30:14 AM	08/30/2019
Smoke Detector	Portables Classroom 20	Tested	8:30:37 AM	08/30/2019
Smoke Detector	Portables Classroom 21	Tested	8:31:08 AM	08/30/2019
Smoke Detector	Portables Classroom 21	Tested	8:31:22 AM	08/30/2019
Smoke Detector	Portables Classroom 22	Tested	8:32:11 AM	08/30/2019
Smoke Detector	Portables Classroom 22	Tested	8:32:20 AM	08/30/2019
Smoke Detector	Portables Classroom 23	Tested	8:33:06 AM	08/30/2019
Smoke Detector	Portables Classroom 23	Tested	8:33:14 AM	08/30/2019
Smoke Detector	Portables Classroom 24	Tested	8:34:02 AM	08/30/2019
Smoke Detector	Portables Classroom 24	Tested	8:34:09 AM	08/30/2019
Smoke Detector	Portables Classroom 25	Tested	8:34:53 AM	08/30/2019
Smoke Detector	Portables Classroom 25	Tested	8:34:59 AM	08/30/2019
Smoke Detector	Portables Classroom 6	Tested	8:02:19 AM	08/30/2019
Smoke Detector	Portables Classroom 6	Tested	8:02:29 AM	08/30/2019
Smoke Detector	Portables Classroom 7	Tested	8:03:10 AM	08/30/2019
Smoke Detector	Portables Classroom 7	Tested	8:03:18 AM	08/30/2019
Smoke Detector	Portables Girl's Restroom	Tested	7:53:08 AM	08/30/2019
Smoke Detector	Portables PK-1	Tested	7:55:54 AM	08/30/2019
Smoke Detector	Portables PK-1	Tested	7:56:13 AM	08/30/2019
Smoke Detector	Portables PK-2	Tested	7:56:44 AM	08/30/2019
Smoke Detector	Portables PK-2	Tested	7:56:56 AM	08/30/2019
Smoke Detector	Portables PK-3	Tested	7:57:47 AM	08/30/2019
Smoke Detector	Portables PK-3	Tested	7:57:56 AM	08/30/2019
Smoke Detector	Portables Staff Restroom	Tested	7:53:38 AM	08/30/2019
Smoke Detector	Boy's Restroom Behind Classroom 10	Tested	8:15:32 AM	08/30/2019
Smoke Detector	Boy's Restroom Behind Classroom 13	Tested	8:22:57 AM	08/30/2019
Smoke Detector	Boy's Restroom Behind Classroom 8	Tested	8:10:51 AM	08/30/2019
Smoke Detector	Classroom 10	Tested	8:18:27 AM	08/30/2019
Smoke Detector	Classroom 10	Tested	8:18:37 AM	08/30/2019
Smoke Detector	Classroom 11	Tested	8:19:15 AM	08/30/2019
Smoke Detector	Classroom 11	Tested	8:19:27 AM	08/30/2019
Smoke Detector	Classroom 12	Tested	8:20:54 AM	08/30/2019
Smoke Detector	Classroom 12	Tested	8:21:02 AM	08/30/2019
Smoke Detector	Classroom 13	Tested	8:25:58 AM	08/30/2019
Smoke Detector	Classroom 13	Tested	8:26:10 AM	08/30/2019
Smoke Detector	Classroom 16	Tested	8:43:53 AM	08/30/2019
Smoke Detector	Classroom 16	Tested	8:44:04 AM	08/30/2019
Smoke Detector	Classroom 17	Tested	8:45:24 AM	08/30/2019
Smoke Detector	Classroom 17	Tested	8:45:32 AM	08/30/2019
Smoke Detector	Classroom 18	Tested	8:45:36 AM	08/30/2019
Smoke Detector	Classroom 18	Tested	8:45:42 AM	08/30/2019
Smoke Detector	Classroom 19	Tested	8:45:46 AM	08/30/2019
Smoke Detector	Classroom 19	Tested	8:45:54 AM	08/30/2019
Smoke Detector	Classroom 3	Tested	7:58:57 AM	08/30/2019
Smoke Detector	Classroom 3	Tested	7:59:16 AM	08/30/2019
Smoke Detector	Classroom 4	Tested	8:00:18 AM	08/30/2019
Smoke Detector	Classroom 4	Tested	8:00:25 AM	08/30/2019
SHOKE DELECIOI		icicu		00,00,2019

Device Type	Location	Service	Time	Date
	Passed			
Smoke Detector	Classroom 5	Tested	8:00:56 AM	08/30/2019
Smoke Detector	Classroom 5	Tested	8:01:03 AM	08/30/2019
Smoke Detector	Classroom 8	Tested	8:03:53 AM	08/30/2019
Smoke Detector	Classroom 8	Tested	8:04:03 AM	08/30/2019
Smoke Detector	Classroom 9	Tested	8:11:30 AM	08/30/2019
Smoke Detector	Classroom 9	Tested	8:11:38 AM	08/30/2019
Smoke Detector	Electrical Behind Classroom 17	Tested	8:52:56 AM	08/30/2019
Smoke Detector	Girl's Restroom By Classroom 10	Tested	8:17:22 AM	08/30/2019
Smoke Detector	Girl's Restroom By Classroom 13	Tested	8:22:15 AM	08/30/2019
Smoke Detector	Girl's Restroom By Classroom 8	Tested	8:08:56 AM	08/30/2019
Smoke Detector	Library Conference Room	Tested	8:41:48 AM	08/30/2019
Smoke Detector	Library	Tested	8:42:21 AM	08/30/2019
Smoke Detector	Library	Tested	8:42:25 AM	08/30/2019
Smoke Detector	Library	Tested	8:42:29 AM	08/30/2019
Smoke Detector	Staff Restroom By Classroom 13	Tested	8:22:28 AM	08/30/2019
Smoke Detector	Staff Restroom By Classroom 13	Tested	8:22:35 AM	08/30/2019
Smoke Detector	Staff Restroom By Classroom 8	Tested	8:09:40 AM	08/30/2019
Smoke Detector	Staff Restroom By Classroom 8	Tested	8:09:52 AM	08/30/2019
Smoke Detector	Storage Behind Classroom 10	Tested	8:16:38 AM	08/30/2019
Smoke Detector	Workroom By Classroom 10	Tested	8:17:59 AM	08/30/2019
Smoke Detector	Workroom By Classroom 13	Tested	8:23:48 AM	08/30/2019
Smoke Detector	Workroom By Classroom 8	Tested	8:05:20 AM	08/30/2019

Service Summary

Generated by: BuildingReports.com

Building: NMUSD - Woodland Elementary

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity					
Passed							
Annunciator	Tested	1					
Battery	Tested	12					
Control Panel	Tested	1					
Heat Detector	Tested	34					
Power Supply	Tested	5					
Pull Station	Tested	5					
Smoke Detector	Tested	100					
Total		158					

Sound and Visual Testing

Generated by: BuildingReports.com

Building: NMUSD - Woodland Elementary

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

		Ambient	Alarm	🦻 Intell	igibility	Sound				
🗘 Location	 Comment 	◀ dB	◀ dB	Voice	STI	Test				
Passed										
Sound Test Points										
Entire Campus	Passed					0001				

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: NMUSD - Woodland Elementary

Control Panel: 1 - Simplex 4100U

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item		Category		% of Inventory	Quantity		
Control Panel		Control		0.63%	1		
Battery		Control		7.55%	12		
Smoke Detector		Initiating		62.89%	100		
Pull Station		Initiating		3.14%	5		
Power Supply		Control		3.14%	5		
Annunciator		Control		0.63%	1		
Heat Detector		Initiating		21.38%	34		
Туре	Qty	Model #	Description		Install Date		
New (under 90 days)							
Simplex							
Annunciator	1	4100U			08/30/2019		
Control Panel	1	4100U			08/30/2019		
Heat Detector	34	4098-9403	Fixed Tempera	ture	08/30/2019		
Power Supply	5	4009 IDNET			08/30/2019		
Pull Station	5	4099-9001	Keyed		08/30/2019		
Smoke Detector	100	4098-9714	Photoelectric		08/30/2019		
In Service - 2 Years to 3 Years							
Battery	2	12v 24ah	Sealed Lead Ac	id	08/17/2017		
Battery	10	12v 7ah	Sealed Lead Ac	id	08/17/2017		